

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 16, 2022

Progress Estin		Contract ID Prime Contractor	220121-D04 E & C Bridge, LLC	Pay Period Start Pay Period End	July 16, 2022 August 15, 2022	Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,408,489.55 \$0.00 \$1,408,489.55
Approval Date							By User
August 16, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by						
August 18, 2022		Revie	ewed and Approved	(and should be cons	sidered Draft) at th	e Resident Engineer Level by	browns1
August 19, 2022			Revie	ewed and Approved	at the Central Offi	ce Controllers Office Level by	ramses1
Original Comp	letion Date	Current Compl	% of Current Contract Amou	nt Complete			
December	1, 2022	December 1	1, 2022			99.84%	
	Contract	Informational Dates		N/	liloetonoe		

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	No Milestones Exist for Contract	
Acceptance Date			
Awarded Date	February 2, 2022	February 2, 2022	
Letting Date	January 21, 2022	January 21, 2022	
Notice to Proceed Date	February 17, 2022	February 17, 2022	
Open to Traffic Date			
Work Began Date	March 7, 2022	March 7, 2022	

Contract Total Pay	Contract Total Pay For Estimate No. 10												
		This Estimate	Previous	To Date									
220121-D04													
	Total Posted Items Pay	\$5,250.00	\$1,400,987.55	\$1,406,237.55									
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00									
	Incentive	\$0.00	\$0.00	\$0.00									
	Disincentive	\$0.00	\$0.00	\$0.00									
	Liquidated Damage	\$0.00	\$0.00	\$0.00									
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00									
			\$1,400,987.55	\$1,406,237.55									
<b>Contract Total Pay</b>	yable This Estimate:	\$5,250.00											

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount				
J5S3283	0240	8059901	MISC.SEEDING - COOL SEASON IXTURE	LS	\$5,250.000	1	\$5,250.00				
Project J5S3283	- Total						\$5,250.00				
Overall - Total	verall - Total										

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments Exist on Contract						
Line item	Aujusti	Hents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3283	0220	PERMANENT EROSION CONTROL GEOTEXTILE	Material			-1,686	\$3.00	(\$5,058.00)
	0220	PERMANENT EROSION CONTROL GEOTEXTILE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user bashoa1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	1,686	\$3.00	\$5,058.00
	0270	SILT FENCE	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-70	\$2.90	(\$203.00)
	0270	SILT FENCE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user bashoa1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	70	\$2.90	\$203.00
	0300	BRIDGE APPROACH SLAB	Material			-114	\$215.00	(\$24,510.00)

Revision 4/1/2020 Page 1 of 19



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 16, 2022

Progress Estimate Number	Contract ID	220121-D04	Pay Period Start	July 16, 2022	Original Contract Amount	\$1,408,489.55
10	<b>Prime Contractor</b>	E & C Bridge, LLC	Pay Period End	August 15, 2022	Net Change Order Amount	
					Current Contract Amount	\$1,408,489.55

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3283		(MINOR ROAD)						
	0300	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user bashoa1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	114	\$215.00	\$24,510.00
J5S3348	0590	SILT FENCE	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-20	\$2.90	(\$58.00)
	0590	SILT FENCE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user bashoa1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	20	\$2.90	\$58.00
	0710	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-6	\$900.00	(\$5,400.00)
	0710	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user bashoa1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	6	\$900.00	\$5,400.00
	0720	ROCK SOCKETS (3 FT 0 IN. DIA.)	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-2	\$825.00	(\$1,650.00)
	0720	ROCK SOCKETS (3 FT 0 IN. DIA.)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user bashoa1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	2	\$825.00	\$1,650.00
	0760	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-13	\$125.00	(\$1,625.00)
	0760	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user bashoa1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	13	\$125.00	\$1,625.00
	0820	REINFORCING STEEL (BRIDGES)	Material			-12,220	\$1.50	(\$18,330.00)
	0820	REINFORCING STEEL (BRIDGES)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user bashoa1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	12,220	\$1.50	\$18,330.00
Total								\$0.00

Revision 4/1/2020 Page 2 of 19



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	Contract Project Information	on			
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work			
J5S3283	FAF 100-1(77)	Bridge deck replacement	100	OSAGE	over Deer Creek 4 miles we	est of Chamois				
J5S3348 FAF Bridge 100-1(78) Preplacement 100 OSAGE over Cedar Creek 0.1 Miles south of Route C in Luystown										
Γotals by J	Job Numbe	rs								
J5S3283		d Item Pay Item Adjustmo		Item Pay	This Estimate \$5,250.00 \$0.00 <b>\$5,250.00</b>	<b>Previous</b> \$491,108.00 \$0.00 <b>\$491,108.00</b>	To Date \$496,358.00 \$0.00 \$496,358.00			
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			
J5S3348		d Item Pay Item Adjustmo		Item Pay	This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$909,879.55 \$0.00 \$909,879.55	To Date \$909,879.55 \$0.00 \$909,879.55			
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			

Revision 4/1/2020 Page 3 of 19



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3283, Item 4019905, Project Item Line Number 0040, Material Set 401990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action 0501CCPAQCQA Pavement is insufficient.	Bashoa1: Awaiting Materials to resolve. Concrete was used in Lieu of contractors mix.	bashoa1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3283, Item 5031011A, Project Item Line Number 0300, Material Set 5031011A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	Bashoa1: Materials to resolve at a later date .	bashoa1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3283, Item 5031011A, Project Item Line Number 0300, Material Set 5031011A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Bashoa1: Materials to resolve at a later date .	bashoa1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3283, Item 6240103A, Project Item Line Number 0220, Material Set 6240103A96, Material 1011GXT3 - Geotextile Fabric for ErosionControl(T3), Acceptance Action Generic 1011GXT3 is insufficient.	Bashoa1: Materials to enter test .	bashoa1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3348, Item 7032003, Project Item Line Number 0780, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Bashoa1: Materials to resolve at a later date .	bashoa1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3348, Item 7061060, Project Item Line Number 0820, Material Set 706106096, Material 1036RSDFPL42M29 - Reinforcing Steel No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Bashoa1: Materials to resolve at a later date .	bashoa1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3348, Item 7061060, Project Item Line Number 0820, Material Set 706106096, Material 1036RSDFPL42M32 - Reinforcing Steel No. 10/M32 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.	Bashoa1: Materials to resolve at a later date .	bashoa1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3348, Item 7061060, Project Item Line Number 0820, Material Set 706106096, Material 1036RSDFPL42M36 - Reinforcing Steel No. 11/M36 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.	Bashoa1: Materials to resolve at a later date .	bashoa1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3348, Item 7061060, Project Item Line Number 0820, Material Set 706106096, Material 1036RSDFPL42M22 - Reinforcing Steel No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Bashoa1: Materials to resolve at a later date .	bashoa1	Overridden
Estimate Exception Type: Item Overrun: Contract 220121-D04, Contract Project J5S3283, Project Item Line Number 0270, Contract Line Item Number 0270, Item 8061019, Minor Item.	Bashoa1: Modot change order item.	bashoa1	Overridden
Estimate Exception Type: Item Overrun: Contract 220121-D04, Contract Project J5S3348, Project Item Line Number 0590, Contract Line Item Number 0590, Item 8061019, Minor Item.	Bashoa1: Modot change order item.	bashoa1	Overridden
Estimate Exception Type: Item Overrun: Contract 220121-D04, Contract Project J5S3348, Project Item Line Number 0710, Contract Line Item Number 0710, Item 7011105, Minor Item.	Bashoa1: Modot change order item.	bashoa1	Overridden
Estimate Exception Type: Item Overrun: Contract 220121-D04, Contract Project J5S3348, Project Item Line Number 0720, Contract Line Item Number 0720, Item 7011204, Minor Item.	Bashoa1: Modot change order item.	bashoa1	Overridden
Estimate Exception Type: Item Overrun: Contract 220121-D04, Contract Project J5S3348, Project Item Line Number 0760, Contract Line Item Number 0760, Item 7021212, Minor Item.	Bashoa1: Modot change order item.	bashoa1	Overridden

Revision 4/1/2020 Page 4 of 19



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract	Project No.	Category	Line No.	ltem Code	eport Generated date and can differ from the posted amo	Bid Quantity	Net Change	Total Current	unit	Total Posted	Unit Price	Total Value POSTED To Date (See report
							Order	Quantity		Approved Qty		generated date)
21-D04	J5S3283	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$10,000.00	\$10,000.00
		0001	0020	2121000A	SUBGRADING AND SHOULDERING CLASS 1	1.00	0.00	1.00	100F	1.00	\$1,500.00	\$1,500.0
		0001	0030	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	256.00	0.00	256.00	SQYD	256.00	\$14.50	\$3,712.0
		0001	0040	4019905	MISC.Optional Pavement	256.00	0.00	256.00	SQYD	256.00	\$90.00	\$23,040.0
		0001	0050	6069901	MISC.MGS GUARDRAIL CONNECTOR PLATE	1.00	0.00	1.00	LS	1.00	\$8,735.00	\$8,735.0
		0001	0060	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	1.00	0.00	1.00	CUYD	0.00	\$500.00	\$0.0
		0001	0070	6096041	PLACING TYPE 1 ROCK DITCH LINER	1.00	0.00	1.00	CUYD	0.00	\$500.00	\$0.0
		0001	0800	6113020	FURNISHING TYPE 2 ROCK BLANKET	2,474.00	0.00	2,474.00	CUYD	2,474.00	\$48.00	\$118,752.0
		0001	0090	6113040	PLACING TYPE 2 ROCK BLANKET	2,474.00	0.00	2,474.00	CUYD	2,474.00	\$18.00	\$44,532.0
		0001	0100	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0.0
		0001	0110	6161005	CONSTRUCTION SIGNS	370.00	0.00	370.00	SQFT	329.00	\$7.00	\$2,303.0
		0001	0120	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	2.00	\$45.00	\$90.0
		0001	0130	6161010	RELOCATED SIGNS	25.00	0.00	25.00	SQFT	25.00	\$6.00	\$150.
		0001	0140	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$145.00	\$1,450.0
		0001	0150	6161052	WARNING LIGHT, TYPE B	20.00	0.00	20.00	EA	12.00	\$85.00	\$1,020.0
		0001	0160	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.0
		0001	0170	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$21,500.00	\$21,500.0
		0001	0180	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$400.50	\$0.0
		0001	0190	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	596.00	0.00	596.00	LF	596.00	\$1.00	\$596.
		0001	0200	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	596.00	0.00	596.00	LF	596.00	\$1.00	\$596
		0001	0210	6214600A	FLOWABLE BACKFILL	20.00	0.00	20.00	CUYD	20.00	\$250.00	\$5,000
		0001	0220	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,775.00	0.00	1,775.00	SQYD	1,686.00	\$3.00	\$5,058.
		0001	0230	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$1,500.00	\$1,500
		0001	0240	8059901	MISC.SEEDING - COOL SEASON IXTURE	1.00	0.00	1.00	LS	1.00	\$5,250.00	\$5,250
		0001	0250	8061005	ROCK DITCH CHECK	56.00	0.00	56.00	LF	0.00	\$14.00	\$0
		0001	0260	8061016	SEDIMENT REMOVAL	16.00	0.00	16.00	CUYD	0.00	\$8.00	\$0.
		0001	0270	8061019	SILT FENCE	200.00	0.00	200.00	LF	270.00	\$2.90	\$783.
		0070	0280	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	14.00	0.00	14.00	SQFT	14.00	\$175.00	\$2,450
		0070	0290	2162500	REMOVAL OF EXISTING BRIDGE DECK	4,543.00	0.00	4,543.00	SQFT	4,543.00	\$8.00	\$36,344.
		0070	0300	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	114.00	0.00	114.00	SQYD	114.00	\$215.00	\$24,510
		0070	0310	7034212	SLAB ON STEEL	503.00	0.00	503.00	SQYD	503.00	\$250.00	\$125,750
		0070	0320	7034219A	TYPE D BARRIER	316.00	0.00	316.00	LF	316.00	\$80.00	\$25,280
		0070	0330	7125102	SURFACE PREPARATION FOR APPLYING EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	1.00	\$7,866.00	\$7,866
		0070	0340	7125961	GRAY EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	1.00	\$7,866.00	\$7,866.
		0070	0350	7126000	NON-DESTRUCTIVE TESTING	45.00	0.00	45.00	LF	45.00	\$25.00	\$1,125.
		0070	0360	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,800.00	\$3,600
	Project J	5S3283 - To	otal Value	e Posted to D	late as of Report Generated Date							\$496,358.
	J5S3348	0001	0370	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$12,000.00	\$12,000
		0001	0380	2031000	CLASS A EXCAVATION	285.00	0.00	285.00	CUYD	285.00	\$15.00	\$4,275.
		0001	0390	2035500	EMBANKMENT IN PLACE	180.00	0.00	180.00	CUYD	180.00	\$25.00	\$4,500
		0001	0400	2036000	COMPACTING EMBANKMENT	246.00	0.00	246.00	CUYD	246.00	\$10.00	\$2,460
		0001	0410	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	263.00	0.00	263.00	SQYD	263.00	\$12.50	\$3,287
		0001	0420	4019905	MISC.OPTIONAL PAVEMENT	262.60	0.00	262.60	SQYD	262.60	\$90.00	\$23,634.
		0001	0430	6113020	FURNISHING TYPE 2 ROCK BLANKET	538.00	0.00	538.00	CUYD	538.00	\$45.00	\$24,210.

Revision 4/1/2020 Page 5 of 19



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract lm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTI To Date (See repo generated date)
20121-D04	J5S3348	0001	0440	6113040	PLACING TYPE 2 ROCK BLANKET	538.00	0.00	538.00	CUYD	538.00	\$15.00	\$8,070
		0001	0450	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0
		0001	0460	6161005	CONSTRUCTION SIGNS	1,155.00	0.00	1,155.00	SQFT	1,114.00	\$6.00	\$6,684
		0001	0470	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	2.00	\$45.00	\$90
		0001	0480	6161030	TYPE III MOVEABLE BARRICADE	8.00	0.00	8.00	EA	8.00	\$145.00	\$1,160
		0001	0490	6161052	WARNING LIGHT, TYPE B	16.00	0.00	16.00	EA	16.00	\$85.00	\$1,360
		0001	0500	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000
		0001	0510	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$32,500.00	\$0
		0001	0511	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$23,605.00	\$23,60
		0001	0520	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,010.00	0.00	1,010.00	LF	1,010.00	\$0.50	\$50
		0001	0530	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,010.00	0.00	1,010.00	LF	1,010.00	\$0.50	\$50
		0001	0540	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	806.00	0.00	806.00	SQYD	806.00	\$3.00	\$2,41
		0001	0550	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$2,400.00	\$2,40
		0001	0560	8059901	MISC.SEEDING - COOL SEASON MIXTURE	1.00	0.00	1.00	LS	1.00	\$5,250.00	\$5,25
		0001	0570	8061005	ROCK DITCH CHECK	165.00	0.00	165.00	LF	26.00	\$14.00	\$36
		0001	0580	8061016	SEDIMENT REMOVAL	31.00	0.00	31.00	CUYD	0.00	\$8.00	\$
		0001	0590	8061019	SILT FENCE	180.00	0.00	180.00	LF	200.00	\$2.90	\$58
		0001	0600	8061050	TYPE C BERM	198.00	0.00	198.00	LF	198.00	\$15.00	\$2,9
		0001	0610	8064129	TYPE 2 TURF REINFORCEMENT MAT	964.00	0.00	964.00	SQYD	964.00	\$2.20	\$2,12
		0010	0620	6061060	MGS GUARDRAIL	75.00	0.00	75.00	LF	75.00	\$36.95	\$2,7
		0010	0630	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$3,735.00	\$14,9
		0010	0640	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$3,485.00	\$13,9
		0040	0650	9031010	CONCRETE FOOTINGS, EMBEDDED	0.20	0.00	0.20	CUYD	0.20	\$2,750.00	\$5
		0040	0660	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	6.00	0.00	6.00	LF	6.00	\$325.00	\$1,9
		0070	0670	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	16.00	0.00	16.00	SQFT	16.00	\$175.00	\$2,8
		0070	0680	2061000	CLASS 1 EXCAVATION	70.00	0.00	70.00	CUYD	70.00	\$45.00	\$3,1
		0070	0690	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$37,500.00	\$37,5
		0070	0700	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	118.00	0.00	118.00	SQYD	118.00	\$225.00	\$26,5
		0070	0710	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	54.80	0.00	54.80	LF	60.80	\$900.00	\$54,7
		0070	0720	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	44.00	0.00	44.00	LF	46.00	\$825.00	\$37,9
		0070	0730	7011300	VIDEO CAMERA INSPECTION	4.00	0.00	4.00	EA	4.00	\$900.00	\$3,6
		0070	0740	7011400	FOUNDATION INSPECTION HOLES	84.00	0.00	84.00	LF	84.00	\$100.00	\$8,4
		0070	0750	7011600	SONIC LOGGING TESTING	4.00	0.00	4.00	EA	4.00	\$1,300.00	\$5,2
		0070	0760	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	164.00	0.00	164.00	LF	177.00	\$125.00	\$22,1
		0070	0770	7026000	PRE-BORE FOR PILING	152.00	0.00	152.00	LF	152.00	\$100.00	\$15,2
		0070	0780	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	54.40	0.00	54.40	CUYD	54.40	\$800.00	\$43,5
		0070	0790	7034219A	TYPE D BARRIER	439.00	0.00	439.00	LF	439.00	\$80.00	\$35,1
		0070	0800	7034221	SLAB ON CONCRETE NU-GIRDER	645.00	0.00	645.00	SQYD	645.00	\$320.00	\$206,4
		0070	0810	7056021	NU 35, PRESTRESSED CONCRETE NU-GIRDER	599.00	0.00	599.00	LF	599.00	\$310.00	\$185,6
		0070	0820	7061060	REINFORCING STEEL (BRIDGES)	12,220.00	0.00	12,220.00	LB	12,220.00	\$1.50	\$18,3
		0070	0830	7123610	SLAB DRAIN	38.00	0.00	38.00	EA	38.00	\$400.00	\$15,2
		0070	0840	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,800.00	\$3,6
		0070	0850	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	6.00	\$175.00	\$1,0
			0860	7161002	LAMINATED NEOPRENE BEARING PAD	12.00	0.00	12.00	EA	12.00	\$190.00	\$2,2

Revision 4/1/2020 Page 6 of 19



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

140to. 1 ootou Q	uantitioo	and value	oo are b	acca on re	opert contrated date and can affer from the posted ame	ant at the	unio uno	Louinate W	20 00110	ratou.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-D04	J5S3348	0001	5001	6189901	MISC.New Adjustment Mobilization for Contract Bond	0.00	1.00	1.00	LS	1.00	\$8,895.00	\$8,895.00
	Project J5S3348 - Total Value Posted to Date as of Report Generated Date										\$909,879.55	
220121-D04 Overall - Total Value Posted to Date as of Report Generated Date										\$1,406,237.55		

Revision 4/1/2020 Page 7 of 19



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5S3283

Line Numbe		Description		DWR Approval Date			Location		Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
024	0 8059901	MISC. SEEDING	8/8/22	8/16/22	1.00	LS	Rt Lt Centerline	417+21		420+18.93		Seeded on 7-18-22

			e details for Construction Sign		Ct- "	1	las "	Niverbay 611	055-10	S 1 0:	05 5h 0 : 10:	T-4-105 : -
	Line Number		Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	
348	0460	March 7, 2022	1071	See Special Sign Details		.021		1.00		Special Detour signs 36x78 50E	19.50	1
				See Special Sign Details		.029		1.00		Special Detour signs 36x78 50c	19.50	1
				See Special Sign Details		99.485		1.00		Special Detour signs 36x78 50F	19.50	1
				See Special Sign Details		96.500		1.00		Special Detour signs 36x78 50F	19.50	1
				See Special Sign Details		96.416		1.00		Special Detour signs 36x78 50D	19.50	1
				See Special Sign Details		.056		1.00		Special Detour signs 36x78 50F	19.50	
				See Special Sign Details		.323		1.00		Special Detour signs 36x78 50H	19.50	
				WO20-2 48x48 16.00 DETOUR AHEAD		0.000		1.00	16			
				See Special Sign Details		0.095		1.00		Special Detour signs 36x78 50G	19.50	
				WO20-3 48x48 16.00 ROAD					40	Special Delour signs 36x76 50G	19.50	
				CLOSED AHEAD		1.909		1.00	16			
				See Special Sign Details		10.456		1.00		Special Detour signs 36x78 50H	19.50	
				See Special Sign Details		10.461		1.00		Special Detour signs 36x78 50G	19.50	
				WO20-2 48x48 16.00 DETOUR		10.490		1.00	16			
				AHEAD								
				R11-3a 60x30 12.50 ROAD CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY		103.400		1.00	12.5			
				See Special Sign Details		107.833		1.00		Special Detour signs 36x78 50F	19.50	
				See Special Sign Details		11.314		1.00		Special Detour signs 36x78 50F	19.50	
				R11-3a 60x30 12.50 ROAD		111.037		1.00	12.5			
				CLOSED XX MILES AHEAD LOCAL								
				TRAFFIC ONLY				4.00		0 1101 1	40.50	
				See Special Sign Details		114.000		1.00	10.5	Special Detour signs 36x78 50F	19.50	
				R11-3a 60x30 12.50 ROAD CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY		114.000		1.00	12.5			
				R11-3a 60x30 12.50 ROAD CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY		115.600		1.00	12.5			
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		117.000		1.00	16			
				R11-3a 60x30 12.50 ROAD CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY		117.035		1.00	12.5			
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		117.050		1.00	16			
				R3-1 48x48 16.00 NO RIGHT TURN (SYMBOL)		117.267		1.00	16			
				R3-2 48x48 16.00 NO LEFT TURN (SYMBOL)		117.267		1.00	16			
				R11-2 48x30 10.00 ROAD CLOSED		117.267	On closure barricades		10			
				R11-3a 60x30 12.50 ROAD CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY		118.036		1.00	12.5			
				R11-3a 60x30 12.50 ROAD CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY		120.088		1.00	12.5			
				See Special Sign Details		13.599		1.00		Special Detour signs 36x78 50F	19.50	
				See Special Sign Details		16.313		1.00		Special Detour signs 36x78 50F	19.50	
				WO20-2 48x48 16.00 DETOUR		160.116		1.00	16			
				AHEAD		100.110		1.00	10			
				See Special Sign Details		160.273		1.00		Special Detour signs 36x78 50A	19.50	
				See Special Sign Details		164.659		1.00		Special Detour signs 36x78 50A	19.50	
				See Special Sign Details		165.290		1.00		Special Detour signs 36x78 50c	19.50	
				See Special Sign Details		165.472		1.00		Special Detour signs 36x78 50E	19.50	
				See Special Sign Details		17.601		1.00		Special Detour signs 36x78 50l	19.50	
				See Special Sign Details		17.817		1.00		Special Detour signs 36x78 50l	19.50	
				See Special Sign Details		17.817		1.00		Special Detour signs 36x78 50J	19.50	
				See Special Sign Details		18.090		1.00		Special Detour signs 36x78 50J	19.50	
				See Special Sign Details		2.149		1.00		Special Detour signs 36x78 50A	19.50	
				See Special Sign Details		22.264		1.00		Special Detour signs 36x78 50A  Special Detour signs 36x78 50A	19.50	
				See Special Sign Details See Special Sign Details				1.00			19.50	
				See Special Sign Details		23.126 25.002				Special Detour signs 36x78 50A		
				Con Consist Cian D-4-11-				1.00		Special Detour signs 36x78 50A	19.50	
				See Special Sign Details				1.00		Special Detour signs 36x78 50A		
				See Special Sign Details		27.196					19.50	
				See Special Sign Details See Special Sign Details		27.196 29.602		1.00		Special Detour signs 36x78 50A	19.50	
				See Special Sign Details See Special Sign Details See Special Sign Details		27.196 29.602 3.275		1.00		Special Detour signs 36x78 50A Special Detour signs 36x78 50F	19.50 19.50	
				See Special Sign Details See Special Sign Details See Special Sign Details See Special Sign Details		27.196 29.602 3.275 31.237		1.00 1.00 1.00		Special Detour signs 36x78 50A Special Detour signs 36x78 50F Special Detour signs 36x78 50A	19.50 19.50 19.50	
				See Special Sign Details See Special Sign Details See Special Sign Details		27.196 29.602 3.275 31.237 34.031		1.00 1.00 1.00 1.00		Special Detour signs 36x78 50A Special Detour signs 36x78 50F	19.50 19.50 19.50 19.50	
				See Special Sign Details See Special Sign Details See Special Sign Details See Special Sign Details		27.196 29.602 3.275 31.237		1.00 1.00 1.00		Special Detour signs 36x78 50A Special Detour signs 36x78 50F Special Detour signs 36x78 50A	19.50 19.50 19.50	
				See Special Sign Details		27.196 29.602 3.275 31.237 34.031		1.00 1.00 1.00 1.00		Special Detour signs 36x78 50A Special Detour signs 36x78 50F Special Detour signs 36x78 50A Special Detour signs 36x78 50A	19.50 19.50 19.50 19.50	
				See Special Sign Details		27.196 29.602 3.275 31.237 34.031 35.288		1.00 1.00 1.00 1.00		Special Detour signs 36x78 50A Special Detour signs 36x78 50F Special Detour signs 36x78 50A Special Detour signs 36x78 50A Special Detour signs 36x78 50A	19.50 19.50 19.50 19.50 19.50	
				See Special Sign Details		27.196 29.602 3.275 31.237 34.031 35.288 36.064		1.00 1.00 1.00 1.00 1.00		Special Detour signs 36x78 50A Special Detour signs 36x78 50F Special Detour signs 36x78 50A	19.50 19.50 19.50 19.50 19.50 19.50	
				See Special Sign Details		27.196 29.602 3.275 31.237 34.031 35.288 36.064 4.136		1.00 1.00 1.00 1.00 1.00 1.00 1.00		Special Detour signs 36x78 50A Special Detour signs 36x78 50F Special Detour signs 36x78 50A	19.50 19.50 19.50 19.50 19.50 19.50 19.50	
				See Special Sign Details		27.196 29.602 3.275 31.237 34.031 35.288 36.064 4.136 6.059		1.00 1.00 1.00 1.00 1.00 1.00 1.00		Special Detour signs 36x78 50A Special Detour signs 36x78 50F Special Detour signs 36x78 50A	19.50 19.50 19.50 19.50 19.50 19.50 19.50	
				See Special Sign Details		27.196 29.602 3.275 31.237 34.031 35.288 36.064 4.136 6.059 8.657		1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	16	Special Detour signs 36x78 50A Special Detour signs 36x78 50F Special Detour signs 36x78 50A Special Detour signs 36x78 50F Special Detour signs 36x78 50F	19.50 19.50 19.50 19.50 19.50 19.50 19.50 19.50	
				See Special Sign Details AREAD AREAD DETOUR AHEAD		27.196 29.602 3.275 31.237 34.031 35.288 36.064 4.136 6.059 8.657 9.651		1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	16	Special Detour signs 36x78 50A Special Detour signs 36x78 50F Special Detour signs 36x78 50A Special Detour signs 36x78 50F Special Detour signs 36x78 50F	19.50 19.50 19.50 19.50 19.50 19.50 19.50 19.50 19.50	
				See Special Sign Details		27.196 29.602 3.275 31.237 34.031 35.288 36.064 4.136 6.059 8.657 9.651		1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	16	Special Detour signs 36x78 50A Special Detour signs 36x78 50F Special Detour signs 36x78 50A Special Detour signs 36x78 50F Special Detour signs 36x78 50F	19.50 19.50 19.50 19.50 19.50 19.50 19.50 19.50	

Revision 4/1/2020 Page 8 of 19



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable).

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J5S3348	0460	June 13, 2022	70	See Special Sign Details		0.014	RT C AND A	1.00		MO4-13 96X48	32.00	32
				MO4-8a 24x18 3.00 END DETOUR		38.693		1.00	3			3
	0460 - Total											1082

Revision 4/1/2020 Page 9 of 19



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3283	0040	MISC.	Material		8	Jun 30, 2022	SYSTEM	\$23,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bashoa1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jun 30, 2022	SYSTEM	(\$23,040.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0040 -	Total						\$0.00	
	0050	MISC. GUARDRAIL ITEM	Material		8	Jun 30, 2022	SYSTEM	\$8,735.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bashoa1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Jun 30, 2022	SYSTEM	(\$8,735.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0050 -	Total						\$0.00	
	0190	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		9	Jul 18, 2022	SYSTEM	\$596.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bashoa1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$596.00)	
	0190 - Tota			- Total				\$0.00	
			Material - Tota					\$0.00	
	0190 -	Total						\$0.00	
	0200	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		9	Jul 18, 2022	SYSTEM	\$596.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bashoa1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		WARRING			9	Jul 18, 2022	SYSTEM	(\$596.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0200 -	Total						\$0.00	
	0220	PERMANENT EROSION CONTROL GEOTEXTILE	Material		7	Jun 16, 2022	SYSTEM	\$5,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user bashoa1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		GEOTEXTILE			7	Jun 16, 2022	SYSTEM	(\$5,325.00)	
					8	Jun 30, 2022	SYSTEM	\$5,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bashoa1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Jun 30, 2022	SYSTEM	(\$5,325.00)	
					9	Jul 18, 2022	SYSTEM	\$5,058.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bashoa1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$5,058.00)	
					10	Aug 16, 2022	SYSTEM	\$5,058.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bashoa1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					10	Aug 16, 2022	SYSTEM	(\$5,058.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0220 -	· Total						\$0.00	
	0270	SILT FENCE	Overrun	Overrun	8	Jun 30, 2022	SYSTEM	\$203.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user bashoa1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					0	lum 20	SYSTEM	(\$203.00)	
					8	Jun 30, 2022	STSTEIN	(\$203.00)	
					9		SYSTEM	(\$203.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
S3283	0270	SILT FENCE	Overrun	Overrun					Estimate Exception 14 on the current Payment Estimate.
					10	Aug 16, 2022	SYSTEM	(\$203.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					10	Aug 16, 2022	SYSTEM	\$203.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user bashoa1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				Overrun - To	otal			\$0.00	Estimate Exception to on the eartern't ayment Estimate.
			Overrun - Tota					\$0.00	
	0270 -	Total		*				\$0.00	
	0300	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		8	Jun 30, 2022	SYSTEM	\$24,510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bashoa1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		(			8	Jun 30,	SYSTEM	(\$24,510.00)	Examine Exception 2 Strate cultivative System Examines
					9	Jul 18, 2022	SYSTEM	\$24,510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bashoa1 overridding Payment
							0)/07514	(204.540.00)	Estimate Item Adjustment (0009) due to user basing a Verndung Payment Estimate Exception 2 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$24,510.00)	
					10	Aug 16, 2022	SYSTEM	\$24,510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bashoa1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Aug 16, 2022	SYSTEM	(\$24,510.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0300 -	Total						\$0.00	
	0310	SLAB ON STEEL	Construction Stockpile		7	Jun 16, 2022	SYSTEM	(\$20,780.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$20,780.00)	
			Construction	Stockpile - To	otal			(\$20,780.00)	
			Construction Stockpile STMA		6	Jun 2, 2022	SYSTEM	\$20,780.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STWA	- Total				\$20,780.00	
			Construction	Stockpile STI	MA - Total			\$20,780.00	
			Material		7	Jun 16, 2022	SYSTEM	\$69,162.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user bashoa1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$69,162.50)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0310 -	Total						\$0.00	
	0320	TYPE D BARRIER	Material		8	Jun 30, 2022	SYSTEM	\$25,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user bashoa1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Jun 30, 2022	SYSTEM	(\$25,280.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0320 -	Total						\$0.00	
	0340	GRAY EPOXY- MASTIC PRIMER	Material		7	Jun 16, 2022	SYSTEM	\$7,866.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user bashoa1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$7,866.00)	
					8	Jun 30, 2022	SYSTEM	\$7,866.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user bashoa1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					8	Jun 30, 2022	SYSTEM	(\$7,866.00)	
				- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J5S3283	0340	GRAY EPOXY- MASTIC PRIMER	Material - Tota					\$0.00				
	0340 -	Total						\$0.00				
J5S3283	- Total							\$0.00				
J5S3348	0410	TYPE 5 AGGREGATE FOR BASE	Material		5	May 17, 2022	SYSTEM	\$3,287.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user bashoa1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					5	May 17, 2022	SYSTEM	(\$3,287.50)				
				- Total				\$0.00				
			Material - Tota	l				\$0.00				
	0410 -	Total						\$0.00				
	0420	MISC.	Material		5	May 17, 2022	SYSTEM	\$23,634.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bashoa1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					5	May 17, 2022	SYSTEM	(\$23,634.00)				
					6	Jun 2, 2022	SYSTEM	\$23,634.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user bashoa1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					6	Jun 2, 2022	SYSTEM	(\$23,634.00)				
						7	Jun 16, 2022	SYSTEM	\$23,634.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user bashoa1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					7	Jun 16, 2022	SYSTEM	(\$23,634.00)				
			- Total					\$0.00				
			Material - Tota					\$0.00				
	0420 -	Total						\$0.00				
	0520	4 IN. WHITE WATERBORNE PAVEMENT	Material		7	Jun 16, 2022	SYSTEM	\$505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bashoa1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
		MARKING	MARKING	MARKING	MARKING			7	Jun 16, 2022	SYSTEM	(\$505.00)	
					8	Jun 30, 2022	SYSTEM	\$505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bashoa1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					8	Jun 30, 2022	SYSTEM	(\$505.00)				
				- Total				\$0.00				
			Material - Tota					\$0.00				
	0520 -	Total						\$0.00				
	0530	4 IN. YELLOW WATERBORNE PAVEMENT	Material		7	Jun 16, 2022	SYSTEM	\$505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bashoa1 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
		MARKING			7	Jun 16, 2022	SYSTEM	(\$505.00)				
				8 .	Jun 30, 2022	SYSTEM	\$505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user bashoa1 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
					8	Jun 30, 2022	SYSTEM	(\$505.00)				
				- Total				\$0.00				
			Material - Tota	l e				\$0.00				
	0530 -	Total						\$0.00				
	0570	ROCK DITCH CHECK	Material		2	Apr 5, 2022	SYSTEM	\$364.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bashoa1 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
					2	Apr 5, 2022	SYSTEM	(\$364.00)				
				- Total				\$0.00				
			Material - Tota					\$0.00				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3348	0570 -	Total						\$0.00	
	0590	SILT FENCE	Material		1	Mar 16, 2022	SYSTEM	(\$580.00)	
				- Total				(\$580.00)	
			Material - Tota	ı				(\$580.00)	
			MaterialCredit		2	Apr 5, 2022	SYSTEM	\$580.00	
				- Total				\$580.00	
			MaterialCredit	- Total				\$580.00	
			Overrun	Overrun	1	Mar 16, 2022	SYSTEM	\$58.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 2 on the current Payment Estimate. Material Insufficiency Quantity 200.000; Overrun Quantity Balance 20.00.
					1	Mar 16, 2022	SYSTEM	(\$58.00)	
					2	Apr 5, 2022	SYSTEM	(\$58.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					2	Apr 5, 2022	SYSTEM	\$58.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user bashoa1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$58.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					3	Apr 18, 2022	SYSTEM	\$58.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user bashoa1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$58.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					4	May 2, 2022	SYSTEM	\$58.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user bashoa1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					5	May 17, 2022	SYSTEM	(\$58.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	May 17, 2022	SYSTEM	\$58.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user bashoa1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					6	Jun 2, 2022	SYSTEM	(\$58.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Jun 2, 2022	SYSTEM	\$58.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user bashoa1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$58.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Jun 16, 2022	SYSTEM	\$58.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bashoa1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					8	Jun 30, 2022	SYSTEM	(\$58.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					8	Jun 30, 2022	SYSTEM	\$58.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user bashoa1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$58.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					9	Jul 18, 2022	SYSTEM	\$58.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user bashoa1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					10	Aug 16, 2022	SYSTEM	(\$58.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					10	Aug 16, 2022	SYSTEM	\$58.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user bashoa1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	05 <u>90</u> -	Total						\$0.00	
	0600	TYPE C BERM	Material		2	Apr 5, 2022	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user bashoa1 overridding Payment Estimate Exception 16 on the current Payment Estimate.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J5S3348	0600	TYPE C BERM	Material		2	Apr 5, 2022	SYSTEM	(\$1,500.00)	
				- Total				\$0.00	
			Material - Tota	l e				\$0.00	
	0600 -	· Total						\$0.00	
	0610	TYPE 2 TURF REINFORCEMENT MAT	Material		8	Jun 30, 2022	SYSTEM	\$2,120.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user bashoa1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					8	Jun 30, 2022	SYSTEM	(\$2,120.80)	
					9	Jul 18, 2022	SYSTEM	\$2,120.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user bashoa1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$2,120.80)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0610 -	· Total						\$0.00	
	0700	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		5	May 17, 2022	SYSTEM	\$26,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bashoa1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
	0700 - To				5	May 17, 2022	SYSTEM	(\$26,550.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
		· Total						\$0.00	
	0710	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		2	Apr 5, 2022	SYSTEM	\$54,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user bashoa1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Apr 5, 2022	SYSTEM	(\$54,720.00)	
					3	Apr 18, 2022	SYSTEM	\$54,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user bashoa1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$54,720.00)	
					4	May 2, 2022	SYSTEM	\$54,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user bashoa1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$54,720.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
			Overrun	Overrun	2	Apr 5, 2022	SYSTEM	\$5,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 18 on the current Payment Estimate. Material Insufficiency Quantity 60.800; Overrun Quantity Balance 6.00.
					2	Apr 5, 2022	SYSTEM	(\$5,400.00)	
					3	Apr 18, 2022	SYSTEM	(\$5,400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					3	Apr 18, 2022	SYSTEM	\$5,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 60.800; Overrun Quantity Balance 6.00.
					4	May 2, 2022	SYSTEM	(\$5,400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					4	May 2, 2022	SYSTEM	\$5,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate. Material Insufficiency Quantity 60.800; Overrun Quantity Balance 6.00.
					5	May 17, 2022	SYSTEM	(\$5,400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	May 17, 2022	SYSTEM	\$5,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user bashoa1 overridding Payment Estimate Exception 16 on the current Payment Estimate.



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J5S3348	0710	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Overrun	Overrun	6	Jun 2, 2022	SYSTEM	(\$5,400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				
					6	Jun 2, 2022	SYSTEM	\$5,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user bashoa1 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
					7	Jun 16, 2022	SYSTEM	(\$5,400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				
					7	Jun 16, 2022	SYSTEM	\$5,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user bashoa1 overridding Payment Estimate Exception 17 on the current Payment Estimate.				
					8	Jun 30, 2022	SYSTEM	(\$5,400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				
					8	Jun 30, 2022	SYSTEM	\$5,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user bashoa1 overridding Payment Estimate Exception 20 on the current Payment Estimate.				
					9	Jul 18, 2022	SYSTEM	(\$5,400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				
					9	Jul 18, 2022	SYSTEM	\$5,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user bashoa1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					10	Aug 16, 2022	SYSTEM	(\$5,400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				
					10	Aug 16, 2022	SYSTEM	\$5,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user bashoa1 overridding Payment Estimate Exception 12 on the current Payment Estimate.				
			Overrun - Total	Overrun - T	otal			\$0.00					
				Overrun - Total \$					\$0.00				
	0710 -	Total						\$0.00					
	0720	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		2	Apr 5, 2022	SYSTEM	(\$37,950.00)					
		,						- Total				(\$37,950.00)	
					Material - Tota					(\$37,950.00)			
			Material - Total MaterialCredit										
			MaterialCredit		3	Apr 18, 2022	SYSTEM	\$37,950.00					
			MaterialCredit	- Total	3		SYSTEM	\$37,950.00 \$37,950.00					
			MaterialCredit  MaterialCredit		3		SYSTEM						
							SYSTEM	\$37,950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 46.000; Overrun Quantity Balance 2.00.				
			MaterialCredit	- Total		2022 Apr 5,		\$37,950.00 \$37,950.00	Estimate Item Adjustment (0005) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 46.000;				
			MaterialCredit	- Total	2	Apr 5, 2022	SYSTEM	\$37,950.00 \$37,950.00 \$1,650.00	Estimate Item Adjustment (0005) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 46.000;				
			MaterialCredit	- Total	2	Apr 5, 2022  Apr 5, 2022  Apr 18,	SYSTEM	\$37,950.00 \$37,950.00 \$1,650.00 (\$1,650.00)	Estimate Item Adjustment (0005) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 46.000; Overrun Quantity Balance 2.00.  Averaged Price Adjustment from this item on all previous payment estimates				
			MaterialCredit	- Total	2 2 3	Apr 5, 2022  Apr 5, 2022  Apr 18, 2022  Apr 18,	SYSTEM SYSTEM	\$37,950.00 \$37,950.00 \$1,650.00 (\$1,650.00)	Estimate Item Adjustment (0005) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 46.000; Overrun Quantity Balance 2.00.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user bashoa1 overridding Payment				
			MaterialCredit	- Total	2 2 3 3 3	Apr 5, 2022  Apr 5, 2022  Apr 18, 2022  Apr 18, 2022  May 2, May 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$37,950.00 \$37,950.00 \$1,650.00 (\$1,650.00) (\$1,650.00)	Estimate Item Adjustment (0005) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 46.000; Overrun Quantity Balance 2.00.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user bashoa1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates				
			MaterialCredit	- Total	2 2 3 3 4	Apr 5, 2022  Apr 5, 2022  Apr 18, 2022  Apr 18, 2022  May 2, 2022  May 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$37,950.00 \$37,950.00 \$1,650.00 (\$1,650.00) \$1,650.00 (\$1,650.00)	Estimate Item Adjustment (0005) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 46.000; Overrun Quantity Balance 2.00.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user bashoa1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user bashoa1 overridding Payment				
			MaterialCredit	- Total	2 3 3 4 4 4	Apr 5, 2022  Apr 5, 2022  Apr 18, 2022  Apr 18, 2022  May 2, 2022  May 17, May 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$37,950.00 \$37,950.00 \$1,650.00 (\$1,650.00) (\$1,650.00) (\$1,650.00) \$1,650.00	Estimate Item Adjustment (0005) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 46.000; Overrun Quantity Balance 2.00.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user bashoa1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user bashoa1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates				
			MaterialCredit	- Total	2 2 3 3 4 4 5	Apr 5, 2022 Apr 5, 2022 Apr 18, 2022 Apr 18, 2022 May 2, 2022 May 17, 2022 May 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$37,950.00 \$37,950.00 \$1,650.00 (\$1,650.00) (\$1,650.00) \$1,650.00 (\$1,650.00)	Estimate Item Adjustment (0005) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 46.000; Overrun Quantity Balance 2.00.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user bashoa1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user bashoa1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 11 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				
			MaterialCredit	- Total	2 2 3 3 4 4 5 5	Apr 5, 2022  Apr 18, 2022  Apr 18, 2022  May 2, 2022  May 17, 2022  May 17, 2022  Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$37,950.00 \$37,950.00 \$1,650.00 (\$1,650.00) (\$1,650.00) \$1,650.00 (\$1,650.00) \$1,650.00	Estimate Item Adjustment (0005) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 46.000; Overrun Quantity Balance 2.00.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user bashoa1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user bashoa1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 17 on the current Payment Estimate Exception 17 on the current Payment Estimate Exception 17 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates				
			MaterialCredit	- Total	2 2 3 3 4 4 5 5	Apr 5, 2022  Apr 18, 2022  Apr 18, 2022  May 2, 2022  May 17, 2022  May 17, 2022  Jun 2, 2022  Jun 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$37,950.00 \$37,950.00 \$1,650.00 (\$1,650.00) (\$1,650.00) (\$1,650.00) (\$1,650.00) (\$1,650.00)	Estimate Item Adjustment (0005) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 46.000; Overrun Quantity Balance 2.00.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user bashoa1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 11 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user bashoa1 overridding Payment Estimate Item Adjustment (0003) due to user bashoa1 overridding Payment Estimate Item Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 17 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J5S3348	0720	ROCK SOCKETS (3 FT 0 IN. DIA.)	Overrun	Overrun					Estimate Exception 18 on the current Payment Estimate.					
		(SFI OIN. DIA.)			8	Jun 30, 2022	SYSTEM	(\$1,650.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
					8	Jun 30, 2022	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user bashoa1 overridding Payment Estimate Exception 21 on the current Payment Estimate.					
					9	Jul 18, 2022	SYSTEM	(\$1,650.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
					9	Jul 18, 2022	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user bashoa1 overridding Payment Estimate Exception 17 on the current Payment Estimate.					
					10	Aug 16, 2022	SYSTEM	(\$1,650.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
					10	Aug 16, 2022	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user bashoa1 overridding Payment Estimate Exception 13 on the current Payment Estimate.					
				Overrun - To	otal			\$0.00	Estimate Exception to on the surrout aymont Estimate.					
			Overrun - Tota					\$0.00						
	0720 -	Total						\$0.00						
	0760	STRUCTURAL STEEL PILES (12	Material		2	Apr 5, 2022	SYSTEM	\$22,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bashoa1 overridding Payment Estimate Exception 7 on the current Payment Estimate.					
		IN			2	Apr 5, 2022	SYSTEM	(\$22,125.00)						
				- Total				\$0.00						
			Material - Tota					\$0.00						
			Overrun	Overrun	2	Apr 5, 2022	SYSTEM	\$1,625.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 177.000; Overrun Quantity Balance 13.00.					
					2	Apr 5, 2022	SYSTEM	(\$1,625.00)						
					3	Apr 18, 2022	SYSTEM	(\$1,625.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
					3	Apr 18, 2022	SYSTEM	\$1,625.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bashoa1 overridding Payment Estimate Exception 13 on the current Payment Estimate.					
					4	May 2, 2022	SYSTEM	(\$1,625.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
					4	May 2, 2022	SYSTEM	\$1,625.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user bashoa1 overridding Payment Estimate Exception 12 on the current Payment Estimate.					
					5	May 17, 2022	SYSTEM	(\$1,625.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
					5	May 17, 2022	SYSTEM	\$1,625.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user bashoa1 overridding Payment Estimate Exception 18 on the current Payment Estimate.					
					6	Jun 2, 2022	SYSTEM	(\$1,625.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
					6	Jun 2, 2022	SYSTEM	\$1,625.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user bashoa1 overridding Payment Estimate Exception 12 on the current Payment Estimate.					
					7	Jun 16, 2022	SYSTEM	(\$1,625.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
										7	Jun 16, 2022	SYSTEM	\$1,625.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user bashoa1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					8	Jun 30, 2022	SYSTEM	(\$1,625.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
									8	Jun 30, 2022	SYSTEM	\$1,625.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user bashoa1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	
					9	Jul 18, 2022	SYSTEM	(\$1,625.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
					9	Jul 18, 2022	SYSTEM	\$1,625.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user bashoa1 overridding Payment Estimate Exception 18 on the current Payment Estimate.					



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
3348	0760	GALVANIZED STRUCTURAL	Overrun	Overrun	10	Aug 16, 2022	SYSTEM	(\$1,625.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
		STEEL PILES (12 IN			10	Aug 16, 2022	SYSTEM	\$1,625.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user bashoa1 overridding Payment Estimate Exception 14 on the current Payment Estimate.												
				Overrun - T	otal			\$0.00													
			Overrun - Tota					\$0.00													
	0760 -	Total						\$0.00													
	0780	CLASS B CONCRETE (SUBSTRUCTURE)	Material		2	Apr 5, 2022	SYSTEM	\$9,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user bashoa1 overridding Payment Estimate Exception 8 on the current Payment Estimate.												
					2	Apr 5, 2022	SYSTEM	(\$9,920.00)													
				- Total				\$0.00													
			Material - Tota	ı				\$0.00													
	0780 -	Total						\$0.00													
	0800	SLAB ON CONCRETE NU- GIRDER	Material		3	Apr 18, 2022	SYSTEM	\$41,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bashoa1 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
					3	Apr 18, 2022	SYSTEM	(\$41,280.00)													
					4	May 2, 2022	SYSTEM	\$103,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bashoa1 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
					4	May 2, 2022	SYSTEM	(\$103,200.00)													
					5	May 17, 2022	SYSTEM	\$60,945.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bashoa1 overridding Payment Estimate Exception 10 on the current Payment Estimate.												
																	5	May 17, 2022	SYSTEM	(\$60,945.60)	
						6	Jun 2, 2022	SYSTEM	\$60,945.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bashoa1 overridding Payment Estimate Exception 4 on the current Payment Estimate.											
							6	Jun 2, 2022	SYSTEM	(\$60,945.60)											
					7	Jun 16, 2022	SYSTEM	\$60,945.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bashoa1 overridding Payment Estimate Exception 10 on the current Payment Estimate.												
					7	Jun 16, 2022	SYSTEM	(\$60,945.60)													
					8	Jun 30, 2022	SYSTEM	\$60,945.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bashoa1 overridding Payment Estimate Exception 11 on the current Payment Estimate.												
					8	Jun 30, 2022	SYSTEM	(\$60,945.60)													
				- Total				\$0.00													
			Material - Tota					\$0.00													
	0800 -	Total						\$0.00													
	0810	NU 35, PRESTRESSED CONC NU-GIRDER	Construction Stockpile		3	Apr 18, 2022	SYSTEM	(\$94,080.21)	Payment Estimate Item Adjustment generated Stockpile Transaction												
		CONO NO-GINDER		- Total				(\$94,080.21)													
			Construction S	Stockpile - To	otal			(\$94,080.21)													
			Construction Stockpile STMI		1	Mar 16, 2022	SYSTEM	\$94,080.21	Payment Estimate Item Adjustment generated Stockpile Transaction												
			O I IVII	- Total				\$94,080.21													
			Construction S	Stockpile STI	/II - Total			\$94,080.21													
	0810 -	Total						\$0.00													
	0820	REINFORCING STEEL (BRIDGES)	Material		2	Apr 5, 2022	SYSTEM	\$11,452.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bashoa1 overridding Payment Estimate Exception 11 on the current Payment Estimate.												
					2	Apr 5, 2022	SYSTEM	(\$11,452.50)													
					3	Apr 18,	SYSTEM	\$18,330.00	This adjustment offsets the original system-generated Material Payment												



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
48	0820	REINFORCING STEEL (BRIDGES)	Material			2022			Estimate Item Adjustment (0010) due to user bashoa1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$18,330.00)	
					4	May 2, 2022	SYSTEM	\$18,330.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bashoa1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$18,330.00)	
					5	May 17, 2022	SYSTEM	\$18,330.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bashoa1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					5	May 17, 2022	SYSTEM	(\$18,330.00)	
					6	Jun 2, 2022	SYSTEM	\$18,330.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bashoa1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Jun 2, 2022	SYSTEM	(\$18,330.00)	
					7	Jun 16, 2022	SYSTEM	\$18,330.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user bashoa1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$18,330.00)	
					8	Jun 30, 2022	SYSTEM	\$18,330.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user bashoa1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					8	Jun 30, 2022	SYSTEM	(\$18,330.00)	
					9	Jul 18, 2022	SYSTEM	\$18,330.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user bashoa1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$18,330.00)	
					10	Aug 16, 2022	SYSTEM	\$18,330.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bashoa1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					10	Aug 16, 2022	SYSTEM	(\$18,330.00)	
				- Total				\$0.00	
	0820 -	Total	Material - Tota					\$0.00 \$0.00	
	0830	SLAB DRAIN	Material		4	May 2, 2022	SYSTEM	\$15,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bashoa1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$15,200.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0830 - 0850	PLAIN NEOPRENE BEARING PAD	Material		3	Apr 18, 2022	SYSTEM	<b>\$0.00</b> <b>\$1,050.00</b>	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user bashoa1 overridding Paymen
		DEARING PAD			3	Apr 18,	SYSTEM	(\$1,050.00)	Estimate item Adjustment (0011) due to user pasnoa1 overridding Paymen Estimate Exception 8 on the current Payment Estimate.
				- Total		2022		\$0.00	
			Material - Tota					\$0.00	
	0850 -	Total						\$0.00	
	0860	LAMINATED NEOPRENE BEARING PAD	Material		3	Apr 18, 2022	SYSTEM	\$2,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bashoa1 overridding Paymen Estimate Exception 9 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$2,280.00)	
				- Total	3		SYSTEM	(\$2,280.00)	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3348	8 0860 - Total							\$0.00	
J5S3348	J5S3348 - Total								
Overall - Total								\$0.00	