

Pay Estimate Created Date: November 3, 2022

t \$57,400.63	original Contract Amount or 1, 2022 Net Change Order Amount Current Contract Amount		Contract ID 220121-D06 Prime Contractor Lehman Constructi	ess Estimate Number 14			
By User		val Date	Approval Date				
linkd1	ed Draft) at the Project Office Level by	Approved (and should be considered	Generated and	er 3, 2022	November 3, 2022		
abbote1	aft) at the Resident Engineer Level by	roved (and should be considered Dra	Reviewed and App	er 3, 2022	November 3, 2022		
ramses1	ntral Office Controllers Office Level by	Reviewed and Approved at the Cer		er 4, 2022	November 4, 2022		
nt Complete	% of Current Contract Amoun	Actual Completion Date	Original Completion Date Current Completion Date				
	23.45%	v 1. 2024 July 1. 2024 23.45%					

	Contract Informational Dates										
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract								
Acceptance Date											
Awarded Date	February 2, 2022	February 2, 2022									
Letting Date	January 21, 2022	January 21, 2022									
Notice to Proceed Date	April 4, 2022	April 4, 2022									
Open to Traffic Date											
Work Began Date											

Contract Total Pa	y For Estimate No. 14				
		This Estimate	Previous	To Date	
220121-D06					
	Total Posted Items Pay	\$996,464.88	\$10,848,082.64	\$11,844,547.52	
	Gross Item Adjustments	(\$124,089.49)	\$1,796,783.39	\$1,672,693.90	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$5,003.32	\$5,003.32	
			\$12,649,869.35	\$13,522,244.74	
Contract Total Pa	yable This Estimate:	\$872,375.39			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5I3397	0800	2153000	SHAPING SLOPES, CLASS III	100F	\$900.000	0.8	\$720.00
	0140	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	TONS	\$95.600	1,802	\$172,271.20
	0150	4071005	TACK COAT	GAL	\$2.050	1,614	\$3,308.70
	0180	5062030A	FURNISHING UNBONDED CONCRETE OVERLAY	CUYD	\$125.000	1,406.5	\$175,812.50
	0190	5062033	UNBONDED CONCRETE OVERLAY INTERLAYER	SQYD	\$3.000	8,138.4	\$24,415.20
	0200	5069905	MISC.UNBONDED CONCRETE OVERLAY	SQYD	\$8.000	8,766.5	\$70,132.00
	0300	6122030	IMPACT ATTENUATOR (RELOCATION)	EA	\$1,000.000	2	\$2,000.00
	0400	6161005	CONSTRUCTION SIGNS	SQFT	\$4.500	308	\$1,386.00
	0470	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	EA	\$400.000	4	\$1,600.00
	0510 6173600D TEMPORARY TRAFFIC BARRIER, CON- RETAINED		TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	LF	\$18.500	1,862.5	\$34,456.25
	0520	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	LF	\$41.000	5,687.5	\$233,187.50
	0580	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.500	5,510	\$2,755.00
	0590	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.500	2,005	\$1,002.50
	0630	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$1.400	16,558	\$23,181.20
	0890	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	LF	\$33.910	437.5	\$14,835.63
	0930	6061080	MGS END ANCHOR	EA	\$1,100.000	1	\$1,100.00
	0940	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$3,200.000	1	\$3,200.00

Revision 4/1/2020 Page 1 of 51



Pay Estimate Created Date: November 3, 2022

			•	,	Original Contract Amount	. , ,
1.1	Prime Contractor	Lehman Construction, LLC	Pay Period End	November 1, 2022	Net Change Order Amount	\$57,400.63
14					Current Contract Amount	\$50,509,988.94

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
Project J5I	oject J5l3397 - Total								
J5I3572	1690	2079909	MISC.MODIFIED LINEAR GRADING CLASS 2	STA	\$600.000	20	\$12,000.00		
	2300	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$6.000	7,661	\$45,966.00		
	2310	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	SQYD	\$56.000	3,091.7	\$173,135.20		
Project J5I	3572 - Tota	al					\$231,101.20		
Overall - To	otal						\$996,464.88		

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

oject mber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3397	0140	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Other Item Adjustment	Asphalt Cement Price Adjustment	1802 tons I DIFF 252.5 6.2% VAC +\$28,210.31			\$28,210.31
	0150	TACK COAT	Material			-1,614	\$2.05	(\$3,308.70
	0150	TACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1,614	\$2.05	\$3,308.70
	0180	FURNISHING UNBONDED CONCRETE OVERLAY	Overrun			-748.1	\$125.00	(\$93,512.50
	0180	FURNISHING UNBONDED CONCRETE OVERLAY	Material			-10,195.1	\$125.00	(\$1,274,387.50
	0180	FURNISHING UNBONDED CONCRETE OVERLAY	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	10,195.1	\$125.00	\$1,274,387.50
0	0190	UNBONDED CONCRETE OVERLAY INTERLAYER	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$632.73
	0190	UNBONDED CONCRETE OVERLAY INTERLAYER	Overrun			-1,960	\$3.00	(\$5,880.00
	0190	UNBONDED CONCRETE OVERLAY INTERLAYER	Overrun			-1,212.9	\$3.00	(\$3,638.70
	0200	MISC.	Overrun			-1,960	\$8.00	(\$15,680.00
	0200	MISC.	Overrun			-1,773.3	\$8.00	(\$14,186.40
	0200	MISC.	Overrun			-67.7	\$8.00	(\$541.60
	0200	MISC.	Other Item Adjustment	Fuel Price	8766.5 SY CI 3.38 I DIFF +0.99 +\$5,207.30			\$5,207.30
	0320	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-565.3	\$274.00	(\$154,892.20
	0320	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	565.3	\$274.00	\$154,892.20
	0360	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL	Material			-542	\$11.25	(\$6,097.50

Revision 4/1/2020 Page 2 of 51



Pay Estimate Created Date: November 3, 2022

Progress Estimate Number	Contract ID	220121-D06		Pay Period Start	October 16, 2022	Original Contract Amount	\$50,452,588.31
1.4	Prime Contractor	Lehman Construction,	LLC	Pay Period End	November 1, 2022	Net Change Order Amount	\$57,400.63
14						Current Contract Amount	\$50,509,988.94

ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
397		DEPTH PAVEMENT REPAIR						
	0360	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user linkd1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	542	\$11.25	\$6,097.50
	0370	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material			-254	\$9.75	(\$2,476.50)
	0370	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user linkd1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	254	\$9.75	\$2,476.50
	0510	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material			-3,112.5	\$18.50	(\$57,581.25)
	0510	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user linkd1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	3,112.5	\$18.50	\$57,581.25
	0520	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	Material			-31,200	\$41.00	(\$1,279,200.00)
	0520	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0031) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	31,200	\$41.00	\$1,279,200.00
	0550	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-4,749	\$0.22	(\$1,044.78)
	0550	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user linkd1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	4,749	\$0.22	\$1,044.78
	0560	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-6,300	\$0.22	(\$1,386.00)
	0560	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user linkd1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	6,300	\$0.22	\$1,386.00
	0580	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-30,220	\$0.50	(\$15,110.00)
	0580	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0034) due to user linkd1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	30,220	\$0.50	\$15,110.00
	0590	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material			-33,875	\$0.50	(\$16,937.50)

Revision 4/1/2020 Page 3 of 51



Pay Estimate Created Date: November 3, 2022

Progress Estimate Number
14 Contract ID 220121-D06 Pay Period Start October 16, 2022 Original Contract Amount \$50,452,588.31
Pay Period End November 1, 2022 Net Change Order Amount \$57,400.63
Current Contract Amount \$50,509,988.94

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5I3397		BEADS						
	0590	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0035) due to user linkd1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	33,875	\$0.50	\$16,937.50
	0890	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$9,256.81)
	0920	MGS VERTICAL CONCRETE BARRIER TRANSITION	Material			-4	\$3,350.00	(\$13,400.00)
	0920	MGS VERTICAL CONCRETE BARRIER TRANSITION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0037) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	4	\$3,350.00	\$13,400.00
	0930	MGS END ANCHOR	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$543.10)
	0940	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$2,066.22)
	5002	ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS	Material			-4	\$483.00	(\$1,932.00)
	5002	ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0040) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	4	\$483.00	\$1,932.00
	5003	MGS HEIGHT AND BLOCK TRANSITION	Material			-4	\$850.50	(\$3,402.00)
	5003	MGS HEIGHT AND BLOCK TRANSITION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0041) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	4	\$850.50	\$3,402.00
J5I3482	1590	OPTIONAL CONCRETE WEARING SURFACE	Material			-78.5	\$200.00	(\$15,700.00)
	1590	OPTIONAL CONCRETE WEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	78.5	\$200.00	\$15,700.00
	1610	HALF-SOLE REPAIR	Material			-32	\$100.00	(\$3,200.00)
	1610	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	32	\$100.00	\$3,200.00
J5l3572	1960	PAVEMENT EDGE TREATMENT	Material			-44,156	\$5.00	(\$220,780.00)
	1960	PAVEMENT EDGE TREATMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	44,156	\$5.00	\$220,780.00
	2000	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-56,719	\$0.40	(\$22,687.60)
	2000	4 IN. WHITE STANDARD	Material		This adjustment offsets the original system-	56,719	\$0.40	\$22,687.60



Pay Estimate Created Date: November 3, 2022

Progress Estimate Number
14 Contract ID 220121-D06 Pay Period Start October 16, 2022 Original Contract Amount \$50,452,588.31
Pay Period End November 1, 2022 Net Change Order Amount \$57,400.63
Current Contract Amount \$50,509,988.94

	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
'2		WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS			generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 28 on the current Payment Estimate.			
2	2010	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-45,460	\$0.40	(\$18,184.00
	2010	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	45,460	\$0.40	\$18,184.00
2	2140	SEEDING - COOL SEASON GRASSES	Material			-14.2	\$2,350.00	(\$33,370.00
2	2140	SEEDING - COOL SEASON GRASSES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	14.2	\$2,350.00	\$33,370.00
2	2170	ROCK DITCH CHECK	Material			-27	\$11.00	(\$297.00
2	2170	ROCK DITCH CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 39 on the current Payment Estimate.	27	\$11.00	\$297.00
2	2180	CURB INLET CHECK	Material			-42	\$145.00	(\$6,090.00
2	2180	CURB INLET CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 40 on the current Payment Estimate.	42	\$145.00	\$6,090.00
2	2300	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,672.2	\$0.15	\$248.32
2	2300	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	2,644.4	\$0.15	\$392.69
2	2300	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	3,344.4	\$0.15	\$496.64
1	2300	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Material			-67,176.9	\$6.00	(\$403,061.40
2	2300	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	67,176.9	\$6.00	\$403,061.40
	2310	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,750	\$0.59	\$1,039.50
	2310	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,341.7	\$0.59	\$796.97
2	2310	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$607.02
2	2310	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$13,936.14
2	2310	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Material			-49,425.6	\$56.00	(\$2,767,833.60

Revision 4/1/2020 Page 5 of 51



Pay Estimate Created Date: November 3, 2022

Progress Estimate Number 14 Contract ID 220121-D06 Prime Contractor Lehman Construction						Pay Period Start October 16, 2022 Ori n, LLC Pay Period End November 1, 2022 Ne Cu		der Amount	
Project Number	Line No.	Item Desci	ription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5l3572	2310	CONCRETE PA		Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		\$56.00	\$2,767,833.60
Total									(\$124,089.49)

Revision 4/1/2020 Page 6 of 51



					(Contract Project Information							
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work						
J5I3397	I-44-3(208)	Coldmill, Resurface, Replace WBL Shoulder	1-44	PHELPS	from Sugartree Road in	nterchange to east of Route F	interchange						
J5l3482	I 44-2(330)	2 Bridge rehabilitations and culvert extension	I-44	PHELPS	over Bourbouse River	over Bourbouse River Branch and over East Fork Little Beaver Creek							
J5l3572	I 44-2(332)	Reconstruction of pavement	I-44	PHELPS	on east bound lanes of	f I-44 from Rolla to St. James							
otals by	Job Number	S											
J5l3397		ve	s G <mark>ross Ite</mark>	m Pay	This Estimate \$765,363.68 (\$112,520.45) \$652,843.23 \$0.00 \$0.00	Previous \$6,532,819.75 \$307,095.04 \$6,839,914.79 \$0.00 \$0.00	To Date \$7,298,183,43 \$194,574.59 \$7,492,758.02 \$0.00 \$0.00						
		ited Damages Contract Adjustm	ents		\$0.00 \$0.00	\$0.00 \$1,894.76	\$0.00 \$1,894.76						
J5I3482		Item Pay tem Adjustments	s Gross Ite	m Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$62,757.73 \$21,937.56 \$84,695.29	To Date \$62,757.73 \$21,937.56 \$84,695.29						
			ients		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$62.04	\$0.00 \$0.00 \$0.00 \$62.04						
J5l3572		Item Pay tem Adjustments	s Gross Ite	m Pay	This Estimate \$231,101.20 (\$11,569.04) \$219,532.16	Previous \$4,252,505.16 \$1,467,750.79 \$5,720,255.95	To Date \$4,483,606.36 \$1,456,181.75 \$5,939,788.11						
			nents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$3,046.52	\$0.00 \$0.00 \$0.00 \$3,046.52						

Revision 4/1/2020 Page 7 of 51



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
		,	
Estimate Exception Type: Insufficient Materials: Project J513572, Item 3040143, Project Item Line Number 2300, Material Set 304014396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3572, Item 3040143, Project Item Line Number 2300, Material Set 304014396, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3397, Item 4071005, Project Item Line Number 0150, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J513572, Item 5021308, Project Item Line Number 2310, Material Set 502130896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J513572, Item 5021308, Project Item Line Number 2310, Material Set 502130896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J513572, Item 5021308, Project Item Line Number 2310, Material Set 502130896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3482, Item 5050001, Project Item Line Number 1590, Material Set 505000196, Material 1005GECMLSBD - Bridge Wearing Surface Grade E LS/DO, Acceptance Action Generic 1005GECMLSBD is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3397, Item 5062030A, Project Item Line Number 0180, Material Set 5062030A96, Material 100510.CPCMLD - PCCP or Masonry 1" Max LS/DC Acceptance Action Generic 100510.CPCMLD is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3397, Item 5062030A, Project Item Line Number 0180, Material Set 5062030A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mi or QCQA, Acceptance Action 0501CCPAQCQA Overlay is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3397, Item 5062030A, Project Item Line Number 0180, Material Set 5062030A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3397, Item 6061070, Project Item Line Number 0920, Material Set 606107096, Material 1040GRAB - Bridge Anchor Section, Acceptance Actic Generic 1040GRAB is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3397, Item 6061074, Project Item Line Number 5003, Material Set 606107496, Material 1040GRTS - Transition Section, Acceptance Action Generic 1040GRTS is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3397, Item 6062303, Project Item Line Number 5002, Material Set 606230396, Material 1040GRTS - Transition Section, Acceptance Action Generic 1040GRTS is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3397, Item 6131010, Project Item Line Number 0320, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3397, Item 6131010, Project Item Line Number 0320, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3397, Item 6131010, Project Item Line Number 0320, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3397, Item 6131015, Project Item Line Number 0360, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3397, Item 6131015, Project Item Line Number 0360, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3397, Item 6131017, Project Item Line Number 0370, Material Set 613101796, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J513397, Item 6131017, Project Item Line Number 0370, Material Set 613101796, Material 1057JMDBEC6.11 - Dowel Bar Epoxy Ctd Gr60 1 1/4 @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J513397, Item 6173600D, Project Item Line Number 0510, Material Set 6173600D96, Material 0617TCRCTF - Type F Concrete Traffic Barrier, Acceptance Action Generic 0617TCRCTF is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J513397, Item 6173700B, Project Item Line Number 0520, Material Set 6173700B96, Material 0617TCRCTF - Type F Concrete Traffic Barrier, Acceptance Action Generic 0617TCRCTF is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J513572, Item 6191000, Project Item Line Number 1960, Material Set 619100096, Material 0619PET - Material for Pavement Edge Treatment, Acceptance Action Generic 0619PET is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3397, Item 6205902A, Project Item Line Number 0550, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L	Waiting on QC/QA	linkd1	Overridden

Revision 4/1/2020 Page 8 of 51



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J5I3397, Item 6205902A, Project Item Line Number 0550, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3397, Item 6205903A, Project Item Line Number 0560, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3397, Item 6205903A, Project Item Line Number 0560, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3572, Item 6206000C, Project Item Line Number 2000, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3572, Item 6206000C, Project Item Line Number 2000, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3397, Item 6206000C, Project Item Line Number 0580, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3397, Item 6206000C, Project Item Line Number 0580, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3572, Item 6206001C, Project Item Line Number 2010, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3572, Item 6206001C, Project Item Line Number 2010, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3397, Item 6206001C, Project Item Line Number 0590, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3397, Item 6206001C, Project Item Line Number 0590, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5i3482, Item 7040104, Project Item Line Number 1610, Material Set 704010496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3572, Item 8051000A, Project Item Line Number 2140, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3572, Item 8051000A, Project Item Line Number 2140, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3572, Item 8061005, Project Item Line Number 2170, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3572, Item 8061007A, Project Item Line Number 2180, Material Set 8061007A96, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Waiting on QC/QA	linkd1	Overridden
Estimate Exception Type: Item Overrun: Contract 220121-D06, Contract Project J5I3482, Project Item Line Number 1140, Contract Line Item Number 1140, Item 6161005, Minor Item.	Waiting on CO	linkd1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220121-D06, Contract Project J5I3482, Project Item Line Number 1510, Contract Line Item Number 1510, Item 7031004, Minor Item.	Waiting on CO	linkd1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220121-D06, Contract Project J5I3397, Project Item Line Number 0350, Contract Line Item Number 0350, Item 6131014, Minor Item.	Waiting on CO	linkd1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220121-D06, Contract Project J5I3397, Project Item Line Number 5004, Contract Line Item Number 5004, Item 6061063, Minor Item.	Waiting on CO	linkd1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220121-D06, Contract Project J5I3397, Project Item Line Number 0190, Contract Line Item Number 0190, Item 5062033, Minor Item.	Waiting on CO	linkd1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220121-D06, Contract Project J5I3397, Project Item Line Number 0180, Contract Line Item Number 0180, Item 5062030A, Minor Item.	Waiting on CO	linkd1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220121-D06, Contract Project J5l3397, Project Item Line Number 0200, Contract Line Item Number 0200, Item 5069905, Minor Item.	Waiting on CO	linkd1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220121-D06, Contract Project J5l3572, Project Item Line Number 2180, Contract Line Item Number 2180, Item 8061007A, Minor Item.	Waiting on CO	linkd1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220121-D06, Contract Project J5l3397, Project Item Line Number 0320, Contract Line Item Number 0320, Item 6131010, Minor Item.	Waiting on CO	linkd1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220121-D06, Contract Project J5l3397, Project Item Line Number 0370, Contract Line Item Number 0370, Item 6131017, Minor Item.	Waiting on CO	linkd1	Acknowledged

Revision 4/1/2020 Page 9 of 51



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Item Overrun: Contract 220121-D06, Contract Project J5I3397, Project Item Line Number 5002, Contract Line Item Number 5002, Item 6062303, Minor Item.	Waiting on CO	linkd1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220121-D06, Contract Project J5I3397, Project Item Line Number 5003, Contract Line Item Number 5003, Item 6061074, Minor Item.	Waiting on CO	linkd1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220121-D06, Contract Project J5I3572, Project Item Line Number 1840, Contract Line Item Number 1840, Item 6161008, Minor Item.	Waiting on CO	linkd1	Acknowledged

Revision 4/1/2020 Page 10 of 51



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT		Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-D06	J5I3397	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$1,480,000.00	\$1,332,000.00
		0001	0020	2035000	UNCLASSIFIED EXCAVATION	14,503.00	0.00	14,503.00	CUYD	0.00	\$13.00	\$0.00
		0001	0030	2036000	COMPACTING EMBANKMENT	1,222.00	0.00	1,222.00	CUYD	0.00	\$4.00	\$0.00
		0001	0040	2063100	CLASS 3 EXCAVATION IN ROCK	30.00	0.00	30.00	CUYD	0.00	\$60.00	\$0.00
		0001	0050	2079909	MISC.MODIFIED LINEAR GRADING CLASS 2	30.00	0.00	30.00	STA	0.00	\$900.00	\$0.00
		0001	0060	2142000	FURNISHING ROCK FILL	15,779.00	0.00	15,779.00	CUYD	0.00	\$35.00	\$0.00
		0001	0070	2143000	PLACING ROCK FILL	15,779.00	0.00	15,779.00	CUYD	0.00	\$15.00	\$0.00
		0001	0080	2153000	SHAPING SLOPES, CLASS III	32.00	0.00	32.00	100F	18.80	\$900.00	\$16,920.00
		0001	0090	3040183	TYPE 1 AGGREGATE FOR BASE (8 IN. THICK)	2,478.00	0.00	2,478.00	SQYD	0.00	\$9.00	\$0.00
		0001	0100	3105002	GRAVEL (A) OR CRUSHED STONE (B)	1,160.00	0.00	1,160.00	TONS	0.00	\$32.00	\$0.00
		0001	0110	4010150	TYPE A2 SHOULDER	2,126.00	0.00	2,126.00	SQYD	0.00	\$26.25	\$0.00
		0001	0120	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	10,913.90	0.00	10,913.90	TONS	0.00	\$65.25	\$0.00
		0001	0130	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	537.00	0.00	537.00	TONS	0.00	\$83.00	\$0.00
		0001	0140	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	67,415.10	0.00	67,415.10	TONS	1,802.00	\$95.60	\$172,271.20
		0001	0150	4071005	TACK COAT	74,090.00	0.00	74,090.00	GAL	1,614.00	\$2.05	\$3,308.70
		0001	0160	4133200	ULTRATHIN BONDED WEARING SURFACE, TYPE C	21,358.00	0.00	21,358.00	SQYD	0.00	\$5.50	\$0.00
		0001	0170	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)	353.00	0.00	353.00	SQYD	0.00	\$65.00	\$0.00
		0001	0180	5062030A	FURNISHING UNBONDED CONCRETE OVERLAY	9,447.00	0.00	9,447.00	CUYD	10,195.10	\$125.00	\$1,274,387.50
		0001	0190	5062033	UNBONDED CONCRETE OVERLAY INTERLAYER	42,508.00	0.00	42,508.00	SQYD	45,680.90	\$3.00	\$137,042.70
		0001	0200	5069905	MISC.UNBONDED CONCRETE OVERLAY	42,508.00	0.00	42,508.00	SQYD	46,309.00	\$8.00	\$370,472.00
		0001	0210	6042020	ADJUSTING BASIN OR INLET	1.00	0.00	1.00	EA	0.00	\$3,000.00	\$0.00
		0001	0220	6044011	PIPE COLLAR, TYPE A	5.00	0.00	5.00	EA	0.00	\$2,000.00	\$0.00
		0001	0230	6059909	MISC.GUARDRAIL BLOCKOUT REPAIR/REPLACEMENT	15.00	0.00	15.00	STA	0.00	\$851.00	\$0.00
		0001	0240	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	151.00	0.00	151.00	CUYD	0.00	\$60.00	\$0.00
		0001	0250	6096041	PLACING TYPE 1 ROCK DITCH LINER	151.00	0.00	151.00	CUYD	0.00	\$30.00	\$0.00
		0001	0260	6113010	FURNISHING TYPE 1 ROCK BLANKET	163.00	0.00	163.00	CUYD	0.00	\$60.00	\$0.00
		0001	0270	6113030	PLACING TYPE 1 ROCK BLANKET	163.00	0.00	163.00	CUYD	0.00	\$30.00	\$0.00
		0001	0280	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	4.00	0.00	4.00	EA	2.00	\$2,500.00	\$5,000.00
		0001	0290	6122020	REPLACEMENT SAND BARREL	60.00	0.00	60.00	EA	0.00	\$250.00	\$0.00
		0001	0300	6122030	IMPACT ATTENUATOR (RELOCATION)	11.00	0.00	11.00	EA	6.00	\$1,000.00	\$6,000.00
		0001	0310	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	1.00	\$1,150.00	\$1,150.00
		0001	0320	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	561.00	0.00	561.00	SQYD	565.30	\$274.00	\$154,892.20
		0001	0330	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	56.00	0.00	56.00	SQYD	0.00	\$10.00	\$0.00
		0001	0340	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	56.00	0.00	56.00	SQYD	0.00	\$10.00	\$0.00
		0001	0350	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	2,028.00	0.00	2,028.00	LF	2,148.00	\$12.75	\$27,387.00
		0001	0360	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	1,242.00	0.00	1,242.00	EA	542.00	\$11.25	\$6,097.50
		0001	0370	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	120.00	0.00	120.00	EA	254.00	\$9.75	\$2,476.50
		0001	0380	6139911	MISC.CLASS A PARTIAL DEPTH CONCRETE PAVEMENT REPAIR USING FLEXIBLE, HOT POLYMER MODIFIED REPAIR MATERIAL	9,120.00	0.00	9,120.00	LB	0.00	\$3.66	\$0.00
		0001	0390	6141022	GRATE AND BEARING PLATE (3 FT. X 3 FT. OR 914 MM X 914 MM)	3.00	0.00	3.00	EA	0.00	\$1,903.00	\$0.00
		0001	0400	6161005	CONSTRUCTION SIGNS	8,427.00	0.00	8,427.00	SQFT	2,623.00	\$4.50	\$11,803.50
		0001	0410	6161008	ADVANCED WARNING RAIL SYSTEM	40.00	0.00	40.00	EA	14.00	\$25.00	\$350.00
		0001	0420	6161025	CHANNELIZER (TRIM LINE)	1,000.00	0.00	1,000.00	EA	280.00	\$20.00	\$5,600.00
		0001	0430	6161033	DIRECTIONAL INDICATOR BARRICADE	140.00	0.00	140.00	EA	70.00	\$25.00	\$1,750.00
		0001	0440	6161040	FLASHING ARROW PANEL	16.00	0.00	16.00	EA	3.00	\$500.00	\$1,500.00

Page 11 of 51 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
20121-D06	J5I3397	0001	0450	6161095	RADAR SPEED ADVISORY SYSTEM	4.00	0.00	4.00	EA	0.00	\$4,000.00	\$0.00
		0001	0460	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	12.00	0.00	12.00	EA	5.00	\$2,600.00	\$13,000.00
		0001	0470	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	52.00	0.00	52.00	EA	28.00	\$400.00	\$11,200.00
		0001	0480	6169901	MISC.TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING	1.00	0.00	1.00	LS	0.00	\$32,770.00	\$0.0
		0001	0490	6169901	MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	1.00	0.00	1.00	LS	0.80	\$85,000.00	\$68,000.0
		0001	0500	6173103	CONCRETE TRAFFIC BARRIER, TYPE D (MOMENT SLAB)	280.00	0.00	280.00	LF	30.00	\$290.00	\$8,700.00
		0001	0510	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	3,875.00	0.00	3,875.00	LF	3,112.50	\$18.50	\$57,581.2
		0001	0520	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	33,753.00	0.00	33,753.00	LF	31,200.00	\$41.00	\$1,279,200.00
		0001	0530	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$1,650,800.00	\$0.0
		0001	0531	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.75	\$1,466,516.00	\$1,099,887.0
		0001	0540	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	2.00	0.00	2.00	EA	0.00	\$600.00	\$0.0
		0001	0550	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	310,128.00	0.00	310,128.00	LF	4,749.00	\$0.22	\$1,044.7
		0001	0560	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	253,558.00	0.00	253,558.00	LF	6,300.00	\$0.22	\$1,386.0
		0001	0570	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	9,799.00	0.00	9,799.00	LF	0.00	\$0.65	\$0.0
		0001	0580	6206000C		36,240.00	0.00	36,240.00	LF	30,220.00	\$0.50	\$15,110.0
		0001	0590	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	35,400.00	0.00	35,400.00	LF	33,875.00	\$0.50	\$16,937.5
		0001	0600	6207001	PAVEMENT MARKING REMOVAL	78,760.00	0.00	78,760.00	LF	27,730.00	\$0.50	\$13,865.0
		0001	0610	6209903	MISC.13" PAVEMENT MARKING GROOVE, 100 MILS DEPTH	1,421.00	0.00	1,421.00	LF	0.00	\$1.00	\$0.0
		0001	0620	6209903	MISC.7" PAVEMENT MARKING GROOVE, 100 MILS DEPTH	110,940.00	0.00	110,940.00	LF	0.00	\$0.50	\$0.0
		0001	0630	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	751,830.00	0.00	751,830.00	SQYD	16,558.00	\$1.40	\$23,181.2
		0001	0640	6240104A	SEPARATION GEOTEXTILE	4,660.00	0.00	4,660.00	SQYD	0.00	\$5.00	\$0.0
		0001	0650	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	3,410.00	0.00	3,410.00	STA	0.00	\$8.75	\$0.0
		0001	0660	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$83,820.00	\$0.0
		0001	0670	7261015	15 IN. PIPE GROUP A	32.00	0.00	32.00	LF	0.00	\$56.00	\$0.0
		0001	0680	7261018	18 IN. PIPE GROUP A	21.00	0.00	21.00	LF	0.00	\$60.00	\$0.0
		0001	0690	7311033	PRECAST CONCRETE DROP INLET 3 FT X 3 FT	8.00	0.00	8.00	FT	0.00	\$850.00	\$0.0
		0001	0700	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	10.00	0.00	10.00	FT	0.00	\$680.00	\$0.0
		0001	0710	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$900.00	\$0.0
		0001	0720	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$925.00	\$0.0
		0001	0730	8051000A	SEEDING - COOL SEASON GRASSES	4.00	0.00	4.00	ACRE	0.00	\$2,350.00	\$0.0
		0001	0740	8061003	SEDIMENT TRAP EXCAVATION	26.00	0.00	26.00	CUYD	0.00	\$35.00	\$0.0
		0001	0750	8061004	SEDIMENT TRAP ROCK	35.00	0.00	35.00	CUYD	0.00	\$50.00	\$0.0
		0001	0760	8061005	ROCK DITCH CHECK	17.00	0.00	17.00	LF	0.00	\$11.00	\$0.0
		0001	0770	8061006	ALTERNATE DITCH CHECK	1,440.00	0.00	1,440.00	LF	0.00	\$9.50	\$0.0
		0001	0780	8061007A	CURB INLET CHECK	2.00	0.00	2.00	EA	0.00	\$145.00	\$0.0
		0001	0790	8061016	SEDIMENT REMOVAL	263.00	0.00	263.00	CUYD	0.00	\$15.00	\$0.0
		0001	0800	8061017	TEMPORARY SEEDING	2.00	0.00	2.00	ACRE	0.00	\$1,950.00	\$0.0
		0001	0810	8061019	SILT FENCE	3,885.00	0.00	3,885.00	LF	0.00	\$2.20	\$0.0
		0002	0820	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	13,651.00	0.00	13,651.00	SQYD	0.00	\$8.00	\$0.0
		0002	0830	4030403	10 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125C	13,651.00	0.00	13,651.00	SQYD	0.00	\$40.00	\$0.0
		0002	0840	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	308.00	0.00	308.00	STA	0.00	\$8.75	\$0.0
		0010	0880	6061060	MGS GUARDRAIL	15,063.00	0.00	15,063.00	LF	6,326.50	\$31.57	\$199,727.6
		0010	0890	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	19,116.00	0.00	19,116.00	LF	18,587.50	\$33.91	\$630,302.1
		0010	0900	6061067	MGS DOUBLE FACED GUARDRAIL	50.00	0.00	50.00	LF	0.00	\$51.34	\$0.00

Revision 4/1/2020 Page 12 of 51



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Po	osted Quantities and	d Values are based on Report	Generated date and	can differ from the posted amoun	t at the time the Estimate was Generated.

Contract		Category	Line	Item	Report Generated date and can differ from the posted am Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTED
Nm.CONTRACT	No.	oategory	No.	Code	Besoription	Quantity	Change Order	Current Quantity	Onit	Posted Approved Qty	Office floor	To Date (See report generated date)
220121-D06	J5l3397	0010	0910	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	8.00	0.00	8.00	EA	1.00	\$3,400.00	\$3,400.00
		0010	0920	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	4.00	0.00	4.00	EA	4.00	\$3,350.00	\$13,400.00
		0010	0930	6061080	MGS END ANCHOR	34.00	0.00	34.00	EA	23.00	\$1,100.00	\$25,300.00
		0010	0940	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	42.00	0.00	42.00	EA	27.00	\$3,200.00	\$86,400.00
		0010	0950	6063016	TYPE B CRASHWORTHY END TERMINAL	2.00	0.00	2.00	EA	0.00	\$5,531.00	\$0.00
		0030	0960	9028500	CABLE, LOOP DETECTOR, IN DUCT	220.00	0.00	220.00	LF	0.00	\$12.65	\$0.00
		0030	0970	9028510	CABLE, LOOP DETECTOR, LEAD-IN	30.00	0.00	30.00	LF	0.00	\$1.50	\$0.00
		0040	0980	9031010	CONCRETE FOOTINGS, EMBEDDED	4.40	0.00	4.40	CUYD	0.00	\$623.00	\$0.00
		0040	0990	9031210	STRUCTURAL STEEL POSTS	3,140.00	0.00	3,140.00	LB	0.00	\$7.10	\$0.00
		0040	1000	9031270A	2 IN. PSST POST - 12 GA.	80.00	0.00	80.00	LF	0.00	\$16.95	\$0.00
		0040	1010	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	15.00	0.00	15.00	LF	0.00	\$29.68	\$0.00
		0001	5001	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$184,284.00	\$184,284.00
		0010	5002	6062303	ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS	0.00	2.00	2.00	EA	4.00	\$483.00	\$1,932.00
		0010	5003	6061074	MGS HEIGHT AND BLOCK TRANSITION	0.00	2.00	2.00	EA	4.00	\$850.50	\$3,402.00
		0010	5004	6061063	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	0.00	50.00	50.00	LF	75.00	\$68.48	\$5,136.00
		0010	5005	6061065	MGS GUARDRAIL, 6 FT. POSTS, 1 FT 6.75 IN. SPACING	0.00	62.50	62.50	LF	62.50	\$86.37	\$5,398.12
		0010	5006	6069903		0.00	2,550.00	2,550.00	LF	0.00	\$17.17	\$0.00
	Project J	513397 - To	otal Value	Posted to D	Date as of Report Generated Date							\$7,298,183.38
	J5I3482	0001	1020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.25	\$8,000.00	\$2,000.00
		0001	1030	2035500	EMBANKMENT IN PLACE	210.00	0.00	210.00	CUYD	0.00	\$23.00	\$0.00
		0001	1040	2036000	COMPACTING EMBANKMENT	180.00	0.00	180.00	CUYD	0.00	\$8.00	\$0.00
		0001	1050	2079909	MISC.MODIFIED LINEAR GRADING CLASS 2	1.00	0.00	1.00	STA	0.00	\$3,000.00	\$0.00
		0001	1060	2153000	SHAPING SLOPES, CLASS III	1.00	0.00	1.00	100F	0.00	\$3,000.00	\$0.00
		0001	1070	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	32.00	0.00	32.00	CUYD	0.00	\$30.00	\$0.00
		0001	1080	6096041	PLACING TYPE 1 ROCK DITCH LINER	32.00	0.00	32.00	CUYD	0.00	\$28.00	\$0.00
		0001	1090	6113020	FURNISHING TYPE 2 ROCK BLANKET	106.00	0.00	106.00	CUYD	0.00	\$32.00	\$0.00
		0001	1100	6113040	PLACING TYPE 2 ROCK BLANKET	106.00	0.00	106.00	CUYD	0.00	\$28.00	\$0.00
		0001	1110	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	1.00	0.00	1.00	EA	0.00	\$2,500.00	\$0.00
		0001	1120	6122020	REPLACEMENT SAND BARREL	10.00	0.00	10.00	EA	0.00	\$250.00	\$0.00
		0001	1130	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0.00
		0001	1140	6161005	CONSTRUCTION SIGNS	112.00	0.00	112.00	SQFT	308.00	\$4.50	\$1,386.00
		0001	1150	6161008	ADVANCED WARNING RAIL SYSTEM	6.00	0.00	6.00	EA	6.00	\$25.00	\$150.00
		0001	1160	6161010	RELOCATED SIGNS	16.00	0.00	16.00	SQFT	0.00	\$6.00	\$0.00
		0001	1170	6161025	CHANNELIZER (TRIM LINE)	200.00	0.00	200.00	EA	200.00	\$4.00	\$800.00
		0001	1180	6161033	DIRECTIONAL INDICATOR BARRICADE	14.00	0.00	14.00	EA	14.00	\$20.00	\$280.00
		0001	1190	6161040	FLASHING ARROW PANEL	1.00	0.00	1.00	EA	1.00	\$25.00	\$25.00
		0001	1200	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	8.00	0.00	8.00	EA	4.00	\$400.00	\$1,600.00
		0001	1210	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	3.00	0.00	3.00	EA	0.00	\$1,200.00	\$0.00
		0001	1220	6169901	MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	1.00	0.00	1.00	LS	0.80	\$1,000.00	\$800.00
		0001	1230	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	800.00	0.00	800.00	LF	0.00	\$18.50	\$0.00
		0001	1240	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	800.00	0.00	800.00	LF	0.00	\$7.00	\$0.00
		0001	1250	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.25	\$125,000.00	\$31,250.00
		0001	1260	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	2.00	0.00	2.00	EA	0.00	\$600.00	\$0.00
		0001	1270	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	3,310.00	0.00	3,310.00	LF	0.00	\$1.00	\$0.00
		0001	1280	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,650.00	0.00	2,650.00	LF	0.00	\$1.00	\$0.00
		0001	1290	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	4,630.00	0.00	4,630.00	LF	0.00	\$1.00	\$0.00
Di-i 4/4/000	_											

Revision 4/1/2020 Page 13 of 51



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ract Proj TRACT No	ject	Category	Line No.	Item Code	Report Generated date and can differ from the posted ar Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
006 J5I3	482				PAINT, TYPE P BEADS					,		
		0001	1300	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	4,630.00	0.00	4,630.00	LF	0.00	\$1.00	\$0.00
		0001	1310	6207001	PAVEMENT MARKING REMOVAL	4,900.00	0.00	4,900.00	LF	0.00	\$1.00	\$0.00
		0001	1320	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,817.00	0.00	1,817.00	SQYD	0.00	\$5.20	\$0.00
		0001	1330	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$25,000.00	\$0.00
		0001	1340	8051000A	SEEDING - COOL SEASON GRASSES	0.60	0.00	0.60	ACRE	0.00	\$6,750.00	\$0.00
		0001	1350	8061016	SEDIMENT REMOVAL	4.00	0.00	4.00	CUYD	0.00	\$10.00	\$0.00
		0001	1360	8061019	SILT FENCE	330.00	0.00	330.00	LF	0.00	\$2.20	\$0.00
		0010	1370	6061060	MGS GUARDRAIL	813.00	0.00	813.00	LF	0.00	\$34.48	\$0.00
		0010	1380	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	2.00	0.00	2.00	EA	0.00	\$3,600.00	\$0.00
		0010	1390	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	2.00	0.00	2.00	EA	0.00	\$3,500.00	\$0.00
		0010	1400	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$3,400.00	\$0.00
		0070	1410	2063300	CLASS 4 EXCAVATION	54.00	0.00	54.00	CUYD	0.00	\$30.00	\$0.00
		0070	1420	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	0.00	\$15,000.00	\$0.00
		0070	1430	2069901	MISC.DEWATERING	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0070	1440	2163501	PARTIAL REMOVAL OF CULVERT-BRIDGE CONCRETE	1.00	0.00	1.00	LS	0.00	\$12,000.00	\$0.00
		0070	1450	7034040	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)	149.70	0.00	149.70	CUYD	0.00	\$520.00	\$0.00
		0070	1460	7061020	REINFORCING STEEL (CULVERTS-BRIDGE)	20,810.00	0.00	20,810.00	LB	0.00	\$3.00	\$0.00
		0071	1470	2161000	SCARIFICATION OF BRIDGE DECK	135.00	0.00	135.00	SQYD	78.50	\$14.85	\$1,165.72
		0071	1480	2161501	REMOVAL OF ASPHALT WEARING SURFACE	1,219.00	0.00	1,219.00	SQFT	708.00	\$1.65	\$1,168.20
		0071	1490	2161503	REMOVAL OF EXISTING DECK REPAIR	25.00	0.00	25.00	SQFT	0.00	\$100.00	\$0.00
		0071	1500	5050001	OPTIONAL CONCRETE WEARING SURFACE	135.00	0.00	135.00	SQYD	0.00	\$200.00	\$0.00
		0071	1510	7031004	DIAMOND GRINDING	135.00	0.00	135.00	SQYD	269.40	\$12.00	\$3,232.80
		0071	1520	7034600	CURB BLOCKOUT	65.00	0.00	65.00	LF	0.00	\$275.00	\$0.00
		0071	1530	7040104	HALF-SOLE REPAIR	150.00	0.00	150.00	SQFT	0.00	\$100.00	\$0.00
		0071	1540	7040113	CLEANING AND EPOXY COATING	63.00	0.00	63.00	SQFT	0.00	\$80.00	\$0.00
		0071	1550	7049902	MISC.PLUGGING EXISTING CURB OUTLET	8.00	0.00	8.00	EA	0.00	\$350.00	\$0.00
		0072	1560	2161000	SCARIFICATION OF BRIDGE DECK	157.00	0.00	157.00	SQYD	0.00	\$14.85	\$0.00
		0072	1570	2161501	REMOVAL OF ASPHALT WEARING SURFACE	1,416.00	0.00	1,416.00	SQFT	0.00	\$1.65	\$0.00
		0072	1580	2161503	REMOVAL OF EXISTING DECK REPAIR	25.00	0.00	25.00	SQFT	0.00	\$100.00	\$0.00
		0072	1590	5050001	OPTIONAL CONCRETE WEARING SURFACE	157.00	0.00	157.00	SQYD	78.50	\$200.00	\$15,700.00
		0072	1600	7031004	DIAMOND GRINDING	157.00	0.00	157.00	SQYD	0.00	\$12.00	\$0.00
		0072	1610	7040104	HALF-SOLE REPAIR	150.00	0.00	150.00	SQFT	32.00	\$100.00	\$3,200.00
		0072	1620	7040113	CLEANING AND EPOXY COATING	54.00	0.00	54.00	SQFT	0.00	\$80.00	\$0.00
		0072	1630	7049902	MISC.PLUGGING EXISTING CURB OUTLET	6.00	0.00	6.00	EA	0.00	\$350.00	\$0.00
					Date as of Report Generated Date							\$62,757.72
J5I3	572	0001	1640	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$1,613,040.00	\$419,390.40
		0001	1650	2035000	UNCLASSIFIED EXCAVATION EMBANKMENT IN PLACE	109.00	0.00	109.00	CUYD	0.00	\$55.00	\$0.00
		0001	1660	2035500		2,172.00	0.00	2,172.00	CUYD	0.00	\$25.00	\$0.00
		0001	1670	2036000	COMPACTING EMBANKMENT	87.00	0.00	87.00	CUYD	0.00	\$5.00	\$0.00
		0001	1680	2063100	CLASS 3 EXCAVATION IN ROCK MISC MODIFIED LINEAR CRADING CLASS 2	55.00	0.00	55.00	CUYD	0.00	\$120.00	\$0.00
		0001	1690	2079909	MISC.MODIFIED LINEAR GRADING CLASS 2	1,740.00	0.00	1,740.00	STA	362.60	\$600.00	\$217,560.00
		0001	1700	2153000	SHAPING SLOPES, CLASS III MISC PAVEMENT FOR VEGETATIVE RARRIER 3 IN DEPTH	9.162.00	0.00	9.162.00	100F	0.00	\$1,100.00	\$0.00
		0001	1710 1720	4019905 6044011	MISC.PAVEMENT FOR VEGETATIVE BARRIER 3 IN. DEPTH PIPE COLLAR, TYPE A	9,162.00	0.00	9,162.00	SQYD	0.00	\$11.00 \$1,500.00	\$0.00 \$0.00
		0001	1720	6044011	PIPE COLLAR, TYPE C			2.00	EA			
		0001	1730	0044013	FIFE COLLAR, FIFE C	2.00	0.00	2.00	EA	0.00	\$1,500.00	\$0.00

Revision 4/1/2020 Page 14 of 51



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-D06	J5l3572	0001	1740	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	77.00	0.00	77.00	CUYD	0.00	\$30.00	\$0.0
		0001	1750	6096041	PLACING TYPE 1 ROCK DITCH LINER	77.00	0.00	77.00	CUYD	0.00	\$28.00	\$0.0
		0001	1760	6097000	ROCK LINING	5.00	0.00	5.00	CUYD	0.00	\$100.00	\$0.0
		0001	1770	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	4.00	0.00	4.00	EA	0.00	\$2,500.00	\$0.0
		0001	1780	6122020	REPLACEMENT SAND BARREL	40.00	0.00	40.00	EA	0.00	\$250.00	\$0.0
		0001	1790	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0.0
		0001	1800	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	0.00	\$1,150.00	\$0.0
		0001	1810	6129902	MISC.CRASH CUSHION	1.00	0.00	1.00	EA	0.00	\$4,000.00	\$0.0
		0001	1820	6143012	MANHOLE FRAME AND COVER, TYPE 2	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.0
		0001	1830	6161005	CONSTRUCTION SIGNS	3,529.00	0.00	3,529.00	SQFT	844.00	\$12.19	\$10,288.3
		0001	1840	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	4.00	\$25.00	\$100.0
		0001	1850	6161025	CHANNELIZER (TRIM LINE)	675.00	0.00	675.00	EA	400.00	\$20.00	\$8,000.0
		0001	1860	6161030	TYPE III MOVEABLE BARRICADE	2.00	0.00	2.00	EA	0.00	\$125.00	\$0.0
		0001	1870	6161033	DIRECTIONAL INDICATOR BARRICADE	40.00	0.00	40.00	EA	28.00	\$25.00	\$700.0
		0001	1880	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	1.00	\$500.00	\$500.0
		0001	1890	6161070	TUBULAR MARKER	800.00	0.00	800.00	EA	0.00	\$85.00	\$0.0
		0001	1900	6169901	MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	1.00	0.00	1.00	LS	0.00	\$85,000.00	\$0.0
		0001	1910	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	43,296.00	0.00	43,296.00	LF	0.00	\$18.50	\$0.0
		0001	1920	6173700B		16,368.00	0.00	16,368.00	LF	0.00	\$31.00	\$0.0
		0001	1930	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	43,296.00	0.00	43,296.00	LF	0.00	\$7.00	\$0.0
		0001	1940	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$705,000.00	\$352,500.0
		0001	1950	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	2.00	0.00	2.00	EA	2.00	\$600.00	\$1,200.0
		0001	1960	6191000	PAVEMENT EDGE TREATMENT	44,341.00	0.00	44,341.00	LF	44,156.00	\$5.00	\$220,780.0
		0001	1970	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	54,210.00	0.00	54,210.00	LF	0.00	\$0.24	\$0.0
		0001	1980	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	43,300.00	0.00	43,300.00	LF	0.00	\$0.22	\$0.0
		0001	1990	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	490.00	0.00	490.00	LF	0.00	\$2.00	\$0.0
		0001	2000	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	194,400.00	0.00	194,400.00	LF	56,719.00	\$0.40	\$22,687.6
		0001	2010	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	181,500.00	0.00	181,500.00	LF	45,460.00	\$0.40	\$18,184.0
		0001	2020	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$180,000.00	\$0.0
		0001	2030	7034041	CLASS B-1 CONCRETE (CULVERTS)	15.70	0.00	15.70	CUYD	0.00	\$1,500.00	\$0.0
		0001	2040	7061030	REINFORCING STEEL (CULVERTS)	2,120.00	0.00	2,120.00	LB	0.00	\$3.00	\$0.0
		0001	2050	7250415	15 IN. PIPE GROUP C	640.00	0.00	640.00	LF	0.00	\$50.00	\$0.0
		0001	2060	7261018	18 IN. PIPE GROUP A	65.00	0.00	65.00	LF	0.00	\$60.00	\$0.0
		0001	2070	7261024	24 IN. PIPE GROUP A	19.00	0.00	19.00	LF	0.00	\$65.00	\$0.0
		0001	2080	7310048	PRECAST CONCRETE MANHOLE - 48 IN.	7.00	0.00	7.00	FT	0.00	\$710.00	\$0.0
		0001	2090	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	8.00	0.00	8.00	FT	0.00	\$1,222.00	\$0.0
		0001	2100	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$1,150.00	\$0.0
		0001	2110	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$1,190.00	\$0.0
		0001	2120	7321013A	15 IN. OR ALLOWED SUBSTITUTE SAFETY SLOPE END SECTION	4.00	0.00	4.00	EA	0.00	\$1,612.50	\$0.0
		0001	2130	7321016A	24 IN. OR ALLOWED SUBSTITUTE SAFETY SLOPE END SECTION	2.00	0.00	2.00	EA	0.00	\$3,340.00	\$0.0
		0001	2140	8051000A	SEEDING - COOL SEASON GRASSES	62.00	0.00	62.00	ACRE	14.20	\$2,350.00	\$33,370.0
		0001	2150	8061003	SEDIMENT TRAP EXCAVATION	3.00	0.00	3.00	CUYD	0.00	\$35.00	\$0.0
		0001	2160	8061004	SEDIMENT TRAP ROCK	4.00	0.00	4.00	CUYD	0.00	\$50.00	\$0.0
		0001	2170	8061005	ROCK DITCH CHECK	3,904.00	0.00	3,904.00	LF	27.00	\$11.00	\$297.0

Revision 4/1/2020 Page 15 of 51



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-D06	J5l3572	0001	2180	8061007A	CURB INLET CHECK	32.00	0.00	32.00	EA	42.00	\$145.00	\$6,090.00
		0001	2190	8061016	SEDIMENT REMOVAL	24.00	0.00	24.00	CUYD	0.00	\$10.00	\$0.00
		0001	2200	8061017	TEMPORARY SEEDING	62.00	0.00	62.00	ACRE	0.00	\$1,950.00	\$0.00
		0003	2240	3030600	FURNISHING ROCK BASE MATERIAL	200,280.00	0.00	200,280.00	SQYD	0.00	\$4.00	\$0.00
		0003	2250	3030610A	PLACING ROCK BASE	200,280.00	0.00	200,280.00	SQYD	0.00	\$16.00	\$0.00
		0003	2260	5021311	CONCRETE PAVEMENT (11 IN. NON-REINFORCED 15 FT. JOINTS)	200,280.00	0.00	200,280.00	SQYD	0.00	\$69.00	\$0.00
		0005	2300	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	83,730.00	0.00	83,730.00	SQYD	67,176.90	\$6.00	\$403,061.40
		0005	2310	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	83,730.00	0.00	83,730.00	SQYD	49,425.60	\$56.00	\$2,767,833.60
		0005	2320	6262000A	PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP	1,740.00	0.00	1,740.00	STA	0.00	\$58.00	\$0.00
		0010	2330	6061060	MGS GUARDRAIL	3,690.00	0.00	3,690.00	LF	0.00	\$33.08	\$0.00
		0010	2340	6061080	MGS END ANCHOR	5.00	0.00	5.00	EA	0.00	\$1,100.00	\$0.00
		0010	2350	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	5.00	0.00	5.00	EA	0.00	\$3,200.00	\$0.00
		0010	2360	6069902	MISC.HTGC ANCHOR ASSEMBLY	14.00	0.00	14.00	EA	0.00	\$3,680.00	\$0.00
		0010	2370	6069903	MISC.HIGH TENSION GUARD CABLE	45,217.00	0.00	45,217.00	LF	0.00	\$19.50	\$0.00
		0020	2380	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	4.00	0.00	4.00	EA	0.00	\$3,630.00	\$0.00
		0020	2390	9011115	BRACKET ARM, 15 FT. OR 4.6 M	4.00	0.00	4.00	EA	0.00	\$1,053.00	\$0.00
		0020	2400	9011312	LUMINAIRE, LED-B	4.00	0.00	4.00	EA	0.00	\$352.00	\$0.00
		0020	2410	9014003	CONDUIT, 3 IN. RIGID, PUSHED	292.00	0.00	292.00	LF	0.00	\$27.50	\$0.00
		0020	2420	9015010	TRENCHING TYPE I	3,268.00	0.00	3,268.00	LF	0.00	\$3.25	\$0.00
		0020	2430	9016110	PULL BOX, PREFORMED CLASS 1	7.00	0.00	7.00	EA	0.00	\$1,385.00	\$0.00
		0020	2440	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	520.00	0.00	520.00	LF	0.00	\$0.95	\$0.00
		0020	2450	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	3,830.00	0.00	3,830.00	LF	0.00	\$4.30	\$0.00
		0020	2460	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	4.00	0.00	4.00	EA	0.00	\$1,980.00	\$0.00
		0040	2470	9031010	CONCRETE FOOTINGS, EMBEDDED	10.20	0.00	10.20	CUYD	0.00	\$651.00	\$0.00
		0040	2480	9031210	STRUCTURAL STEEL POSTS	6,230.00	0.00	6,230.00	LB	0.00	\$9.94	\$0.00
		0040	2490	9031220	PIPE POSTS	100.00	0.00	100.00	LB	0.00	\$13.52	\$0.00
		0040	2500	9031270A	2 IN. PSST POST - 12 GA.	16.00	0.00	16.00	LF	0.00	\$25.26	\$0.00
		0040	2510	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	3.00	0.00	3.00	LF	0.00	\$70.89	\$0.00
		0001	5201	6161055	SEQUENTIAL FLASHING WARNING LIGHT	0.00	28.00	28.00	EA	14.00	\$76.00	\$1,064.00
					late as of Report Generated Date							\$4,483,606.36
220121-D06 Ove	rall - Tota	I Value Pos	sted to Da	ate as of Rep	ort Generated Date							\$11,844,547.47

Revision 4/1/2020 Page 16 of 51



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5l3397

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0800	2153000	SHAPING SLOPES, CLASS III	10/28/22	11/3/22	0.80	100F	Truck Parking					
0140	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP1	10/28/22	11/3/22	1,802.00	TONS	EB DL	179.852		181.868		
0150	4071005	TACK COAT	10/28/22	11/3/22	1,614.00	GAL	EB DL	179.852		181.868		
0180	5062030A	FURNISHING UNBONDED CONCRETE OVERLAY	10/28/22	11/3/22	319.20	CUYD	WB DL	464+79		462+58		221'x13'/9 = 319.2 SY
				11/3/22	1,087.30	CUYD	WB DL	462+58		453+59		699'x14'/9 = 1087.3 SY
0190	5062033	UNBONDED CONCRETE OVERLAY INTERLAYER	10/24/22	11/3/22	1,960.00	SQYD	WB DL	508+68		496+08		1260'x14' /9 = 1960 SY
			10/26/22	11/3/22	1,773.30	SQYD	WB DL	496+08		484+68		1140'x14'/9 = 1773.3 SY
			10/27/22	11/3/22	1,240.80	SQYD	WB DL	473+38		464+79		859'x13'/9= 1240.8 SY
				11/3/22	1,757.80	SQYD	WB DL	484+68		473+38		1130'x14'/9 = 1757.8 SY
			10/28/22	11/3/22	319.20	SQYD	WB DL	464+79		453+59		221'x13'/9= 319.2 SY
				11/3/22	1,087.30	SQYD	WB DL	453+59		453+59		699'x14'/9 = 1087.3 SY
0200	5069905	MISC.	10/24/22	11/3/22	1,960.00	SQYD	WB DL	508+68		496+08		1260'x14'/9 = 1960 SY
			10/26/22	11/3/22	1,773.30	SQYD	WB DL	496+08		484+68		1140'x14'/9 = 1773.3 SY
			10/27/22	11/3/22	1,240.80	SQYD	WB DL	473+38		464+79		859'x13'/9 = 1240.8 SY
				11/3/22	1,757.80	SQYD	WB DL	484+68		473+38		859'x13'/9= 1240.8 SY
			10/28/22	11/3/22	2,034.60	SQYD	WB DL	508+68		453+59		8138.4 SY 9" AVG Depth. 2034.6 CY Pay for all 4 paves on segment 6.
0300	6122030	IMPACT ATTENUATOR (RELOCATION)	10/17/22	11/2/22	1.00	EA	Segment 6 Unbonded Section	115.630				Start of barrier wall for segment 6 of unbonded
			10/31/22	11/2/22	1.00	EA	Segment 7 Unbonded Section	116.400				Start of barrier wall for segment 7 of unbonded
0400	6161005	CONSTRUCTION SIGNS	10/17/22	11/2/22	308.00	SQFT	See Template	0.01				
0470	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	10/17/22	11/2/22	2.00	EA	Unbonded Section	113.868				Segment six of unbonded section before RWA signs
				11/2/22	2.00	EA	Unbonded Section	114.562				Segment six of unbonded section before RLCA signs
0510	6173600D	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	10/17/22	11/2/22	237.50	LF	Unbonded Section	115.630		115.675		Segment six of unbonded section taper
			10/31/22	11/2/22	1,625.00	LF	Unbonded Section	116.400		116.630		Segment seven of unbonded section
0520	6173700B	TEMP. TRAFFIC BARRIER ANCHORED., CONT	10/17/22	11/2/22	5,687.50	LF	Unbonded Section	115.675		116.752		Segment six of the unbonded section
0580	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	10/17/22	11/2/22	150.00	LF	Unbonded Section	115.630				Segment 5 wall taper
				11/2/22	860.00	LF	Unbonded Section	115.467		115.630		Segment 5 Taper at DIBS
				11/2/22	4,500.00	LF	Unbonded Section	113.501		114.353		Temp Edge line Segment 5
0590	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	10/31/22	11/2/22	380.00	LF	Unbonded Section	116.328		116.400		Segment seven of unbonded section taper
				11/2/22	1,625.00	LF	Unbonded Section	116.400		116.630		Segment seven of unbonded section base of wall
0630	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	10/28/22	11/3/22	16,558.00	SQYD	EB DL	179.852		181.868		10644'x14'/9 = 16558 SY
0890	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	10/28/22	11/3/22	437.50	LF	WB Truck Parking					
0930	6061080	MGS END ANCHOR	10/28/22	11/3/22	1.00	EA	WB Truck Parking					
0940	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	10/28/22	11/3/22	1.00	EA	WB Truck Parking					

Project: J5l3572

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
1690	2079909	MISC. GRADING	10/31/22	11/3/22	20.00	STA	WB LT	101.793		103.065		Pay for initial grading for base rock installation. 67 sta @ 30% = 20 Sta
2300	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	10/17/22	11/2/22	2,644.40	SQYD	WB 7' Shoulder	101.104		101.748		(3400' x 7' / 9) = 2644.4 SY
			10/24/22	11/3/22	1,672.20	SQYD	WB Left Shoulder	101.748		102.155		2150'x7'/9 = 1672.2 SY
			10/27/22	11/3/22	3,344.40	SQYD	WB 7' Shoulder	102.155		102.969		4300'x7'/9= 3344.4 SY
2310	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED,	10/20/22	11/3/22	1,750.00	SQYD	WB 7' Shoulder	97.764		98.190		2250'x7'/9 = 1750 Sy
			10/31/22	11/3/22	1,341.70	SQYD	WB 7' Shoulder	98.190		98.517		1725'x7'/9= 1341.7 SY

he info	rmation be	elow this line are	e details for Construction Sig	ns (if applicable).								
Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J513397	0400	April 30, 2022	444	CONST-7 72x36 18.00 RATE OUR WORK ZONE		176.065		1.00	18			18
				GO20-2 48x24 8.00 END ROAD WORK		116.732		2.00	8			16
				See Special Sign Details								
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte. V EB & WB On Ramps	2.00	16			32
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte. T EB & WB On Ramps	2.00	16			32
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte. E EB & WB On Ramps	2.00	16			32
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte. 72 Bus. EB & WB ON Ramps	2.00	16			32
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte. 68/8 EB & WB On Ramps	2.00	16			32
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte. 63 EB & WB On Ramps	2.00	16			32
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		176.109		2.00	10			20
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		176.211		2.00	12			24
				CONST-5 96x48 32.00 POINT OF PRESENCE		178.003		1.00	32			32
				GO20-2 48x24 8.00 END ROAD WORK		204.839		2.00	8			16
				CONST-7 72x36 18.00 RATE OUR WORK ZONE		91.625		1.00	18			18
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		91.729		2.00	10			20
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		91.828		2.00	12			24
				CONST-5 96x48 32.00 POINT OF PRESENCE		92.767		1.00	32			32
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte. F WB On ramp	1.00	16			16
				WO20-1 48x48 16.00			Sugar Tree EB on ramp	1.00	16			16

Revision 4/1/2020 Page 17 of 51



mation below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

THE IIIIOIIIIauoii i	Delow tills lille	is supplement	ai to the Estima	le allu is provideu id
The information I	halaw thia lina	are details for	Construction Ci	ana (if annliaahla)

Project	Line	DWR Date	Total Quantity Posted For DWR	Sign Information	Station	Log	Location	Number of	SF Each	Special Sign	SF Each Special	Total SF to
	Number	Ail 20, 2022	Date			Log Mile		Items	Sign		Sign	Post
J5I3397	0400	April 30, 2022 August 1, 2022	233	ROAD/BRIDGE/RAMP WORK AHEAD WO20-1 48x48 16.00			Mobile Package	2.00	16.00			32.00
				ROAD/BRIDGE/RAMP WORK AHEAD WO3-5 48x48 16.00 SPEED LIMIT			Mobile Package	2.00	16.00			32.00
				XX AHEAD (SYMBOL)								
				R4-2 36x48 12.00 PASS WITH CARE			Mobile Package	2.00	12.00			24.00
				R4-1 36x48 12.00 DO NOT PASS GO20-5aP 36x24 6.00 WORK ZONE			Mobile Package Mobile Package	2.00 4.00	12.00			24.00 24.00
				(PLAQUE)								
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)			Mobile Package	2.00	4.67			9.34
				CONST-3A 60x48 20.00 FINE SIGN R2-1 36x48 12.00 SPEED LIMIT			Mobile Package Mobile Package	2.00	20.00			40.00
				XX			•	4.00	12.00			48.00
		August 4, 2022	344	See Special Sign Details		107.978	WB 44	2.00		During Backups Use Both Lanes	32.00	64.00
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		107.895	WB 44	2.00	16.00			32.00
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		109.004	WB 44	2.00	16.00			32.00
				R2-1 36x48 12.00 SPEED LIMIT XX		110.256	Wb 44	2.00	12.00			24.00
				GO20-5aP 36x24 6.00 WORK ZONE		110.256	WB 44	2.00	6.00			12.00
				(PLAQUE) See Special Sign Details		110.042	WB 44	2.00		Take Turns	5.00	10.00
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		110.042	WB 44	1.00	16.00			16.00
				WO4-1aL 48x48 16.00 MERGE		110.042	WB 44	1.00	16.00			16.00
				(ARROW SYMBOL) WO20-5 48x48 16.00		109.726	WB 44	2.00	16.00			32.00
				RIGHT/CENTER/LEFT LANE CLOSED AHEAD								
				See Special Sign Details		109.726		2.00		Take Turns at Merge	5.00	10.00
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		109.201	WB 44	2.00	16.00			32.00
				See Special Sign Details		109.099	WB 44	2.00		During Backups Use Both Lanes	32.00	64.00
		August 22, 2022	332	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		109.313	Unbonded segment 2	2.00	16.00			32.00
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		109.408	Unbonded Segment 2	64.00	1.00	Use Both Lanes Take turns	32.00	64.00
				Variable ??x?? 1.00 SPECIAL SIGN		111.004	Unbonded section 2	10.00	1.00	Take Turns	5.00	10.00
				BY QUANTITY OF SQUARE FEET WO20-6a 48x48 16.00		111.004	Unbonded section 2	1.00	16.00			16.00
				RIGHT/CENTER/LEFT LANE CLOSED								
				WO4-1R 48x48 16.00 MERGE (SYMBOL FROM RIGHT)			Unbonded section 2	1.00	16.00			16.00
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		110.815	Unbonded section 2	2.00	16.00			32.00
				Variable ??x?? 1.00 SPECIAL SIGN		110.815	Unbonded section 2	10.00	1.00	Take Turns at Merge	5.00	10.00
				BY QUANTITY OF SQUARE FEET R2-1 36x48 12:00 SPEED LIMIT		110.598	Unbonded section 2	2.00	12.00			24.00
				xx			Unbonded section 2	2.00	16.00			32.00
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD								
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		110.408	Unbonded section 2	64.00	1.00	Use Both Lanes Take Turns	32.00	64.00
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		110.313	Unbonded segment 2	2.00	16.00			32.00
		September 6, 2022	308	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		110.313	Unbonded Segment 3	2.00	16.00			32.00
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		110.408	Unbonded Segment 3	64.00	1.00	Use Both Lanes Take Turns	32.00	64.00
				WO20-1 48x48 16.00		111.313	Unbonded Segment 3	2.00	16.00			32.00
				ROAD/BRIDGE/RAMP WORK AHEAD Variable ??x?? 1.00 SPECIAL SIGN		111.408	Unbonded Segment 3	64.00	1.00	Use Both Lanes Take Turns	32.00	64.00
				BY QUANTITY OF SQUARE FEET Variable ??x?? 1.00 SPECIAL SIGN		112 004	Unbonded Segment 3	10.00	1.00		5.00	10.00
				BY QUANTITY OF SQUARE FEET								
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET			Unbonded Segment 3	10.00	1.00		5.00	10.00
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		111.815	Unbonded Segment 3	2.00	16.00			32.00
				WO4-1R 48x48 16.00 MERGE		112.004	Unbonded Segment 3	1.00	16.00			16.00
				(SYMBOL FROM RIGHT) WO20-6a 48x48 16.00		112 004	Unbonded Segment 3	1.00	16.00			16.00
				RIGHT/CENTER/LEFT LANE CLOSED WO20-1 48x48 16.00			Unbonded Segment 3	2.00	16.00			32.00
				ROAD/BRIDGE/RAMP WORK AHEAD								
		September 19, 2022	212	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		111.786	Unbonded Segment 4	2.00	16.00			32.00
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		111.862	Unbonded Segment 4	64.00	1.00		32.00	64.00
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		111.957	Unbonded Segment 4	2.00	16.00			32.00
				Variable ??x?? 1.00 SPECIAL SIGN		112.452	Unbonded Segment 4	10.00	1.00		5.00	10.00
				BY QUANTITY OF SQUARE FEET WO20-5 48x48 16.00		112.452	Unbonded Segment 4	2.00	16.00			32.00
				RIGHT/CENTER/LEFT LANE CLOSED AHEAD								
				WO4-1aL 48x48 16.00 MERGE (ARROW SYMBOL)		112.641	Unbonded Segment 4	1.00	16.00			16.00
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		112.641	Unbonded Segment 4	1.00	16.00			16.00

Revision 4/1/2020 Page 18 of 51



roject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
13397 0	1400	September 22, 2022	102	R1-2 48 TRI 6.93 YIELD WO3-4 8x48 16.00 BE			Rte V and Rte 68 Rte V and Rte 68	3.00	6.93 16.00			13.8
				PREPARED TO STOP R11-2 48x30 10.00 ROAD			Exit 179 On Ramp Closure	4.00	10.00			40.0
		October 3, 2022	340	CLOSED W020-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD	113.990		Unbonded Segment 5 Ramp	1.00	16.00			16.0
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED	113.995		Unbonded Segment 5 Ramp	1.00	16.00			16.0
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET	113.896		Unbonded Segment 5	10.00	1.00	Take Turns	5.00	10.
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET	113.620		Unbonded Segment 5	10.00	1.00	Take Turns at Merge	5.00	10.
				R2-1 36x48 12.00 SPEED LIMIT XX	112.742		Unbonded Segment 5	2.00	12.00			24.
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	112.947		Unbonded Segment 5	2.00	16.00			32.
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED	113.896		Unbonded Segment 5	1.00	16.00			16.
				WO4-1aL 48x48 16.00 MERGE (ARROW SYMBOL)	113.896		Unbonded Segment 5	1.00	16.00			16.
				R2-1 36x48 12.00 SPEED LIMIT XX	113.999		Unbonded Segment 5	1.00	12.00			12
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	113.110		Unbonded Segment 5	2.00	16.00			32.
				Variable ??x?? 1.00 SPECIAL SIGN	113.030		Unbonded Segment 5	64.00	1.00	Use Both Lanes/Take Turns	32.00	64.
				BY QUANTITY OF SQUARE FEET R2-1 36x48 12.00 SPEED LIMIT			WB Inside Shoulder	5.00	12.00			60.
				XX WO20-5 48x48 16.00	113.620		Unbonded Segment 5	2.00	16.00			32.
				RIGHT/CENTER/LEFT LANE CLOSED AHEAD								
		October 17, 2022	308	WO4-1R 48x48 16.00 MERGE (SYMBOL FROM RIGHT)	114.963			1.00	16.00			16.
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED	114.963			1.00	16.00			16
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET	114.657			10.00	1.00	Take Turns	5.00	10
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET	114.963			10.00	1.00	Take Turns	5.00	10
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET	114.040			64.00	1.00	Use Both Lanes/Take Turns	32.00	64
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	113.963			2.00	16.00			32
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET	113.030			64.00	1.00	Use Both Lanes/Take Turns	32.00	64
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD	114.657			2.00	16.00			32
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	114.138			2.00	16.00			32
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	112.946		WB	2.00	16.00			32
3482 1	1400 - Total	June 15, 2022	308	WO20-1 48x48 16.00		97.9		2.00	16			262
				ROAD/BRIDGE/RAMP WORK AHEAD special ??x?? ??.00 NO PASSING		97.4		2.00		During Back-ups Use Both	32.00	
				ZONE WO20-1 48x48 16.00		97.3		2.00	16	Lanes	02.00	
				ROAD/BRIDGE/RAMP WORK AHEAD special ??x?? ??.00 NO PASSING		98.000		2.00	10	During Back Ups Use Both	32.00	
				ZONE						Lanes		
				special ??x?? ??.00 NO PASSING ZONE		99.316		2.00		Take Turns	5.00	
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		99.316		1.00	16			
				WO4-1aL 48x48 16.00 MERGE (ARROW SYMBOL)		99.316		1.00	16			
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		99.032		2.00	16			
				special ??x?? ??.00 NO PASSING ZONE		99.032		2.00		Take Turns at Merge	5.00	
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		98.532		2.00	16			
13572 1	140 - Total 830	April 30, 2022	237	WO4-1aL 48x48 16.00 MERGE				1.00	16			3
		,		(ARROW SYMBOL) W020-6a 48x48 16.00				1.00	16			
				RIGHT/CENTER/LEFT LANE CLOSED GO20-5aP 36x24 6.00 WORK ZONE				2.00	6			
				(PLAQUE) R4-1 36x48 12.00 DO NOT PASS				2.00	12			
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)				2.00	4.67			9
				WO3-5 48x48 16.00 SPEED LIMIT				2.00	16			
				XX AHEAD (SYMBOL) WO20-1 48x48 16.00				2.00	16			
				ROAD/BRIDGE/RAMP WORK AHEAD				2.00	16			
				WO20-5 48x48 16.00								
				RIGHT/CENTER/LEFT LANE CLOSED AHEAD								
				RIGHT/CENTER/LEFT LANE CLOSED				2.00	20			

Revision 4/1/2020 Page 19 of 51

various locations through out job 4.00

WO8-17p 30x24 5.00 SHOULDER



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable)

roject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
13572	1830	May 15, 2022	116	DROP-OFF (PLAQUE)			WB					
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)			various locations through out job WB	4.00	16			64
		June 28, 2022	491	GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)			Various	10.00	6			60
				special ??x?? ??.00 NO PASSING ZONE			Various	2.00		Take Turns	5.00	10
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)			Various	2.00	5			10
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)			Various	2.00	16			32
				CONST-3A 60x48 20.00 FINE SIGN			Various	4.00	20			80
				R2-1 36x48 12.00 SPEED LIMIT XX			Various	6.00	12			72
				R4-1 36x48 12.00 DO NOT PASS			Various	4.00	12			48
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)			Various	4.00	4.67			18.68
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Various	3.00	16			48
				WO3-2 48x48 16.00 YIELD AHEAD (SYMBOL)			Various	3.00	16			48
				WO3-5 48x48 16.00 SPEED LIMIT XX AHEAD (SYMBOL)			Various	4.00	16			64
	1830 - Total											844.02

Revision 4/1/2020 Page 20 of 51



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J5I3397	0140	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP1	Other Item Adjustment	ACAD	14	Nov 3, 2022	linkd1	\$28,210.31	1802 tons I DIFF 252.5 6.2% VAC +\$28,210.31					
				ACAD - Tota	al			\$28,210.31						
			Other Item A	djustment - T	otal			\$28,210.31						
	0140 -	Total						\$28,210.31						
	0150	TACK COAT	Material		14	Nov 3, 2022	SYSTEM	\$3,308.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					14	Nov 3, 2022	SYSTEM	(\$3,308.70)						
				- Total				\$0.00						
			Material - Tot	al				\$0.00						
	0150 -	Total						\$0.00						
	0180	FURNISHING UNBONDED CONCRETE	Material		10	Sep 6, 2022	SYSTEM	\$400,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.					
		OVERLAY			10	Sep 6, 2022	SYSTEM	(\$400,200.00)						
					11	Sep 16, 2022	SYSTEM	\$577,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.					
					11	Sep 16, 2022	SYSTEM	(\$577,700.00)						
					12	Oct 4, 2022	SYSTEM	\$804,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user gabelj3 overridding Payment Estimate Exception 7 on the current Payment Estimate.					
					12	Oct 4, 2022	SYSTEM	(\$804,325.00)						
					13	Oct 18, 2022	SYSTEM	\$1,098,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0101) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.					
					13	Oct 18, 2022	SYSTEM	(\$1,098,575.00)						
					14	Nov 3, 2022	SYSTEM	\$1,274,387.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
					14	Nov 3, 2022	SYSTEM	(\$1,274,387.50)						
				- Total		2022		\$0.00						
			Material - Tot					\$0.00						
			Overrun	Overrun	14	Nov 3, 2022	SYSTEM	(\$93,512.50)						
				Overrun - To	otal			(\$93,512.50)						
			Overrun - To					(\$93,512.50)						
	0180 -	Total						(\$93,512.50)						
	0190	UNBONDED CONCRETE	Construction		Construction Stockpile					10	Sep 6, 2022	SYSTEM	(\$39,119.58)	Payment Estimate Item Adjustment generated Stockpile Transaction
		OVERLAY INTERLAYER			11	Sep 16, 2022	SYSTEM	(\$15,943.89)	Payment Estimate Item Adjustment generated Stockpile Transaction					
				12	Oct 4, 2022	SYSTEM	(\$12,390.09)	Payment Estimate Item Adjustment generated Stockpile Transaction						
					13	Oct 17, 2022	SYSTEM	(\$8,565.94)	Payment Estimate Item Adjustment generated Stockpile Transaction					
					14	Nov 3, 2022	SYSTEM	(\$632.73)	Payment Estimate Item Adjustment generated Stockpile Transaction					
				- Total				(\$76,652.23)						
			Construction		「otal			(\$76,652.23)						
			Construction Stockpile		3	May 16, 2022	SYSTEM	\$33,869.59	Payment Estimate Item Adjustment generated Stockpile Transaction					
			STMA	- Total		2022		\$33,869.59						
			Construction		TMA - Tota	al		\$33,869.59						
			- Johnsti digiti di	nonpile of				,00,000.00						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J5I3397	0190	UNBONDED CONCRETE OVERLAY	Construction Stockpile STMI		2	May 3, 2022	SYSTEM	\$42,782.64	Payment Estimate Item Adjustment generated Stockpile Transaction										
		INTERLAYER	STIVII	- Total				\$42,782.64											
			Construction	Stockpile S1	MI - Tota			\$42,782.64											
			Overrun	Overrun	14	Nov 3, 2022	SYSTEM	(\$9,518.70)											
				Overrun - To	otal			(\$9,518.70)											
			Overrun - To	tal				(\$9,518.70)											
	0190 -	Total						(\$9,518.70)											
	0200	MISC.	Other Item Adjustment	FUEL	10	Sep 6, 2022	marzua1	\$10,978.36	System did not calculate due to bid item number being a 99 number rather than bid item 506,2031. Manual Calculation: current index - 3.66 base index - 2.39 Index Difference - 1.27 Usage Factor - 0.60 14407.30 SY x 1.27 x 0.60 = 10,978.36										
					11	Sep 16, 2022	linkd1	\$6,271.51	5872.2 SY Usage factor 0.6 +\$6271.51										
					12	Oct 4, 2022	gabelj3	\$8,103.45	7587.5 SY Fuel Factor 0.60 +\$8,103.45										
					13	Oct 18, 2022	linkd1	\$5,747.31	9675.60 SY Fuel Index 0.6 Index Difference CI 3.38, BI 2.39, DIF 0.99 +\$5747.31										
					14	Nov 3, 2022	linkd1	\$5,207.30	8766.5 SY CI 3.38 I DIFF +0.99 +\$5,207.30										
			FUEL - Tota				\$36,307.93												
			djustment - T	otal		\$36,307.93													
			Overrun	Overrun	14	Nov 3, 2022	SYSTEM	(\$30,408.00)											
							Overrun - To	otal			(\$30,408.00)								
			Overrun - To	tal				(\$30,408.00)											
	0200 -	Total						\$5,899.93											
	0280	IMPACT ATTENUATOR 70 MPH (SAND	Material		7	Jul 19, 2022	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.										
		BARREL ARRAY)			7	Jul 19, 2022	SYSTEM	(\$2,500.00)											
					8	Aug 2, 2022	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.										
					8	Aug 2, 2022	SYSTEM	(\$2,500.00)											
					9	Aug 17, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.										
					9	Aug 17, 2022	SYSTEM	(\$5,000.00)											
															10	Sep 6, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
								10	Sep 6, 2022	SYSTEM	(\$5,000.00)								
				1		SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate.											
					11	Sep 16, 2022	SYSTEM	(\$5,000.00)											
					12	Oct 4, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user gabelj3 overridding Payment Estimate Exception 12 on the current Payment Estimate.										
					12	Oct 4,	SYSTEM	(\$5,000.00)											



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks						
				Туре			-,								
J5I3397	0280	IMPACT ATTENUATOR 70	Material	- Total		2022		\$0.00							
		MPH (SAND BARREL ARRAY)	Material - To					\$0.00							
	0280 -	Total						\$0.00							
	0310	TRUCK OR TRAILER MOUNTED ATTEN	Material		10	Sep 6, 2022	SYSTEM	\$1,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate.						
		(TMA)			10	Sep 6, 2022	SYSTEM	(\$1,150.00)							
					11	Sep 16, 2022	SYSTEM	\$1,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate.						
					11	Sep 16, 2022	SYSTEM	(\$1,150.00)							
					12	Oct 4, 2022	SYSTEM	\$1,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user gabelj3 overridding Payment Estimate Exception 13 on the current Payment Estimate.						
					12	Oct 4, 2022	SYSTEM	(\$1,150.00)							
				- Total				\$0.00							
			Material - To	tal				\$0.00							
	0310 -	Total						\$0.00							
	0320	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		4	Jun 2, 2022	SYSTEM	\$5,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
					4	Jun 2, 2022	SYSTEM	(\$5,480.00)							
					5	Jun 17, 2022	SYSTEM	\$103,626.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.						
					5	Jun 17, 2022	SYSTEM	(\$103,626.80)							
					6	Jul 2, 2022	SYSTEM	\$116,039.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user abbote1 overridding Payment Estimate Exception 17 on the current Payment Estimate.						
					6	Jul 1, 2022	SYSTEM	(\$116,039.00)							
					7	Jul 19, 2022	SYSTEM	\$116,039.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate.						
					7	Jul 19, 2022	SYSTEM	(\$116,039.00)							
					8	Aug 2, 2022	SYSTEM	\$133,410.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.						
					8	Aug 2, 2022	SYSTEM	(\$133,410.60)							
					9	Aug 17, 2022	SYSTEM	\$140,726.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.						
					9	Aug 17, 2022	SYSTEM	(\$140,726.40)							
									10	Sep 6, 2022	SYSTEM	\$140,726.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate.		
					10	Sep 6, 2022	SYSTEM	(\$140,726.40)							
											11	Sep 16, 2022	SYSTEM	\$140,726.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					11	Sep 16, 2022	SYSTEM	(\$140,726.40)							
					12	Oct 4, 2022	SYSTEM	\$154,892.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user gabel 3 overridding Payment Estimate Exception 14 on the current Payment Estimate.						
					12	Oct 4,	SYSTEM	(\$154,892.20)							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J5I3397	0320	FURN & PLACE	Material			2022				
		CONC MATL FOR FULL DEPTH			13	Oct 18, 2022	SYSTEM	\$154,892.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0102) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
					13	Oct 18, 2022	SYSTEM	(\$154,892.20)		
					14	Nov 3, 2022	SYSTEM	\$154,892.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					14	Nov 3, 2022	SYSTEM	(\$154,892.20)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
			Overrun	Overrun	12	Oct 4, 2022	SYSTEM	(\$1,178.20)		
				Overrun - T	otal			(\$1,178.20)		
			Overrun - To	tal				(\$1,178.20)		
	0320 -	· Total						(\$1,178.20)		
	0350	FULL DEPTH PAVEMENT	Overrun	Overrun	12	Oct 4, 2022	SYSTEM	(\$1,530.00)		
		REPAIR SAW CUT (FOR		Overrun - T	otal			(\$1,530.00)		
		(, 2, ,	Overrun - To	tal				(\$1,530.00)		
	0350 -	50 - Total						(\$1,530.00)		
	0360	DOWEL BAR (DRILLING, FURNISHING AND	Material		4	Jun 2, 2022	SYSTEM	\$112.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
		INST			4	Jun 2, 2022	SYSTEM	(\$112.50)		
					5	Jun 17, 2022	SYSTEM	\$3,757.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
					5	Jun 17, 2022	SYSTEM	(\$3,757.50)		
					6	Jul 2, 2022	SYSTEM	\$3,982.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user abbote1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
						6	Jul 1, 2022	SYSTEM	(\$3,982.50)	
					7	Jul 19, 2022	SYSTEM	\$3,982.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					7	Jul 19, 2022	SYSTEM	(\$3,982.50)		
					8	Aug 2, 2022	SYSTEM	\$5,017.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
					8	Aug 2, 2022	SYSTEM	(\$5,017.50)		
					9	Aug 17, 2022	SYSTEM	\$5,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
					9	Aug 17, 2022	SYSTEM	(\$5,220.00)		
					10	Sep 6, 2022	SYSTEM	\$5,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user linkd1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
					10	Sep 6, 2022	SYSTEM	(\$5,220.00)		
					11	Sep 16, 2022	SYSTEM	\$5,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
					11	Sep 16, 2022	SYSTEM	(\$5,220.00)		
					12	Oct 4, 2022	SYSTEM	\$6,097.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user gabelj3 overridding Payment	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J5I3397	0360	DOWEL BAR	Material						Estimate Exception 17 on the current Payment Estimate.														
		(DRILLING, FURNISHING AND INST			12	Oct 4, 2022	SYSTEM	(\$6,097.50)															
					13	Oct 18, 2022	SYSTEM	\$6,097.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0103) due to user linkd1 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
					13	Oct 18, 2022	SYSTEM	(\$6,097.50)															
					14	Nov 3, 2022	SYSTEM	\$6,097.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user linkd1 overridding Payment Estimate Exception 17 on the current Payment Estimate.														
					14	Nov 3, 2022	SYSTEM	(\$6,097.50)															
				- Total				\$0.00															
			Material - To	tal				\$0.00															
	0360 -	Total						\$0.00															
	0370	DOWEL BAR (FURNISH AND INSTALL WITH BASK	Material		4	Jun 2, 2022	SYSTEM	\$48.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate.														
		BAOK			4	Jun 2, 2022	SYSTEM	(\$48.75)															
					5	Jun 17, 2022	SYSTEM	\$458.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user linkd1 overridding Payment Estimate Exception 15 on the current Payment Estimate.														
					5	Jun 17, 2022	SYSTEM	(\$458.25)															
					6	Jul 2, 2022	SYSTEM	\$809.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user abbote1 overridding Payment Estimate Exception 22 on the current Payment Estimate.														
																			6	Jul 1, 2022	SYSTEM	(\$809.25)	
					7	Jul 19, 2022	SYSTEM	\$809.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user linkd1 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
					7	Jul 19, 2022	SYSTEM	(\$809.25)															
					8	Aug 2, 2022	SYSTEM	\$1,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user linkd1 overridding Payment Estimate Exception 15 on the current Payment Estimate.														
					8	Aug 2, 2022	SYSTEM	(\$1,560.00)															
					9	Aug 17, 2022	SYSTEM	\$1,891.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 15 on the current Payment Estimate.														
					9	Aug 17, 2022	SYSTEM	(\$1,891.50)															
					10	Sep 6, 2022	SYSTEM	\$1,891.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user linkd1 overridding Payment Estimate Exception 18 on the current Payment Estimate.														
					10	Sep 6, 2022	SYSTEM	(\$1,891.50)															
					11	Sep 16, 2022	SYSTEM	\$1,891.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user linkd1 overridding Payment Estimate Exception 19 on the current Payment Estimate.														
					11	Sep 16, 2022	SYSTEM	(\$1,891.50)															
						12	Oct 4, 2022	SYSTEM	\$2,476.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user gabelj3 overridding Payment Estimate Exception 19 on the current Payment Estimate.													
									12	Oct 4, 2022	SYSTEM	(\$2,476.50)											
										SYSTEM	\$2,476.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0104) due to user linkd1 overridding Payment Estimate Exception 18 on the current Payment Estimate.											
					13	Oct 18, 2022	SYSTEM	(\$2,476.50)															
					14	Nov 3,	SYSTEM	\$2,476.50	This adjustment offsets the original system-generated Material Payment														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J5I3397	0370	DOWEL BAR (FURNISH AND	Material			2022			Estimate Item Adjustment (0029) due to user linkd1 overridding Payment Estimate Exception 19 on the current Payment Estimate.						
		INSTALL WITH BASK			14	Nov 3, 2022	SYSTEM	(\$2,476.50)							
				- Total				\$0.00							
			Material - To	tal				\$0.00							
			Overrun	Overrun	8	Aug 2, 2022	SYSTEM	(\$390.00)							
					9	Aug 17, 2022	SYSTEM	(\$331.50)							
					12	Oct 4, 2022	SYSTEM	(\$585.00)							
				Overrun - T	otal			(\$1,306.50)							
			Overrun - To	tal				(\$1,306.50)							
	0370 -	Total						(\$1,306.50)							
	0400	CONSTRUCTION SIGNS	Material		2	May 3, 2022	SYSTEM	\$1,998.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user marzua1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
					2	May 3, 2022	SYSTEM	(\$1,998.00)							
					3	May 16, 2022	SYSTEM	\$1,998.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user marzua1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
					3	May 16, 2022	SYSTEM	(\$1,998.00)							
					4	Jun 2, 2022	SYSTEM	\$1,998.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate.						
					4	Jun 2, 2022	SYSTEM	(\$1,998.00)							
					5	Jun 17, 2022	SYSTEM	\$1,998.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user linkd1 overridding Payment Estimate Exception 17 on the current Payment Estimate.						
					5	Jun 17, 2022	SYSTEM	(\$1,998.00)							
					6	Jul 2, 2022	SYSTEM	\$1,998.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user abbote1 overridding Payment Estimate Exception 24 on the current Payment Estimate.						
					6	Jul 1, 2022	SYSTEM	(\$1,998.00)							
					7	Jul 19, 2022	SYSTEM	\$1,998.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user linkd1 overridding Payment Estimate Exception 18 on the current Payment Estimate.						
					7	Jul 19, 2022	SYSTEM	(\$1,998.00)							
					8	Aug 2, 2022	SYSTEM	\$3,046.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment Estimate Exception 17 on the current Payment Estimate.						
					8	Aug 2, 2022	SYSTEM	(\$3,046.50)							
					9	Aug 17, 2022	SYSTEM	\$4,594.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 17 on the current Payment Estimate.						
					9	Aug 17, 2022	SYSTEM	(\$4,594.50)							
										10	Sep 6, 2022	SYSTEM	\$6,088.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user linkd1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
					10	Sep 6, 2022	SYSTEM	(\$6,088.50)							
											11	Sep 16, 2022	SYSTEM	\$7,474.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user linkd1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					11	Sep 16, 2022	SYSTEM	(\$7,474.50)							
					12	Oct 4,	SYSTEM	\$8,887.50	This adjustment offsets the original system-generated Material Payment						



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																						
513397	0400	CONSTRUCTION SIGNS	Material			2022			Estimate Item Adjustment (0027) due to user gabelj3 overridding Payment Estimate Exception 21 on the current Payment Estimate.																						
					12	Oct 4, 2022	SYSTEM	(\$8,887.50)																							
				- Total				\$0.00																							
			Material - To	tal				\$0.00																							
	0400 -	Total						\$0.00																							
	0410	ADVANCED WARNING RAIL SYSTEM	Material		8	Aug 2, 2022	SYSTEM	\$50.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user linkd1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																						
					8	Aug 2, 2022	SYSTEM	(\$50.00)																							
					9	Aug 17, 2022	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user linkd1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																						
					9	Aug 17, 2022	SYSTEM	(\$200.00)																							
					10	Sep 6, 2022	SYSTEM	\$350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																						
					10	Sep 6, 2022	SYSTEM	(\$350.00)																							
															11	Sep 16, 2022	SYSTEM	\$350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user linkd1 overridding Payment Estimate Exception 23 on the current Payment Estimate.												
						11	Sep 16, 2022	SYSTEM	(\$350.00)																						
								12	Oct 4, 2022	SYSTEM	\$350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user gabelj3 overridding Payment Estimate Exception 23 on the current Payment Estimate.																			
					12	Oct 4, 2022	SYSTEM	(\$350.00)																							
				- Total				\$0.00																							
			Material - To	Material - Total				\$0.00																							
	0410 -	Total						\$0.00																							
	0420	CHANNELIZER (TRIM LINE)	Material		8	Aug 2, 2022	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user linkd1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																						
						8	Aug 2, 2022	SYSTEM	(\$5,600.00)																						
					9	Aug 17, 2022	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																						
						9	9	Aug 17, 2022	SYSTEM	(\$5,600.00)																					
							10												1								10	Sep 6, 2022	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user linkd1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
										10	Sep 6, 2022	SYSTEM	(\$5,600.00)																		
					11	Sep 16, 2022	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user linkd1 overridding Payment Estimate Exception 25 on the current Payment Estimate.																						
			11	11	Sep 16, 2022	SYSTEM	(\$5,600.00)																								
					12	Oct 4, 2022	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user gabelj3 overridding Payment Estimate Exception 25 on the current Payment Estimate.																						
					12	Oct 4, 2022	SYSTEM	(\$5,600.00)																							
				- Total				\$0.00																							
			Material - To	tal				\$0.00																							
	0420 -	Total						\$0.00																							
	0430	DIRECTIONAL INDICATOR	Material		6	Jul 2, 2022	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user abbote1 overridding Payment																						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5I3397	0430	BARRICADE	Material						Estimate Exception 28 on the current Payment Estimate.
					6	Jul 1, 2022	SYSTEM	(\$700.00)	
					7	Jul 19, 2022	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					7	Jul 19, 2022	SYSTEM	(\$700.00)	
					8	Aug 2, 2022	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user linkd1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					8	Aug 2, 2022	SYSTEM	(\$1,050.00)	
					9	Aug 17, 2022	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user linkd1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					9	Aug 17, 2022	SYSTEM	(\$1,400.00)	
					10	Sep 6, 2022	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user linkd1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					10	Sep 6, 2022	SYSTEM	(\$1,750.00)	
					11	Sep 16, 2022	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user linkd1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					11	Sep 16, 2022	SYSTEM	(\$1,750.00)	
					12	Oct 4, 2022	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user gabelj3 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					12	Oct 4, 2022	SYSTEM	(\$1,750.00)	
						2022			
				- Total		2022		\$0.00	
			Material - To			2022		\$0.00	
	0430 -							\$0.00 \$0.00	
	0430 - 0440	Total FLASHING ARROW PANEL	Material - Tot		8	Aug 2, 2022	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user linkd1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
		FLASHING			8	Aug 2,	SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0024) due to user linkd1 overridding Payment
		FLASHING				Aug 2, 2022		\$0.00 \$0.00 \$500.00	Estimate Item Adjustment (0024) due to user linkd1 overridding Payment
		FLASHING			8	Aug 2, 2022 Aug 2, 2022 Aug 17,	SYSTEM	\$0.00 \$0.00 \$500.00 (\$500.00)	Estimate Item Adjustment (0024) due to user link11 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user link11 overridding Payment
		FLASHING			8	Aug 2, 2022 Aug 2, 2022 Aug 17, 2022 Aug 17,	SYSTEM	\$0.00 \$0.00 \$500.00 (\$500.00) \$1,000.00	Estimate Item Adjustment (0024) due to user link11 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user link11 overridding Payment
		FLASHING			9	Aug 2, 2022 Aug 2, 2022 Aug 17, 2022 Aug 17, 2022 Sep 6,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 (\$500.00) \$1,000.00	Estimate Item Adjustment (0024) due to user linkd1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user linkd1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user linkd1 overridding Payment
		FLASHING			9 9 10	Aug 2, 2022 Aug 2, 2022 Aug 17, 2022 Aug 17, 2022 Sep 6, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 (\$500.00) \$1,000.00 (\$1,000.00)	Estimate Item Adjustment (0024) due to user linkd1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user linkd1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user linkd1 overridding Payment
		FLASHING			8 9 9 10 10	Aug 2, 2022 Aug 2, 2022 Aug 17, 2022 Aug 17, 2022 Sep 6, 2022 Sep 6, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 (\$500.00) \$1,000.00 (\$1,000.00) \$1,500.00	Estimate Item Adjustment (0024) due to user link11 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user link11 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user link11 overridding Payment Estimate Exception 28 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user link11 overridding Payment Estimate Item Adjustment (0026) due to user link11 overridding Payment
		FLASHING			8 9 9 10 10	Aug 2, 2022 Aug 2, 2022 Aug 17, 2022 Sep 6, 2022 Sep 16, 2022 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 \$500.00 \$1,000.00 \$1,500.00 \$1,500.00 \$1,500.00	Estimate Item Adjustment (0024) due to user link11 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user link11 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user link11 overridding Payment Estimate Exception 28 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user link11 overridding Payment Estimate Item Adjustment (0026) due to user link11 overridding Payment
		FLASHING		tal	9 9 10 10 11 11 11	Aug 2, 2022 Aug 2, 2022 Aug 17, 2022 Aug 17, 2022 Sep 6, 2022 Sep 16, 2022 Sep 16, 2022 Oct 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 (\$500.00) \$1,000.00 (\$1,000.00) \$1,500.00 (\$1,500.00)	Estimate Item Adjustment (0024) due to user link11 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user link11 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user link11 overridding Payment Estimate Exception 28 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user link11 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 29 on the current Payment Estimate.
		FLASHING	Material	- Total	8 9 9 10 10 11 11 11 12	Aug 2, 2022 Aug 17, 2022 Aug 17, 2022 Sep 6, 2022 Sep 16, 2022 Sep 16, 2022 Oct 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 \$500.00 (\$500.00) \$1,000.00 (\$1,000.00) \$1,500.00 (\$1,500.00) \$1,500.00 (\$1,500.00) \$1,500.00	Estimate Item Adjustment (0024) due to user link11 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user link11 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user link11 overridding Payment Estimate Exception 28 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user link11 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 29 on the current Payment Estimate.
	0440	FLASHING ARROW PANEL		- Total	8 9 9 10 10 11 11 11 12	Aug 2, 2022 Aug 17, 2022 Aug 17, 2022 Sep 6, 2022 Sep 16, 2022 Sep 16, 2022 Oct 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 (\$500.00) \$1,000.00 (\$1,000.00) \$1,500.00 (\$1,500.00) \$1,500.00 (\$1,500.00) \$0.00	Estimate Item Adjustment (0024) due to user link11 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user link11 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user link11 overridding Payment Estimate Exception 28 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user link11 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 29 on the current Payment Estimate.
		FLASHING ARROW PANEL	Material - To	- Total	8 9 9 10 10 11 11 11 12	Aug 2, 2022 Aug 17, 2022 Aug 17, 2022 Sep 6, 2022 Sep 16, 2022 Sep 16, 2022 Oct 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 \$500.00 (\$500.00) \$1,000.00 (\$1,000.00) \$1,500.00 (\$1,500.00) \$1,500.00 (\$1,500.00) \$1,500.00	Estimate Item Adjustment (0024) due to user link11 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user link11 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user link11 overridding Payment Estimate Exception 28 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user link11 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 29 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J5I3397	0460	INTERFACE,	Material						Estimate Exception 27 on the current Payment Estimate.					
		CONT F/			8	Aug 2, 2022	SYSTEM	(\$7,800.00)						
					9	Aug 17, 2022	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user linkd1 overridding Payment Estimate Exception 27 on the current Payment Estimate.					
					9	Aug 17, 2022	SYSTEM	(\$10,400.00)						
					10	Sep 6, 2022	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user linkd1 overridding Payment Estimate Exception 30 on the current Payment Estimate.					
					10	Sep 6, 2022	SYSTEM	(\$10,400.00)						
					11	Sep 16, 2022	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user linkd1 overridding Payment Estimate Exception 31 on the current Payment Estimate.					
					11	Sep 16, 2022	SYSTEM	(\$10,400.00)						
					12	Oct 4, 2022	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user gabelj3 overridding Payment Estimate Exception 31 on the current Payment Estimate.					
					12	Oct 4, 2022	SYSTEM	(\$13,000.00)						
				- Total				\$0.00						
			Material - To	tal				\$0.00						
	0460 -	Total						\$0.00						
	0470	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		9	Aug 17, 2022	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user linkd1 overridding Payment Estimate Exception 29 on the current Payment Estimate.					
					9	Aug 17, 2022	SYSTEM	(\$400.00)						
					10	Sep 6, 2022	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user linkd1 overridding Payment Estimate Exception 32 on the current Payment Estimate.					
								10	Sep 6, 2022	SYSTEM	(\$4,800.00)			
					11	Sep 16, 2022	SYSTEM	\$7,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user linkd1 overridding Payment Estimate Exception 33 on the current Payment Estimate.					
										11	Sep 16, 2022	SYSTEM	(\$7,200.00)	
							12	Oct 4, 2022	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user gabelj3 overridding Payment Estimate Exception 33 on the current Payment Estimate.			
					12	Oct 4, 2022	SYSTEM	(\$8,800.00)						
				- Total				\$0.00						
			Material - To	tal				\$0.00						
	0470 - 0500	CONCRETE			10	Sep 6,	SYSTEM	\$0.00 \$12,357.07	Payment Estimate Item Adjustment generated Stockpile Transaction					
		TRAFFIC BARRIER, TYPE D (MOMENT SLAB)	Stockpile STMI	- Total		2022		\$12,357.07						
		, , , , , , , , , , , , , , , , , , , ,	Construction	Stockpile S	ΓΜΙ - Total			\$12,357.07						
	0500 -	Total						\$12,357.07						
	0510	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material		10	Sep 6, 2022	SYSTEM	\$5,781.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user linkd1 overridding Payment Estimate Exception 33 on the current Payment Estimate.					
		FURIV/RE			10	Sep 6, 2022	SYSTEM	(\$5,781.25)						
						11	Sep 16, 2022	SYSTEM	\$10,868.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user linkd1 overridding Payment Estimate Exception 34 on the current Payment Estimate.				
						11	Sep 16, 2022	SYSTEM	(\$10,868.75)					
					12	Oct 4,	SYSTEM	\$19,656.25	This adjustment offsets the original system-generated Material Payment					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																								
J5I3397	0510	TEMPORARY TRAFFIC	Material			2022			Estimate Item Adjustment (0034) due to user gabelj3 overridding Payment Estimate Exception 34 on the current Payment Estimate.																								
		BARRIER, CONT. FURN/RE			12	Oct 4, 2022	SYSTEM	(\$19,656.25)																									
					13	Oct 18, 2022	SYSTEM	\$23,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0105) due to user linkd1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																								
					13	Oct 18, 2022	SYSTEM	(\$23,125.00)																									
					14	Nov 3, 2022	SYSTEM	\$57,581.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user linkd1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																								
					14	Nov 3, 2022	SYSTEM	(\$57,581.25)																									
				- Total				\$0.00																									
			Material - To	tal				\$0.00																									
	0510 -							\$0.00																									
	0520	TEMP. TRAFFIC BARRIER ANCHORED., CONT	Material		9	Aug 17, 2022	SYSTEM	\$212,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user linkd1 overridding Payment Estimate Exception 30 on the current Payment Estimate.																								
		CONT								9	Aug 17, 2022	SYSTEM	(\$212,687.50)																				
						10	Sep 6, 2022	SYSTEM	\$424,862.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user linkd1 overridding Payment Estimate Exception 34 on the current Payment Estimate.																							
					10	Sep 6, 2022	SYSTEM	(\$424,862.50)																									
					11	Sep 16, 2022	SYSTEM	\$583,737.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user linkd1 overridding Payment Estimate Exception 35 on the current Payment Estimate.																								
																					11	Sep 16, 2022	SYSTEM	(\$583,737.50)									
						12	Oct 4, 2022	SYSTEM	\$783,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user gabelj3 overridding Payment Estimate Exception 35 on the current Payment Estimate.																							
										12	Oct 4, 2022	SYSTEM	(\$783,100.00)																				
					13	Oct 18, 2022	SYSTEM	\$1,046,012.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0106) due to user linkd1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																								
																13	Oct 18, 2022	SYSTEM	(\$1,046,012.50)														
									14	Nov 3, 2022	SYSTEM	\$1,279,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																				
					14	Nov 3, 2022	SYSTEM	(\$1,279,200.00)																									
				- Total				\$0.00																									
			Material - To	tal				\$0.00																									
	0520 -							\$0.00																									
	0550	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	IILD RNE	BUILD	ILD RNE		10	Sep 6, 2022	SYSTEM	\$193.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user linkd1 overridding Payment Estimate Exception 36 on the current Payment Estimate.																						
		174141						10	Sep 6, 2022	SYSTEM	(\$193.60)																						
																													11	Sep 16, 2022	SYSTEM	\$566.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user linkd1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
																				11	Sep 16, 2022	SYSTEM	(\$566.28)										
						12	Oct 4, 2022	SYSTEM	\$922.24	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user gabelj3 overridding Payment Estimate Exception 37 on the current Payment Estimate.																							
					12	1:			12	Oct 4, 2022	SYSTEM	(\$922.24)																					
					13	Oct 18,	SYSTEM	\$1,044.78	This adjustment offsets the original system-generated Material Payment																								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																								
J5I3397	0550	6 IN. WHITE HIGH BUILD	Material			2022			Estimate Item Adjustment (0107) due to user linkd1 overridding Payment Estimate Exception 23 on the current Payment Estimate.																								
		WATERBORNE PAINT			13	Oct 18, 2022	SYSTEM	(\$1,044.78)																									
					14	Nov 3, 2022	SYSTEM	\$1,044.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user linkd1 overridding Payment Estimate Exception 24 on the current Payment Estimate.																								
					14	Nov 3, 2022	SYSTEM	(\$1,044.78)																									
				- Total				\$0.00																									
			Material - To	tal				\$0.00																									
	0550 -	Total						\$0.00																									
	0560	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material		10	Sep 6, 2022	SYSTEM	\$1,166.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user linkd1 overridding Payment Estimate Exception 38 on the current Payment Estimate.																								
					10	Sep 6, 2022	SYSTEM	(\$1,166.00)																									
					11	Sep 16, 2022	SYSTEM	\$1,166.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user linkd1 overridding Payment Estimate Exception 39 on the current Payment Estimate.																								
								11	Sep 16, 2022	SYSTEM	(\$1,166.00)																						
							12	Oct 4, 2022	SYSTEM	\$1,386.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user gabelj3 overridding Payment Estimate Exception 39 on the current Payment Estimate.																						
						12	Oct 4, 2022	SYSTEM	(\$1,386.00)																								
								13	Oct 18, 2022	SYSTEM	\$1,386.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0108) due to user linkd1 overridding Payment Estimate Exception 25 on the current Payment Estimate.																					
					13	Oct 18, 2022	SYSTEM	(\$1,386.00)																									
											14	Nov 3, 2022	SYSTEM	\$1,386.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user linkd1 overridding Payment Estimate Exception 26 on the current Payment Estimate.																		
					14	Nov 3, 2022	SYSTEM	(\$1,386.00)																									
				- Total				\$0.00																									
			Material - To	tal				\$0.00																									
	0560 -	Total						\$0.00																									
	0580	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		9	Aug 17, 2022	SYSTEM	\$3,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user linkd1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																								
		WARRING				9	Aug 17, 2022	SYSTEM	(\$3,540.00)																								
					10	Sep 6, 2022	SYSTEM	\$4,335.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user linkd1 overridding Payment Estimate Exception 40 on the current Payment Estimate.																								
			2022 11 Sep 16, SYSTEM \$6,23 11 Sep 16, SYSTEM (\$6,23				10		SYSTEM	(\$4,335.00)																							
																															11		SYSTEM
				(\$6,235.00)																													
					12		SYSTEM	\$8,725.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user gabelj3 overridding Payment Estimate Exception 43 on the current Payment Estimate.																								
					12	Oct 4, 2022	SYSTEM	(\$8,725.00)																									
						13	Oct 18, 2022	SYSTEM	\$12,355.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0109) due to user linkd1 overridding Payment Estimate Exception 29 on the current Payment Estimate.																							
					13	Oct 18, 2022	SYSTEM	(\$12,355.00)																									
						14	Nov 3,	SYSTEM	\$15,110.00	This adjustment offsets the original system-generated Material Payment																							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J5l3397	0580	4 IN. WHITE WATERBORNE	Material			2022			Estimate Item Adjustment (0034) due to user linkd1 overridding Payment Estimate Exception 30 on the current Payment Estimate.			
		PAVEMENT MARKING			14	Nov 3, 2022	SYSTEM	(\$15,110.00)				
				- Total				\$0.00				
			Material - Tot	al				\$0.00				
	0580 -	Total						\$0.00				
	0590	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		9	Aug 17, 2022	SYSTEM	\$4,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user linkd1 overridding Payment Estimate Exception 34 on the current Payment Estimate.			
					9	Aug 17, 2022	SYSTEM	(\$4,350.00)				
					10	Sep 6, 2022	SYSTEM	\$15,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user linkd1 overridding Payment Estimate Exception 42 on the current Payment Estimate.			
					10	Sep 6, 2022	SYSTEM	(\$15,935.00)				
					11	Sep 16, 2022	SYSTEM	\$15,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user linkd1 overridding Payment Estimate Exception 43 on the current Payment Estimate.			
					11	Sep 16, 2022	SYSTEM	(\$15,935.00)				
					12	Oct 4, 2022	SYSTEM	\$15,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user gabelj3 overridding Payment Estimate Exception 47 on the current Payment Estimate.			
						12	Oct 4, 2022	SYSTEM	(\$15,935.00)			
								13	Oct 18, 2022	SYSTEM	\$15,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0110) due to user linkd1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
						13	Oct 18, 2022	SYSTEM	(\$15,935.00)			
									14	Nov 3, 2022	SYSTEM	\$16,937.50
					14	Nov 3, 2022	SYSTEM	(\$16,937.50)				
				- Total				\$0.00				
			Material - Tot	rial - Total				\$0.00				
	0590 -	Total						\$0.00				
	0640	SEPARATION GEOTEXTILE	Construction Stockpile STMI		2	May 3, 2022	SYSTEM	\$9,760.00	Payment Estimate Item Adjustment generated Stockpile Transaction			
			C11411	- Total				\$9,760.00				
			Construction	Stockpile S1	MI - Tota			\$9,760.00				
	0640 -	Total						\$9,760.00				
	0880	MGS GUARDRAIL	Construction Stockpile		5	Jun 17, 2022	SYSTEM	(\$10,831.80)	Payment Estimate Item Adjustment generated Stockpile Transaction			
					6	Jul 1, 2022	SYSTEM	(\$281,069.71)	Payment Estimate Item Adjustment generated Stockpile Transaction			
					7	Jul 19, 2022	SYSTEM	(\$51,896.96)	Payment Estimate Item Adjustment generated Stockpile Transaction			
							9	Aug 17, 2022	SYSTEM	(\$9,412.69)	Payment Estimate Item Adjustment generated Stockpile Transaction	
					11	Sep 16, 2022	SYSTEM	(\$25,968.83)	Payment Estimate Item Adjustment generated Stockpile Transaction			
					12	Oct 4, 2022	SYSTEM	(\$10,939.06)	Payment Estimate Item Adjustment generated Stockpile Transaction			
				1	13	13	Oct 17, 2022	SYSTEM	(\$13,483.04)	Payment Estimate Item Adjustment generated Stockpile Transaction		
				- Total				(\$403,602.09)				
			Construction	Stockpile - 1	otal			(\$403,602.09)				
					5	Jun 17, 2022	SYSTEM	\$162,977.88	Payment Estimate Item Adjustment generated Stockpile Transaction			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J5I3397	0880	MGS GUARDRAIL	Construction Stockpile STMA		6	Jul 1, 2022	SYSTEM	\$160,580.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			STIVIA	- Total				\$323,557.88		
			Construction	Stockpile S	ΓMA - Tota	ıl		\$323,557.88		
			Construction Stockpile		2	May 3, 2022	SYSTEM	\$128,923.63	Payment Estimate Item Adjustment generated Stockpile Transaction	
			STMI		6	Jul 1, 2022	SYSTEM	\$128,923.63	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$257,847.26		
			Construction	Stockpile S	ГМI - Total			\$257,847.26		
			Material		5	Jun 17, 2022	SYSTEM	\$11,459.91	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					5	Jun 17, 2022	SYSTEM	(\$11,459.91)		
					6	Jul 2, 2022	SYSTEM	\$26,455.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user abbote1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					6	Jul 1, 2022	SYSTEM	(\$26,455.66)		
		Total		- Total				\$0.00		
			Material - Tot	tal				\$0.00		
	0880 -	Total						\$177,803.05		
	0890	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Construction Stockpile		6	Jul 1, 2022	SYSTEM	(\$398,381.48)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		F1 3 IIV				7	Jul 19, 2022	SYSTEM	(\$68,235.93)	Payment Estimate Item Adjustment generated Stockpile Transaction
					8	Aug 2, 2022	SYSTEM	(\$109,759.35)	Payment Estimate Item Adjustment generated Stockpile Transaction	
					9	Aug 17, 2022	SYSTEM	(\$14,017.46)	Payment Estimate Item Adjustment generated Stockpile Transaction	
					10	Sep 6, 2022	SYSTEM	(\$97,593.25)	Payment Estimate Item Adjustment generated Stockpile Transaction	
					11	Sep 16, 2022	SYSTEM	(\$20,629.47)	Payment Estimate Item Adjustment generated Stockpile Transaction	
					14	Nov 3, 2022	SYSTEM	(\$9,256.81)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$717,873.75)		
			Construction	Stockpile - 1				(\$717,873.75)		
			Construction Stockpile STMA		5	Jun 17, 2022	SYSTEM	\$174,832.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
					6	Jul 1, 2022	SYSTEM	\$174,832.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$349,664.00		
			Construction	Stockpile S				\$349,664.00		
			Construction Stockpile STMI		2	May 3, 2022	SYSTEM	\$189,695.99	Payment Estimate Item Adjustment generated Stockpile Transaction	
					6	Jul 1, 2022	SYSTEM	\$189,695.99	Payment Estimate Item Adjustment generated Stockpile Transaction	
			0	- Total				\$379,391.98		
			Construction	Stockpile S			OVOTEL	\$379,391.98	This adjustment offsets the original week	
			Material		6	Jul 2, 2022	SYSTEM	\$118,261.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user abbote1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					6	Jul 1, 2022	SYSTEM	(\$118,261.12)		
				- Total				\$0.00		
			Material - Tot	al				\$0.00		
	0890 -	Total						\$11,182.23		
	0910	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile		6	Jul 1, 2022	SYSTEM	(\$18,000.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J5I3397	0910	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile		9	Aug 17, 2022	SYSTEM	(\$2,250.00)	Payment Estimate Item Adjustment generated Stockpile Transaction															
		(NEG/NO CONB)		- Total				(\$20,250.00)																
			Construction	Stockpile - 1	Total			(\$20,250.00)																
			Construction Stockpile STMA		6	Jul 1, 2022	SYSTEM	\$17,880.00	Payment Estimate Item Adjustment generated Stockpile Transaction															
			OTIVIA	- Total				\$17,880.00																
			Construction	Stockpile S	ΓMA - Tota	al		\$17,880.00																
			Construction Stockpile STMI		2	May 3, 2022	SYSTEM	\$9,060.00	Payment Estimate Item Adjustment generated Stockpile Transaction															
					6	Jul 1, 2022	SYSTEM	\$9,060.00	Payment Estimate Item Adjustment generated Stockpile Transaction															
				- Total				\$18,120.00																
			Construction	Stockpile S	MI - Tota			\$18,120.00																
	0910 -							\$15,750.00																
	0920	MGS VERTICAL CONCRETE BARRIER	Construction Stockpile		13	Oct 17, 2022	SYSTEM	(\$8,940.00)	Payment Estimate Item Adjustment generated Stockpile Transaction															
		TRANSITION		- Total				(\$8,940.00)																
			Construction	Stockpile - 1	Total			(\$8,940.00)																
			Construction Stockpile STMI		6	Jul 1, 2022	SYSTEM	\$8,940.00	Payment Estimate Item Adjustment generated Stockpile Transaction															
				- Total				\$8,940.00																
			Construction	Stockpile S	MI - Total			\$8,940.00																
			Material		13	Oct 18, 2022	SYSTEM	\$13,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0111) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.															
					13	Oct 18, 2022	SYSTEM	(\$13,400.00)																
					14	Nov 3, 2022	SYSTEM	\$13,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate.															
					14	Nov 3, 2022	SYSTEM	(\$13,400.00)																
				- Total				\$0.00																
			Material - Tot	al				\$0.00																
	0920 -							\$0.00																
	0930	MGS END ANCHOR	Construction Stockpile		5	Jun 17, 2022	SYSTEM	(\$926.47)	Payment Estimate Item Adjustment generated Stockpile Transaction															
						6	Jul 1, 2022	SYSTEM	(\$29,046.63)	Payment Estimate Item Adjustment generated Stockpile Transaction														
							7	Jul 19, 2022	SYSTEM	(\$2,172.42)	Payment Estimate Item Adjustment generated Stockpile Transaction													
																				8	Aug 2, 2022	SYSTEM	(\$2,172.41)	Payment Estimate Item Adjustment generated Stockpile Transaction
																		9	Aug 17, 2022	SYSTEM	(\$543.10)	Payment Estimate Item Adjustment generated Stockpile Transaction		
					10	Sep 6, 2022	SYSTEM	(\$543.11)	Payment Estimate Item Adjustment generated Stockpile Transaction															
					11	Sep 16, 2022	SYSTEM	(\$543.10)	Payment Estimate Item Adjustment generated Stockpile Transaction															
					12	Oct 4, 2022	SYSTEM	(\$1,629.31)	Payment Estimate Item Adjustment generated Stockpile Transaction															
										13	Oct 17, 2022	SYSTEM	(\$1,086.21)	Payment Estimate Item Adjustment generated Stockpile Transaction										
					14	Nov 3, 2022	SYSTEM	(\$543.10)	Payment Estimate Item Adjustment generated Stockpile Transaction															
				- Total				(\$39,205.86)																
			Construction	Stockpile - 1	Total			(\$39,205.86)																
			Construction Stockpile STMA		6	Jul 1, 2022	SYSTEM	\$13,680.00	Payment Estimate Item Adjustment generated Stockpile Transaction															
			J	- Total				\$13,680.00																



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
397	0930	MGS END	Construction	Stockpile S1	MA - Tota	ıl		\$13,680.00		
		ANCHOR	Construction Stockpile		2	May 3, 2022	SYSTEM	\$15,750.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			STMI		6	Jul 1, 2022	SYSTEM	\$15,750.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$31,500.00		
			Construction	Stockpile S1	MI - Tota			\$31,500.00		
	0930 -	Total						\$5,974.14		
	0940	TYPE A CRASHWORTHY	Construction Stockpile		5	Jun 17, 2022	SYSTEM	(\$1,911.90)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		END TERMINAL (MASH)			6	Jul 1, 2022	SYSTEM	(\$74,538.10)	Payment Estimate Item Adjustment generated Stockpile Transaction	
					7	Jul 19, 2022	SYSTEM	(\$10,331.08)	Payment Estimate Item Adjustment generated Stockpile Transaction	
					8	Aug 2, 2022	SYSTEM	(\$4,132.43)	Payment Estimate Item Adjustment generated Stockpile Transaction	
					9	Aug 17, 2022	SYSTEM	(\$6,198.65)	Payment Estimate Item Adjustment generated Stockpile Transaction	
						11	Sep 16, 2022	SYSTEM	(\$4,132.43)	Payment Estimate Item Adjustment generated Stockpile Transaction
					12	Oct 4, 2022	SYSTEM	(\$6,198.65)	Payment Estimate Item Adjustment generated Stockpile Transaction	
						13	Oct 17, 2022	SYSTEM	(\$12,397.30)	Payment Estimate Item Adjustment generated Stockpile Transaction
					14	Nov 3, 2022	SYSTEM	(\$2,066.22)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$121,906.76)		
			Construction	Stockpile - 1	otal			(\$121,906.76)		
			Construction Stockpile STMA		6	Jul 1, 2022	SYSTEM	\$72,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$72,600.00		
			Construction Stockpile STMI	Stockpile S1	MA - Tota	ıl		\$72,600.00		
				Stockpile	Stockpile	2	May 3, 2022	SYSTEM	\$40,150.00	Payment Estimate Item Adjustment generated Stockpile Transaction
					6	Jul 1, 2022	SYSTEM	\$40,150.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$80,300.00		
			Construction	n Stockpile STMI - Total				\$80,300.00		
	0940 -	Total						\$30,993.24		
	0950	TYPE B CRASHWORTHY	Stockpile		6	Jul 1, 2022	SYSTEM	\$8,069.52	Payment Estimate Item Adjustment generated Stockpile Transaction	
		END TERMINAL	STMI	- Total				\$8,069.52		
			Construction	Stockpile S1	MI - Tota			\$8,069.52		
	0950 -	Total						\$8,069.52		
	5002	ASYMMETRICAL TRNS. SEC., 6.5 FT. POSTS	Material		6	Jul 2, 2022	SYSTEM	\$966.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user abbote1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
					6	Jul 1, 2022	SYSTEM	(\$966.00)	,	
					7	Jul 19, 2022	SYSTEM	\$966.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					7	Jul 19, 2022	SYSTEM	(\$966.00)		
					8	Aug 2, 2022	SYSTEM	\$966.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					8	Aug 2, 2022	SYSTEM	(\$966.00)		
					9	Aug 17, 2022	SYSTEM	\$966.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																										
J5I3397	5002	ASYMMETRICAL TRNS. SEC., 6.5	Material		9	Aug 17, 2022	SYSTEM	(\$966.00)																											
		FT. POSTS			10	Sep 6, 2022	SYSTEM	\$966.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																										
					10	Sep 6, 2022	SYSTEM	(\$966.00)																											
					11	Sep 16, 2022	SYSTEM	\$966.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate.																										
					11	Sep 16, 2022	SYSTEM	(\$966.00)																											
					12	Oct 4, 2022	SYSTEM	\$1,932.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user gabelj3 overridding Payment Estimate Exception 11 on the current Payment Estimate.																										
					12	Oct 4, 2022	SYSTEM	(\$1,932.00)																											
					13	Oct 18, 2022	SYSTEM	\$1,932.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0112) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate.																										
					13	Oct 18, 2022	SYSTEM	(\$1,932.00)																											
					14	Nov 3, 2022	SYSTEM	\$1,932.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																										
					14	Nov 3, 2022	SYSTEM	(\$1,932.00)																											
				- Total				\$0.00																											
			Material - Tot	al				\$0.00																											
			Overrun	Overrun	12	Oct 4, 2022	SYSTEM	(\$966.00)																											
				Overrun - To	otal			(\$966.00)																											
			Overrun - To	tal				(\$966.00)																											
	5002 -	Total						(\$966.00)																											
	5003	MGS HEIGHT AND BLOCK TRANSITION	Material		6	Jul 2, 2022	SYSTEM	\$1,701.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user abbote1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																										
							6	Jul 1, 2022	SYSTEM	(\$1,701.00)																									
					7	Jul 19, 2022	SYSTEM	\$1,701.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.																										
							8	7	Jul 19, 2022	SYSTEM	(\$1,701.00)																								
													8	Aug 2, 2022	SYSTEM	\$1,701.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																		
																						9	9	9			8	8	8	8	8	Aug 2, 2022	SYSTEM	(\$1,701.00)	
																											9	Aug 17, 2022	SYSTEM	\$1,701.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
																									9	Aug 17, 2022	SYSTEM	(\$1,701.00)							
								10	10	Sep 6, 2022	SYSTEM	\$1,701.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																						
					10	Sep 6, 2022	SYSTEM	(\$1,701.00)																											
						11			11	Sep 16, 2022	SYSTEM	\$1,701.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																						
							11	Sep 16, 2022	SYSTEM	(\$1,701.00)																									
					12	Oct 4, 2022	SYSTEM	\$3,402.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user gabelj3 overridding Payment Estimate Exception 10 on the current Payment Estimate.																										



					_								
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J5l3397	5003	MGS HEIGHT AND BLOCK	Material		12	Oct 4, 2022	SYSTEM	(\$3,402.00)					
		TRANSITION			13	Oct 18, 2022	SYSTEM	\$3,402.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0113) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate.				
					13	Oct 18, 2022	SYSTEM	(\$3,402.00)					
					14	Nov 3, 2022	SYSTEM	\$3,402.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate.				
					14	Nov 3, 2022	SYSTEM	(\$3,402.00)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
			Overrun	Overrun	12	Oct 4, 2022	SYSTEM	(\$1,701.00)					
				Overrun - T	otal			(\$1,701.00)					
			Overrun - To	tal				(\$1,701.00)					
	5003 -	· Total						(\$1,701.00)					
	5004	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5	Material		6	Jul 2, 2022	SYSTEM	\$3,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user abbote1 overridding Payment Estimate Exception 11 on the current Payment Estimate.				
					6	Jul 1, 2022	SYSTEM	(\$3,424.00)					
				- Total				\$0.00					
			Material - To					\$0.00					
			Overrun	Overrun	13	Oct 18, 2022	SYSTEM	(\$1,712.00)					
				Overrun - T	otal			(\$1,712.00)					
			Overrun - To	tal				(\$1,712.00)					
	5004 -	· Total						(\$1,712.00)					
	5005	Total MGS GUARDRAIL, 6 FT. POSTS, 1 FT 6.75	Material		6	Jul 2, 2022	SYSTEM	\$5,398.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user abbote1 overridding Payment Estimate Exception 13 on the current Payment Estimate.				
					6	Jul 1, 2022	SYSTEM	(\$5,398.12)					
					- Total			\$0.00					
			Material - To	tal				\$0.00					
	5005 -	· Total						\$0.00					
J5l3397 -	Total							\$194,574.59					
J5I3482	1140	CONSTRUCTION SIGNS	Overrun	Overrun	5	Jun 17, 2022	SYSTEM	(\$882.00)					
				Overrun - T	otal			(\$882.00)					
			Overrun - To	tal				(\$882.00)					
	1140 -	· Total						(\$882.00)					
	1150	ADVANCED WARNING RAIL SYSTEM	Material		5	Jun 17, 2022	SYSTEM	\$150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 18 on the current Payment Estimate.				
					5	Jun 17, 2022	SYSTEM	(\$150.00)					
					6	Jul 2, 2022	SYSTEM	\$150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user abbote1 overridding Payment Estimate Exception 25 on the current Payment Estimate.				
					6	Jul 1, 2022	SYSTEM	(\$150.00)					
					7	Jul 19, 2022	SYSTEM	\$150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 19 on the current Payment Estimate.				
					7	Jul 19, 2022	SYSTEM	(\$150.00)					
									8	Aug 2, 2022	SYSTEM	\$150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment
									g. symon				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J5I3482	1150	ADVANCED	Material						Estimate Exception 18 on the current Payment Estimate.								
		WARNING RAIL SYSTEM			8	Aug 2, 2022	SYSTEM	(\$150.00)									
					9	Aug 17, 2022	SYSTEM	\$150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 18 on the current Payment Estimate.								
					9	Aug 17, 2022	SYSTEM	(\$150.00)									
					10	Sep 6, 2022	SYSTEM	\$150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 21 on the current Payment Estimate.								
					10	Sep 6, 2022	SYSTEM	(\$150.00)									
					11	Sep 16, 2022	SYSTEM	\$150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.								
					11	Sep 16, 2022	SYSTEM	(\$150.00)									
					12	Oct 4, 2022	SYSTEM	\$150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user gabelj3 overridding Payment Estimate Exception 22 on the current Payment Estimate.								
					12	Oct 4, 2022	SYSTEM	(\$150.00)									
				- Total				\$0.00									
			Material - To	tal				\$0.00									
	1150 -	Total						\$0.00									
	1170	CHANNELIZER (TRIM LINE)	Material		5	Jun 17, 2022	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 19 on the current Payment Estimate.								
							5	Jun 17, 2022	SYSTEM	(\$800.00)							
								6	Jul 2, 2022	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user abbote1 overridding Payment Estimate Exception 26 on the current Payment Estimate.					
					6	Jul 1, 2022	SYSTEM	(\$800.00)									
					7	Jul 19, 2022	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 20 on the current Payment Estimate.								
					7	Jul 19, 2022	SYSTEM	(\$800.00)									
					8	Aug 2, 2022	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 20 on the current Payment Estimate.								
													8	Aug 2, 2022	SYSTEM	(\$800.00)	
														9	Aug 17, 2022	SYSTEM	\$800.00
					9	Aug 17, 2022	SYSTEM	(\$800.00)									
				1	1								10	Sep 6, 2022	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
							10	Sep 6, 2022	SYSTEM	(\$800.00)							
						1	11 Sep 16, SYSTEM 2022	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 24 on the current Payment Estimate.								
											11	Sep 16, 2022	SYSTEM	(\$800.00)			
											12	Oct 4, 2022	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user gabelj3 overridding Payment Estimate Exception 24 on the current Payment Estimate.		
					12	Oct 4, 2022	SYSTEM	(\$800.00)									
				- Total				\$0.00									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J5I3482	1170	CHANNELIZER (TRIM LINE)	Material - To	tal				\$0.00					
	1170 -	Total						\$0.00					
	1180	DIRECTIONAL INDICATOR BARRICADE	Material		5	Jun 17, 2022	SYSTEM	\$280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user linkd1 overridding Payment Estimate Exception 20 on the current Payment Estimate.				
					5	Jun 17, 2022	SYSTEM	(\$280.00)					
					6	Jul 2, 2022	SYSTEM	\$280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user abbote1 overridding Payment Estimate Exception 27 on the current Payment Estimate.				
					6	Jul 1, 2022	SYSTEM	(\$280.00)					
					7	Jul 19, 2022	SYSTEM	\$280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 21 on the current Payment Estimate.				
					7	Jul 19, 2022	SYSTEM	(\$280.00)					
					8	Aug 2, 2022	SYSTEM	\$280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.				
					8	Aug 2, 2022	SYSTEM	(\$280.00)					
					9	Aug 17, 2022	SYSTEM	\$280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.				
					9	Aug 17, 2022	SYSTEM	(\$280.00)					
					10	Sep 6, 2022	SYSTEM	\$280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 25 on the current Payment Estimate.				
					10	Sep 6, 2022	SYSTEM	(\$280.00)					
					11	Sep 16, 2022	SYSTEM	\$280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 26 on the current Payment Estimate.				
					11	Sep 16, 2022	SYSTEM	(\$280.00)					
								12	Oct 4, 2022	SYSTEM	\$280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user gabelj3 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
					12	Oct 4, 2022	SYSTEM	(\$280.00)					
				- Total				\$0.00					
			Material - To	al				\$0.00					
	1180 -	Total						\$0.00					
	1190	FLASHING ARROW PANEL	Material		5	Jun 17, 2022	SYSTEM	\$25.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment Estimate Exception 21 on the current Payment Estimate.				
					5	Jun 17, 2022	SYSTEM	(\$25.00)					
					6	Jul 2, 2022	SYSTEM	\$25.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user abbote1 overridding Payment Estimate Exception 29 on the current Payment Estimate.				
					6	Jul 1, 2022	SYSTEM	(\$25.00)					
					7	Jul 19, 2022	SYSTEM	\$25.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 23 on the current Payment Estimate.				
					7	Jul 19, 2022	SYSTEM	(\$25.00)					
					8	Aug 2, 2022	SYSTEM	\$25.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 24 on the current Payment Estimate.				
						1	8	Aug 2, 2022	SYSTEM	(\$25.00)			
									9	Aug 17,	SYSTEM	\$25.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5l3482	1190	FLASHING ARROW PANEL	Material			2022			Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					9	Aug 17, 2022	SYSTEM	(\$25.00)	
					10	Sep 6, 2022	SYSTEM	\$25.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					10	Sep 6, 2022	SYSTEM	(\$25.00)	
					11	Sep 16, 2022	SYSTEM	\$25.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					11	Sep 16, 2022	SYSTEM	(\$25.00)	
					12	Oct 4, 2022	SYSTEM	\$25.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user gabelj3 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					12	Oct 4, 2022	SYSTEM	(\$25.00)	
				- Total				\$0.00	
			Material - To	al				\$0.00	
	1190 -	Total						\$0.00	
	1200	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		5	Jun 17, 2022	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user linkd1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					5	Jun 17, 2022	SYSTEM	(\$1,600.00)	
					6	Jul 2, 2022	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user abbote1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					6	Jul 1, 2022	SYSTEM	(\$1,600.00)	
					7	Jul 19, 2022	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					7	Jul 19, 2022	SYSTEM	(\$1,600.00)	
					8	Aug 2, 2022	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					8	Aug 2, 2022	SYSTEM	(\$1,600.00)	
					9	Aug 17, 2022	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					9	Aug 17, 2022	SYSTEM	(\$1,600.00)	
					10	Sep 6, 2022	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					10	Sep 6, 2022	SYSTEM	(\$1,600.00)	
					11	Sep 16, 2022	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					11	Sep 16, 2022	SYSTEM	(\$1,600.00)	
					12	Oct 4, 2022	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user gabelj3 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					12	Oct 4, 2022	SYSTEM	(\$1,600.00)	
				- Total				\$0.00	
			Material - To	al				\$0.00	
	1200 -							\$0.00	
	1370	MGS GUARDRAIL	Construction		6	Jul 1,	SYSTEM	\$7,028.08	Payment Estimate Item Adjustment generated Stockpile Transaction



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J5I3482	1370	MGS GUARDRAIL	Stockpile			2022								
			STMI	- Total				\$7,028.08						
			Construction	Stockpile S	ΓΜΙ - Total			\$7,028.08						
	1370 -	Total						\$7,028.08						
	1380	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile STMI		6	Jul 1, 2022	SYSTEM	\$4,470.00	Payment Estimate Item Adjustment generated Stockpile Transaction					
		(1126/110 00112)	011111	- Total				\$4,470.00						
			Construction	Stockpile S	MI - Total			\$4,470.00						
	1380 -	Total						\$4,470.00						
	1390	MGS VERTICAL CONCRETE BARRIER	Construction Stockpile STMI		6	Jul 1, 2022	SYSTEM	\$4,470.00	Payment Estimate Item Adjustment generated Stockpile Transaction					
		TRANSITION		- Total				\$4,470.00						
			Construction	Stockpile S	「MI - Total			\$4,470.00						
	1390 -	Total						\$4,470.00						
	1400	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile STMI		6	Jul 1, 2022	SYSTEM	\$7,260.00	Payment Estimate Item Adjustment generated Stockpile Transaction					
		(MASH)		- Total				\$7,260.00						
			Construction	Stockpile S	MI - Total			\$7,260.00						
	1400 -	Total						\$7,260.00						
	1510	DIAMOND GRINDING	Overrun	Overrun	11	Sep 16, 2022	SYSTEM	(\$1,612.80)						
				Overrun - T	otal			(\$1,612.80)						
			Overrun - To	tal				(\$1,612.80)						
	1510 -	Total						(\$1,612.80)						
	1520		Construction Stockpile STMI		10	Sep 6, 2022	SYSTEM	\$1,204.28	Payment Estimate Item Adjustment generated Stockpile Transaction					
			OTIVII	- Total				\$1,204.28						
			Construction	Stockpile S	MI - Total			\$1,204.28						
	1520 -	Total						\$1,204.28						
	1590	OPTIONAL CONCRETE WEARING	Material		5	Jun 17, 2022	SYSTEM	\$15,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.					
		SURFACE			5	Jun 17, 2022	SYSTEM	(\$15,700.00)						
					6	Jul 2, 2022	SYSTEM	\$15,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user abbote1 overridding Payment Estimate Exception 7 on the current Payment Estimate.					
					6	Jul 1, 2022	SYSTEM	(\$15,700.00)						
					7	Jul 19, 2022	SYSTEM	\$15,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
					7	Jul 19, 2022	SYSTEM	(\$15,700.00)						
					8	Aug 2, 2022	SYSTEM	\$15,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
					8	Aug 2, 2022	SYSTEM	(\$15,700.00)						
				9	9	Aug 17, 2022	SYSTEM	\$15,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
			9	9	Aug 17, 2022	SYSTEM	(\$15,700.00)							
				10	10	Sep 6, 2022	SYSTEM	\$15,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
					10	Sep 6, 2022	SYSTEM	(\$15,700.00)						
										11	Sep 16, 2022	SYSTEM	\$15,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks			
J5l3482	1590	OPTIONAL CONCRETE	Material	Туре	11	Sep 16, 2022	SYSTEM	(\$15,700.00)				
		WEARING SURFACE			12	Oct 4, 2022	SYSTEM	\$15,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user gabelj3 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					12	Oct 4, 2022	SYSTEM	(\$15,700.00)				
					13	Oct 18, 2022	SYSTEM	\$15,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0099) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					13	Oct 18, 2022	SYSTEM	(\$15,700.00)				
					14	Nov 3, 2022	SYSTEM	\$15,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					14	Nov 3, 2022	SYSTEM	(\$15,700.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	1590 -	Total						\$0.00				
	1610	HALF-SOLE REPAIR	Material		5	Jun 17, 2022	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user linkd1 overridding Payment Estimate Exception 25 on the current Payment Estimate.			
					5	Jun 17, 2022	SYSTEM	(\$3,200.00)				
					6	Jul 2, 2022	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user abbote1 overridding Payment Estimate Exception 33 on the current Payment Estimate.			
							6	Jul 1, 2022	SYSTEM	(\$3,200.00)		
					7	Jul 19, 2022	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user linkd1 overridding Payment Estimate Exception 27 on the current Payment Estimate.			
					7	Jul 19, 2022	SYSTEM	(\$3,200.00)				
					8	Aug 2, 2022	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 30 on the current Payment Estimate.			
					8	Aug 2, 2022	SYSTEM	(\$3,200.00)				
					9	Aug 17, 2022	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 36 on the current Payment Estimate.			
					9	Aug 17, 2022	SYSTEM	(\$3,200.00)				
					10	Sep 6, 2022	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 44 on the current Payment Estimate.			
					10	Sep 6, 2022	SYSTEM	(\$3,200.00)				
					11	Sep 16, 2022	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 45 on the current Payment Estimate.			
								11	Sep 16, 2022	SYSTEM	(\$3,200.00)	
					12	Oct 4, 2022	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user gabelj3 overridding Payment Estimate Exception 49 on the current Payment Estimate.			
					12	Oct 4, 2022	SYSTEM	(\$3,200.00)				
					13	Oct 18, 2022	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0100) due to user linkd1 overridding Payment Estimate Exception 35 on the current Payment Estimate.			
					13	Oct 18, 2022	SYSTEM	(\$3,200.00)				
					14	Nov 3, 2022	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5I3482	1610	HALF-SOLE	Material						Estimate Exception 36 on the current Payment Estimate.
		REPAIR			14	Nov 3, 2022	SYSTEM	(\$3,200.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		- Total						\$0.00	
J5l3482 -								\$21,937.56	
J5l3572	1840	ADVANCED WARNING RAIL SYSTEM	Material		2	May 3, 2022	SYSTEM	\$50.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user marzua1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	May 3, 2022	SYSTEM	(\$50.00)	
				- Total				\$0.00	
			Material - To					\$0.00	
			Overrun	Overrun	3	May 16, 2022	SYSTEM	(\$50.00)	
				Overrun - T	otal			(\$50.00)	
			Overrun - To	tal				(\$50.00)	
	1840 -	- Total						(\$50.00)	
	1850	CHANNELIZER (TRIM LINE)	Material		2	May 3, 2022	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user marzua1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	May 3, 2022	SYSTEM	(\$4,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1850 -							\$0.00	
	1870		Material		2	May 3, 2022	SYSTEM	\$350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user marzua1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
						2	May 3, 2022	SYSTEM	(\$350.00)
				- Total				\$0.00	
			Material - Total						
	1870 -	- Total						\$0.00	
	1880	FLASHING ARROW PANEL	Material		2	May 3, 2022	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user marzua1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					2	May 3, 2022	SYSTEM	(\$500.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1880 -	- Total						\$0.00	
	1960	PAVEMENT EDGE TREATMENT	Material		2	May 3, 2022	SYSTEM	\$50,130.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user marzua1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					2	May 3, 2022	SYSTEM	(\$50,130.00)	
					3	May 16, 2022	SYSTEM	\$110,190.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user marzua1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				3 4	3	May 16, 2022	SYSTEM	(\$110,190.00)	
					4	Jun 2, 2022	SYSTEM	\$110,190.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					4	Jun 2, 2022	SYSTEM	(\$110,190.00)	
					5	Jun 17, 2022	SYSTEM	\$154,245.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					5	Jun 17,	SYSTEM	(\$154,245.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																			
J5I3572	1960	PAVEMENT EDGE	Material			2022																						
		TREATMENT			6	Jul 2, 2022	SYSTEM	\$220,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user abbote1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																			
					6	Jul 1, 2022	SYSTEM	(\$220,780.00)																				
					7	Jul 19, 2022	SYSTEM	\$220,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 26 on the current Payment Estimate.																			
					7	Jul 19, 2022	SYSTEM	(\$220,780.00)																				
					8	Aug 2, 2022	SYSTEM	\$220,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 29 on the current Payment Estimate.																			
					8	Aug 2, 2022	SYSTEM	(\$220,780.00)																				
					9	Aug 17, 2022	SYSTEM	\$220,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 31 on the current Payment Estimate.																			
								9	Aug 17, 2022	SYSTEM	(\$220,780.00)																	
					10	Sep 6, 2022	SYSTEM	\$220,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 35 on the current Payment Estimate.																			
					10	Sep 6, 2022	SYSTEM	(\$220,780.00)																				
					11	Sep 16, 2022	SYSTEM	\$220,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 36 on the current Payment Estimate.																			
							11	Sep 16, 2022	SYSTEM	(\$220,780.00)																		
					12	Oct 4, 2022	SYSTEM	\$220,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user gabelj3 overridding Payment Estimate Exception 36 on the current Payment Estimate.																			
					12	Oct 4, 2022	SYSTEM	(\$220,780.00)																				
					13	Oct 18, 2022	SYSTEM	\$220,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0092) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																			
									13	Oct 18, 2022	SYSTEM	(\$220,780.00)																
										14	Nov 3, 2022	SYSTEM	\$220,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 23 on the current Payment Estimate.														
					14	Nov 3, 2022	SYSTEM	(\$220,780.00)																				
				- Total				\$0.00																				
			Material - Tot	tal				\$0.00																				
	1960 -	Total						\$0.00																				
	2000	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		12	Oct 4, 2022	SYSTEM	\$22,687.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user gabelj3 overridding Payment Estimate Exception 41 on the current Payment Estimate.																			
		MAKKING			12	Oct 4, 2022	SYSTEM	(\$22,687.60)																				
																								13	Oct 18, 2022	SYSTEM	\$22,687.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0093) due to user linkd1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
																13	Oct 18, 2022	SYSTEM	(\$22,687.60)									
					14	Nov 3, 2022	SYSTEM	\$22,687.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 28 on the current Payment Estimate.																			
					14	Nov 3, 2022	SYSTEM	(\$22,687.60)																				
				- Total	- Total	- Total					\$0.00																	
			Material - Tot	al				\$0.00																				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J5l3572	2000 -	Total						\$0.00												
	2010	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		12	Oct 4, 2022	SYSTEM	\$18,184.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user gabelj3 overridding Payment Estimate Exception 45 on the current Payment Estimate.											
		WARKING			12	Oct 4, 2022	SYSTEM	(\$18,184.00)												
					13	Oct 18, 2022	SYSTEM	\$18,184.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0094) due to user linkd1 overridding Payment Estimate Exception 31 on the current Payment Estimate.											
					13	Oct 18, 2022	SYSTEM	(\$18,184.00)												
					14	Nov 3, 2022	SYSTEM	\$18,184.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 32 on the current Payment Estimate.											
					14	Nov 3, 2022	SYSTEM	(\$18,184.00)												
				- Total				\$0.00												
			Material - To	tal				\$0.00												
	2010 -	Total						\$0.00												
	2140	SEEDING - COOL SEASON GRASSES	Material		6	Jul 2, 2022	SYSTEM	\$14,335.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user abbote1 overridding Payment Estimate Exception 34 on the current Payment Estimate.											
					6	Jul 1, 2022	SYSTEM	(\$14,335.00)												
					7	Jul 19, 2022	SYSTEM	\$14,335.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 28 on the current Payment Estimate.											
							7	Jul 19, 2022	SYSTEM	(\$14,335.00)										
						8	Aug 2, 2022	SYSTEM	\$14,335.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 31 on the current Payment Estimate.										
					8	Aug 2, 2022	SYSTEM	(\$14,335.00)												
					9	Aug 17, 2022	SYSTEM	\$33,370.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 37 on the current Payment Estimate.											
					9	Aug 17, 2022	SYSTEM	(\$33,370.00)												
					10	Sep 6, 2022	SYSTEM	\$33,370.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 45 on the current Payment Estimate.											
					10	Sep 6, 2022	SYSTEM	(\$33,370.00)												
																11	Sep 16, 2022	SYSTEM	\$33,370.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					11	Sep 16, 2022	SYSTEM	(\$33,370.00)												
					12	Oct 4, 2022	SYSTEM	\$33,370.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user gabelj3 overridding Payment Estimate Exception 50 on the current Payment Estimate.											
					12	Oct 4, 2022	SYSTEM	(\$33,370.00)												
					13 13 14	13							1	13	Oct 18, 2022	SYSTEM	\$33,370.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0095) due to user linkd1 overridding Payment Estimate Exception 36 on the current Payment Estimate.		
							13	Oct 18, 2022	SYSTEM	(\$33,370.00)										
							14	14	Nov 3, 2022	SYSTEM	\$33,370.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 37 on the current Payment Estimate.								
					14	Nov 3, 2022	SYSTEM	(\$33,370.00)												
				- Total				\$0.00												
			Material - To	tal				\$0.00												



PROCRUTCH	ct I	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
2022 Estimate item Adjustment (000) due to used insect overmidding Prigment Estimate	2 2	2140 -	Total						\$0.00								
1	2	2170		Material		13		SYSTEM	\$297.00	Estimate Item Adjustment (0096) due to user linkd1 overridding Payment							
						13		SYSTEM	(\$297.00)								
Total						14		SYSTEM	\$297.00	Estimate Item Adjustment (0010) due to user linkd1 overridding Payment							
						14		SYSTEM	(\$297.00)								
13					- Total				\$0.00								
2180 CURB INSET CHECK Material 13				Material - To	tal				\$0.00								
CHECK	2	2170 -	Total						\$0.00								
2022 14	2	2180		Material		13		SYSTEM	\$6,090.00	Estimate Item Adjustment (0090) due to user linkd1 overridding Payment							
2022 Estimate Item Agustment (0011) due to user linked overriding Payment Estimate Exception 40 on the current Payment Estimate.						13		SYSTEM	(\$6,090.00)								
2022 So. 00 Material - Total So. 00						14		SYSTEM	\$6,090.00	Estimate Item Adjustment (0011) due to user linkd1 overridding Payment							
Naterial - Total Support Suppo						14		SYSTEM	(\$6,090.00)								
Overrun					- Total				\$0.00								
2022 (\$1,450.00)				Material - Total					\$0.00								
2180 - Total				Overrun	Overrun	13		SYSTEM	(\$1,450.00)								
					Overrun - T	otal			(\$1,450.00)								
TEMPORARY SEEDING				Overrun - To	tal				(\$1,450.00)								
2022 Estimate Item Adjustment (0005) due to user linked to veerididing Payment Estimate.	2	2180 -	Total						(\$1,450.00)								
2022 5 Jun 17, 2022	2	2200	TEMPORARY	Material		4		SYSTEM	\$2,730.00	Estimate Item Adjustment (0009) due to user linkd1 overridding Payment							
2022 Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 26 on the current Payment Estimate.													4		SYSTEM	(\$2,730.00)	
2022 30.00									5		SYSTEM	\$2,730.00	Estimate Item Adjustment (0011) due to user linkd1 overridding Payment				
2200 - Total 2260 CONCRETE PAVEMENT (11 IN NON-REINFORCED STMI Succepile STMI S						5		SYSTEM	(\$2,730.00)								
CONCRETE PAVEMENT (11 IN NON-REINFORCED STMI STMI Support					- Total				\$0.00								
CONCRETE PAVEMENT (11 IN. NON-REINFORCED STMI				Material - To	tal				\$0.00								
PAVEMENT (11 IN. NON-REINFORCED STMI STMI) 3 May 16, 2022 11 Sep 16, 2022 11 Sep 16, 2022 11 Sep 16, 2022 11 Sep 16, 2022 1250 - Total Construction Stockpile STMI - Total 2260 - Total 2300 TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) THICK) AGGREGATE FOR BASE (4 IN. THICK) AGGREGATE FOR BASE (4 IN. THICK) 2 May 3, 2022 3 May 16, SYSTEM \$58,656.00 2 May 3, 2022 3 May 16, SYSTEM \$71,394.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate Estimate Item Adjustment (0011) due to user marzual overridding Payment Estimate Estimate Exception 1 on the current Payment Estimate Estimate Exception 1 on the current Payment Estimate Estimate Exception 1 on the current Payment Estimate.	2	2200 -	Total						\$0.00								
REINFORCED 3	2	2260	PAVEMENT (11	Stockpile		2		SYSTEM	\$144,417.76	Payment Estimate Item Adjustment generated Stockpile Transaction							
2022 - Total \$1,028,898.20				STIMI		3		SYSTEM	\$36,104.44	Payment Estimate Item Adjustment generated Stockpile Transaction							
2260 - Total 2300 TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) 2 May 3, 2022 3 May 16, 2022 3 May 16, SYSTEM 3 May 16, SYSTEM 3 May 16, SYSTEM 3 May 16, SYSTEM 3 SYSTEM 3 SYSTEM 3 STATEM 4 STATEM 5 STAT						11		SYSTEM	\$848,376.00	Payment Estimate Item Adjustment generated Stockpile Transaction							
2260 - Total 2300 TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) 2 May 3, 2022 3 May 16, 2022 3 May 16, SYSTEM 3 SYSTEM SY																	
2300 TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) 2 May 3, 2022 3 May 16, 2022 3 May 16, SYSTEM 3 \$58,656.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user marzua1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0011) due to user marzua1 overridding Payment Estimate Exception 1 on the current Payment Estimate. 3 May 16, SYSTEM (\$71,394.00)				Construction	n Stockpile Si	「MI - Total											
AGGREGATE FOR BASE (4 IN. THICK) 2 May 3, 2022 3 May 16, 2022 3 May 16, 2022 3 May 16, SYSTEM (\$71,394.00)																	
2 May 3, 2022 3 May 16, 2022 \$71,394.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user marzua1 overridding Payment Estimate Exception 1 on the current Payment Estimate. 3 May 16, SYSTEM (\$71,394.00)	2		AGGREGATE FOR BASE (4 IN.	Material			2022			Estimate Item Adjustment (0005) due to user marzua1 overridding Payment							
2022 Estimate Item Adjustment (0011) due to user marzua1 overridding Payment Estimate Exception 1 on the current Payment Estimate. 3 May 16, SYSTEM (\$71,394.00)			THICK)			2		SYSTEM	(\$58,656.00)								
								SYSTEM	\$71,394.00	Estimate Item Adjustment (0011) due to user marzua1 overridding Payment							
						3	May 16, 2022	SYSTEM	(\$71,394.00)								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5I3572	2300	TYPE 1 AGGREGATE FOR BASE (4 IN.	Material		4	Jun 2, 2022	SYSTEM	\$116,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		THICK)			4	Jun 2, 2022	SYSTEM	(\$116,700.00)	
					5	Jun 17, 2022	SYSTEM	\$188,208.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jun 17, 2022	SYSTEM	(\$188,208.00)	
					6	Jul 1, 2022	SYSTEM	\$255,018.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user abbote1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jul 1, 2022	SYSTEM	(\$255,018.00)	
					7	Jul 19, 2022	SYSTEM	\$283,236.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jul 19, 2022	SYSTEM	(\$283,236.00)	
					8	Aug 2, 2022	SYSTEM	\$283,236.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Aug 2, 2022	SYSTEM	(\$283,236.00)	
					9	Aug 17, 2022	SYSTEM	\$283,236.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Aug 17, 2022	SYSTEM	(\$283,236.00)	
					10	Sep 6, 2022	SYSTEM	\$283,236.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Sep 6, 2022	SYSTEM	(\$283,236.00)	
					11	Sep 16, 2022	SYSTEM	\$283,236.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Sep 16, 2022	SYSTEM	(\$283,236.00)	
					12	Oct 4, 2022	SYSTEM	\$283,236.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user gabelj3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Oct 4, 2022	SYSTEM	(\$283,236.00)	
					13	Oct 18, 2022	SYSTEM	\$357,095.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0097) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Oct 18, 2022	SYSTEM	(\$357,095.40)	
					14	Nov 3, 2022	SYSTEM	\$403,061.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Nov 3, 2022	SYSTEM	(\$403,061.40)	
			Material - To	- Total				\$0.00 \$0.00	
			Price FUEL		2	May 3, 2022	SYSTEM	\$408.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					2	May 3, 2022	SYSTEM	\$1,615.63	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					3	May 16, 2022	SYSTEM	\$636.90	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Jun 2, 2022	SYSTEM	\$2,265.30	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Jun 17, 2022	SYSTEM	\$4,361.98	Reference Item Price Adjustment Index Adjustment Type applied is FUEL



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J5I3572	2300	TYPE 1 AGGREGATE	Price FUEL		6	Jul 1, 2022	SYSTEM	\$4,075.41	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
		FOR BASE (4 IN. THICK)			7	Jul 19, 2022	SYSTEM	\$1,269.81	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
					13	Oct 17, 2022	SYSTEM	\$1,828.03	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
					14	Nov 3, 2022	SYSTEM	\$1,137.65	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
				- Total				\$17,598.71															
			Price FUEL -	Total				\$17,598.71															
	2300 -	Total						\$17,598.71															
	2310	CONCRETE PAVEMENT (8 IN.	Construction Stockpile		3	May 16, 2022	SYSTEM	(\$14,111.81)	Payment Estimate Item Adjustment generated Stockpile Transaction														
		NON- REINFORCED,			4	Jun 2, 2022	SYSTEM	(\$33,529.66)	Payment Estimate Item Adjustment generated Stockpile Transaction														
					5	Jun 17, 2022	SYSTEM	(\$55,592.99)	Payment Estimate Item Adjustment generated Stockpile Transaction														
					6	Jul 1, 2022	SYSTEM	(\$57,845.25)	Payment Estimate Item Adjustment generated Stockpile Transaction														
					7	Jul 19, 2022	SYSTEM	(\$50,676.91)	Payment Estimate Item Adjustment generated Stockpile Transaction														
					10	Sep 6, 2022	SYSTEM	(\$6,195.09)	Payment Estimate Item Adjustment generated Stockpile Transaction														
						14	Nov 3, 2022	SYSTEM	(\$14,543.16)	Payment Estimate Item Adjustment generated Stockpile Transaction													
				- Total				(\$232,494.87)															
			Construction	Stockpile - 1	Γotal			(\$232,494.87)															
			Construction Stockpile STMI		2	May 3, 2022	SYSTEM	\$16,439.50	Payment Estimate Item Adjustment generated Stockpile Transaction														
				STMI		3	May 16, 2022	SYSTEM	\$377,421.10	Payment Estimate Item Adjustment generated Stockpile Transaction													
				- Total				\$393,860.60															
						Stockpile S	ГМI - Total			\$393,860.60													
			Material		3	May 16, 2022	SYSTEM	\$168,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user marzua1 overridding Payment Estimate Exception 3 on the current Payment Estimate.														
			4 5 5 6 6	4 4 5 5 6	4 4 5 5 6	4 4 5 5 6	4 4 5 5 6		4 5			3	May 16, 2022	SYSTEM	(\$168,000.00)								
											4	Jun 2, 2022	SYSTEM	\$567,168.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
															4	Jun 2, 2022	SYSTEM	(\$567,168.00)					
																			5	Jun 17, 2022	SYSTEM	\$1,228,998.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
													5	Jun 17, 2022	SYSTEM	(\$1,228,998.40)							
										6	Jul 1, 2022	SYSTEM	\$1,917,641.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user abbote1 overridding Payment Estimate Exception 3 on the current Payment Estimate.									
								6	Jul 1, 2022	SYSTEM	(\$1,917,641.60)												
								7	Jul 19, 2022	SYSTEM	\$2,520,946.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
				7	Jul 19, 2022	SYSTEM	(\$2,520,946.40)																
					8	Aug 2, 2022	SYSTEM	\$2,520,946.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.														
					8	Aug 2, 2022	SYSTEM	(\$2,520,946.40)															
					9	Aug 17,	SYSTEM	\$2,520,946.40	This adjustment offsets the original system-generated Material Payment														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5l3572	2310	CONCRETE PAVEMENT (8 IN.	Material			2022			Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		NON- REINFORCED,			9	Aug 17, 2022	SYSTEM	(\$2,520,946.40)	
					10	Sep 6, 2022	SYSTEM	\$2,594,698.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Sep 6, 2022	SYSTEM	(\$2,594,698.40)	
					11	Sep 16, 2022	SYSTEM	\$2,594,698.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Sep 16, 2022	SYSTEM	(\$2,594,698.40)	
					12	Oct 4, 2022	SYSTEM	\$2,594,698.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user gabelj3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Oct 4, 2022	SYSTEM	(\$2,594,698.40)	
					13	Oct 18, 2022	SYSTEM	\$2,594,698.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0098) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	Oct 18, 2022	SYSTEM	(\$2,594,698.40)	
					14	Nov 3, 2022	SYSTEM	\$2,767,833.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					14	Nov 3, 2022	SYSTEM	(\$2,767,833.60)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment		10	Sep 6, 2022	linkd1	\$9,577.40	J513572 - WB 10' Shoulder, 56.00/ SY Lot 21, +\$4643.80, 3317 SY 2.5% Bonus Lot 22, +\$2249.80, 1607 SY 2.5% Bonus Lot 23, +\$2683.80, 1917 SY 2.5% Bonus
					10	Sep 6, 2022	linkd1	\$31,576.44	J513572 - Wb 10' Shoulder 56.00/ SY Lot 11, *\$3570.00, 2550 SY 2.5% Bonus Lot 12, +1636.32, 1168.8 SY 2.5% Bonus Lot 13, +3850.00, 2750 SY 2.5% Bonus Lot 14, *\$4176.62, 2983.3 SY 2.5% Bonus Lot 14, *\$4176.62, 2983.3 SY 2.5% Bonus Lot 15, *\$4573.38, 3266.7 SY 2.5% Bonus Lot 16, *\$1730.54, 1236.1 SY 2.5% Bonus Lot 17, *\$2940.00, 2100 SY 2.5% Bonus Lot 18, *\$3593.38, 2566.7 SY 2.5% Bonus Lot 18, *\$35220.00, 2300 SY 2.5% Bonus Lot 20, *\$2286.20, 1633 SY 2.5% Bonus
					10	Sep 6, 2022	linkd1	\$23,279.76	J513572 - Wb 10' Shoulder, 56.00/ SY Lot 1, +\$1843.80, 1317 SY 2.5% Bonus Lot 2, +\$2076.20, 1483 SY 2.5% Bonus Lot 3, +1890.00, 1350 SY 2.5% Bonus Lot 4, +\$2053.80, 1467 SY 2.5% Bonus Lot 5, +\$2683.80, 1917 SY 2.5% Bonus Lot 5, +\$2681.60, 1894 SY 2.5% Bonus Lot 7, +\$2590.00, 1850 SY 2.5% Bonus Lot 8, +\$2823.38, 2016.7 SY 2.5% Bonus Lot 8, +\$2823.38, 2016.7 SY 2.5% Bonus Lot 9, +\$1283.38, 916.7 SY 2.5% Bonus Lot 10, +\$3383.80, 2417 SY 2.5% Bonus Lot 10, +\$3383.80, 2417 SY 2.5% Bonus
					al			\$64,433.60	
				PCCT	10	Sep 6, 2022	linkd1	\$30,201.93	J5i3572 - WB 10' Shoulder - 56.00/SY Lot 11, +\$3570.00, 2550 SY 2.5% Bonus Lot 12, +\$261.81, 1168.8 SY 0.4% Bonus Lot 13, +\$3850.00, 2750 SY 2.5% Bonus Lot 14, +\$4176.62, 2983.3 SY 2.5% Bonus Lot 15, +\$4573.38, 3266.7 SY 2.5% Bonus Lot 16, +\$1730.54, 1236.1 SY 2.5% Bonus Lot 17, +\$2940.00, 2100 SY 2.5% Bonus Lot 18, +\$3593.38, 2566.7 SY 2.5% Bonus Lot 18, +\$3593.38, 2566.7 SY 2.5% Bonus Lot 19, +\$3220.00, 2300 SY 2.5% Bonus Lot 20, +\$2286.20, 1633 SY 2.5% Bonus
					10	Sep 6, 2022	linkd1	\$23,279.76	J5I3572 - WB 10' Shoulder 56.00/ SY Lot 1, +\$1843.80, 1317 SY 2.5% Bonus Lot 2, +\$2076.20, 1483 SY 2.5% Bonus Lot 3, +\$1890.00, 1350 SY 2.5% Bonus Lot 4, +\$2053.80, 1467 SY 2.5% Bonus



PACKENTY T RM	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
PCCT - Total	513572	2310	PAVEMENT (8 IN. NON-		PCCT					Lot 6, +\$2651.60, 1894 SY 2.5% Bonus Lot 7, +\$2590.00, 1850 SY 2.5% Bonus Lot 8, +\$2823.38, 2016.7 SY 2.5% Bonus Lot 9, +\$1283.38, 916.7 SY 2.5% Bonus
SUB						10		linkd1	\$9,577.40	Lot 21, +\$4643.80, 3317 SY 2.5% Bonus Lot 22, +\$2249.80, 1607 SY 2.5% Bonus
2022 1585572, See NOCK for further details, 50% Deout of 791 SY at \$56,000 SY 30% of \$44,256,000 = 432,746,000					PCCT - Total				\$63,059.09	
Other Item Adjustment - Total					SUBI	11		linkd1	(\$22,148.00)	J5I3572. See NCR for further details. 50% Deduct of 791 SY at \$56.00/ SY.
Price PUEL									(\$22,148.00)	
2002 S. S. S. S. S. 80 Reference Item Price Adjustment Index Adjustment Type applied is PUEL				Other Item Adjustment - Total					\$105,344.69	
2022 5				Price FUEL		3		SYSTEM	\$3,600.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
2022 6						4		SYSTEM	\$8,553.60	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
2022 7 Jul 19, SYSTEM \$11,835.17 Reference Item Price Adjustment Index Adjustment Type applied is FUEL 2022 10 Sep 6, SYSTEM \$1,590.40 Reference Item Price Adjustment Index Adjustment Type applied is FUEL 2022 14 Nov. 3, SYSTEM \$1,590.47 Reference Item Price Adjustment Index Adjustment Type applied is FUEL 2022						5		SYSTEM	\$17,302.14	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
10 Sep 6 SySTEM \$1,580.40 Reference Item Price Adjustment Index Adjustment Type applied is FUEL						6		SYSTEM	\$18,003.10	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
14						7		SYSTEM	\$11,635.17	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
Total Se2,510.88						10		SYSTEM	\$1,580.40	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
Price FUEL - Total \$62,510.88						14		SYSTEM	\$1,836.47	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
2310 - Total 2320 MGS GUARDRAIL Construction Stockpile STMI - Total S68,613.54 Payment Estimate Item Adjustment generated Stockpile Transaction S68,613.54										
Second										
Stockpile STMI - Total										
2330 - Total 2340 MGS END ANCHOR ANCH ANCH ANCH ANCH ANCH ANCH ANCH ANCH		2330	MGS GUARDRAIL	Stockpile STMI		6		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
2340 MGS END ANCHOR Stockpile STMI - Total										
MGS END ANCHOR Stockpile STMI 2022 SYSTEM \$4,275.00 Payment Estimate Item Adjustment generated Stockpile Transaction \$4,275.00				Construction	1 Stockpile S	MI - Tota				
ANCHOR Stockpile STMI - Total \$4,275.00 2340 - Total \$4,275.00 2340 - Total \$4,275.00 2350 TYPE A CRASHWORTHY END TERMINAL (MASH) COnstruction Stockpile STMI - Total \$9,075.00 2350 - Total \$9,075.00 2360 - Total \$9,075.00 2370 - Total \$9,075.00 2380 - Total \$1,06										
Construction Stockpile STMI - Total \$4,275.00				Stockpile		6		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
2350 TYPE A CRASHWORTHY END TERMINAL (MASH) 2350 Total 24 May 3, SYSTEM \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user marzuard overridding Payment Estimate Exception 8 on the current Payment Estimate. 2 May 3, SYSTEM \$1,064.00 This adjustment (0014) due to user marzuard overridding Payment Estimate Item Adjustment (0014) due to user marzuard overridding Payment Estimate Item Adjustment (0014) due to user marzuard overridding Payment Estimate Item Adjustment (0014) due to user marzuard overridding Payment Estimate Item Adjustment (0014) due to user marzuard overridding Payment Estimate Item Adjustment (0014) due to user marzuard overridding Payment Estimate Item Adjustment (0018) due to user marzuard overridding Payment Estimate Item Adjustment (0018) due to user inkid overridding Payment Estimate Item Adjustment (0018) due to user linkid overridding Payment Estimate Item Adjustment (0018) due to user linkid overridding Payment Estimate Item Adjustment (0018) due to user linkid overridding Payment Estimate Item Adjustment (0018) due to user linkid overridding Payment Estimate Item Adjustment (0018) due to user linkid overridding Payment Estimate Item Adjustment (0018) due to user linkid overridding Payment Estimate Item Adjustment (0018) due to user linkid overridding Payment Estimate Item Adjustment (0018) due to user linkid overridding Payment Item Adjustment (0018) due to user linkid overridding Payment Item Adjustment (0018) due to user linkid overridding Payment Item Adjustment Item Adjustment (0018) due to user linkid overridding Payment Item Adjustment Ite				0						
TYPE A CRASHWORTHY END TERMINAL (MASH) TOTAL TOTAL SEQUENTIAL FLASHING WARNING LIGHT SEQUENTIAL FLASHING WARNING LIGH			Total	Construction	Istruction Stockpile STML-Total					
CRASHWORTHY END TERMINAL (MASH) Total Construction Stockpile STMI - Total S9,075.00 2350 - Total SEQUENTIAL FLASHING WARNING LIGHT SEQUENTIAL FLASHING WARNING LIGHT Material 2 May 3, 2022 SYSTEM (\$1,064.00) This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 2 May 3, SYSTEM (\$1,064.00) This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 3 May 16, SYSTEM 2022 SYSTEM \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate. 3 May 16, SYSTEM 2022 4 Jun 2, SYSTEM \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate. 3 May 16, SYSTEM 2022 4 Jun 2, SYSTEM \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate.				Construction		6	Jul 4	CVCTERA		Poyment Estimate Item Adjustment generated Charles In Transaction
Construction Stockpile STMI - Total \$9,075.00 2350 - Total \$9,075.00 \$9,075.00 \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user marzual overridding Payment Estimate Exception 8 on the current Payment Estimate. 2 May 3, 2022 3 May 16, 2022 3 May 16, SYSTEM \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user marzual overridding Payment Estimate Exception 7 on the current Payment Estimate. 3 May 16, SYSTEM (\$1,064.00) 4 Jun 2, SYSTEM \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate. 4 Jun 2, SYSTEM \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate.		2350	CRASHWORTHY END TERMINAL	Stockpile	Total	0		STOLEM	,,,,	rayment Estimate item Adjustment generated Stockpile Transaction
\$9,075.00 SEQUENTIAL FLASHING WARNING LIGHT Material 2 May 3, 2022 SYSTEM \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 2 May 3, 2022 SYSTEM (\$1,064.00) 3 May 16, 2022 SYSTEM \$1,064.00 This adjustment (0014) due to user marzual overridding Payment Estimate Item Adjustment (0014) due to user marzual overridding Payment Estimate Item Adjustment (0014) due to user marzual overridding Payment Estimate Exception 7 on the current Payment Estimate. 3 May 16, 2022 SYSTEM (\$1,064.00) 4 Jun 2, 2022 SYSTEM \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate. 4 Jun 2, SYSTEM \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate.				Construction						
SEQUENTIAL FLASHING WARNING LIGHT 2 May 3, 2022 SYSTEM \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 2 May 3, 2022 SYSTEM (\$1,064.00) 3 May 16, 2022 SYSTEM \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user marzual overridding Payment Estimate Item Adjustment (0014) due to user marzual overridding Payment Estimate Exception 7 on the current Payment Estimate. 3 May 16, 2022 SYSTEM (\$1,064.00) 4 Jun 2, 2022 SYSTEM \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate. 4 Jun 2, SYSTEM (\$1,064.00)		2250	Total	Construction	- Stockpile S	-wii - Total				
2 May 3, 2022 SYSTEM (\$1,064.00) 3 May 16, 2022 SYSTEM \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user marzua1 overridding Payment Estimate Exception 7 on the current Payment Estimate. 3 May 16, 2022 SYSTEM (\$1,064.00) 4 Jun 2, 2022 SYSTEM \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate.			1 SEQUENTIAL FLASHING			2		SYSTEM	· · · · · · · · · · · · · · · · · · ·	Estimate Item Adjustment (0021) due to user marzua1 overridding Payment
3 May 16, 2022 \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user marzua1 overridding Payment Estimate Exception 7 on the current Payment Estimate. 3 May 16, 2022 \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate. 4 Jun 2, SYSTEM (\$1,064.00)						2		SYSTEM	(\$1,064.00)	
4 Jun 2, SYSTEM \$1,064.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate. 4 Jun 2, SYSTEM (\$1,064.00)						3	May 16,	SYSTEM	\$1,064.00	Estimate Item Adjustment (0014) due to user marzua1 overridding Payment
Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate. 4 Jun 2, SYSTEM (\$1,064.00)						3		SYSTEM	(\$1,064.00)	
						4		SYSTEM	\$1,064.00	Estimate Item Adjustment (0018) due to user linkd1 overridding Payment
						4	Jun 2, 2022	SYSTEM	(\$1,064.00)	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J513572	5201	SEQUENTIAL FLASHING WARNING LIGHT	6		5	Jun 17, 2022	SYSTEM	\$1,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					5	Jun 17, 2022	SYSTEM	(\$1,064.00)	
					6	Jul 2, 2022	SYSTEM	\$1,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user abbote1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					6	Jul 1, 2022	SYSTEM	(\$1,064.00)	
					7	Jul 19, 2022	SYSTEM	\$1,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user linkd1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					7	Jul 19, 2022	SYSTEM	(\$1,064.00)	
					8	Aug 2, 2022	SYSTEM	\$1,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user linkd1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					8	Aug 2, 2022	SYSTEM	(\$1,064.00)	
					9	Aug 17, 2022	SYSTEM	\$1,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user linkd1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					9	Aug 17, 2022	SYSTEM	(\$1,064.00)	
					10	Sep 6, 2022	SYSTEM	\$1,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user linkd1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					10	Sep 6, 2022	SYSTEM	(\$1,064.00)	
					11	Sep 16, 2022	SYSTEM	\$1,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user linkd1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					11	Sep 16, 2022	SYSTEM	(\$1,064.00)	
					12	Oct 4, 2022	SYSTEM	\$1,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user gabelj3 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					12	Oct 4, 2022	SYSTEM	(\$1,064.00)	
				- Total				\$0.00	
			Material - To	al				\$0.00	
	5201 -	Total						\$0.00	
J5l3572 -	Total							\$1,456,181.75	
Overall -	Total							\$1,672,693.90	