83.79%



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 16, 2022

Progress Estin	nate Number	Contract ID Prime Contractor	220121-F04 Kozeny-Wagner, Inc	Pay Period Start : Pay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	\$555,000.00 \$0.00 \$555,000.00			
Approval Date							By User			
June 16, 2022		(	Generated and Approv	red (and should be co	nsidered Draft) a	t the Project Office Level by	washid1			
June 16, 2022		Revie	ewed and Approved (a	and should be conside	red Draft) at the	Resident Engineer Level by	washas			
June 17, 2022	Reviewed and Approved at the Central Office Controllers Office Level by									
Original Comp	Original Completion Date									

August 1, 2022	2	August	1, 2022			
	Contract I	Milestones				
Date Description	Original C	ompletion Date	Current Comple	tion Date	No Milestones Exist for	Contract
Acceptance Date						
Awarded Date	February 2	, 2022	February 2, 2022			
Letting Date	January 21	, 2022	January 21, 2022			
Notice to Proceed Date	March 7, 2	022	March 7, 2022			

Contract Total Pay	For Estimate No. 5			
		This Estimate	Previous	To Date
220121-F04				
	Total Posted Items Pay	\$0.00	\$465,050.00	\$465,050.00
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$465,050.00	\$465,050.00
<b>Contract Total Pay</b>	able This Estimate:	\$0.00		

### **Items Paid This Estimate Period**

No Data Available

Open to Traffic Date
Work Began Date

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		tments Exist on Contract						
Line Item /	<u>Adjustr</u>	nents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6M3413	0050	SUBSTRUCTURE REPAIR (FORMED)	Material			-50	\$250.00	(\$12,500.00)
	0050	SUBSTRUCTURE REPAIR (FORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	50	\$250.00	\$12,500.00
	0060	CLEANING AND EPOXY COATING	Material			-4	\$100.00	(\$400.00)
	0060	CLEANING AND EPOXY COATING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	4	\$100.00	\$400.00
	0070	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	Material			-1	\$74,000.00	(\$74,000.00)
	0070	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1	\$74,000.00	\$74,000.00

Revision 4/1/2020 Page 1 of 9



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 16, 2022

Progr		imate Number 5	Contract II Prime Con		121-F04 eny-Wagner,	Inc. Pay Period End June 15, 2022 Net	ginal Contract Change Order rent Contract	r Amount	\$555,000.00 \$0.00 \$555,000.00
Project Number	Line No.	Item Descr	ription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6M3413	0800	FIELD APPLI INORGANIC ZI		Material			-1	\$4,000.00	(\$4,000.00
	0800	FIELD APPLI INORGANIC ZI		Material		This adjustment offsets the original systen generated Material Payment Estimate Ite Adjustment (0004) due to user washic overridding Payment Estimate Exception 4 of the current Payment Estimate	m l1 on	\$4,000.00	\$4,000.00
	0090		OIATE FIELD SYSTEM G)	Material			-1	\$4,000.00	(\$4,000.00)
	0090		DIATE FIELD SYSTEM G)	Material		This adjustment offsets the original system generated Material Payment Estimate Ite Adjustment (0005) due to user washic overridding Payment Estimate Exception 5 of the current Payment Estimate	m l1 on	\$4,000.00	\$4,000.00
	0100		FIELD COAT SYSTEM G)	Material			-1	\$4,000.00	(\$4,000.00)
	0100		FIELD COAT SYSTEM G)	Material		This adjustment offsets the original system generated Material Payment Estimate Ite Adjustment (0006) due to user washic overridding Payment Estimate Exception 6 of the current Payment Estimate	m l1 on	\$4,000.00	\$4,000.00
Total									\$0.00

Revision 4/1/2020 Page 2 of 9



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information									
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work					
J6M3413		Bridge rehabilitation	I-70	ST LOUIS CITY	over Grand Blvd.					
J6M3414		Bridge rehabilitation	I-70	ST LOUIS CITY	at Taylor Ave.					

als by Jo	b Numbers			
10140440				
J6M3413		This Estimate	Previous	To Date
	Posted Item Pay	\$0.00	\$149,280.00	\$149,280.00
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	Gross Item Pay	\$0.00	\$149,280.00	\$149,280.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
6M3414		This Estimate	Previous	To Date
	Posted Item Pay	\$0.00	\$315,770.00	\$315,770.00
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	Gross Item Pay	\$0.00	\$315,770.00	\$315,770.00
	_			
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 3 of 9



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6M3413, Item 7040101, Project Item Line Number 0050, Material Set 704010196, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Will meet with MoDOT Materials Department to resolve discrepancy.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M3413, Item 7040113, Project Item Line Number 0060, Material Set 704011396, Material 1039ERBCT3 - Type III Epoxy Resin for Conc Patch Cmp, Acceptance Action Generic 1039ERBCT3 is insufficient.	Will meet with MoDOT Materials Department to resolve discrepancy.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M3413, Item 7125100, Project Item Line Number 0070, Material Set 712510096, Material 1045PTGREPMA - Gray Epoxy-Mastic Primer, Acceptance Action Generic 1045PTGREPMA is insufficient.	Will meet with MoDOT Materials Department to resolve discrepancy.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M3413, Item 7125110, Project Item Line Number 0080, Material Set 712511096, Material 1045PTIZ - High Solids Inorganic Zinc Silicat Paint, Acceptance Action Generic 1045PTIZ is insufficient.	Will meet with MoDOT Materials Department to resolve discrepancy.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M3413, Item 7125111, Project Item Line Number 0090, Material Set 712511196, Material 1045PTEP - High Solids Epoxy System G Intrmdte Coat, Acceptance Action Generic 1045PTEP is insufficient.	Will meet with MoDOT Materials Department to resolve discrepancy.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M3413, Item 7125112, Project Item Line Number 0100, Material Set 712511296, Material 1045PTAP - Polyurethane System G Finish Coating, Acceptance Action Generic 1045PTAP is insufficient.	Will meet with MoDOT Materials Department to resolve discrepancy.	washid1	Overridden

Revision 4/1/2020 Page 4 of 9



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
0121-F04	J6M3413	0001	0010	6169901	MISC.Temporary Traffic Control	1.00	0.00	1.00	LS	1.00	\$25,180.00	\$25,180.00
		0001	0020	6169901	MISC.Traffic Signal Maintenance and Programming	1.00	0.00	1.00	LS	1.00	\$10,200.00	\$10,200.00
		0001	0030	6169902	MISC.NTCIP Compliant Changeable Message Sign (Contractor Furnished and Retained)	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0.00
		0001	0040	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0070	0050	7040101	SUBSTRUCTURE REPAIR (FORMED)	50.00	0.00	50.00	SQFT	50.00	\$250.00	\$12,500.0
		0070	0060	7040113	CLEANING AND EPOXY COATING	4.00	0.00	4.00	SQFT	4.00	\$100.00	\$400.0
		0070	0070	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	1.00	\$74,000.00	\$74,000.00
		0070	0080	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	1.00	\$4,000.00	\$4,000.00
		0070	0090	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	1.00	\$4,000.00	\$4,000.00
		0070	0100	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	1.00	\$4,000.00	\$4,000.00
	Project J6	M3413 - To	tal Value	e Posted to	Date as of Report Generated Date							\$149,280.0
	J6M3414	0001	0110	6169901	MISC.Temporary Traffic Control	1.00	0.00	1.00	LS	0.75	\$120,000.00	\$90,000.0
		0001	0120	6169901	MISC.Traffic Signal Maintenance and Programming	1.00	0.00	1.00	LS	0.50	\$14,700.00	\$7,350.0
		0001	0130	6169902	MISC.NTCIP Compliant Changeable Message Sign (Contractor Furnished and Retain)	6.00	0.00	6.00	EA	5.00	\$1,000.00	\$5,000.0
		0001	0140	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$40,000.00	\$40,000.0
		0070	0150	2169902	MISC.Removal of Diaphragm	2.00	0.00	2.00	EA	2.00	\$1,700.00	\$3,400.0
		0070	0160	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	1,260.00	0.00	1,260.00	LB	1,260.00	\$42.00	\$52,920.0
		0070	0170	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	0.00	\$43,600.00	\$0.00
		0070	0180	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	0.00	\$2,000.00	\$0.0
		0070	0190	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$2,000.00	\$0.0
		0070	0200	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$2,000.00	\$0.0
		0070	0210	7126000	NON-DESTRUCTIVE TESTING	39.00	0.00	39.00	LF	39.00	\$200.00	\$7,800.0
		0070	0220	7129901	MISC.Grind Surface Deformities	1.00	0.00	1.00	LS	1.00	\$3,600.00	\$3,600.0
		0070	0230	7129901	MISC.Heat Straightening	1.00	0.00	1.00	LS	1.00	\$98,500.00	\$98,500.0
		0070	0240	7129902	MISC.Crack Repairs	2.00	0.00	2.00	EA	2.00	\$3,600.00	\$7,200.00
	Project J6	M3414 - To	otal Value	e Posted to	Date as of Report Generated Date							\$315,770.0
0121-F04 Ove	rall - Total	/alue Post	ed to Dat	te as of Rep	ort Generated Date							\$465,050.0

Revision 4/1/2020 Page 5 of 9



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 6 of 9



# Line Item Adjustments by Estimate

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J6M3413	0010	MISC.	Material		1	Apr 18, 2022	SYSTEM	\$18,885.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.										
					1	Apr 18, 2022	SYSTEM	(\$18,885.00)											
					2	May 2, 2022	SYSTEM	\$25,180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.										
					2	May 2, 2022	SYSTEM	(\$25,180.00)											
					3	May 16, 2022	SYSTEM	\$25,180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
					3	May 16, 2022	SYSTEM	(\$25,180.00)											
				- Total				\$0.00											
			Material - T	otal				\$0.00											
	0010 -	Total						\$0.00											
	0050	SUBSTRUCTURE REPAIR (FORMED)	Material		2	May 2, 2022	SYSTEM	\$12,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
					2	May 2, 2022	SYSTEM	(\$12,500.00)											
					3	May 16, 2022	SYSTEM	\$12,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.										
					3	May 16, 2022	SYSTEM	(\$12,500.00)											
															4	Jun 1, 2022	SYSTEM	\$12,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jun 1, 2022	SYSTEM	(\$12,500.00)											
					5	Jun 16, 2022	SYSTEM	\$12,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.										
					5	Jun 16, 2022	SYSTEM	(\$12,500.00)											
				- Total				\$0.00											
			Material - T	otal				\$0.00											
	0050 -	Total						\$0.00											
	0060	CLEANING AND EPOXY COATING	Material		2	May 2, 2022	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.										
					2	May 2, 2022	SYSTEM	(\$400.00)											
					3	May 16, 2022	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.										
					3	May 16, 2022	SYSTEM	(\$400.00)											
					4	Jun 1, 2022	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
					4	Jun 1, 2022	SYSTEM	(\$400.00)											
					5	Jun 16, 2022	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
					5	Jun 16, 2022	SYSTEM	(\$400.00)											
				- Total				\$0.00											
			Material - T	otal				\$0.00											
	0060 -	Total						\$0.00											



# Line Item Adjustments by Estimate

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J6M3413	0070	SURFACE PREPARATION FOR	Material		1	Apr 18, 2022	SYSTEM	\$37,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
		RECOATING STRUC			1	Apr 18, 2022	SYSTEM	(\$37,000.00)							
					2	May 2, 2022	SYSTEM	\$74,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.						
					2	May 2, 2022	SYSTEM	(\$74,000.00)							
					3	May 16, 2022	SYSTEM	\$74,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.						
					3	May 16, 2022	SYSTEM	(\$74,000.00)							
					4	Jun 1, 2022	SYSTEM	\$74,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
					4	Jun 1, 2022	SYSTEM	(\$74,000.00)							
					5	Jun 16, 2022	SYSTEM	\$74,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
					5	Jun 16, 2022	SYSTEM	(\$74,000.00)							
				- Total				\$0.00							
			Material - To	otal				\$0.00							
	0070 -	Total						\$0.00							
	0800	FIELD APPLICATION OF INORGANIC ZINC	Material		2	May 2, 2022	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
		21110							2	May 2, 2022	SYSTEM	(\$4,000.00)			
					3	May 16, 2022	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
					3	May 16, 2022	SYSTEM	(\$4,000.00)							
											4	Jun 1, 2022	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Jun 1, 2022	SYSTEM	(\$4,000.00)							
					5	Jun 16, 2022	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.						
					5	Jun 16, 2022	SYSTEM	(\$4,000.00)							
				- Total				\$0.00							
			Material - To	otal				\$0.00							
	0080 -	Total						\$0.00							
	0090	INTERMEDIATE FIELD COAT (SYSTEM G)	COAT		2	May 2, 2022	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.						
					2	May 2, 2022	SYSTEM	(\$4,000.00)							
			3				3	May 16, 2022	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.				
				3	May 16, 2022	SYSTEM	(\$4,000.00)								
					4	Jun 1, 2022	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.						
					4	Jun 1,	SYSTEM	(\$4,000.00)							

Jun 18, 2022



# Line Item Adjustments by Estimate

### Contract ID:190215-D05

March   1000   Member   1000   Member   1000   10	Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
FIELD COAT   GYSTEM   Section   Se					Туре					
Section   Sect	J6M3413	0090	FIELD COAT	Material		5	Jun 16,	SYSTEM	\$4,000.00	Estimate Item Adjustment (0005) due to user washid1 overridding Payment
Material - Total   Material - Total   South   South						5		SYSTEM	(\$4,000.00)	Estimate Exception 5 on the current Payment Estimate.
100					- Total				\$0.00	
1000				Material - To	otal					
COAT (SYSTEM   COAT		0090 -	Total						\$0.00	
100		0100	COAT (SYSTEM	Material		2	May 2, 2022	SYSTEM	\$4,000.00	Estimate Item Adjustment (0007) due to user washid1 overridding Payment
Seminate   Seminate						2		SYSTEM	(\$4,000.00)	
						3		SYSTEM	\$4,000.00	Estimate Item Adjustment (0009) due to user washid1 overridding Payment
2022   Estimate [tem Adjustment (0006) due to user washid1 overridding Payment Estimate.						3	May 16, 2022	SYSTEM	(\$4,000.00)	
2022   5						4		SYSTEM	\$4,000.00	Estimate Item Adjustment (0006) due to user washid1 overridding Payment
Set   Set						4		SYSTEM	(\$4,000.00)	
Substitution   Subs						5		SYSTEM	\$4,000.00	Estimate Item Adjustment (0006) due to user washid1 overridding Payment
Material - Total   S0.00   System   S						5		SYSTEM	(\$4,000.00)	
Second   S					- Total				\$0.00	
Substitute   Sub				Material - To	otal				\$0.00	
Material - Total		0100 -	Total						\$0.00	
2022   Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.    3	J6M3413 -	- Total							\$0.00	
CONTROL   DEVICES   Material - Total   S0.00	J6M3414	0110	MISC.	Material		3		SYSTEM	\$90,000.00	Estimate Item Adjustment (0001) due to user washid1 overridding Payment
Material - Total   \$0.00						3		SYSTEM	(\$90,000.00)	
O110 - Total  O130 MISC. TRAFFIC CONTROL DEVICES  O130 May 16, 2022 SYSTEM S5,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  3 May 16, SYSTEM (\$5,000.00)  - Total \$0.00  Material - Total \$0.00  O130 - Total \$0.00  J6M3414 - Total \$0.00									\$0.00	
0130 MISC. TRAFFIC CONTROL DEVICES Material 2022 SYSTEM \$5,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid 1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  3 May 16, 2022 SYSTEM (\$5,000.00)  - Total \$0.00  Material - Total \$0.00  0130 - Total \$0.00  J6M3414 - Total \$0.00				Material - To	otal				\$0.00	
CONTROL DEVICES    2022   Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.   3		0110 -	Total						\$0.00	
2022		0130	CONTROL	Material		3		SYSTEM	\$5,000.00	Estimate Item Adjustment (0002) due to user washid1 overridding Payment
Material - Total \$0.00 0130 - Total \$0.00  J6M3414 - Total \$0.00					3			SYSTEM	(\$5,000.00)	
0130 - Total \$0.00  J6M3414 - Total \$0.00					- Total				\$0.00	
J6M3414 - Total \$0.00				Material - To	otal				\$0.00	
		0130 -	Total						\$0.00	
Overall - Total \$0.00	J6M3414	- Total							\$0.00	
	Overall - 1	Γotal							\$0.00	