

Pay Estimate Created Date: June 3, 2022

Progress Estimate Number 6	Contract ID 220121-F08 Prime Contractor N.B. West Contracting Company	Pay Period Start May 16, 2022 Original Contract Amoun Pay Period End June 1, 2022 Net Change Order Amount Current Contract Amount	nt \$14,972.00
1.0.1			Б. 11

By User		Approval Date
wagamt1	Generated and Approved (and should be considered Draft) at the Project Office Level by	June 3, 2022
vancef1	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	June 3, 2022
ramses1	Reviewed and Approved at the Central Office Controllers Office Level by	June 6, 2022

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2022	November 1, 2022		91.86%

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	February 2, 2022	February 2, 2022	
Letting Date	January 21, 2022	January 21, 2022	
Notice to Proceed Date	March 7, 2022	March 7, 2022	
Open to Traffic Date			
Work Began Date			

Contract Total Pa	ay For Estimate No. 6			
		This Estimate	Previous	To Date
220121-F08	Total Destad Itama Day	\$437,535.50	¢2 200 700 40	¢2.747.245.60
	Total Posted Items Pay Gross Item Adjustments	\$18,875.97	\$2,309,780.10 (\$15,914.64)	\$2,747,315.60 \$2,961.33
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage Other Contract Adjustments	\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00
	Other Contract Adjustments	φυ.υυ	\$2,293,865.46	\$2,750,276.93
Contract Total Pa	ayable This Estimate:	\$456,411.47		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3293	0070	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$83.000	118.3	\$9,818.90
	0090	4139912	MISC.OPTIONAL SURFACE TREATMENT	GAL	\$2.450	146	\$357.70
	0100	6083003	3 IN. CONCRETE MEDIAN STRIP	SQYD	\$78.000	0.2	\$15.60
	0140	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	SQYD	\$1.000	67.8	\$67.80
	0150	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	SQYD	\$5.000	67.8	\$339.00
	0160	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	LF	\$3.000	161	\$483.00
	0180	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$11.000	9	\$99.00
	0240	6169901	MISC.TEMPORARY TRAFFIC CONTROL	LS	\$12,500.000	0.45	\$5,625.00
	0270	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$17.000	76	\$1,292.00
	0280	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	EA	\$300.000	2	\$600.00
	0300	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	EA	\$400.000	1	\$400.00
	0310	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.100	89,619	\$8,961.90
	0320	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.100	88,773	\$8,877.30
	0330	6207001	PAVEMENT MARKING REMOVAL	LF	\$1.000	653	\$653.00

Revision 4/1/2020 Page 1 of 19



Pay Estimate Created Date: June 3, 2022

Progress Estimate Number			•		Original Contract Amount	. , ,
c	Prime Contractor	r N.B. West Contracting Company	Pay Period End	June 1, 2022	Net Change Order Amount	\$14,972.00
0					Current Contract Amount	\$2,990,613.14

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3293	0340	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$1.500	10,014	\$15,021.00
	0370	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$1,500.000	0.4	\$600.00
Project J6	S3293 - To	otal					\$53,211.20
J6S3628	0560	3105002	GRAVEL (A) OR CRUSHED STONE (B)	TONS	\$230.000	18	\$4,140.00
	0580	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$85.000	3,927.38	\$333,827.30
	0590	4071005	TACK COAT	GAL	\$2.000	200	\$400.00
	0600	4139912	MISC.Optional Surface Treatment	GAL	\$2.450	12,860	\$31,507.00
	0660	6169901	MISC.Temporary Traffic Control	LS	\$16,000.000	0.45	\$7,200.00
	0680	6181000	MOBILIZATION	LS	\$29,000.000	0.25	\$7,250.00
Project J6	S3628 - T	otal					\$384,324.30
Overall - 1	Γotal						\$437,535.50

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
l6S3293	0070	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material			-9,508.29	\$83.00	(\$789,188.07)
	0070	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user wagamt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	9,508.29	\$83.00	\$789,188.07
	0070	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	Asphalt Cement Price Adjustment	118.30 Tons placed 5/2-5/15 SL22-9A Virgin AC 4.7% Base 502.5 Current 637.5 DIFF 135 Total 750.61			\$750.61
	0100	3 IN. CONCRETE MEDIAN STRIP	Material			-89.8	\$78.00	(\$7,004.40)
	0100	3 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user wagamt1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	89.8	\$78.00	\$7,004.40
	0130	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-329	\$210.00	(\$69,090.00)
	0130	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user wagamt1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	329	\$210.00	\$69,090.00
	0130	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Overrun	Overrun				\$12,180.00
	0140	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material			-313	\$1.00	(\$313.00)

Revision 4/1/2020 Page 2 of 19



Pay Estimate Created Date: June 3, 2022

Progress Estimate Number
6
Contract ID 220121-F08 Pay Period Start May 16, 2022 Original Contract Amount \$2,975,641.14
Prime Contractor N.B. West Contracting Company Pay Period End June 1, 2022 Net Change Order Amount \$14,972.00
Current Contract Amount \$2,990,613.14

ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment	Comments	Adjustment Quantity	Line Item Adjustment	Adjustment amount
293	0140	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material	Туре	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user wagamt1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	313	\$1.00	\$313.0
	0140	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Overrun	Overrun				\$218.2
	0150	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material			-313	\$5.00	(\$1,565.0
	0150	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user wagamt1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	313	\$5.00	\$1,565.0
	0150	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Overrun	Overrun				\$1,091.0
	0160	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3.00000 - 3.00000, 'is applied (if non-zero).	315	\$3.00	\$945.0
	0270	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-76	\$17.00	(\$1,292.0
	0270	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user wagamt1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	76	\$17.00	\$1,292.0
	0280	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-2	\$300.00	(\$600.0
	0280	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user wagamt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	2	\$300.00	\$600.0
	0300	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	Material			-1	\$400.00	(\$400.0
	0300	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user wagamt1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	1	\$400.00	\$400.0
	0310	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-89,619	\$0.10	(\$8,961.9
	0310	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user wagamt1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	89,619	\$0.10	\$8,961.9
	0320	4 IN. YELLOW STANDARD	Material			-88,773	\$0.10	(\$8,877.30

Revision 4/1/2020 Page 3 of 19



Pay Estimate Created Date: June 3, 2022

Progress Estimate Number
6
Contract ID 220121-F08 Pay Period Start May 16, 2022 Original Contract Amount \$2,975,641.14
Prime Contractor N.B. West Contracting Company Pay Period End June 1, 2022 Original Contract Amount \$14,972.00
Current Contract Amount \$2,990,613.14

						ireni contra		\$2,990,013.14
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3293		WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS						
	0320	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user wagamt1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	88,773	\$0.10	\$8,877.30
	0360	MISC.	Material			-864	\$3.00	(\$2,592.00)
	0360	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user wagamt1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	864	\$3.00	\$2,592.00
J6S3628	0550	MISC.	Material			-311	\$28.00	(\$8,708.00)
	0550	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user wagamt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	311	\$28.00	\$8,708.00
	0580	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun			-184.38	\$85.00	(\$15,672.30)
	0580	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material			-3,927.38	\$85.00	(\$333,827.30)
	0580	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 3927.380; Overrun Quantity Balance 184.38.	184.38	\$85.00	\$15,672.30
	0580	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user wagamt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	3,927.38	\$85.00	\$333,827.30
	0580	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	Asphalt Cement Price Adjustment	3927.38 Tons placed 5/16-6/1 SL20-27A Virgin AC 3.8% Base 502.5 Current 637.5 DIFF 135 Total 20147.46			\$20,147.46
	0580	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun	Overrun				(\$15,672.30)
	0600	MISC.	Overrun			-320	\$2.45	(\$784.00)
	0730	MISC.	Material			-368	\$10.00	(\$3,680.00)
	0730	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user wagamt1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	368	\$10.00	\$3,680.00
Total								\$18,875.97

Revision 4/1/2020 Page 4 of 19



						Contract Project Information				
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work					
J6S3293	FAS S502(56)	Resurfacing	BB	JEFFERSON	from Route 30 in Ced	ar Hill to Elm Street in Hillsbo	oro			
J6S3628	FAS S503(16)	Resurface	F	JEFFERSON	from Route O to St. J	oseph Hills Road				
Totals by .	Job Numbe	rs								
J6S3293	Posted Item Pay Gross Item Adjustments		This Estimate \$53,211.20 \$15,184.81	Previous \$1,827,581.59 \$22,860.50	To Date \$1,880,792.79 \$38,045.31					
		tive centive lated Damages		s Item Pay	\$68,396.01 \$0.00 \$0.00 \$0.00	\$1,850,442.09 \$0.00 \$0.00 \$0.00	\$1,918,838.10 \$0.00 \$0.00 \$0.00			
		Contract Adju			\$0.00	\$0.00	\$0.00			
J6S3628		d Item Pay Item Adjustm		s Item Pay	This Estimate \$384,324.30 \$3,691.16 \$388,015.46	Previous \$482,198.51 (\$38,775.14) \$443,423.37	To Date \$866,522.81 (\$35,083.98) \$831,438.83			
	Liquid	tive centive lated Damages Contract Adiu			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			

Revision 4/1/2020 Page 5 of 19



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3628, Item 3049905, Project Item Line Number 0550, Material Set 304990596, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with materials to resolve this exception	wagamt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3293, Item 4020520, Project Item Line Number 0070, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient.	Working with materials to resolve this exception	wagamt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3628, Item 4020520, Project Item Line Number 0580, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient.	Working with materials to resolve this exception	wagamt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3293, Item 6083003, Project Item Line Number 0100, Material Set 608300396, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Working with materials to resolve this exception	wagamt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3293, Item 6083003, Project Item Line Number 0100, Material Set 608300396, Material 0501CCPAQCQA - Concrete, Payment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working on QA QC reports to resolve	wagamt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3293, Item 6131010, Project Item Line Number 0130, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with materials to resolve this exception	wagamt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3293, Item 6131010, Project Item Line Number 0130, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Working with materials to resolve this exception	wagamt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3293, Item 6131012, Project Item Line Number 0140, Material Set 613101296, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Working with materials to resolve this exception	wagamt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3293, Item 6131013, Project Item Line Number 0150, Material Set 613101396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with materials to resolve this exception	wagamt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3293, Item 6200015, Project Item Line Number 0270, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Emailed the contractor on 6/1 for certs.	wagamt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3293, Item 6200021, Project Item Line Number 0280, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Emailed the contractor on 6/1 for certs.	wagamt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3293, Item 6200027, Project Item Line Number 0300, Material Set 620002796, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Emailed the contractor on 6/1 for certs.	wagamt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3293, Item 6206000C, Project Item Line Number 0310, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Emailed the contractor on 6/1 for certs.	wagamt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3293, Item 6206000C, Project Item Line Number 0310, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Emailed the contractor on 6/1 for certs.	wagamt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3293, Item 6206001C, Project Item Line Number 0320, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Emailed the contractor on 6/1 for certs.	wagamt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3293, Item 6206001C, Project Item Line Number 0320, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Emailed the contractor on 6/1 for certs.	wagamt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3293, Item 6249905, Project Item Line Number 0360, Material Set 624990596, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient.	Working with materials to resolve this exception	wagamt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3628, Item 6249905, Project Item Line Number 0730, Material Set 624990596, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient.	Working with materials to resolve this exception	wagamt1	Overridden
Estimate Exception Type: Item Overrun: Contract 220121-F08, Contract Project J6S3628, Project Item Line Number 0580, Contract Line Item Number 0580, Item 4020520, Minor Item.	CO forthcoming	wagamt1	Overridden
Estimate Exception Type: Item Overrun: Contract 220121-F08, Contract Project J6S3628, Project Item Line Number 0600, Contract Line Item Number 0600, Item 4139912, Minor Item.	CO forthcoming	wagamt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220121-F08, Contract Project J6S3293, Project Item Line Number 0200, Contract Line Item Number 0200, Item 6133020, Minor Item.	CO forthcoming	wagamt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220121-F08, Contract Project J6S3293, Project Item Line Number 0210, Contract Line Item Number 0210, Item 6133021, Minor Item.	CO forthcoming	wagamt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220121-F08, Contract Project J6S3628, Project Item Line Number 0570, Contract Line Item Number 0570, Item 4013000, Minor Item.	CO forthcoming	wagamt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220121-F08, Contract Project J6S3628, Project Item Line Number 0640, Contract Line Item Number 0640, Item 6133020, Minor Item.	CO forthcoming	wagamt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220121-F08, Contract Project J6S3628, Project Item Line Number 0650, Contract Line Item Number 0650, Item 6133021, Minor Item.	CO forthcoming	wagamt1	Acknowledged

Revision 4/1/2020 Page 6 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-F08	J6S3293	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.90	\$14,400.00	\$12,960.00
		0001	0020	2063000	CLASS 3 EXCAVATION	52.00	0.00	52.00	CUYD	52.00	\$0.01	\$0.52
		0001	0030	2153000	SHAPING SLOPES, CLASS III	8.00	0.00	8.00	100F	8.00	\$1,200.00	\$9,600.00
		0001	0040	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	56.00	0.00	56.00	SQYD	56.00	\$2.50	\$140.00
		0001	0050	3105002	GRAVEL (A) OR CRUSHED STONE (B)	86.00	0.00	86.00	TONS	0.00	\$160.00	\$0.00
		0001	0060	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	18.40	0.00	18.40	TONS	10.57	\$150.00	\$1,585.50
		0001	0070	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	12,166.70	0.00	12,166.70	TONS	9,508.29	\$83.00	\$789,188.07
		0001	0080	4071005	TACK COAT	13,946.00	0.00	13,946.00	GAL	2,305.00	\$2.00	\$4,610.00
		0001	0090	4139912	MISC.OPTIONAL SURFACE TREATMENT	33,085.00	0.00	33,085.00	GAL	30,038.00	\$2.45	\$73,593.10
		0001	0100	6083003	3 IN. CONCRETE MEDIAN STRIP	89.80	0.00	89.80	SQYD	89.80	\$78.00	\$7,004.40
		0001	0110	6097000	ROCK LINING	9.00	0.00	9.00	CUYD	9.00	\$240.00	\$2,160.00
		0001	0120	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$0.01	\$0.00
		0001	0130	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	271.00	58.00	329.00	SQYD	329.00	\$210.00	\$69,090.00
		0001	0140	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	27.00	286.00	313.00	SQYD	313.00	\$1.00	\$313.00
		0001	0150	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	27.00	286.00	313.00	SQYD	313.00	\$5.00	\$1,565.00
		0001	0160	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	1,041.00	476.00	1,517.00	LF	1,517.00	\$3.00	\$4,551.00
		0001	0170	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	340.00	0.00	340.00	EA	340.00	\$7.00	\$2,380.00
		0001	0180	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	84.00	-32.00	52.00	EA	52.00	\$11.00	\$572.00
		0001	0190	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	42.00	0.00	42.00	EA	42.00	\$3.00	\$126.00
		0001	0200	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	4,053.00	0.00	4,053.00	TONS	4,117.70	\$90.00	\$370,593.00
		0001	0210	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	24,770.00	0.00	24,770.00	SQYD	25,629.00	\$11.00	\$281,919.00
		0001	0220	6161047	TYPE III OBJECT MARKER	2.00	0.00	2.00	EA	0.00	\$600.00	\$0.00
		0001	0230	6161070	TUBULAR MARKER	12.00	0.00	12.00	EA	0.00	\$65.00	\$0.00
		0001	0240	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.95	\$12,500.00	\$11,875.0
		0001	0250	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	4.00	0.00	4.00	EA	0.00	\$1,000.00	\$0.00
		0001	0260	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$98,000.00	\$98,000.0
		0001	0270	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	76.00	0.00	76.00	LF	76.00	\$17.00	\$1,292.0
		0001	0280	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	2.00	0.00	2.00	EA	2.00	\$300.00	\$600.00
		0001	0290	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	4.00	0.00	4.00	EA	0.00	\$200.00	\$0.00
		0001	0300	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	1.00	0.00	1.00	EA	1.00	\$400.00	\$400.00
		0001	0310	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	112,024.00	0.00	112,024.00	LF	89,619.00	\$0.10	\$8,961.9
		0001	0320	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	110,967.00	0.00	110,967.00	LF	88,773.00	\$0.10	\$8,877.30
		0001	0330	6207001	PAVEMENT MARKING REMOVAL	653.00	0.00	653.00	LF	653.00	\$1.00	\$653.00
		0001	0340	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	10,014.00	0.00	10,014.00	SQYD	10,014.00	\$1.50	\$15,021.00
		0001	0350	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	6,950.00	0.00	6,950.00	SQYD	6,950.00	\$6.00	\$41,700.0
		0001	0360	6249905	MISC.INSTALLING HIGH PERFORMANCE GEOTEXTILE	864.00	0.00	864.00	SQYD	864.00	\$3.00	\$2,592.0
		0001	0370	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.90	\$1,500.00	\$1,350.0
		0001	0380	7261036	36 IN. PIPE GROUP A	38.00	0.00	38.00	LF	38.00	\$340.00	\$12,920.0
		0001	0390	7320636A	36 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
		0001	0400	8061005	ROCK DITCH CHECK	80.00	0.00	80.00	LF	0.00	\$15.00	\$0.00
		0001	0410	8061019	SILT FENCE	400.00	0.00	400.00	LF	0.00	\$3.80	\$0.00
		0010	0420	6061050	GUARDRAIL TYPE E, 6 FT. POST, 3 FT1.5 IN. SPACING	63.00	0.00	63.00	LF	63.00	\$60.00	\$3,780.00

Page 7 of 19 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-F08	J6S3293	0010	0430	6061060	MGS GUARDRAIL	38.00	0.00	38.00	LF	38.00	\$40.00	\$1,520.00
		0010	0440	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$3,650.00	\$14,600.00
		0010	0450	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	1.00	\$1,500.00	\$1,500.0
		0010	0460	6062301A	TRANSITION SECTION, 7.5 FT. POSTS	2.00	0.00	2.00	EA	2.00	\$600.00	\$1,200.00
		0010	0470	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	5.00	0.00	5.00	EA	5.00	\$3,200.00	\$16,000.0
		0040	0480	9031270A	2 IN. PSST POST - 12 GA.	29.00	0.00	29.00	LF	0.00	\$24.00	\$0.00
		0040	0490	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	6.00	0.00	6.00	LF	0.00	\$40.00	\$0.0
		0040	0500	9035004A	SH-FLAT SHEET	18.00	0.00	18.00	SQFT	0.00	\$26.00	\$0.0
		0040	0510	9035069A	SHF-FLAT SHEET FLUORESCENT	4.00	0.00	4.00	SQFT	0.00	\$30.00	\$0.0
	Project Je	S3293 - To	tal Value	Posted to D	ate as of Report Generated Date							\$1,880,792.7
	J6S3628	0001	0520	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$6,000.00	\$6,000.0
		0001	0530	2031000	CLASS A EXCAVATION	203.00	0.00	203.00	CUYD	203.00	\$42.00	\$8,526.0
		0001	0540	2153000	SHAPING SLOPES, CLASS III	6.00	0.00	6.00	100F	6.00	\$1,200.00	\$7,200.0
		0001	0550	3049905	MISC.14 IN. TYPE 5 AGGREGATE FOR BASE	311.00	0.00	311.00	SQYD	311.00	\$28.00	\$8,708.0
		0001	0560	3105002	GRAVEL (A) OR CRUSHED STONE (B)	18.00	0.00	18.00	TONS	18.00	\$230.00	\$4,140.0
		0001	0570	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	132.00	0.00	132.00	TONS	148.57	\$120.00	\$17,828.4
		0001	0580	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	3,743.00	0.00	3,743.00	TONS	3,927.38	\$85.00	\$333,827.3
		0001	0590	4071005	TACK COAT	4,712.00	0.00	4,712.00	GAL	1,025.00	\$2.00	\$2,050.0
		0001	0600	4139912	MISC.Optional Surface Treatment	12,540.00	0.00	12,540.00	GAL	12,860.00	\$2.45	\$31,507.0
		0001	0610	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	636.00	0.00	636.00	CUYD	531.00	\$46.00	\$24,426.0
		0001	0620	6096042	PLACING TYPE 2 ROCK DITCH LINER	636.00	0.00	636.00	CUYD	531.00	\$40.00	\$21,240.0
		0001	0630	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	0.00	\$0.01	\$0.0
		0001	0640	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	1,627.40	0.00	1,627.40	TONS	1,994.19	\$90.00	\$179,477.1
		0001	0650	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	9,972.80	0.00	9,972.80	SQYD	10,605.00	\$10.00	\$106,050.0
		0001	0660	6169901	MISC.Temporary Traffic Control	1.00	0.00	1.00	LS	0.95	\$16,000.00	\$15,200.0
		0001	0670	6169902	MISC.NTCIP Compliant Changeable Message Sign (Contractor Furnished & Retained)	4.00	0.00	4.00	EA	0.00	\$1,000.00	\$0.0
		0001	0680	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$29,000.00	\$29,000.0
		0001	0690	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	28.00	0.00	28.00	LF	0.00	\$17.00	\$0.0
		0001	0700	6206000C	$4\ \mbox{IN}.$ WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	42,770.00	0.00	42,770.00	LF	0.00	\$0.09	\$0.0
		0001	0710	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	42,460.00	0.00	42,460.00	LF	0.00	\$0.09	\$0.0
		0001	0720	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	6,979.00	0.00	6,979.00	SQYD	6,979.00	\$5.00	\$34,895.0
		0001	0730	6249905	MISC.FURNISHING AND PLACING SEPARATION GEOTEXTILE- TENSAR TRIAX TX7 GEOGRID	368.00	0.00	368.00	SQYD	368.00	\$10.00	\$3,680.0
		0001	0740	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	212.00	0.00	212.00	STA	0.00	\$14.00	\$0.0
		0001	0750	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$0.01	\$0.0
		0010	0760	6061060	MGS GUARDRAIL	163.00	0.00	163.00	LF	163.00	\$36.00	\$5,868.0
		0010	0770	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	2.00	0.00	2.00	EA	2.00	\$3,800.00	\$7,600.0
		0010	0780	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	2.00	0.00	2.00	EA	2.00	\$3,650.00	\$7,300.0
		0010	0790	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$3,000.00	\$12,000.0
i i	Project Je	S3628 - To	otal Value	Posted to D	ate as of Report Generated Date							\$866,522.8

Revision 4/1/2020 Page 8 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6S3293

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/Distance	To Station/ Log Mile	Offset/Distance	Comments
0070	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	5/19/22	5/19/22	118.30	TONS	Route BB	L.M 0.019		L.M 10.435		Catching up pay from 5/13
0090	4139912	MISC. ULTRATHIN BONDED WEARING SURFACE	5/19/22	5/19/22	146.00	GAL	Route BB	L.M 0.019		L.M 10.435		Catching up pay from 5/13
0100	6083003	3 IN. CONCRETE MEDIAN STRIP	6/1/22	6/3/22	0.20	SQYD	Route BB	L.M 0.115		L.M 0.119		
0140	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEM	6/1/22	6/3/22	67.80	SQYD	Route BB	L.M .02		L.M .09		
0150	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. TH	6/1/22	6/3/22	67.80	SQYD		L.M .02		L.M .09		
0160	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	6/1/22	6/3/22	161.00	LF	Route BB	L.M .02		L.M .09		
0180	6131017	DOWEL BAR (FURNISH AND INSTALL WITH BASK	6/1/22	6/3/22	9.00	EA	Route BB	L.M .02		L.M .09		
0240	6169901	MISC.	6/1/22	6/3/22	0.45	LS		L.M . 019		L.M 10.435		3 partial payment temporary traffic control
0270	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	5/23/22	6/1/22	76.00	LF		0.019		0.361		
0280	6200021	PREF THERMO PVMT MARK, LT/RT ARROW	5/23/22	6/1/22	2.00	EA		0.019		0.224		
0300	6200027	PREF THERMO PVMT MARKING, COMBO	5/23/22	6/1/22	1.00	EA		0.019		0.224		
0310	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	5/23/22	6/1/22	89,619.00	LF		0.019		10.435		Paid 80%, (89619.00) will pay balance of 20% (22405.0) after retro-reflectivity results come back.
0320	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	5/23/22	6/1/22	88,773.00	LF		0.019		10.435		Paid 80%, (88773.00) will pay balance of 20% (22194.0) after retro-reflectivity results come back.
0330	6207001	PAVEMENT MARKING REMOVAL	5/23/22	6/1/22	653.00	LF		0.019		0.224		
0340	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	6/1/22	6/3/22	10,014.00	SQYD	Route BB	L.M .02		L.M .09		
0370	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	6/1/22	6/3/22	0.40	LS	Route BB	L.M 0.019		L.M 10.435		

Project: J6S3628

Line lumber	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0560	3105002	GRAVEL (A) OR CRUSHED STONE (B)	5/31/22	6/2/22	18.00	TONS	Route F	L.M 2.488		L.M 6.509		
0580	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	5/23/22	5/25/22	1,761.39	TONS	Route F	SB/NB L.M6.5&SB 5.8		NB/SB L.M5.8&SB 3.2		
			5/24/22	5/25/22	1,289.61	TONS	Route F	SBL.M2.48&NBL.M2.48		SB L.M 3.2& NBL.M4.4		
			5/26/22	6/2/22	752.63	TONS	Route F	L.M 4.4		L.M 5.8		
			5/31/22	6/2/22	123.75	TONS	Route F	L.M 2.488		L.M 6.509		
0590	4071005	TACK COAT	5/31/22	6/2/22	200.00	GAL	Route F	L.M 2.488		L.M 6.509		
0600	4139912	MISC. ULTRATHIN BONDED WEARING SURFACE	5/23/22	5/25/22	6,139.00	GAL	Route F	SB/NB L.M6.5&SB 5.8		NB/SB L.M5.8&SB 3.2		
			5/24/22	5/25/22	4,385.00	GAL	Route F	SBL.M2.48&NBL.M2.48		SB L.M 3.2& NBL.M4.4		
			5/26/22	6/2/22	2,336.00	GAL	Route F	L.M 4.4		L.M 5.8		
0660	6169901	MISC.	6/1/22	6/3/22	0.45	LS	Route F	L.M 2.488		L.M 6.509		
0680	6181000	MOBILIZATION	6/1/22	6/3/22	0.25	LS	Route F	L.M 2.488		L.M 6.509		

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 9 of 19



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
SS3293	0060	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BAS	Other Item Adjustment	ACAD	4	May 2, 2022	BOWMAM2	\$11.55	10.57 tons placed 03/16 to 04/01 3.8% virgin BP1 19-19 Base 502.50 Current 531.25 Diff 28.75 Total 11.55
				ACAD - Tota	al			\$11.55	
			Other Item	Adjustment -	Total			\$11.55	
	0060 -							\$11.55	
	0070	PAVEMENT MIXTURE PG64-22 (SUR	Material		4	May 2, 2022	SYSTEM	\$322,049.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		1 004-22 (0010			4	May 2, 2022	SYSTEM	(\$322,049.96)	
					5	May 16, 2022	SYSTEM	\$779,369.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$779,369.17)	
					6	Jun 3, 2022	SYSTEM	\$789,188.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wagamt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jun 3, 2022	SYSTEM	(\$789,188.07)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	ACAD	4	May 2, 2022	BOWMAM2	\$10,030.11	3880.12 tons placed 04/16 to 05/01 4.7% virgin SL22-9A Base 502.50 Current 557.50 Diff 55.00 Total 10030.11
					5	May 16, 2022	BOWMAM2	\$34,960.13	5509.87 tons placed from 5/2 to 5/15 SL22-9A 4.7% virgin AC Base 502.5 Current 637.5 Difference 135 Total 34960.13
					6	Jun 3, 2022	wagamt1	\$750.61	118.30 Tons placed 5/2-5/15 SL22-9A Virgin AC 4.7% Base 502.5 Current 637.5 DIFF 135 Total 750.61
				ACAD - Tota	al			\$45,740.85	
			Other Item	Adjustment -	Total			\$45,740.85	
	0070 -	Total						\$45,740.85	
	0800	TACK COAT	Material		2	Apr 4, 2022	SYSTEM	\$1,018.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Apr 4, 2022	SYSTEM	(\$1,018.00)	
					3	Apr 18, 2022	SYSTEM	\$4,610.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$4,610.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0080 -	Total						\$0.00	
	0100	3 IN. CONCRETE MEDIAN STRIP	Material		2	Apr 4, 2022	SYSTEM	\$6,988.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user bowmam2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Apr 4, 2022	SYSTEM	(\$6,988.80)	
					3	Apr 18, 2022	SYSTEM	\$6,988.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3293	0100	3 IN.	Material						Estimate Exception 3 on the current Payment Estimate.
		CONCRETE MEDIAN STRIP			3	Apr 18, 2022	SYSTEM	(\$6,988.80)	
					4	May 2, 2022	SYSTEM	\$6,988.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$6,988.80)	
					5	May 16, 2022	SYSTEM	\$6,988.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$6,988.80)	
					6	Jun 3, 2022	SYSTEM	\$7,004.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wagamt1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Jun 3, 2022	SYSTEM	(\$7,004.40)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0100 -	· Total						\$0.00	
	0110	ROCK LINING	Material		2	Apr 4, 2022	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					2	Apr 4, 2022	SYSTEM	(\$2,160.00)	
					3	Apr 18, 2022	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$2,160.00)	
					4	May 2, 2022	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user bowmam2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$2,160.00)	
					5	May 16, 2022	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$2,160.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0110 -	· Total						\$0.00	
	0130	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		2	Apr 4, 2022	SYSTEM	\$69,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user bowmam2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
		FOLL DEPTH			2	Apr 4, 2022	SYSTEM	(\$69,090.00)	
					3	Apr 18, 2022	SYSTEM	\$69,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$69,090.00)	
					4	May 2, 2022	SYSTEM	\$69,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$69,090.00)	
					5	May 16, 2022	SYSTEM	\$69,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$69,090.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3293	0130	FURN & PLACE CONC MATL FOR	Material		6	Jun 3, 2022	SYSTEM	\$69,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wagamt1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		FULL DEPTH			6	Jun 3, 2022	SYSTEM	(\$69,090.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	2	Apr 4, 2022	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 329.000; Overrun Quantity Balance 58.00.
					2	Apr 4, 2022	BOWMAM2	(\$12,180.00)	
					2	Apr 4, 2022	SYSTEM	(\$12,180.00)	
					3	Apr 18, 2022	SYSTEM	(\$12,180.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					3	Apr 18, 2022	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 18 on the current Payment Estimate. Material Insufficiency Quantity 329.000; Overrun Quantity Balance 58.00.
					4	May 2, 2022	SYSTEM	(\$12,180.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					4	May 2, 2022	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 17 on the current Payment Estimate. Material Insufficiency Quantity 329.000; Overrun Quantity Balance 58.00.
					5	May 16, 2022	SYSTEM	(\$12,180.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	May 16, 2022	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 17 on the current Payment Estimate. Material Insufficiency Quantity 329.000; Overrun Quantity Balance 58.00.
					6	Jun 3, 2022	wagamt1	\$12,180.00	
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0130 -	Total						\$0.00	
	0140	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEM	Material		2	Apr 4, 2022	SYSTEM	\$245.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
		(1714			2	Apr 4, 2022	SYSTEM	(\$245.20)	
					3	Apr 18, 2022	SYSTEM	\$245.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user bowmam2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$245.20)	
					4	May 2, 2022	SYSTEM	\$245.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$245.20)	
					5	May 16, 2022	SYSTEM	\$245.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$245.20)	
					6	Jun 3, 2022	SYSTEM	\$313.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wagamt1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Jun 3, 2022	SYSTEM	(\$313.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3293	0140	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEM	Overrun	Overrun	2	Apr 4, 2022	SYSTEM	\$146.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) overridding Payment Estimate Exception 21 on the current Payment Estimate. Material Insufficiency Quantity 245.200; Overrun Quantity Balance 218.20.
					2	Apr 4, 2022	SYSTEM	\$71.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) overridding Payment Estimate Exception 21 on the current Payment Estimate. Material Insufficiency Quantity 245.200; Overrun Quantity Balance 218.20.
					2	Apr 4, 2022	BOWMAM2	(\$218.20)	
					2	Apr 4, 2022	SYSTEM	(\$218.20)	
					3	Apr 18, 2022	SYSTEM	(\$218.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					3	Apr 18, 2022	SYSTEM	\$218.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 245.200; Overrun Quantity Balance 218.20.
					4	May 2, 2022	SYSTEM	(\$218.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					4	May 2, 2022	SYSTEM	\$218.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 18 on the current Payment Estimate. Material Insufficiency Quantity 245.200; Overrun Quantity Balance 218.20.
					5	May 16, 2022	SYSTEM	(\$218.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	May 16, 2022	SYSTEM	\$218.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 18 on the current Payment Estimate. Material Insufficiency Quantity 245.200; Overrun Quantity Balance 218.20.
					6	Jun 3, 2022	wagamt1	\$218.20	
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0140 -							\$0.00	
	0150	TYPE 1 OR 5 AGGREGATE	Material		2	Apr 4, 2022	SYSTEM	\$1,226.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user bowmam2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
		FOR BASE (4 IN. TH							
					2	Apr 4, 2022	SYSTEM	(\$1,226.00)	
					3		SYSTEM	(\$1,226.00) \$1,226.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
						2022 Apr 18,			Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment
					3	2022 Apr 18, 2022 Apr 18,	SYSTEM	\$1,226.00	Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment
					3	2022 Apr 18, 2022 Apr 18, 2022 May 2,	SYSTEM	\$1,226.00 (\$1,226.00)	Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment
					3 4	2022 Apr 18, 2022 Apr 18, 2022 May 2, 2022 May 2,	SYSTEM SYSTEM SYSTEM	\$1,226.00 (\$1,226.00) \$1,226.00	Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment
					3 4 4	2022 Apr 18, 2022 Apr 18, 2022 May 2, 2022 May 2, 2022 May 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,226.00 (\$1,226.00) \$1,226.00	Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment
					3 3 4 4 5	2022 Apr 18, 2022 Apr 18, 2022 May 2, 2022 May 16, 2022 May 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,226.00 (\$1,226.00) \$1,226.00 (\$1,226.00) \$1,226.00	Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment
					3 3 4 4 5	2022 Apr 18, 2022 Apr 18, 2022 May 2, 2022 May 16, 2022 May 16, 2022 Jun 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,226.00 (\$1,226.00) \$1,226.00 (\$1,226.00) (\$1,226.00)	Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wagamt1 overridding Payment Estimate Item Adjustment (0009) due to user wagamt1 overridding Payment
				- Total	3 4 4 5 5 6 6	2022 Apr 18, 2022 Apr 18, 2022 May 2, 2022 May 16, 2022 May 16, 2022 Jun 3, 2022 Jun 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,226.00 (\$1,226.00) \$1,226.00 (\$1,226.00) \$1,226.00 (\$1,226.00)	Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wagamt1 overridding Payment Estimate Item Adjustment (0009) due to user wagamt1 overridding Payment
			Material - To		3 4 4 5 5 6 6	2022 Apr 18, 2022 Apr 18, 2022 May 2, 2022 May 16, 2022 May 16, 2022 Jun 3, 2022 Jun 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,226.00 (\$1,226.00) \$1,226.00 (\$1,226.00) \$1,226.00 (\$1,226.00) (\$1,565.00)	Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wagamt1 overridding Payment Estimate Item Adjustment (0009) due to user wagamt1 overridding Payment
			Material - To		3 3 4 4 5 5 6	2022 Apr 18, 2022 Apr 18, 2022 May 2, 2022 May 16, 2022 May 16, 2022 Jun 3, 2022 Jun 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,226.00 (\$1,226.00) \$1,226.00 (\$1,226.00) \$1,226.00 (\$1,226.00) \$1,565.00 (\$1,565.00)	Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wagamt1 overridding Payment Estimate Item Adjustment (0009) due to user wagamt1 overridding Payment



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3293	0150	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. TH	Overrun	Overrun		2022			Estimate Item Adjustment (0049) overridding Payment Estimate Exception 22 on the current Payment Estimate. Material Insufficiency Quantity 245.200; Overrun Quantity Balance 218.20.
		IIN. ITI			2	Apr 4, 2022	BOWMAM2	(\$1,091.00)	
					2	Apr 4, 2022	SYSTEM	(\$1,091.00)	
					3	Apr 18, 2022	SYSTEM	(\$1,091.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					3	Apr 18, 2022	SYSTEM	\$1,091.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 245.200; Overrun Quantity Balance 218.20.
					4	May 2, 2022	SYSTEM	(\$1,091.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					4	May 2, 2022	SYSTEM	\$1,091.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 245.200; Overrun Quantity Balance 218.20.
					5	May 16, 2022	SYSTEM	(\$1,091.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	May 16, 2022	SYSTEM	\$1,091.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 245.200; Overrun Quantity Balance 218.20.
					6	Jun 3, 2022	wagamt1	\$1,091.00	
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0150 -	Total						\$0.00	
	0160	FULL DEPTH PAVEMENT	Overrun	Overrun	2	Apr 4, 2022	SYSTEM	(\$945.00)	
		REPAIR SAW CUT (FOR			6	Jun 3, 2022	SYSTEM	\$945.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3.00000 - 3.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0160 -	Total						\$0.00	
	0170	DOWEL BAR (DRILLING,						Ψ0.00	
		FÜRNISHING	Material		2	Apr 4, 2022	SYSTEM	\$2,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			Material		2		SYSTEM		Estimate Item Adjustment (0057) due to user bowmam2 overridding Payment
		FÜRNISHING	Material	- Total		2022 Apr 4,		\$2,380.00	Estimate Item Adjustment (0057) due to user bowmam2 overridding Payment
		FÜRNISHING	Material Material - T			2022 Apr 4,		\$2,380.00 (\$2,380.00)	Estimate Item Adjustment (0057) due to user bowmam2 overridding Payment
	0170 -	FÙRNISHING AND INST				2022 Apr 4,		\$2,380.00 (\$2,380.00) \$0.00	Estimate Item Adjustment (0057) due to user bowmam2 overridding Payment
	0170 -	FÜRNISHING AND INST Total DOWEL BAR (FURNISH AND INSTALL WITH				2022 Apr 4,		\$2,380.00 (\$2,380.00) \$0.00	Estimate Item Adjustment (0057) due to user bowmam2 overridding Payment
		FÜRNISHING AND INST Total DOWEL BAR (FURNISH AND	Material - T		2	2022 Apr 4, 2022	SYSTEM	\$2,380.00 (\$2,380.00) \$0.00 \$0.00	Estimate Item Adjustment (0057) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user bowmam2 overridding Payment
		FÜRNISHING AND INST Total DOWEL BAR (FURNISH AND INSTALL WITH	Material - T		2	Apr 4, 2022 Apr 4, 2022 Apr 4, 2022	SYSTEM	\$2,380.00 (\$2,380.00) \$0.00 \$0.00 \$473.00	Estimate Item Adjustment (0057) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user bowmam2 overridding Payment
		FÜRNISHING AND INST Total DOWEL BAR (FURNISH AND INSTALL WITH	Material - T		2 2	Apr 4, 2022 Apr 4, 2022 Apr 4, 2022 Apr 18,	SYSTEM SYSTEM SYSTEM	\$2,380.00 (\$2,380.00) \$0.00 \$0.00 \$473.00	Estimate Item Adjustment (0057) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user bowmam2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment
		FÜRNISHING AND INST Total DOWEL BAR (FURNISH AND INSTALL WITH	Material - T		2 2 3	Apr 4, 2022 Apr 4, 2022 Apr 4, 2022 Apr 4, 2022 Apr 18, 2022 Apr 18, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$2,380.00 (\$2,380.00) \$0.00 \$0.00 \$473.00 (\$473.00)	Estimate Item Adjustment (0057) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user bowmam2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment
		FÜRNISHING AND INST Total DOWEL BAR (FURNISH AND INSTALL WITH	Material - T	otal - Total	2 2 3	Apr 4, 2022 Apr 4, 2022 Apr 4, 2022 Apr 4, 2022 Apr 18, 2022 Apr 18, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$2,380.00 (\$2,380.00) \$0.00 \$0.00 \$473.00 (\$473.00) \$473.00	Estimate Item Adjustment (0057) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user bowmam2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment
		FÜRNISHING AND INST Total DOWEL BAR (FURNISH AND INSTALL WITH BASK	Material - T	otal - Total	2 2 3	Apr 4, 2022 Apr 4, 2022 Apr 4, 2022 Apr 4, 2022 Apr 18, 2022 Apr 18, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$2,380.00 (\$2,380.00) \$0.00 \$0.00 \$473.00 (\$473.00) \$473.00 (\$473.00)	Estimate Item Adjustment (0057) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user bowmam2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment
	0180	FÜRNISHING AND INST Total DOWEL BAR (FURNISH AND INSTALL WITH BASK	Material - T	otal - Total	2 2 3	Apr 4, 2022 Apr 4, 2022 Apr 4, 2022 Apr 4, 2022 Apr 18, 2022 Apr 18, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$2,380.00 (\$2,380.00) \$0.00 \$0.00 \$473.00 (\$473.00) \$473.00 (\$473.00) \$0.00 \$0.00	Estimate Item Adjustment (0057) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user bowmam2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3293	0190	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	Material		3	Apr 18, 2022	SYSTEM	\$126.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
		(IIIEL			3	Apr 18, 2022	SYSTEM	(\$126.00)	
					4	May 2, 2022	SYSTEM	\$126.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bowmam2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$126.00)	
					5	May 16, 2022	SYSTEM	\$126.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$126.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0190 -	Total						\$0.00	
	0200	FURN & PLACE BIT. MATL FOR CL C PARTIAL	Other Item Adjustment	ACAD	2	Apr 4, 2022	BOWMAM2	\$1,560.32	1043.69 tons placed 3/16 - 4/1 BP1 19-19 5.2% virgin AC Base 502.5 Current 531.25 Diff 28.75 Total 1560.32
					3	Apr 18, 2022	BOWMAM2	\$8,791.67	3074.01 tons placed 4/01/2022 to 4/15/2022 5.2% virgin AC BP1 19-19 Base \$ 502.50 Current \$557.50 Diff \$ 55 Total \$ 8791.67
					4	May 2, 2022	BOWMAM2	\$1,140.23	Correct dollar adjustment for virgin AC from estimate 0002
					4	May 2, 2022	BOWMAM2	(\$1,560.32)	Corrects estimate 0002 virgin AC
					4	May 2, 2022	BOWMAM2	\$6,424.68	Corrects virgin AC on estimate 0003
					4	May 2, 2022	BOWMAM2	(\$8,791.67)	Incorrect virgin AC on estimate 0003
				ACAD - Tota	al			\$7,564.91	
			Other Item	Adjustment -	Total			\$7,564.91	
			Overrun	Overrun	3	Apr 18, 2022	SYSTEM	(\$5,806.80)	
					4	May 2, 2022	SYSTEM	(\$16.20)	
				Overrun - To	otal			(\$5,823.00)	
			Overrun - T	otal				(\$5,823.00)	
	0200 -							\$1,741.91	
	0210	REMOVAL FOR CLASS C PARTIAL	Overrun	Overrun	3	Apr 18, 2022	SYSTEM	(\$9,449.00)	
		DEPTH PAVT		Overrun - To	otal			(\$9,449.00)	
		REPAIR	Overrun - T	otal				(\$9,449.00)	
	0210 -	Total						(\$9,449.00)	
	0270	PREF THERMO PVMT MARK, 24 IN WHIT	Material		6	Jun 3, 2022	SYSTEM	\$1,292.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wagamt1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		24 111 111111			6	Jun 3, 2022	SYSTEM	(\$1,292.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0270 -	Total						\$0.00	
	0280	PREF THERMO PVMT MARK, LT/RT ARROW	Material		6	Jun 3, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wagamt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3293	0280	PREF THERMO	Material		6	Jun 3, 2022	SYSTEM	(\$600.00)	
		PVMT MARK, LT/RT ARROW		- Total				\$0.00	
			Material - T	otal				\$0.00	
	0280 -	- Total						\$0.00	
	0300	PREF THERMO PVMT	Material		6	Jun 3, 2022	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wagamt1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
		MARKING, COMBO			6	Jun 3, 2022	SYSTEM	(\$400.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0300 -	- Total						\$0.00	
	0310	4 IN. WHITE WATERBORNE PAVEMENT	Material		6	Jun 3, 2022	SYSTEM	\$8,961.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user wagamt1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
		MARKING			6	Jun 3, 2022	SYSTEM	(\$8,961.90)	
				- Total				\$0.00	
			Material - T					\$0.00	
	0310	- Total	atomar-1					\$0.00	
	0320	4 IN. YELLOW WATERBORNE PAVEMENT	Material		6	Jun 3, 2022	SYSTEM	\$8,877.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user wagamt1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
		MARKING			6	Jun 3, 2022	SYSTEM	(\$8,877.30)	Esumate Exception 15 on the current Payment Esumate.
				- Total		2022		\$0.00	
			Material - T					\$0.00	
	0220	- Total	Wateriai - 1	otai				\$0.00	
			Matarial		4	Marrio	OVOTEM		This adjustes are effects the adjusted analysis of Material December
	0360	MISC. GEOTEXTILE	Material		4	May 2, 2022	SYSTEM	\$2,592.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user bowmam2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$2,592.00)	
					5	May 16, 2022	SYSTEM	\$2,592.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment
									Estimate Exception 15 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$2,592.00)	Estimate Exception 15 on the current Payment Estimate.
					5		SYSTEM	(\$2,592.00) \$2,592.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wagamt1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
						2022 Jun 3,		\$2,592.00 (\$2,592.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wagamt1 overridding Payment
				- Total	6	Jun 3, 2022 Jun 3,	SYSTEM	\$2,592.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wagamt1 overridding Payment
			Material - T		6	Jun 3, 2022 Jun 3,	SYSTEM	\$2,592.00 (\$2,592.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wagamt1 overridding Payment
	0360 -	- Total	Material - T		6	Jun 3, 2022 Jun 3,	SYSTEM	\$2,592.00 (\$2,592.00) \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wagamt1 overridding Payment
	0360 - 0390	- Total 36 IN. GROUP A FLARED END SECT	Material - T		6	Jun 3, 2022 Jun 3,	SYSTEM	\$2,592.00 (\$2,592.00) \$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wagamt1 overridding Payment
		36 IN. GROUP A FLARED			6	Jun 3, 2022 Jun 3, 2022 Apr 4,	SYSTEM	\$2,592.00 (\$2,592.00) \$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wagamt1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user bowmam2 overridding Payment
		36 IN. GROUP A FLARED			6	2022 Jun 3, 2022 Jun 3, 2022 Apr 4, 2022	SYSTEM SYSTEM SYSTEM	\$2,592.00 (\$2,592.00) \$0.00 \$0.00 \$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wagamt1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user bowmam2 overridding Payment
		36 IN. GROUP A FLARED		otal - Total	6	2022 Jun 3, 2022 Jun 3, 2022 Apr 4, 2022	SYSTEM SYSTEM SYSTEM	\$2,592.00 (\$2,592.00) \$0.00 \$0.00 \$6,000.00 (\$6,000.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wagamt1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user bowmam2 overridding Payment
	0390	36 IN. GROUP A FLARED	Material	otal - Total	6	2022 Jun 3, 2022 Jun 3, 2022 Apr 4, 2022	SYSTEM SYSTEM SYSTEM	\$2,592.00 (\$2,592.00) \$0.00 \$0.00 \$6,000.00 (\$6,000.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wagamt1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user bowmam2 overridding Payment
J6S3293	0390	36 IN. GROUP A FLARED END SECT	Material	otal - Total	6	2022 Jun 3, 2022 Jun 3, 2022 Apr 4, 2022	SYSTEM SYSTEM SYSTEM	\$2,592.00 (\$2,592.00) \$0.00 \$0.00 \$6,000.00 (\$6,000.00) \$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wagamt1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user bowmam2 overridding Payment
J6S3293 J6S3628	0390	36 IN. GROUP A FLARED END SECT Total MISC. AGGREGATE	Material	otal - Total	6	2022 Jun 3, 2022 Jun 3, 2022 Apr 4, 2022	SYSTEM SYSTEM SYSTEM	\$2,592.00 (\$2,592.00) \$0.00 \$0.00 \$6,000.00 (\$6,000.00) \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wagamt1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user bowmam2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user bowmam2 overridding Payment Estimate Item Adjustment (0017) due to user bowmam2 overridding Payment
	0390 0390 -	36 IN. GROUP A FLARED END SECT	Material Material - T	otal - Total	6 6 2 2	2022 Jun 3, 2022 Jun 3, 2022 Apr 4, 2022 May 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$2,592.00 (\$2,592.00) \$0.00 \$0.00 \$6,000.00 (\$6,000.00) \$0.00 \$0.00 \$38,045.31	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wagamt1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user bowmam2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3628	0550	MISC. AGGREGATE FOR BASE	Material		5	May 16, 2022	SYSTEM	\$8,708.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$8,708.00)	
					6	Jun 3, 2022	SYSTEM	\$8,708.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user wagamt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 3, 2022	SYSTEM	(\$8,708.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0550 -	Total						\$0.00	
	0570	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BAS	Other Item Adjustment	ACAD	4	May 2, 2022	BOWMAM2	\$367.71	148.57 tons placed 04/02 to 04/15 4.5% virgin BP1 22-10 Base 502.50 Current 557.50 Diff 55.00 Total 367.71
				ACAD - Total				\$367.71	
			Other Item /	Adjustment -	Total			\$367.71	
			Overrun	Overrun	4	May 2, 2022	SYSTEM	(\$1,988.40)	
				Overrun - To	otal			(\$1,988.40)	
			Overrun - T	otal				(\$1,988.40)	
	0570 -	Total						(\$1,620.69)	
	0580	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Material		6	Jun 3, 2022	SYSTEM	\$333,827.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wagamt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Jun 3, 2022	SYSTEM	(\$333,827.30)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	ACAD	6	Jun 3, 2022	wagamt1	\$20,147.46	3927.38 Tons placed 5/16-6/1 SL20-27A Virgin AC 3.8% Base 502.5 Current 637.5 DIFF 135 Total 20147.46
				ACAD - Total				\$20,147.46	
			Other Item /	Adjustment -	Total			\$20,147.46	
			Overrun	Overrun	6	Jun 3, 2022	SYSTEM	\$15,672.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 3927.380; Overrun Quantity Balance 184.38.
					6	Jun 3, 2022	SYSTEM	(\$15,672.30)	
					6	Jun 3, 2022	wagamt1	(\$15,672.30)	
				Overrun - Total				(\$15,672.30)	
			Overrun - Total					(\$15,672.30)	
	0580 -	0580 - Total							
	0590	TACK COAT	Material		2	Apr 4, 2022	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Apr 4, 2022	SYSTEM	(\$1,650.00)	
					3	Apr 18, 2022	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$1,650.00)	
				- Total				\$0.00	



Project	Line	Description	Adjustment	Other	Est.	Created	Created By	Amount	Remarks
			Туре	Adjustment Type	Number	Date			
J6S3628	0590	TACK COAT	Material - To	otal				\$0.00	
	0590 -	- Total						\$0.00	
	0600	MISC. ULTRATHIN	Overrun	Overrun	6	Jun 3, 2022	SYSTEM	(\$784.00)	
		BONDED WEARING		Overrun - To	otal			(\$784.00)	
		SURFACE	Overrun - Total					(\$784.00)	
	0600 -	· Total						(\$784.00)	
	0610	FURN. TYPE 2 ROCK DITCH LINER	Material		3	Apr 18, 2022	SYSTEM	\$24,426.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$24,426.00)	
					4	May 2, 2022	SYSTEM	\$24,426.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$24,426.00)	
					5	May 16, 2022	SYSTEM	\$24,426.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$24,426.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0610 -	· Total						\$0.00	
	0640	FURN & PLACE BIT. MATL FOR CL C PARTIAL	Other Item Adjustment	ACAD	2	Apr 4, 2022	BOWMAM2	\$2,981.31	1994.19 tons placed 3/16 - 4/1 BP1 19-19 5.2% virgin AC Base 502.5 Current 531.25 Diff 28.75 Total 2981.31
					4	May 2, 2022	BOWMAM2	\$2,178.65	Correct dollar adjustment for virgin AC from estimate 2
					4	May 2, 2022	BOWMAM2	(\$2,981.31)	Corrects estimate 0002 virgin AC
				ACAD - Total				\$2,178.65	
			Other Item A	Adjustment -	Total			\$2,178.65	
			Overrun	Overrun	2	Apr 4, 2022	SYSTEM	(\$33,011.10)	
				Overrun - Total				(\$33,011.10)	
			Overrun - To	otal				(\$33,011.10)	
	0640 -	· Total						(\$30,832.45)	
	0650	REMOVAL FOR CLASS C	Overrun	Overrun	2	Apr 4,	SYSTEM	(\$6,322.00)	
		PARTIAL DEPTH PAVT REPAIR		Overrup - To	otal			(\$6,322.00)	
			Overrup -T	Overrun - Total					
	0050	Total	Overrun - Total					(\$6,322.00)	
	0650 - 0730	MISC. GEOTEXTILE	Material		3	Apr 18, 2022	SYSTEM	(\$6,322.00) \$3,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user bowmam2 overridding Payment
					3	Apr 18, 2022	SYSTEM	(\$3,680.00)	Estimate Exception 17 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	\$3,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bowmam2 overridding Payment
					4	May 2,	SYSTEM	(\$3,680.00)	Estimate Exception 16 on the current Payment Estimate.
					5	2022 May 16,	SYSTEM	\$3,680.00	This adjustment offsets the original system-generated Material Payment
						2022			Estimate Item Adjustment (0014) due to user bowmam2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$3,680.00)	

Jun 7, 2022



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3628	0730	0 MISC. GEOTEXTILE	Material		6	Jun 3, 2022	SYSTEM	\$3,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user wagamt1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					6	Jun 3, 2022	SYSTEM	(\$3,680.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0730 -	Total					\$0.00		
J6S3628 -	Total						(\$35,083.98)		
Overall -	Total						\$2,961.33		