

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 3, 2022

Progress Estimate Number	Contract ID	220121-F10	Pay Period Start	September 16, 2022	Original Contract Amount	\$6,570,000.00
8	Prime Contractor	Pace Construction Company, LLC	Pay Period End	September 30, 2022	Net Change Order Amount Current Contract Amount	\$0.00 \$6,570,000.00

Approval Date		By User
October 3, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	arnold1
October 3, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	janssm
October 4, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 3, 2023	November 3, 2023		19.77%

Contract Informational Dates Milestones

Date Description	Original Completion Date	Current Completion Date
Acceptance Date		
Awarded Date	February 2, 2022	February 2, 2022
Letting Date	January 21, 2022	January 21, 2022
Notice to Proceed Date	April 4, 2022	April 4, 2022
Open to Traffic Date		
Work Began Date		

Date Description	Original	Current	Days	Diary
	Completion	Completion	Remaining on	Charge
	Date	Date	Milestone	Days
JSP G Liquidated Damages Specified (For Reconstruction of the Midland Blvd. Bridge Deck)	October 7, 2022	October 7, 2022	3	

Contract Total Pa	y For Estimate No. 8			
		This Estimate	Previous	To Date
220121-F10				
	Total Posted Items Pay	\$259,794.00	\$1,039,211.30	\$1,299,005.30
	Gross Item Adjustments	\$0.00	(\$3,198.00)	(\$3,198.00)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	,		\$1,036,013.30	\$1,295,807.30

Contract Total Payable This Estimate: \$259,794.00

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount					
J6S3404	0750	7034212	SLAB ON STEEL	SQYD	\$510.000	509.4	\$259,794.00					
Project J6S3404 - T	Project J6S3404 - Total											
Overall - Total	Overall - Total											

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3404	0750	SLAB ON STEEL	Material			-1,439.6	\$510.00	(\$734,196.00)
	0750	SLAB ON STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user arnold1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,439.6	\$510.00	\$734,196.00
	0780	SUBSTRUCTURE REPAIR	Material			-120	\$168.00	(\$20,160.00)

Revision 4/1/2020 Page 1 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 3, 2022

Progress Estimate Number	Contract ID	220121-F10	Pay Period Start	September 16, 2022	Original Contract Amount \$	6,570,000.00
8	Prime Contractor	Pace Construction Company, LLC	Pay Period End	September 30, 2022	Net Change Order \$ Amount Current Contract Amount \$	0.00 6,570,000.00

						diront cont	uot / tillouit	ψ0,070,000.00
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3404		(FORMED)						
	0780	SUBSTRUCTURE REPAIR (FORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user arnold1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	120	\$168.00	\$20,160.00
	0790	SUBSTRUCTURE REPAIR (UNFORMED)	Material			-39	\$152.00	(\$5,928.00)
	0790	SUBSTRUCTURE REPAIR (UNFORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user arnold1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	39	\$152.00	\$5,928.00
Total								\$0.00

Revision 4/1/2020 Page 2 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Informatio	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6S3404	FAS S502(033)	2 Bridge replacements	Lackland, Midland	ST LOUIS	on Lackland Road & N	/Ildland Blvd over I-170	
Totals by J	Job Number	rs					
J6S3404		l Item Pay Item Adjustmer	nts Gross Item	ı Pay	This Estimate \$259,794.00 \$0.00 \$259,794.00	Previous \$1,039,211.30 (\$3,198.00) \$1,036,013.30	To Date \$1,299,005.30 (\$3,198.00) \$1,295,807.30
			ments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 3 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3404, Item 7034212, Project Item Line Number 0750, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Working with contractor QC and MODOT Materials to input test data for materials reports.	arnold1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3404, Item 7034212, Project Item Line Number 0750, Material Set 703421296, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	Working with contractor QC and MODOT Materials to input test data for materials reports.	arnold1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3404, Item 7034212, Project Item Line Number 0750, Material Set 703421296, Material 0705DPRCPS30 - Prestress Conc Deck Panel 3" (75 mm), Acceptance Action Generic 0705DPRCPS30 is insufficient.	Working with MoDOT Materials to remove this exception. No Prestressed Panes will be used on this line item.	arnold1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3404, Item 7034212, Project Item Line Number 0750, Material Set 703421296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Modified B-2 Concrete has been used on this line at this time. Payment includes forming, reinforcing steel and B-2 Concrete.	arnold1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3404, Item 7034212, Project Item Line Number 0750, Material Set 703421296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Concrete Sealer has been used on the project at this time. This material will be needed after the bridge deck has been poured.	arnold1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3404, Item 7040101, Project Item Line Number 0780, Material Set 704010196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Working with MODOT Materials to remove this requirement from this line. All substructure repair on this project will e performed with shotcrete.	arnold1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3404, Item 7040102, Project Item Line Number 0790, Material Set 704010296, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	The contractor is using an approved shotcrete material for this line. Awaiting input of materials report certification for this item.	arnold1	Overridden
Estimate Exception Type: Item Overrun: Contract 220121-F10, Contract Project J6S3404, Project Item Line Number 0260, Contract Line Item Number 0260, Item 6169902, Minor Item.	No Remark was entered by Engineer	arnold1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220121-F10, Contract Project J6S3404, Project Item Line Number 0370, Contract Line Item Number 0370, Item 6207001, Minor Item.	No Remark was entered by Engineer	arnold1	Acknowledged

Revision 4/1/2020 Page 4 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Contract lm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
20121-F10	J6S3404	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.05	\$60,000.00	\$3,000
		0001	0020	2063000	CLASS 3 EXCAVATION	71.00	0.00	71.00	CUYD	0.00	\$21.00	\$0.
		0001	0030	2072000	LINEAR GRADING CLASS 2	1.50	0.00	1.50	STA	0.00	\$5,650.00	\$0.
		0001	0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,661.00	0.00	1,661.00	SQYD	0.00	\$13.50	\$0.
		0001	0050	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	50.00	0.00	50.00	TONS	0.00	\$281.00	\$0
		0001	0060	4071005	TACK COAT	23.00	0.00	23.00	GAL	0.00	\$25.00	\$0
		0001	0070	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)	87.70	0.00	87.70	SQYD	0.00	\$91.70	\$0
		0001	0800	5021333	CONCRETE PAVEMENT (9 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	1,519.80	0.00	1,519.80	SQYD	0.00	\$75.80	\$0
		0001	0090	6071012A	CHAIN-LINK FENCE (60 IN.)	559.00	0.00	559.00	LF	0.00	\$48.99	\$0
		0001	0100	6081012	TRUNCATED DOMES	110.00	0.00	110.00	SQFT	0.00	\$31.00	\$0
		0001	0110	6083006	6 IN. CONCRETE MEDIAN STRIP	1.90	0.00	1.90	SQYD	0.00	\$192.10	\$0
		0001	0120	6085007	PAVED APPROACH, 7 IN.	30.20	0.00	30.20	SQYD	0.00	\$93.35	\$0
		0001	0130	6089902	MISC.CONCRETE CURB RAMP	6.00	0.00	6.00	EA	0.00	\$2,788.00	\$0
		0001	0140	6089905	MISC.CONCRETE SIDEWALK, 6 IN.	106.20	0.00	106.20	SQYD	0.00	\$94.00	\$0.0
		0001	0150	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	23.00	0.00	23.00	LF	0.00	\$40.00	\$0
		0001	0160	6091041	CONCRETE GUTTER TYPE A	168.00	0.00	168.00	LF	0.00	\$75.00	\$
		0001	0170	6091042	CONCRETE GUTTER TYPE B	20.00	0.00	20.00	LF	0.00	\$110.00	\$
		0001	0180	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	297.00	0.00	297.00	LF	0.00	\$29.25	\$
				6097000	ROCK LINING	12.00	0.00	12.00	CUYD	0.00	\$75.00	\$
		0001	0200	6113020	FURNISHING TYPE 2 ROCK BLANKET	300.00	0.00	300.00	CUYD	0.00	\$45.00	\$
		0001	0210	6113040	PLACING TYPE 2 ROCK BLANKET	300.00	0.00	300.00	CUYD	0.00	\$19.00	\$
		0001 0220 6119905 MISC.RUBBLIZE			MISC.RUBBLIZE CONCRETE SLOPE PROTECTION	500.00	0.00	500.00	SQYD	0.00	\$18.00	\$
		0001	0230	6141121	CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	3.00	0.00	3.00	EA	0.00	\$2,000.00	\$
		0001	0240	6143013	MANHOLE FRAME AND COVER, TYPE 3	1.00	0.00	1.00	EA	0.00	\$375.00	\$
		0001	0250	6169901	MISC.TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$400,000.00	\$200,00
		0001	0260	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED/RETAINED)	10.00	0.00	10.00	EA	11.00	\$2,800.00	\$30,80
		0001	0270	6173100	CONCRETE TRAFFIC BARRIER, TYPE D	238.00	0.00	238.00	LF	0.00	\$125.00	\$
		0001	0280	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	663.00	0.00	663.00	LF	473.00	\$25.26	\$11,94
		0001	0290	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$158,092.62	\$79,04
		0001	0300	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	1.00	0.00	1.00	EA	0.00	\$600.00	\$
		0001 03		6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	92.00	0.00	92.00	LF	0.00	\$6.50	\$0.
		0001 0320 6200015			PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	40.00	0.00	40.00	LF	0.00	\$25.00	\$
		0001	0330	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	42.00	0.00	42.00	LF	0.00	\$25.00	\$
		0001	0340	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	3.00	0.00	3.00	EA	0.00	\$350.00	\$
		0001	0350	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,245.00	0.00	2,245.00	LF	240.00	\$0.75	\$18
		0001	0360	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,172.00	0.00	2,172.00	LF	308.00	\$0.75	\$23
		0001	0370	6207001	PAVEMENT MARKING REMOVAL	120.00	0.00	120.00	LF	319.00	\$2.00	\$63
		0001	0380	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	454.00	0.00	454.00	SQYD	0.00	\$25.00	\$
		0001	0390	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.05	\$7,100.00	\$35
		0001	0400	7250312A	12 IN. PIPE GROUP B	14.00	0.00	14.00	LF	0.00	\$70.00	\$
		0001	0410	7250415	15 IN. PIPE GROUP C	40.00	0.00	40.00	LF	0.00	\$75.00	\$
		0001	0420	7310048	PRECAST CONCRETE MANHOLE - 48 IN.	10.00	0.00	10.00	FT	0.00	\$250.00	\$
		0001	0430	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	8.00	0.00	8.00	FT	0.00	\$400.00	\$

Revision 4/1/2020 Page 5 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

oto. i ootou Q	uanililes	and valu	es are c	ased on R	eport Generated date and can differ from the posted amo	ount at the	ume me	Estimate w	as Gene	rateu.		Tatal Value BOOTED
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-F10	J6S3404	0001	0440	7320815A	15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$700.00	\$0.00
		0001	0450	8051000A	SEEDING - COOL SEASON GRASSES	0.60	0.00	0.60	ACRE	0.00	\$4,840.00	\$0.00
		0001	0460	8061005	ROCK DITCH CHECK	94.00	0.00	94.00	LF	0.00	\$28.00	\$0.00
		0001	0470	8061007A	CURB INLET CHECK	4.00	0.00	4.00	EA	0.00	\$155.00	\$0.00
		0001	0480	8061016	SEDIMENT REMOVAL	36.00	0.00	36.00	CUYD	0.00	\$4.60	\$0.00
		0001	0490	8061017	TEMPORARY SEEDING	0.60	0.00	0.60	ACRE	0.00	\$2,500.00	\$0.00
		0001	0500	8061019	SILT FENCE	1,254.00	0.00	1,254.00	LF	0.00	\$3.05	\$0.00
		0001	0510	8064131	TYPE 1A EROSION CONTROL BLANKET	1,976.00	0.00	1,976.00	SQYD	0.00	\$2.95	\$0.00
		0001	0520	8064133	TYPE 1C EROSION CONTROL BLANKET	77.00	0.00	77.00	SQYD	0.00	\$2.95	\$0.00
		0001	0530	8064134	TYPE 1D EROSION CONTROL BLANKET	823.00	0.00	823.00	SQYD	0.00	\$2.95	\$0.00
		0010	0540	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	300.00	0.00	300.00	LF	0.00	\$42.73	\$0.00
		0010	0550	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	1.00	0.00	1.00	EA	0.00	\$4,643.06	\$0.00
		0010	0560	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	0.00	\$2,536.55	\$0.00
		0010	0570	6063020	TYPE C CRASHWORTHY END TERMINAL (MASH)	1.00	0.00	1.00	EA	0.00	\$29,325.38	\$0.00
		0030	0580	9029902	MISC.Base, Type E-3, Concrete	2.00	0.00	2.00	EA	0.00	\$4,620.00	\$0.00
		0030 0580 9029			MISC.Fiber Optic Cable Termination Housing, in Aluminum Cabinet, Approx. 36" H x 24" W x 22" D, Ground Mounted	2.00	0.00	2.00	EA	0.00	\$5,255.00	\$0.00
		0030	0600	9029902	MISC.Preformed Pull Box (17" W x 30" L x 26" min. H), Reinforced Polymer Concrete w/1' Concrete Apron	3.00	0.00	3.00	EA	0.00	\$1,450.00	\$0.00
		0030	0610	9029903	MISC.2" CONDUIT	319.00	0.00	319.00	LF	0.00	\$18.00	\$0.00
		0030	0620	9029903	MISC.Cable, Communication, Fiber Optic, 36 Fibers (30 Single-Mode and 6 Multi-Mode)	538.00	0.00	538.00	LF	0.00	\$3.50	\$0.00
		0030	0630	9109901	MISC.Fiber Management Tool	1.00	0.00	1.00	LS	0.00	\$1,200.00	\$0.00
		0040	0640	9031270A	2 IN. PSST POST - 12 GA.	18.00	0.00	18.00	LF	0.00	\$38.92	\$0.00
		0040	0650	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	6.00	0.00	6.00	LF	0.00	\$163.96	\$0.00
		0040	0660	9031280	5 IN. PSST POST - 12 GA.	72.00	0.00	00 72.00	LF	0.00	\$23.05	\$0.00
		0040	0670	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	18.00	0.00	18.00	LF	0.00	\$88.24	\$0.00
		0040	0680	9035004A	SH-FLAT SHEET	33.00	0.00	33.00	SQFT	0.00	\$18.78	\$0.00
		0040	0690	9035069A	SHF-FLAT SHEET FLUORESCENT	21.00	0.00	21.00	SQFT	0.00	\$23.93	\$0.00
		0040	0700	9039902	MISC.RELOCATION OF EXISTING SIGNS	6.00	0.00	6.00	EA	0.00	\$2,960.70	\$0.00
		0070	0710	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	23.00	0.00	23.00	SQFT	23.00	\$525.00	\$12,075.00
		0070	0720	2162500	REMOVAL OF EXISTING BRIDGE DECK	25,056.00	0.00	25,056.00	SQFT	25,056.00	\$8.00	\$200,448.00
		0070	0730	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	422.00	0.00	422.00	SQYD	0.00	\$225.00	\$0.00
		0070	0740	6079903	MISC.(60 IN.) DECORATIVE PEDESTRIAN FENCE (STRUCTURES)	544.00	0.00	544.00	LF	0.00	\$175.00	\$0.00
		0070	0750	7034212	SLAB ON STEEL	2,638.00	0.00	2,638.00	SQYD	1,439.60	\$510.00	\$734,196.00
		0070	0760	7034430	SIDEWALK (BRIDGES)	3,406.00	0.00	3,406.00	SQFT	0.00	\$15.00	\$0.00
		0070	0770	7039903	MISC.MODIFIED BARRIER CURB	608.00	0.00	608.00	LF	0.00	\$230.00	\$0.00
		0070	0780	7040101	SUBSTRUCTURE REPAIR (FORMED)	200.00	0.00	200.00	SQFT	120.00	\$168.00	\$20,160.0
		0070	0790	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	850.00	0.00	850.00	SQFT	39.00	\$152.00	\$5,928.0
		0070	0800	7040110	EPOXY PRESSURE INJECTING	100.00	0.00	100.00	LF	0.00	\$70.00	\$0.00
		0070	0810	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	0.00	\$11,410.00	\$0.0
		0070	0820	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$6,000.00	\$0.00
		0070	0830	7123610	SLAB DRAIN	14.00	0.00	14.00	EA	0.00	\$800.00	\$0.00
		0070	0840	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	32,800.00	0.00	32,800.00	SQFT	0.00	\$20.00	\$0.00
		0070	0850	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	32,800.00	0.00	32,800.00	SQFT	0.00	\$2.00	\$0.00
		0070	0860	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	32,800.00	0.00	32,800.00	SQFT	0.00	\$2.00	\$0.00
		0070	0870	71253704	FINISH FIELD COAT (SYSTEM G)	3,600.00	0.00	3,600.00	SQFT	0.00	\$2.00	\$0.00

Revision 4/1/2020 Page 6 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-F10	J6S3404	0070	0880	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$2,000.00	\$0.00
		0071	0890	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	32.00	0.00	32.00	SQFT	0.00	\$515.00	\$0.00
		0071	0900	2162500	REMOVAL OF EXISTING BRIDGE DECK	20,712.00	0.00	20,712.00	SQFT	0.00	\$7.00	\$0.00
		0071	0910	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	221.00	0.00	221.00	SQYD	0.00	\$200.00	\$0.00
		0071	0920	6079903	MISC.(60 IN.) DECORATIVE PEDESTRIAN FENCE (STRUCTURES)	752.00	0.00	752.00	LF	0.00	\$155.00	\$0.00
		0071	0930	7034212	SLAB ON STEEL	1,959.00	0.00	1,959.00	SQYD	0.00	\$400.00	\$0.00
		0071	0940	7034430	SIDEWALK (BRIDGES)	4,741.00	0.00	4,741.00	SQFT	0.00	\$14.00	\$0.00
		0071	0950	7039903	MISC.MODIFIED BARRIER CURB	790.00	0.00	790.00	LF	0.00	\$190.00	\$0.00
		0071	0960	7040101	SUBSTRUCTURE REPAIR (FORMED)	270.00	0.00	270.00	SQFT	0.00	\$168.00	\$0.00
		0071	0970	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	125.00	0.00	125.00	SQFT	0.00	\$152.00	\$0.00
		0071	0980	7040110	EPOXY PRESSURE INJECTING	75.00	0.00	75.00	LF	0.00	\$70.00	\$0.00
		0071	0990	7040164	FIBER REINFORCED POLYMER WRAP	610.00	0.00	610.00	SF	0.00	\$55.00	\$0.00
		0071	1000	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$7,500.00	\$0.00
		0071	1010	7121121	FABRICATED STRUCTURAL LOW ALLOY STEEL (PLATE GIRDER) A709, GRADE 50	56,310.00	0.00	56,310.00	LB	0.00	\$5.00	\$0.00
		0071	1020	7123610	SLAB DRAIN	10.00	0.00	10.00	EA	0.00	\$700.00	\$0.00
		0071	1030	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	24,400.00	0.00	24,400.00	SQFT	0.00	\$20.00	\$0.00
		0071	1040	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	24,400.00	0.00	24,400.00	SQFT	0.00	\$2.00	\$0.00
		0071	1050	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	27,300.00	0.00	27,300.00	SQFT	0.00	\$2.00	\$0.00
		0071	1060	7125370A	FINISH FIELD COAT (SYSTEM G)	5,000.00	0.00	5,000.00	SQFT	0.00	\$2.00	\$0.00
		0071	1065	7129901	MISC.RECONFIGURE EXISTING STRUCTURAL STEEL	1.00	0.00	1.00	LS	0.00	\$125,000.00	\$0.00
		0071	1080	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$2,000.00	\$0.00
		0071	1090	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	6.00	0.00	6.00	EA	0.00	\$6,000.00	\$0.00
	Project J	6S3404 - To	otal Value	e Posted to D	late as of Report Generated Date							\$1,299,005.29
20121-F10 Ove	erall - Total	Value Post	ed to Da	te as of Repo	ort Generated Date							\$1,299,005.29

Page 7 of 10 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

$\underline{\textbf{The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.}$

Project: J6S3404

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	Offset/ Distance	Comments
0750	7034212	SLAB ON STEEL	9/29/22	10/3/22	509.40	SQYD	Br A-31732	0			98% Forming Complete 90% Resteel Complete Shear Blocks and Side Walls Poured

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 8 of 10



Line Item Adjustments by Estimate

Contract ID:190215-D05

Jessado 10 Jun 1 Jun 16 SYSTEM (\$2,800.00)		Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks	
CONTROL CONTROL COVERTUR - Total (\$2,800.00)	1000404	0000	MICO TRAFFIC		Туре			·	(\$0.000.00)		
	J6S3404	0260	CONTROL	Overrun				SYSTEM	(\$2,800.00)		
					Overrun - T	otal			(\$2,800.00)		
A IN. WHITE WATERBORNE PAVEMENT MARKING				Overrun - T	otal				(\$2,800.00)		
AARKING		0260 -	· Total						(\$2,800.00)		
1		0350	WATERBORNE PAVEMENT	Material		1		SYSTEM	\$180.00	Estimate Item Adjustment (0003) due to user arnold1 overridding Payment	
2022 SYSTEM Estimate Item Adjustment (0001) due to user armold1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			MARKING			1		SYSTEM	(\$180.00)		
2022 3						2		SYSTEM	\$180.00	Estimate Item Adjustment (0001) due to user arnold1 overridding Payment	
2022 Estimate Item Adjustment (0001) due to user arnold1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						2		SYSTEM	(\$180.00)		
- Total - Su.00 - Total - Su.00 - Total - Su.00 - Total - Su.00 - This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user arnold1 overridding Payment Estimate Exception 4 on the current Payment Estimate. - System - Syst						3		SYSTEM	\$180.00	Estimate Item Adjustment (0001) due to user arnold1 overridding Payment	
D350 - Total S0.00						3		SYSTEM	(\$180.00)		
D350 - Total S0.00					- Total				\$0.00		
0360 4 IN. YELLOW WATERBORNE PAVEMENT MARKING 1 Jun 16, 2022 2 Jul 1, 2022 2 Jul 1, 2022 3 Jul 18, 2022 3 Jul 18, 2022 3 Jul 18, 2022 3 Jul 18, 2022 3 SYSTEM 5 231.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 1 Jun 16, 2022 2 Jul 1, 2022 3 Jul 18, 2022 3 Jul 18, 2022 3 SYSTEM 5 231.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. 2 Jul 1, 2022 3 Jul 18, 2022 3 Jul 18, 2022 3 SYSTEM 5 231.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. 5 2 Jul 18, 2022 5 3 Jul 18, 2022 5 3 SYSTEM 5 231.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user arnold1 overridding Payment Estimate Item Adjustment (0002) due to user arnold1 overridding Payment Estimate Item Adjustment (0002) due to user arnold1 overridding Payment Estimate Item Adjustment (0002) due to user arnold1 overridding Payment Estimate Item Adjustment (0002) due to user arnold1 overridding Payment				Material - To							
WATERBORNE PAVEMENT MARKING 2022 Estimate Item Adjustment (0004) due to user arnold1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 1 Jun 16, 2022 2 Jul 1, 2022 SYSTEM (\$231.00) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user arnold1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 2 Jul 1, 2022 SYSTEM (\$231.00) 1 Jul 18, 2022 3 Jul 18, 2022 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user arnold1 overridding Payment Estimate Item Adjustment (0002) due to user arnold1 overridding Payment		0350 -	· Total						\$0.00		
1 Jun 16, 2022 SYSTEM (\$231.00) 2 Jul 1, 2022 SYSTEM \$231.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user arnold1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 2 Jul 1, 2022 SYSTEM (\$231.00) 3 Jul 18, 2022 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user arnold1 overridding Payment Estimate Item Adjustment (0002) due to user arnold1 overridding Payment		0360	0 4 IN. YELLOW WATERBORNE PAVEMENT	Material		1		SYSTEM	\$231.00	Estimate Item Adjustment (0004) due to user arnold1 overridding Payment	
2 Jul 1, 2022 SYSTEM (\$231.00) 3 Jul 18, 2022 Estimate Item Adjustment (0002) due to user amold1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user amold1 overridding Payment Estimate Item Adjustment (0002) due to user amold1 overridding Payment							1		SYSTEM	(\$231.00)	
2022 3 Jul 18, SYSTEM \$231.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user arnold1 overridding Payment							2		SYSTEM	\$231.00	Estimate Item Adjustment (0002) due to user arnold1 overridding Payment
2022 Estimate Item Adjustment (0002) due to user arnold1 overridding Payment						2		SYSTEM	(\$231.00)		
Estimate Exception 3 on the current Payment Estimate.						3		SYSTEM	\$231.00	Estimate Item Adjustment (0002) due to user arnold1 overridding Payment	
3 Jul 18, 2022 (\$231.00)						3		SYSTEM	(\$231.00)		
- Total \$0.00					- Total				\$0.00		
Material - Total \$0.00				Material - To	otal				\$0.00		
0360 - Total \$0.00		0360 -	· Total						\$0.00		
0370 PAVEMENT Overrun Overrun 1 Jun 16, SYSTEM (\$398.00) MARKING 2022		0370		Overrun	Overrun	1		SYSTEM	(\$398.00)		
REMOVAL Overrun - Total (\$398.00)					Overrun - T	otal			(\$398.00)		
Overrun - Total (\$398.00)				Overrun - T							
0370 - Total (\$398.00)		0370 -	· Total						<u> </u>		
0750 SLAB ON STEEL Material 3 Jul 18, 2022 \$27,030.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user amold1 overridding Payment Estimate Exception 5 on the current Payment Estimate.				Material		3		SYSTEM		Estimate Item Adjustment (0003) due to user arnold1 overridding Payment	
3 Jul 18, 2022 (\$27,030.00)						3		SYSTEM	(\$27,030.00)		
4 Aug 2, 2022 \$YSTEM \$102,765.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user amold1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						4	Aug 2,	SYSTEM	\$102,765.00	Estimate Item Adjustment (0001) due to user arnold1 overridding Payment	
4 Aug 2, SYSTEM (\$102,765.00)						4		SYSTEM	(\$102,765.00)		
5 Aug 16, 2022 \$ SYSTEM \$285,090.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user arnold1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						5		SYSTEM	\$285,090.00	Estimate Item Adjustment (0001) due to user arnold1 overridding Payment	
5 Aug 16, SYSTEM (\$285,090.00)						5		SYSTEM	(\$285,090.00)		
6 Sep 1, 2022 SYSTEM \$447,321.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user arnold1 overridding Payment											





Line Item Adjustments by Estimate

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J6S3404	0750	SLAB ON STEEL	Material						Estimate Exception 1 on the current Payment Estimate.			
					6	Sep 1, 2022	SYSTEM	(\$447,321.00)				
					7	Sep 16, 2022	SYSTEM	\$474,402.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user arnold1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
				7	Sep 16, 2022	SYSTEM	(\$474,402.00)					
					8	Oct 3, 2022	SYSTEM	\$734,196.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user arnold1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					8	Oct 3, 2022	SYSTEM	(\$734,196.00)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0750 -	· Total						\$0.00				
	0780	SUBSTRUCTURE REPAIR (FORMED)	Material	Material	Material	Material		7	Sep 16, 2022	SYSTEM	\$20,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user arnold1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
						7	Sep 16, 2022	SYSTEM	(\$20,160.00)			
					8	Oct 3, 2022	SYSTEM	\$20,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user arnold1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					8	Oct 3, 2022	SYSTEM	(\$20,160.00)				
				- Total				\$0.00				
			Material - To	Total				\$0.00				
	0780 -	· Total						\$0.00				
	0790	SUBSTRUCTURE REPAIR (UNFORMED)	Material		7	Sep 16, 2022	SYSTEM	\$5,928.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user arnold1 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					7	Sep 16, 2022	SYSTEM	(\$5,928.00)				
					8	Oct 3, 2022	SYSTEM	\$5,928.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user arnold1 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					8	Oct 3, 2022	SYSTEM	(\$5,928.00)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0790 -	Total						\$0.00				
J6S3404 -	Total							(\$3,198.00)				
Overall -	Total							(\$3,198.00)				