

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 17, 2022

April 11, 2022

Progress Estimate N 10	umber	Contract ID Prime Contractor	220121-H01 Robertson Contra	ctors, Inc.			Original Contract Amount Net Change Order Amount Current Contract Amount	t \$89,055.83		
Approval Date								By User		
August 17, 2022			Generated and A	Approved (and should be considered	d Draft) at	the Project Office Level by	woodsk1		
August 17, 2022		R	eviewed and Appro	nd Approved (and should be considered Draft) at the Resident Engineer Level by						
August 18, 2022			1	Reviewed	and Approved at the Cent	tral Office	Controllers Office Level by	ramses1		
Original Completion	n Date	Current Cor	npletion Date	Actu	al Completion Date	of Current Contract Amoun	ount Complete			
May 1, 2023							42.56%			
	Contrac	t Informational Da	tes		Milestones					
Date Description	Origina	I Completion Date	Current Comple	tion Date	No Milestones Exist for	Contract				
Acceptance Date										
Awarded Date	Februar	y 2, 2022	February 2, 2022							
Letting Date	7 7 7		January 21, 2022							
Notice to Proceed Date	April 4, 2	2022	April 4, 2022							
Open to Traffic Date										

Contract Total Pay For Estimate N	o. 10			
000404 1104		This Estimate	Previous	To Date
220121-H01 Total Posted Gross Item A Incentive Disincentive Liquidated D Other Contra	Adjustments Damage	\$714,670.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$870,467.42 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$870,467,42	\$1,585,137.42 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$1,585,137.42
Contract Total Payable This Estima	ate:	\$714,670.00	ψ010,401.42	Ψ1,300,107.42

April 11, 2022

Items Paid This Estimate Period

Work Began Date

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9I3643	0140	6122020	REPLACEMENT SAND BARREL	EA	\$250.000	4	\$1,000.00
	0210	6161033	DIRECTIONAL INDICATOR BARRICADE	EA	\$65.000	38	\$2,470.00
	0240	6161070	TUBULAR MARKER	EA	\$35.000	25	\$875.00
	0500	7034212	SLAB ON STEEL	SQYD	\$525.000	1,353	\$710,325.00
Project J9I3643	· Total						\$714,670.00
Overall - Total							

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjus	tments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3643	0500	SLAB ON STEEL	Material			-1,353	\$525.00	(\$710,325.00)
	0500	SLAB ON STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	1,353	\$525.00	\$710,325.00
	0540	SLAB DRAIN	Material			-20	\$450.00	(\$9,000.00)
	0540	SLAB DRAIN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	20	\$450.00	\$9,000.00

Revision 4/1/2020 Page 1 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 17, 2022

Progress Estimate Number 10 Contract ID 220121-H01 Prime Contractor Robertson Contract						Pay Period Start Pay Period End	August 15, 2022		er Amount	\$89,055.83
Project Number	Line No.	Item Desci	ription	Adjustment Type	Other Item Adjustment Type	Comme	nts	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
Total										\$0.00

Revision 4/1/2020 Page 2 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	on
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9I3643	I 55-1(176)	2 bridge deck replacement	I-55	SCOTT	over Route 62		
Γotals by .	Job Numbe	rs					
J9I3643		d Item Pay Item Adjustm		Item Pay	This Estimate \$714,670.00 \$0.00 \$714,670.00	Previous \$870,467.42 \$0.00 \$870,467.42	To Date \$1,585,137.42 \$0.00 \$1,585,137.42
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 3 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 4019905, Project Item Line Number 0050, Material Set 401990596, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034212, Project Item Line Number 0500, Material Set 703421296, Material 0705DPRCPS30 - Prestress Conc Deck Panel 3" (75 mm), Acceptance Action Generic 0705DPRCPS30 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034212, Project Item Line Number 0500, Material Set 703421296, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913643, Item 7034212, Project Item Line Number 0500, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7123610, Project Item Line Number 0540, Material Set 712361096, Material 0712STDRSB - Slab Drain, Acceptance Action Generic 0712STDRSB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden

Revision 4/1/2020 Page 4 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Report Generated date and can differ from the posted am Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-H01	J9I3643	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.50	\$15,000.00	\$7,500.00
		0001	0020	2071000	LINEAR GRADING CLASS 1	4.40	0.00	4.40	STA	0.00	\$2,600.00	\$0.00
		0001	0030	2072000	LINEAR GRADING CLASS 2	32.40	0.00	32.40	STA	32.40	\$3,850.00	\$124,740.00
		0001	0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,174.00	0.00	1,174.00	SQYD	0.00	\$15.00	\$0.00
		0001	0050	4019905	MISC.Optional Pavement	2,932.00	791.00	3,723.00	SQYD	3,723.00	\$50.53	\$188,123.19
		0001	0060	5021334	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	1,173.60	0.00	1,173.60	SQYD	0.00	\$95.00	\$0.00
		0001	0070	5041000	CONCRETE APPROACH PAVEMENT	404.80	0.00	404.80	SQYD	0.00	\$105.00	\$0.00
		0001	0080	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	349.00	0.00	349.00	LF	0.00	\$20.00	\$0.00
		0001	0090	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	47.00	0.00	47.00	CUYD	0.00	\$45.00	\$0.00
		0001	0100	6096041	PLACING TYPE 1 ROCK DITCH LINER	47.00	0.00	47.00	CUYD	0.00	\$80.00	\$0.00
		0001	0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	853.00	0.00	853.00	CUYD	0.00	\$40.00	\$0.00
		0001	0120	6113040	PLACING TYPE 2 ROCK BLANKET	853.00	0.00	853.00	CUYD	0.00	\$25.00	\$0.00
		0001	0130	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	2.00	1.00	3.00	EA	3.00	\$2,000.00	\$6,000.00
		0001	0140	6122020	REPLACEMENT SAND BARREL	6.00	0.00	6.00	EA	6.00	\$250.00	\$1,500.00
		0001	0150	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	1.00	3.00	EA	0.00	\$1,000.00	\$0.00
		0001	0160	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	0.00	\$5,000.00	\$0.00
		0001	0170	6161005	CONSTRUCTION SIGNS	2,140.00	0.00	2,140.00	SQFT	1,560.00	\$6.50	\$10,140.00
		0001	0180	6161008	ADVANCED WARNING RAIL SYSTEM	18.00	0.00	18.00	EA	4.00	\$25.00	\$100.00
		0001	0190	6161025	CHANNELIZER (TRIM LINE)	500.00	0.00	500.00	EA	332.00	\$17.00	\$5,644.00
		0001	0200	6161030	TYPE III MOVEABLE BARRICADE	21.00	0.00	21.00	EA	15.00	\$145.00	\$2,175.00
		0001	0210	6161033	DIRECTIONAL INDICATOR BARRICADE	100.00	0.00	100.00	EA	74.00	\$65.00	\$4,810.00
		0001	0220	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	3.00	\$1,500.00	\$4,500.00
		0001	0230	6161052	WARNING LIGHT, TYPE B	50.00	0.00	50.00	EA	0.00	\$15.00	\$0.00
		0001	0240	6161070	TUBULAR MARKER	650.00	0.00	650.00	EA	245.00	\$35.00	\$8,575.00
		0001	0250	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$4,800.00	\$19,200.00
		0001	0260	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	16.00	0.00	16.00	EA	8.00	\$800.00	\$6,400.00
		0001	0270	6173600D	RETAINED	451.00	100.00	551.00	LF	551.00	\$40.00	\$22,040.00
		0001	0280	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	451.00	100.00	551.00	LF	0.00	\$35.00	\$0.00
		0001	0290	6181000	MOBILIZATION	1.00	-1.00	0.00	LS		\$225,000.00	\$0.00
		0001	0291	6181000	MOBILIZATION	0.00	1.00	1.00	LS		\$200,165.00	\$100,082.50
		0001	0300	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	10.00	0.00	10.00	EA	0.00	\$250.00	\$0.00
		0001	0310	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	3,645.00	0.00	3,645.00	LF	2,231.00	\$2.00	\$4,462.00
		0001	0320	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	6,090.00	2,500.00	8,590.00	LF	8,590.00	\$2.00	\$17,180.00
		0001	0330	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT	2,705.00	27,660.00 19,126.00	30,365.00 20,900.00	LF LF	0.00	\$0.30 \$0.30	\$0.00
		0001			MARKING PAINT, TYPE L BEADS							
		0001	0350	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	13,177.00	-13,177.00	0.00	LF	0.00	\$0.15	\$0.00
		0001	0360	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6,704.00	-6,704.00	0.00	LF	0.00	\$0.15	\$0.00
		0001	0370	6206125A	MARKING PAINT, TYPE P BEADS	75.00	-75.00	0.00	LF	0.00	\$5.00	\$0.00
		0001	0380	6207001	PAVEMENT MARKING REMOVAL	50,359.00	0.00	50,359.00	LF	8,328.00	\$0.50	\$4,164.00
		0001	0390	6208063	TEMPORARY PAVEMENT MARKING	34,359.00	0.00	34,359.00	EA	24,249.00	\$0.25	\$6,062.25
		0001	0400	6240102A	TEMPORARY SILT FENCE GEOTEXTILE	1,040.00	0.00	1,040.00	SQYD	0.00	\$1.50	\$0.00
		0001	0410	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,689.00	0.00	1,689.00	SQYD	0.00	\$4.00	\$0.00
		0001	0420	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$20,000.00	\$10,000.00
		0001	0430	7250312A	12 IN. PIPE GROUP B	1,100.00	0.00	1,100.00	LF	1,100.00	\$50.00	\$55,000.00

Revision 4/1/2020 Page 5 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-H01	J9I3643	0001	0440	8061016	SEDIMENT REMOVAL	10.00	0.00	10.00	CUYD	3.00	\$1.00	\$3.00
		0010	0450	6061060	MGS GUARDRAIL	100.00	315.00	415.00	LF	0.00	\$40.00	\$0.00
		0010	0460	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	6.00	0.00	6.00	EA	0.00	\$4,000.00	\$0.00
		0010	0470	6069901	MISC.Remove and Reinstall High-Tension Gurad Cable	1.00	0.00	1.00	LS	0.50	\$55,000.00	\$27,500.00
		0070	0480	2162500	REMOVAL OF EXISTING BRIDGE DECK	11,771.00	0.00	11,771.00	SQFT	11,771.00	\$14.00	\$164,794.00
		0070	0490	5031010A	BRIDGE APPROACH SLAB (MAJOR)	188.00	0.00	188.00	SQYD	0.00	\$415.00	\$0.00
		0070	0500	7034212	SLAB ON STEEL	1,353.00	0.00	1,353.00	SQYD	1,353.00	\$525.00	\$710,325.00
		0070	0510	7034219A	TYPE D BARRIER	558.00	0.00	558.00	LF	0.00	\$115.00	\$0.00
		0070	0520	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0070	0530	7121159	SHEAR CONNECTORS	1,800.00	0.00	1,800.00	EA	1,800.00	\$15.50	\$27,900.00
		0070	0540	7123610	SLAB DRAIN	20.00	0.00	20.00	EA	20.00	\$450.00	\$9,000.00
		0070	0550	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	12,100.00	0.00	12,100.00	SQFT	0.00	\$9.50	\$0.00
		0070	0560	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	12,100.00	0.00	12,100.00	SQFT	0.00	\$2.50	\$0.00
		0070	0570	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	12,100.00	0.00	12,100.00	SQFT	0.00	\$1.50	\$0.00
		0070	0580	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$3.00	\$0.00
		0070	0590	7126000	NON-DESTRUCTIVE TESTING	109.00	0.00	109.00	LF	109.00	\$45.00	\$4,905.00
		0070	0600	7172054	OPEN CELL FOAM JOINT SEAL	87.00	0.00	87.00	LF	0.00	\$80.00	\$0.00
		0071	0610	2162500	REMOVAL OF EXISTING BRIDGE DECK	11,771.00	0.00	11,771.00	SQFT	0.00	\$14.00	\$0.00
		0071	0620	5031010A	BRIDGE APPROACH SLAB (MAJOR)	188.00	0.00	188.00	SQYD	0.00	\$415.00	\$0.00
		0071	0630	7034212	SLAB ON STEEL	1,353.00	0.00	1,353.00	SQYD	0.00	\$525.00	\$0.00
		0071	0640	7034219A	TYPE D BARRIER	558.00	0.00	558.00	LF	0.00	\$115.00	\$0.00
		0071	0650	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0071	0660	7121159	SHEAR CONNECTORS	1,800.00	0.00	1,800.00	EA	0.00	\$15.50	\$0.00
		0071	0670	7123610	SLAB DRAIN	18.00	0.00	18.00	EA	0.00	\$450.00	\$0.00
		0071	0680	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	12,100.00	0.00	12,100.00	SQFT	0.00	\$9.50	\$0.00
		0071	0690	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	12,100.00	0.00	12,100.00	SQFT	0.00	\$2.50	\$0.00
		0071	0700	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	12,100.00	0.00	12,100.00	SQFT	0.00	\$1.50	\$0.00
		0071	0710	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$3.00	\$0.00
		0071	0720	7126000	NON-DESTRUCTIVE TESTING	109.00	0.00	109.00	LF	0.00	\$45.00	\$0.00
		0071	0730	7172054	OPEN CELL FOAM JOINT SEAL	87.00	0.00	87.00	LF	0.00	\$80.00	\$0.00
		0001	5001	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$24,835.00	\$24,835.00
		0001	5002	6161055	SEQUENTIAL FLASHING WARNING LIGHT	0.00	36.00	36.00	EA	36.00	\$120.75	\$4,347.00
		0001	5003	8061017	TEMPORARY SEEDING	0.00	1.00	1.00	ACRE	0.50	\$5,660.95	\$2,830.48
		0001	5004	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	0.00	6.00	6.00	EA	6.00	\$50.00	\$300.00
					ate as of Report Generated Date							\$1,585,137.42
220121-H01 Ove	rali - Tota	value Pos	sted to Da	ate as of Rep	ort Generated Date							\$1,585,137.42

Revision 4/1/2020 Page 6 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9I3643

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0140	6122020	REPLACEMENT SAND BARREL	8/11/22	8/17/22	4.00	EA	Four (4) more replacement barrels. They were replaced mid July for a total of 6.	1360		1367		Four (4) more replacement barrels. They were replaced mid July for a total of 6.
0210	6161033	DIRECTIONAL INDICATOR BARRICADE	8/11/22	8/17/22	38.00	EA	NB & SB I-55.	1360		1367		NB & SB I-55.
0240	6161070	TUBULAR MARKER	8/11/22	8/17/22	25.00	EA	Under I-55 along Route 62.	1360		1367		Replacement for Channelizers.
0500	7034212	SLAB ON STEEL	8/11/22	8/17/22	1,353.00	SQYD	Northbound Bridge. Phase I.	1360		1367		Northbound Bridge. Phase I. Estimated Percentage payment based on Strength Required Testing.

The information	holow this line are	details for Construction	n Signs (if applicable)

ect	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to I
i43	0170	April 11, 2022	666	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		65.227	NB	2.00	16			
				CONST-3A 60x48 20.00 FINE SIGN		65.501	NB	2.00	20			
				CONST-3X 56x12 4.67		65.501	NB	2.00	4.67			
				SPEEDING/PASSING (PLATE) GO20-5aP 36x24 6.00 WORK ZONE		65.713	NB	2.00	6			
				(PLAQUE)								
				R4-1 36x48 12.00 DO NOT PASS			NB	2.00	12			
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		65.976	NB	2.00	16			
				WO4-1aR 48x48 16.00 MERGE		66.107	NB	1.00	16			
				(ARROW SYMBOL) WO20-6a 48x48 16.00		66.107	NB	1.00	16			
				RIGHT/CENTER/LEFT LANE CLOSED GO20-5aP 36x24 6.00 WORK ZONE		66.489	NB	2.00	6			
				(PLAQUE)								
				R2-1 36x48 12.00 SPEED LIMIT XX		66.489	NB	2.00	12			
				R2-1 36x48 12.00 SPEED LIMIT XX		66.491	SB	2.00	12			
				R2-1 36x48 12.00 SPEED LIMIT		68.153	NB	2.00	12			
				XX GO20-5aP 36x24 6.00 WORK ZONE		68.396	SB	2.00	6			
				(PLAQUE) R2-1 36x48 12.00 SPEED LIMIT			SB					
				xx		68.396		2.00	12			
				WO4-1aR 48x48 16.00 MERGE (ARROW SYMBOL)		68.598	SB	1.00	16			
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		68.598	SB	1.00	16			
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		68.796	SB	2.00	16			
				AHEAD								
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		68.997	SB	2.00	6			
				R2-1 36x48 12.00 SPEED LIMIT XX		68.997	SB	2.00	12			
				CONST-3A 60x48 20.00 FINE SIGN		69.213	SB	2.00	20			
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)		69.213	SB	2.00	4.67			
				WO20-1 48x48 16.00		69.403	SB	2.00	16			
				ROAD/BRIDGE/RAMP WORK AHEAD R2-1 36x48 12:00 SPEED LIMIT			62 to 55 SB Ramp	1.00	12			
				XX								
				R4-1 36x48 12.00 DO NOT PASS			57 NB to 55 NB Ramp	1.00	12			
				R4-1 36x48 12.00 DO NOT PASS WO20-1 48x48 16.00			57 SB to 55 NB Ramp 57 NB to 55 NB Ramp	1.00	12			
				ROAD/BRIDGE/RAMP WORK AHEAD								
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			57 SB to 55 NB Ramp	1.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			62 to 55 SB Ramp	1.00	16			
				WO20-5 48x48 16.00			57 NB to 55 NB Ramp	1.00	16			
				RIGHT/CENTER/LEFT LANE CLOSED AHEAD								
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED			57 SB to 55 NB Ramp	1.00	16			
				AHEAD			CZNO CCNO D	4.00	00			
				CONST-3A 60x48 20.00 FINE SIGN CONST-3A 60x48 20.00 FINE SIGN			57 NB to 55 NB Ramp 57 SB to 55 NB Ramp	1.00	20			
				CONST-3X 56x12 4.67			57 NB to 55 NB Ramp	1.00	4.67			
				SPEEDING/PASSING (PLATE) CONST-3X 56x12 4.67			57 SB to 55 NB Ramp	1.00	4.67			
				SPEEDING/PASSING (PLATE)			·					
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)			57 NB to 55 NB Ramp	1.00	6			
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)			57 SB to 55 NB Ramp	1.00	6			
				GO20-5aP 36x24 6.00 WORK ZONE			62 to 55 SB Ramp	1.00	6			
		April 19, 2022	7	(PLAQUE) R1-2 48 TRI 6.93 YIELD		67.450	US 62 Ramp to I-55 NB	1.00	6.93			
		June 2, 2022		WO20-2 48x48 16.00 DETOUR		61.540	Rte 62 EB	1.00	16			
				WO20-1 48x48 16.00		61.912	Rte 62 EB	1.00	16			
				ROAD/BRIDGE/RAMP WORK AHEAD								
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		61.988	Rte 62 EB	1.00	16			
				AHEAD WO20-6a 48x48 16.00		62.087	Rte 62 EB	1.00	16			
				RIGHT/CENTER/LEFT LANE CLOSED R11-2 48x30 10.00 ROAD					10			
				R11-2 48x30 10.00 ROAD CLOSED		02.287	Rte 62 at I-55 NB Ramp	3.00	10			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		62.676	Rte 62 WB	1.00	16			

Revision 4/1/2020 Page 7 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction State (if applicable).

ect Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to
643 0170	June 2, 2022	126	WO20-2 48x48 16.00 DETOUR AHEAD		62.909	Rte 62 WB	1.00	16			
		249	special ??x?? ??.00 NO PASSIN ZONE	IG	0.149	Rt H NB	1.00		I-55 North Detour Signage 50B	27.69	2
			special ??x?? ??.00 NO PASSIN ZONE	IG	69.377	Rt HH at I-55 NB On Ramp	1.00		I-55 North Detour Signage 50C	27.69	2
			special ??x?? ??.00 NO PASSIN ZONE	IG	62.391	Rte 62 WB	1.00		I-55 North Detour Signage 50B	27.69	:
			special ??x?? ??.00 NO PASSIN ZONE	IG	61.988	Rte 62 WB	1.00		I-55 North Detour Signage 50A	27.69	
			special ??x?? ??.00 NO PASSIN ZONE	IG	1.070	Rt H NB	1.00		I-55 North Detour Signage 50B	27.69	
			special ??x?? ??.00 NO PASSIN ZONE	IG	61.789	Rte 62 EB	1.00		I-55 North Detour Signage 50E	27.69	
			special ??x?? ??.00 NO PASSIN ZONE	IG	1.847	Rt H NB	1.00		I-55 North Detour Signage 50A	27.69	
			special ??x?? ??.00 NO PASSIN ZONE	IG	1.699	Rt H NB	1.00		I-55 North Detour Signage 50D	27.69	
			special ??x?? ??.00 NO PASSIN ZONE	IG	61.854	Rte 62 EB	1.00		I-55 North Detour Signage 50C	27.69	
		488	EO5-1 36x48 12.00 GORE EXI	Т	67.173	I-55 NB to Rte 62 Ramp	1.00	12			
			special ??x?? ??.00 NO PASSIN ZONE	IG	67.015	I-55 NB	2.00		Ramp Exit 500 FT Sign 61	16.00	
			WO1-6 60x30 12.50 HORIZON ARROW (SYMBOL)	TAL	66.991	I-55 NB	2.00	12.5			
			R11-2 48x30 10.00 ROAD CLOSED		66.991	I-55 NB	1.00	10			
			WO13-1 30x30 6.25 ADVISOR SPEED (PLAQUE)	Y	66.804	I-55 NB	1.00	6.25			
			WO1-4L 48x48 16.00 REVERSI CURVE (SYMBOL LEFT ARROW)	=	66.804	I-55 NB	1.00	16			
			GO20-2 48x24 8.00 END ROAI WORK)	65.730	I-55 SB	2.00	8			
			CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		64.654	I-55 NB	2.00	12			
			GO20-1 60x24 10.00 ROAD WO NEXT XX MILES	ORK	64.552	I-55 NB	2.00	10			
			CONST-7 72x36 18.00 RATE OF WORK ZONE	JR	64.454	I-55 NB	1.00	18			
			R11-2 48x30 10.00 ROAD CLOSED		67.253	I-55 NB	1.00	10			
			CONST-7 72x36 18.00 RATE OF WORK ZONE	JR	70.251	I-55 SB	1.00	18			
			WO1-6 60x30 12.50 HORIZON ARROW (SYMBOL)	TAL	67.253	I-55 NB	2.00	12.5			
			R11-2 48x30 10.00 ROAD CLOSED		67.289	I-55 NB	2.00	10			
			R4-1 36x48 12.00 DO NOT PA	SS	67.429	I-55 NB	1.00	12			
			WO6-3 48x48 16.00 TWO WAY TRAFFIC (SYMBOL)	′	67.429	I-55 SB	1.00	16			
			GO20-5aP 36x24 6.00 WORK Z (PLAQUE)	ONE	67.429	I-55 NB	1.00	6			
			R4-1 36x48 12.00 DO NOT PA		67.647	I-55 NB	1.00	12			
			WO6-3 48x48 16.00 TWO WAY TRAFFIC (SYMBOL)	<u></u>	67.647	I-55 SB	1.00	16			
			GO20-5aP 36x24 6.00 WORK Z (PLAQUE)		67.647	I-55 NB	1.00	6			
			WO1-4R 48x48 16.00 REVERS CURVE (SYMBOL RIGHT ARROW)	67.800	I-55 NB	1.00	16			
			WO13-1 30x30 6.25 ADVISOR SPEED (PLAQUE)		67.800	I-55 NB	1.00	6.25			
			WO1-6 60x30 12.50 HORIZON ARROW (SYMBOL)		67.887	I-55 NB	2.00	12.5			
			R5-1 30x30 6.25 DO NOT EN			I-55 NB	2.00	6.25			
			WO6-3 48x48 16.00 TWO WAY TRAFFIC (SYMBOL)	<u></u>		I-55 SB	2.00	16			
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHE	AD		Rt HH Ramp to I-55 SB	1.00	16			
			CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE			I-55 SB	2.00	12			
			GO20-1 60x24 10.00 ROAD WO NEXT XX MILES			I-55 SB	2.00	10			
	June 13, 2022	24	R2-1 36x48 12.00 SPEED LIM XX	IT	62.117	Rt 62 EB	1.00	12			
			R2-1 36x48 12.00 SPEED LIM		62.428	Rt 62 WB	1.00	12			

Revision 4/1/2020 Page 8 of 12



Marcial	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
2022 SYSTEM 3148.15.00 The adjustment offsets the original system generated Material Payment Estimate Engagement of the current Payment Estimate Engagement (Payment Estimate Engagement of the current Payment Estimate Engagement (Payment Estimate	J9I3643	0050	MISC.	Material		4		SYSTEM	\$118,523.17	Estimate Item Adjustment (0001) due to user leez1 overridding Payment				
2022 SYSTEM (\$148, 153.90)						4		SYSTEM	(\$118,523.17)					
2022 6 3 Jul 16 575TEM 5146;153.06 575TEM 5146;153.06 575TEM 575TE						5		SYSTEM	\$148,153.96	Estimate Item Adjustment (0001) due to user leez1 overridding Payment				
2022 SYSTEM S148,153.96 SySTEM Sy						5		SYSTEM	(\$148,153.96)					
2022 7						6		SYSTEM	\$148,153.96	Estimate Item Adjustment (0001) due to user leez1 overridding Payment				
2022 SYSTEM STATE SYSTEM STATE STA						6		SYSTEM	(\$148,153.96)					
Second Content of the Content of Second Conten						7		SYSTEM	\$148,153.96	Estimate Item Adjustment (0001) due to user leez1 overridding Payment				
2022 SYSTEM Status Estimate Exception 2 on the current Payment Estimate.						7		SYSTEM	(\$148,153.96)					
1000 1000						8		SYSTEM	\$148,153.96	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment				
Material - Total S0.00						8		SYSTEM	(\$148,153.96)					
1980 This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. 1980 This adjustment offsets the original system-generated Material Payment Payment Estimate Exception 3 on the current Payment Estimate. 1980 This adjustment offsets the original system-generated Material Payment P					- Total				\$0.00					
Material - Total				Material - To	otal				\$0.00					
ATTENUATOR 70 BARREL ARRAY		0050 -	Total						\$0.00					
10180 Total Total System Syst		0130	ATTENUATOR 70 MPH (SAND	Material		5		SYSTEM	\$4,000.00	Estimate Item Adjustment (0002) due to user leez1 overridding Payment				
Naterial - Total						5		SYSTEM	(\$4,000.00)					
Name					- Total				\$0.00					
ADVANCED WARNING RAIL SYSTEM				Material - To	otal				\$0.00					
WARNING RAIL SYSTEM		0130 -	Total						\$0.00					
2022 3 May 2, SYSTEM \$100.00 This adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate. 3 May 2, SYSTEM (\$100.00) 4 May 16, SYSTEM \$100.00 This adjustment (0002) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate. 4 May 16, SYSTEM \$100.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 5 0.00 180 - Total 190 CHANNELIZER (TRIM LINE) 2 Apr 15, SYSTEM \$2,244.00 2022 3 May 2, SYSTEM \$2,244.00 2022 3 May 3, SYSTEM \$2,244.00 2022 3 May 4, SYSTEM \$2,244.00 2022 3 May 5, SYSTEM \$2,244.00 2022 3 May 6, SYSTEM \$2,244.00 2022 3 May 7, SYSTEM \$2,244.00 2022 3 May 8, SYSTEM \$2,244.00 2022 3 May 9, SYSTEM \$2,244.00		0180	WARNING RAIL		Material		2		SYSTEM	\$100.00	Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment			
2022 Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						2		SYSTEM	(\$100.00)					
A may 16, 2022						3		SYSTEM	\$100.00	Estimate Item Adjustment (0001) due to user leez1 overridding Payment				
Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 4 May 16, 2022 \$0.00 Naterial - Total \$0.00 CHANNELIZER (TRIM LINE) Material \$2 Apr 15, 2022 \$7STEM \$2,244.00 This adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. 2 Apr 15, 2022 \$7STEM \$2,244.00 This adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. 3 May 2, SYSTEM \$2,244.00 This adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate Estimate Exception 2 on the current Payment Estimate.										3		SYSTEM	(\$100.00)	
Total S0.00 Material - Total \$0.00 O180 - Total CHANNELIZER (TRIM LINE) Material 2 Apr 15, 2022 SYSTEM \$2,244.00 CHANNELIZER (TRIM LINE) 2 Apr 15, 2022 SYSTEM (\$2,244.00) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. 3 May 2, 2022 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Estimate Exception 2 on the current Payment Estimate. 3 May 2, SYSTEM (\$2,244.00)										4		SYSTEM	\$100.00	Estimate Item Adjustment (0002) due to user leez1 overridding Payment
Material - Total \$0.00						4		SYSTEM	(\$100.00)					
\$0.00 CHANNELIZER (TRIM LINE) Material 2 Apr 15, 2022 SYSTEM \$2,244.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. Apr 15, 2022 SYSTEM (\$2,244.00) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 3 May 2, SYSTEM (\$2,244.00)					- Total				\$0.00					
CHANNELIZER (TRIM LINE) Material 2 Apr 15, 2022 SYSTEM \$2,244.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. Apr 15, 2022 SYSTEM (\$2,244.00) 3 May 2, SYSTEM \$2,244.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 3 May 2, SYSTEM (\$2,244.00)				Material - To	otal				\$0.00					
(TRIM LINE) 2022 Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. 2 Apr 15, 2022 SYSTEM (\$2,244.00) 3 May 2, 2022 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 3 May 2, SYSTEM (\$2,244.00)		0180 -	Total						\$0.00					
2022 3 May 2, SYSTEM \$2,244.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 3 May 2, SYSTEM (\$2,244.00)		0190		Material		2		SYSTEM	\$2,244.00	Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment				
2022 Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 3 May 2, SYSTEM (\$2,244.00)						2		SYSTEM	(\$2,244.00)					
						3		SYSTEM	\$2,244.00	Estimate Item Adjustment (0002) due to user leez1 overridding Payment				
						3		SYSTEM	(\$2,244.00)					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J9I3643	0190	CHANNELIZER (TRIM LINE)	Material		4	May 16, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
					4	May 16, 2022	SYSTEM	(\$2,244.00)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
	0190 -	Total						\$0.00												
	0210	DIRECTIONAL INDICATOR BARRICADE	Material		2	Apr 15, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
					2	Apr 15, 2022	SYSTEM	(\$2,340.00)												
					3	May 2, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
					3	May 2, 2022	SYSTEM	(\$2,340.00)												
					4	May 16, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.											
					4	May 16, 2022	SYSTEM	(\$2,340.00)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
	0210 -	Total						\$0.00												
	0220	FLASHING ARROW PANEL	Material		2	Apr 15, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.											
												2	Apr 15, 2022	SYSTEM	(\$3,000.00)					
																3	May 2, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
																			3	May 2, 2022
					4	May 16, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.											
					4	May 16, 2022	SYSTEM	(\$3,000.00)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
	0220 -	Total						\$0.00												
	0250	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material		2	Apr 15, 2022	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.											
					2	Apr 15, 2022	SYSTEM	(\$9,600.00)												
														3	May 2, 2022	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
								3	May 2, 2022	SYSTEM	(\$9,600.00)									
					4	May 16, 2022	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.											
					4	May 16, 2022	SYSTEM	(\$9,600.00)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
	0250 -	Total						\$0.00												
	0270	TEMPORARY	Material		5	Jun 2,	SYSTEM	\$11,000.00	This adjustment offsets the original system-generated Material Payment											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J9I3643	0270	TRAFFIC BARRIER, CONT.	Material			2022			Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.									
		FURN/RE			5	Jun 2, 2022	SYSTEM	(\$11,000.00)										
				- Total				\$0.00										
			Material - To	otal				\$0.00										
	0270 -	Total						\$0.00										
	0310	TEMPORARY REMOVABLE MARKING TAPE 4	Material		6	Jun 16, 2022	SYSTEM	\$2,706.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.									
		IN.,			6	Jun 16, 2022	SYSTEM	(\$2,706.00)										
					7	Jul 1, 2022	SYSTEM	\$4,462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.									
					7	Jul 1, 2022	SYSTEM	(\$4,462.00)										
					8	Jul 19, 2022	SYSTEM	\$4,462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.									
					8	Jul 19, 2022	SYSTEM	(\$4,462.00)										
				- Total				\$0.00										
			Material - To	terial - Total				\$0.00										
	0310 -	Total						\$0.00										
	0320	TEMPORARY REMOVABLE MARKING TAPE	Material	Material		6	Jun 16, 2022	SYSTEM	\$7,416.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.								
														6	Jun 16, 2022	SYSTEM	(\$7,416.00)	
														7	Jul 1, 2022	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
																7	Jul 1, 2022	SYSTEM
					8	Jul 19, 2022	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.									
					8	Jul 19, 2022	SYSTEM	(\$12,180.00)										
				- Total				\$0.00										
			Material - To	otal				\$0.00										
	0320 -	Total						\$0.00										
	0390	TEMPORARY PAVEMENT MARKING	Material		6	Jun 16, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.									
							6	Jun 16, 2022	SYSTEM	(\$6,062.25)								
												7	Jul 1, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
							7	Jul 1, 2022	SYSTEM	(\$6,062.25)								
					8	Jul 19, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.									
					8	Jul 19, 2022	SYSTEM	(\$6,062.25)										
				- Total				\$0.00										
			Material - To	otal				\$0.00										
	0390 -	Total						\$0.00										
	0500	SLAB ON STEEL	Material		10	Aug 17, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment									





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J9I3643	0500	SLAB ON STEEL	Material						Estimate Exception 2 on the current Payment Estimate.										
					10	Aug 17, 2022	SYSTEM	(\$710,325.00)											
				- Total				\$0.00											
			Material - Total					\$0.00											
	0500 -	Total						\$0.00											
	0540	SLAB DRAIN	Material		9	Aug 2, 2022	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
					9	Aug 2, 2022	SYSTEM	(\$9,000.00)											
					10	Aug 17, 2022	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.										
					10	Aug 17, 2022	SYSTEM	(\$9,000.00)											
				- Total				\$0.00											
			Material - To	otal				\$0.00											
	0540 -	Total						\$0.00											
	5002	SEQUENTIAL FLASHING WARNING LIGHT	Material	Material		4	May 16, 2022	SYSTEM	\$4,347.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.									
					4	May 16, 2022	SYSTEM	(\$4,347.00)											
				- Total															
			Material - To	otal				\$0.00											
	5002 -	Total						\$0.00											
	5003	TEMPORARY SEEDING			5	Jun 2, 2022	SYSTEM	\$2,830.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.										
															5	Jun 2, 2022	SYSTEM	(\$2,830.48)	
													6	6	Jun 16, 2022	SYSTEM	\$2,830.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
									6	Jun 16, 2022	SYSTEM	(\$2,830.48)							
				- Total				\$0.00											
			Material - To	otal				\$0.00											
	5003 -	Total						\$0.00											
J9I3643 -	Total							\$0.00											
Overall -	Total							\$0.00											