

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 2, 2023

Progress Estimate Number 24		Contract ID Prime Contractor	220121-H01 Robertson Contrac				Original Contract Amour Net Change Order Amou Current Contract Amoun	nt \$116,673.74
Approval Date								By User
May 2, 2023		Generated and Approved (and should be considered Draft) at the Project Office Level by						woodsk1
May 2, 2023		Re	viewed and Approve	ed (and sho	ould be considere	d Draft) at the	Resident Engineer Level by	bollis1
May 3, 2023			Re	eviewed an	d Approved at the	Central Office	Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
May 1, 2023	May 1, 2023		88.44%

	Contract Informational Dates									
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract							
Acceptance Date										
Awarded Date	February 2, 2022	February 2, 2022								
Letting Date	January 21, 2022	January 21, 2022								
Notice to Proceed Date	April 4, 2022	April 4, 2022								
Open to Traffic Date										
Work Began Date	April 11, 2022	April 11, 2022								

Contract Total Pay For Estimate No. 24											
	This Estimate	Previous	To Date								
220121-H01											
Total Posted Items Pay	\$55,911.70	\$3,262,521.65	\$3,318,433.35								
Gross Item Adjustments	\$0.00	\$0.00	\$0.00								
Incentive	\$0.00	\$0.00	\$0.00								
Disincentive	\$0.00	\$0.00	\$0.00								
Liquidated Damage	\$0.00	\$0.00	\$0.00								
Other Contract Adjustments	\$0.00	\$0.00	\$0.00								
		\$3,262,521.65	\$3,318,433.35								
Contract Total Payable This Estimate:	\$55,911.70										

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	. Qty					
J9I3643	0020	2071000	LINEAR GRADING CLASS 1	STA	\$2,600.000	4.4	\$11,440.00		
	0090	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	CUYD	\$45.000	47	\$2,115.00		
	0100	6096041	PLACING TYPE 1 ROCK DITCH LINER	CUYD	\$80.000	47	\$3,760.00		
	0400	6240102A	TEMPORARY SILT FENCE GEOTEXTILE	SQYD	\$1.500	1,040	\$1,560.00		
	0410	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	SQYD	\$4.000	1,689	\$6,756.00		
	0440	8061016	SEDIMENT REMOVAL	CUYD	\$1.000	7	\$7.00		
	0470	6069901	MISC.Remove and Reinstall High-Tension Gurad Cable	LS	\$55,000.000	0.5	\$27,500.00		
	5005	8051000A	SEEDING - COOL SEASON GRASSES	ACRE	\$5,547.390	0.5	\$2,773.70		
Project J9I364	Project J9l3643 - Total								
Overall - Tota	Overall - Total								

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

	Line Item Adjustments Exist on Contract Line Item Adjustments This Estimate											
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount				
J9I3643	0060	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material			-1,173.6	\$95.00	(\$111,492.00)				
	0060	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED,	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	1,173.6	\$95.00	\$111,492.00				

Revision 3/23/2023 Page 1 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 2, 2023

Progress Estimate Number 24 Contract ID 220121-H01 Prime Contractor Robertson Contractors, Inc. Pay Period Start April 2, 2023 Original Contract Amount \$3,635,384.06 Pay Period End May 1, 2023 Net Change Order Amount \$116,673.74 Current Contract Amount \$3,752,057.80

oject mber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3643		15 FT. JOINTS)		Туре	Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		JIIII FIICE	
	0070	CONCRETE APPROACH PAVEMENT	Material			-404.8	\$105.00	(\$42,504.00
	0070	CONCRETE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	404.8	\$105.00	\$42,504.00
	0800	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material			-349	\$20.00	(\$6,980.00
	0800	HEIGHT AND UNDER) TYPE S S Ac overring		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	349	\$20.00	\$6,980.00	
	0090	FURNISHING TYPE 1 ROCK DITCH LINER	Material			-47	\$45.00	(\$2,115.00
	0090	FURNISHING TYPE 1 ROCK DITCH LINER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	47	\$45.00	\$2,115.00
	0490	BRIDGE APPROACH SLAB (MAJOR)	Material			-188	\$415.00	(\$78,020.00
	0490	BRIDGE APPROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	188	\$415.00	\$78,020.00
	0500	SLAB ON STEEL	Material			-1,353	\$525.00	(\$710,325.00
	0500	SLAB ON STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	1,353	\$525.00	\$710,325.00
	0510	TYPE D BARRIER	Material			-558	\$115.00	(\$64,170.00
	0510	TYPE D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	558	\$115.00	\$64,170.00
	0620	BRIDGE APPROACH SLAB (MAJOR)	Material			-188	\$415.00	(\$78,020.00
	0620	0 BRIDGE APPROACH SLAB (MAJOR) Material			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	188	\$415.00	\$78,020.00
	0630	SLAB ON STEEL	Material			-1,353	\$525.00	(\$710,325.00
	0630	SLAB ON STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	1,353	\$525.00	\$710,325.00
	0640	TYPE D BARRIER	Material			-558	\$115.00	(\$64,170.00

Revision 3/23/2023 Page 2 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 2, 2023

Progi	Progress Estimate Number 24 Contract ID 220121-H01 Prime Contractor Robertson Contract						er Amount	\$3,635,384.06 \$116,673.74 \$3,752,057.80	
Project Number	Line No.	Item Descri	iption	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3643	0640	TYPE	D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	558	\$115.00	\$64,170.00
	5005 SEEDING - COC		OL SEASON GRASSES	Material			-0.5	\$5,547.39	(\$2,773.70)
	5005	SEEDING - COO	OL SEASON GRASSES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	0.5	\$5,547.39	\$2,773.70
Total									\$0.00

Revision 3/23/2023 Page 3 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information										
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work					
J9I3643	I 55-1(176)	2 bridge deck replacement	I-55	SCOTT	over Route 62						
Totals by .	Job Numbe	ers									
J9I3643					This Estimate	Previous	To Date				
		d Item Pay Item Adjustm	onto		\$55,911.70 \$0.00	\$3,262,521.65 \$0.00	\$3,318,433.35 \$0.00				
Gross item A		item Aujustin		Item Pay		\$3,262,521.65	\$3,318,433.35				
	Incentive			\$0.00	\$0.00	\$0.00					
		centive			\$0.00	\$0.00	\$0.00				
		dated Damages			\$0.00	\$0.00	\$0.00				
	Other	Contract Adju	stments		\$0.00	\$0.00	\$0.00				

Revision 3/23/2023 Page 4 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 4019905, Project Item Line Number 0050, Material Set 401990596, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5021334, Project Item Line Number 0060, Material Set 502133496, Material 1057JMDAEC6.12 - Dowel Assemblies Epoxy Ctd Gr60 1 1/2" @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5021334, Project Item Line Number 0060, Material Set 502133496, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913643, Item 5031010A, Project Item Line Number 0490, Material Set 5031010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5031010A, Project Item Line Number 0490, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913643, Item 5031010A, Project Item Line Number 0490, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5031010A, Project Item Line Number 0490, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5031010A, Project Item Line Number 0620, Material Set 5031010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5031010A, Project Item Line Number 0620, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4* (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5031010A, Project Item Line Number 0620, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5031010A, Project Item Line Number 0620, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5031010A, Project Item Line Number 0620, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5041000, Project Item Line Number 0070, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5041000, Project Item Line Number 0070, Material Set 504100096, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5041000, Project Item Line Number 0070, Material Set 504100096, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5041000, Project Item Line Number 0070, Material Set 504100096, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 6091010, Project Item Line Number 0080, Material Set 609101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 6096010A, Project Item Line Number 0090, Material Set 6096010A96, Material 0609PDDL - Paved Drainage Material for Ditch Liner, Acceptance Action Generic 0609PDDL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034212, Project Item Line Number 0500, Material Set 703421296, Material 0705DPRCPS30 - Prestress Conc Deck Panel 3" (75 mm), Acceptance Action Generic 0705DPRCPS30 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034212, Project Item Line Number 0500, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034212, Project Item Line Number 0630, Material Set 703421296, Material 0705DPRCPS30 - Prestress Conc Deck Panel 3" (75 mm), Acceptance Action Generic 0705DPRCPS30 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034212, Project Item Line Number 0630, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034219A, Project Item Line Number 0510, Material Set 7034219A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034219A, Project Item Line Number 0640, Material Set 7034219A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @,	No Remark was entered by Engineer	woodsk1	Overridden

Revision 3/23/2023 Page 5 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 1053CSSIL is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 8051000A, Project Item Line Number 5005, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 8051000A, Project Item Line Number 5005, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden

Revision 3/23/2023 Page 6 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Report Generated date and can differ from the posted am Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-H01	J9I3643	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0001	0020	2071000	LINEAR GRADING CLASS 1	4.40	0.00	4.40	STA	4.40	\$2,600.00	\$11,440.00
		0001	0030	2072000	LINEAR GRADING CLASS 2	32.40	0.00	32.40	STA	32.40	\$3,850.00	\$124,740.00
		0001	0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,174.00	0.00	1,174.00	SQYD	1,174.00	\$15.00	\$17,610.00
		0001	0050	4019905	MISC.Optional Pavement	2,932.00	791.00	3,723.00	SQYD	3,723.00	\$50.53	\$188,123.19
		0001	0060	5021334	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	1,173.60	0.00	1,173.60	SQYD	1,173.60	\$95.00	\$111,492.00
		0001	0070	5041000	CONCRETE APPROACH PAVEMENT	404.80	0.00	404.80	SQYD	404.80	\$105.00	\$42,504.00
		0001	0080	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	349.00	0.00	349.00	LF	349.00	\$20.00	\$6,980.00
		0001	0090	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	47.00	0.00	47.00	CUYD	47.00	\$45.00	\$2,115.00
		0001	0100	6096041	PLACING TYPE 1 ROCK DITCH LINER	47.00	0.00	47.00	CUYD	47.00	\$80.00	\$3,760.00
		0001	0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	853.00	0.00	853.00	CUYD	853.00	\$40.00	\$34,120.00
		0001	0120	6113040	PLACING TYPE 2 ROCK BLANKET	853.00	0.00	853.00	CUYD	853.00	\$25.00	\$21,325.00
		0001	0130	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	2.00	2.00	4.00	EA	4.00	\$2,000.00	\$8,000.00
		0001	0140	6122020	REPLACEMENT SAND BARREL	6.00	24.00	30.00	EA	30.00	\$250.00	\$7,500.00
		0001	0150	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	1.00	3.00	EA	3.00	\$1,000.00	\$3,000.00
		0001	0160	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	1.00	\$5,000.00	\$5,000.00
		0001	0170	6161005	CONSTRUCTION SIGNS	2,140.00	0.00	2,140.00	SQFT	1,560.00	\$6.50	\$10,140.00
		0001	0180	6161008	ADVANCED WARNING RAIL SYSTEM	18.00	0.00	18.00	EA	8.00	\$25.00	\$200.00
		0001	0190	6161025	CHANNELIZER (TRIM LINE)	500.00	0.00	500.00	EA	407.00	\$17.00	\$6,919.00
		0001	0200	6161030	TYPE III MOVEABLE BARRICADE	21.00	0.00	21.00	EA	15.00	\$145.00	\$2,175.00
		0001	0210	6161033	DIRECTIONAL INDICATOR BARRICADE	100.00	0.00	100.00	EA	74.00	\$65.00	\$4,810.00
		0001	0220	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	3.00	\$1,500.00	\$4,500.00
		0001	0230	6161052	WARNING LIGHT, TYPE B	50.00	0.00	50.00	EA	0.00	\$15.00	\$0.00
		0001	0240	6161070	TUBULAR MARKER	650.00	0.00	650.00	EA	370.00	\$35.00	\$12,950.00
		0001	0250	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$4,800.00	\$19,200.00
		0001	0260	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	16.00	0.00	16.00	EA	16.00	\$800.00	\$12,800.00
		0001	0270	6173600D	RETAINED	451.00	100.00	551.00	LF	551.00	\$40.00	\$22,040.00
		0001	0280	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	451.00	100.00	551.00	LF	551.00	\$35.00	\$19,285.00
		0001	0290	6181000	MOBILIZATION	1.00	-1.00	0.00	LS		\$225,000.00	\$0.00
		0001	0291	6181000	MOBILIZATION	0.00	1.00	1.00	LS		\$200,165.00	\$200,165.00
		0001	0300	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	10.00	0.00	10.00	EA	0.00	\$250.00	\$0.00
		0001	0310	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	3,645.00	0.00	3,645.00	LF	3,645.00	\$2.00	\$7,290.00
		0001	0320	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	6,090.00	2,500.00	8,590.00	LF	8,590.00	\$2.00	\$17,180.00
		0001	0330	6205902A 6205903A	PAINT, TYPE L BEADS	2,705.00	27,660.00 19,126.00	30,365.00 20,900.00	LF LF	0.00	\$0.30 \$0.30	\$0.00
		0001			MARKING PAINT, TYPE L BEADS	,						
		0001	0350	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	13,177.00	-13,177.00	0.00	LF	0.00	\$0.15	\$0.00
		0001	0360	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6,704.00	-6,704.00	0.00	LF	0.00	\$0.15	\$0.00
		0001	0370	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	75.00	-75.00	0.00	LF	0.00	\$5.00	\$0.00
		0001	0380	6207001	PAVEMENT MARKING REMOVAL	50,359.00	0.00	50,359.00	LF	32,672.00	\$0.50	\$16,336.00
		0001	0390	6208063	TEMPORARY PAVEMENT MARKING	34,359.00	12,215.00	46,574.00	EA	46,574.00	\$0.25	\$11,643.50
		0001	0400	6240102A	TEMPORARY SILT FENCE GEOTEXTILE	1,040.00	0.00	1,040.00	SQYD	1,040.00	\$1.50	\$1,560.00
		0001	0410	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,689.00	0.00	1,689.00	SQYD	1,689.00	\$4.00	\$6,756.00
		0001	0420	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$20,000.00	\$20,000.00
		0001	0430	7250312A	12 IN. PIPE GROUP B	1,100.00	0.00	1,100.00	LF	1,100.00	\$50.00	\$55,000.00

Page 7 of 26 Revision 3/23/2023



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Project Nm.CONTRACT No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-H01 J9I3643	0001	0440	8061016	SEDIMENT REMOVAL	10.00	0.00	10.00	CUYD	10.00	\$1.00	\$10.00
	0010	0450	6061060	MGS GUARDRAIL	100.00	315.00	415.00	LF	415.00	\$40.00	\$16,600.00
	0010	0460	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	6.00	0.00	6.00	EA	6.00	\$4,000.00	\$24,000.00
	0010	0470	6069901	MISC.Remove and Reinstall High-Tension Gurad Cable	1.00	0.00	1.00	LS	1.00	\$55,000.00	\$55,000.00
	0070	0480	2162500	REMOVAL OF EXISTING BRIDGE DECK	11,771.00	0.00	11,771.00	SQFT	11,771.00	\$14.00	\$164,794.00
	0070	0490	5031010A	BRIDGE APPROACH SLAB (MAJOR)	188.00	0.00	188.00	SQYD	188.00	\$415.00	\$78,020.00
	0070	0500	7034212	SLAB ON STEEL	1,353.00	0.00	1,353.00	SQYD	1,353.00	\$525.00	\$710,325.00
	0070	0510	7034219A	TYPE D BARRIER	558.00	0.00	558.00	LF	558.00	\$115.00	\$64,170.00
	0070	0520	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
	0070	0530	7121159	SHEAR CONNECTORS	1,800.00	0.00	1,800.00	EA	1,800.00	\$15.50	\$27,900.00
	0070	0540	7123610	SLAB DRAIN	20.00	0.00	20.00	EA	20.00	\$450.00	\$9,000.00
	0070	0550	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	12,100.00	0.00	12,100.00	SQFT	0.00	\$9.50	\$0.00
	0070	0560	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	12,100.00	0.00	12,100.00	SQFT	0.00	\$2.50	\$0.00
	0070	0570	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	12,100.00	0.00	12,100.00	SQFT	0.00	\$1.50	\$0.00
	0070	0580	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$3.00	\$0.00
	0070	0590	7126000	NON-DESTRUCTIVE TESTING	109.00	0.00	109.00	LF	109.00	\$45.00	\$4,905.00
	0070	0600	7172054	OPEN CELL FOAM JOINT SEAL	87.00	0.00	87.00	LF	87.00	\$80.00	\$6,960.00
	0071	0610	2162500	REMOVAL OF EXISTING BRIDGE DECK	11,771.00	0.00	11,771.00	SQFT	11,771.00	\$14.00	\$164,794.00
	0071	0620	5031010A	BRIDGE APPROACH SLAB (MAJOR)	188.00	0.00	188.00	SQYD	188.00	\$415.00	\$78,020.00
	0071	0630	7034212	SLAB ON STEEL	1,353.00	0.00	1,353.00	SQYD	1,353.00	\$525.00	\$710,325.00
	0071	0640	7034219A	TYPE D BARRIER	558.00	0.00	558.00	LF	558.00	\$115.00	\$64,170.00
	0071	0650	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
	0071	0660	7121159	SHEAR CONNECTORS	1,800.00	0.00	1,800.00	EA	1,800.00	\$15.50	\$27,900.00
	0071	0670	7123610	SLAB DRAIN	18.00	0.00	18.00	EA	18.00	\$450.00	\$8,100.00
	0071	0680	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	12,100.00	0.00	12,100.00	SQFT	0.00	\$9.50	\$0.00
	0071	0690	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	12,100.00	0.00	12,100.00	SQFT	0.00	\$2.50	\$0.00
	0071	0700	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	12,100.00	0.00	12,100.00	SQFT	0.00	\$1.50	\$0.00
	0071	0710	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$3.00	\$0.00
	0071	0720	7126000	NON-DESTRUCTIVE TESTING	109.00	0.00	109.00	LF	109.00	\$45.00	\$4,905.00
	0071	0730	7172054	OPEN CELL FOAM JOINT SEAL	87.00	0.00	87.00	LF	87.00	\$80.00	\$6,960.00
	0001	5001	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$24,835.00	\$24,835.00
	0001	5002	6161055	SEQUENTIAL FLASHING WARNING LIGHT	0.00	36.00	36.00	EA	36.00	\$120.75	\$4,347.00
	0001	5003	8061017	TEMPORARY SEEDING	0.00	1.00	1.00	ACRE	1.00	\$5,660.95	\$5,660.95
	0001	5004	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	0.00	6.00	6.00	EA	6.00	\$50.00	\$300.00
	0001	5005	8051000A	SEEDING - COOL SEASON GRASSES	0.00	1.00	1.00	ACRE	0.50	\$5,547.39	\$2,773.70
	0001	5006	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	0.00	448.00	448.00	SQYD	0.00	\$24.59	\$0.00
				ort Generated Date							\$3,318,433.34 \$3,318,433.34

Revision 3/23/2023 Page 8 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9l3643

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	2071000	LINEAR GRADING CLASS 1	4/28/23	5/2/23	4.40	STA	Southbound Bridge Phase II. Estimated payment percentage.	1360		1367		Southbound Bridge Phase II. Estimated payment percentage.
0090	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	4/28/23	5/2/23	47.00	CUYD	Southbound Bridge Phase II. Estimated payment percentage.	1360		1367		Southbound Bridge Phase II. Estimated payment percentage.
0100	6096041	PLACING TYPE 1 ROCK DITCH LINER	4/28/23	5/2/23	47.00	CUYD	Southbound Bridge Phase II. Estimated payment percentage.	1360		1367		Southbound Bridge Phase II. Estimated payment percentage.
0400	6240102A	TEMPORARY SILT FENCE GEOTEXTILE	4/28/23	5/2/23	1,040.00	SQYD	Southbound Bridge Phase II. Estimated payment percentage.	1360		1367		Southbound Bridge Phase II. Estimated payment percentage.
0410	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	4/28/23	5/2/23	1,689.00	SQYD	Southbound Bridge Phase II. Estimated payment percentage.	1360		1367		Southbound Bridge Phase II. Estimated payment percentage.
0440	8061016	SEDIMENT REMOVAL	4/28/23	5/2/23	7.00	CUYD	Southbound Bridge Phase II. Estimated payment percentage.	1360		1367		Southbound Bridge Phase II. Estimated payment percentage.
0470	6069901	MISC. GUARDRAIL ITEM	4/28/23	5/2/23	0.50	LS	Southbound Bridge Phase II. Estimated payment percentage.	1360		1367		Southbound Bridge Phase II. Estimated payment percentage.
5005	8051000A	SEEDING - COOL SEASON GRASSES	4/28/23	5/2/23	0.50	ACRE	Southbound Bridge Phase II. Estimated payment percentage.	1360		1367		Southbound Bridge Phase II. Estimated payment percentage.

		4hin Iina a	un dataile fou Cometuvation Sie	une (if emplicable)	percenta					percentage.		
	Line Number		re details for Construction Signature Total Quantity Posted For DWR Date	Ins (If applicable). Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Po
913643	0170	April 11, 2022	666	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		65.227	NB	2.00	16			
				CONST-3A 60x48 20.00 FINE SIGN		65.501	NB	2.00	20			
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)		65.501	NB	2.00	4.67			9.
				GO20-5aP 36x24 6.00 WORK ZONE		65.713	NB	2.00	6			
				(PLAQUE) R4-1 36x48 12.00 DO NOT PASS		65.713	NB	2.00	12			
				WO20-5 48x48 16.00		65.976	NB	2.00	16			
				RIGHT/CENTER/LEFT LANE CLOSED AHEAD								
				WO4-1aR 48x48 16.00 MERGE (ARROW SYMBOL)		66.107	NB	1.00	16			
				WO20-6a 48x48 16:00 RIGHT/CENTER/LEFT LANE CLOSED		66.107	NB	1.00	16			
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		66.489	NB	2.00	6			
				R2-1 36x48 12.00 SPEED LIMIT		66.489	NB	2.00	12			
				R2-1 36x48 12.00 SPEED LIMIT		66.491	SB	2.00	12			
				XX R2-1 36x48 12.00 SPEED LIMIT		68.153	NB	2.00	12			
				xx								
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		68.396	SB	2.00	6			
				R2-1 36x48 12.00 SPEED LIMIT XX		68.396	SB	2.00	12			
				WO4-1aR 48x48 16.00 MERGE (ARROW SYMBOL)		68.598	SB	1.00	16			
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		68.598	SB	1.00	16			
				WO20-5 48x48 16:00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		68.796	SB	2.00	16			
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		68.997	SB	2.00	6			
				R2-1 36x48 12.00 SPEED LIMIT XX		68.997	SB	2.00	12			
				CONST-3A 60x48 20.00 FINE SIGN		69.213	SB	2.00	20			
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)		69.213	SB	2.00	4.67			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		69.403	SB	2.00	16			
				R2-1 36x48 12.00 SPEED LIMIT XX			62 to 55 SB Ramp	1.00	12			
				R4-1 36x48 12.00 DO NOT PASS			57 NB to 55 NB Ramp	1.00	12			
				R4-1 36x48 12.00 DO NOT PASS			57 SB to 55 NB Ramp	1.00	12			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			57 NB to 55 NB Ramp	1.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			57 SB to 55 NB Ramp	1.00	16			
				WO20-1 48x48 16.00			62 to 55 SB Ramp	1.00	16			
				WO20-5 48x48 16.00			57 NB to 55 NB Ramp	1.00	16			
				RIGHT/CENTER/LEFT LANE CLOSED AHEAD								
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD			57 SB to 55 NB Ramp	1.00	16			
				CONST-3A 60x48 20.00 FINE SIGN			57 NB to 55 NB Ramp	1.00	20			
				CONST-3A 60x48 20.00 FINE SIGN			57 SB to 55 NB Ramp	1.00	20			
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)			57 NB to 55 NB Ramp	1.00	4.67			
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)			57 SB to 55 NB Ramp	1.00	4.67			
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)			57 NB to 55 NB Ramp	1.00	6			
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)			57 SB to 55 NB Ramp	1.00	6			
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)			62 to 55 SB Ramp	1.00	6			
		April 19, 2022	7	R1-2 48 TRI 6.93 YIELD		67.450	US 62 Ramp to I-55 NB	1.00	6.93			
		June 2, 2022		WO20-2 48x48 16.00 DETOUR AHEAD		61.540	Rte 62 EB	1.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		61.912	Rte 62 EB	1.00	16			

Revision 3/23/2023 Page 9 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

		re details for Construction Signature Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	CE Each Sign	Special Sign	SF Each Special Sign	Total SE to I
Line Number 0170	June 2, 2022	126	WO20-5 48x48 16.00	Station	61.988	Rte 62 EB	1.00	16	Special Sign	or Each opedal olgi	Total SF to F
			RIGHT/CENTER/LEFT LANE CLOSED AHEAD								
			WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		62.087	Rte 62 EB	1.00	16			
			R11-2 48x30 10.00 ROAD CLOSED		62.281	Rte 62 at I-55 NB Ramp	3.00	10			
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		62.676	Rte 62 WB	1.00	16			
			WO20-2 48x48 16.00 DETOUR AHEAD		62.909	Rte 62 WB	1.00	16			
		249	special ??x?? ??.00 NO PASSING ZONE		0.149	Rt H NB	1.00		I-55 North Detour Signage 50B	27.69	
			special ??x?? ??.00 NO PASSING		69.377	Rt HH at I-55 NB On Ramp	1.00		I-55 North Detour Signage 50C	27.69	
			ZONE special ??x?? ??.00 NO PASSING		62.391	Rte 62 WB	1.00		I-55 North Detour Signage 50B	27.69	
			ZONE special ??x?? ??.00 NO PASSING		61.988	Rte 62 WB	1.00		I-55 North Detour Signage 50A	27.69	
			ZONE special ??x?? ??.00 NO PASSING		1.070	Rt H NB	1.00		I-55 North Detour Signage 50B	27.69	
			ZONE special ??x?? ??.00 NO PASSING		61.789	Rte 62 EB	1.00		I-55 North Detour Signage 50E	27.69	
			ZONE special ??x?? ??.00 NO PASSING		1.847	Rt H NB	1.00		I-55 North Detour Signage 50A		
			ZONE special ??x?? ??.00 NO PASSING		1.699	Rt H NB	1.00		I-55 North Detour Signage 50D		
			ZONE								
		400	special ??x?? ??.00 NO PASSING ZONE		61.854	Rte 62 EB	1.00	40	I-55 North Detour Signage 50C	21.03	
		488	EO5-1 36x48 12.00 GORE EXIT special ??x?? ??.00 NO PASSING		67.173 67.015	I-55 NB to Rte 62 Ramp I-55 NB	2.00	12	Ramp Exit 500 FT Sign 61	16.00	
			ZONE WO1-6 60x30 12.50 HORIZONTAL		66.991	I-55 NB	2.00	12.5			
			ARROW (SYMBOL) R11-2 48x30 10.00 ROAD		66.991	I-55 NB	1.00	10			
			CLOSED W013-1 30x30 6.25 ADVISORY		66.804	I-55 NB	1.00	6.25			
			SPEED (PLAQUE) WO1-4L 48x48 16.00 REVERSE		66.804	I-55 NB	1.00	16			
			CURVE (SYMBOL LEFT ARROW)								
			GO20-2 48x24 8.00 END ROAD WORK		65.730	I-55 SB	2.00	8			
			CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		64.654	I-55 NB	2.00	12			
			GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		64.552	I-55 NB	2.00	10			
			CONST-7 72x36 18.00 RATE OUR WORK ZONE		64.454	I-55 NB	1.00	18			
			R11-2 48x30 10.00 ROAD CLOSED		67.253	I-55 NB	1.00	10			
			CONST-7 72x36 18.00 RATE OUR WORK ZONE		70.251	I-55 SB	1.00	18			
			WO1-6 60x30 12.50 HORIZONTAL ARROW (SYMBOL)		67.253	I-55 NB	2.00	12.5			
			R11-2 48x30 10.00 ROAD CLOSED		67.289	I-55 NB	2.00	10			
			R4-1 36x48 12.00 DO NOT PASS		67.429	I-55 NB	1.00	12			
			WO6-3 48x48 16.00 TWO WAY TRAFFIC (SYMBOL)		67.429	I-55 SB	1.00	16			
			GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		67.429	I-55 NB	1.00	6			
			R4-1 36x48 12.00 DO NOT PASS		67.647	I-55 NB	1.00	12			
			WO6-3 48x48 16.00 TWO WAY TRAFFIC (SYMBOL)		67.647	I-55 SB	1.00	16			
			GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		67.647	I-55 NB	1.00	6			
			WO1-4R 48x48 16.00 REVERSE CURVE (SYMBOL RIGHT ARROW)		67.800	I-55 NB	1.00	16			
			WO13-1 30x30 6.25 ADVISORY SPEED (PLAQUE)		67.800	I-55 NB	1.00	6.25			
			WO1-6 60x30 12.50 HORIZONTAL ARROW (SYMBOL)		67.887	I-55 NB	2.00	12.5			
			R5-1 30x30 6.25 DO NOT ENTER		67.890	I-55 NB	2.00	6.25			
			WO6-3 48x48 16.00 TWO WAY TRAFFIC (SYMBOL)		67.890	I-55 SB	2.00	16			
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		69.286	Rt HH Ramp to I-55 SB	1.00	16			
			CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		69.825	I-55 SB	2.00	12			
			GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		70.031	I-55 SB	2.00	10			
	June 13, 2022	24	R2-1 36x48 12.00 SPEED LIMIT XX		62.117	Rt 62 EB	1.00	12			
			R2-1 36x48 12.00 SPEED LIMIT XX		62.428	Rt 62 WB	1.00	12			
0170 - Total			, v.								15

Revision 3/23/2023 Page 10 of 26



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3643	0050	MISC.	Material	1 3 90	4	May 16, 2022	SYSTEM	\$118,523.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$118,523.17)	Esumate Exception For the Current Fayment Esumate.
					5	Jun 2, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$148,153.96)	
					6	Jun 16, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$148,153.96)	
					7	Jul 1, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$148,153.96)	
					8	Jul 19, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Jul 19, 2022	SYSTEM	(\$148,153.96)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0050 -	Total						\$0.00	
	0060	CONCRETE PAVEMENT (10 1/2 IN. NON- REINF,	Material		11	Sep 2, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		IXLIIVI ,			11	Sep 2, 2022	SYSTEM	(\$55,765.00)	
					12	Sep 16, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$55,765.00)	
					13	Sep 30, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$55,765.00)	
					14	Oct 17, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$55,765.00)	
					15	Nov 2, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$55,765.00)	
					16	Nov 16, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$55,765.00)	
					17	Dec 16, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$55,765.00)	
					18	Jan 17, 2023	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3643	0060	CONCRETE PAVEMENT (10	Material		18	Jan 17, 2023	SYSTEM	(\$55,765.00)	
		1/2 IN. NON- REINF,			19	Feb 2, 2023	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					19	Feb 2, 2023	SYSTEM	(\$55,765.00)	
					20	Feb 16, 2023	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					20	Feb 16, 2023	SYSTEM	(\$55,765.00)	
					21	Mar 1, 2023	SYSTEM	\$111,492.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					21	Mar 1, 2023	SYSTEM	(\$111,492.00)	
					22	Mar 16, 2023	SYSTEM	\$111,492.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					22	Mar 16, 2023	SYSTEM	(\$111,492.00)	
					23	Apr 4, 2023	SYSTEM	\$111,492.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					23	Apr 4, 2023	SYSTEM	(\$111,492.00)	
					24	May 2, 2023	SYSTEM	\$111,492.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					24	May 2, 2023	SYSTEM	(\$111,492.00)	
				- Total				\$0.00	
	0060 -	. Total	Material - To					\$0.00	
	0060 -	CONCRETE APPROACH	Material - To		11	Sep 2, 2022	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Fetimate Exception 9 on the current Payment Estimate
		CONCRETE			11	2022 Sep 2,	SYSTEM	\$0.00 \$0.00	
		CONCRETE APPROACH				2022		\$0.00 \$0.00 \$21,252.00	Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment
		CONCRETE APPROACH			11	2022 Sep 2, 2022 Sep 16,	SYSTEM	\$0.00 \$0.00 \$21,252.00 (\$21,252.00)	Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment
		CONCRETE APPROACH			11 12	2022 Sep 2, 2022 Sep 16, 2022 Sep 16,	SYSTEM	\$0.00 \$0.00 \$21,252.00 (\$21,252.00) \$21,252.00	Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment
		CONCRETE APPROACH			11 12 12	2022 Sep 2, 2022 Sep 16, 2022 Sep 16, 2022 Sep 30,	SYSTEM SYSTEM	\$0.00 \$0.00 \$21,252.00 (\$21,252.00) \$21,252.00 (\$21,252.00)	Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment
		CONCRETE APPROACH			11 12 12 13	2022 Sep 2, 2022 Sep 16, 2022 Sep 16, 2022 Sep 30, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$21,252.00 (\$21,252.00) \$21,252.00 (\$21,252.00) \$21,252.00	Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment
		CONCRETE APPROACH			11 12 12 13	2022 Sep 2, 2022 Sep 16, 2022 Sep 16, 2022 Sep 30, 2022 Sep 30, 2022 Oct 17,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$21,252.00 (\$21,252.00) \$21,252.00 (\$21,252.00) \$21,252.00 (\$21,252.00)	Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment
		CONCRETE APPROACH			11 12 12 13 13 14	2022 Sep 2, 2022 Sep 16, 2022 Sep 30, 2022 Sep 30, 2022 Oct 17, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$21,252.00 (\$21,252.00) \$21,252.00 (\$21,252.00) \$21,252.00 (\$21,252.00)	Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment
		CONCRETE APPROACH			11 12 12 13 13 14 14	2022 Sep 2, 2022 Sep 16, 2022 Sep 30, 2022 Sep 30, 2022 Oct 17, 2022 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$21,252.00 (\$21,252.00) \$21,252.00 (\$21,252.00) \$21,252.00 (\$21,252.00) (\$21,252.00)	Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate.
		CONCRETE APPROACH			11 12 12 13 13 14 14 15	2022 Sep 2, 2022 Sep 16, 2022 Sep 30, 2022 Oct 17, 2022 Nov 2, Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$21,252.00 (\$21,252.00) \$21,252.00 (\$21,252.00) \$21,252.00 (\$21,252.00) \$21,252.00 (\$21,252.00)	Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate.
		CONCRETE APPROACH			11 12 12 13 13 14 14 15 15	2022 Sep 2, 2022 Sep 16, 2022 Sep 16, 2022 Sep 30, 2022 Oct 17, 2022 Nov 2, 2022 Nov 16, 16, 16, 16, 16, 16, 16, 16, 16, 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$21,252.00 (\$21,252.00) \$21,252.00 (\$21,252.00) \$21,252.00 (\$21,252.00) \$21,252.00 (\$21,252.00) \$21,252.00	Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3643	0070	CONCRETE APPROACH	Material			2022			Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
		PAVEMENT			17	Dec 16, 2022	SYSTEM	(\$21,252.00)	
					18	Jan 17, 2023	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					18	Jan 17, 2023	SYSTEM	(\$21,252.00)	
					19	Feb 2, 2023	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					19	Feb 2, 2023	SYSTEM	(\$21,252.00)	
					20	Feb 16, 2023	SYSTEM	\$31,752.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					20	Feb 16, 2023	SYSTEM	(\$31,752.00)	
					21	Mar 1, 2023	SYSTEM	\$42,504.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					21	Mar 1, 2023	SYSTEM	(\$42,504.00)	
					22	Mar 16, 2023	SYSTEM	\$42,504.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					22	Mar 16, 2023	SYSTEM	(\$42,504.00)	
					23	Apr 4, 2023	SYSTEM	\$42,504.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					23	Apr 4, 2023	SYSTEM	(\$42,504.00)	
					24	May 2, 2023	SYSTEM	\$42,504.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					24	May 2, 2023	SYSTEM	(\$42,504.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0070 -	Total						\$0.00	
	0800	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	Material		12	Sep 16, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
		SNDLI()			12	Sep 16, 2022	SYSTEM	(\$3,500.00)	
					13	Sep 30, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$3,500.00)	
					14	Oct 17, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$3,500.00)	
					15	Nov 2, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$3,500.00)	
					16	Nov 16, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					16	Nov 16,	SYSTEM	(\$3,500.00)	



et	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
13	0800	CONCRETE	Material			2022			
		CURB (6 IN. HEIGHT AND UNDER)			17	Dec 16, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$3,500.00)	
					18	Jan 17, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					18	Jan 17, 2023	SYSTEM	(\$3,500.00)	
					19	Feb 2, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					19	Feb 2, 2023	SYSTEM	(\$3,500.00)	
					20	Feb 16, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					20	Feb 16, 2023	SYSTEM	(\$3,500.00)	
					21	Mar 1, 2023	SYSTEM	\$6,980.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					21	Mar 1, 2023	SYSTEM	(\$6,980.00)	
					22	Mar 16, 2023	SYSTEM	\$6,980.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					22	Mar 16, 2023	SYSTEM	(\$6,980.00)	
					23	Apr 4, 2023	SYSTEM	\$6,980.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					23	Apr 4, 2023	SYSTEM	(\$6,980.00)	
					24	May 2, 2023	SYSTEM	\$6,980.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					24	May 2, 2023	SYSTEM	(\$6,980.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0080 -	Total						\$0.00	
	0090	FURNISHING TYPE 1 ROCK DITCH LINER	Material		24	May 2, 2023	SYSTEM	\$2,115.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Paymen Estimate Exception 18 on the current Payment Estimate.
					24	May 2, 2023	SYSTEM	(\$2,115.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0090 -	Total						\$0.00	
	0110	FURNISHING TYPE 2 ROCK BLANKET	Material		14	Oct 17, 2022	SYSTEM	\$17,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Paymen Estimate Exception 15 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$17,000.00)	
					15	Nov 2, 2022	SYSTEM	\$17,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Paymen Estimate Exception 15 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$17,000.00)	
					16	Nov 16, 2022	SYSTEM	\$17,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
43	0110	FURNISHING TYPE 2 ROCK	Material		16	Nov 16, 2022	SYSTEM	(\$17,000.00)	
		BLANKET			17	Dec 16, 2022	SYSTEM	\$17,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$17,000.00)	
					18	Jan 17, 2023	SYSTEM	\$17,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					18	Jan 17, 2023	SYSTEM	(\$17,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0110 -	Total						\$0.00	
	0130	IMPACT ATTENUATOR 70 MPH (SAND	Material		5	Jun 2, 2022	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		BARREL ARRAY)			5	Jun 2, 2022	SYSTEM	(\$4,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0130 -	Total						\$0.00	
	0160	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	Material		13	Sep 30, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
		(TWA)			13	Sep 30, 2022	SYSTEM	(\$5,000.00)	
					14	Oct 17, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$5,000.00)	
					15	Nov 2, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$5,000.00)	
					16	Nov 16, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$5,000.00)	
					17	Dec 16, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$5,000.00)	
					18	Jan 17, 2023	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					18	Jan 17, 2023	SYSTEM	(\$5,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0160 -	Total						\$0.00	
	0180	ADVANCED WARNING RAIL SYSTEM	Material		2	Apr 15, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Apr 15, 2022	SYSTEM	(\$100.00)	
					3	May 2, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
913643	0180	ADVANCED WARNING RAIL	Material		3	May 2, 2022	SYSTEM	(\$100.00)										
		SYSTEM			4	May 16, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.									
					4	May 16, 2022	SYSTEM	(\$100.00)										
				- Total				\$0.00										
			Material - To	tal				\$0.00										
	0180 -	Total						\$0.00										
	0190	CHANNELIZER (TRIM LINE)	Material		2	Apr 15, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.									
					2	Apr 15, 2022	SYSTEM	(\$2,244.00)										
					3	May 2, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.									
					3	May 2, 2022	SYSTEM	(\$2,244.00)										
				4	4	May 16, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.									
					4	May 16, 2022	SYSTEM	(\$2,244.00)										
				- Total				\$0.00										
			Material - To	tal				\$0.00										
	0190 -	- Total						\$0.00										
	0210	DIRECTIONAL INDICATOR BARRICADE	Material		2	Apr 15, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.									
					2	Apr 15, 2022	SYSTEM	(\$2,340.00)										
					3	May 2, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.									
						3	May 2, 2022	SYSTEM	(\$2,340.00)									
							4	2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.							
					4	May 16, 2022	SYSTEM	(\$2,340.00)										
				- Total				\$0.00										
			Material - To	tal				\$0.00										
	0210 -	Total						\$0.00										
	0220	FLASHING ARROW PANEL	Material		2	Apr 15, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.									
					2	Apr 15, 2022	SYSTEM	(\$3,000.00)										
														3	May 2, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$3,000.00)										
				4	May 16, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.										
					4	May 16, 2022	SYSTEM	(\$3,000.00)										
				- Total				\$0.00										
			Material - To	tal				\$0.00										
	0220 -	Total						\$0.00										



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
643	0250	CMS W/O COMMUNICATION INTERFACE,	Material		2	Apr 15, 2022	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		CONT F/			2	Apr 15, 2022	SYSTEM	(\$9,600.00)	
					3	May 2, 2022	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$9,600.00)	
					4	May 16, 2022	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$9,600.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0250 -	Total						\$0.00	
	0270	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material		5	Jun 2, 2022	SYSTEM	\$11,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		FURIV/RE			5	Jun 2, 2022	SYSTEM	(\$11,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0270 -	Total						\$0.00	
	0310	TEMPORARY REMOVABLE MARKING TAPE 4	Material		6	Jun 16, 2022	SYSTEM	\$2,706.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		IN.,			6	Jun 16, 2022	SYSTEM	(\$2,706.00)	
					7	Jul 1, 2022	SYSTEM	\$4,462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$4,462.00)	
					8	Jul 19, 2022	SYSTEM	\$4,462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Jul 19, 2022	SYSTEM	(\$4,462.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0310 -	Total						\$0.00	
	0320	TEMPORARY REMOVABLE MARKING TAPE	Material		6	Jun 16, 2022	SYSTEM	\$7,416.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$7,416.00)	
					7	Jul 1, 2022	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$12,180.00)	
					8	Jul 19, 2022	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Paymen Estimate Exception 4 on the current Payment Estimate.
					8	Jul 19, 2022	SYSTEM	(\$12,180.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0320 -	Total						\$0.00	
	0390	TEMPORARY PAVEMENT	Material		6	Jun 16, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
643	0390	MARKING	Material						Estimate Exception 5 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$6,062.25)	
					7	Jul 1, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$6,062.25)	
					8	Jul 19, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Jul 19, 2022	SYSTEM	(\$6,062.25)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0390 -	Total						\$0.00	
	0450	MGS GUARDRAIL	Material		12	Sep 16, 2022	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$8,000.00)	
					13	Sep 30, 2022	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$8,000.00)	
					14	Oct 17, 2022	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$8,000.00)	
					15	Nov 2, 2022	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$8,800.00)	
					16	Nov 16, 2022	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$8,800.00)	
					17	Dec 16, 2022	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$8,800.00)	
					18	Jan 17, 2023	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					18	Jan 17, 2023	SYSTEM	(\$8,800.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0450 -	Total						\$0.00	
	0460	MGS BRIDGE APP. TRANS SEC (EXT CURB)	Material		12	Sep 16, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$12,000.00)	
					13	Sep 30, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$12,000.00)	
					14	Oct 17,	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks								
				Туре	Number		Бу										
J9I3643	0460	MGS BRIDGE APP. TRANS SEC (EXT CURB)	Material			2022			Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.								
		(EXT COND)			14	Oct 17, 2022	SYSTEM	(\$12,000.00)									
					15	Nov 2, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.								
					15	Nov 2, 2022	SYSTEM	(\$12,000.00)									
					16	Nov 16, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.								
					16	Nov 16, 2022	SYSTEM	(\$12,000.00)									
					17	Dec 16, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.								
					17	Dec 16, 2022	SYSTEM	(\$12,000.00)									
					18	Jan 17, 2023	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.								
					18	Jan 17, 2023	SYSTEM	(\$12,000.00)									
				- Total				\$0.00									
			Material - To	tal				\$0.00									
	0460 -	Total						\$0.00									
	0490	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		11	Sep 2, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.								
					11	Sep 2, 2022	SYSTEM	(\$78,020.00)									
					12	Sep 16, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.								
					12	Sep 16, 2022	SYSTEM	(\$78,020.00)									
					13	Sep 30, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.								
					13	Sep 30, 2022	SYSTEM	(\$78,020.00)									
					1	14	Oct 17, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.							
													14	Oct 17, 2022	SYSTEM	(\$78,020.00)	
											15	Nov 2, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
									15	Nov 2, 2022	SYSTEM	(\$78,020.00)					
					16	Nov 16, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.								
					16	Nov 16, 2022	SYSTEM	(\$78,020.00)									
					17	Dec 16, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.								
					17	Dec 16, 2022	SYSTEM	(\$78,020.00)									
					18	Jan 17, 2023	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.								
				18	Jan 17,	SYSTEM	(\$78,020.00)										



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3643	0490	BRIDGE	Material			2023			
		APPROACH SLAB (MAJOR ROAD)			19	Feb 2, 2023	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					19	Feb 2, 2023	SYSTEM	(\$78,020.00)	
					20	Feb 16, 2023	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					20	Feb 16, 2023	SYSTEM	(\$78,020.00)	
					21	Mar 1, 2023	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					21	Mar 1, 2023	SYSTEM	(\$78,020.00)	
					22	Mar 16, 2023	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					22	Mar 16, 2023	SYSTEM	(\$78,020.00)	
					23	Apr 4, 2023	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					23	Apr 4, 2023	SYSTEM	(\$78,020.00)	
				24	May 2, 2023	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					24	May 2, 2023	SYSTEM	(\$78,020.00)	
				- Total				\$0.00	
			Material - To	tol				\$0.00	
			Material - 10	lai				\$0.00	
	0490 -	Total	Material - 10	Lai				\$0.00	
	0490 - 0500	Total SLAB ON STEEL		tai	10	Aug 17, 2022	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				tai	10		SYSTEM SYSTEM	\$0.00	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment
				Lai		2022 Aug 17,		\$0.00 \$710,325.00	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment
				iai	10	2022 Aug 17, 2022 Sep 2,	SYSTEM	\$0.00 \$710,325.00 (\$710,325.00)	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment
				lai	10	2022 Aug 17, 2022 Sep 2, 2022 Sep 2,	SYSTEM SYSTEM	\$0.00 \$710,325.00 (\$710,325.00) \$710,325.00 (\$710,325.00)	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment
				lai	10 11 11	2022 Aug 17, 2022 Sep 2, 2022 Sep 2, 2022 Sep 16,	SYSTEM SYSTEM SYSTEM	\$0.00 \$710,325.00 (\$710,325.00) \$710,325.00 (\$710,325.00)	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment
				lai	10 11 11 12	2022 Aug 17, 2022 Sep 2, 2022 Sep 16, 2022 Sep 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$710,325.00 (\$710,325.00) \$710,325.00 (\$710,325.00) \$710,325.00	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment
				lai	10 11 11 12 12	2022 Aug 17, 2022 Sep 2, 2022 Sep 16, 2022 Sep 16, 2022 Sep 16, 2022 Sep 30,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$710,325.00 (\$710,325.00) \$710,325.00 (\$710,325.00) \$710,325.00	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment
				lai	10 11 11 12 12 13	2022 Aug 17, 2022 Sep 2, 2022 Sep 16, 2022 Sep 16, 2022 Sep 30, 2022 Sep 30, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$710,325.00 (\$710,325.00) \$710,325.00 (\$710,325.00) \$710,325.00 (\$710,325.00)	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment
				lai	10 11 11 12 12 13	2022 Aug 17, 2022 Sep 2, 2022 Sep 16, 2022 Sep 16, 2022 Sep 30, 2022 Oct 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$710,325.00 (\$710,325.00) \$710,325.00 (\$710,325.00) \$710,325.00 (\$710,325.00) (\$710,325.00)	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate.
				lai	10 11 11 12 12 13 13	2022 Aug 17, 2022 Sep 2, 2022 Sep 16, 2022 Sep 16, 2022 Sep 30, 2022 Oct 17, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$710,325.00 (\$710,325.00) \$710,325.00 (\$710,325.00) \$710,325.00 (\$710,325.00) (\$710,325.00) \$710,325.00	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate.
					10	2022 Aug 17, 2022 Sep 2, 2022 Sep 16, 2022 Sep 16, 2022 Sep 30, 2022 Oct 17, 2022 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$710,325.00 (\$710,325.00) \$710,325.00 (\$710,325.00) \$710,325.00 (\$710,325.00) \$710,325.00 (\$710,325.00)	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3643	0500	SLAB ON STEEL	Material						Estimate Exception 17 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$710,325.00)	
					17	Dec 16, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$710,325.00)	
					18	Jan 17, 2023	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					18	Jan 17, 2023	SYSTEM	(\$710,325.00)	
					19	Feb 2, 2023	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					19	Feb 2, 2023	SYSTEM	(\$710,325.00)	
					20	Feb 16, 2023	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					20	Feb 16, 2023	SYSTEM	(\$710,325.00)	
					21	Mar 1, 2023	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					21	Mar 1, 2023	SYSTEM	(\$710,325.00)	
					22	Mar 16, 2023	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					22	Mar 16, 2023	SYSTEM	(\$710,325.00)	
					23	Apr 4, 2023	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					23	Apr 4, 2023	SYSTEM	(\$710,325.00)	
					24	May 2, 2023	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					24	May 2, 2023	SYSTEM	(\$710,325.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0500 - 0510	TYPE D BARRIER	Material		12	Sep 16, 2022	SYSTEM	\$0.00 \$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$64,170.00)	,
					13	Sep 30, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$64,170.00)	
					14	Oct 17, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$64,170.00)	
					15	Nov 2, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$64,170.00)	



ct l	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
13 0	0510	TYPE D BARRIER	Material		16	Nov 16, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$64,170.00)	
					17	Dec 16, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$64,170.00)	
					18	Jan 17, 2023	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					18	Jan 17, 2023	SYSTEM	(\$64,170.00)	
					19	Feb 2, 2023	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					19	Feb 2, 2023	SYSTEM	(\$64,170.00)	
					20	Feb 16, 2023	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					20	Feb 16, 2023	SYSTEM	(\$64,170.00)	
					21	Mar 1, 2023	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Paymen Estimate Exception 25 on the current Payment Estimate.
					21	Mar 1, 2023	SYSTEM	(\$64,170.00)	
					22	Mar 16, 2023	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Paymen Estimate Exception 23 on the current Payment Estimate.
					22	Mar 16, 2023	SYSTEM	(\$64,170.00)	
					23	Apr 4, 2023	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Paymen Estimate Exception 23 on the current Payment Estimate.
					23	Apr 4, 2023	SYSTEM	(\$64,170.00)	
					24	May 2, 2023	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Paymen Estimate Exception 23 on the current Payment Estimate.
					24	May 2, 2023	SYSTEM	(\$64,170.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0 510 - 0540	SLAB DRAIN	Material		9	Aug 2, 2022	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Paymen
					9	Aug 2, 2022	SYSTEM	(\$9,000.00)	Estimate Exception 2 on the current Payment Estimate.
					10	Aug 17, 2022	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Paymen Estimate Exception 5 on the current Payment Estimate.
					10	Aug 17, 2022	SYSTEM	(\$9,000.00)	,
					11	Sep 2, 2022	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Paymen Estimate Exception 16 on the current Payment Estimate.
					11	Sep 2,	SYSTEM	(\$9,000.00)	
						2022			
				- Total		2022		\$0.00	
			Material - To			2022		\$0.00 \$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J9I3643	0620	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		19	Feb 2, 2023	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					19	Feb 2, 2023	SYSTEM	(\$78,020.00)					
					20	Feb 16, 2023	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					20	Feb 16, 2023	SYSTEM	(\$78,020.00)					
					21	Mar 1, 2023	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					21	Mar 1, 2023	SYSTEM	(\$78,020.00)					
					22	Mar 16, 2023	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					22	Mar 16, 2023	SYSTEM	(\$78,020.00)					
					23	Apr 4, 2023	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
					23	Apr 4, 2023	SYSTEM	(\$78,020.00)					
									24	May 2, 2023	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					24	May 2, 2023	SYSTEM	(\$78,020.00)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	0620 -							\$0.00					
	0630	SLAB ON STEEL	Construction Stockpile		16	Nov 16, 2022	SYSTEM	(\$21,103.97)	Payment Estimate Item Adjustment generated Stockpile Transaction				
					17	Dec 16, 2022	SYSTEM	(\$11,995.95)	Payment Estimate Item Adjustment generated Stockpile Transaction				
					18	Jan 17, 2023	SYSTEM	(\$11,995.94)	Payment Estimate Item Adjustment generated Stockpile Transaction				
					21	Mar 1, 2023	SYSTEM	(\$15,017.14)	Payment Estimate Item Adjustment generated Stockpile Transaction				
				- Total	- Total		(\$60,113.00)						
			Construction Stockpile	Stockpile - 1	Total			(\$60,113.00)					
					15	Nov 2, 2022	SYSTEM	\$60,113.00	Payment Estimate Item Adjustment generated Stockpile Transaction				
			STMI	- Total				\$60,113.00					
			Construction	Stockpile S1	MI - Total			\$60,113.00					
			Material		16	Nov 16, 2022	SYSTEM	\$249,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.				
					16	Nov 16, 2022	SYSTEM	(\$249,375.00)					
					17	Dec 16, 2022	SYSTEM	\$391,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.				
					17	Dec 16, 2022	SYSTEM	(\$391,125.00)					
					18	Jan 17, 2023	SYSTEM	\$532,875.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.				
					18	Jan 17, 2023	SYSTEM	(\$532,875.00)					
					19	Feb 2, 2023	SYSTEM	\$532,875.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.				



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks	
rioject	LIIIC	Безеприон	Туре	Adjustment Type	Number	Date	By	Amount	Kemarie	
J9I3643	0630	SLAB ON STEEL	Material		19	Feb 2, 2023	SYSTEM	(\$532,875.00)		
					20	Feb 16, 2023	SYSTEM	\$532,875.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
					20	Feb 16, 2023	SYSTEM	(\$532,875.00)		
					21	Mar 1, 2023	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
					21	Mar 1, 2023	SYSTEM	(\$710,325.00)		
					22	Mar 16, 2023	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
					22	Mar 16, 2023	SYSTEM	(\$710,325.00)		
					23	Apr 4, 2023	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
					23	Apr 4, 2023	SYSTEM	(\$710,325.00)		
					24	May 2, 2023	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	
					24	May 2, 2023	SYSTEM	(\$710,325.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0630 -	Total						\$0.00		
	0640	TYPE D BARRIER	Material	terial	20	Feb 16, 2023	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	
					20	Feb 16, 2023	SYSTEM	(\$64,170.00)		
					21	Mar 1, 2023	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	
					21	Mar 1, 2023	SYSTEM	(\$64,170.00)		
					22	Mar 16, 2023	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	
					22	Mar 16, 2023	SYSTEM	(\$64,170.00)		
						23	Apr 4, 2023	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
							23	Apr 4, 2023	SYSTEM	(\$64,170.00)
					24	May 2, 2023	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	
					24	May 2, 2023	SYSTEM	(\$64,170.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
								\$0.00		
	0640 -	Total								
	0640 - 5002	SEQUENTIAL FLASHING WARNING LIGHT	Material		4	May 16, 2022	SYSTEM	\$4,347.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
		SEQUENTIAL FLASHING	Material		4		SYSTEM SYSTEM	\$4,347.00 (\$4,347.00)	Estimate Item Adjustment (0007) due to user leez1 overridding Payment	
		SEQUENTIAL FLASHING	Material	- Total		2022 May 16,			Estimate Item Adjustment (0007) due to user leez1 overridding Payment	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J9I3643	5002 -	Total						\$0.00		
	5003	TEMPORARY SEEDING	Material		5	Jun 2, 2022	SYSTEM	\$2,830.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					5	Jun 2, 2022	SYSTEM	(\$2,830.48)		
					6	Jun 16, 2022	SYSTEM	\$2,830.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					6	Jun 16, 2022	SYSTEM	(\$2,830.48)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	5003 -	Total						\$0.00		
	5005	SEEDING - COOL SEASON GRASSES	Material	Material		24	May 2, 2023	SYSTEM	\$2,773.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					24	May 2, 2023	SYSTEM	(\$2,773.70)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	5005 -	Total						\$0.00		
J9I3643 -	Total							\$0.00		
Overall -	Total							\$0.00		

MoDOT

Contract Adjustments for Contract - 220121-H01

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 26 of 26