

Pay Estimate Created Date: June 16, 2022

Progress Estimate N 6	umber	Contract ID Prime Contractor	220121-H01 Robertson Contra	actors, Inc.			Original Contract Amount Net Change Order Amount Current Contract Amount	\$3,635,384.06 \$44,086.60 \$3,679,470.66
Approval Date								By User
June 16, 2022			Generated and A	Approved (a	and should be consi	dered Draft) a	the Project Office Level by	leez1
June 16, 2022		Re	eviewed and Appro	ved (and s	hould be considered	d Draft) at the	Resident Engineer Level by	bollis1
June 17, 2022			I	Reviewed a	and Approved at the	Central Office	Controllers Office Level by	ramses1
Original Completion	n Date	Current Con	npletion Date	Actua	al Completion Date	%	of Current Contract Amount	t Complete
May 1, 2023		May 1	, 2023				17.67%	
	Contrac	t Informational Dat	tes		Milesto	nes		
Date Description	Origina	I Completion Date	Current Complet	tion Date	No Milestones Exi	st for Contract		
Acceptance Date								
Awarded Date	Februar	y 2, 2022	February 2, 2022					
Letting Date	January	21, 2022	January 21, 2022					
Notice to Proceed Date	April 4, 2	2022	April 4, 2022					
Open to Traffic Date								
Work Began Date	April 11,	2022	April 11, 2022					

Contract Total Pay For Estimate No. 6				
	This Estimate	Previous	To Date	
220121-H01				
Total Posted Items Pay	\$116,447.45	\$533,747.44	\$650,194.89	
Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
		<mark>\$533,747.44</mark>	\$650,194.89	
Contract Total Payable This Estimate:	\$116,447.45			

Contract Total Payable This Estimate: Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9I3643	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$15,000.000	0.25	\$3,750.00
	0130	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	EA	\$2,000.000	1	\$2,000.0
	0170	6161005	CONSTRUCTION SIGNS	SQFT	\$6.500	887	\$5,765.5
	0190	6161025	CHANNELIZER (TRIM LINE)	EA	\$17.000	200	\$3,400.0
	0200	6161030	TYPE III MOVEABLE BARRICADE	EA	\$145.000	15	\$2,175.0
	0220	6161040	FLASHING ARROW PANEL	EA	\$1,500.000	1	\$1,500.0
	0240	6161070	TUBULAR MARKER	EA	\$35.000	220	\$7,700.0
	0260	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	EA	\$800.000	8	\$6,400.0
	0270	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	LF	\$40.000	100	\$4,000.0
	0310	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	LF	\$2.000	1,353	\$2,706.0
	0320	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	LF	\$2.000	3,708	\$7,416.0
	0380	6207001	PAVEMENT MARKING REMOVAL	LF	\$0.500	5,507	\$2,753.5
	0390	6208063	TEMPORARY PAVEMENT MARKING	EA	\$0.250	24,249	\$6,062.2
	0480	2162500	REMOVAL OF EXISTING BRIDGE DECK	SQFT	\$14.000	4,322.8	\$60,519.2
	5004	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	EA	\$50.000	6	\$300.0
Project J9I3	643 - Total						\$116,447.4
Overall - To	otal						\$116,447.4

Pay Estimate Created Date: June 16, 2022

Progr	ress Es	timate Number 6	Contract ID Prime Cont		21-H01 rtson Contrac	Pay Period Start June 2, 2022 Orig tors, Inc. Pay Period End June 15, 2022 Net Cur		er Amount	\$3,635,384.06 \$44,086.60 \$3,679,470.66
ne Item	Adjust	ments This Estim	nate						
Project Number	Line No.	Item Descr	ription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
913643	0050		MISC.	Material			-2,932	\$50.53	(\$148,153.96
	0050		MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	2,932	\$50.53	\$148,153.96
	0310	TEMPORARY R MARKING	EMOVABLE TAPE 4 IN., WHITE	Material			-1,353	\$2.00	(\$2,706.00
	0310	TEMPORARY R MARKING	EMOVABLE TAPE 4 IN., WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1,353	\$2.00	\$2,706.00
	0320	TEMPORARY R MARKING	EMOVABLE TAPE 4 IN., YELLOW	Material			-3,708	\$2.00	(\$7,416.00
	0320	TEMPORARY R MARKING	EMOVABLE TAPE 4 IN., YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	3,708	\$2.00	\$7,416.00
	0390	TEMPORARY	PAVEMENT MARKING	Material			-24,249	\$0.25	(\$6,062.25
	0390	TEMPORARY	PAVEMENT MARKING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	24,249	\$0.25	\$6,062.25
	5003	TEMPORAR	Y SEEDING	Material			-0.5	\$5,660.95	(\$2,830.48
	5003	TEMPORAR	RY SEEDING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	0.5	\$5,660.95	\$2,830.48
otal									\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	Contract Project Informatic	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9I3643	l 55-1(176)	2 bridge deck replacement	I-55	SCOTT	over Route 62		
Totals by .	Job Numbe	rs					
J9I3643					This Estimate	Previous	To Date

	This Estimate	Previous	To Date
Posted Item Pay	\$116,447.45	\$533,747.44	\$650,194.89
Gross Item Adjustments	\$0.00	\$0.00	\$0.00
Gross Item Pay	\$116,447.45	\$533,747.44	\$650,194.89
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 4019905, Project Item Line Number 0050, Material Set 401990596, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 4019905, Project Item Line Number 0050, Material Set 401990596, Material 0403SP190CLG - Superpave 19.0 mm, Des C 80 Gyros, Acceptance Action AspHigh Temporary Crossing is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 6205301B, Project Item Line Number 0310, Material Set 6205301B96, Material 1048PMRPMTWH - Marking Tape Removable White, Acceptance Action Generic 1048PMRPMTWH is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 6205303B, Project Item Line Number 0320, Material Set 6205303B96, Material 1048PMRPMTYL - Marking Tape Removable Yellow, Acceptance Action Generic 1048PMRPMTYL is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 6208063, Project Item Line Number 0390, Material Set 6208063, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 8061017, Project Item Line Number 5003, Material Set 806101796, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 8061017, Project Item Line Number 5003, Material Set 806101796, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 8061017, Project Item Line Number 5003, Material Set 806101796, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	No Remark was entered by Engineer	leez1	Overridden

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

ed date and can differ from the posted amount at the time the Estimate was Generated. Note: Posted (

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See report generated date)
220121-H01	J9I3643	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.25	\$15,000.00	\$3,750.0
		0001	0020	2071000	LINEAR GRADING CLASS 1	4.40	0.00	4.40	STA	0.00	\$2,600.00	\$0.0
		0001	0030	2072000	LINEAR GRADING CLASS 2	32.40	0.00	32.40	STA	32.40	\$3,850.00	\$124,740.
		0001	0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,174.00	0.00	1,174.00	SQYD	0.00	\$15.00	\$0.
		0001	0050	4019905	MISC.Optional Pavement	2,932.00	0.00	2,932.00	SQYD	2,932.00	\$50.53	\$148,153.
		0001	0060	5021334	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	1,173.60	0.00	1,173.60	SQYD	0.00	\$95.00	\$0.
		0001	0070	5041000	CONCRETE APPROACH PAVEMENT	404.80	0.00	404.80	SQYD	0.00	\$105.00	\$0.
		0001	0080	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	349.00	0.00	349.00	LF	0.00	\$20.00	\$0.
		0001	0090	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	47.00	0.00	47.00	CUYD	0.00	\$45.00	\$0.
		0001	0100	6096041	PLACING TYPE 1 ROCK DITCH LINER	47.00	0.00	47.00	CUYD	0.00	\$80.00	\$0.
		0001	0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	853.00	0.00	853.00	CUYD	0.00	\$40.00	\$0.
		0001	0120	6113040	PLACING TYPE 2 ROCK BLANKET	853.00	0.00	853.00	CUYD	0.00	\$25.00	\$0.
		0001	0130	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	2.00	1.00	3.00	EA	3.00	\$2,000.00	\$6,000.
		0001	0140	6122020	REPLACEMENT SAND BARREL	6.00	0.00	6.00	EA	0.00	\$250.00	\$0.
		0001	0150	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	1.00	3.00	EA	0.00	\$1,000.00	\$0.
		0001	0160	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	0.00	\$5,000.00	\$0.
		0001	0170	6161005	CONSTRUCTION SIGNS	2,140.00	0.00	2,140.00	SQFT	1,560.00	\$6.50	\$10,140.
		0001	0180	6161008	ADVANCED WARNING RAIL SYSTEM	18.00	0.00	18.00	EA	4.00	\$25.00	\$100.
		0001	0190	6161025	CHANNELIZER (TRIM LINE)	500.00	0.00	500.00	EA	332.00	\$17.00	\$5,644
		0001	0200	6161030	TYPE III MOVEABLE BARRICADE	21.00	0.00	21.00	EA	15.00	\$145.00	\$2,175
		0001	0210	6161033	DIRECTIONAL INDICATOR BARRICADE	100.00	0.00	100.00	EA	36.00	\$65.00	\$2,340.
		0001	0220	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	3.00	\$1,500.00	\$4,500.
		0001	0230	6161052	WARNING LIGHT, TYPE B	50.00	0.00	50.00	EA	0.00	\$15.00	\$0.
		0001	0240	6161070	TUBULAR MARKER	650.00	0.00	650.00	EA	220.00	\$35.00	\$7,700.
		0001	0250	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$4,800.00	\$19,200.
		0001	0260	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	16.00	0.00	16.00	EA	8.00	\$800.00	\$6,400.
		0001	0270	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	451.00	100.00	551.00	LF	375.00	\$40.00	\$15,000.
		0001	0280	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	451.00	100.00	551.00	LF	0.00	\$35.00	\$0
		0001	0290	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$225,000.00	\$0.
		0001	0291	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.50	\$200,165.00	\$100,082.
		0001	0300	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	10.00	0.00	10.00	EA	0.00	\$250.00	\$0.
		0001	0310	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	3,645.00	0.00	3,645.00	LF	1,353.00	\$2.00	\$2,706
		0001	0320	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	6,090.00	0.00	6,090.00	LF	3,708.00	\$2.00	\$7,416.
		0001	0330	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,705.00	27,660.00	30,365.00	LF	0.00	\$0.30	\$0.
		0001	0340	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,774.00	19,126.00	20,900.00	LF	0.00	\$0.30	\$0.
		0001	0350	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	13,177.00	-13,177.00	0.00	LF	0.00	\$0.15	\$0
		0001	0360	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6,704.00	-6,704.00	0.00	LF	0.00	\$0.15	\$0
		0001	0370	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	75.00	-75.00	0.00	LF	0.00	\$5.00	\$0
		0001	0380	6207001	PAVEMENT MARKING REMOVAL	50,359.00	0.00	50,359.00	LF	5,507.00	\$0.50	\$2,753
		0001	0390	6208063	TEMPORARY PAVEMENT MARKING	34,359.00	0.00	34,359.00	EA	24,249.00	\$0.25	\$6,062
		0001	0400	6240102A	TEMPORARY SILT FENCE GEOTEXTILE	1,040.00	0.00	1,040.00	SQYD	0.00	\$1.50	\$0
		0001	0410	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,689.00	0.00	1,689.00	SQYD	0.00	\$4.00	\$0.
		0001	0420	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$20,000.00	\$0.
		0001	0430	7250312A	12 IN. PIPE GROUP B	1,100.00	0.00	1,100.00	LF	1,100.00	\$50.00	\$55,000.

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

te: Posted Q	uantities			based on F	Report Generated date and can differ from the posted an		e time the E					
Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
0121-H01	J9I3643	0001	0440	8061016	SEDIMENT REMOVAL	10.00	0.00	10.00	CUYD	0.00	\$1.00	\$0.00
		0010	0450	6061060	MGS GUARDRAIL	100.00	315.00	415.00	LF	0.00	\$40.00	\$0.00
		0010	0460	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	6.00	0.00	6.00	EA	0.00	\$4,000.00	\$0.00
		0010	0470	6069901	MISC.Remove and Reinstall High-Tension Gurad Cable	1.00	0.00	1.00	LS	0.50	\$55,000.00	\$27,500.00
		0070	0480	2162500	REMOVAL OF EXISTING BRIDGE DECK	11,771.00	0.00	11,771.00	SQFT	4,322.80	\$14.00	\$60,519.20
		0070	0490	5031010A	BRIDGE APPROACH SLAB (MAJOR)	188.00	0.00	188.00	SQYD	0.00	\$415.00	\$0.00
		0070	0500	7034212	SLAB ON STEEL	1,353.00	0.00	1,353.00	SQYD	0.00	\$525.00	\$0.00
		0070	0510	7034219A	TYPE D BARRIER	558.00	0.00	558.00	LF	0.00	\$115.00	\$0.00
		0070	0520	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0070	0530	7121159	SHEAR CONNECTORS	1,800.00	0.00	1,800.00	EA	0.00	\$15.50	\$0.00
		0070	0540	7123610	SLAB DRAIN	20.00	0.00	20.00	EA	0.00	\$450.00	\$0.00
		0070	0550	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	12,100.00	0.00	12,100.00	SQFT	0.00	\$9.50	\$0.00
		0070	0560	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	12,100.00	0.00	12,100.00	SQFT	0.00	\$2.50	\$0.00
		0070	0570	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	12,100.00	0.00	12,100.00	SQFT	0.00	\$1.50	\$0.00
		0070	0580	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$3.00	\$0.00
		0070	0590	7126000	NON-DESTRUCTIVE TESTING	109.00	0.00	109.00	LF	0.00	\$45.00	\$0.00
		0070	0600	7172054	OPEN CELL FOAM JOINT SEAL	87.00	0.00	87.00	LF	0.00	\$80.00	\$0.00
		0071	0610	2162500	REMOVAL OF EXISTING BRIDGE DECK	11,771.00	0.00	11,771.00	SQFT	0.00	\$14.00	\$0.00
		0071	0620	5031010A	BRIDGE APPROACH SLAB (MAJOR)	188.00	0.00	188.00	SQYD	0.00	\$415.00	\$0.00
		0071	0630	7034212	SLAB ON STEEL	1,353.00	0.00	1,353.00	SQYD	0.00	\$525.00	\$0.00
		0071	0640	7034219A	TYPE D BARRIER	558.00	0.00	558.00	LF	0.00	\$115.00	\$0.00
		0071	0650	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0071	0660	7121159	SHEAR CONNECTORS	1,800.00	0.00	1,800.00	EA	0.00	\$15.50	\$0.00
		0071	0670	7123610	SLAB DRAIN	18.00	0.00	18.00	EA	0.00	\$450.00	\$0.00
		0071	0680	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	12,100.00	0.00	12,100.00	SQFT	0.00	\$9.50	\$0.00
		0071	0690	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	12,100.00	0.00	12,100.00	SQFT	0.00	\$2.50	\$0.00
		0071	0700	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	12,100.00	0.00	12,100.00	SQFT	0.00	\$1.50	\$0.00
		0071	0710	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$3.00	\$0.00
		0071	0720	7126000	NON-DESTRUCTIVE TESTING	109.00	0.00	109.00	LF	0.00	\$45.00	\$0.00
		0071	0730	7172054	OPEN CELL FOAM JOINT SEAL	87.00	0.00	87.00	LF	0.00	\$80.00	\$0.00
		0001	5001	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$24,835.00	\$24,835.00
		0001	5002	6161055	SEQUENTIAL FLASHING WARNING LIGHT	0.00	36.00	36.00	EA	36.00	\$120.75	\$4,347.00
		0001	5003	8061017	TEMPORARY SEEDING	0.00	1.00	1.00	ACRE	0.50	\$5,660.95	\$2,830.48
		0001	5004	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	0.00	6.00	6.00	EA	6.00	\$50.00	\$300.00
	Project .	1913643 - To	otal Value	Posted to D	Date as of Report Generated Date							\$650,194.88
0121-H01 Ove	erall - Tota	I Value Pos	sted to Da	ate as of Rep	port Generated Date							\$650,194.88



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line lumber	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/Log Mile	Offset/ Distance	To Station/Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	6/13/22	6/16/22	0.25	LS	South approach pavement of NB bridge	1364+75		1365+81		
0130	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL	6/2/22	6/16/22	1.00	EA	I-55 SB	67.410				Sand Barrel Array at SB Bridge end
0170	0404005	ARRAY) CONSTRUCTION SIGNS	0.00/000	0/40/00	400.00	SQFT	Rte 62 EB and WB	00.005		67.982		Route 62 East Log Miles are used
0170	0101005	CONSTRUCTION SIGNS	6/2/22	6/16/22 6/16/22	126.00 249.00		Route H Detour	66.905		67.982		I-55 Detour Signs using Route H and Route 62 Log mile
				6/16/22	488.00		I-55 Head to Head Traffic in the SBL	66.905		67.982		100 Detodi olgris daling rodite ri and rodite oz Eog mile
			6/13/22				Route 62 Under I-55	62.428		62.117		Log Miles are in Route 62 E
0190	6161025	CHANNELIZER (TRIM LINE)	6/2/22	6/16/22	200.00		I-55 and Route 62	66.905		67.982		Channelizers for Route 62 lane delineation.
0200	6161030	TYPE III MOVEABLE BARRICADE	6/2/22		2.00		I-55 NB at Exit Ramp Crossover	67.289				
				6/16/22	3.00	EA	I-55 NB at Exit Ramp Crossover	67.253				
				6/16/22	3.00	EA	I-55 NB at far south crossover	66.991				
				6/16/22	3.00	EA	Route 62 to I-55 NB Ramp	62.281				
									62 Log Miles			
				6/16/22	4.00	EA	I-55 at far north crossover	67.887				
0220	6161040	FLASHING ARROW PANEL	6/2/22	6/16/22	1.00	EA	Route 62 at I-55 SB Ramps	62.121				Route 62 East Log Mile Used
0240	6161070	TUBULAR MARKER	6/2/22	6/16/22	220.00	EA	I-55 NB and SB	66.899		67.912		Tubular Markers delineate I-55 head to head traffic as a as traffic on the crossovers
0260	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	6/13/22	6/16/22	2.00	EA	I-55 NB	65.953				as traine on the clossovers
0200	0102002		0/13/22	6/16/22	2.00		I-55 NB	66.084				
				6/16/22	2.00		1-55 SB	68.621				
				6/16/22	2.00		I-55 SB	68.819				
0270	6173600D	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	6/2/22	6/16/22	100.00		I-55 SB Bridge	67.429		67.410		Temp barriers for Sand Barrel Array at SB Bridge end
0310	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	6/2/22	6/16/22	350.00		Route 62 East of I-55 Bridges	62.432		62.251		Log Miles are in Rt 62 E.
												9 - 12' Skips East of I-55 NB On ramp = 96 LF 254 LF of White tape at Rt turn only lane east of I-55 N on ramp Total White Temp Tape: 350 LF
				6/16/22	1,003.00	LF	Route 62 West of I-55NB off ramp signal					Log Miles are in Rt 62 E. 931 LE temp white tape from L55 NB on ramp west to L
												931 LF temp white tape from I-55 NB on ramp west to SB on ramp 72 LF temp white tape for EB stop bar at I-55 NB on ra signal (6 strips of 4" white tape 12" wide to provide a 24 stop bar = 72 LF) Total Temp White Tape: 1003 LF
0320	6205303B	TEMPORARY REMOVABLE MARKING TAPE	6/2/22	6/16/22	1,818.00	LF	Route 62 East of I-55 Bridges	62.405		62.311		Log Miles are in Rt 62 E. 345 LF of Double Yellow at I-55 NB Ramp Turn lane 564 LF of Double Yellow CL Quantities doubled to compensate for placement of double yellow tape. Total Temp yellow tape. (345x2)+(564x2) = 1818 LF
				6/16/22	1,890.00	LF	Route 62 West of I-55NB off ramp signal	62.298		62.134		Log Miles are in Rt 62 E. 945 LF of CL yellow Quantity is doubled to compensate for placement of double yellow tape: Total temp yellow tape: 945 x 2 = 1890 LF
0380	6207001	PAVEMENT MARKING REMOVAL	6/2/22	6/16/22	96.00	LF	Route 62 East of I-55 Bridges	62.379		62.313		Log miles are in Rt 62 E. 8 - 12' white skip removals =
												LF
				6/16/22 6/16/22	228.00 312.00		I-55 at NB Taper I-55 at SB Taper	66.745		66.598 68.317		19 - 12' White skip removals = 228 LF 26 - 12' White skip removals = 312 LF
				6/16/22	528.00		Route 62 West of I-55NB off ramp signal	62.298		62.134		 Lo Title Virtue Skip Removals Log Miles are in R162 E. White Skip Removals: T2 Vihite Skips EB 62 Driving Lane = 204 LF L2 White Skips EB 62 Driving and Passing Lanes L6 LF L7 Mile Skips WB 62 Driving and Passing Lanes L6 LF L7 Call White Skip Removal: 528 LF
				6/16/22	550.00	LF	Route 62 East of I-55 Bridges	62.432		62.251		Log Miles are in R162 E. Lane Line Removals at signal: 215 LF WB 62 Lane line 65 LF EB 62 Lane line at 155 Off Ramp 270 LF EB lane line for Rt turn only lane Total Lane Line Removal: 550
				6/16/22	1,105.00	LF	Route 62 West of I-55NB off ramp signal	62.298		62.134		Log Miles are in R162 E. Solid White Lane Line Removals: 85 LF EB 62 Driving Lane at L55 NB On Ramp 190 LF EB 62 Driving and Passing Lane at L55 NB On Ramp 760 LF WB Turn lane for L55 SB On Ramp 50 LF WB Driving and Passing Lane at L55 SB On Rai Total Removals: 1105 LF
				6/16/22	1,128.00	LF	Route 62 East of I-55 Bridges	62.405		62.311		Log Miles are in Rt 62 E. 564 LF Double Yellow stripe removal east of I-55 bridges. Quantity doubled to compensate double yellow removal
0.07	0.5			6/16/22	1,560.00		Route 62 West of I-55NB off ramp signal	62.298		62.134		Log Miles are in Rt 62 E. 780 LF Double Yellow stripe removal from I-55 NB on ramp to I-55 SB on ramp. Quantity doubled to compensate double yellow remova
0390	0208063	TEMPORARY PAVEMENT MARKING	6/2/22	6/16/22	328.00	EA	Temp White I-55 NB	67.108		67.046		4" white stripe between far south crossover and mid so crossover
				6/16/22	740.00	EA	Temp Yellow SBL After Far South Crossover	67.054		66.914		4" yellow
				6/16/22	980.00	EA	Temp White Stripe in Far South Crossover	66.953		67.046		Quantity Sheets show only 4" Temporary Pavement Markings to be used. By Spec. the crossovers require stripes. 490 LF of white stripe for the crossovers was fi measured and this quantity will be double to compense for the additional 4 inches of width needed to create an
				6/16/22	980.00	EA	Temp White Stripe in Mid South Crossover	67.201		67.108		stripe. Quantity Skeets show only 4" Temporary Pavement Markings to be used. By Spec. the crossovers require stripes. 490 LF of white stripe for the crossovers was fit measured and this quantity will be double to compensi for the additional 4 inches of width needed to create an inframe.
				6/16/22	980.00	EA	Temp Yellow in Mid South Crossover	67.209		67.116		stripe. Quantity Sheets show only 4" Temporary Pavement Markings to be used. By Spec. the crossovers require stripes. 490 LF of white stripe for the crossovers was fit measured and this quantity will be double to compensa for the additional 4 inches of width needed to create an intrince
				6/16/22	982.00	EA	Temp White in Far North Crossover	67.932		67.839		stripe. Quantity Sheets show only 4" Temporary Pavement Markings to be used. By Spec. the crossovers require stripes. 491 LF of white stripe for the crossovers was fit measured and this quantity will be double to compensa for the additional 4 inches of width needed to create an etrice.
				6/16/22	982.00	EA	Temp Yellow in Far North Crossover	67.940		67.847		stripe. Quantity Sheets show only 4" Temporary Pavement Markings to be used. By Spec. the crossovers require stripes. 491 LF of white stripe for the crossovers was fi measured and this quantity will be double to compense



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line	Item	now unis line is		DWR	DWR	Quantity		n of detai	II, Iocatic	on and quantity of work.	From	Offset/	То	Offset/		Comments	
Line Number	Item Code		Description	DWR Date	DWR Approval Date		Units			Location	From Station/Log Mile			Distance		Comments	
0390	6208063	TEMPORARY PA	/EMENT MARKING	6/2/22											for the additio stripe.	nal 4 inches of width neede	d to create an 8
					6/16/22	990.00	EA	Temp Yello	w Stripe in	Far South Crossover	67.054		66.960		Markings to b stripes. 495 L field measure	ts show only 4" Temporary e used. By Spec. the crosss F of yellow stripe for the crc d and this quantity will be d or the additional 4 inches of tripe.	overs require 8" ossovers was ouble to
					6/16/22	1,930.00		Temp white			66.588		66.953		4" white		
					6/16/22 6/16/22	3,163.00 3,820.00		Temp Yello Temp White		aper	68.438 67.839		67.839		4" Yellow 4" White		
					6/16/22	8,374.00		Temp Doub		SBL	67.847		67.054		Field measure	ed quantity is 4,187 LF. Sine ble yellow stripe, quantity is	ce the 4" yellow
0480	2162500	REMOVAL OF EX	ISTING BRIDGE DECK	6/13/22	6/16/22	2,568.00	SQFT	I-55 NB Bri	dge Span 4		1364+11.39		1364+71.39	1		om bent 4 to abutment 5 an	
				6/14/22	6/16/22	1,754.80	SQFT	I-55 NB Bri	dge Half of	Span 3	1363+70.39		1364+11.39	1	Half of Span 3	se or 1: 41' from mid span 3 to be	nt 4 and 42.8'
															width 41 x 42.8 = 17		
5004 e infor			KING REMOVAL (SYMBOLS) re details for Construction Sig		6/16/22	6.00	EA	Route 62 W	lest of I-55	NB off ramp signal	62.298		62.134		Log Miles are	in Rt 62 E	
roject	Line Numbe	r DWR Date	Total Quantity Posted For DWR Date		Sign Ir	nformation		Station	Log Mile	Location	Number of Items		n Sign	Speci	ial Sign	SF Each Special Sign	Total SF to
3643	0170	April 11, 2022	666	WO20- ROAD	-1 48x48 /BRIDGE/R/	16.00 AMP WOR	K AHEAD	,	65.227	NB	2.00	16					
					T-3A 60x4		INE SIGN		65.501 65.501	NB	2.00	20 4.67					
				SPEED	DING/PASS	ING (PLAT		F	65.713	NB	2.00	6					
				(PLAQ	UE)												
				WO20-	36x48 1 -5 48x48	16.00			65.713 65.976	NB	2.00	12 16					
				AHEAD)									
				(ARRC	aR 48x48 W SYMBO	L)	ERGE		66.107	NB	1.00	16					
				RIGHT	6a 48x48 /CENTER/L	EFT LANE			66.107	NB	1.00	16					
				GO20- (PLAQ	5aP 36x24 UE)	6.00 W0	ORK ZON	E	66.489	NB	2.00	6					
				R2-1 XX	36x48 1	2.00 SPEE	D LIMIT		66.489	NB	2.00	12					
				R2-1 XX	36x48 1	2.00 SPEE	D LIMIT		66.491	SB	2.00	12					
				R2-1 XX	36x48 1	2.00 SPEE	D LIMIT		68.153	NB	2.00	12					
				GO20- (PLAQ	5aP 36x24 UE)	6.00 W	ORK ZON	E	68.396	SB	2.00	6					
				R2-1 XX	36x48 1	2.00 SPEE	D LIMIT		68.396	SB	2.00	12					
					aR 48x48 W SYMBO		ERGE		68.598	SB	1.00	16					
				WO20-	-6a 48x48 /CENTER/L	16.00			68.598	SB	1.00	16					
				WO20-	-5 48x48 /CENTER/L	16.00			68.796	SB	2.00	16					
					5aP 36x24	6.00 W	ORK ZON	E	68.997	SB	2.00	6					
				R2-1 XX		2.00 SPEE	D LIMIT		68.997	SB	2.00	12					
					T-3A 60x4		INE SIGN		69.213	SB	2.00	20					
				CONS' SPEED	T-3X 56x1 DING/PASS	2 4.67 ING (PLAT	E)		69.213	SB	2.00	4.67					
				WO20- ROAD	1 48x48 /BRIDGE/R/	16.00 AMP WOR	K AHEAD	1	69.403	SB	2.00	16					
				R2-1 XX	36x48 1	2.00 SPEE	D LIMIT			62 to 55 SB Ramp	1.00	12					
					36x48 1					57 NB to 55 NB Ramp	1.00	12					
				R4-1 WO20-	1 48x48	2.00 DO N 16.00				57 SB to 55 NB Ramp 57 NB to 55 NB Ramp	1.00	12 16					
				WO20-	/BRIDGE/R/	16.00				57 SB to 55 NB Ramp	1.00	16					
				WO20-	/BRIDGE/R/ -1 48x48	16.00				62 to 55 SB Ramp	1.00	16					
				WO20- RIGHT	/BRIDGE/R/ -5 48x48 //CENTER/L	16.00				57 NB to 55 NB Ramp	1.00	16					
				RIGHT	-5 48x48 /CENTER/L	16.00 .EFT LANE	CLOSE)		57 SB to 55 NB Ramp	1.00	16					
				CONS.	D T-3A 60x4	8 20.00 F	INE SIGN			57 NB to 55 NB Ramp	1.00	20					
					T-3A 60x4		INE SIGN			57 SB to 55 NB Ramp 57 NB to 55 NB Ramp	1.00	20 4.67					
				SPEED	DING/PASS T-3X 56x1	ING (PLAT	E)				1.00	4.67					
				SPEED	5aP 36x24	ING (PLAT	'	F		57 SB to 55 NB Ramp							
				(PLAQ	UE)					57 NB to 55 NB Ramp	1.00	6					
				(PLAQ						57 SB to 55 NB Ramp	1.00	6					
				(PLAQ				E		62 to 55 SB Ramp	1.00	6					
		April 19, 2022 June 2, 2022	7 126		48 TRI 6				67.450 61.540	US 62 Ramp to I-55 NB Rte 62 EB	1.00	6.93 16					
				AHEAD	-2 48x48				61.912	Rte 62 EB	1.00	16					
				ROAD	/BRIDGE/R/	AMP WOR	K AHEAD	•									
				WO20- RIGHT AHEAD	-5 48x48 //CENTER/L	16.00 EFT LANE	CLOSE	0	61.988	Rte 62 EB	1.00	16					



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Simos (if applicable)

			e details for Construction Sign									
	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile		Number of Items		Special Sign	SF Each Special Sign	Total SF to
3 (0170	June 2, 2022	126	WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		62.087	Rte 62 EB	1.00	16			
				R11-2 48x30 10.00 ROAD CLOSED		62.281	Rte 62 at I-55 NB Ramp	3.00	10			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		62.676	Rte 62 WB	1.00	16			
				WO20-2 48x48 16.00 DETOUR		62.909	Rte 62 WB	1.00	16			
			249	AHEAD special ??x?? ??.00 NO PASSING		0.149	Rt H NB	1.00		I-55 North Detour Signage 50B	27.69	
				ZONE				4.00			07.00	
				special ??x?? ??.00 NO PASSING ZONE		69.377	Rt HH at I-55 NB On Ramp	1.00		I-55 North Detour Signage 50C	27.69	
				special ??x?? ??.00 NO PASSING ZONE		62.391	Rte 62 WB	1.00		I-55 North Detour Signage 50B	27.69	
				special ??x?? ??.00 NO PASSING ZONE		61.988	Rte 62 WB	1.00		I-55 North Detour Signage 50A	27.69	
				special ??x?? ??.00 NO PASSING ZONE		1.070	Rt H NB	1.00		I-55 North Detour Signage 50B	27.69	
				special ??x?? ??.00 NO PASSING		61.789	Rte 62 EB	1.00		I-55 North Detour Signage 50E	27.69	
				ZONE special ??x?? ??.00 NO PASSING		1.847	Rt H NB	1.00		I-55 North Detour Signage 50A	27.69	
				ZONE special ??x?? ??.00 NO PASSING		1.699	Rt H NB	1.00		I-55 North Detour Signage 50D	27.69	
				ZONE								
				special ??x?? ??.00 NO PASSING ZONE		61.854	Rte 62 EB	1.00		I-55 North Detour Signage 50C	27.69	
			488	E05-1 36x48 12.00 GORE EXIT		67.173	I-55 NB to Rte 62 Ramp	1.00	12		40.00	
				special ??x?? ??.00 NO PASSING ZONE		67.015	I-55 NB	2.00		Ramp Exit 500 FT Sign 61	16.00	
				WO1-6 60x30 12.50 HORIZONTAL ARROW (SYMBOL)		66.991	I-55 NB	2.00	12.5			
				R11-2 48x30 10.00 ROAD CLOSED		66.991	I-55 NB	1.00	10			
				WO13-1 30x30 6.25 ADVISORY SPEED (PLAQUE)		66.804	I-55 NB	1.00	6.25			
				W01-4L 48x48 16.00 REVERSE CURVE (SYMBOL LEFT ARROW)		66.804	I-55 NB	1.00	16			
				GO20-2 48x24 8.00 END ROAD		65.730	I-55 SB	2.00	8			
				WORK CONST-8 48x36 12.00 WORK		64.654	I-55 NB	2.00	12			
				ZONE NO PHONE ZONE								
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		64.552	I-55 NB	2.00	10			
				CONST-7 72x36 18.00 RATE OUR WORK ZONE		64.454	I-55 NB	1.00	18			
				R11-2 48x30 10.00 ROAD CLOSED		67.253	I-55 NB	1.00	10			
				CONST-7 72x36 18.00 RATE OUR WORK ZONE		70.251	I-55 SB	1.00	18			
				WO1-6 60x30 12.50 HORIZONTAL		67.253	I-55 NB	2.00	12.5			
				ARROW (SYMBOL) R11-2 48x30 10.00 ROAD		67.289	I-55 NB	2.00	10			
				CLOSED R4-1 36x48 12.00 DO NOT PASS		67.429	I-55 NB	1.00	12			
				W06-3 48x48 16.00 TWO WAY		67.429	I-55 NB	1.00	12			
				TRAFFIC (SYMBOL) GO20-5aP 36x24 6.00 WORK ZONE		67.429	I-55 NB	1.00	6			
				(PLAQUE)								
				R4-1 36x48 12.00 DO NOT PASS WO6-3 48x48 16.00 TWO WAY		67.647 67.647	I-55 NB I-55 SB	1.00	12			
				TRAFFIC (SYMBOL) GO20-5aP 36x24 6.00 WORK ZONE		67.647	I-55 NB	1.00	6			
				(PLAQUE)								
				WO1-4R 48x48 16.00 REVERSE CURVE (SYMBOL RIGHT ARROW)		67.800	I-55 NB	1.00	16			
				WO13-1 30x30 6.25 ADVISORY SPEED (PLAQUE)		67.800	I-55 NB	1.00	6.25			
				WO1-6 60x30 12.50 HORIZONTAL ARROW (SYMBOL)		67.887	I-55 NB	2.00	12.5			
				R5-1 30x30 6.25 DO NOT ENTER		67.890	I-55 NB	2.00	6.25			
				WO6-3 48x48 16.00 TWO WAY TRAFFIC (SYMBOL)		67.890	I-55 SB	2.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		69.286	Rt HH Ramp to I-55 SB	1.00	16			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		69.825	I-55 SB	2.00	12			
				GO20-1 60x24 10.00 ROAD WORK		70.031	I-55 SB	2.00	10			
		June 13, 2022	24	NEXT XX MILES R2-1 36x48 12.00 SPEED LIMIT		62.117	Rt 62 EB	1.00	12			
				xx								
				R2-1 36x48 12.00 SPEED LIMIT XX		62.428	Rt 62 WB	1.00	12			



Line Item Adjustments by Estimate

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3643	0050	MISC.	Material		4	May 16, 2022	SYSTEM	\$118,523.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$118,523.17)	
					5	Jun 2, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$148,153.96)	
					6	Jun 16, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$148,153.96)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0050 -	Total						\$0.00	
	0130	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	Material		5	Jun 2, 2022	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$4,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0130 -	Total						\$0.00	
	0180	ADVANCED WARNING RAIL SYSTEM	Material		2	Apr 15, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Apr 15, 2022	SYSTEM	(\$100.00)	
					3	May 2, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$100.00)	
					4	May 16, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$100.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0180 - Total							\$0.00	
	0190	CHANNELIZER (TRIM LINE)	Material		2	Apr 15, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total	2	Apr 15, 2022	SYSTEM	(\$2,244.00)	
					3	May 2, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$2,244.00)	
					4	May 16, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$2,244.00)	
								\$0.00	
			Material - Total						
			Material - To	otal				\$0.00	
	0190 -	Total	Material - To	otal				\$0.00 \$0.00	



Line Item Adjustments by Estimate

Contract ID:190215-D05

oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
013643	0210	INDICATOR BARRICADE	Material			2022			Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Apr 15, 2022	SYSTEM	(\$2,340.00)	
					3	May 2, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$2,340.00)	
					4	May 16, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$2,340.00)	
				- Total			\$0.00		
			Material - To	otal				\$0.00	
	0210 -	Total						\$0.00	
	0220	FLASHING ARROW PANEL	Material		2	Apr 15, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Apr 15, 2022	SYSTEM	(\$3,000.00)	
					3	May 2, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$3,000.00)	
					4	May 16, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	May 16,	SYSTEM	(\$3,000.00)	
						2022			
				- Total		2022		\$0.00	
			Material - To			2022		\$0.00 \$0.00	
	0220 -	Total	Material - To			2022			
	0220 - 0250	CMS W/O COMMUNICATION INTERFACE,	Material - To		2	Apr 15, 2022	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		CMS W/O COMMUNICATION			2	Apr 15,	SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment
		CMS W/O COMMUNICATION INTERFACE,				Apr 15, 2022 Apr 15,		\$0.00 \$0.00 \$9,600.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment
		CMS W/O COMMUNICATION INTERFACE,			2	Apr 15, 2022 Apr 15, 2022 May 2,	SYSTEM	\$0.00 \$0.00 \$9,600.00 (\$9,600.00)	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment
		CMS W/O COMMUNICATION INTERFACE,			2 3	Apr 15, 2022 Apr 15, 2022 May 2, 2022 May 2,	SYSTEM SYSTEM	\$0.00 \$0.00 \$9,600.00 (\$9,600.00) \$9,600.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment
		CMS W/O COMMUNICATION INTERFACE,		otal	2 3 3	Apr 15, 2022 Apr 15, 2022 May 2, 2022 May 2, 2022 May 16,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$9,600.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment
		CMS W/O COMMUNICATION INTERFACE,	Material	otal - Total	2 3 3 4	Apr 15, 2022 Apr 15, 2022 May 2, 2022 May 2, 2022 May 16, 2022 May 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$9,600.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment
		CMS W/O COMMUNICATION INTERFACE,		otal - Total	2 3 3 4	Apr 15, 2022 Apr 15, 2022 May 2, 2022 May 2, 2022 May 16, 2022 May 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$9,600.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment
		CMS W/O COMMUNICATION INTERFACE, CONT F/	Material	otal - Total	2 3 3 4	Apr 15, 2022 Apr 15, 2022 May 2, 2022 May 2, 2022 May 16, 2022 May 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00)	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment
	0250	CMS W/O COMMUNICATION INTERFACE, CONT F/ Total	Material	otal - Total	2 3 3 4	Apr 15, 2022 Apr 15, 2022 May 2, 2022 May 2, 2022 May 16, 2022 May 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$0.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment
	0250 -	CMS W/O COMMUNICATION INTERFACE, CONT F/ Total	Material	otal - Total	2 3 3 4 4	Apr 15, 2022 Apr 15, 2022 May 2, 2022 May 2, 2022 May 16, 2022 May 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
	0250 -	CMS W/O COMMUNICATION INTERFACE, CONT F/ Total	Material	otal - Total	2 3 3 4 4 5	Apr 15, 2022 2022 2022 May 2, 2022 May 16, 2022 May 16, 2022 May 16, 2022 Jun 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$0.00 \$0.00 \$11,000.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
	0250 -	CMS W/O COMMUNICATION INTERFACE, CONT F/ Total	Material	- Total otal - Total	2 3 3 4 4 5	Apr 15, 2022 2022 2022 May 2, 2022 May 16, 2022 May 16, 2022 May 16, 2022 Jun 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$0.00 \$0.00 \$11,000.00 (\$11,000.00)	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
	0250 -	CMS W/O COMMUNICATION INTERFACE, CONT F/ Total TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material Material - To Material	- Total otal - Total	2 3 3 4 4 5	Apr 15, 2022 2022 2022 May 2, 2022 May 16, 2022 May 16, 2022 May 16, 2022 Jun 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$0.00 \$0.00 \$11,000.00 (\$11,000.00) \$0.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.



Line Item Adjustments by Estimate

Jun 18, 2022

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3643	0310	MARKING TAPE 4 IN.,	Material						Estimate Exception 3 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$2,706.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0310 -	0310 - Total							
	0320	TEMPORARY REMOVABLE MARKING TAPE	Material		6	Jun 16, 2022	SYSTEM	\$7,416.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$7,416.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0320 -	Total						\$0.00	
	0390	TEMPORARY PAVEMENT MARKING	Material		6	Jun 16, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$6,062.25)	
			- Total					\$0.00	
			Material - Total					\$0.00	
	0390 -	Total			_			\$0.00	
	5002	SEQUENTIAL FLASHING WARNING LIGHT	Material		4	May 16, 2022	SYSTEM	\$4,347.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$4,347.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5002 -	Total						\$0.00	
	5003	TEMPORARY SEEDING	Material		5	Jun 2, 2022	SYSTEM	\$2,830.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$2,830.48)	
					6	Jun 16, 2022	SYSTEM	\$2,830.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$2,830.48)	
			- Total					\$0.00	
			Material - Total					\$0.00	
	5003 -	Total						\$0.00	
J9I3643 -	Total							\$0.00	
Overall -	Total							\$0.00	