

Pay Estimate Created Date: July 19, 2022

Progress Estimate N 8	lumber	Contract ID Prime Contractor	220121-H01 Robertson Contra	actors, Inc.			Original Contract Amount Net Change Order Amount Current Contract Amount	\$3,635,384.06 \$44,086.60 \$3,679,470.66			
Approval Date								By User			
July 19, 2022			Generated and A	Approved (a	and should be consi	dered Draft) a	t the Project Office Level by	woodsk1			
July 19, 2022		Re	eviewed and Appro	ved and Approved (and should be considered Draft) at the Resident Engineer Level by							
July 20, 2022			I	e Controllers Office Level by	ramses1						
Original Completio	n Date	Current Con	npletion Date	Actua	I Completion Date	%	of Current Contract Amoun	t Complete			
May 1, 2023		May 1	, 2023				22.19%				
	Contrac	t Informational Dat	tes		Milesto	nes					
Date Description	Original	Completion Date	Current Complet	tion Date	No Milestones Exis	st for Contract					
Acceptance Date											
Awarded Date	February	/ 2, 2022	February 2, 2022								
Letting Date	January	21, 2022	January 21, 2022								
Notice to Proceed Date	April 4, 2	2022	April 4, 2022								
Open to Traffic Date											
Work Began Date	April 11,	2022	April 11, 2022								

Contract Total Pay For Estimate No. 8				
	This Estimate	Previous	To Date	
220121-H01				
Total Posted Items Pay	\$33,305.00	\$783,190.19	\$816,495.19	
Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
		<mark>\$783,190.19</mark>	\$816,495.19	
Contract Total Payable This Estimate:	\$33,305.00			

Contract Total Payable This Estimate: Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9I3643	0140	6122020	REPLACEMENT SAND BARREL	EA	\$250.000	2	\$500.00
	0530	7121159	SHEAR CONNECTORS	EA	\$15.500	1,800	\$27,900.00
	0590	7126000	NON-DESTRUCTIVE TESTING	LF	\$45.000	109	\$4,905.00
Project J9I3643 -	Total						\$33,305.00
Overall - Total							\$33,305.00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3643	0050	MISC.	Material			-2,932	\$50.53	(\$148,153.96)
	0050	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	2,932	\$50.53	\$148,153.96
	0310	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material			-2,231	\$2.00	(\$4,462.00)
	0310	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	2,231	\$2.00	\$4,462.00



Pay Estimate Created Date: July 19, 2022

Prog	ress Es	timate Number 8	Contract ID Prime Cont		21-H01 rtson Contrac		er Amount	\$3,635,384.06 \$44,086.60 \$3,679,470.66	
Project Number	Line No.	Item Descri	iption	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3643	0320	TEMPORARY R MARKING	EMOVABLE TAPE 4 IN., YELLOW	Material			-6,090	\$2.00	(\$12,180.00
	0320	TEMPORARY RI MARKING	EMOVABLE TAPE 4 IN., YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	6,090	\$2.00	\$12,180.00
	0390	TEMPORARY	PAVEMENT MARKING	Material			-24,249	\$0.25	(\$6,062.25
	0390	TEMPORARY	PAVEMENT MARKING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	24,249	\$0.25	\$6,062.25
Total	1								\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9I3643	l 55-1(176)	2 bridge deck replacement	I-55	SCOTT	over Route 62		
Totals by .	Job Numbe	rs					
J9I3643					This Estimate	Previous	To Date

13043	This Estimate	Previous	To Date
Posted Item Pay	\$33,305.00	\$783,190.19	\$816,495.19
Gross Item Adjustments	\$0.00	\$0.00	\$0.00
Gross Iter	n Pay \$33,305.00	\$783,190.19	\$816,495.19
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 4019905, Project Item Line Number 0050, Material Set 401990596, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridder
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 4019905, Project Item Line Number 0050, Material Set 401990596, Material 0403SP190CLG - Superpave 19.0 mm, Des C 80 Gyros, Acceptance Action AspHigh Temporary Crossing is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 6205301B, Project Item Line Number 0310, Material Set 6205301B96, Material 1048PMRPMTWH - Marking Tape Removable White, Acceptance Action Generic 1048PMRPMTWH is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 6205303B, Project Item Line Number 0320, Material Set 6205303B96, Material 1048PMRPMTYL - Marking Tape Removable Yellow, Acceptance Action Generic 1048PMRPMTYL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridder
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 6208063, Project Item Line Number 0390, Material Set 6208063, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient.	No Remark was entered by Engineer	woodsk1	Overridder

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

ed date and can differ from the posted amount at the time the Estimate was Generated. Note: Posted

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
20121-H01	J9I3643	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.50	\$15,000.00	\$7,500.
		0001	0020	2071000	LINEAR GRADING CLASS 1	4.40	0.00	4.40	STA	0.00	\$2,600.00	\$0.
		0001	0030	2072000	LINEAR GRADING CLASS 2	32.40	0.00	32.40	STA	32.40	\$3,850.00	\$124,740
		0001	0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,174.00	0.00	1,174.00	SQYD	0.00	\$15.00	\$0.
		0001	0050	4019905	MISC.Optional Pavement	2,932.00	0.00	2,932.00	SQYD	2,932.00	\$50.53	\$148,153
		0001	0060	5021334	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	1,173.60	0.00	1,173.60	SQYD	0.00	\$95.00	\$0
		0001	0070	5041000	CONCRETE APPROACH PAVEMENT	404.80	0.00	404.80	SQYD	0.00	\$105.00	\$0
		0001	0080	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	349.00	0.00	349.00	LF	0.00	\$20.00	\$0
		0001	0090	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	47.00	0.00	47.00	CUYD	0.00	\$45.00	\$0
		0001	0100	6096041	PLACING TYPE 1 ROCK DITCH LINER	47.00	0.00	47.00	CUYD	0.00	\$80.00	\$(
		0001	0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	853.00	0.00	853.00	CUYD	0.00	\$40.00	\$
		0001	0120	6113040	PLACING TYPE 2 ROCK BLANKET	853.00	0.00	853.00	CUYD	0.00	\$25.00	\$(
		0001	0130	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	2.00	1.00	3.00	EA	3.00	\$2,000.00	\$6,00
		0001	0140	6122020	REPLACEMENT SAND BARREL	6.00	0.00	6.00	EA	2.00	\$250.00	\$50
		0001	0150	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	1.00	3.00	EA	0.00	\$1,000.00	\$
		0001	0160	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	0.00	\$5,000.00	\$
		0001	0170	6161005	CONSTRUCTION SIGNS	2,140.00	0.00	2,140.00	SQFT	1,560.00	\$6.50	\$10,14
		0001	0180	6161008	ADVANCED WARNING RAIL SYSTEM	18.00	0.00	18.00	EA	4.00	\$25.00	\$10
		0001	0190	6161025	CHANNELIZER (TRIM LINE)	500.00	0.00	500.00	EA	332.00	\$17.00	\$5,64
		0001	0200	6161030	TYPE III MOVEABLE BARRICADE	21.00	0.00	21.00	EA	15.00	\$145.00	\$2,17
		0001	0210	6161033	DIRECTIONAL INDICATOR BARRICADE	100.00	0.00	100.00	EA	36.00	\$65.00	\$2,34
		0001	0220	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	3.00	\$1,500.00	\$4,50
		0001	0230	6161052	WARNING LIGHT, TYPE B	50.00	0.00	50.00	EA	0.00	\$15.00	\$
		0001	0240	6161070	TUBULAR MARKER	650.00	0.00	650.00	EA	220.00	\$35.00	\$7,70
		0001	0250	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$4,800.00	\$19,20
		0001	0260	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	16.00	0.00	16.00	EA	8.00	\$800.00	\$6,40
		0001	0270	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	451.00	100.00	551.00	LF	551.00	\$40.00	\$22,04
		0001	0280	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	451.00	100.00	551.00	LF	0.00	\$35.00	\$
		0001	0290	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$225,000.00	9
		0001	0291	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.50	\$200,165.00	\$100,08
		0001	0300	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	10.00	0.00	10.00	EA	0.00	\$250.00	\$
		0001	0310	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	3,645.00	0.00	3,645.00	LF	2,231.00	\$2.00	\$4,46
		0001	0320	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	6,090.00	0.00	6,090.00	LF	6,090.00	\$2.00	\$12,18
		0001	0330	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,705.00	27,660.00	30,365.00	LF	0.00	\$0.30	9
		0001	0340	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,774.00	19,126.00	20,900.00	LF	0.00	\$0.30	\$
		0001	0350	6206000C		13,177.00	-13,177.00	0.00	LF	0.00	\$0.15	\$
		0001	0360	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	6,704.00	-6,704.00	0.00	LF	0.00	\$0.15	\$
		0001	0370	6206125A	MARKING PAINT, TYPE P BEADS 24 IN. YELLOW STANDARD WATERBORNE PAVEMENT	75.00	-75.00	0.00	LF	0.00	\$5.00	\$
		0001	0380	6207001	MARKING PAINT, TYPE P BEADS PAVEMENT MARKING REMOVAL	50,359.00	0.00	50,359.00	LF	8,328.00	\$0.50	\$4,16
		0001	0390	6208063	TEMPORARY PAVEMENT MARKING	34,359.00	0.00	34,359.00	EA	24,249.00	\$0.25	\$6,06
		0001	0400	6240102A	TEMPORARY SILT FENCE GEOTEXTILE	1,040.00	0.00	1,040.00	SQYD	0.00	\$1.50	\$
		0001	0410	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,689.00	0.00	1,689.00	SQYD	0.00	\$4.00	\$
		0001	0420	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$20,000.00	\$10,00
		0001	0430	7250312A	12 IN. PIPE GROUP B	1,100.00	0.00	1,100.00	LF	1,100.00	\$50.00	\$55,00

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Note: Posted Q	uantities	and Valu	les are	based on F	Report Generated date and can differ from the posted am		e time the E	stimate was	Genera	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-H01	J9I3643	0001	0440	8061016	SEDIMENT REMOVAL	10.00	0.00	10.00	CUYD	0.00	\$1.00	\$0.00
		0010	0450	6061060	MGS GUARDRAIL	100.00	315.00	415.00	LF	0.00	\$40.00	\$0.00
		0010	0460	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	6.00	0.00	6.00	EA	0.00	\$4,000.00	\$0.00
		0010	0470	6069901	MISC.Remove and Reinstall High-Tension Gurad Cable	1.00	0.00	1.00	LS	0.50	\$55,000.00	\$27,500.00
		0070	0480	2162500	REMOVAL OF EXISTING BRIDGE DECK	11,771.00	0.00	11,771.00	SQFT	11,771.00	\$14.00	\$164,794.00
		0070	0490	5031010A	BRIDGE APPROACH SLAB (MAJOR)	188.00	0.00	188.00	SQYD	0.00	\$415.00	\$0.00
		0070	0500	7034212	SLAB ON STEEL	1,353.00	0.00	1,353.00	SQYD	0.00	\$525.00	\$0.00
		0070	0510	7034219A	TYPE D BARRIER	558.00	0.00	558.00	LF	0.00	\$115.00	\$0.00
		0070	0520	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0070	0530	7121159	SHEAR CONNECTORS	1,800.00	0.00	1,800.00	EA	1,800.00	\$15.50	\$27,900.00
		0070	0540	7123610	SLAB DRAIN	20.00	0.00	20.00	EA	0.00	\$450.00	\$0.00
		0070	0550	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	12,100.00	0.00	12,100.00	SQFT	0.00	\$9.50	\$0.00
		0070	0560	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	12,100.00	0.00	12,100.00	SQFT	0.00	\$2.50	\$0.00
		0070	0570	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	12,100.00	0.00	12,100.00	SQFT	0.00	\$1.50	\$0.00
		0070	0580	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$3.00	\$0.00
		0070	0590	7126000	NON-DESTRUCTIVE TESTING	109.00	0.00	109.00	LF	109.00	\$45.00	\$4,905.00
		0070	0600	7172054	OPEN CELL FOAM JOINT SEAL	87.00	0.00	87.00	LF	0.00	\$80.00	\$0.00
		0071	0610	2162500	REMOVAL OF EXISTING BRIDGE DECK	11,771.00	0.00	11,771.00	SQFT	0.00	\$14.00	\$0.00
		0071	0620	5031010A	BRIDGE APPROACH SLAB (MAJOR)	188.00	0.00	188.00	SQYD	0.00	\$415.00	\$0.00
		0071	0630	7034212	SLAB ON STEEL	1,353.00	0.00	1,353.00	SQYD	0.00	\$525.00	\$0.00
		0071	0640	7034219A	TYPE D BARRIER	558.00	0.00	558.00	LF	0.00	\$115.00	\$0.00
		0071	0650	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0071	0660	7121159	SHEAR CONNECTORS	1,800.00	0.00	1,800.00	EA	0.00	\$15.50	\$0.00
		0071	0670	7123610	SLAB DRAIN	18.00	0.00	18.00	EA	0.00	\$450.00	\$0.00
		0071	0680	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	12,100.00	0.00	12,100.00	SQFT	0.00	\$9.50	\$0.00
		0071	0690	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	12,100.00	0.00	12,100.00	SQFT	0.00	\$2.50	\$0.00
		0071	0700	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	12,100.00	0.00	12,100.00	SQFT	0.00	\$1.50	\$0.00
		0071	0710	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$3.00	\$0.00
		0071	0720	7126000	NON-DESTRUCTIVE TESTING	109.00	0.00	109.00	LF	0.00	\$45.00	\$0.00
		0071	0730	7172054	OPEN CELL FOAM JOINT SEAL	87.00	0.00	87.00	LF	0.00	\$80.00	\$0.00
		0001	5001	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$24,835.00	\$24,835.00
		0001	5002	6161055	SEQUENTIAL FLASHING WARNING LIGHT	0.00	36.00	36.00	EA	36.00	\$120.75	\$4,347.00
		0001	5003	8061017	TEMPORARY SEEDING	0.00	1.00	1.00	ACRE	0.50	\$5,660.95	\$2,830.48
		0001	5004	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	0.00	6.00	6.00	EA	6.00	\$50.00	\$300.00
	Project .	1913643 - To	otal Value	Posted to D	late as of Report Generated Date							\$816,495.18
220121-H01 Ove	erall - Tota	I Value Pos	sted to Da	ate as of Rep	ort Generated Date							\$816,495.18



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code		Description	DWR Date	DWR Approval	Quantity I Posted	Units			Location		From Station/	Offset/ Distance		Offset/ / Distance		Comments	
					Date							Log Mile		Log Mile				
		REPLACEMENT		7/15/22	7/19/22	2.00	EA			f I-55 Head To Head Partition oject work zone in the SB Lar		1360		136	7	Replaced two t	barrels Wednesday July 13	ιh, 2022.
		SHEAR CONNEC NON-DESTRUCT		7/15/22		1,800.00		Northbound Br				1360 1360		136 136		Northbound Bri Northbound Bri		
			are details for Constructio				LF	Northbound Br	nuge.			1300		130		Northbound Br	luge.	
Project	Line Numbe	r DWR Date	Total Quantity Posted For DWR I	Date	Sign Inf	formation		Station Log		Location		er of Items	SF Each	Sign	Spe	cial Sign	SF Each Special Sign	
913643	0170	April 11, 2022	666	WO20-1 ROAD/BR	48x48 IDGE/RA	16.00 MP WORK /	AHEAD	65.	.227	NB	2.00		16					
						20.00 FINE	SIGN		.501	NB	2.00		20					
				CONST-3 SPEEDIN		4.67 NG (PLATE)		65.	.501	NB	2.00		4.67					ę
				GO20-5aF (PLAQUE		6.00 WOR	K ZONE	65.	.713	NB	2.00		6					
						2.00 DO NOT	PASS		.713	NB	2.00		12					
				WO20-5 RIGHT/CE AHEAD	48x48 ENTER/LE	16.00 EFT LANE C	LOSED	65.	.976	NB	2.00		16					
				WO4-1aR	48x48	16.00 MER	GE	66.	i.107	NB	1.00		16					
				(ARROW WO20-6a				66.	6.107	NB	1.00		16					
				RIGHT/CE	NTER/LE	EFT LANE C 6.00 WOR				NB			6					
				(PLAQUE)				i.489		2.00							
				R2-1 3 XX	6x48 12	2.00 SPEED	LIMIT	66.	i.489	NB	2.00		12					
				R2-1 3 XX	6x48 12	2.00 SPEED	LIMIT	66.	i.491	SB	2.00		12					
				R2-1 3 XX	6x48 12	2.00 SPEED	LIMIT	68.	.153	NB	2.00		12					
				GO20-5aF (PLAQUE	9 36x24	6.00 WOR	K ZONE	E 68.	.396	SB	2.00		6					
						2.00 SPEED	LIMIT	68.	.396	SB	2.00		12					
				WO4-1aR		16.00 MER	GE	68.	.598	SB	1.00		16					
				(ARROW WO20-6a	48x48	16.00		68.	.598	SB	1.00		16					
				RIGHT/CE WO20-5		EFT LANE C 16.00	LOSED		.796	SB	2.00		16					
						EFT LANE C	LOSED											
				GO20-5aF (PLAQUE		6.00 WOR	K ZONE	E 68.	.997	SB	2.00		6					
				R2-1 3 XX	6x48 12	2.00 SPEED	LIMIT	68.	.997	SB	2.00		12					
					A 60x48	20.00 FINE	E SIGN	69.	.213	SB	2.00		20					
				CONST-3 SPEEDIN	X 56x12 G/PASSIN	4.67 NG (PLATE)		69.	.213	SB	2.00		4.67					
				WO20-1 ROAD/BR		16.00 MP WORK /		69.	.403	SB	2.00		16					
				R2-1 3		2.00 SPEED				62 to 55 SB Ramp	1.00		12					
				XX R4-1 3	6x48 12	2.00 DO NOT	PASS			57 NB to 55 NB Ramp	1.00		12					
				R4-1 3	6x48 12	2.00 DO NOT	PASS			57 SB to 55 NB Ramp	1.00		12					
				WO20-1 ROAD/BR	48x48 IDGE/RA	16.00 MP WORK /	HEAD			57 NB to 55 NB Ramp	1.00		16					
				WO20-1 ROAD/BR		16.00 MP WORK /	HEAD			57 SB to 55 NB Ramp	1.00		16					
				WO20-1 ROAD/BR	48x48 IDGE/RA	16.00 MP WORK /				62 to 55 SB Ramp	1.00		16					
				WO20-5	48x48					57 NB to 55 NB Ramp	1.00		16					
				AHEAD			LOOLD											
				WO20-5 RIGHT/CE AHEAD	48x48 NTER/LE	16.00 EFT LANE C	LOSED			57 SB to 55 NB Ramp	1.00		16					
					A 60x48	20.00 FINE	SIGN			57 NB to 55 NB Ramp	1.00		20					
						20.00 FINE	SIGN			57 SB to 55 NB Ramp	1.00		20					
					G/PASSI	NG (PLATE)				57 NB to 55 NB Ramp	1.00		4.67					
				CONST-3 SPEEDIN	X 56x12 G/PASSIN	4.67 NG (PLATE)				57 SB to 55 NB Ramp	1.00		4.67					
				GO20-5aF (PLAQUE	9 36x24	6.00 WOR	K ZONE	=		57 NB to 55 NB Ramp	1.00		6					
				GO20-5aF (PLAQUE	9 36x24	6.00 WOR	K ZONE	=		57 SB to 55 NB Ramp	1.00		6					
					36x24	6.00 WOR	K ZONE	=		62 to 55 SB Ramp	1.00		6					
		April 19, 2022	7	R1-2 4		.93 YIELD		67.	.450	US 62 Ramp to I-55 NB	1.00		6.93					
		June 2, 2022	126	WO20-2 AHEAD	48x48	16.00 DETC	UR	61.	.540	Rte 62 EB	1.00		16					
				WO20-1	48x48 IDGF/RA	16.00 MP WORK /		61.	.912	Rte 62 EB	1.00		16					
				WO20-5	48x48			61.	.988	Rte 62 EB	1.00		16					
				AHEAD			LUSED		0.05-	DL 00.55	4		46					
					INTER/LE	EFT LANE C	LOSED	62.	.087	Rte 62 EB	1.00		16					
				R11-2 CLOSED	48x30 10	0.00 ROAD		62.	2.281	Rte 62 at I-55 NB Ramp	3.00		10					
				WO20-1 ROAD/BR		16.00 MP WORK /	HEAD		.676	Rte 62 WB	1.00		16					
						16.00 DETC			.909	Rte 62 WB	1.00		16					



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Ct	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sight	Special Sign	SF Each Special Sign	I otal SF to
43	0170	June 2, 2022	126	AHEAD								
			249	special ??x?? ??.00 NO PASSING ZONE		0.149	Rt H NB	1.00		I-55 North Detour Signage 50B	27.69	2
				special ??x?? ??.00 NO PASSING ZONE		69.377	Rt HH at I-55 NB On Ramp	1.00		I-55 North Detour Signage 50C	27.69	:
				special ??x?? ??.00 NO PASSING ZONE		62.391	Rte 62 WB	1.00		I-55 North Detour Signage 50B	27.69	
				special ??x?? ??.00 NO PASSING		61.988	Rte 62 WB	1.00		I-55 North Detour Signage 50A	27.69	
				ZONE special ??x?? ??.00 NO PASSING		1.070	Rt H NB	1.00		I-55 North Detour Signage 50B	27.69	
				ZONE special ??x?? ??.00 NO PASSING		61.789	Rte 62 EB	1.00		I-55 North Detour Signage 50E		
				ZONE								
				special ??x?? ??.00 NO PASSING ZONE		1.847	Rt H NB	1.00		I-55 North Detour Signage 50A	27.69	
				special ??x?? ??.00 NO PASSING ZONE		1.699	Rt H NB	1.00		I-55 North Detour Signage 50D	27.69	
				special ??x?? ??.00 NO PASSING ZONE		61.854	Rte 62 EB	1.00		I-55 North Detour Signage 50C	27.69	
			488	EO5-1 36x48 12.00 GORE EXIT		67.173	I-55 NB to Rte 62 Ramp	1.00	12			
				special ??x?? ??.00 NO PASSING ZONE		67.015	I-55 NB	2.00		Ramp Exit 500 FT Sign 61	16.00	
				WO1-6 60x30 12.50 HORIZONTAL ARROW (SYMBOL)		66.991	I-55 NB	2.00	12.5			
				R11-2 48x30 10.00 ROAD CLOSED		66.991	I-55 NB	1.00	10			
				WO13-1 30x30 6.25 ADVISORY		66.804	I-55 NB	1.00	6.25			
				SPEED (PLAQUE) WO1-4L 48x48 16.00 REVERSE		66.804	I-55 NB	1.00	16			
				CURVE (SYMBOL LEFT ARROW)			1-55 SB		8			
				GO20-2 48x24 8.00 END ROAD WORK		65.730		2.00				
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		64.654	I-55 NB	2.00	12			
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		64.552	I-55 NB	2.00	10			
				CONST-7 72x36 18.00 RATE OUR WORK ZONE		64.454	I-55 NB	1.00	18			
				R11-2 48x30 10.00 ROAD CLOSED		67.253	I-55 NB	1.00	10			
				CONST-7 72x36 18.00 RATE OUR WORK ZONE		70.251	I-55 SB	1.00	18			
				WO1-6 60x30 12.50 HORIZONTAL ARROW (SYMBOL)		67.253	I-55 NB	2.00	12.5			
				R11-2 48x30 10.00 ROAD		67.289	I-55 NB	2.00	10			
				CLOSED R4-1 36x48 12.00 DO NOT PASS		67.429	I-55 NB	1.00	12			
				WO6-3 48x48 16.00 TWO WAY TRAFFIC (SYMBOL)		67.429	I-55 SB	1.00	16			
				GO20-5aP 36x24 6.00 WORK ZONE		67.429	I-55 NB	1.00	6			
				(PLAQUE) R4-1 36x48 12.00 DO NOT PASS		67.647	I-55 NB	1.00	12			
				WO6-3 48x48 16.00 TWO WAY		67.647	I-55 SB	1.00	16			
				TRAFFIC (SYMBOL) GO20-5aP 36x24 6.00 WORK ZONE		67.647	I-55 NB	1.00	6			
				(PLAQUE) WO1-4R 48x48 16.00 REVERSE		67.800	I-55 NB	1.00	16			
				CURVE (SYMBOL RIGHT ARROW) WO13-1 30x30 6.25 ADVISORY		67.800	I-55 NB	1.00	6.25			
				SPEED (PLAQUE)								
				WO1-6 60x30 12.50 HORIZONTAL ARROW (SYMBOL)		67.887	I-55 NB	2.00	12.5			
				R5-1 30x30 6.25 DO NOT ENTER		67.890	I-55 NB	2.00	6.25			
				WO6-3 48x48 16.00 TWO WAY TRAFFIC (SYMBOL)		67.890	I-55 SB	2.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		69.286	Rt HH Ramp to I-55 SB	1.00	16			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		69.825	I-55 SB	2.00	12			
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		70.031	I-55 SB	2.00	10			
		June 13, 2022	24	R2-1 36x48 12.00 SPEED LIMIT		62.117	Rt 62 EB	1.00	12			
				XX R2-1 36x48 12.00 SPEED LIMIT		62.428	Rt 62 WB	1.00	12			
				XX								



Project		Decerinting	Adjusters	Others	Eat	Created	Created	Δ	Demostra
	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3643	0050	MISC.	Material		4	May 16, 2022	SYSTEM	\$118,523.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$118,523.17)	
					5	Jun 2, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$148,153.96)	
					6	Jun 16, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$148,153.96)	
					7	Jul 1, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$148,153.96)	
					8	Jul 19, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Jul 19, 2022	SYSTEM	(\$148,153.96)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0050 -	Total						\$0.00	
	0130	IMPACT ATTENUATOR 70 MPH (SAND	Material		5	Jun 2, 2022	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
									Esumale Exception 5 on the current Fayment Esumale.
		BARREL ARRAY)			5	Jun 2, 2022	SYSTEM	(\$4,000.00)	Estimate Exception 3 on the current Payment Estimate.
				- Total	5		SYSTEM	(\$4,000.00) \$0.00	Estimate Exception 3 on the current Payment Estimate.
			Material - Te		5		SYSTEM		Estimate Exception 3 on the current Payment Estimate.
	0130 -	BARREL ARRAY)	Material - To		5		SYSTEM	\$0.00	
	0130 - 0180	BARREL ARRAY)			2		SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		BARREL ARRAY) Total ADVANCED WARNING RAIL				2022 Apr 15,		\$0.00 \$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment
		BARREL ARRAY) Total ADVANCED WARNING RAIL			2	2022 Apr 15, 2022 Apr 15,	SYSTEM	\$0.00 \$0.00 \$0.00 \$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment
		BARREL ARRAY) Total ADVANCED WARNING RAIL			2	2022 Apr 15, 2022 Apr 15, 2022 May 2,	SYSTEM	\$0.00 \$0.00 \$100.00 \$100.00 (\$100.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		BARREL ARRAY) Total ADVANCED WARNING RAIL			2 2 3	2022 Apr 15, 2022 Apr 15, 2022 May 2, 2022 May 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$100.00 (\$100.00) \$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		BARREL ARRAY) Total ADVANCED WARNING RAIL			2 2 3 3	2022 Apr 15, 2022 Apr 15, 2022 May 2, 2022 May 2, 2022 May 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$100.00 \$100.00 \$100.00 \$100.00 \$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		BARREL ARRAY) Total ADVANCED WARNING RAIL			2 2 3 3 4	2022 Apr 15, 2022 Apr 15, 2022 May 2, 2022 May 2, 2022 May 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$100.00 (\$100.00) \$100.00 (\$100.00) \$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
	0180	BARREL ARRAY)		otal - Total	2 2 3 3 4	2022 Apr 15, 2022 Apr 15, 2022 May 2, 2022 May 2, 2022 May 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$100.00 (\$100.00) \$100.00 (\$100.00) \$100.00 (\$100.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		BARREL ARRAY)	Material	otal - Total	2 2 3 3 4	2022 Apr 15, 2022 Apr 15, 2022 May 2, 2022 May 2, 2022 May 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$100.00 (\$100.00) \$100.00 (\$100.00) \$100.00 (\$100.00) \$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
	0180	BARREL ARRAY)	Material	otal - Total	2 2 3 3 4	2022 Apr 15, 2022 Apr 15, 2022 May 2, 2022 May 2, 2022 May 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$100.00 (\$100.00) \$100.00 (\$100.00) \$100.00 (\$100.00) \$100.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
	0180	BARREL ARRAY)	Material	otal - Total	2 2 3 3 4 4 2 2 2	2022 Apr 15, 2022 Apr 15, 2022 May 2, 2022 May 16, 2022 May 16, 2022 May 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$100.00 (\$100.00) \$100.00 (\$100.00) \$100.00 (\$100.00) (\$100.00) \$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment
	0180	BARREL ARRAY)	Material	otal - Total	2 2 3 3 4 4 2 2	2022 Apr 15, 2022 Apr 15, 2022 May 2, 2022 May 2, 2022 May 16, 2022 May 16, 2022 Apr 15, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$100.00 (\$100.00) \$100.00 (\$100.00) \$100.00 (\$100.00) \$0.00 \$0.00 \$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment



Jul 21, 2022

Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks					
Filgeot	LINE	Description	Туре	Adjustment	Number	Date	By	Amount	Itellians					
J9I3643	0190	CHANNELIZER	Material	Туре	4	May 16,	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment					
		(TRIM LINE)				2022			Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					4	May 16, 2022	SYSTEM	(\$2,244.00)						
				- Total				\$0.00						
			Material - Total					\$0.00						
	0190 -	Total						\$0.00						
	0210	DIRECTIONAL INDICATOR BARRICADE	Material		2	Apr 15, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					2	Apr 15, 2022	SYSTEM	(\$2,340.00)						
					3	May 2, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					3	May 2, 2022	SYSTEM	(\$2,340.00)						
					4	May 16, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					4	May 16, 2022	SYSTEM	(\$2,340.00)						
				- Total				\$0.00						
			Material - T	otal				\$0.00						
	0210 -	Total						\$0.00						
	0220	FLASHING ARROW PANEL	Material		2	Apr 15, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					2	Apr 15, 2022	SYSTEM	(\$3,000.00)						
					3	May 2, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					3	May 2, 2022	SYSTEM	(\$3,000.00)						
					4	May 16, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
					4	May 16, 2022	SYSTEM	(\$3,000.00)						
				- Total				\$0.00						
			Material - Te	otal				\$0.00						
	0220 -	Total						\$0.00						
	0250	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material		2	Apr 15, 2022	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
										2	Apr 15, 2022	SYSTEM	(\$9,600.00)	
					3	May 2, 2022	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
					3	May 2, 2022	SYSTEM	(\$9,600.00)						
					4	May 16, 2022	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.					
					4	May 16, 2022	SYSTEM	(\$9,600.00)						
				- Total				\$0.00						
			Material - Total					\$0.00						
	0250 -	Total						\$0.00						
	0270	TEMPORARY	Material		5	Jun 2,	SYSTEM	\$11,000.00	This adjustment offsets the original system-generated Material Payment					



Jul 21, 2022

Broject	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Pomorko					
Project	Line	Description	Adjustment Type	Adjustment Type		Created Date	By	Amount	Remarks					
J9I3643	0270	TRAFFIC BARRIER, CONT. FURN/RE	Material			2022			Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
		FORN/RE			5	Jun 2, 2022	SYSTEM	(\$11,000.00)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0270 -	Total						\$0.00						
	0310	TEMPORARY REMOVABLE MARKING TAPE 4	Material		6	Jun 16, 2022	SYSTEM	\$2,706.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
		IN.,			6	Jun 16, 2022	SYSTEM	(\$2,706.00)						
					7	Jul 1, 2022	SYSTEM	\$4,462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					7	Jul 1, 2022	SYSTEM	(\$4,462.00)						
					8	Jul 19, 2022	SYSTEM	\$4,462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					8	Jul 19, 2022	SYSTEM	(\$4,462.00)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0310 -	Total						\$0.00						
	0320	TEMPORARY REMOVABLE MARKING TAPE	Material		6	Jun 16, 2022	SYSTEM	\$7,416.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					6	Jun 16, 2022	SYSTEM	(\$7,416.00)						
					7	Jul 1, 2022	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					7	Jul 1, 2022	SYSTEM	(\$12,180.00)						
					8	Jul 19, 2022	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					8	Jul 19, 2022	SYSTEM	(\$12,180.00)						
				- Total				\$0.00						
			Material - Total					\$0.00						
	0320 -	Total						\$0.00						
	0390	TEMPORARY PAVEMENT MARKING	Material		6	Jun 16, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
										6	Jun 16, 2022	SYSTEM	(\$6,062.25)	
					7	Jul 1, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
					7	Jul 1, 2022	SYSTEM	(\$6,062.25)						
					8	Jul 19, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
					8	Jul 19, 2022	SYSTEM	(\$6,062.25)						
				- Total				\$0.00						
			Material - Total					\$0.00						
	0390 -	Total						\$0.00						
	5002	SEQUENTIAL FLASHING	Material		4	May 16, 2022	SYSTEM	\$4,347.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment					



Jul 21, 2022

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
			.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Туре	. tumbor	Duto	29		
J9I3643	5002	WARNING LIGHT	Material						Estimate Exception 6 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$4,347.00)	
				- Total				\$0.00	
			Material - T	Material - Total					
	5002 -	Total						\$0.00	
	5003	TEMPORARY SEEDING	Material		5	Jun 2, 2022	SYSTEM	\$2,830.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$2,830.48)	
					6	Jun 16, 2022	SYSTEM	\$2,830.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$2,830.48)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5003 -	Total						\$0.00	
J9I3643 -	1/3643 - Total								
Overall -	Overall - Total								