

Pay Estimate Created Date: January 3, 2023

Progress Estimate Number	Contract ID	220218-F07	Pay Period Start	December 16, 2022	Original Contract Amount	\$2,828,777.00
12	Prime Contractor	Pace Construction Company, LLC	Pay Period En	d January 1, 2023	Net Change Order Amount Current Contract Amount	(\$555,639.62) \$2,273,137.38

Approval Date		By User
January 3, 2023	Generated and Approved (and should be considered Draft) at the Project Office Level by	farrac
January 4, 2023	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	washas
January 5, 2023	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2022	November 1, 2022	November 4, 2022	98.34%

	Milestones						
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contrac				
Acceptance Date							
Awarded Date	March 1, 2022	March 1, 2022					
Letting Date	February 18, 2022	February 18, 2022					
Notice to Proceed Date	April 4, 2022	April 4, 2022					
Open to Traffic Date							
Work Began Date	July 5, 2022	July 5, 2022					

Contract Total Pay For Estimate No. 12								
	This Estimate	Previous	To Date					
220218-F07								
Total Posted Items Pay	(\$641.22)	\$2,236,036.20	\$2,235,394.98					
Gross Item Adjustments	\$702.89	\$145,174.99	\$145,877.88					
Incentive	\$0.00	\$0.00	\$0.00					
Disincentive	\$0.00	\$0.00	\$0.00					
Liquidated Damage	\$0.00	(\$7,650.00)	(\$7,650.00)					
Other Contract Adjustments	\$0.00	\$53,813.06	\$53,813.06					
		\$2,427,374.25	\$2,427,435.92					
Contract Total Payable This Estimate:	\$61.67							

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
J6I3424	0060	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)		\$131.500	0.45	\$59.18		
	0090	6049902	MISC.PULLBOX ADJUSTMENT	EA	\$700.000	-1	(\$700.00)		
	0590	9028308	CABLE, 16 AWG 2 CONDUCTOR	LF	\$1.050	2	\$2.10		
	0600	9028310	CABLE, 16 AWG 5 CONDUCTOR	LF	\$1.250	-2	(\$2.50)		
Project J6I342	Project J6l3424 - Total								
Overall - Tota	Overall - Total								

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjust	tments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3424	0060	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	0.45	\$0.86	\$0.39
	0800	TYPE A2 SHOULDER	Material			-133.3	\$160.00	(\$21,328.00)
	0080	TYPE A2 SHOULDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user bedarl2 overridding Payment Estimate Exception 1 on	133.3	\$160.00	\$21,328.00

Revision 4/1/2020 Page 1 of 29



Pay Estimate Created Date: January 3, 2023

Pay Period December 16, **Progress Estimate Contract ID** 220218-F07 Original Contract Amount \$2,828,777.00 Number Start 2022 Prime Pace Construction Company, **Net Change Order** 12 Pay Period End January 1, 2023 (\$555,639.62) Contractor Amount Current Contract Amount \$2,273,137.38

ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
424					the current Payment Estimate.			
	0090	MISC.	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',700.00000 - 700.00000, 'is applied (if non-zero).	1	\$700.00	\$700.00
	0110	6 IN. CONCRETE MEDIAN STRIP	Material			-27.9	\$240.00	(\$6,696.00)
	0110	6 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	27.9	\$240.00	\$6,696.00
	0120	PAVED APPROACH, 7 IN.	Material			-35.7	\$200.00	(\$7,140.00)
	0120	PAVED APPROACH, 7 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user bedarl2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	35.7	\$200.00	\$7,140.00
	0130	PAVED APPROACH, 8 IN.	Material			-20.7	\$245.00	(\$5,071.50)
(0130	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user bedarl2 overridding Payment Estimate Exception 8 on the current Payment Estimate.	20.7	\$245.00	\$5,071.50
	0140	CONCRETE SIDEWALK, 4 IN.	Material			-861	\$70.00	(\$60,270.00)
	0140	CONCRETE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user bedarl2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	861	\$70.00	\$60,270.00
	0150	MISC.	Material			-21	\$2,400.00	(\$50,400.00)
	0150	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	21	\$2,400.00	\$50,400.00
	0160	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material			-86	\$44.50	(\$3,827.00)
	0160	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user bedarl2 overridding Payment Estimate Exception 14 on the current Payment Estimate.	86	\$44.50	\$3,827.00
	0170	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	Material			-142	\$46.00	(\$6,532.00)
	0170	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 16 on the current Payment Estimate.	142	\$46.00	\$6,532.00
	0180	MISC.	Material			-402	\$44.50	(\$17,889.00)
	0180	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	402	\$44.50	\$17,889.00

Revision 4/1/2020 Page 2 of 29



Pay Estimate Created Date: January 3, 2023

Pay Period December 16, **Progress Estimate Contract ID** 220218-F07 Original Contract Amount \$2,828,777.00 Number Start 2022 Prime Pace Construction Company, **Net Change Order** 12 Pay Period End January 1, 2023 (\$555,639.62) Amount (\$555,639.62)

Current Contract Amount \$2,273,137.38 Contractor

ect per	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
24					Adjustment (0010) due to user bedarl2 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
	0190	MISC.	Material			-122	\$95.00	(\$11,590.00
	0190	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user bedarl2 overridding Payment Estimate Exception 21 on the current Payment Estimate.	122	\$95.00	\$11,590.00
	0270	CONCRETE TRAFFIC BARRIER, TYPE C (RETAINING WALL)	Material			-147	\$225.00	(\$33,075.00
	0270	CONCRETE TRAFFIC BARRIER, TYPE C (RETAINING WALL)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user bedarl2 overridding Payment Estimate Exception 23 on the current Payment Estimate.	147	\$225.00	\$33,075.00
C	0370	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-373	\$1.00	(\$373.00)
	0370	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user bedarl2 overridding Payment Estimate Exception 26 on the current Payment Estimate.	373	\$1.00	\$373.00
	0550	POST, SIGNAL 8 FT. OR 2.4 M	Material			-11	\$950.00	(\$10,450.00
	0550	POST, SIGNAL 8 FT. OR 2.4 M	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user bedarl2 overridding Payment Estimate Exception 28 on the current Payment Estimate.	11	\$950.00	\$10,450.00
	0560	VIDEO DETECTION SYSTEM	Material			-2	\$25,000.00	(\$50,000.00
	0560	VIDEO DETECTION SYSTEM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment Estimate Exception 31 on the current Payment Estimate.	2	\$25,000.00	\$50,000.00
	0570	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material			-64	\$14.00	(\$896.00)
	0570	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user bedarl2 overridding Payment Estimate Exception 32 on the current Payment Estimate.	64	\$14.00	\$896.00
	0580	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material			-156	\$35.00	(\$5,460.00
	0580	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user bedarl2 overridding Payment Estimate Exception 33 on the current Payment Estimate.	156	\$35.00	\$5,460.00
	0590	CABLE, 16 AWG 2 CONDUCTOR	Material			-2,340	\$1.05	(\$2,457.00)
	0590	CABLE, 16 AWG 2	Material		This adjustment offsets the original system-	2,340	\$1.05	\$2,457.00

Revision 4/1/2020 Page 3 of 29



Pay Estimate Created Date: January 3, 2023

Pay Period December 16, **Progress Estimate Contract ID** 220218-F07 Original Contract Amount \$2,828,777.00 Number Start 2022 Prime Pace Construction Company, **Net Change Order** 12 Pay Period End January 1, 2023 (\$555,639.62) Amount (\$555,639.62)

Current Contract Amount \$2,273,137.38 Contractor

Adjustment amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	Item Description	Line No.	Project Number
			generated Material Payment Estimate Item Adjustment (0018) due to user bedarl2 overridding Payment Estimate Exception 34 on the current Payment Estimate.			CONDUCTOR		J6I3424
\$2.50	\$1.25	2	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1.25000 - 1.25000, 'is applied (if non-zero).		Overrun	CABLE, 16 AWG 5 CONDUCTOR	0600	
(\$2,925.00)	\$1.25	-2,340			Material	CABLE, 16 AWG 5 CONDUCTOR	0600	
\$2,925.00	\$1.25	2,340	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 35 on the current Payment Estimate.		Material	CABLE, 16 AWG 5 CONDUCTOR	0600	
(\$14,880.00	\$3,100.00	-4.8			Material	BASE, CONCRETE	0610	
\$14,880.00	\$3,100.00	4.8	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment Estimate Exception 36 on the current Payment Estimate.		Material	BASE, CONCRETE	0610	
(\$13,412.00	\$958.00	-14			Material	MISC.	0630	
\$13,412.00	\$958.00	14	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user bedarl2 overridding Payment Estimate Exception 40 on the current Payment Estimate.		Material	MISC.	0630	
(\$6,580.00	\$470.00	-14			Material	MISC.	0640	
\$6,580.00	\$470.00	14	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user bedarl2 overridding Payment Estimate Exception 41 on the current Payment Estimate.		Material	MISC.	0640	
(\$204.00	\$204.00	-1			Material	MISC.	0650	
\$204.00	\$204.00	1	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user bedarl2 overridding Payment Estimate Exception 42 on the current Payment Estimate.		Material	MISC.	0650	
(\$600.00	\$3,000.00	-0.2			Material	CONCRETE FOOTINGS, EMBEDDED	0660	
\$600.00	\$3,000.00	0.2	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user bedarl2 overridding Payment Estimate Exception 43 on the current Payment Estimate.		Material	CONCRETE FOOTINGS, EMBEDDED	0660	
(\$700.00	\$10.00	-70			Material	PIPE POSTS	0670	
\$700.00	\$10.00	70	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user bedarl2 overridding Payment Estimate Exception 46 on the current Payment Estimate.		Material	PIPE POSTS	0670	
(\$400.00	\$40.00	-10			Material	2 IN. PSST POST - 12 GA.	0680	
\$400.00	\$40.00	10	This adjustment offsets the original system- generated Material Payment Estimate Item		Material	2 IN. PSST POST - 12 GA.	0680	

Revision 4/1/2020 Page 4 of 29



Pay Estimate Created Date: January 3, 2023

Progress Estimate Number	Contract ID	220218-F07	Pay Period Start	December 16, 2022	Original Contract Amount	\$2,828,777.00
12	Prime Contractor	Pace Construction Company, LLC	Pay Period End	d January 1, 2023	Net Change Order Amount Current Contract Amount	(\$555,639.62) \$2.273.137.38

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
J6I3424					Adjustment (0025) due to user bedarl2 overridding Payment Estimate Exception 47 on the current Payment Estimate.				
	0690	POST ANCHOR FOR 2 IN. PSST - 12 GA.	Material			-3	\$60.00	(\$180.00)	
	0690	POST ANCHOR FOR 2 IN. PSST - 12 GA.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user bedarl2 overridding Payment Estimate Exception 48 on the current Payment Estimate.	3	\$60.00	\$180.00	
Total								\$702.89	

Revision 4/1/2020 Page 5 of 29



	Contract Project Information												
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work								
J6I3424	I 70-5(347)	Coldmill and resurface	I-70	ST LOUIS CITY	from Branch St to Biddle St under I-44								

Totals by Job	Numbers			
J6I3424		This Estimate	Previous	To Date
	Posted Item Pay Gross Item Adjustments	(\$641.22) \$702.89	\$2,236,036.20 \$145,174.99	\$2,235,394.98 \$145,877.88
	Gross Item Pay	\$61.67	\$2,381,211.19	\$2,381,272.86
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	(\$7,650.00)	(\$7,650.00)
	Other Contract Adjustments	\$0.00	\$53,813.06	\$53,813.06

Revision 4/1/2020 Page 6 of 29



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 5021340, Project Item Line Number 0080, Material Set 502134096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 5021340, Project Item Line Number 0080, Material Set 502134096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 6083006, Project Item Line Number 0110, Material Set 608300696, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 6083006, Project Item Line Number 0110, Material Set 608300696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 6085007, Project Item Line Number 0120, Material Set 608500796, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 6085007, Project Item Line Number 0120, Material Set 608500796, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6085007, Project Item Line Number 0120, Material Set 608500796, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6085008, Project Item Line Number 0130, Material Set 608500896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6085008, Project Item Line Number 0130, Material Set 608500896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6i3424, Item 6086004, Project Item Line Number 0140, Material Set 608600496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6086004, Project Item Line Number 0140, Material Set 608600496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 6089902, Project Item Line Number 0150, Material Set 608990296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 6089902, Project Item Line Number 0150, Material Set 608990296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 6091010, Project Item Line Number 0160, Material Set 609101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6091010, Project Item Line Number 0160, Material Set 609101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6092021, Project Item Line Number 0170, Material Set 609202196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6092021, Project Item Line Number 0170, Material Set 609202196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 6099903, Project Item Line Number 0180, Material Set 6099903, Material 1057JMTBE42013 - Tie Bar Ep Ctd 12" No. 4/M13 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 6099903, Project Item Line Number 0180, Material Set 6099903, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 6099903, Project Item Line Number 0180, Material Set 6099903, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 6099903, Project Item Line Number 0190, Material Set 6099903, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 6099903, Project Item Line Number 0190, Material Set 6099903, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 6173001, Project Item Line Number 0270, Material Set 6173001, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 6173001, Project Item Line Number 0270, Material Set 6173001, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO,	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden

Revision 4/1/2020 Page 7 of 29



Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 100510CPCMLD is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6173001, Project Item Line Number 0270, Material Set 6173001, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 6205901A, Project Item Line Number 0370, Material Set 6205901A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 6205901A, Project Item Line Number 0370, Material Set 6205901A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 9022708, Project Item Line Number 0550, Material Set 902270896, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9022708, Project Item Line Number 0550, Material Set 902270896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 9022708, Project Item Line Number 0550, Material Set 902270896, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 9024975, Project Item Line Number 0560, Material Set 902497596, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9025300, Project Item Line Number 0570, Material Set 902530096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9027300, Project Item Line Number 0580, Material Set 902730096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9028308, Project Item Line Number 0590, Material Set 902830896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9028310, Project Item Line Number 0600, Material Set 902831096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 9029902, Project Item Line Number 0630, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 9029902, Project Item Line Number 0640, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9029902, Project Item Line Number 0650, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9031010, Project Item Line Number 0660, Material Set 903101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9031010, Project Item Line Number 0660, Material Set 903101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9031010, Project Item Line Number 0660, Material Set 903101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9031220, Project Item Line Number 0670, Material Set 903122096, Material 0903HSPSPI - Pipe Post for Highway Signing, Acceptance Action Generic 0903HSPSPI is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9031270A, Project Item Line Number 0680, Material Set 9031270A96, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Working with MoDOT Material Department and the Contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9031271, Project Item Line	Working with MoDOT Material Department and the Contractor	bedarl2	Overridden

Revision 4/1/2020 Page 8 of 29



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Number 0690, Material Set 903127196, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	to get this updated.		
Estimate Exception Type: Item Overrun: Contract 220218-F07, Contract Project J6l3424, Project Item Line Number 0370, Contract Line Item Number 0370, Item 6205901A, Minor Item.	Pending Change Order #3	bedarl2	Acknowledged

Revision 4/1/2020 Page 9 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract	Project	Category	Line	Item	Report Generated date and can differ from the posted an Description	Bid	Net	Total	S Gener Unit	Total	Unit Price	Total Value POSTED
Nm.CONTRACT	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)
220218-F07	J6I3424	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$53,771.65	\$53,771.65
		0001	0020	2072000	LINEAR GRADING CLASS 2	5.70	0.00	5.70	STA	5.70	\$2,000.00	\$11,400.00
		0001	0030	2153000	SHAPING SLOPES, CLASS III	8.00	-5.00	3.00	100F	1.00	\$1,400.00	\$1,400.00
		0001	0040	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	145.00	-12.00	133.00	SQYD	133.00	\$3.00	\$399.00
		0001	0050	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	1,827.20	-606.20	1,221.00	TONS	1,221.00	\$82.25	\$100,427.25
		0001	0060	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	9,175.80	-2,119.80	7,056.00	TONS	7,056.00	\$131.50	\$927,864.00
		0001	0070	4071005	TACK COAT	17,772.00	-11,542.00	6,230.00	GAL	6,230.00	\$2.30	\$14,329.00
		0001	0800	5021340	TYPE A2 SHOULDER	145.30	-12.00	133.30	SQYD	133.30	\$160.00	\$21,328.00
		0001	0090	6049902	MISC.PULLBOX ADJUSTMENT	8.00	0.00	8.00	EA	8.00	\$700.00	\$5,600.00
		0001	0100	6049902	MISC.INLET TOP REPLACEMENT	2.00	-2.00	0.00	EA	0.00	\$1,300.00	\$0.00
		0001	0110	6083006	6 IN. CONCRETE MEDIAN STRIP	27.90	0.00	27.90	SQYD	27.90	\$240.00	\$6,696.00
		0001	0120	6085007	PAVED APPROACH, 7 IN.	15.00	0.00	15.00	SQYD	15.00	\$200.00	\$3,000.00
		0001	0130	6085008	PAVED APPROACH, 8 IN.	20.70	0.00	20.70	SQYD	20.70	\$245.00	\$5,071.50
		0001	0140	6086004	CONCRETE SIDEWALK, 4 IN.	861.00	0.00	861.00	SQYD	861.00	\$70.00	\$60,270.00
		0001	0150	6089902	MISC.ADA CURB RAMP	22.00	0.00	22.00	EA	21.00	\$2,400.00	\$50,400.00
		0001	0160	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	86.00	0.00	86.00	LF	86.00	\$44.50	\$3,827.00
		0001	0170	6092021	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	142.00	0.00	142.00	LF	142.00	\$46.00	\$6,532.00
		0001	0180	6099903	MISC.CONCRETE CURB UNDER GUARDRAIL	1,106.00	-704.00	402.00	LF	402.00	\$44.50	\$17,889.00
		0001	0190	6099903	MISC.MODIFIED TYPE A INTEGRAL CURB (OVER 6 IN HEIGHT) DOWELED ON CONCRETE	122.00	0.00	122.00	LF	122.00	\$95.00	\$11,590.00
		0001	0200	6119907	MISC.FURNISHING MODIFIED ROCK BLANKET	238.00	0.00	238.00	CUYD	134.00	\$31.00	\$4,154.00
		0001	0210	6119907	MISC.PLACING MODIFIED ROCK BLANKET	238.00	0.00	238.00	CUYD	134.00	\$30.00	\$4,020.00
		0001	0220	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0230	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	145.00	-12.00	133.00	SQYD	133.00	\$20.00	\$2,660.00
		0001	0240	6169901	MISC.TEMP TRAFFIC CONTROL	1.00	0.00	1.00	LS	1.00	\$13,927.00	\$13,927.00
		0001	0250	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN CONTRACTOR FURNISHED/RETAINED	2.00	2.00	4.00	EA	4.00	\$2,850.00	\$11,400.00
		0001	0260	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	18.00	-18.00	0.00	LF	0.00	\$455.00	\$0.00
		0001	0270	6173001	CONCRETE TRAFFIC BARRIER, TYPE C (RETAINING WALL)	147.00	0.00	147.00	LF	147.00	\$225.00	\$33,075.00
		0001	0280	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$290,000.00	\$290,000.00
		0001	0290	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	37.00	0.00	37.00	LF	37.00	\$10.00	\$370.00
		0001	0300	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	709.00	0.00	709.00	LF	649.00	\$20.00	\$12,980.00
		0001	0310	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	7.00	0.00	7.00	EA	6.00	\$300.00	\$1,800.00
		0001	0320	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	6.00	0.00	6.00	EA	4.00	\$300.00	\$1,200.00
		0001	0330	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	3.00	0.00	3.00	EA	3.00	\$550.00	\$1,650.00
		0001	0340	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	3.00	0.00	3.00	EA	2.00	\$550.00	\$1,100.00
		0001	0350	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	91.00	0.00	91.00	EA	39.00	\$180.00	\$7,020.00
		0001	0360	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	14.00	0.00	14.00	EA	14.00	\$55.00	\$770.00
		0001	0370	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	240.00	0.00	240.00	LF	373.00	\$1.00	\$373.00
		0001	0380	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	27,957.00	0.00	27,957.00	LF	26,411.00	\$0.30	\$7,923.30
		0001	0390	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	19,604.00	0.00	19,604.00	LF	6,592.00	\$0.30	\$1,977.60
		0001	0400	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,025.00	0.00	7,025.00	LF	3,575.00	\$1.00	\$3,575.00
		0001	0410	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	2.00	0.00	2.00	EA	2.00	\$250.00	\$500.00
		0001	0420	6209901	MISC.Temporary Pavement Marking Paint	1.00	0.00	1.00	LS	1.00	\$9,600.00	\$9,600.00
		0001	0430	6209902	MISC.INLAID PAVEMENT MARKERS	330.00	-129.00	201.00	EA	201.00	\$40.00	\$8,040.00

Revision 4/1/2020 Page 10 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220218-F07	J6I3424	0001	0440	6209902	MISC.PREFORMED THERMOPLASTIC SOLID WHITE LANE DROP MERGE LEFT ARROW	4.00	0.00	4.00	EA	2.00	\$1,500.00	\$3,000.00
		0001	0450	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	94,037.00	-31,189.00	62,848.00	SQYD	62,848.00	\$2.90	\$182,259.20
		0001	0460	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	4,750.00	-782.90	3,967.10	SQYD	3,967.10	\$4.75	\$18,843.72
		0001	0470	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	475.00	0.00	475.00	SQYD	475.00	\$1.95	\$926.25
		0001	0480	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	280.00	-127.50	152.50	STA	152.50	\$54.00	\$8,235.00
		0001	0490	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$1,500.00	\$1,500.00
		0010	0500	6061060	MGS GUARDRAIL	2,700.00	-737.50	1,962.50	LF	1,962.50	\$39.00	\$76,537.50
		0010	0510	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	15.00	-4.00	11.00	EA	11.00	\$3,900.00	\$42,900.00
		0010	0520	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	2.00	0.00	2.00	EA	2.00	\$3,800.00	\$7,600.00
		0010	0530	6061080	MGS END ANCHOR	5.00	-1.00	4.00	EA	4.00	\$1,600.00	\$6,400.00
		0010	0540	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	10.00	0.00	10.00	EA	9.00	\$3,300.00	\$29,700.00
		0030	0550	9022708	POST, SIGNAL 8 FT. OR 2.4 M	11.00	0.00	11.00	EA	11.00	\$950.00	\$10,450.00
		0030	0560	9024975	VIDEO DETECTION SYSTEM	2.00	0.00	2.00	EA	2.00	\$25,000.00	\$50,000.00
		0030	0570	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	64.00	0.00	64.00	LF	64.00	\$14.00	\$896.00
		0030	0580	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	156.00	0.00	156.00	LF	156.00	\$35.00	\$5,460.00
		0030	0590	9028308	CABLE, 16 AWG 2 CONDUCTOR	2,340.00	0.00	2,340.00	LF	2,340.00	\$1.05	\$2,457.00
		0030	0600	9028310	CABLE, 16 AWG 5 CONDUCTOR	2,340.00	0.00	2,340.00	LF	2,340.00	\$1.25	\$2,925.00
		0030	0610	9029100	BASE, CONCRETE	4.80	0.00	4.80	CUYD	4.80	\$3,100.00	\$14,880.00
		0030	0620	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING	1.00	0.00	1.00	LS	1.00	\$27,000.00	\$27,000.00
		0030	0630	9029902	MISC.APS-AUDIBLE PEDESTRIAN PUSH BUTTON & SIGNING	14.00	0.00	14.00	EA	14.00	\$958.00	\$13,412.00
		0030	0640	9029902	MISC.COUNTDOWN PEDESTRIAN SIGNAL HEAD, TYPE 1 S	14.00	0.00	14.00	EA	14.00	\$470.00	\$6,580.00
		0030	0650	9029902	MISC.PUSH BUTTON EXTENSION	2.00	0.00	2.00	EA	1.00	\$204.00	\$204.00
		0040	0660	9031010	CONCRETE FOOTINGS, EMBEDDED	0.20	0.00	0.20	CUYD	0.20	\$3,000.00	\$600.00
		0040	0670	9031220	PIPE POSTS	70.00	0.00	70.00	LB	70.00	\$10.00	\$700.00
		0040	0680	9031270A	2 IN. PSST POST - 12 GA.	10.00	0.00	10.00	LF	10.00	\$40.00	\$400.00
		0040	0690	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	3.00	0.00	3.00	LF	3.00	\$60.00	\$180.00
		0040	0700	9035004A	SH-FLAT SHEET	11.00	0.00	11.00	SQFT	11.00	\$40.00	\$440.00
		0050	0710	9109903	MISC.MODOT ITS ASSETS RELOCATION	138.00	-138.00	0.00	LF	0.00	\$19.50	\$0.00
	Project .	1613424 - To	tal Value	Posted to D	Pate as of Report Generated Date							\$2,235,394.98
220218-F07 Ove	erall - Tota	Value Pos	ted to Da	ate as of Rep	ort Generated Date							\$2,235,394.98

Revision 4/1/2020 Page 11 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: J6I3424

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0060	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP1	12/27/22	1/3/23	0.45	TONS		0+00				Final rounding
0090	6049902	MISC. DRAINAGE ITEM	12/27/22	1/3/23	-1.00	EA	Overpayment of 1.					
0590	9028308	CABLE, 16 AWG 2 CONDUCTOR	12/27/22	1/3/23	2.00	LF		0+00				Final rounding
0600	9028310	CABLE, 16 AWG 5 CONDUCTOR	12/27/22	1/3/23	-2.00	LF	Overpayment of 2 LF					

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 12 of 29



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J6I3424	0040	TYPE 5 AGGREGATE	Price FUEL		8	Nov 2, 2022	SYSTEM	\$13.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
		FOR BASE			9	Nov 17, 2022	SYSTEM	(\$0.07)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
				- Total				\$12.93														
			Price FUEL -	Total				\$12.93														
	0040 -	Total						\$12.93														
	0050	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Other Item Adjustment	ACAD	6	Oct 3, 2022	bedarl2	\$9,098.57	BP-1 21-16 Second Period September 2022													
		1 004-22 (BI -1)			9	Nov 17, 2022	bedarl2	\$148.69	BP-1 First Period of November													
				ACAD - Tot	al			\$9,247.26														
			Other Item A	.djustment - T	otal			\$9,247.26														
			Overrun	Overrun	9	Nov 17, 2022	SYSTEM	(\$2,177.43)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
					11	Dec 15, 2022	SYSTEM	\$2,177.43	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',87.09720 - 82.25000, 'is applied (if non-zero).													
				Overrun - T	otal			\$0.00														
			Overrun - To	tal				\$0.00														
			Price FUEL		6	Oct 3, 2022	SYSTEM	\$5,719.95	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
					7	Oct 17, 2022	SYSTEM	(\$0.95)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
					9	Nov 17, 2022	SYSTEM	\$121.18	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
				- Total				\$5,840.18														
			Price FUEL -	Total				\$5,840.18														
	0050 -							\$15,087.44														
	0060	ASPHALTIC CONCRETE MIXTURE PG	Material		5	Sep 16, 2022	SYSTEM	\$806,292.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
		76-22 (SP1																5	Sep 16, 2022	SYSTEM	(\$806,292.25)	
														6	Oct 3, 2022	SYSTEM	\$927,804.82	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					6	Oct 3, 2022	SYSTEM	(\$927,804.82)														
				- Total				\$0.00														
			Material - To	tal				\$0.00														
			Other Item Adjustment	ACAD	6	Oct 3, 2022	bedarl2	\$83,694.14	SP125 21-17 First Period September 2022													
					6	Oct 3, 2022	bedarl2	\$12,611.45	SP125 21-17 Second Period September 2022													
				ACAD - Tot	al			\$96,305.59														
			Other Item A	.djustment - T				\$96,305.59														
			Price FUEL		5	Sep 16, 2022	SYSTEM	\$29,313.47	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
					6	Oct 3,	SYSTEM	\$4,417.70	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
						2022																
					12	Jan 3, 2023	SYSTEM	\$0.39	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
				- Total		Jan 3,	SYSTEM	\$33,731.56	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
			Price FUEL -			Jan 3,	SYSTEM	\$33,731.56 \$33,731.56	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
	0060 -	Total	Price FUEL -			Jan 3,	SYSTEM	\$33,731.56	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
	0060 - 0070	Total TACK COAT	Price FUEL -			Jan 3,	SYSTEM	\$33,731.56 \$33,731.56	Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user bedarl2 overridding Payment Estimate Exception 2 on the current Payment Estimate.													



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
24	0070	TACK COAT	Material			2022					
				- Total				\$0.00			
			Material - Tot	tal				\$0.00			
			Overrun	Overrun	9	Nov 17, 2022	SYSTEM	(\$115.00)			
					11	Dec 15, 2022	SYSTEM	\$115.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.30000 - 2.30000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - To	tal				\$0.00			
	0070 -	Total						\$0.00			
	0800	TYPE A2 SHOULDER	Material		8	Nov 2, 2022	SYSTEM	\$21,328.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					8	Nov 2, 2022	SYSTEM	(\$21,328.00)			
					9	Nov 17, 2022	SYSTEM	\$21,328.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					9	Nov 17, 2022	SYSTEM	(\$21,328.00)			
					10	Dec 2, 2022	SYSTEM	\$21,328.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user bedarl2 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
							10	Dec 2, 2022	SYSTEM	(\$21,328.00)	
					11	Dec 15, 2022	SYSTEM	\$21,328.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					11	Dec 15, 2022	SYSTEM	(\$21,328.00)			
					12	Jan 3, 2023	SYSTEM	\$21,328.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					12	Jan 3, 2023	SYSTEM	(\$21,328.00)			
				- Total				\$0.00			
			Material - Tot	tal				\$0.00			
	0080 -	Total						\$0.00			
	0090	MISC. DRAINAGE ITEM	Material		8	Nov 2, 2022	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					8	Nov 2, 2022	SYSTEM	(\$700.00)			
				- Total				\$0.00			
			Material - Tot	tal				\$0.00			
			Overrun	Overrun	9	Nov 17, 2022	SYSTEM	(\$700.00)			
					12	Jan 3, 2023	SYSTEM	\$700.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',700.00000 - 700.00000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - To	tal				\$0.00			
	0090 -	Total						\$0.00			
	0110	6 IN. CONCRETE MEDIAN STRIP	Material		11	Dec 15, 2022	SYSTEM	\$6,696.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bedarl2 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					11	Dec 15, 2022	SYSTEM	(\$6,696.00)			
					12	Jan 3, 2023	SYSTEM	\$6,696.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment Estimate Exception 3 on the current Payment Estimate.		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J6I3424	0110	6 IN. CONCRETE	Material		12	Jan 3, 2023	SYSTEM	(\$6,696.00)			
		MEDIAN STRIP		- Total				\$0.00			
			Material - To	tal				\$0.00			
	0110 -	Total						\$0.00			
	0120	PAVED APPROACH, 7 IN.	Material		8	Nov 2, 2022	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bedarl2 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
					8	Nov 2, 2022	SYSTEM	(\$7,140.00)			
					9	Nov 17, 2022	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
						9	Nov 17, 2022	SYSTEM	(\$7,140.00)		
					10	Dec 2, 2022	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user bedarl2 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					10	Dec 2, 2022	SYSTEM	(\$7,140.00)			
						11	Dec 15, 2022	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user bedarl2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
						11	Dec 15, 2022	SYSTEM	(\$7,140.00)		
					12	Jan 3, 2023	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user bedarl2 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
					12	Jan 3, 2023	SYSTEM	(\$7,140.00)			
				- Total				\$0.00			
			Material - Tot	aterial - Total				\$0.00			
			Overrun	Overrun	8	Nov 2, 2022	SYSTEM	(\$4,147.40)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
					11	Dec 15, 2022	SYSTEM	\$4,147.40	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',200.35749 - 200.00000, 'is applied (if non-zero).		
				Overrun - To	otal			\$0.00			
			Overrun - To	tal				\$0.00			
			Price FUEL	Price FUEL	Price FUEL		8	Nov 2, 2022	SYSTEM	\$12.76	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					11	Dec 15, 2022	SYSTEM	(\$2.96)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
				- Total				\$9.80			
			Price FUEL -	Total				\$9.80			
	0120 -	Total						\$9.80			
	0130	PAVED APPROACH, 8 IN.	Material		11	Dec 15, 2022	SYSTEM	\$5,071.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user bedarl2 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
					11	Dec 15, 2022	SYSTEM	(\$5,071.50)			
					12	Jan 3, 2023	SYSTEM	\$5,071.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user bedarl2 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
					12	Jan 3, 2023	SYSTEM	(\$5,071.50)			
				- Total				\$0.00			
			Material - Tot	tal				\$0.00			
			Price FUEL		11	Dec 15, 2022	SYSTEM	\$3.23	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
				- Total				\$3.23			
			Price FUEL -	Total				\$3.23			



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
13424	0130 -	Total		,				\$3.23		
	0140	CONCRETE SIDEWALK, 4 IN.	Material		8	Nov 2, 2022	SYSTEM	\$57,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					8	Nov 2, 2022	SYSTEM	(\$57,120.00)		
						9	Nov 17, 2022	SYSTEM	\$60,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bedarl2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$60,270.00)		
						10	Dec 2, 2022	SYSTEM	\$60,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$60,270.00)		
					11	Dec 15, 2022	SYSTEM	\$60,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					11	Dec 15, 2022	SYSTEM	(\$60,270.00)		
					12	Jan 3, 2023	SYSTEM	\$60,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bedarl2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					12	Jan 3, 2023	SYSTEM	(\$60,270.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0140 -	Total						\$0.00		
	0150		Material	Material		8	Nov 2, 2022	SYSTEM	\$31,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user bedarl2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
								8	Nov 2, 2022	SYSTEM
					9	Nov 17, 2022	SYSTEM	\$50,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					9	Nov 17, 2022	SYSTEM	(\$50,400.00)		
					10	Dec 2, 2022	SYSTEM	\$50,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user bedarl2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					10	Dec 2, 2022	SYSTEM	(\$50,400.00)		
					11	Dec 15, 2022	SYSTEM	\$50,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bedarl2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					11	Dec 15, 2022	SYSTEM	(\$50,400.00)		
					12	Jan 3, 2023	SYSTEM	\$50,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					12	Jan 3, 2023	SYSTEM	(\$50,400.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0150 -	Total						\$0.00		
	0160	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	Material		8	Nov 2, 2022	SYSTEM	\$2,714.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user bedarl2 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
		UNDER)			8	Nov 2, 2022	SYSTEM	(\$2,714.50)		
					9	Nov 17, 2022	SYSTEM	\$3,827.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user bedarl2 overridding Payment Estimate Exception 13 on the current Payment Estimate.	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3424	0160	CONCRETE CURB (6 IN.	Material		9	Nov 17, 2022	SYSTEM	(\$3,827.00)	
		HEIGHT AND UNDER)			10	Dec 2, 2022	SYSTEM	\$3,827.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user bedarl2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$3,827.00)	
					11	Dec 15, 2022	SYSTEM	\$3,827.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					11	Dec 15, 2022	SYSTEM	(\$3,827.00)	
					12	Jan 3, 2023	SYSTEM	\$3,827.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bedarl2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$3,827.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0160 -	Total						\$0.00	
	0170	INTEGRAL CURB (OVER 6 IN. HEIGHT)	Material		8	Nov 2, 2022	SYSTEM	\$6,210.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bedarl2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
		TYPE A			8	Nov 2, 2022	SYSTEM	(\$6,210.00)	
					9	Nov 17, 2022	SYSTEM	\$6,532.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user bedarl2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$6,532.00)	
					10	Dec 2, 2022	SYSTEM	\$6,532.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bedarl2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$6,532.00)	
					11	Dec 15, 2022	SYSTEM	\$6,532.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user bedarl2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					11	Dec 15, 2022	SYSTEM	(\$6,532.00)	
					12	Jan 3, 2023	SYSTEM	\$6,532.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$6,532.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0170 -	Total						\$0.00	
	0180	MISC. PAVED DRAINAGE	Material		8	Nov 2, 2022	SYSTEM	\$17,889.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user bedarl2 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					8	Nov 2, 2022	SYSTEM	(\$17,889.00)	
					9	Nov 17, 2022	SYSTEM	\$17,889.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bedarl2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$17,889.00)	
					10	Dec 2, 2022	SYSTEM	\$17,889.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$17,889.00)	
					11	Dec 15, 2022	SYSTEM	\$17,889.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user bedarl2 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
612424	0400	MISC. PAVED	Matarial	Туре					Catimate Evention 40 on the gureant Dayment Estimate
613424	0180	DRAINAGE	Material		11	Dec 15,	SYSTEM	(\$17,889.00)	Estimate Exception 18 on the current Payment Estimate.
						2022		(\$11,000.00)	
					12	Jan 3, 2023	SYSTEM	\$17,889.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user bedarl2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$17,889.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0180 -	Total						\$0.00	
	0190	MISC. PAVED DRAINAGE	Material		11	Dec 15, 2022	SYSTEM	\$11,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bedarl2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					11	Dec 15, 2022	SYSTEM	(\$11,590.00)	
					12	Jan 3, 2023	SYSTEM	\$11,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user bedarl2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$11,590.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0190 -	Total						\$0.00	
	0200	MISC. EMBANKMENT PROTECTION	Material		8	Nov 2, 2022	SYSTEM	\$7,357.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user bedarl2 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					8	Nov 2, 2022	SYSTEM	(\$7,357.85)	
					9	Nov 17, 2022	SYSTEM	\$4,154.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user bedarl2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$4,154.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0200 -				-			\$0.00	
	0230	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEM	Material		8	Nov 2, 2022	SYSTEM	\$2,666.00	This adjustment offsets the original system-generated Material Payment
		/: \(\neg \neq \neq \neq \neq \neq \neq \neq \neq							Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					8	Nov 2, 2022	SYSTEM	(\$2,666.00)	
				- Total	8		SYSTEM	(\$2,666.00)	
			Material - To		8		SYSTEM	(, , ,	
	0230 -	Total	Material - To		8		SYSTEM	\$0.00	
	0230 - 0240	Total MISC.	Material - To		5		SYSTEM	\$0.00 \$0.00	
						2022 Sep 16,		\$0.00 \$0.00 \$0.00	Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment
					5	2022 Sep 16, 2022 Sep 16,	SYSTEM	\$0.00 \$0.00 \$0.00 \$6,963.50	Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment
				tal - Total	5	2022 Sep 16, 2022 Sep 16,	SYSTEM	\$0.00 \$0.00 \$0.00 \$6,963.50 (\$6,963.50)	Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment
		MISC.	Material	tal - Total	5	2022 Sep 16, 2022 Sep 16,	SYSTEM	\$0.00 \$0.00 \$0.00 \$6,963.50 (\$6,963.50)	Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment
	0240	MISC. Total MISC. TRAFFIC CONTROL	Material	tal - Total	5	2022 Sep 16, 2022 Sep 16,	SYSTEM	\$0.00 \$0.00 \$0.00 \$6,963.50 (\$6,963.50) \$0.00	Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment
	0240	MISC. Total MISC. TRAFFIC	Material Material - To	- Total	5	2022 Sep 16, 2022 Sep 16, 2022	SYSTEM	\$0.00 \$0.00 \$0.00 \$6,963.50 (\$6,963.50) \$0.00 \$0.00	Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment
	0240	MISC. Total MISC. TRAFFIC CONTROL	Material Material - To	- Total	5 5 6 7	2022 Sep 16, 2022 Sep 16, 2022 Oct 3, 2022 Oct 17,	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$6,963.50 (\$6,963.50) \$0.00 \$0.00 (\$5,700.00)	Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment Estimate Exception 3 on the current Payment Estimate. Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of 1,2850.00000 - 2850.00000,
	0240	MISC. Total MISC. TRAFFIC CONTROL	Material Material - To	- Total tal Overrun	5 5 6 7	2022 Sep 16, 2022 Sep 16, 2022 Oct 3, 2022 Oct 17,	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$6,963.50 (\$6,963.50) \$0.00 \$0.00 (\$5,700.00)	Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment Estimate Exception 3 on the current Payment Estimate. Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of 1,2850.00000 - 2850.00000,



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3424	0270	CONCRETE TRAFFIC BARRIER, TYPE	Material		8	Nov 2, 2022	SYSTEM	\$33,075.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user bedarl2 overridding Payment Estimate Exception 34 on the current Payment Estimate.
		C (RETAINING WALL)			8	Nov 2, 2022	SYSTEM	(\$33,075.00)	
					9	Nov 17, 2022	SYSTEM	\$33,075.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user bedarl2 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$33,075.00)	
					10	Dec 2, 2022	SYSTEM	\$33,075.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bedarl2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$33,075.00)	
					11	Dec 15, 2022	SYSTEM	\$33,075.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user bedarl2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					11	Dec 15, 2022	SYSTEM	(\$33,075.00)	
					12	Jan 3, 2023	SYSTEM	\$33,075.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bedarl2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$33,075.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0270 -	· Total						\$0.00	
	0290	PREF THERMO PAVMT MARKING, 6 IN WHITE	Material		9	Nov 17, 2022	SYSTEM	\$370.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user bedarl2 overridding Payment Estimate Exception 26 on the current Payment Estimate.
		******			9	Nov 17, 2022	SYSTEM	(\$370.00)	
				- Total				\$0.00	
			Material - To					\$0.00	
	0290 -	· Total	Material - To						
	0290 -	PREF THERMO PVMT MARK, 24 IN WHIT			7	Oct 17, 2022	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		PREF THERMO PVMT MARK, 24			7		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment
		PREF THERMO PVMT MARK, 24				2022 Oct 17,		\$0.00 \$0.00 \$2,800.00	Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment
1		PREF THERMO PVMT MARK, 24			7	2022 Oct 17, 2022 Nov 2,	SYSTEM	\$0.00 \$0.00 \$2,800.00 (\$2,800.00)	Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user bedarl2 overridding Payment
		PREF THERMO PVMT MARK, 24			7	Oct 17, 2022 Nov 2, 2022 Nov 2,	SYSTEM	\$0.00 \$0.00 \$2,800.00 (\$2,800.00) \$2,800.00	Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user bedarl2 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
		PREF THERMO PVMT MARK, 24			7 8	Oct 17, 2022 Nov 2, 2022 Nov 2, 2022 Nov 17,	SYSTEM SYSTEM	\$0.00 \$0.00 \$2,800.00 (\$2,800.00) \$2,800.00	Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user bedarl2 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment
		PREF THERMO PVMT MARK, 24	Material	- Total	7 8 8 9	2022 Oct 17, 2022 Nov 2, 2022 Nov 17, 2022 Nov 17,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$2,800.00 (\$2,800.00) \$2,800.00 (\$2,800.00) \$12,260.00	Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user bedarl2 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment
	0300	PREF THERMO PVMT MARK, 24 IN WHIT		- Total	7 8 8 9	2022 Oct 17, 2022 Nov 2, 2022 Nov 17, 2022 Nov 17,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$2,800.00 (\$2,800.00) \$2,800.00 (\$2,800.00) \$12,260.00 (\$12,260.00) \$0.00	Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user bedarl2 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment
	0300 -	PREF THERMO PVMT MARK, 24 IN WHIT	Material - To	- Total	7 8 8 9 9	2022 Oct 17, 2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$2,800.00 (\$2,800.00) \$2,800.00 (\$2,800.00) \$12,260.00) \$0.00 \$0.00	Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user bedarl2 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment Estimate Exception 27 on the current Payment Estimate.
	0300	PREF THERMO PVMT MARK, 24 IN WHIT	Material - To	- Total	7 8 8 9 9	2022 Oct 17, 2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022 Oct 17, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$2,800.00 (\$2,800.00) \$2,800.00 (\$12,260.00) \$0.00 \$0.00 \$1,500.00	Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user bedarl2 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment
	0300 -	PREF THERMO PVMT MARK, 24 IN WHIT Total PREF THERMO PVMT MARK,	Material - To	- Total	7 8 8 9 9	2022 Oct 17, 2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022 Oct 17,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$2,800.00 (\$2,800.00) \$2,800.00 (\$2,800.00) \$12,260.00) \$0.00 \$0.00	Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user bedarl2 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user bedarl2 overridding Payment Estimate Item Adjustment (0004) due to user bedarl2 overridding Payment Estimate Item Adjustment (0004) due to user bedarl2 overridding Payment
	0300 -	PREF THERMO PVMT MARK, 24 IN WHIT Total PREF THERMO PVMT MARK,	Material - To	- Total	7 8 8 9 9	2022 Oct 17, 2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022 Oct 17, 2022 Oct 17, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$2,800.00 (\$2,800.00) \$2,800.00 (\$12,260.00) \$0.00 \$0.00 \$1,500.00	Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user bedarl2 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user bedarl2 overridding Payment Estimate Item Adjustment (0004) due to user bedarl2 overridding Payment Estimate Item Adjustment (0004) due to user bedarl2 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3424	0310	PREF THERMO PVMT MARK, LT/RT ARROW	Material		9	Nov 17, 2022	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user bedarl2 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$1,500.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0310 -	Total						\$0.00	
	0320	PREF THERMO PVMT MRKG, STRIAGHT ARROW	Material		7	Oct 17, 2022	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user bedarl2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		ARROW			7	Oct 17, 2022	SYSTEM	(\$1,200.00)	
					8	Nov 2, 2022	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					8	Nov 2, 2022	SYSTEM	(\$1,200.00)	
					9	Nov 17, 2022	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user bedarl2 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$1,200.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0320 -	Total						\$0.00	
	0330	PREF THERMO PVMT MARKING,	Material		7	Oct 17, 2022	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bedarl2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		COMBO			7	Oct 17, 2022	SYSTEM	(\$1,100.00)	
					8	Nov 2, 2022	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user bedarl2 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					8	Nov 2, 2022	SYSTEM	(\$1,100.00)	
					9	Nov 17, 2022	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user bedarl2 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$1,100.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0330 -	Total						\$0.00	
	0340	PREF THERMO PVMT MARK, WORD (ONLY)	Material		7	Oct 17, 2022	SYSTEM	\$550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Oct 17, 2022	SYSTEM	(\$550.00)	
					8	Nov 2, 2022	SYSTEM	\$550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user bedarl2 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					8	Nov 2, 2022	SYSTEM	(\$550.00)	
					9	Nov 17, 2022	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$1,100.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0340 -	Total						\$0.00	
	0350	PREF THERMO	Material		9	Nov 17,	SYSTEM	\$5,400.00	This adjustment offsets the original system-generated Material Payment



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
124	0350	PVMT MARK, 30" WHT MIDBL	Material			2022			Estimate Item Adjustment (0020) due to user bedarl2 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$5,400.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0350 -	Total						\$0.00	
	0360	PREF THERMO PVMT MARK, YIELD TRIAN	Material		9	Nov 17, 2022	SYSTEM	\$770.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user bedarl2 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$770.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0360 -	Total						\$0.00	
	0370	4 IN. YELLOW HIGH BUILD WATERBORNE	Material		11	Dec 15, 2022	SYSTEM	\$373.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment Estimate Exception 26 on the current Payment Estimate.
		PAINT			11	Dec 15, 2022	SYSTEM	(\$373.00)	
					12	Jan 3, 2023	SYSTEM	\$373.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user bedarl2 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$373.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	11	Dec 15, 2022	SYSTEM	(\$133.00)	
				Overrun - T	otal			(\$133.00)	
			Overrun - To	tal				(\$133.00)	
	0370 -	Total						(\$133.00)	
		6 IN. WHITE							
	0380	HIGH BUILD WATERBORNE	Material		10	Dec 2, 2022	SYSTEM	\$7,082.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 25 on the current Payment Estimate.
	0380	HIGH BUILD	Material		10		SYSTEM	\$7,082.10 (\$7,082.10)	Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment
	0380	HIGH BUILD WATERBORNE	Material	- Total		2022 Dec 2,			Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment
	0380	HIGH BUILD WATERBORNE	Material - To			2022 Dec 2,		(\$7,082.10)	Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment
	0380	HIGH BUILD WATERBORNE			10	2022 Dec 2,		(\$7,082.10) \$0.00	Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment
	0380	HIGH BUILD WATERBORNE	Material - To	tal	10	Dec 2, 2022 Dec 15,	SYSTEM	(\$7,082.10) \$0.00 \$0.00	Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 25 on the current Payment Estimate. 105% = .015 extra per 10,886.500 LF = \$ 163.30 extra 80% = .06 deduct per 12,566.90 LF = \$ -754.01 deduct
	0380	HIGH BUILD WATERBORNE	Material - To Other Item Adjustment	tal REFL	10	Dec 2, 2022 Dec 15,	SYSTEM	(\$7,082.10) \$0.00 \$0.00 (\$590.71)	Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 25 on the current Payment Estimate. 105% = .015 extra per 10,886.500 LF = \$ 163.30 extra 80% = .06 deduct per 12,566.90 LF = \$ -754.01 deduct
	0380 -	HIGH BUILD WATERBORNE PAINT	Material - To Other Item Adjustment	REFL - Tota	10	Dec 2, 2022 Dec 15,	SYSTEM	(\$7,082.10) \$0.00 \$0.00 (\$590.71)	Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 25 on the current Payment Estimate. 105% = .015 extra per 10,886.500 LF = \$ 163.30 extra 80% = .06 deduct per 12,566.90 LF = \$ -754.01 deduct
		HIGH BUILD WATERBORNE PAINT Total 6 IN. YELLOW HIGH BUILD WATERBORNE	Material - To Other Item Adjustment	REFL - Tota	10	Dec 2, 2022 Dec 15,	SYSTEM	(\$7,082.10) \$0.00 \$0.00 (\$590.71) (\$590.71)	Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 25 on the current Payment Estimate. 105% = .015 extra per 10,886.500 LF = \$ 163.30 extra 80% = .06 deduct per 12,566.90 LF = \$ -754.01 deduct
	0380 -	HIGH BUILD WATERBORNE PAINT Total 6 IN. YELLOW HIGH BUILD	Material - To Other Item Adjustment	REFL - Tota	10 11 11 Il	Dec 2, 2022 Dec 15, 2022 Dec 2,	SYSTEM bedarl2	(\$7,082.10) \$0.00 \$0.00 (\$590.71) (\$590.71) (\$590.71)	Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 25 on the current Payment Estimate. 105% = .015 extra per 10,886.500 LF = \$ 163.30 extra 80% = .06 deduct per 12,566.90 LF = \$ -754.01 deduct \$ -754.014 - \$ 163.30 = \$ -590.71 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user bedarl2 overridding Payment
	0380 -	HIGH BUILD WATERBORNE PAINT Total 6 IN. YELLOW HIGH BUILD WATERBORNE	Material - To Other Item Adjustment	REFL - Tota	10 11 11 11 11 11 11 11 11 11 11 11 11 1	Dec 2, 2022 Dec 2, 2022 Dec 2, 2022 Dec 2, 2022	SYSTEM bedarl2 SYSTEM	(\$7,082.10) \$0.00 \$0.00 (\$590.71) (\$590.71) (\$590.71) (\$590.71) \$1,977.60	Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 25 on the current Payment Estimate. 105% = .015 extra per 10,886.500 LF = \$ 163.30 extra 80% = .06 deduct per 12,566.90 LF = \$ -754.01 deduct \$ -754.014 - \$ 163.30 = \$ -590.71 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user bedarl2 overridding Payment
	0380 -	HIGH BUILD WATERBORNE PAINT Total 6 IN. YELLOW HIGH BUILD WATERBORNE	Material - To Other Item Adjustment	REFL - Tota djustment - T	10 11 11 11 11 11 11 11 11 11 11 11 11 1	Dec 2, 2022 Dec 2, 2022 Dec 2, 2022 Dec 2, 2022	SYSTEM bedarl2 SYSTEM	(\$7,082.10) \$0.00 \$0.00 (\$590.71) (\$590.71) (\$590.71) (\$590.71) \$1,977.60	Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 25 on the current Payment Estimate. 105% = .015 extra per 10,886.500 LF = \$ 163.30 extra 80% = .06 deduct per 12,566.90 LF = \$ -754.01 deduct \$ -754.014 - \$ 163.30 = \$ -590.71 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user bedarl2 overridding Payment
	0380 -	HIGH BUILD WATERBORNE PAINT Total 6 IN. YELLOW HIGH BUILD WATERBORNE	Material - To Other Item Adjustment Other Item A	REFL - Tota djustment - T	10 11 11 10 10 10 10 10 10 10 10 10 10 1	Dec 2, 2022 Dec 2, 2022 Dec 2, 2022 Dec 2, 2022	SYSTEM bedarl2 SYSTEM	(\$7,082.10) \$0.00 \$0.00 (\$590.71) (\$590.71) (\$590.71) (\$590.71) \$1,977.60 (\$1,977.60)	Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 25 on the current Payment Estimate. 105% = .015 extra per 10,886.500 LF = \$ 163.30 extra 80% = .06 deduct per 12,566.90 LF = \$ -754.01 deduct \$ -754.014 - \$ 163.30 = \$ -590.71 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user bedarl2 overridding Payment
	0380 -	HIGH BUILD WATERBORNE PAINT Total 6 IN. YELLOW HIGH BUILD WATERBORNE	Material - To Other Item Adjustment Other Item A Material Material - To Other Item	REFL - Tota djustment - T	10 11 10 10 10 10 11 11	Dec 2, 2022 Dec 15, 2022	SYSTEM bedarl2 SYSTEM SYSTEM	(\$7,082.10) \$0.00 \$0.00 (\$590.71) (\$590.71) (\$590.71) (\$590.71) \$1,977.60 (\$1,977.60) \$0.00	Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 25 on the current Payment Estimate. 105% = .015 extra per 10,886.500 LF = \$ 163.30 extra 80% = .06 deduct per 12,566.90 LF = \$ -754.01 deduct \$ -754.014 - \$ 163.30 = \$ -590.71 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user bedarl2 overridding Payment Estimate Exception 27 on the current Payment Estimate.
	0380 -	HIGH BUILD WATERBORNE PAINT Total 6 IN. YELLOW HIGH BUILD WATERBORNE	Material - To Other Item Adjustment Other Item A Material Material - To Other Item Adjustment	REFL - Tota djustment - T - Total tal REFL	10 11 11 10 10 10 10 10 10 11 11 11 11 1	Dec 2, 2022 Dec 15, 2022	SYSTEM bedarl2 SYSTEM SYSTEM	(\$7,082.10) \$0.00 \$0.00 (\$590.71) (\$590.71) (\$590.71) (\$590.71) \$1,977.60 \$0.00 \$0.00 (\$498.96)	Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 25 on the current Payment Estimate. 105% = .015 extra per 10,886.500 LF = \$ 163.30 extra 80% = .06 deduct per 12,566.90 LF = \$ -754.01 deduct \$ -754.014 - \$ 163.30 = \$ -590.71 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user bedarl2 overridding Payment Estimate Exception 27 on the current Payment Estimate.
	0380 -	HIGH BUILD WATERBORNE PAINT Total 6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material - To Other Item Adjustment Other Item A Material Material - To Other Item Adjustment	REFL - Total tal REFL REFL REFL REFL	10 11 11 10 10 10 10 10 10 11 11 11 11 1	Dec 2, 2022 Dec 15, 2022	SYSTEM bedarl2 SYSTEM SYSTEM	(\$7,082.10) \$0.00 \$0.00 (\$590.71) (\$590.71) (\$590.71) (\$590.71) \$1,977.60 (\$1,977.60) \$0.00 (\$498.96)	Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 25 on the current Payment Estimate. 105% = .015 extra per 10,886.500 LF = \$ 163.30 extra 80% = .06 deduct per 12,566.90 LF = \$ -754.01 deduct \$ -754.014 - \$ 163.30 = \$ -590.71 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user bedarl2 overridding Payment Estimate Exception 27 on the current Payment Estimate.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J6I3424	0400	WATERBORNE PAINT	Material						Estimate Exception 29 on the current Payment Estimate.
		LAINT			10	Dec 2, 2022	SYSTEM	(\$3,575.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0400 -	Total						\$0.00	
	0420	MISC. PAVEMENT MARKINGS	Material		10	Dec 2, 2022	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bedarl2 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$9,600.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0420 -	Total						\$0.00	
	0430	MISC. PAVEMENT MARKINGS	Material		9	Nov 17, 2022	SYSTEM	\$8,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user bedarl2 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$8,040.00)	
				- Total				\$0.00	
			Material - Tot					\$0.00	
	0430 -	Total						\$0.00	
	0470	PERMANENT EROSION CONTROL	Material		8	Nov 2, 2022	SYSTEM	\$925.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user bedarl2 overridding Payment Estimate Exception 45 on the current Payment Estimate.
		GEOTEXTILE			8	Nov 2, 2022	SYSTEM	(\$925.65)	Estimate Estopion 10 on the canonic afficient Estimate.
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
								Ψ0.00	
	0470 -	Total		•				\$0.00	
	0470 - 0500	Total MGS GUARDRAIL	Construction Stockpile		3	Jul 18, 2022	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
		MGS	Construction		3		SYSTEM SYSTEM	\$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
		MGS	Construction			2022 Aug 2,		\$0.00 (\$30,315.00)	
		MGS	Construction		4	2022 Aug 2, 2022 Nov 2,	SYSTEM	\$0.00 (\$30,315.00) (\$7,578.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
		MGS	Construction	- Total	4 8	2022 Aug 2, 2022 Nov 2, 2022 Dec 15,	SYSTEM	\$0.00 (\$30,315.00) (\$7,578.75) (\$1,768.38)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
		MGS	Construction Stockpile		8 11	2022 Aug 2, 2022 Nov 2, 2022 Dec 15,	SYSTEM	\$0.00 (\$30,315.00) (\$7,578.75) (\$1,768.38) (\$14,904.87)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
		MGS	Construction Stockpile Construction Construction Stockpile	- Total	8 11	2022 Aug 2, 2022 Nov 2, 2022 Dec 15,	SYSTEM	\$0.00 (\$30,315.00) (\$7,578.75) (\$1,768.38) (\$14,904.87) (\$54,567.00)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
		MGS	Construction Stockpile Construction Construction	- Total	4 8 11	2022 Aug 2, 2022 Nov 2, 2022 Dec 15, 2022	SYSTEM SYSTEM SYSTEM	\$0.00 (\$30,315.00) (\$7,578.75) (\$1,768.38) (\$14,904.87) (\$54,567.00) (\$54,567.00)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
		MGS	Construction Stockpile Construction Construction Stockpile STMI	- Total 1 Stockpile - T	4 8 11 Cotal 1	2022 Aug 2, 2022 Nov 2, 2022 Dec 15, 2022 Apr 4, 2022	SYSTEM SYSTEM SYSTEM	\$0.00 (\$30,315.00) (\$7,578.75) (\$1,768.38) (\$14,904.87) (\$54,567.00) (\$54,567.00)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
		MGS GUARDRAIL	Construction Stockpile Construction Construction Stockpile STMI	- Total n Stockpile - T - Total	4 8 11 Cotal 1	2022 Aug 2, 2022 Nov 2, 2022 Dec 15, 2022 Apr 4, 2022	SYSTEM SYSTEM SYSTEM	\$0.00 (\$30,315.00) (\$7,578.75) (\$1,768.38) (\$14,904.87) (\$54,567.00) (\$54,567.00) \$54,567.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
	0500	MGS GUARDRAIL Total MGS BRIDGE APP. TRANS	Construction Stockpile Construction Construction Stockpile STMI	- Total n Stockpile - T - Total	4 8 11 Cotal 1	2022 Aug 2, 2022 Nov 2, 2022 Dec 15, 2022 Apr 4, 2022	SYSTEM SYSTEM SYSTEM	\$0.00 (\$30,315.00) (\$7,578.75) (\$1,768.38) (\$14,904.87) (\$54,567.00) (\$54,567.00) \$54,567.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
	0500 -	MGS GUARDRAIL	Construction Stockpile Construction Construction Stockpile STMI Construction	- Total n Stockpile - T - Total	4 8 11 Fotal 1	2022 Aug 2, 2022 Nov 2, 2022 Dec 15, 2022 Apr 4, 2022 Jul 18,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$30,315.00) (\$7,578.75) (\$1,768.38) (\$14,904.87) (\$54,567.00) (\$54,567.00) \$54,567.00 \$54,567.00 \$54,567.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	0500 -	MGS GUARDRAIL Total MGS BRIDGE APP. TRANS SEC (EXT	Construction Stockpile Construction Construction Stockpile STMI Construction	- Total n Stockpile - T - Total	4 8 11 Fotal 1 TMI - Total	2022 Aug 2, 2022 Nov 2, 2022 Dec 15, 2022 Apr 4, 2022 Jul 18, 2022 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$30,315.00) (\$7,578.75) (\$1,768.38) (\$14,904.87) (\$54,567.00) (\$54,567.00) \$54,567.00 \$0.00 (\$13,200.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
	0500 -	MGS GUARDRAIL Total MGS BRIDGE APP. TRANS SEC (EXT	Construction Stockpile Construction Construction Stockpile STMI Construction	- Total n Stockpile - T - Total	4 8 11 1 Fotal 1 3 4	2022 Aug 2, 2022 Nov 2, 2022 Dec 15, 2022 Apr 4, 2022 Jul 18, 2022 Aug 2, 2022 Nov 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$30,315.00) (\$7,578.75) (\$1,768.38) (\$14,904.87) (\$54,567.00) (\$54,567.00) \$54,567.00 \$0.00 (\$13,200.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
	0500 -	MGS GUARDRAIL Total MGS BRIDGE APP. TRANS SEC (EXT	Construction Stockpile Construction Construction Stockpile STMI Construction	- Total n Stockpile - T - Total	4 8 11 1 Total 3 4 8	2022 Aug 2, 2022 Nov 2, 2022 Dec 15, 2022 Apr 4, 2022 Jul 18, 2022 Aug 2, 2022 Nov 2, 2022 Dec 15, 18, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$30,315.00) (\$7,578.75) (\$1,768.38) (\$14,904.87) (\$54,567.00) (\$54,567.00) \$54,567.00 \$0.00 (\$13,200.00) (\$4,400.00)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
	0500 -	MGS GUARDRAIL Total MGS BRIDGE APP. TRANS SEC (EXT	Construction Stockpile Construction Construction Stockpile STMI Construction Construction	- Total n Stockpile - T - Total n Stockpile ST	4 8 111 1 Total 3 4 8 111	2022 Aug 2, 2022 Nov 2, 2022 Dec 15, 2022 Apr 4, 2022 Jul 18, 2022 Aug 2, 2022 Nov 2, 2022 Dec 15, 18, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$30,315.00) (\$7,578.75) (\$1,768.38) (\$14,904.87) (\$54,567.00) (\$54,567.00) \$54,567.00 \$0.00 (\$13,200.00) (\$4,400.00) (\$6,600.00)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
	0500 -	MGS GUARDRAIL Total MGS BRIDGE APP. TRANS SEC (EXT	Construction Stockpile Construction Construction Stockpile STMI Construction Construction	- Total - Total - Stockpile ST	4 8 111 1 Total 3 4 8 111	2022 Aug 2, 2022 Nov 2, 2022 Dec 15, 2022 Apr 4, 2022 Jul 18, 2022 Aug 2, 2022 Nov 2, 2022 Dec 15, 18, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$30,315.00) (\$7,578.75) (\$1,768.38) (\$14,904.87) (\$54,567.00) (\$54,567.00) \$54,567.00 \$0.00 (\$13,200.00) (\$4,400.00) (\$6,600.00) (\$8,800.00)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
613424	0510	MGS BRIDGE APP. TRANS SEC (EXT CURB)	Construction	n Stockpile S	TMI - Tota			\$33,000.00	
	0510 -	Total						\$0.00	
	0520	MGS VERTICAL CONCRETE BARRIER	Construction Stockpile		3	Jul 18, 2022	SYSTEM	(\$1,940.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		TRANSITION			4	Aug 2, 2022	SYSTEM	(\$1,940.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$3,880.00)	
			Construction	n Stockpile - 1	Total			(\$3,880.00)	
			Construction Stockpile STMI		2	Jul 5, 2022	SYSTEM	\$3,880.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$3,880.00	
			Construction	1 Stockpile S	TMI - Tota			\$3,880.00	
	0520 -							\$0.00	
	0530	MGS END ANCHOR	Construction Stockpile		3	Jul 18, 2022	SYSTEM	(\$2,550.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					11	Nov 2, 2022 Dec 15.	SYSTEM	(\$850.00)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
					L.,	2022	STOTEW	(ψοσο.σο)	. symmet Lournage transaction regional description transaction
				- Total				(\$4,250.00)	
			Construction	1 Stockpile - 1	Total			(\$4,250.00)	
			Construction Stockpile STMI		1	Apr 4, 2022	SYSTEM	\$4,250.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			OTIVII	- Total				\$4,250.00	
			Construction	1 Stockpile S	TMI - Tota			\$4,250.00	
	0530 -	Total						\$0.00	
	0540	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		3	Jul 18, 2022	SYSTEM	(\$11,700.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)			4	Aug 2, 2022	SYSTEM	(\$3,900.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					9	Nov 17, 2022	SYSTEM	(\$1,950.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$17,550.00)	
			Construction	n Stockpile - 1	Total			(\$17,550.00)	
			Construction Stockpile STMI		1	Apr 4, 2022	SYSTEM	\$19,500.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			3	- Total				\$19,500.00	
			Construction	Stockpile S	TMI - Tota	l e		\$19,500.00	
	0540 -	Total						\$1,950.00	
	0550	POST, SIGNAL 8 FT. OR 2.4 M	Material		8	Nov 2, 2022	SYSTEM	\$10,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user bedarl2 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					8	Nov 2, 2022	SYSTEM	(\$10,450.00)	
					9	Nov 17, 2022	SYSTEM	\$20,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user bedarl2 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$20,900.00)	
					10	Dec 2, 2022	SYSTEM	\$20,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user bedarl2 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$20,900.00)	
					11	Dec 15, 2022	SYSTEM	\$10,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user bedarl2 overridding Payment Estimate Exception 28 on the current Payment Estimate.
									Estimate Exception 20 on the current rayment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3424	0550	POST, SIGNAL 8 FT. OR 2.4 M	Material			2022			
		F1. UR 2.4 W			12	Jan 3, 2023	SYSTEM	\$10,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user bedarl2 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$10,450.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
			Overrun	Overrun	9	Nov 17, 2022	SYSTEM	(\$10,450.00)	
					11	Dec 15, 2022	SYSTEM	\$10,450.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',950.00000 - 950.00000, 'is applied (if non-zero).
				Overrun - To	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0550 -	Total						\$0.00	
	0560	VIDEO DETECTION SYSTEM	Material		9	Nov 17, 2022	SYSTEM	\$50,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user bedarl2 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$50,000.00)	
					10	Dec 2, 2022	SYSTEM	\$50,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user bedarl2 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$50,000.00)	
					11	Dec 15, 2022	SYSTEM	\$50,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					11	Dec 15, 2022	SYSTEM	(\$50,000.00)	
					12	Jan 3, 2023	SYSTEM	\$50,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$50,000.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0560 -	Total						\$0.00	
	0570	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		9	Nov 17, 2022	SYSTEM	\$896.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user bedarl2 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$896.00)	
					10	Dec 2, 2022	SYSTEM	\$896.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$896.00)	
					11	Dec 15, 2022	SYSTEM	\$896.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user bedarl2 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					11	Dec 15, 2022	SYSTEM	(\$896.00)	
					12	Jan 3, 2023	SYSTEM	\$896.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user bedarl2 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$896.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0570 -	Total						\$0.00	
	0580	CONDUIT, 3 IN.,	Material		9	Nov 17,	SYSTEM	\$5,460.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type		Date	Ву		
J6I3424	0580	PUSHED WITH TRACER WIRE	Material			2022			Estimate Item Adjustment (0028) due to user bedarl2 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$5,460.00)	
					10	Dec 2, 2022	SYSTEM	\$5,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user bedarl2 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$5,460.00)	
					11	Dec 15, 2022	SYSTEM	\$5,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user bedarl2 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					11	Dec 15, 2022	SYSTEM	(\$5,460.00)	
					12	Jan 3, 2023	SYSTEM	\$5,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user bedarl2 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$5,460.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0580 -	Total						\$0.00	
	0590	CABLE, 16 AWG 2 CONDUCTOR	Material		9	Nov 17, 2022	SYSTEM	\$2,454.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$2,454.90)	
					10	Dec 2, 2022	SYSTEM	\$2,454.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user bedarl2 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$2,454.90)	
					11	Dec 15, 2022	SYSTEM	\$2,454.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user bedarl2 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					11	Dec 15, 2022	SYSTEM	(\$2,454.90)	
					12	Jan 3, 2023	SYSTEM	\$2,457.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user bedarl2 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$2,457.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0590 -	Total						\$0.00	
	0600	CABLE, 16 AWG 5 CONDUCTOR	Material		9	Nov 17, 2022	SYSTEM	\$2,927.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user bedarl2 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$2,927.50)	
					10	Dec 2, 2022	SYSTEM	\$2,927.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user bedarl2 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$2,927.50)	
					11	Dec 15, 2022	SYSTEM	\$2,927.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user bedarl2 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					11	Dec 15, 2022	SYSTEM	(\$2,927.50)	
					12	Jan 3, 2023	SYSTEM	\$2,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$2,925.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3424	0600	CABLE, 16 AWG	Material	- Total				\$0.00	
		5 CONDUCTOR	Material - To	tal				\$0.00	
			Overrun	Overrun	9	Nov 17, 2022	SYSTEM	(\$2.50)	
					12	Jan 3, 2023	SYSTEM	\$2.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1.25000 - 1.25000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0600 -	Total						\$0.00	
	0610	BASE, CONCRETE	Material		8	Nov 2, 2022	SYSTEM	\$14,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user bedarl2 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					8	Nov 2, 2022	SYSTEM	(\$14,880.00)	
					9	Nov 17, 2022	SYSTEM	\$14,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user bedarl2 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$14,880.00)	
					10	Dec 2, 2022	SYSTEM	\$14,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$14,880.00)	
					11	Dec 15, 2022	SYSTEM	\$14,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user bedarl2 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					11	Dec 15, 2022	SYSTEM	(\$14,880.00)	
					12	Jan 3, 2023	SYSTEM	\$14,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$14,880.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0610 -	Total						\$0.00	
	0630	MISC.	Material		9	Nov 17, 2022	SYSTEM	\$13,412.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user bedarl2 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$13,412.00)	
					10	Dec 2, 2022	SYSTEM	\$13,412.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user bedarl2 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$13,412.00)	
					11	Dec 15, 2022	SYSTEM	\$13,412.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user bedarl2 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					11	Dec 15, 2022	SYSTEM	(\$13,412.00)	
					12	Jan 3, 2023	SYSTEM	\$13,412.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user bedarl2 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$13,412.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0630 -	Total						\$0.00	
	0640	MISC.	Material		9	Nov 17, 2022	SYSTEM	\$6,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user bedarl2 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3424	0640	MISC.	Material						Estimate Exception 49 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$6,580.00)	
					10	Dec 2, 2022	SYSTEM	\$6,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user bedarl2 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$6,580.00)	
					11	Dec 15, 2022	SYSTEM	\$6,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user bedarl2 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					11	Dec 15, 2022	SYSTEM	(\$6,580.00)	
					12	Jan 3, 2023	SYSTEM	\$6,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user bedarl2 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$6,580.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0640 -	Total						\$0.00	
	0650	MISC.	Material		9	Nov 17, 2022	SYSTEM	\$204.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user bedarl2 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$204.00)	
					10	Dec 2, 2022	SYSTEM	\$204.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user bedarl2 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$204.00)	
					11	Dec 15, 2022	SYSTEM	\$204.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user bedarl2 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					11	Dec 15, 2022	SYSTEM	(\$204.00)	
					12	Jan 3, 2023	SYSTEM	\$204.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user bedarl2 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$204.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0650 - 0660	CONCRETE	Material		9	Nov 17,	SYSTEM	\$0.00 \$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user bedarl2 overridding Payment
		FOOTINGS, EMBEDDED			0	2022 Nov 17	SYSTEM	(\$600.00)	Estimate term Adjustment (0036) due to user bedanz overhidding Payment Estimate Exception 51 on the current Payment Estimate.
					9	Nov 17, 2022		(\$600.00)	This adjustment effects the eniginal question generated Metarial Doument
					10	Dec 2, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user bedarl2 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$600.00)	
					11	Dec 15, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user bedarl2 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					11	Dec 15, 2022	SYSTEM	(\$600.00)	
					12	Jan 3, 2023	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user bedarl2 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$600.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3424	0660	CONCRETE FOOTINGS,	Material	- Total				\$0.00	
		EMBEDDED	Material - To	tal				\$0.00	
	0660 -						0)/0==1/	\$0.00	
	0670	PIPE POSTS	Material		8	Nov 2, 2022	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user bedarl2 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					8	Nov 2, 2022	SYSTEM	(\$700.00)	
					9	Nov 17, 2022	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user bedarl2 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$700.00)	
					10	Dec 2, 2022	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user bedarl2 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$700.00)	
					11	Dec 15, 2022	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					11	Dec 15, 2022	SYSTEM	(\$700.00)	
					12	Jan 3, 2023	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user bedarl2 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$700.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0670 -	Total						\$0.00	
	0680	2 IN. PSST POST - 12 GA.	Material		8	Nov 2, 2022	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate.
	0680		Material		8		SYSTEM	\$400.00 (\$400.00)	Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment
	0680		Material			2022 Nov 2,			Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment
	0680		Material		8	2022 Nov 2, 2022 Nov 17,	SYSTEM	(\$400.00)	Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user bedarl2 overridding Payment
	0680		Material		8	Nov 2, 2022 Nov 17, 2022 Nov 17,	SYSTEM SYSTEM	(\$400.00) \$400.00	Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user bedarl2 overridding Payment
	0680		Material		9	Nov 2, 2022 Nov 17, 2022 Nov 17, 2022 Dec 2,	SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00)	Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user bedarl2 overridding Payment
	0680		Material		8 9 9	2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022 Dec 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00) \$400.00	Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user bedarl2 overridding Payment
	0680		Material		8 9 9 10	2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022 Dec 2, 2022 Dec 2, 2022 Dec 15,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00) \$400.00	Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user bedarl2 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user bedarl2 overridding Payment Estimate Item Adjustment (0030) due to user bedarl2 overridding Payment
	0680		Material		8 9 9 10 10 11 11	2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022 Dec 2, 2022 Dec 2, 2022 Dec 15, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00) \$400.00 (\$400.00)	Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user bedarl2 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user bedarl2 overridding Payment Estimate Item Adjustment (0030) due to user bedarl2 overridding Payment
	0680		Material		9 9 10 10 11 11 11	2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022 Dec 2, 2022 Dec 15, 2022 Jan 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00) \$400.00 (\$400.00)	Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user bedarl2 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user bedarl2 overridding Payment Estimate Exception 48 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 48 on the current Payment Estimate.
	0680		Material	- Total	8 9 9 10 10 11 11 11 12	2022 Nov 17, 2022 Nov 17, 2022 Dec 2, 2022 Dec 15, 2022 Jan 3, 2023 Jan 3, 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00) \$400.00 (\$400.00) \$400.00 \$400.00	Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user bedarl2 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user bedarl2 overridding Payment Estimate Exception 48 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 48 on the current Payment Estimate.
	0680		Material - To		8 9 9 10 10 11 11 11 12	2022 Nov 17, 2022 Nov 17, 2022 Dec 2, 2022 Dec 15, 2022 Jan 3, 2023 Jan 3, 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00) \$400.00 (\$400.00) \$400.00 (\$400.00)	Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user bedarl2 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user bedarl2 overridding Payment Estimate Exception 48 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 48 on the current Payment Estimate.
	0680	POST - 12 GA.			8 9 9 10 10 11 11 11 12	2022 Nov 17, 2022 Nov 17, 2022 Dec 2, 2022 Dec 15, 2022 Jan 3, 2023 Jan 3, 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00) \$400.00 (\$400.00) \$400.00 (\$400.00) \$400.00	Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user bedarl2 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user bedarl2 overridding Payment Estimate Exception 48 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 48 on the current Payment Estimate.
		POST - 12 GA.	Material - To		8 9 9 10 10 11 11 11 12	2022 Nov 17, 2022 Nov 17, 2022 Dec 2, 2022 Dec 15, 2022 Jan 3, 2023 Jan 3, 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00) \$400.00 (\$400.00) \$400.00 (\$400.00) \$0.00	Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user bedarl2 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user bedarl2 overridding Payment Estimate Exception 48 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 48 on the current Payment Estimate.





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J613424	0690	POST ANCHOR FOR 2 IN. PSST - 12 GA.	Material		9	Nov 17, 2022	SYSTEM	\$180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user bedarl2 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$180.00)	
					10	Dec 2, 2022	SYSTEM	\$180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$180.00)	
					11	Dec 15, 2022	SYSTEM	\$180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user bedarl2 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					11	Dec 15, 2022	SYSTEM	(\$180.00)	
					12	Jan 3, 2023	SYSTEM	\$180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user bedarl2 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					12	Jan 3, 2023	SYSTEM	(\$180.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0690 - Total							\$0.00	
J6l3424 -	24 - Total							\$145,877.88	
Overall -	Overall - Total							\$145,877.88	