

Pay Estimate Created Date: December 1, 2022

Progress 7	Estimate Number	Contract IE Prime Contractor	Radn	18-C01 nacher Brothers Ex nc.	cavating	Pay Period Start Pay Period End	2022	ember 1,	Original Contract Amount Net Change Order Amount Current Contract Amount	\$3,322,828.03 (\$35,013.14) \$3,287,814.89
Approval Date										By User
December 2, 2022				Generated and A	pproved (a	and should be cons	sidered	Draft) at th	e Project Office Level by	degrow1
December 2, 2022			Re	viewed and Appro	ved (and s	hould be considere	ed Drat	t) at the Re	sident Engineer Level by	rileyr1
December 5, 2022				F	Reviewed a	and Approved at th	e Cent	ral Office Co	ontrollers Office Level by	ramses1
Original Comp	letion Dat	e Cu	urrent Com	pletion Date	Actua	al Completion Dat	te	% of	Current Contract Amour	nt Complete
December	1, 2022		Decembe	er 1, 2022					96.05%	
	Cor	tract Information	ational Dat	es		Milest	ones			
Date Description	on Orig	ginal Comple	tion Date	Current Complet	tion Date	No Milestones E	xist for	Contract		
Acceptance Date										
Awarded Date	Apri	l 6, 2022		April 6, 2022						
Letting Date	Mar	ch 18, 2022		March 18, 2022						
Notice to Proceed	Date May	/ 10, 2022		May 10, 2022						
Open to Traffic Da	te									
Work Began Date	Aug	ust 22, 2022		August 22, 2022						

Contract Total Pa	ay For Estimate No. 7			
		This Estimate	Previous	To Date
220318-C01				
	Total Posted Items Pay	\$160,007.54	\$2,998,019.21	\$3,158,026.75
	Gross Item Adjustments	\$15,379.44	\$68,963.84	\$84,343.28
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$3,066,983.05	\$3,242,370.03
Contract Total Pa	avable This Estimate:	\$175.386.98		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J3P3078	0230	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	EA	\$252.000	6	\$1,512.00
	0240	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	EA	\$36.750	4	\$147.00
	0250	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$0.750	118	\$88.50
	0260	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$0.750	1,144	\$858.00
	0290	6207001	PAVEMENT MARKING REMOVAL	LF	\$0.400	1,108	\$443.20
	0390	8051000A	SEEDING - COOL SEASON GRASSES	ACRE	\$2,604.000	0.16	\$416.64
	0410	8061006	ALTERNATE DITCH CHECK	LF	\$6.200	545	\$3,379.00
	0420	8061016	SEDIMENT REMOVAL	CUYD	\$9.700	170	\$1,649.00
	0440	8064131	TYPE 1A EROSION CONTROL BLANKET	SQYD	\$2.650	675	\$1,788.75
	0490	9011060	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 1	EA	\$4,491.900	4	\$17,967.60
	0500	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	EA	\$3,612.000	4	\$14,448.00
	0510	9011115	BRACKET ARM, 15 FT. OR 4.6 M	EA	\$1,199.100	8	\$9,592.80
	0520	9011312	LUMINAIRE, LED-B	EA	\$405.300	8	\$3,242.40
	0570	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	LF	\$1.050	960	\$1,008.00
	0580	9017401	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL,	LF	\$14.700	40	\$588.00



Pay Estimate Created Date: December 1, 2022

Pro	Progress Estimate Number 7 Prime Contract I Prime Contracto		rime	220318-C01 Radmacher Brothers Excavating Co.,Inc.	Pay Period Start Pay Period End	Novemł 2022 Decemł 2022		Amour Net Ch Amour	ange Order it t Contract	\$3,322,828.03 (\$35,013.14) \$3,287,814.89
Project Number	Line Number	Item Code		Item Description		U	Jnit	Unit Price	Current Installed Qty	Current Installed Amount
J3P3078			2 AWG							
	0590	9017404	CABLE-C 6 AWG	ONDUIT, 1 IN., 2 CONDUCTORS AND	0 1 BARE NEUT	RAL, LF	:	\$6.300	3,670	\$23,121.00
	0600	9017407	CABLE-C 8 AWG	ONDUIT, 1 IN., 2 CONDUCTORS AND	0 1 BARE NEUT	RAL, LF	:	\$4.950	2,610	\$12,919.50
	0620	9018612	POWER S	SUPPLY ASSEMBLY, TYPE 2, 240/12 S ONLY	0 VOLT SERVIC	E, EA	Ą	\$2,100.000	1	\$2,100.00
	0630	9031010	CONCRE	TE FOOTINGS, EMBEDDED		CL	JYD	\$1,050.000	4.41	\$4,630.50
	0640	9031210	STRUCTU	JRAL STEEL POSTS		LB	3	\$7.900	882.05	\$6,968.20
	0650	9031241	BREAKAV	VAY ASSEMBLY (PERFORATED SQI	JARE STEEL TU	JBE) EA	4	\$367.500	30	\$11,025.00
	0660	9031256	7 FT. CHA	ANNEL POST DELINEATOR, WHITE		EA	Ą	\$47.250	3	\$141.75
	0670	9031272	2.25 IN. P	SST POST - 12 GA.		LF		\$21.000	66	\$1,386.00
	0680	9031280	2.5 IN. PS	ST POST - 12 GA.		LF	:	\$26.250	555	\$14,568.75
	0690	9031281	POST AN	CHOR FOR 2.5 IN. PSST - 7 GA.		LF		\$52.500	144	\$7,560.00
	0700	9035004	SH-FLAT	SHEET		SC	QFT	\$21.000	787.55	\$16,538.55
	0715	90350694	A SHF-FLAT	SHEET FLUORESCENT		SC	QFT	\$22.050	18	\$396.90
	5005	9025200	CONDUIT	, 2 IN., TRENCH WITH TRACER WIR	E	LF	:	\$13.125	76	\$997.50
	5006	9105200	CONDUIT	, 2 IN., RIGID, IN TRENCH		LF		\$26.250	20	\$525.00
Project J3	<mark>P3078 - To</mark>	tal								\$160,007.54
Overall - T	otal									\$160,007.54

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J3P3078	0460	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Material			-255.8	\$76.65	(\$19,607.07
	0460	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user degrow1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	255.8	\$76.65	\$19,607.07
	0460	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Other Item Adjustment	PCCP QC/QA Strength Adjustment	Lot 10 = \$3108.73 Lot 11 = \$3429.32 Lot 12 = \$1151.67			\$7,689.72
	0460	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Other Item Adjustment	PCCP QC/QA Thickness Adjustment	Lot 10 = \$3108.73 Lot 11 = \$3429.32 Lot 12 = \$1151.67			\$7,689.72
	0660	7 FT. CHANNEL POST DELINEATOR, WHITE	Material			-121	\$47.25	(\$5,717.25
	0660	7 FT. CHANNEL POST DELINEATOR, WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user degrow1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	121	\$47.25	\$5,717.25
Total								\$15.379.4



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Informatic	n
Project Number	Federal Proj. Number	Description	Route	County			Location of Work
J3P3078	FAF 50-2(63)	Intersection improvement	50	PETTIS	at the intersection of Route	127 near La Monte	
Totals by J	Job Numb	oers					
J3P3078		ed Item Pay ss Item Adjustm		s Item Pay	This Estimate \$160,007.54 \$15,379.44 \$175,386.98	Previous \$2,998,019.21 \$68,963.84 \$3,066,983.05	To Date \$3,158,026.75 \$84,343.28 \$3,242,370.03
	Liqu	ntive ncentive idated Damage er Contract Adju		5	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J3P3078, Item 5021308, Project Item Line Number 0460, Material Set 502130896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	QC has grabbed last gradation sample. Waiting on test results.	degrow1	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3078, Item 9031256, Project Item Line Number 0660, Material Set 903125696, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	Certifications have been sent to KC District Materials.	degrow1	Overridden

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See report generated date)
220318-C01	J3P3078	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$118,751.65	\$118,751.6
		0001	0020	2031000	CLASS A EXCAVATION	5,554.80	0.00	5,554.80	CUYD	5,554.80	\$10.20	\$56,658.9
		0001	0030	2035500	EMBANKMENT IN PLACE	3,735.50	0.00	3,735.50	CUYD	3,735.50	\$22.30	\$83,301.6
		0001	0040	2036000	COMPACTING EMBANKMENT	2,261.90	0.00	2,261.90	CUYD	2,261.90	\$1.30	\$2,940.4
		0001	0045	2037075	COMPACTING IN CUT	123.80	0.00	123.80	STA	0.00	\$859.35	\$0.0
		0001	0050	2063000	CLASS 3 EXCAVATION	35.00	0.00	35.00	CUYD	35.00	\$8.65	\$302.7
		0001	0060	3040163	TYPE 1 AGGREGATE FOR BASE (6 IN. THICK)	25,537.00	0.00	25,537.00	SQYD	25,537.00	\$9.60	\$245,155.2
		0001	0080	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	154.80	0.00	154.80	SQYD	154.80	\$136.85	\$21,184.3
		0001	0090	6083006	6 IN. CONCRETE MEDIAN STRIP	115.30	0.00	115.30	SQYD	115.30	\$93.15	\$10,740.2
		0001	0100	6097000	ROCK LINING	10.00	0.00	10.00	CUYD	10.00	\$89.35	\$893.5
		0001	0110	6141028	GRATE AND BEARING PLATE (5 FT. 1 IN. X 3 FT. 1 IN. OR 1549 MM X 940 MM)	1.00	0.00	1.00	EA	1.00	\$3,837.65	\$3,837.6
		0001	0120	6161005	CONSTRUCTION SIGNS	2,520.50	0.00	2,520.50	SQFT	2,001.00	\$6.30	\$12,606.3
		0001	0130	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$47.25	\$189.0
		0001	0140	6161025	CHANNELIZER (TRIM LINE)	154.00	86.00	240.00	EA	240.00	\$15.75	\$3,780.0
		0001	0150	6161030	TYPE III MOVEABLE BARRICADE	12.00	14.00	26.00	EA	26.00	\$183.75	\$4,777.5
		0001	0160	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$1,050.00	\$2,100.0
		0001	0170	6161047	TYPE III OBJECT MARKER	2.00	0.00	2.00	EA	0.00	\$210.00	\$0.0
		0001	0180	6161055	SEQUENTIAL FLASHING WARNING LIGHT	28.00	0.00	28.00	EA	28.00	\$47.25	\$1,323.0
		0001	0190	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	8.00	0.00	8.00	EA	8.00	\$3,412.50	\$27,300.
		0001	0200	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	4.00	\$934.50	\$3,738.
		0001	0210	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$178,895.00	\$178,895.
		0001	0220	6191000	PAVEMENT EDGE TREATMENT	14,039.00	0.00	14,039.00	LF	14,039.00	\$7.50	\$105,292.
		0001	0230	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	21.00	0.00	21.00	EA	21.00	\$252.00	\$5,292.
		0001	0240	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	40.00	0.00	40.00	EA	40.00	\$36.75	\$1,470.
		0001	0250	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	12,247.00	0.00	12,247.00	LF	12,247.00	\$0.75	\$9,185.
		0001	0260	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,210.00	0.00	7,210.00	LF	7,210.00	\$0.75	\$5,407.
		0001	0270	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,786.00	0.00	1,786.00	LF	1,786.00	\$1.45	\$2,589.
		0001	0280	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	139.00	0.00	139.00	LF	139.00	\$14.70	\$2,043.
		0001	0290	6207001	PAVEMENT MARKING REMOVAL	15,400.00	0.00	15,400.00	LF	1,128.00	\$0.40	\$451.
		0001	0300	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	6.00	0.00	6.00	EA	0.00	\$52.50	\$0.
		0001	0310	6208063	TEMPORARY PAVEMENT MARKING	6.00	0.00	6.00	EA	6.00	\$84.00	\$504.
		0001	0320	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	2,507.00	0.00	2,507.00	LF	420.00	\$1.50	\$630.0
		0001	0330	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.75	\$15,750.00	\$11,812.
		0001	0340	7250324A	24 IN. PIPE GROUP B	89.00	0.00	89.00	LF	89.00	\$68.75	\$6,118.
		0001	0350	7265018	JACKED 18 IN. CLASS III REINFORCED CONCRETE PIPE	92.00	-92.00	0.00	LF	0.00	\$1,172.65	\$0.0
		0001	0360	7311053	CULVERTS (GASKET TYPE) PRECAST CONCRETE DROP INLET 5 FT X 3 FT	3.00	0.00	3.00	FT	3.00	\$2,253.85	\$6.761.
		0001	0370	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END	1.00	0.00	1.00	EA	1.00	\$1,955.90	\$1,955.
		0001	0380	7321016A	SECTION 24 IN. OR ALLOWED SUBSTITUTE SAFETY SLOPE END SECTION	2.00	0.00	2.00	EA	2.00	\$3,032.15	\$6,064.
		0001	0390	8051000A	SEEDING - COOL SEASON GRASSES	3.80	0.00	3.80	ACRE	3.80	\$2,604.00	\$9,895.
		0001	0400	8061004	SEDIMENT TRAP ROCK	100.00	0.00	100.00	CUYD	20.00	\$82.70	\$1,654.
		0001	0410	8061006	ALTERNATE DITCH CHECK	750.00	0.00	750.00	LF	750.00	\$6.20	\$4,650.
		0001	0420	8061016	SEDIMENT REMOVAL	170.00	0.00	170.00	CUYD	170.00	\$9.70	\$1,649.0
		0001	0430	8061019	SILT FENCE	4,411.00	-152.00	4,259.00	LF	4,259.00	\$1.85	\$7,879.

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

					teport Generated date and can differ from the posted am							THUNKIN DOOTED
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220318-C01	J3P3078	0001	0440	8064131	TYPE 1A EROSION CONTROL BLANKET	675.00	0.00	675.00	SQYD	675.00	\$2.65	\$1,788.75
		0003	0460	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	18,257.60	0.00	18,257.60	SQYD	18,257.60	\$76.65	\$1,399,445.04
		0005	0480	5021340	TYPE A2 SHOULDER	7,156.50	0.00	7,156.50	SQYD	7,156.50	\$55.80	\$399,332.70
		0020	0490	9011060	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 1	4.00	0.00	4.00	EA	4.00	\$4,491.90	\$17,967.60
		0020	0500	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	4.00	0.00	4.00	EA	4.00	\$3,612.00	\$14,448.00
		0020	0510	9011115	BRACKET ARM, 15 FT. OR 4.6 M	8.00	0.00	8.00	EA	8.00	\$1,199.10	\$9,592.80
		0020	0520	9011312	LUMINAIRE, LED-B	8.00	0.00	8.00	EA	8.00	\$405.30	\$3,242.40
		0020	0530	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	1.00	0.00	1.00	EA	1.00	\$7,728.00	\$7,728.00
		0020	0540	9014003	CONDUIT, 3 IN. RIGID, PUSHED	625.00	90.00	715.00	LF	715.00	\$23.10	\$16,516.50
		0020	0550	9015010	TRENCHING TYPE I	5,149.00	0.00	5,149.00	LF	5,149.00	\$4.75	\$24,457.75
		0020	0560	9016110	PULL BOX, PREFORMED CLASS 1	15.00	2.00	17.00	EA	17.00	\$1,218.00	\$20,706.00
		0020	0570	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	960.00	0.00	960.00	LF	960.00	\$1.05	\$1,008.00
		0020	0580	9017401	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 2 AWG	40.00	0.00	40.00	LF	40.00	\$14.70	\$588.00
		0020	0590	9017404	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG	3,670.00	0.00	3,670.00	LF	3,670.00	\$6.30	\$23,121.00
		0020	0600	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	2,610.00	0.00	2,610.00	LF	2,610.00	\$4.95	\$12,919.50
		0020	0610	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	8.00	0.00	8.00	EA	8.00	\$2,041.20	\$16,329.60
		0020	0620	9018612	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	1.00	0.00	1.00	EA	1.00	\$2,100.00	\$2,100.00
		0040	0630	9031010	CONCRETE FOOTINGS, EMBEDDED	10.03	0.00	10.03	CUYD	10.03	\$1,050.00	\$10,531.50
		0040	0640	9031210	STRUCTURAL STEEL POSTS	3,120.00	0.00	3,120.00	LB	3,120.00	\$7.90	\$24,648.00
		0040	0650	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	60.00	0.00	60.00	EA	60.00	\$367.50	\$22,050.00
		0040	0660	9031256	7 FT. CHANNEL POST DELINEATOR, WHITE	121.00	0.00	121.00	EA	121.00	\$47.25	\$5,717.25
		0040	0670	9031272	2.25 IN. PSST POST - 12 GA.	132.00	0.00	132.00	LF	132.00	\$21.00	\$2,772.00
		0040	0680	9031280	2.5 IN. PSST POST - 12 GA.	1,095.00	0.00	1,095.00	LF	1,095.00	\$26.25	\$28,743.75
		0040	0690	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	273.00	0.00	273.00	LF	273.00	\$52.50	\$14,332.50
		0040	0700	9035004A	SH-FLAT SHEET	1,500.00	0.00	1,500.00	SQFT	1,500.00	\$21.00	\$31,500.00
		0040	0710	9035011A	ST-STRUCTURAL	386.00	0.00	386.00	SQFT	386.00	\$28.90	\$11,155.40
		0040	0715	9035069A	SHF-FLAT SHEET FLUORESCENT	36.00	0.00	36.00	SQFT	36.00	\$22.05	\$793.80
		0001	5001	6139905	MISC.PAVEMENT REPAIR	0.00	32.00	32.00	SQYD	32.00	\$258.21	\$8,262.72
		0001	5002	7261018	18 IN. PIPE GROUP A	0.00	92.00	92.00	LF	92.00	\$100.85	\$9,278.20
		0001	5003	2029901	MISC.Removal Of Improvements	0.00	1.00	1.00	LS	1.00	\$950.00	\$950.00
		0001	5004	1046002	VALUE ENGINEERING	0.00	44,696.44	44,696.44	EA	44,696.44	\$1.00	\$44,696.44
		0020	5005	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	0.00	76.00	76.00	LF	76.00	\$13.12	\$997.50
		0020	5006	9105200	CONDUIT, 2 IN., RIGID, IN TRENCH	0.00	20.00	20.00	LF	20.00	\$26.25	\$525.00
					Date as of Report Generated Date							\$3,158,026.70
220318-C01 Ove	rall - Total	Value Post	ted to Da	te as of Rep	ort Generated Date							\$3,158,026.70



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

	J3P3078											
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0230	6200021	PREF THERMO PVMT MARK, LT/RT ARROW	12/1/22	12/1/22	6.00	EA	WB Phase III Locations: 214-29.57 = 1 212-30.81 = 1 211-04.95 = 1 207-75.05 = 1 207-74.09 = 1 207-93.44 = 1					
0240	6200042	PREF THERMO PVMT MARK, YIELD TRIAN	12/1/22	12/1/22	4.00	EA	Route 50 WB Phase III = 4					
0250	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	12/1/22	12/1/22	118.00	LF	Route 50 EB/WB Phase III section = 118					
0260	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	12/1/22	12/1/22	1,144.00	LF	EB/WB Phase III section = 1144					
0290	6207001	PAVEMENT MARKING REMOVAL	12/1/22	12/1/22	1,108.00	LF	Removals of intermittent tane lines for Acceleration/Deacceleration lanes set up in the plans/should have been called out as 3' dotted line/not 10' intermittent line = 700' Removal of existing striping for Phase III tie in to					
							existinting stripe = 408'					
		SEEDING - COOL SEASON GRASSES		12/1/22			Phase III section = 0.16					
0410	8061006	ALTERNATE DITCH CHECK		12/1/22	545.00	LF	187+07-188+25 = 30 189+65-199+40 = 130 204+00-206+00 = 20 202+00-208+00 = 30 212+00-218+00 = 90 214+00-216+00 = 20 221+80-225+40 = 70 226+60-231+80 = 140 229+40-232+60(part) = 15					
0420	8061016	SEDIMENT REMOVAL	12/1/22	12/1/22	170.00	CUYD	Wattle cleanouts throughout the job = 170					
0440	8064131	TYPE 1A EROSION CONTROL BLANKET	12/1/22	12/1/22	675.00	SQYD	$\begin{array}{l} 187+07-188+25=27\\ 189+65-199+40=117\\ 204+00-206+00=18\\ 202+00-208+00=27\\ 212+00-218+00=27\\ 212+00-218+00=81\\ 221+80-225+40=63\\ 226+60-231+80=126\\ 229+40-2325+60=81\\ 233+68-235+68=54\\ 237+60-240+00=63\\ \end{array}$					
0490	9011060	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT	12/1/22	12/1/22	4.00	EA	189+13.90 = 1 232+78.85 = 1 236+15.96 = 1 237+12.05 = 1					
0500	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT	12/1/22	12/1/22	4.00	EA	209+32 = 1 210+67 = 1 209+54.29 = 1 210+33.30 = 1					
0510	9011115	BRACKET ARM, 15 FT. OR 4.6 M	12/1/22	12/1/22	8.00	EA	209432 = 1 210457 = 1 20945429 = 1 210433.00 = 1 189413.00 = 1 232478.85 = 1 233415.96 = 1 237412.05 = 1					
0520	9011312	LUMINAIRE, LED-B	12/1/22	12/1/22	8.00	EA	209402 = 1 201477 = 1 201474 20 = 1 210433 20 = 1 189413 30 = 1 232478 85 = 1 233415 96 = 1 237412 05 = 1					
0570	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE & BRACKE	12/1/22	12/1/22	960.00	LF	209+32 = 120 210+67 = 120 210+54.29 = 120 210+33.30 = 120 189+13.30 = 120 232+78.85 = 120 236+15.96 = 120 237+12.05 = 120					
0580	9017401	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS	12/1/22	12/1/22	40.00	LF	Power Supply - Controller = 40					
0590		CABLE-CONDUIT, 1 IN., 2 CONDUCTORS		12/1/22	3,670.00	LF	Controller - PB1 = 24 PB1-PB7=51.6 PB7-61-28.8 C1-02=89.2 C2-PB8-P810=531 PB8-PB10=531 PB10-PB11=531 PB10-PB11=531 PB12-PB13=257.3 PB13-PB14=162.7 PB13-PB15=387.9 PB13-PB15=387.9 PB13-PB15=387.9 PB15-C5=110.8					
0600	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS	12/1/22	12/1/22	2,610.00	LF	PBS-PB6=531 PB6-B1=533.6 Controlex-PB1=22 PB1-PB2=43.5 PB2-PB3=167.7 PB3-A1=533 A1-A2=14.6.5 Controlex-PB1=24 PB1-PB2=43.5 PB2-PB4=531 PB2-PB4=531					
0620	9018612	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120	12/1/22	12/1/22	1.00	EA	19+70.98 = 1					
0630	9031010	CONCRETE FOOTINGS, EMBEDDED	12/1/22	12/1/22	4.41	CUYD	3=.09 4=.09 6=.18 8=.09 9=.03 12=-10 14=.00 14=.00 14=.00 21=.00 23=.00 23=.00 23=.00 23=.00 23=.00 30=.18 35=.09 37=.09					



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

							on of detail, location and quantity of work.					
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
							45=09 46=09 46=09 49=09 52=09 54=09 54=09 58=09 58=09 63=09 63=09 63=09 63=09 63=09 63=09 63=09 63=09 63=09 63=09 63=09 63=09 74=09 75=18 77=18 77=18 78=18	MIT		IMIE		
0640	9031210	STRUCTURAL STEEL POSTS	12/1/22	12/1/22	882.05	LB	#8=63.8 9=31.9 10=85 15=63.8 15=63.8 23=63.8 35=63.8 35=63.8 52=63.8 54=63.8 54=63.8 63=63.8 63=63.8 63=63.8 63=63.1 68=53.1 73(par)=20.95					
0650	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	12/1/22	12/1/22	30.00	EA	#6=2 8=1 9=1 12=2 15=1 138-1 233=1 30=2 35=1 43=2 45=1 54=1 59=2 60=2 63=1 63=1 77=2 78=2					
0660		7 FT. CHAN, POST DELINE,, WHITE 225 IN. PSST POST - 12 GA.	12/1/22		3.00		Part of EB Phase III = 3 #15=6 18=6 18=6 28=6 29=6 29=6 52=6 54=6 68=6 68=6 69=6 73=6					
0680		2.5 IN. PSST POST - 12 GA.	12/1/22		555.00	LF	$\begin{split} & \text{Sign Hat=0.7} \\ & \text{G=14.3} \\ & \text{G=24.3} \\ & \text{I} \\ & I$					
0690	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	12/1/22	12/1/22	144.00	LF	Tops://sci Sign #4-3 6=6 Sign #4-3 12=6 1 14=3 1 15=3 21=3 21=3 21=3 23=3 35=3 37=3 35=3 37=3 43=6 45=3 48=3 49=3 49=3					



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line	Item	Description	DWR	DWR	Quantity	Units	Location	From	Offset/	То	Offset/	Comments
umber	Code		Date	Approval Date	Posted			Station/ Log Mile	Distance	Station/ Log Mile	Distance	
							52=3 54=3 57=3 53=6 60=6 62=3 63=3 63=3 63=3 63=3 63=3 63=3 63					
0700	9035004A	SH-FLAT SHEET	12/1/22	12/1/22	787.55	SQFT	Sign #B = 30.5 9=12.5 15=40.79 18=39.79 21=13.93 23=39.79 33=39.79 33=39.79 33=29.79 33=12.5 43=13.93 43=13.93 43=13.93 43=33.010 53=20.50 63=12.5 63=20.50 63=12.5 63=20.50 63=12.50 73=16 74=10.75 74=10.75 74=50.75 63=20.5					
0715	9035069A	SHF-FLAT SHEET FLUORESCENT	12/1/22	12/1/22	18.00	SQFT	#26=9 #46=9					
5005	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	12/1/22	12/1/22	76.00	LF	Power Supply - Controller = 26 Power Supply - Pole - Up Pole = 50					
5006	9105200	CONDUIT, 2 IN., RIGID, IN TRENCH	12/1/22	12/1/22	20.00	LF	Power Supply - PB1 = 10 Pole - Power Supply = 10					

The information below this line are details for Construction Signs (if applicable). No Data Available



Dec 6, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J3P3078	0020	CLASS A EXCAVATION	Other Item Adjustment	FUEL	5	Nov 2, 2022	degrow1	(\$190.02)	This is to correct the wrong fuel factor from estimate #0004: \$421.84-\$231.82 = \$190.02			
				FUEL - Tota	I			(\$190.02)				
			Other Item A	Adjustment -	Total			(\$190.02)				
			Price FUEL		1	Sep 1, 2022	SYSTEM	\$268.48	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
					2	Sep 16, 2022	SYSTEM	\$422.32	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
					4	Oct 17, 2022	SYSTEM	\$421.84	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
					6	Nov 15, 2022	SYSTEM	\$181.19	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
				- Total				\$1,293.83				
			Price FUEL	- Total				\$1,293.83				
	0020 -	Total						\$1,103.81				
	0030	EMBANKMENT IN PLACE	Material		1	Sep 1, 2022	SYSTEM	\$11,500.11	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user degrow1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					1	Sep 1, 2022	SYSTEM	(\$11,500.11)				
					2	Sep 16, 2022	SYSTEM	\$23,000.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user degrow1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					2	Sep 16, 2022	SYSTEM	(\$23,000.22)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
			Other Item Adjustment	FUEL	5	Nov 2, 2022	degrow1	(\$254.43)	This is to correct the wrong fuel factor from estimate #0004: \$564.84-\$310.41 = \$254.43			
				FUEL - Tota	l			(\$254.43)				
			Other Item A	Adjustment -	Total			(\$254.43)				
			Price FUEL		1	Sep 1, 2022	SYSTEM	\$160.64	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
					2	Sep 16, 2022	SYSTEM	\$252.69	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
								4	Oct 17, 2022	SYSTEM	\$564.84	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Nov 15, 2022	SYSTEM	\$621.35	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
				- Total				\$1,599.52				
			Price FUEL	- Total				\$1,599.52				
	0030 -	Total						\$1,345.09				
	0040	COMPACTING EMBANKMENT	Material		2	Sep 16, 2022	SYSTEM	\$852.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user degrow1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					2	Sep 16, 2022	SYSTEM	(\$852.80)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0040 -	Total						\$0.00				
	0060	TYPE 1 AGGREGATE FOR BASE (6	Material		1	Sep 1, 2022	SYSTEM	\$45,379.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user degrow1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
		IN. THICK)			1	Sep 1, 2022	SYSTEM	(\$45,379.20)				
					2	Sep 16, 2022	SYSTEM	\$108,956.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user degrow1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					2	Sep 16, 2022	SYSTEM	(\$108,956.16)				



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
P3078	0060	TYPE 1 AGGREGATE FOR BASE (6	Material		3	Oct 3, 2022	SYSTEM	\$41,467.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user degrow1 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
		IN. THICK)			3	Oct 3, 2022	SYSTEM	(\$41,467.20)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
			Other Item Adjustment	FUEL	5	Nov 2, 2022	degrow1	(\$761.10)	This is to correct the wrong fuel factor from estimate #0004: \$ 1689.65 - \$ 928.55 = \$761.10				
				FUEL - Tota	I			(\$761.10)					
			Other Item	Adjustment -	Total			(\$761.10)					
			Price FUEL		1	Sep 1, 2022	SYSTEM	\$967.62	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
					2	Sep 16, 2022	SYSTEM	\$2,132.48	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
					3	Oct 3, 2022	SYSTEM	\$419.86	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
					4	Oct 17, 2022	SYSTEM	\$1,689.65	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
					5	Nov 1, 2022	SYSTEM	\$521.42	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
					6	Nov 15, 2022	SYSTEM	\$832.41	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
				- Total				\$6,563.44					
			Price FUEL	- Total				\$6,563.44					
	0060 -	Total						\$5,802.34					
	0080	CONCRETE PAVEMENT (8 IN. NON- REINFORCED,	Material		5	Nov 1, 2022	SYSTEM	\$21,184.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user degrow1 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					5	Nov 1, 2022	SYSTEM	(\$21,184.38)					
					6	Nov 15, 2022	SYSTEM	\$21,184.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user degrow1 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					6	Nov 15, 2022	SYSTEM	(\$21,184.38)					
				- Total		\$0.00							
			Material - To	otal				\$0.00					
			Price FUEL		5	Nov 1, 2022	SYSTEM	\$56.66	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
				- Total				\$56.66					
			Price FUEL	- Total				\$56.66					
	0080 -	Total						\$56.66					
	0090	6 IN. CONCRETE MEDIAN STRIP	Material		2	Sep 16, 2022	SYSTEM	\$5,495.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Exception 9 on the current Payment Estimate.				
					2	Sep 16, 2022	SYSTEM	(\$5,495.85)					
									3	Oct 3, 2022	SYSTEM	\$10,740.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user degrow1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Oct 3, 2022	SYSTEM	(\$10,740.20)					
					4	Oct 17, 2022	SYSTEM	\$10,740.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user degrow1 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
					4	Oct 17, 2022	SYSTEM	(\$10,740.20)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
	0090 -	Total						\$0.00					



3P3737 10 µ ROX LINKS F Market F 10 µ ROX LINKS F ROX LINKS F <throx links<br="">F ROX LINKS F</throx>	Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks		
Image: constraint of the control of the con	J3P3078	0100	ROCK LINING	Material	Туре	5		SYSTEM	\$893.50			
Image: state of the s												
Internal Foul Internal Foul Internal Foul Internal Found Internal F						5		SYSTEM	· · ·			
Stab. Table Test Stab. Table Stab. Table <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>												
9230 VVIT MARK, VITER APPORT VVIT APPORT VVIT MARK, VITER APPORT VVIT APPORT VVIT MARK, VITER APPORT VVIT APPORT VVIT MARK, VITER APPORT VVIT APPORT V				Material - To	otal				\$0.00			
$ \begin{array}{ c $		0100 -	Total						\$0.00			
Color Color System Citation System Citation Addresidal - Total		0230	THERMO	Material		4		SYSTEM	\$1,512.00	Estimate Item Adjustment (0005) due to user degrow1 overridding Payment		
Material - Total 40.00 0230 - Total 9000 0240 - Total PREF Material - Total \$1,323.00 - TetEMAR YELD TRANK - Total \$1,323.00 This adjustment officits the original system-generated Material Payment Estimate Isen Adjustment officits the original system-generated Material Payment - Total - Total \$1,323.00 - 0240 - Total - Total \$1,020.00 - 0240 - Total - Total \$1,000 - 0240 - Total - Total \$5,900.75 - 0240 - Total - Total \$5,900.75 - 041 - Total - Total \$5,900.75 - 041 - Total - Total \$5,900.75 - 041 - Total - Total			LI/RI ARROW			4		SYSTEM	(\$1,512.00)			
0230 - Total United by the second seco					- Total				\$0.00			
0240 PREF THERD PVLF MARK, YELD TRIAN VELOTION Material here 4 0x17, 2022, 3 SYSTEM \$1,232.00 This adjustment officiate the original system-spectrated Material Payment Estimate Exception 11 on the current Payment Estimate. 0240 - Total - Total - Total - Total - Total 0240 - Total - Total - Total - Total - Total 0240 - Total - Total - Total - Total - Total 0240 - Total - Total - Total - Total - Total 0240 - Total - Total - Total - Total - Total 0240 - Total - Total - Total - Total - Total 0240 - Total -				Material - To	otal				\$0.00			
0240 PREF THERD PVLF MARK, YELD TRIAN VELOTION Material here 4 0x17, 2022, 3 SYSTEM \$1,232.00 This adjustment officiate the original system-spectrated Material Payment Estimate Exception 11 on the current Payment Estimate. 0240 - Total - Total - Total - Total - Total 0240 - Total - Total - Total - Total - Total 0240 - Total - Total - Total - Total - Total 0240 - Total - Total - Total - Total - Total 0240 - Total - Total - Total - Total - Total 0240 - Total - Total - Total - Total - Total 0240 - Total -		0230 -	Total						\$0.00			
Code			PREF THERMO PVMT MARK,	Material		4		SYSTEM		Estimate Item Adjustment (0006) due to user degrow1 overridding Payment		
Image: constraint of the second sec			YIELD I RIAN			4		SYSTEM	(\$1,323.00)			
O240 - Total Status Status <thstatus< th=""> <thstatus< th=""> <thstat< td=""><td></td><td></td><td></td><td></td><td>- Total</td><td></td><td></td><td></td><td>\$0.00</td><td></td></thstat<></thstatus<></thstatus<>					- Total				\$0.00			
O240 - Total Status Status <thstatus< th=""> <thstatus< th=""> <thstat< td=""><td></td><td></td><td></td><td>Material - To</td><td>otal</td><td></td><td></td><td></td><td>\$0.00</td><td></td></thstat<></thstatus<></thstatus<>				Material - To	otal				\$0.00			
0250 6 IN. WHITE HIGH BUILD WATENDRIVE Material HIGH BUILD PAINT Material PAINT 4 0cd 17. 2022 SYSTEM 56,990.75 This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate. AIR TENDRIVE 4 0cd 17. 2022 SYSTEM 56,990.75 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. VIEW PAINT 5 Nov 1. 2022 SYSTEM 56,990.75 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. VIEW PAINT - Total VIEW PAINT 56,990.75 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. VIEW PAINT - Total VIEW PAINT 4 0cd 17. 2022 SYSTEM 56,990.75 VIEW PAINT Material - Total VIEW PAINT 4 0cd 17. 2022 SYSTEM 50.00 VIEW PAINT Material - Total VIEW PAINT 4 0cd 17. 2022 SYSTEM 500.750 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustm		0240 -	Total						\$0.00			
High Bulk High Bulk High Bulk Image and adjustment (0007) due io user degrow1 overridding Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate PAINT PAINT V<				Material		4	0-147	OVOTEM		This adjustes and effects the entries I contains accounted Material Decourses		
		0250	HIGH BUILD WATERBORNE	Material		4		SYSTEM	\$6,990.75	Estimate Item Adjustment (0007) due to user degrow1 overridding Payment		
Image: Part of the second se						4		SYSTEM	(\$6,990.75)			
Vision Vision Vision 0260 - Total 50.00 0250 - Total 50.00 0260 6 IN, YELLOW, HIGH BULD WATERDARM, PAINT Material - Total 4 Oct 17, 2022 SYSTEM \$307.50 This adjustment offsets the original system-generated Material Payment Estimate tem Adjustment (0006) due to user degrow1 overridding Payment Estimate tem Adjustment (0006) due to user degrow1 overridding Payment Estimate tem Adjustment (0006) due to user degrow1 overridding Payment Estimate tem Adjustment (0006) due to user degrow1 overridding Payment Estimate tem Adjustment (0006) due to user degrow1 overridding Payment Estimate Exception 10 on the current Payment Estimate. 0 - Total 5 Nov 1, 2022 SYSTEM (\$307.50) - Total - Total 5 Nov 1, 2022 SYSTEM (\$307.50) 0 - Total - Total - So.00 - So.00 0260 - Total - Total - So.00 - So.00 0260 - Total - Cotal - So.00 - So.00 0260 - Total - Cotal - Cot 1, 2022 SYSTEM S0.03 0280 - Zi IN. WHITE MARKING 4 Oct 17, 2022 SYSTEM S2.043.30 This adjustment offsets the o						5		SYSTEM	\$6,990.75	Estimate Item Adjustment (0005) due to user degrow1 overridding Payment		
Material - Total Store 0260 - Total 50.00 0260 - Total SYSTEM S00.00 0260 - Michel BORNE PAINT Material - Total SYSTEM S00.00 Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate 0260 - Total SYSTEM SVSTEM S00.00 0270 - Total SYSTEM SVSTEM SVSTEM 0260 - Total SVSTEM SVSTEM SVSTEM 0270 - Total SVSTEM SVSTEM SVSTEM 0270 - Total SVSTEM SVSTEM SVSTEM 0270 - Total SVSTEM SVSTEM SVSTEM 0280 - Total SVSTEM SVSTEM SVSTEM 0280 - Total SVSTEM SVSTEM SVSTEM 0280 - SVSTEM SVSTEM SVSTEM SVSTEM 0290 - SVSTEM						5		SYSTEM	(\$6,990.75)			
O250 - Total S0.00 0260 6 IN. YELLOW HIGH BUILD WATERBORNE PAINT Material Extende Issue Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user degrowt overridding Payment Estimate Item Adjustment (0008) due to user degrowt overridding Payment Estimate Item Adjustment (0006) due to user degrowt overridding Payment Estimate Item Adjustment (0006) due to user degrowt overridding Payment Estimate Exception 14 on the current Payment Estimate. 0 0 - Total \$307.50 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. 0 - Total \$2022 SYSTEM \$307.50 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. 0 - Total \$2022 SYSTEM \$307.50 0 - Total \$2021 SYSTEM \$307.50 0 - Total \$2022 SYSTEM \$2.043.30 0 - Total \$2022					- Total				\$0.00			
0260 6 IN. YELLOW HIGH BUILD WATERSONT PAINT Material HIGH BUILD WATERSONT PAINT Material HIGH BUILD PAINT Material HIGH PAINT Material HIGH PAINT SYSTEM PAINT SYSTEM PAINT SYSTEM PAINT SYSTEM HIGH PAINT SYSTEM PAINT SYSTEM HIGH PAINT SYSTEM PAINT SYSTEM HIGH PAINT SYSTEM PAINT SYSTEM P				Material - To	otal				\$0.00			
 HICH BUILD WATERBORNE PAINT HICH BUILD PAINT HICH BUILD PAINT HICH BUILD PAINT PAINT PA		0250 -	Total						\$0.00			
 		0260	6 IN. YELLOW HIGH BUILD	Material		4		SYSTEM	\$307.50	Estimate Item Adjustment (0008) due to user degrow1 overridding Payment		
$ \begin{array}{c c c c c c c c c c c c c c c c c c c $			PAINT					4		SYSTEM	(\$307.50)	
Image: bit in the second se								5		SYSTEM	\$307.50	Estimate Item Adjustment (0006) due to user degrow1 overridding Payment
Material - Total \$0.00 O260 - Total \$0.00 V \$0.00 O280 24 IN. WHITE PAVEMENT MARKING Material Oct 17, 2022 SYSTEM \$2,043.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user degrow1 overridding Payment Estimate Item Adjustment (0009) due to user degrow1 overridding Payment Estimate Item Adjustment (0009) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding						5		SYSTEM	(\$307.50)			
O260 - Total \$0.00 0280 24 IN. WHITE WATERBORNE PAVEMENT MARKING Material 4 Oct 17, 2022 SYSTEM \$2,043.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user degrow1 overridding Payment Estimate Exception 16 on the current Payment Estimate. 4 Oct 17, 2022 SYSTEM (\$2,043.30) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user degrow1 overridding Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Exception 12 on the current Payment Estimate.					- Total				\$0.00			
O260 - Total \$0.00 0280 24 IN. WHITE WATERBORNE PAVEMENT MARKING Material 4 Oct 17, 2022 SYSTEM \$2,043.30 This adjustment offsets the original system-generated Material Payment Estimate texception 16 on the current Payment Estimate. 4 Oct 17, 2022 SYSTEM (\$2,043.30) This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate. 5 Nov 1, 2022 SYSTEM \$2,043.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Exception 12 on the current Payment Estimate.				Material - To	otal				\$0.0 <u>0</u>			
0280 24 IN. WHITE WATERBORNE PAVEMENT MARKING Material 4 Oct 17, 2022 SYSTEM \$2,043.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user degrow1 overridding Payment 4 Oct 17, 2022 SYSTEM (\$2,043.30) This adjustment offsets the original system-generated Material Payment 5 Nov 1, 2022 SYSTEM \$2,043.30 This adjustment offsets the original system-generated Material Payment 5 Nov 1, 2022 SYSTEM \$2,043.30 This adjustment offsets the original system-generated Material Payment 5 Nov 1, 2022 SYSTEM \$2,043.30 This adjustment offsets the original system-generated Material Payment 5 Nov 1, 2022 SYSTEM \$2,043.30 This adjustment offsets the original system-generated Material Payment 5 Nov 1, 2022 SYSTEM \$2,043.30 This adjustment offsets the original system-generated Material Payment		0260	Total									
MARKING MARKING 4 Oct 17, 2022 SYSTEM (\$2,043.30) 5 Nov 1, 2022 SYSTEM \$2,043.30			24 IN. WHITE WATERBORNE	Material		4		SYSTEM		Estimate Item Adjustment (0009) due to user degrow1 overridding Payment		
2022 Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Exception 12 on the current Payment Estimate. 5 Nov 1, 2022 SYSTEM (\$2,043.30)						4		SYSTEM	(\$2,043.30)			
2022						5		SYSTEM	\$2,043.30	Estimate Item Adjustment (0007) due to user degrow1 overridding Payment		
- Total \$0.00						5		SYSTEM	(\$2,043.30)			
					- Total				\$0.00			



Dec 6, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J3P3078	0280	24 IN. WHITE WATERBORNE PAVEMENT MARKING	Material - To	otal				\$0.00					
	0280 -	Total						\$0.00					
	0390	SEEDING - COOL SEASON	Material		3	Oct 3, 2022	SYSTEM	\$6,978.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user degrow1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
		GRASSES			3	Oct 3, 2022	SYSTEM	(\$6,978.72)					
					4	Oct 17, 2022	SYSTEM	\$6,978.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user degrow1 overridding Payment Estimate Exception 19 on the current Payment Estimate.				
					4	Oct 17, 2022	SYSTEM	(\$6,978.72)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
	0390 -	Total						\$0.00					
	0460	CONCRETE PAVEMENT (8 IN. NON- REINFORCED,	Material		2	Sep 16, 2022	SYSTEM	\$388,561.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate.				
		Reini OROED,			2	Sep 16, 2022	SYSTEM	(\$388,561.84)					
					3	Oct 3, 2022	SYSTEM	\$731,685.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user degrow1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					3	Oct 3, 2022	SYSTEM	(\$731,685.57)					
									4	Oct 17, 2022	SYSTEM	\$1,107,147.93	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user degrow1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Oct 17, 2022	SYSTEM	(\$1,107,147.93)					
					5	Nov 1, 2022	SYSTEM	\$1,316,701.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user degrow1 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
					5	Nov 1, 2022	SYSTEM	(\$1,316,701.36)					
					6	Nov 15, 2022	SYSTEM	\$1,399,445.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user degrow1 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
					6	Nov 15, 2022	SYSTEM	(\$1,399,445.04)					
					7	Dec 1, 2022	SYSTEM	\$19,607.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user degrow1 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					7	Dec 1, 2022	SYSTEM	(\$19,607.07)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
			Other Item Adjustment	PCCS	5	Nov 2, 2022	degrow1	\$12,637.76	Lots 1-6 strength adjustments: Lot 1 = \$2500.71 Lot 2 = \$538.54 Lot 3 = \$2017.58 Lot 4 = \$2949.88 Lot 5 = \$4154.24 Lot 6 = \$1553.89				
					6	Nov 15, 2022	degrow1	\$7,120.79	Lots 7-9 Lot 7 = \$2130.87 Lot 8 = \$2,893.54 Lot 9 = \$2,096.38				
					7	Dec 2, 2022	degrow1	\$7,689.72	Lot 10 = \$3108.73 Lot 11 = \$3429.32 Lot 12 = \$1151.67				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3P3078	0460	CONCRETE	Other Item	PCCS - Tota	ıl			\$27,448.27	
		PAVEMENT (8 IN. NON- REINFORCED,	Adjustment	PCCT	5	Nov 2, 2022	degrow1	\$18,107.05	Lots 1-6 thickness adjustment: Lot 1 =\$2500.71 Lot 2 =\$4487.86 Lot 3 =\$2460.47 Lot 4 =\$2949.88 Lot 5 =\$4154.24 Lot 6 =\$1553.89
					6	Nov 15, 2022	degrow1	\$7,120.79	Lots 7 - 9 Lot 7 = \$2130.87 Lot 8 = \$2,893.54 Lot 9 = \$2,096.38
					7	Dec 2, 2022	degrow1	\$7,689.72	Lot 10 = \$3108.73 Lot 11 = \$3429.32 Lot 12 = \$1151.67
				PCCT - Tota	ıl			\$32,917.56	
					5	Nov 2, 2022	degrow1	(\$1,469.52)	This is to correct the wrong fuel factor from estimate #0004: \$3262.33-\$1792.81 = \$1469.52
				- Total				(\$1,469.52)	
			Other Item	Adjustment -	Total			\$58,896.31	
			Price FUEL		2	Sep 16, 2022	SYSTEM	\$4,258.21	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					3	Oct 3, 2022	SYSTEM	\$3,760.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Oct 17, 2022	SYSTEM	\$3,262.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Nov 1, 2022	SYSTEM	\$1,000.61	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Nov 15, 2022	SYSTEM	\$919.73	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$13,201.14	
			Price FUEL	- Total	Total				
	0460 -	- Total						\$72,097.45	
	0480	SHOULDER	Material		2	Sep 16, 2022	SYSTEM	\$89,118.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user degrow1 overridding Payment
									Estimate Exception 7 on the current Payment Estimate.
					2	Sep 16, 2022	SYSTEM	(\$89,118.18)	
					2		SYSTEM SYSTEM	(\$89,118.18) \$269,380.08	
						2022 Oct 17,			Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user degrow1 overridding Payment
					4	2022 Oct 17, 2022 Oct 17,	SYSTEM	\$269,380.08	Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user degrow1 overridding Payment
					4 4 5 5	2022 Oct 17, 2022 Oct 17, 2022 Nov 1, 2022 Nov 1, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$269,380.08 (\$269,380.08) \$315,560.16 (\$315,560.16)	Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4 5	2022 Oct 17, 2022 Oct 17, 2022 Nov 1, 2022 Nov 1,	SYSTEM SYSTEM SYSTEM	\$269,380.08 (\$269,380.08) \$315,560.16	Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user degrow1 overridding Payment
					4 4 5 5	2022 Oct 17, 2022 Oct 17, 2022 Nov 1, 2022 Nov 1, 2022 Nov 1, 2022 Nov 15,	SYSTEM SYSTEM SYSTEM SYSTEM	\$269,380.08 (\$269,380.08) \$315,560.16 (\$315,560.16) \$399,332.70 (\$399,332.70)	Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.
				- Total	4 4 5 5 6	2022 Oct 17, 2022 Oct 17, 2022 Nov 1, 2022 Nov 1, 2022 Nov 15, Nov 15,	SYSTEM SYSTEM SYSTEM SYSTEM	\$269,380.08 (\$269,380.08) \$315,560.16 (\$315,560.16) \$399,332.70 (\$399,332.70) \$0.00	Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.
			Material - T	otal	4 4 5 5 6 6	2022 Oct 17, 2022 Oct 17, 2022 Nov 17, 2022 Nov 1, 2022 Nov 15, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$269,380.08 (\$269,380.08) \$315,560.16 (\$315,560.16) \$399,332.70 (\$399,332.70) \$0.00	Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.
			Material - T Other Item Adjustment		4 5 5 6 6 2	2022 Oct 17, 2022 Oct 17, 2022 Nov 1, 2022 Nov 1, 2022 Nov 15, 2022 Nov 15, 2022 Sep 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$269,380.08 (\$269,380.08) \$315,560.16 (\$315,560.16) \$399,332.70 (\$399,332.70) \$0.00 \$0.00 \$1,095.61	Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.
			Other Item	otal	4 4 5 5 6 6 2 3	2022 Oct 17, 2022 Oct 17, 2022 Nov 1, 2022 Nov 1, 2022 Nov 15, 2022 Nov 15, 2022 Sep 16, 2022 Oct 3, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM degrow1 degrow1	\$269,380.08 (\$269,380.08) \$315,560.16 (\$315,560.16) \$399,332.70 (\$399,332.70) \$0.00 \$0.00 \$1,095.61 \$1,036.27	Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. \$1.40 * 1597.10 SY * 0.49 = \$1,095.61 \$1.40 * 1510.60 square yards * 0.49 = \$1,036.27
			Other Item	otal	4 4 5 5 6 6 2 3 4	2022 Oct 17, 2022 Nov 1, 2022 Nov 1, 2022 Nov 1, 2022 Nov 15, 2022 Seep 16, 2022 Oct 3, 2022 Oct 17, 2022 Oct	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM degrow1 degrow1 degrow1	\$269,380.08 (\$269,380.08) \$315,560.16 (\$315,560.16) \$399,332.70 (\$399,332.70) \$0.00 \$0.00 \$1,095.61 \$1,036.27 \$935.45	Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. \$1.40 * 1597.10 SY * 0.49 = \$1,095.61 \$1.40 * 1510.60 square yards * 0.49 = \$1,036.27 \$1.11 x 1,719.9 SY x 0.49 = \$935.45
			Other Item	otal	4 4 5 5 6 6 2 3	2022 Oct 17, 2022 Oct 17, 2022 Nov 1, 2022 Nov 1, 2022 Nov 15, 2022 Nov 15, 2022 Nov 15, 2022 Oct 3, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM degrow1 degrow1	\$269,380.08 (\$269,380.08) \$315,560.16 (\$315,560.16) \$399,332.70 (\$399,332.70) \$0.00 \$0.00 \$1,095.61 \$1,036.27	Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate. \$1.40 * 1597.10 SY * 0.49 = \$1,095.61 \$1.40 * 1510.60 square yards * 0.49 = \$1,036.27



Dec 6, 2022

ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
8078	0480	TYPE A2	Other Item	FUEL		2022							
		SHOULDER	Adjustment	FUEL - Tota	ıl			\$4,359.30					
					5	Nov 2, 2022	degrow1	(\$421.37)	This is to correct the wrong fuel factor from estimate #0004: \$ 935.45 - \$ 514.08= \$ 421.37				
				- Total				(\$421.37)					
			Other Item	Adjustment -	Total			\$3,937.93					
	0480 -	Total						\$3,937.93					
	0530	MOUNTED CONTROL	Material		5	Nov 1, 2022	SYSTEM	\$7,728.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user degrow1 overridding Payment Estimate Exception 15 on the current Payment Estimate.				
		STATION			5	Nov 1, 2022	SYSTEM	(\$7,728.00)					
					6	Nov 15, 2022	SYSTEM	\$7,728.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					6	Nov 15, 2022	SYSTEM	(\$7,728.00)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
	0530 -	Total						\$0.00					
	0630	CONCRETE FOOTINGS, EMBEDDED	Material		6	Nov 15, 2022	SYSTEM	\$5,901.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user degrow1 overridding Payment Estimate Exception 9 on the current Payment Estimate.				
					6	Nov 15, 2022	SYSTEM	(\$5,901.00)					
				- Total				\$0.00					
	Material - Total							\$0.00					
	0630 -	Total						\$0.00					
	0660	7 FT. CHAN. POST DELINE., WHITE	Material	Material		6	Nov 15, 2022	SYSTEM	\$5,575.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user degrow1 overridding Payment Estimate Exception 10 on the current Payment Estimate.			
							6	Nov 15, 2022	SYSTEM	(\$5,575.50)			
					7	Dec 1, 2022	SYSTEM	\$5,717.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user degrow1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					7	Dec 1, 2022	SYSTEM	(\$5,717.25)					
				- Total				\$0.00					
			Material - Total					\$0.00					
	0660 -	Total						\$0.00					
	0710	ST- STRUCTURAL	Material		6	Nov 15, 2022	SYSTEM	\$11,155.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user degrow1 overridding Payment Estimate Exception 12 on the current Payment Estimate.				
					6	Nov 15, 2022	SYSTEM	(\$11,155.40)					
				- Total				\$0.00					
			Material - T	otal				\$0.00					
	0710 -	Total						\$0.00					
	5001	MISC. PAVEMENT REPAIR	Material		2	Sep 16, 2022	SYSTEM	\$4,725.24	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user degrow1 overridding Payment Estimate Exception 12 on the current Payment Estimate.				
										2	Sep 16, 2022	SYSTEM	(\$4,725.24)
					3	Oct 3, 2022	SYSTEM	\$4,725.24	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
						3	Oct 3, 2022	SYSTEM	(\$4,725.24)				
					4	Oct 17,	SYSTEM	\$4,725.24	This adjustment offsets the original system-generated Material Payment				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3P3078	5001	MISC.	Material						Estimate Exception 9 on the current Payment Estimate.
		PAVEMENT REPAIR			4	Oct 17, 2022	SYSTEM	(\$4,725.24)	
					5	Nov 1, 2022	SYSTEM	\$4,725.24	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user degrow1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Nov 1, 2022	SYSTEM	(\$4,725.24)	
					6	Nov 15, 2022	SYSTEM	\$8,262.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user degrow1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Nov 15, 2022	SYSTEM	(\$8,262.72)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5001 -	Total						\$0.00	
J3P3078 -	Total						\$84,343.28		
Overall -	Total						\$84,343.28		