

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 2, 2022

Progress Estimate Number 1		o		See NTP Date September 1, 202	Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,651,413.81 \$0.00 \$1,651,413.81		
Approval Date							By User	
September 2, 2022	er 2, Generated and Approved (and should be considered Draft) at the Project Office Level by							
September 2, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by							
September 6, 2022	Reviewed and Approved at the Central Office Controllers Office Level by							
Original Comp	Original Completion Date		tion Date	Actual Compl	etion Date	% of Current Contract Amount Complete		
November 18, 2022		November 18	, 2022			10.08%		

	Milestones		
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	May 4, 2022	May 4, 2022	
Letting Date	April 15, 2022	April 15, 2022	
Notice to Proceed Date	June 6, 2022	June 6, 2022	
Open to Traffic Date			
Work Began Date	August 22, 2022	August 22, 2022	

Contract Total Pay For Estimate No. 1									
		This Estimate	Previous	To Date					
220415-C02									
	Total Posted Items Pay	\$166,402.98	\$0.00	\$166,402.98					
	Gross Item Adjustments	(\$1,505.78)	\$0.00	(\$1,505.78)					
	Incentive	\$0.00	\$0.00	\$0.00					
	Disincentive	\$0.00	\$0.00	\$0.00					
	Liquidated Damage	\$0.00	\$0.00	\$0.00					
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00					
			\$0.00	\$164,897.20					
<b>Contract Total Pa</b>	yable This Estimate:	\$164,897.20							

## Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4S3343	0010	2019919	MISC.DEBRIS AND VEGETATION REMOVAL	ACRE	\$26,250.000	0.2	\$5,250.00
	0020	2022010	REMOVAL OF IMPROVEMENTS	LS	\$170,180.000	0.05	\$8,509.00
	0030	2079909	MISC.LINEAR GRADING FOR SIDEWALKS	STA	\$2,900.000	2	\$5,800.00
	0130	6085008	PAVED APPROACH, 8 IN.	SQYD	\$96.050	92	\$8,836.60
	0140	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$67.650	114.7	\$7,759.46
	0150	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	LF	\$36.150	30	\$1,084.50
	0160	6099903	MISC.CURB AND GUTTER TYPE CG-1	LF	\$39.650	104	\$4,123.60
	0180	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	SQYD	\$294.100	163.26	\$48,014.77
	0210	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	LF	\$1.450	742	\$1,075.90
	0220	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$7.550	343	\$2,589.65
			CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	EA	\$4,700.000	2	\$9,400.00
	0270	6169901	MISC.TEMPORARY TRAFFIC CONTROL	LS	\$13,000.000	0.5	\$6,500.00
	0280	6169902	MISC.ADA COMPLIANT MOVEABLE BARRICADE	EA	\$100.000	4	\$400.00
	0290	6169902	MISC.CONCRETE CURB RAMP	EA	\$1,916.100	3	\$5,748.30

Revision 4/1/2020 Page 1 of 10



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 2, 2022

Progress Estimate Number			Pay Period Start		9	\$1,651,413.81
1	Prime Contractor	ldeker, Inc.	Pay Period End	September 1, 2022	Net Change Order Amount	\$0.00
·					Current Contract Amount	\$1,651,413.81

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4S3343	0300	6181000	MOBILIZATION	LS	\$201,044.800	0.25	\$50,261.20
	0440 8061006 ALTERNATE DITCH CHECK		ALTERNATE DITCH CHECK	LF	\$17.500	60	\$1,050.00
Project J4S3343 - Total							
Overall -	Total						\$166,402.98

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
4S3343	0130	PAVED APPROACH, 8 IN.	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	46	(\$0.07)	(\$3.04
	0130	PAVED APPROACH, 8 IN.	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	46	(\$0.07)	(\$3.04
	0130	PAVED APPROACH, 8 IN.	Material			-92	\$96.05	(\$8,836.60)
	0130	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user baiamf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	92	\$96.05	\$8,836.60
	0140	CONCRETE SIDEWALK, 4 IN.	Material			-114.7	\$67.65	(\$7,759.46)
	0140	CONCRETE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user baiamf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	114.7	\$67.65	\$7,759.46
	0150	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Overrun			-2	\$36.15	(\$72.30)
	0150	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material			-30	\$36.15	(\$1,084.50)
	0150	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user baiamf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	30	\$36.15	\$1,084.50
	0160	MISC.	Overrun			-36	\$39.65	(\$1,427.40)
	0180	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-163.26	\$294.10	(\$48,014.77)
	0180	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user baiamf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	163.26	\$294.10	\$48,014.77
	0220	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-343	\$7.55	(\$2,589.65)
	0220	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user baiamf1 overridding Payment Estimate Exception 8 on	343	\$7.55	\$2,589.65

Revision 4/1/2020 Page 2 of 10



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 2, 2022

			Pay Period Start		9	\$1,651,413.81
1	Prime Contractor	ldeker, Inc.	Pay Period End	September 1, 2022	Net Change Order Amount	\$0.00
'					Current Contract Amount	\$1,651,413.81

						Outlett Contract Amount \$\psi_1,001,410.01					
Project Number	Line No.	Item Descript	tion	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount		
J4S3343						the current Payment Estimate.					
	0250	COMMUI INTERFACE, CON FURNISHED, CON	IGN WITH NICATION TRACTOR	Material			-2	\$4,700.00	(\$9,400.00)		
	0250	COMMUI INTERFACE, CON FURNISHED, CON	IGN WITH NICATION TRACTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	2	\$4,700.00	\$9,400.00		
Total									(\$1,505.78)		

Revision 4/1/2020 Page 3 of 10



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

Contract Project Information										
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work					
J4S3343		Coldmill and resurface	1	CLAY	from the south ramps of I-35 to Route 210					
otals by	Job Numbe	rs								
J4S3343		d Harry Barr			This Estimate Previous	To Date				

Totals by Job Nur	s by Job Numbers							
J4S3343		This Estimate	Previous	To Date				
Po	osted Item Pay	\$166,402.98	\$0.00	\$166,402.98				
Gr	ross Item Adjustments	(\$1,505.78)	\$0.00	(\$1,505.78)				
	Gross Item Pay	\$164,897.20	\$0.00	\$164,897.20				
Inc	centive	\$0.00	\$0.00	\$0.00				
Di	isincentive	\$0.00	\$0.00	\$0.00				
	iquidated Damages	\$0.00	\$0.00	\$0.00				
Ot	ther Contract Adjustments	\$0.00	\$0.00	\$0.00				

Revision 4/1/2020 Page 4 of 10



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3343, Item 6085008, Project Item Line Number 0130, Material Set 608500896, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	waiting concrete 28 day strength	baiamf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3343, Item 6085008, Project Item Line Number 0130, Material Set 608500896, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	waiting concrete 28 day strength	baiamf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3343, Item 6085008, Project Item Line Number 0130, Material Set 608500896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	waiting concrete 28 day strength	baiamf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3343, Item 6086004, Project Item Line Number 0140, Material Set 608600496, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	waiting concrete 28 day strength	baiamf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3343, Item 6091010, Project Item Line Number 0150, Material Set 609101096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	waiting concrete 28 day strength	baiamf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3343, Item 6131010, Project Item Line Number 0180, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	waiting concrete 28 day strength	baiamf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3343, Item 6131015, Project Item Line Number 0220, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	waiting for materials records	baiamf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3343, Item 6131015, Project Item Line Number 0220, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	waiting for materials records	baiamf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3343, Item 6161099, Project Item Line Number 0250, Material Set 616109996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	waiting for materials records	baiamf1	Overridden
Estimate Exception Type: Item Overrun: Contract 220415-C02, Contract Project J4S3343, Project Item Line Number 0150, Contract Line Item Number 0150, Item 6091010, Minor Item.	change order being written for overrun	baiamf1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220415-C02, Contract Project J4S3343, Project Item Line Number 0160, Contract Line Item Number 0160, Item 6099903, Minor Item.	change order being written for overrun	baiamf1	Acknowledged

Revision 4/1/2020 Page 5 of 10



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTE To Date (See repor generated date)
220415-C02	J4S3343	0001	0010	2019919	MISC.DEBRIS AND VEGETATION REMOVAL	0.20	0.00	0.20	ACRE	Qty 0.20	\$26,250.00	\$5,250.0
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.05	\$170,180.00	\$8,509.
		0001	0030	2079909	MISC.LINEAR GRADING FOR SIDEWALKS	2.00	0.00	2.00	STA	2.00	\$2,900.00	\$5,800.
		0001	0040	2122000A	SUBGRADING AND SHOULDERING CLASS 2	131.00	0.00	131.00	100F	0.00	\$282.00	\$0.
		0001	0050	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	8,191.00	0.00	8,191.00	SQYD	0.00	\$10.45	\$0.
		0001	0060	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	3,093.00	0.00	3,093.00	SQYD	0.00	\$14.50	\$0.
		0001	0070	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	9.80	0.00	9.80	TONS	0.00	\$98.00	\$0.
		0001	0080	4011231	BITUMINOUS PAVEMENT MIXTURE PG58-28, (BP-1)	1,026.00	0.00	1,026.00	TONS	0.00	\$100.66	\$0.
		0001	0090	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	3,767.50	0.00	3,767.50	TONS	0.00	\$102.92	\$0.
		0001	0100	4030106	ASPHALTIC CONCRETE MIXTURE PG 58-28 (SP125C MIX)	2,733.00	0.00	2,733.00	TONS	0.00	\$78.78	\$0.
		0001	0110	4071005	TACK COAT	3,952.00	0.00	3,952.00	GAL	0.00	\$3.00	\$0.
		0001	0120	6042010	ADJUSTING MANHOLE	5.00	0.00	5.00	EA	0.00	\$2,300.00	\$0.
		0001	0130	6085008	PAVED APPROACH, 8 IN.	107.20	0.00	107.20	SQYD	92.00	\$96.05	\$8,836.
		0001	0140	6086004	CONCRETE SIDEWALK, 4 IN.	134.50	0.00	134.50	SQYD	114.70	\$67.65	\$7,759.
		0001	0150	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	28.00	0.00	28.00	LF	30.00	\$36.15	\$1,084.
		0001	0160	6099903	MISC.CURB AND GUTTER TYPE CG-1	68.00	0.00	68.00	LF	104.00	\$39.65	\$4,123.
		0001	0170	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$3,000.00	\$0
		0001	0180	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL	200.00	0.00	200.00	SQYD	163.26	\$294.10	\$48,014.
					DEPTH PAVEMENT REPAIR							
		0001	0190	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	20.00	0.00	20.00	SQYD	0.00	\$1.00	\$0
		0001	0200	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	20.00	0.00	20.00	SQYD	0.00	\$1.00	\$0
		0001	0210	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	960.00	0.00	960.00	LF	742.00	\$1.45	\$1,075
		0001	0220	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	600.00	0.00	600.00	EA	343.00	\$7.55	\$2,589
		0001	0230	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	201.40	0.00	0.00 201.40	TONS	0.00	\$159.31	\$0.
		0001	0240	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	905.00	0.00	905.00	SQYD	0.00	\$86.94	\$0
		0001	0250	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$4,700.00	\$9,400
		0001	0260	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	0.00	\$800.00	\$0
		0001	0270	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$13,000.00	\$6,500
		0001	0280	6169902	MISC.ADA COMPLIANT MOVEABLE BARRICADE	4.00	0.00	4.00	EA	4.00	\$100.00	\$400
		0001	0290	6169902	MISC.CONCRETE CURB RAMP	3.00	0.00	3.00	EA	3.00	\$1,916.10	\$5,748
		0001	0300	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.25	\$201,044.80	\$50,261
		0001	0310	6191000	PAVEMENT EDGE TREATMENT	12,979.00	0.00	12,979.00	LF	0.00	\$2.35	\$0
		0001	0320	6200006	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN	338.00	0.00	338.00	LF	0.00	\$2.00	\$0
		0001	0330	6200015	YELLOW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	60.00	0.00	60.00	LF	0.00	\$12.00	\$0
		0001	0340	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	48.00	0.00	48.00	LF	0.00	\$12.00	\$0
		0001	0350	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	6.00	0.00	6.00	EA	0.00	\$250.00	\$0
		0001	0360	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	33.00	0.00	33.00	EA	0.00	\$85.00	\$0
		0001	0370	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	18,564.00	0.00	18,564.00	LF	0.00	\$0.15	\$0
		0001	0380	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	19,607.00	0.00	19,607.00	LF	0.00	\$0.15	\$0
		0001	0390	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	34.00	0.00	34.00	LF	0.00	\$6.00	\$0
		0001	0400	6207001	PAVEMENT MARKING REMOVAL	471.00	0.00	471.00	LF	0.00	\$0.35	\$0
		0001	0410	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	1.00	0.00	1.00	EA	0.00	\$55.00	\$0
		0001	0420	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	29,793.00	0.00	29,793.00	SQYD	0.00	\$2.13	\$0.

Page 6 of 10 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220415-C02	J4S3343	0001	0430	8051000A	SEEDING - COOL SEASON GRASSES	1.80	0.00	1.80	ACRE	0.00	\$2,800.00	\$0.00
		0001	0440	8061006	ALTERNATE DITCH CHECK	244.00	0.00	244.00	LF	60.00	\$17.50	\$1,050.00
		0001	0450	8061007A	CURB INLET CHECK	25.00	0.00	25.00	EA	0.00	\$125.00	\$0.00
		0001	0460	8061016	SEDIMENT REMOVAL	69.00	0.00	69.00	CUYD	0.00	\$40.00	\$0.00
		0001	0470	8061017	TEMPORARY SEEDING	0.40	0.00	0.40	ACRE	0.00	\$2,000.00	\$0.00
		0001	0480	8061019	SILT FENCE	4,107.00	0.00	4,107.00	LF	0.00	\$3.00	\$0.00
Project J4S3343 - Total Value Posted to Date as of Report Generated Date												\$166,402.97
220415-C02 Ove	220415-C02 Overall - Total Value Posted to Date as of Report Generated Date											\$166,402.97

Revision 4/1/2020 Page 7 of 10



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

## The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4S3343

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2019919	MISC. MOWING	8/31/22	9/1/22	0.20	ACRE	SB lane by 43rd st	5.388		5.485		
0020	2022010	REMOVAL OF IMPROVEMENTS	8/25/22	9/2/22	0.05	LS	north end of project	5.325		5.373		
0030	2079909	MISC. GRADING	8/25/22	9/2/22	2.00	STA	grading around 43st to I-35	5.330		5.376		
0130	6085008	PAVED APPROACH, 8 IN.	8/25/22	9/2/22	46.00	SQYD	South side of paved approach paved	5.356				
			8/26/22	9/1/22	46.00	SQYD		5.356				second half of paved approach
0140	6086004	CONCRETE SIDEWALK, 4 IN.	8/26/22	9/1/22	114.70	SQYD		5.330		5.373		
0150	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	8/29/22	9/1/22	30.00	LF	in front of Missouri auto check station	5.369				
0160	6099903	MISC. PAVED DRAINAGE	8/25/22	9/2/22	104.00	LF	Curb from 43st to paved approach	5.370		5.376		24.5 LF additional curb added on sides of paved approa
0180	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	8/30/22	9/1/22	78.88	SQYD	log miles 5.830 5.834 5.854 5.854 5.859 5.864 5.950 5.972 5.984 6.060 6.060	5.872	6.06			1 8*10 ft patch 1 11*10 ft pstch 1 10*10 ft patch the rest are 6*10
			8/31/22	9/1/22	84.38	SQYD	5.831 5.834 5.854 5.950 5.971 5.972 5.994 6.060	5.827		6.060		1 8*10ft, 2 10*10 ft, 7 6*10ft
0210	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	8/30/22	9/1/22	362.00	LF	5.830 5.834 5.854 5.859 5.890 5.990 5.972 5.994 6.060	5.827		6.060		
			8/31/22	9/1/22	380.00	LF	5.831 5.854 5.854 5.950 5.971 5.972 5.994 6.060	5.827		6.06		
0220	6131015	DOWEL BAR (DRILLING, FURNISHING AND INST	8/30/22	9/1/22	182.00	EA	5.830 5.834 5.856 5.859 5.864 5.950 5.972 5.994 6.060	5.827		6.06		
			8/31/22	9/1/22	161.00	EA	5.831 5.854 5.854 5.950 5.971 5.972 5.994 6.060	5.827		6.060		
0250	6161099	CMS WITH COMMUNICATION INTERFACE, CONT F	8/15/22	8/24/22	2.00	EA		5.325		7.246		
0070	6460001	MICC	0/04/00	0/4/00	0.50	10	1-35	E 205		7.040		500/ toff
	6169901		8/31/22		0.50	LS	4 4 4 4 5 000 0 4 5 070 C 3 ND 5D	5.325		7.246		50% traffic control payed at 5% job total price
		MISC. TRAFFIC CONTROL DEVICES	8/24/22		4.00		4 placed 1 at 5.330 3 at 5.376 facing NB EB WB	5.330		5.376		
0290	ь169902	MISC. TRAFFIC CONTROL DEVICES	8/26/22	9/1/22	3.00	EA	curb ramps north and south of paved approach and at 43rd st	5.364		3.376		
0300	6181000	MOBILIZATION	8/31/22	9/1/22	0.25	LS		5.325		7.246		25% mobilization payed at 5% job total price
0440	0004000	ALTERNATE DITCH CHECK	8/29/22	9/1/22	60.00	LF		5.372		5.353		3 20LF alternate ditch checks 20 at the curb at 5.372 1

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 8 of 10



## Line Item Adjustments by Estimate

Contract ID:190215-D05

Type Adjustment Type Date By										
APPROACH & No.	oject	Line	Description		Adjustment				Amount	Remarks
Total   Sep 2   SYSTEM   (88,856.60)	3343	0130		Material		1	Sep 2, 2022	SYSTEM	\$8,836.60	Estimate Item Adjustment (0003) due to user baiamf1 overridding Payment
Material - Total   Sep 2   SYSTEM   (\$6.08)   Reference Rem Price Adjustment Index Adjustment Type applied is FUEL						1		SYSTEM	(\$8,836.60)	
Price   Price   1   Sep 2   SYSTEM   18.08)   Reference team Price Adjustment Index Adjustment Type applied is FUEL   Total   18.08)					- Total				\$0.00	
Price   Price   1   Sep 2   SYSTEM   18.08)   Reference team Price Adjustment Index Adjustment Type applied is FUEL   Total   18.08)				Material - To	otal				\$0.00	
100   Total				Price		1		SYSTEM		Reference Item Price Adjustment Index Adjustment Type applied is FUEL
10130					- Total				(\$6.08)	
CONCRETE   Material   Food   SiDEYMAIX, 4 INL   Material   Food   SiDEYMAIX, 4 INL   Si				Price FUEL	- Total				(\$6.08)	
SIDEWALK 4 IN.     2022       Estimate Item Agistment (0004) due to user balantf overridding Payment Estimate Exception 4 on the current Payment Estimate.     1 Sep 2, 2022     1 Sep 2, 2022     2022     2022     2022     2022     2022     2022     2022     2022     2022     2022     2022   2022     2022		0130 -	Total						(\$6.08)	
Total   So.00		0140		Material		1		SYSTEM	\$7,759.46	Estimate Item Adjustment (0004) due to user baiamf1 overridding Payment
						1		SYSTEM	(\$7,759.46)	
1					- Total				\$0.00	
CONDECTE   Miderial   Payment   Sep 2, 2022   SYSTEM   \$1,084.50   This adjustment offsets the original system-generated Material Payment   Estimate   Exception S on the current Payment   Estimate   Exception S on the cu				Material - To	otal				\$0.00	
CURR (a Nate in HeiGHT AND UNDER)		0140 -	Total						\$0.00	
1   Sep 2, 2022   SYSTEM (\$1,684.50)		0150	CURB (6 IN. HEIGHT AND	Material		1		SYSTEM	\$1,084.50	Estimate Item Adjustment (0006) due to user baiamf1 overridding Payment
Material - Total			UNDER)			1		SYSTEM	(\$1,084.50)	
Overrun					- Total				\$0.00	
1   Sep 2, SYSTEM   S48,014.77				Material - To	otal				\$0.00	
Overrun - Total   (\$72.30)				Overrun	Overrun	1		SYSTEM	(\$72.30)	
1   Sep 2   SySTEM   (\$1,427.40)					Overrun - Total				(\$72.30)	
Oten				Overrun - T	otal				(\$72.30)	
DRAINAGE		0150 -	Total						(\$72.30)	
1		0160		Overrun				SYSTEM		
1   Sep 2, 2022   SYSTEM   \$48,014.77   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user baiamf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.										
Total   Sep 2, 2022   SYSTEM   \$48,014.77   This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate.    Total				Overrun - T	otal					
CONC MATL FOR FULL DEPTH    2022   SYSTEM   (\$48,014.77)										
CMS WITH COMMUNICATION INTERFACE, CONT F   Communication   Communica		0180	CONC MATL FOR	Material		1		SYSTEM	\$48,014.77	Estimate Item Adjustment (0008) due to user baiamf1 overridding Payment
DOWEL BAR (DRILLING, FURNISHING AND INST   Total   Sep 2, 2022   SYSTEM   \$2,589.65   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user baiamf1 overridding Payment Estimate Exception 8 on the current Payment Estimate.   1 Sep 2, 2022   SYSTEM (\$2,589.65)    -Total   \$0.00    -Total   \$0.00    -Total   \$0.00    Total   \$0.00								SYSTEM	(\$48,014.77)	
Sep 2, 2022   SYSTEM   S2,589.65   This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate.					- Total					
DOWEL BAR (DRILLING, FURNISHING AND INST    1				Material - To	otal					
(DRILLING, FURNISHING AND INST		0180 -	Total						\$0.00	
Total  Sep 2, 2022  SYSTEM (\$2,589.65)  - Total  S0.00  Material - Total  S0.00  CMS WITH COMMUNICATION INTERFACE, CONT F  Sep 2, 2022  SYSTEM \$9,400.00  SYSTEM \$9,400.00  System-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  System \$9,400.00  Sys		0220	(DRILLING, FURNISHING AND	Material		1		SYSTEM	\$2,589.65	Estimate Item Adjustment (0009) due to user baiamf1 overridding Payment
Material - Total   \$0.00			INST			1			(\$2,589.65)	
CMS WITH COMMUNICATION INTERFACE, CONT F   Sep 2, 2022   SYSTEM   S9,400.00   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 9 on the current Payment Estimate.					- Total				\$0.00	
O250 CMS WITH COMMUNICATION INTERFACE, CONT F 1 Sep 2, 2022 SYSTEM \$9,400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  1 Sep 2, 2022 SYSTEM \$9,400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 9 on the current Payment Estimate.				Material - To	otal				\$0.00	
COMMUNICATION INTERFACE, CONT F  2022  Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  1 Sep 2, 2022  SYSTEM (\$9,400.00)		0220 -	Total						\$0.00	
1 Sep 2, 2022 (\$9,400.00)		0250	COMMUNICATION INTERFACE,	Material		1	Sep 2, 2022	SYSTEM	\$9,400.00	Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment
- Total \$0.00						1	Sep 2, 2022	SYSTEM	(\$9,400.00)	
					- Total				\$0.00	

Sep 7, 2022



## Line Item Adjustments by Estimate

## Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3343		CMS WITH COMMUNICATION INTERFACE, CONT F	Material - To	otal				\$0.00	
	0250 -	Total						\$0.00	
J4S3343 - Total								(\$1,505.78)	
Overall - Total								(\$1,505.78)	