

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 16, 2023

Progress Estimate Number	Contract ID	220415-F01	Pay Period Start	October 1, 2023	Original Contract Amount	\$8,459,000.00
30	Prime Contractor	KCI Construction Company	Pay Period End	-, -, -	Net Change Order Amount Current Contract Amount	, ,

Approval Date		By User
October 16, 2023	Generated and Approved (and should be considered Draft) at the Project Office Level by	corrij1
October 16, 2023	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	amburs1
October 17, 2023	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
June 15, 2024	June 15, 2024		84.20%

	Contract Informational Date	tes	Milestones				
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract				
Acceptance Date							
Awarded Date	May 4, 2022	May 4, 2022					
Letting Date	April 15, 2022	April 15, 2022					
Notice to Proceed Date	July 5, 2022	July 5, 2022					
Open to Traffic Date							
Work Began Date	August 8, 2022	August 8, 2022					

Contract Total Pay For Estimate No. 30										
		This Estimate	Previous	To Date						
220415-F01										
	Total Posted Items Pay	\$89,392.00	\$7,509,029.33	\$7,598,421.33						
	Gross Item Adjustments	\$43,900.00	(\$43,050.00)	\$850.00						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
	•		\$7,465,979.33	\$7,599,271.33						
Contract Total Pa	ayable This Estimate:	\$133,292.00								

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3489	0350	8061016	SEDIMENT REMOVAL	CUYD	\$91.000	15	\$1,365.00
	0440	7040101	SUBSTRUCTURE REPAIR (FORMED)	SQFT	\$275.000	10	\$2,750.00
	0450	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	SQFT	\$175.000	10	\$1,750.00
	0680	2169902	MISC.REMOVAL OF EXISTING BEARINGS	EA	\$3,800.000	3	\$11,400.00
	0730	7040101	SUBSTRUCTURE REPAIR (FORMED)	SQFT	\$255.000	45	\$11,475.00
	0870	7129902	MISC.CONDUIT CONNECTION REPAIR	EA	\$5,440.000	1	\$5,440.00
	0910	7129902	MISC.SLAB DRAIN BRACKET REPAIR	EA	\$1,150.000	13	\$14,950.00
	0920	7129902	MISC.SLAB DRAIN EXTENSION	EA	\$710.000	28	\$19,880.00
	0950	7163000	TYPE N PTFE BEARING	EA	\$3,500.000	3	\$10,500.00
	5015	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	CY	\$900.000	10.98	\$9,882.00
Project J6I348	9 - Total						\$89,392.00
Overall - Total							\$89,392.00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ourionto Exiot oir Contidot						
Line Item	Adjust	tments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3489	0060	MISC.	Material			-1,173.38	\$85.00	(\$99,737.30)
	0060	MISC.	Material		This adjustment offsets the original system-	1,173.38	\$85.00	\$99,737.30

Revision 3/23/2023 Page 1 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 16, 2023

Progress Estimate Number 30 Contract ID 220415-F01 Pay Period Start October 1, 2023 Original Contract Amount \$8,459,000.00 Pay Period End October 15, 2023 Net Change Order Amount \$565,726.85 Current Contract Amount \$9,024,726.85

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3489					generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
	0600	MISC.	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3000.00000 - 3000.00000, 'is applied (if non-zero).	2	\$3,000.00	\$6,000.00
	0720	MISC.	Material			-30.6	\$14,650.00	(\$448,290.00
	0720	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	30.6	\$14,650.00	\$448,290.00
	0760	HALF-SOLE REPAIR	Other Item Adjustment	PCCP QC/QA Adjustment	CRE 20 Report for the Concrete Pour on 08/14/2023 has been completed.			\$30,233.50
	0770	FULL DEPTH REPAIR	Other Item Adjustment	PCCP QC/QA Adjustment	CRE 20 Report for the Concrete Pour on 08/14/2023 has been completed.			\$7,666.50
	0960	STRIP SEAL EXPANSION JOINT SYSTEM	Material			-137	\$700.00	(\$95,900.00
(0960	STRIP SEAL EXPANSION JOINT SYSTEM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user corrij1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	137	\$700.00	\$95,900.00
Total								\$43,900.00

Revision 3/23/2023 Page 2 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information									
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work					
J6I3489 I 2 Bridge rehabilitations I -44 ST LOUIS over the Meramec River just west of Lewis Road										
Totals by	otals by Job Numbers									

2	14-4(205) rehabilitations LO	UIS		
Totals by Jo	b Numbers			
J6I3489		This Estimate	Previous	To Date
	Posted Item Pay	\$89,392.00	\$7,509,029.33	\$7,598,421.33
	Gross Item Adjustments	\$43,900.00	(\$43,050.00)	\$850.00
	Gross Item F	Pay \$133,292.00	\$7,465,129.33	\$7,598,421.33
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00

Revision 3/23/2023 Page 3 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6l3489, Item 4019905, Project Item Line Number 0060, Material Set 401990596, Material 1036RSDFEC42M16 - Rein Steel EC No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	This line item is currently being adjusted to reflect actual construction, this discrepancy will be fixed on the next estimate.	corrij1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3489, Item 7039907, Project Item Line Number 0720, Material Set 703990796, Material 1036RSMBS - Mechanical Bar Splice for Reinf Steel @, Acceptance Action Generic ReinforcingMisc is insufficient.	This line item is currently being adjusted to reflect actual construction, this discrepancy will be fixed on the next estimate.	corrij1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3489, Item 7039907, Project Item Line Number 0720, Material Set 703990796, Material 4501CCUHPC - Concrete, Ultra High Performance Concrete JSP, Acceptance Action Generic 4501CCUHPC is insufficient.	QA Samples are currently being adjusted, this discrepancy will be fixed on the next estimate.	corrij1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3489, Item 7172001, Project Item Line Number 0960, Material Set 717200196, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	This line item is currently being adjusted to reflect actual construction, this discrepancy will be fixed on the next estimate.	corrij1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3489, Item 7172001, Project Item Line Number 0960, Material Set 717200196, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	This line item is currently being adjusted to reflect actual construction, this discrepancy will be fixed on the next estimate.	corrij1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3489, Item 7172001, Project Item Line Number 0960, Material Set 717200196, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	This line item is currently being adjusted to reflect actual construction, this discrepancy will be fixed on the next estimate.	corrij1	Overridden

Revision 3/23/2023 Page 4 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

	uantities				Report Generated date and can differ from the posted am			Estimate wa				
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220415-F01	J6I3489	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	1.00	\$0.01	\$0.01
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$3,600.00	\$0.00
		0001	0030	2031000	CLASS A EXCAVATION	5,619.00	0.00	5,619.00	CUYD	132.20	\$40.00	\$5,288.00
		0001	0040	2036000	COMPACTING EMBANKMENT	842.00	0.00	842.00	CUYD	0.00	\$60.00	\$0.00
		0001	0050	2037075	COMPACTING IN CUT	30.00	-30.00	0.00	STA	0.00	\$1,500.00	\$0.00
		0001	0060	4019905	MISC.OPTIONAL PAVEMENT	2,435.00	-1,261.62	1,173.38	SQYD	1,173.38	\$85.00	\$99,737.30
		0001	0070	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	900.00	0.00	900.00	CUYD	0.00	\$52.00	\$0.00
		0001	0800	6096042	PLACING TYPE 2 ROCK DITCH LINER	900.00	0.00	900.00	CUYD	0.00	\$50.00	\$0.00
		0001	0090	6113020	FURNISHING TYPE 2 ROCK BLANKET	206.00	0.00	206.00	CUYD	0.00	\$39.00	\$0.00
		0001	0100	6113040	PLACING TYPE 2 ROCK BLANKET	206.00	0.00	206.00	CUYD	0.00	\$47.00	\$0.00
		0001	0110	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	2.00	\$3,911.00	\$7,822.00
		0001	0120	6122020	REPLACEMENT SAND BARREL	2.00	40.00	42.00	EA	35.00	\$472.00	\$16,520.00
		0001	0130	6122030	IMPACT ATTENUATOR (RELOCATION)	34.00	0.00	34.00	EA	34.00	\$146.00	\$4,964.00
		0001	0140	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$28,000.00	\$56,000.00
		0001	0150	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	24.00	0.00	24.00	EA	6.00	\$1,000.00	\$6,000.00
		0001	0160	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	-1.00	0.00	LS	0.00	\$77,597.12	\$0.00
		0001	0170	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN	2.00	2.00	4.00	EA	4.00	\$3,200.00	\$12,800.00
		0001	0185	6173700B	CONTRACTOR FURNISHED AND RETAINED TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR	3,543.00	-2,943.00	600.00	LF	600.00	\$29.98	\$17,988.00
					FURNISHED / RETAINED							
		0001	0195	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	3,541.00	-1,700.00	1,841.00	LF	200.00	\$13.32	\$2,664.00
		0001	0200	6181000	MOBILIZATION	1.00	0.00	1.00	LS		\$426,582.41	\$426,582.41
		0001	0210	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	48,958.00	-3,300.00	45,658.00	LF	7,728.00	\$1.20	\$9,273.60
		0001	0220	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	15,419.00	-800.00	14,619.00	LF	3,877.00	\$1.20	\$4,652.40
		0001	0230	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	8,034.00	2,196.00	10,230.00	LF	5,115.00	\$0.50	\$2,557.50
		0001	0240	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	5,635.00	765.00	6,400.00	LF	3,184.00	\$0.50	\$1,592.00
		0001	0250	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	270.00	830.00	1,100.00	LF	523.00	\$5.00	\$2,615.00
		0001	0260	6207001	PAVEMENT MARKING REMOVAL	78,316.00	0.00	78,316.00	LF	17,588.00	\$0.50	\$8,794.00
		0001	0270	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	2,522.00	0.00	2,522.00	SQYD	0.00	\$2.15	\$0.00
		0001	0280	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.80	\$15,000.00	\$12,000.00
		0001	0290	7209905	MISC.4-INCH MINUS GRANULAR FILL	30.00	0.00	30.00	SQYD	0.00	\$53.00	\$0.00
		0001	0300	8061003	SEDIMENT TRAP EXCAVATION	167.00	0.00	167.00	CUYD	0.00	\$19.00	\$0.00
		0001	0310	8061004	SEDIMENT TRAP ROCK	167.00	0.00	167.00	CUYD	0.00	\$91.00	\$0.00
		0001	0320	8061005	ROCK DITCH CHECK	16.00	0.00	16.00	LF	16.00	\$110.00	\$1,760.00
		0001	0330	8061010A	TYPE B BERM	126.00	0.00	126.00	LF	0.00	\$13.00	\$0.00
		0001	0340	8061011	SLOPE DRAINS	22.00	0.00	22.00	LF	0.00	\$212.00	\$0.00
		0001	0350	8061016	SEDIMENT REMOVAL	18.00	0.00	18.00	CUYD	15.00	\$91.00	\$1,365.00
		0001	0360	8061019	SILT FENCE	631.00	0.00	631.00	LF	631.00	\$8.00	\$5,048.00
		0001	0370	8061050	TYPE C BERM	127.00	0.00	127.00	LF	60.00	\$99.00	\$5,940.00
		0010	0380	6061060	MGS GUARDRAIL	288.00	0.00	288.00	LF	0.00	\$32.00	\$0.00
		0010	0390	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	0.00	\$1,800.00	\$0.00
		0010	0400	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$3,800.00	\$0.00
		0070	0410	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	1,308.00	0.00	1,308.00	LF	1,308.00	\$43.00	\$56,244.00
		0070	0420	2169902	MISC.REMOVAL OF EXISTING BEARINGS	40.00	0.00	40.00	EA	40.00	\$4,000.00	\$160,000.00
		0070	0430	2169903	MISC.REMOVE AND REINSTALL COUNDUIT	1,308.00	0.00	1,308.00	LF	1,308.00	\$32.00	\$41,856.00
		0070	0440	7040101	SUBSTRUCTURE REPAIR (FORMED)	70.00	127.00	197.00	SQFT	197.00	\$275.00	\$54,175.00
		0070	0450	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	305.00	34.00	339.00	SQFT	314.00	\$175.00	\$54,950.00

Page 5 of 19 Revision 3/23/2023



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted C	luantities	and vail	ies are	based on r	Report Generated date and can differ from the posted al	nount at the	e unie uie i	Estimate wa	s Gener	alcu.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220415-F01	J6I3489	0070	0460	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	1,043.00	0.00	1,043.00	SQFT	854.00	\$150.00	\$128,100.00
		0070	0470	7040104	HALF-SOLE REPAIR	1,000.00	0.00	1,000.00	SQFT	731.00	\$112.00	\$81,872.00
		0070	0480	7040106	FULL DEPTH REPAIR	600.00	-400.00	200.00	SQFT	51.00	\$170.00	\$8,670.00
		0070	0490	7040107	SLAB EDGE REPAIR (BRIDGES)	300.00	389.00	689.00	LF	689.00	\$215.00	\$148,135.00
		0070	0500	7040163	CONCRETE CRACK FILLER	5,722.00	0.00	5,722.00	SQYD	5,722.00	\$30.00	\$171,660.00
		0070	0510	7049903	MISC.BARRIER CURB REPAIR	50.00	0.00	50.00	LF	20.00	\$440.00	\$8,800.00
		0070	0520	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	1.00	\$48,000.00	\$48,000.00
		0070	0530	7121100	(EPOXY) FABRICATED STRUCTURAL LOW ALLOY STEEL (MISC)	500.00	0.00	500.00	LB	0.00	\$90.00	\$0.00
		0070	0540	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL	24,300.00	0.00	24,300.00	SQFT	24,300.00	\$25.00	\$607,500.00
		0070	0550	7125210	STEEL FIELD APPLICATION OF INORGANIC ZINC PRIMER	24,300.00	0.00	24,300.00	SQFT	24,300.00	\$2.00	\$48,600.00
		0070	0560	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	24,300.00	0.00	24,300.00	SQFT	24,300.00	\$2.00	\$48,600.00
		0070	0570	7125370A	FINISH FIELD COAT (SYSTEM G)	24,300.00	0.00	24,300.00	SQFT	24,300.00	\$2.00	\$48,600.00
		0070	0580	7129902	MISC.CORED SLAB DRAINS	20.00	0.00	20.00	EA	20.00	\$1,675.00	\$33,500.00
		0070	0590	7129902	MISC.EXPANSION DEVICE DRAINAGE TROUGH SYSTEM	1.00	0.00	1.00	EA	0.00	\$87,000.00	\$0.00
		0070	0600	7129902	MISC.FATIGUE CRACK REPAIR	25.00	2.00	27.00	EA	27.00	\$3,000.00	\$81,000.00
		0070	0610	7129902	MISC.SLAB DRAIN EXTENSION	431.00	0.00	431.00	EA	431.00	\$700.00	\$301,700.00
		0070	0620	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	20.00	0.00	20.00	EA	19.00	\$4,400.00	\$83,600.00
		0070	0630	7163000	TYPE N PTFE BEARING	20.00	0.00	20.00	EA	20.00	\$4,500.00	\$90,000.00
		0070	0640	7173002	SILICONE EXPANSION JOINT SEALANT	1,308.00	0.00	1,308.00	LF	1,308.00	\$16.00	\$20,928.00
		0071	0650	2161000	SCARIFICATION OF BRIDGE DECK	9,582.00	0.00	9,582.00	SQYD	9,582.00	\$6.00	\$57,492.00
		0071	0660	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	0.00	100.00	SQFT	70.00	\$85.00	\$5,950.00
		0071	0670	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	206.00	0.00	206.00	LF	206.00	\$570.00	\$117,420.00
		0071	0680	2169902	CONCRETE MISC.REMOVAL OF EXISTING BEARINGS	64.00	0.00	64.00	EA	56.00	\$3,800.00	\$212,800.00
		0071	0690	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	28.00	0.00	28.00	LF	28.00	\$3,300.00	\$92,400.00
		0071	0700	5057000	POLYESTER POLYMER CONCRETE WEARING SURFACE	9,515.00	0.00	9,515.00	SQYD	9,515.00	\$131.00	\$1,246,465.00
		0071	0710	7034001	CLASS B-1 CONCRETE	2.00	0.00	2.00	CUYD	2.00	\$6,550.00	\$13,100.00
		0071	0720	7039907	MISC.ULTRA HIGH PERFORMANCE CONCRETE (JT.	30.60	0.00	30.60	CUYD	30.60	\$14,650.00	\$448,290.00
		0071	0730	7040101	REPLACEMENT) SUBSTRUCTURE REPAIR (FORMED)	235.00	300.00	535.00	SQFT	340.00	\$255.00	\$86,700.00
		0071	0740	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	1,570.00	900.00	2,470.00	SQFT	2,377.93	\$175.00	\$416,137.75
		0071	0750	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	195.00	80.00	275.00	SQFT	245.48	\$170.00	\$41,731.60
		0071	0760	7040104	HALF-SOLE REPAIR	1,830.00	0.00	1,830.00	SQFT	790.00	\$119.50	\$94,405.00
		0071	0770	7040106	FULL DEPTH REPAIR	200.00	0.00	200.00	SQFT	66.00	\$201.75	\$13,315.50
		0071	0780	7040110	EPOXY PRESSURE INJECTING	350.00	0.00	350.00	LF	0.00	\$49.00	\$0.00
		0071	0790	7049903	MISC.MEDIAN CURB REPAIR	300.00	0.00	300.00	LF	300.00	\$282.00	\$84,600.00
		0071	0800	7101000	REINFORCING STEEL (EPOXY COATED)	2,220.00	0.00	2,220.00	LB	2,220.00	\$7.00	\$15,540.00
		0071	0810	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.80	\$72,000.00	\$57,600.00
		0071	0820	7121100	(EPOXY) FABRICATED STRUCTURAL LOW ALLOY STEEL (MISC)	3,500.00	0.00	3,500.00	LB	3,500.00	\$29.00	\$101,500.00
		0071	0830	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL	6,900.00	0.00	6,900.00	SQFT	4,000.00	\$25.00	\$100,000.00
					STEEL							
		0071	0840	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	6,900.00	0.00	6,900.00	SQFT	4,000.00	\$2.00	\$8,000.00
		0071	0850	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	6,900.00	0.00	6,900.00	SQFT	3,000,00	\$2.00	\$8,000.00 \$6,000.00
		0071	0860	7125370A		6,900.00	0.00	6,900.00		3,000.00	\$2.00	
		0071	0870	7129902 7129902	MISC.CONDUIT CONNECTION REPAIR MISC.CORED SLAB DRAINS	3.00	0.00	1.00	EA EA	1.00	\$5,440.00 \$2,250.00	\$5,440.00 \$27,000.00
		0071	0890	7129902	MISC.DRIP BAR	16.00	0.00	16.00	EA	16.00	\$1,250.00	\$20,000.00
		0071	0900	7129902	MISC.FATIGUE CRACK REPAIR	17.00	0.00	17.00	EA	0.00	\$3,000.00	\$20,000.00
		0071	0300	1 123802	MIGG. ATIGGE GRACINETAIN	17.00	0.00	17.00	EA	0.00	φυ,υυυ.υυ	φυ.00

Page 6 of 19 Revision 3/23/2023



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
20415-F01	J6I3489	0071	0910	7129902	MISC.SLAB DRAIN BRACKET REPAIR	25.00	0.00	25.00	EA	25.00	\$1,150.00	\$28,750.00
	0071 0920 7129902 MISC.SLAB DRAIN EXTENSION 0071 0930 7129903 MISC.EXPANSION DEVICE (FINGER PLATE) WITH DRAI		MISC.SLAB DRAIN EXTENSION	318.00	0.00	318.00	EA	318.00	\$710.00	\$225,780.00		
		0071	0930	7129903	MISC.EXPANSION DEVICE (FINGER PLATE) WITH DRAINAGE TROUGH SYSTEM	69.00	-69.00	0.00	LF	0.00	\$5,700.00	\$0.00
		0071	0940	7161002	LAMINATED NEOPRENE BEARING PAD	32.00	0.00	32.00	EA	32.00	\$1,535.00	\$49,120.00
		0071	0950	7163000	TYPE N PTFE BEARING	32.00	0.00	32.00	EA	24.00	\$3,500.00	\$84,000.00
		0071	0960	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	137.00	0.00	137.00	LF	137.00	\$700.00	\$95,900.00
		0001	5001	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	0.00	4,850.00	4,850.00	LF	4,850.00	\$25.95	\$125,857.50
		0001	5002	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	0.00	3,600.00	3,600.00	LF	2,800.00	\$9.30	\$26,040.00
		0001	5003	6169901	MISC.Temporary Traffic Control	0.00	1.00	1.00	LS	0.95	\$92,042.12	\$87,440.01
		0001	5004	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	0.00	18,232.00	18,232.00	LF	17,687.00	\$0.50	\$8,843.50
		0001	5005	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	0.00	6,552.00	6,552.00	LF	4,957.00	\$0.50	\$2,478.50
		0001	5006	7049904	MISC.Shallow Depth Repair	0.00	170.00	170.00	SQFT	143.00	\$73.22	\$10,470.46
		0071	5007	7129903	MISC.REVISED EXPANSION DEVICE (FINGER PLATE) WITH DRAINAGE TROUGH SYSTEM	0.00	69.00	69.00	LF	54.00	\$6,348.00	\$342,792.00
		0071	5008	7129902	MISC.DRAIN BRACKET MODIFICATIONS	0.00	55.00	55.00	EA	55.00	\$246.00	\$13,530.00
		0001	5009	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	0.00	1,162.27	1,162.27	SQYD	1,162.27	\$9.65	\$11,215.91
		0071	5010	1094000A	FORCE ACCOUNT	0.00	2,615.31	2,615.31	EA	2,615.31	\$1.00	\$2,615.31
		0001	5011	6189901	MISC.Misc. Mobilization for Acceleration	0.00	1.00	1.00	LS	1.00	\$50,000.00	\$50,000.00
		0071	5012	1094000A	FORCE ACCOUNT	0.00	6,655.12	6,655.12	EA	6,655.12	\$1.00	\$6,655.12
		0001	5013	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$4,725.00	\$4,725.00
		0001	5014	6139911	MISC.Misc. Removal, Furnishing and Placing Hot Polymer Concrete Patching for Class A Partial Depth Pavement Repair	0.00	27,735.00	27,735.00	LB	27,735.00	\$3.57	\$99,013.95
		0071	5015	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	0.00	41.00	41.00	CY	40.96	\$900.00	\$36,864.00
	Project .	1613489 - To	tal Value	Posted to D	ate as of Report Generated Date							\$7,630,431.3
0415-F01 Ove	rall - Tota	Value Pos	ted to Da	te as of Rep	ort Generated Date							\$7,630,431.33

Page 7 of 19 Revision 3/23/2023



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6I3489

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0350	8061016	SEDIMENT REMOVAL	10/10/23	10/12/23	15.00	CUYD	All Sediment Removal across the J6l3489 job through 10/10/2023.	440+33.46		452+41.3		
0440	7040101	SUBSTRUCTURE REPAIR (FORMED)	10/6/23	10/9/23	10.00	SQFT	Bent 1 on Bridge A1796, Substructure Repair.	440+35		440+35		
0450	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	10/6/23	10/9/23	10.00	SQFT	Bent 1 on Bridge A1796, Substructure Repair.	440+35		440+35		
0680	2169902	MISC. REMOVALS	10/10/23	10/12/23	1.00	EA	Bent 12 Girder 8 Bearing Removal.	447+00		447+00		Payment is for Stopper Plates Installation.
				10/12/23	2.00	EA	Bent 3 Girders 1 and 2 Bearing Removals on West Side.	441+00		441+00		
0730	7040101	SUBSTRUCTURE REPAIR (FORMED)	10/6/23	10/9/23	45.00	SQFT	Bent 16 Substructure Repair on Bridge L0611 near Girder 8.	452+00		452+00		
0870	7129902	MISC.	10/10/23	10/12/23	1.00	EA	Conduit by Finger at Bent 12 on Bridge L0611.	447+00		447+00		
0910	7129902	MISC.	10/4/23	10/5/23	13.00	EA	Bracket Repairs took place on spans 12 and 13 over the Meramec River on Bridge L0611.	447+00		451+00		
0920	7129902	MISC.	10/12/23	10/16/23	28.00	EA	Drain Extensions installed from bent 12 to bent 16 by girder 8.	447+00		452+00		
0950	7163000	TYPE N PTFE BEARING	10/10/23	10/12/23	3.00	EA	Bent 12 Girders 6, 7 and 8 Bearings at Bridge L0611.	447+00		447+00		Payment is for Stopper Plates Installation.
5015	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	10/12/23	10/16/23	10.98	CY	PPC Overage Located in Stage 3 Construction for Lane 3.	440+33.46		453+41.3		Change Order 016 was approved on 10/12/2023, therefore payment for this item is also on 10/12/2023

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023 Page 8 of 19



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3489	0060	MISC.	Material		16	Mar 16, 2023	SYSTEM	(\$29,742.35)	
					17	Apr 3, 2023	SYSTEM	\$99,737.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					17	Apr 3, 2023	SYSTEM	(\$99,737.30)	
					18	Apr 17, 2023	SYSTEM	\$99,737.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					18	Apr 17, 2023	SYSTEM	(\$99,737.30)	
					19	May 2, 2023	SYSTEM	\$99,737.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user corrij1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					19	May 2, 2023	SYSTEM	(\$99,737.30)	
					20	May 16, 2023	SYSTEM	\$99,737.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					20	May 16, 2023	SYSTEM	(\$99,737.30)	
					21	Jun 2, 2023	SYSTEM	\$99,737.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user corrij1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					21	Jun 2, 2023	SYSTEM	(\$99,737.30)	
					22	Jun 19, 2023	SYSTEM	\$99,737.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					22	Jun 16, 2023	SYSTEM	(\$99,737.30)	
					23	Jun 30, 2023	SYSTEM	\$99,737.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					23	Jun 30, 2023	SYSTEM	(\$99,737.30)	
					24	Jul 17, 2023	SYSTEM	\$99,737.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					24	Jul 17, 2023	SYSTEM	(\$99,737.30)	
					25	Aug 2, 2023	SYSTEM	\$99,737.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					25	Aug 2, 2023	SYSTEM	(\$99,737.30)	
					30	Oct 16, 2023	SYSTEM	\$99,737.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					30	Oct 16, 2023	SYSTEM	(\$99,737.30)	
			Market Take	- Total				(\$29,742.35)	
			Material - Total		17	Apr 3,	SYSTEM	(\$29,742.35) \$29,742.35	
			a.c.iaioioait	- Total		2023	S. STEW	\$29,742.35	
			MaterialCredit					\$29,742.35	
	0060 -	Total	materialorealt	Total				\$0.00	
	0120	REPLACEMENT SAND BARREL	Overrun	Overrun	19	May 2, 2023	SYSTEM	(\$1,888.00)	
					22	Jun 16, 2023	SYSTEM	(\$4,720.00)	
					23	Jun 30, 2023	SYSTEM	\$6,608.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',472.00000 - 472.00000, 'is applied (if non-zero).
					27	Sep 5,	SYSTEM	(\$1,416.00)	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
189	0120	REPLACEMENT	Overrun	Overrun		2023			
		SAND BARREL			29	Oct 2, 2023	SYSTEM	\$1,416.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',472.00000 - 472.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0120 -	Total						\$0.00	
	0210	TEMPORARY REMOVABLE MARKING TAPE 4	Material		2	Aug 16, 2022	SYSTEM	(\$2,127.60)	
		IN.,			3	Sep 2, 2022	SYSTEM	(\$2,127.60)	
					4	Sep 16, 2022	SYSTEM	\$2,127.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Sep 16, 2022	SYSTEM	(\$2,127.60)	
					5	Oct 3, 2022	SYSTEM	(\$2,127.60)	
					18	Apr 17, 2023	SYSTEM	\$6,136.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user corrij1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					18	Apr 17, 2023	SYSTEM	(\$6,136.80)	
				- Total				(\$6,382.80)	
			Material - Tota	I				(\$6,382.80)	
			MaterialCredit		3	Sep 2, 2022	SYSTEM	\$2,127.60	
					4	Sep 16, 2022	SYSTEM	\$2,127.60	
				Total	6	Oct 17, 2022	SYSTEM	\$2,127.60	
				- Total				\$6,382.80	
			24 / 1 10 11/					00.000.00	
	0240	Total	MaterialCredit	- Total				\$6,382.80	
	0210 -			- Total	40	Apr. 47	CVCTEM	\$0.00	This adjustment of at the ariginal party as a control Material Dayment
	0210 - 0220	Total TEMPORARY REMOVABLE MARKING TAPE	MaterialCredit Material	- Total	18	Apr 17, 2023	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user corrij1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
		TEMPORARY REMOVABLE		- Total	18		SYSTEM	\$0.00	Estimate Item Adjustment (0012) due to user corrij1 overridding Payment
		TEMPORARY REMOVABLE	Material	- Total		2023 Apr 17,		\$0.00 \$3,081.60 (\$3,081.60)	Estimate Item Adjustment (0012) due to user corrij1 overridding Payment
	0220	TEMPORARY REMOVABLE MARKING TAPE		- Total		2023 Apr 17,		\$0.00 \$3,081.60 (\$3,081.60) \$0.00	Estimate Item Adjustment (0012) due to user corrij1 overridding Payment
		TEMPORARY REMOVABLE MARKING TAPE	Material	- Total		2023 Apr 17,		\$0.00 \$3,081.60 (\$3,081.60)	Estimate Item Adjustment (0012) due to user corrij1 overridding Payment
	0220	TEMPORARY REMOVABLE MARKING TAPE	Material Material - Tota	- Total	18	2023 Apr 17, 2023 Aug 2, 2023	SYSTEM	\$0.00 \$3,081.60 (\$3,081.60) \$0.00 \$0.00 \$0.00 (\$1,265.00)	Estimate Item Adjustment (0012) due to user corrij1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
	0220	TEMPORARY REMOVABLE MARKING TAPE Total 12 IN. WHITE HIGH BUILD	Material Material - Tota	- Total	18	2023 Apr 17, 2023	SYSTEM	\$0.00 \$3,081.60 (\$3,081.60) \$0.00 \$0.00	Estimate Item Adjustment (0012) due to user corrij1 overridding Payment
	0220	TEMPORARY REMOVABLE MARKING TAPE Total 12 IN. WHITE HIGH BUILD WATERBORNE	Material Material - Tota	- Total	18 25 29	2023 Apr 17, 2023 Aug 2, 2023 Oct 2,	SYSTEM	\$0.00 \$3,081.60 (\$3,081.60) \$0.00 \$0.00 \$0.00 (\$1,265.00)	Estimate Item Adjustment (0012) due to user corrij1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is
	0220	TEMPORARY REMOVABLE MARKING TAPE Total 12 IN. WHITE HIGH BUILD WATERBORNE	Material Material - Tota	- Total I Overrun Overrun - T	18 25 29	2023 Apr 17, 2023 Aug 2, 2023 Oct 2,	SYSTEM	\$0.00 \$3,081.60 (\$3,081.60) \$0.00 \$0.00 (\$1,265.00) \$1,265.00	Estimate Item Adjustment (0012) due to user corrij1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is
	0220	TEMPORARY REMOVABLE MARKING TAPE Total 12 IN. WHITE HIGH BUILD WATERBORNE PAINT	Material - Tota Overrun	- Total I Overrun Overrun - T	18 25 29	2023 Apr 17, 2023 Aug 2, 2023 Oct 2,	SYSTEM	\$0.00 \$3,081.60 (\$3,081.60) \$0.00 \$0.00 (\$1,265.00) \$1,265.00	Estimate Item Adjustment (0012) due to user corrij1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is
	0220 - 0250	TEMPORARY REMOVABLE MARKING TAPE Total 12 IN. WHITE HIGH BUILD WATERBORNE PAINT	Material - Tota Overrun	- Total I Overrun Overrun - T	18 25 29	2023 Apr 17, 2023 Aug 2, 2023 Oct 2,	SYSTEM	\$0.00 \$3,081.60 (\$3,081.60) \$0.00 \$0.00 (\$1,265.00) \$1,265.00 \$0.00	Estimate Item Adjustment (0012) due to user corrij1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is
	0220 - 0220 - 0250 -	TEMPORARY REMOVABLE MARKING TAPE Total 12 IN. WHITE HIGH BUILD WATERBORNE PAINT Total ROCK DITCH	Material - Tota Overrun Overrun - Tota	- Total I Overrun Overrun - T	18 25 29 otal	2023 Apr 17, 2023 Aug 2, 2023 Oct 2, 2023 Oct 17,	SYSTEM SYSTEM SYSTEM	\$0.00 \$3,081.60 (\$3,081.60) \$0.00 \$0.00 (\$1,265.00) \$1,265.00 \$0.00 \$0.00	Estimate Item Adjustment (0012) due to user corrij1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment
	0220 - 0220 - 0250 -	TEMPORARY REMOVABLE MARKING TAPE Total 12 IN. WHITE HIGH BUILD WATERBORNE PAINT Total ROCK DITCH	Material - Tota Overrun Overrun - Tota	- Total I Overrun Overrun - T	25 29 otal	2023 Apr 17, 2023 Aug 2, 2023 Oct 2, 2023 Oct 17, 2022 Oct 17,	SYSTEM SYSTEM SYSTEM	\$0.00 \$3,081.60 (\$3,081.60) \$0.00 \$0.00 (\$1,265.00) \$1,265.00 \$0.00 \$0.00 \$1,760.00	Estimate Item Adjustment (0012) due to user corrij1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment
	0220 - 0220 - 0250 -	TEMPORARY REMOVABLE MARKING TAPE Total 12 IN. WHITE HIGH BUILD WATERBORNE PAINT Total ROCK DITCH	Material - Tota Overrun Overrun - Tota	- Total Overrun Overrun - T	25 29 otal	2023 Apr 17, 2023 Aug 2, 2023 Oct 2, 2023 Oct 17, 2022 Oct 17,	SYSTEM SYSTEM SYSTEM	\$0.00 \$3,081.60 (\$3,081.60) \$0.00 \$0.00 (\$1,265.00) \$1,265.00 \$0.00 \$0.00 \$1,760.00	Estimate Item Adjustment (0012) due to user corrij1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment
	0220 - 0220 - 0250 -	TEMPORARY REMOVABLE MARKING TAPE Total 12 IN. WHITE HIGH BUILD WATERBORNE PAINT Total ROCK DITCH CHECK	Material - Tota Overrun Overrun - Tota Material	- Total Overrun Overrun - T	25 29 otal	2023 Apr 17, 2023 Aug 2, 2023 Oct 2, 2023 Oct 17, 2022 Oct 17,	SYSTEM SYSTEM SYSTEM	\$0.00 \$3,081.60 (\$3,081.60) \$0.00 \$0.00 (\$1,265.00) \$1,265.00 \$0.00 \$0.00 \$1,760.00 (\$1,760.00)	Estimate Item Adjustment (0012) due to user corrij1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment
	0220 - 0220 - 0250 - 0250 - 0320	TEMPORARY REMOVABLE MARKING TAPE Total 12 IN. WHITE HIGH BUILD WATERBORNE PAINT Total ROCK DITCH CHECK	Material - Tota Overrun - Tota Material - Tota Material - Tota	- Total Overrun Overrun - T	25 29 otal	2023 Apr 17, 2023 Aug 2, 2023 Oct 2, 2023 Oct 17, 2022 Oct 17,	SYSTEM SYSTEM SYSTEM	\$0.00 \$3,081.60 (\$3,081.60) \$0.00 \$0.00 (\$1,265.00) \$1,265.00 \$0.00 \$0.00 \$1,760.00 (\$1,760.00)	Estimate Item Adjustment (0012) due to user corrij1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J6I3489	0360	SILT FENCE	Material	. 72 -	4	Sep 16, 2022	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user gummer1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					4	Sep 16, 2022	SYSTEM	(\$4,000.00)	,						
					5	Oct 3, 2022	SYSTEM	(\$4,000.00)							
				- Total				(\$11,200.00)							
			Material - Tota	ı				(\$11,200.00)							
			MaterialCredit		3	Sep 2, 2022	SYSTEM	\$3,600.00							
					4	Sep 16, 2022	SYSTEM	\$3,600.00							
					6	Oct 17, 2022	SYSTEM	\$4,000.00							
				- Total				\$11,200.00							
			MaterialCredit					\$11,200.00							
	0360 -	Total						\$0.00							
	0440	SUBSTRUCTURE	Overrun	Overrun	12	Jan 17,	SYSTEM	(\$13,200.00)							
	UT+U	REPAIR (FORMED)	Overruit	Overiuli	14	2023 Feb 16,	SYSTEM	\$13,200.00	Unit price based on averaged overrun adjustments for installed quantity on all						
						2023	01012	ψ10,200.00	previous payment estimates. Price Adjustments of ',275.00000 - 275.00000, 'is applied (if non-zero).						
				Overrun - T	otal			\$0.00							
			Overrun - Tota	ıl				\$0.00							
	0440 -	Total						\$0.00							
	0450	SUBSTRUCTURE REPAIR (UNFORMED)	Material		11	Jan 3, 2023	SYSTEM	\$51,275.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					11	Jan 3, 2023	SYSTEM	(\$51,275.00)							
					12	Jan 17, 2023	SYSTEM	\$38,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					12	Jan 17, 2023	SYSTEM	(\$38,850.00)							
				- Total				\$0.00							
			Material - Tota					\$0.00							
	0450 -	Total						\$0.00							
	0460	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		7	Nov 2, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					7	Nov 2, 2022	SYSTEM	(\$12,000.00)							
					8	Nov 16, 2022	SYSTEM	\$27,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					8	Nov 16, 2022	SYSTEM	(\$27,300.00)							
							9	Dec 2, 2022	SYSTEM	\$37,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
				g	9	Dec 2, 2022	SYSTEM	(\$37,950.00)							
											10	Dec 16, 2022	SYSTEM	\$44,766.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Dec 16, 2022	SYSTEM	(\$44,766.60)							
					11	Jan 3, 2023	SYSTEM	\$44,766.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					11	Jan 3, 2023	SYSTEM	(\$44,766.60)							
				12	Jan 17,	SYSTEM	\$44,766.60	This adjustment offsets the original system-generated Material Payment							



t Line	e Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
9 046	0 SUPERSTRUCTURE REPAIR (UNFORMED)	Material			2023			Estimate Item Adjustment (0004) due to user corrij1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
	(ON ONNED)			12	Jan 17, 2023	SYSTEM	(\$44,766.60)	
			- Total				\$0.00	
		Material - Tota	ıl				\$0.00	
046	0 - Total						\$0.00	
049	0 SLAB EDGE REPAIR (BRIDGES)	Overrun	Overrun		Dec 2, 2022	SYSTEM	(\$1,075.00)	
				10	Dec 16, 2022	SYSTEM	\$1,075.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',215.00000 - 215.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
		Overrun - Tota	ıl				\$0.00	
049	0 - Total						\$0.00	
050	0 CONCRETE CRACK FILLER	Material		7	Nov 2, 2022	SYSTEM	\$3,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user gummer1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				7	Nov 2, 2022	SYSTEM	(\$3,840.00)	
			- Total				\$0.00	
		Material - Tota	ıl				\$0.00	
050	0 - Total						\$0.00	
060	0 MISC.	Overrun	Overrun	29	Oct 2, 2023	SYSTEM	(\$6,000.00)	
				30	Oct 16, 2023	SYSTEM	\$6,000.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3000.00000 - 3000.00000 'is applied (if non-zero).
				Overrun - Total				
		Overrun - Tota	al				\$0.00	
060	0 - Total						\$0.00	
062	0 LAMINATED NEOPRENE BEARING PAD	Material		13	Feb 3, 2023	SYSTEM	(\$22,000.00)	
	ASSEMBLY			14	Feb 16, 2023	SYSTEM	\$22,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				14	Feb 16, 2023	SYSTEM	(\$22,000.00)	
			- Total				(\$22,000.00)	
		Material - Tota MaterialCredit	ıl	14	Feb 16, 2023	SYSTEM	(\$22,000.00) \$22,000.00	
			- Total				\$22,000.00	
		MaterialCredit	- Total				\$22,000.00	
062	0 - Total	MaterialCredit	- Total					
063	0 - Total TYPE N PTFE BEARING	Material Credit	- Total	14	Feb 16, 2023	SYSTEM	\$22,000.00 \$0.00 \$22,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user corrij1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
	0 TYPE N PTFE		- Total	14		SYSTEM	\$0.00	
	0 TYPE N PTFE		- Total		2023 Feb 16,		\$0.00 \$22,500.00	Estimate Item Adjustment (0004) due to user corrij1 overridding Payment
	0 TYPE N PTFE		- Total		2023 Feb 16,		\$0.00 \$22,500.00 (\$22,500.00)	Estimate Item Adjustment (0004) due to user corrij1 overridding Payment
063	0 TYPE N PTFE	Material	- Total		2023 Feb 16,		\$0.00 \$22,500.00 (\$22,500.00)	Estimate Item Adjustment (0004) due to user corrij1 overridding Payment
063	0 TYPE N PTFE BEARING 0 - Total 0 SILICONE EXPANSION JOINT	Material	- Total	14	2023 Feb 16, 2023 Jun 2, 2023	SYSTEM	\$0.00 \$22,500.00 (\$22,500.00) \$0.00 \$0.00 (\$20,512.00)	Estimate Item Adjustment (0004) due to user corrij1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
063	0 TYPE N PTFE BEARING 0 - Total 0 SILICONE	Material Material - Tota	- Total	14	2023 Feb 16, 2023	SYSTEM	\$0.00 \$22,500.00 (\$22,500.00) \$0.00 \$0.00	Estimate Item Adjustment (0004) due to user corrij1 overridding Payment
063	0 TYPE N PTFE BEARING 0 - Total 0 SILICONE EXPANSION JOINT	Material Material - Tota	- Total	14	2023 Feb 16, 2023 Jun 2, 2023 Jun 19,	SYSTEM	\$0.00 \$22,500.00 (\$22,500.00) \$0.00 \$0.00 (\$20,512.00)	Estimate Item Adjustment (0004) due to user corrij1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user corrij1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3489	0640	SILICONE	Material						Estimate Exception 5 on the current Payment Estimate.
		EXPANSION JOINT SEALANT			24	Jul 17, 2023	SYSTEM	(\$19,680.00)	
					25	Aug 2, 2023	SYSTEM	\$19,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					25	Aug 2, 2023	SYSTEM	(\$19,680.00)	Estimate Exception 3 on the current rayment Estimate.
				- Total		2023		(\$20,512.00)	
			Material - Tota					(\$20,512.00)	
			MaterialCredit		22	Jun 16,	SYSTEM	\$20,512.00	
						2023		400 540 40	
				- Total				\$20,512.00	
	0040	Total	MaterialCredit	- I otal				\$20,512.00	
	0640 -		Material		00	A 45	OVOTEM	\$0.00	This adjustes at Material Downson
	0660	REMOVAL OF EXISTING DECK REPAIR	Material		26	Aug 15, 2023	SYSTEM	\$5,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					26	Aug 15, 2023	SYSTEM	(\$5,950.00)	
					27	Sep 5, 2023	SYSTEM	\$5,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					27	Sep 5, 2023	SYSTEM	(\$5,950.00)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
	0660 -	Total						\$0.00	
	0700	POLYESTER POLYMER CONCRETE	Material		23	Jun 30, 2023	SYSTEM	\$741,198.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user corrij1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		WEARING SURFACE			23	Jun 30, 2023	SYSTEM	(\$741,198.00)	
					24	Jul 17, 2023	SYSTEM	\$741,198.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					24	Jul 17, 2023	SYSTEM	(\$741,198.00)	,
				- Total		2020		\$0.00	
			Material - Tota	ı				\$0.00	
	0700 -	Total						\$0.00	
	0720	MISC. CONCRETE CONSTRUCTION	Material		22	Jun 19, 2023	SYSTEM	\$91,416.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user corrij1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					22	Jun 16, 2023	SYSTEM	(\$91,416.00)	
					23	Jun 30, 2023	SYSTEM	\$274,248.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user corrij1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					23	Jun 30, 2023	SYSTEM	(\$274,248.00)	
					24	Jul 17, 2023	SYSTEM	\$274,248.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user corrij1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					24	Jul 17, 2023	SYSTEM	(\$274,248.00)	
					25	Aug 2, 2023	SYSTEM	\$274,248.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user corrij1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					25	Aug 2, 2023	SYSTEM	(\$274,248.00)	
					26	Aug 15, 2023	SYSTEM	\$274,248.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment
						2023			Estimate Exception 3 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3489	0720	MISC. CONCRETE	Material			2023			
		CONSTRUCTION			27	Sep 5, 2023	SYSTEM	\$448,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user corrij1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					27	Sep 5, 2023	SYSTEM	(\$448,290.00)	
					28	Sep 18, 2023	SYSTEM	\$448,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					28	Sep 18,	SYSTEM	(\$448,290.00)	Estimate Exception 1 on the current rayment Estimate.
					29	2023 Oct 2, 2023	SYSTEM	\$448,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					29	Oct 2, 2023	SYSTEM	(\$448,290.00)	Estimate Exception 1 on the current rayment Estimate.
					30	Oct 16, 2023	SYSTEM	\$448,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					30	Oct 16, 2023	SYSTEM	(\$448,290.00)	Estimate Exception 2 on the editor of the Estimate.
				- Total		2023		\$0.00	
			Material - Tota					\$0.00	
	0720 -	Total						\$0.00	
	0730	SUBSTRUCTURE	Overrun	Overrun	19	May 2,	SYSTEM	(\$15,300.00)	
		REPAIR (FORMED)			21	2023 Jun 2, 2023	SYSTEM	\$15,300.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',255.00000 - 255.00000, 'is
				O	4-1			00.00	applied (if non-zero).
			Overrun - Tota	Overrun - T	otai			\$0.00 \$0.00	
	0730 -	Total	Overruit - Tota	"				\$0.00	
	0740	SUBSTRUCTURE	Material		13	Feb 3,	SYSTEM	\$64,400.00	This adjustment offsets the original system-generated Material Payment
	0140	REPAIR (UNFORMED)	Waterial			2023			Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Feb 3,	SYSTEM	(\$64,400.00)	
						2023			
					14	Feb 16, 2023	SYSTEM	\$119,875.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Feb 16,	SYSTEM	\$119,875.00 (\$119,875.00)	Estimate Item Adjustment (0005) due to user corrij1 overridding Payment
						Feb 16, 2023			Estimate Item Adjustment (0005) due to user corrij1 overridding Payment
					14	Feb 16, 2023 Feb 16, 2023 Mar 2,	SYSTEM	(\$119,875.00)	Estimate Item Adjustment (0005) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment
					14	Feb 16, 2023 Feb 16, 2023 Mar 2, 2023 Mar 2,	SYSTEM SYSTEM	(\$119,875.00)	Estimate Item Adjustment (0005) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment
					14 15	Feb 16, 2023 Feb 16, 2023 Mar 2, 2023 Mar 2, 2023 Mar 16,	SYSTEM SYSTEM	(\$119,875.00) \$208,250.00 (\$208,250.00)	Estimate Item Adjustment (0005) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
					14 15 15	Feb 16, 2023 Feb 16, 2023 Mar 2, 2023 Mar 2, 2023 Mar 16, 2023 Mar 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM	(\$119,875.00) \$208,250.00 (\$208,250.00) \$274,750.00	Estimate Item Adjustment (0005) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment
					14 15 15 16 16	Feb 16, 2023 Feb 16, 2023 Mar 2, 2023 Mar 2, 2023 Mar 16, 2023 Apr 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$119,875.00) \$208,250.00 (\$208,250.00) \$274,750.00 (\$274,750.00)	Estimate Item Adjustment (0005) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment
					14 15 15 16 16 17	Feb 16, 2023 Feb 16, 2023 Mar 2, 2023 Mar 16, 2023 Mar 16, 2023 Apr 3, 2023 Apr 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$119,875.00) \$208,250.00 (\$208,250.00) \$274,750.00 (\$274,750.00) \$340,725.00	Estimate Item Adjustment (0005) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment
					14 15 15 16 16 17 17	Feb 16, 2023 Feb 16, 2023 Mar 2, 2023 Mar 16, 2023 Mar 16, 2023 Apr 3, 2023 Apr 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$119,875.00) \$208,250.00 (\$208,250.00) \$274,750.00 (\$274,750.00) \$340,725.00	Estimate Item Adjustment (0005) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment
					14 15 15 16 16 17 17 18	Feb 16, 2023 Feb 16, 2023 Mar 2, 2023 Mar 16, 2023 Mar 16, 2023 Apr 3, 2023 Apr 17, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$119,875.00) \$208,250.00 (\$208,250.00) \$274,750.00 (\$274,750.00) \$340,725.00 (\$340,725.00) \$375,375.00	Estimate Item Adjustment (0005) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J6I3489	0740	SUBSTRUCTURE REPAIR (UNFORMED)	Material		20	May 16, 2023	SYSTEM	\$379,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Exception 9 on the current Payment Estimate.								
					20	May 16, 2023	SYSTEM	(\$379,925.00)									
					21	Jun 2, 2023	SYSTEM	\$379,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user corrij¹ overridding Payment Estimate Exception 7 on the current Payment Estimate.								
					21	Jun 2, 2023	SYSTEM	(\$379,925.00)									
					22	Jun 19, 2023	SYSTEM	\$379,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user corrij1 overridding Payment Estimate Exception 8 on the current Payment Estimate.								
					22	Jun 16, 2023	SYSTEM	(\$379,925.00)									
				- Total				\$0.00									
			Material - Tota					\$0.00									
			Overrun	Overrun	17	Apr 3, 2023	SYSTEM	(\$65,975.00)									
					18	Apr 17, 2023	SYSTEM	(\$34,650.00)									
					19	May 2, 2023	SYSTEM	(\$4,550.00)									
					21	Jun 2, 2023	SYSTEM	\$105,175.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',175.00000 - 175.00000, 'is applied (if non-zero).								
				Overrun - T	otal			\$0.00									
			Overrun - Tota					\$0.00									
	0740 -	Total						\$0.00									
	0750	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		21	Jun 2, 2023	SYSTEM	\$3,060.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user corrij1 overridding Payment Estimate Exception 9 on the current Payment Estimate.								
					21	Jun 2, 2023	SYSTEM	(\$3,060.00)									
					22	Jun 19, 2023	SYSTEM	\$3,060.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user corrij1 overridding Payment Estimate Exception 9 on the current Payment Estimate.								
					22	Jun 16, 2023	SYSTEM	(\$3,060.00)									
					23	Jun 30, 2023	SYSTEM	\$3,060.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user corrij1 overridding Payment Estimate Exception 4 on the current Payment Estimate.								
					23	Jun 30, 2023	SYSTEM	(\$3,060.00)									
					24	Jul 17, 2023	SYSTEM	(\$3,060.00)									
					25	Aug 2, 2023	SYSTEM	\$20,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user corrij1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
					25	Aug 2, 2023	SYSTEM	(\$20,400.00)	·								
					26	Aug 15, 2023	SYSTEM	\$23,630.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment Estimate Exception 4 on the current Payment Estimate.								
			2	27	2	26 Aug 15, SYSTEM (\$23,630.00)											
													27	Sep 5, 2023	SYSTEM	\$24,310.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user corrij1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
									27	Sep 5, 2023	SYSTEM	(\$24,310.00)					
					28	Sep 18, 2023	SYSTEM	\$24,310.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					28	Sep 18, 2023	SYSTEM	(\$24,310.00)									
					29	Oct 2,	SYSTEM	\$41,731.60	This adjustment offsets the original system-generated Material Payment								



1 1 1 1 1 1 1 1 1 1										
SEPARR 2	ct	Line	Description		Adjustment				Amount	Remarks
Formation Power	39	0750	REPAIR	Material			2023			
Material Crost			(UNFORMED)			29		SYSTEM	(\$41,731.60)	
MaterialCredit 25 Aug 2, SYSTEM \$3,000.00					- Total				(\$3,060.00)	
Total 1,				Material - Tota	ı				(\$3,060.00)	
Material Credit 10				MaterialCredit		25	Aug 2,	SYSTEM	\$3,060.00	
Material Credit - Total 27 Sep 5, corright (\$17-340.00) 102 SQFT-wit be left this estimate due to the CRE 20 reports on the project more being up to dise.							2023			
Other lam										
Adjustment				MaterialCredit					\$3,060.00	
PCCP 28 Sep 18 Corrigit S17,340.00 Cre 20 put in for Superstructure Pours.					OTHR	27		corrij1	(\$17,340.00)	
POCP - Total					OTHR - Tota	al			(\$17,340.00)	
Other Item Adjustment - Total \$0.00					PCCP	28		corrij1	\$17,340.00	Cre 20 put in for Superstructure Pours.
1750 - Total					PCCP - Tota	al			\$17,340.00	
Name				Other Item Adj	justment - To	tal			\$0.00	
Name Part		0750 -	Total						\$0.00	
2023 \$0.00		0760	HALF-SOLE REPAIR		PCCP	28		corrij1	(\$30,233.50)	No CRE 20 Report for 08/14/2023.
Other Item Adjustment - Total S0.00						30		corrij1	\$30,233.50	CRE 20 Report for the Concrete Pour on 08/14/2023 has been completed.
Solid					PCCP - Tota	al			\$0.00	
FULL DEPTH Cher Item PCP 28 Sep 18, 2023 2023 2023 27,666.50 CRE 20 Report for 18/14/2023.				Other Item Adj	justment - To	tal			\$0.00	
REPAIR Adjustment 2023 30 Oct 16, corrij1 \$7,666.50 CRE 20 Report for the Concrete Pour on 08/14/2023 has been completed.		0760 -	Total						\$0.00	
PCCP - Total S0.00		0770			PCCP	28		corrij1	(\$7,666.50)	No CRE 20 Report for 08/14/2023.
Other Item Adjustment - Total						30		corrij1	\$7,666.50	CRE 20 Report for the Concrete Pour on 08/14/2023 has been completed.
					PCCP - Tota	al			\$0.00	
				Other Item Adi						
Misc. Material 20		0770 -	Total							
2023 Estimate Item Adjustment (0003) due to user corrij1 overridding Payment Estimate Exception 10 on the current Payment Estimate.				Material		20	May 16.	SYSTEM		This adjustment offsets the original system-generated Material Payment
2023										Estimate Item Adjustment (0003) due to user corrij1 overridding Payment
2023 Estimate Item Adjustment (0007) due to user corrij1 overridding Payment Estimate Exception 10 on the current Payment Estimate.						20		SYSTEM	(\$83,190.00)	
21						21		SYSTEM	\$83,190.00	Estimate Item Adjustment (0007) due to user corrij1 overridding Payment
22						21		SYSTEM	(\$83,190.00)	Estimate Exception 10 on the current Payment Estimate.
22						22	Jun 19,	SYSTEM	\$83,190.00	Estimate Item Adjustment (0008) due to user corrij1 overridding Payment
Total \$0.00						22		SYSTEM	(\$83,190.00)	Estimate Exception 10 on the current Payment Estimate.
Material - Total \$0.00					- Total		2023		\$0.00	
Solution Section Solution				Motorial Tetr						
REINFORCING STEEL (EPOXY COATED) Material 29 Oct 2, 2023 SYSTEM \$15,540.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user corrij1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 29 Oct 2, 2023 Oct 2, 2023 SYSTEM \$15,540.00 Formula Summer Steels (\$15,540.00) SUMMER STEEL (EPOXY COATED) A summer Summer Steels (\$15,540.00) Material - Total SUMMER		0700		Materiai - Tota						
STEEL (EPOXY COATED)				Matarial		20	Octo	CVOTE:		This adjustment offsets the colored variations
2023 \$0.00		0800	STEEL (EPOXY	Material		29		SYSTEM	\$15,540.00	Estimate Item Adjustment (0007) due to user corrij1 overridding Payment
Material - Total \$0.00 0800 - Total \$0.00 0940 LAMINATED Material 19 May 2, SYSTEM \$4,605.00 This adjustment offsets the original system-generated Material Payment						29		SYSTEM	(\$15,540.00)	
0800 - Total \$0.00 0940 LAMINATED Material 19 May 2, SYSTEM \$4,605.00 This adjustment offsets the original system-generated Material Payment					- Total				\$0.00	
0940 LAMINATED Material 19 May 2, SYSTEM \$4,605.00 This adjustment offsets the original system-generated Material Payment				Material - Tota					\$0.00	
		0800 -	Total						\$0.00	
BEARING PAD Estimate Exception 12 on the current Payment Estimate.		0940	NEOPRENE	Material		19	May 2, 2023	SYSTEM	\$4,605.00	Estimate Item Adjustment (0007) due to user corrij1 overridding Payment



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
3489	0940	LAMINATED NEOPRENE	Material	. 7 -	19	May 2, 2023	SYSTEM	(\$4,605.00)			
		BEARING PAD			20	May 16, 2023	SYSTEM	\$12,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user corrij1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		
					20	May 16, 2023	SYSTEM	(\$12,280.00)			
				- Total				\$0.00			
			Material - Tota	ı				\$0.00			
	0940 -	· Total						\$0.00			
	0950	TYPE N PTFE BEARING	Material		20	May 16, 2023	SYSTEM	\$14,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user corrij1 overridding Payment Estimate Exception 12 on the current Payment Estimate.		
					20	May 16, 2023	SYSTEM	(\$14,000.00)			
				- Total				\$0.00			
			Material - Tota	ı				\$0.00			
	0950 -	Total						\$0.00			
	0960	STRIP SEAL EXPANSION JOINT SYSTEM	Material		30	Oct 16, 2023	SYSTEM	\$95,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user corrij1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					30	Oct 16, 2023	SYSTEM	(\$95,900.00)			
				- Total				\$0.00			
		- Fotal	Material - Tota	ı				\$0.00			
	0960 -	· Total						\$0.00			
	5001	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material		5	Oct 3, 2022	SYSTEM	\$46,710.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
		TRAFFIC BARRIER,			5	Oct 3, 2022	SYSTEM	(\$46,710.00)			
				- Total				\$0.00			
			Material - Tota	ı				\$0.00			
			Overrun	Overrun	18	Apr 17, 2023	SYSTEM	(\$33,735.00)			
					23	Jun 30, 2023	SYSTEM	\$33,735.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',25.95000 - 25.95000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - Tota	ıl				\$0.00			
	5001 -	Total						\$0.00			
	5004	4 IN. WHITE WATERBORNE PAVEMENT	Material		6	Oct 17, 2022	SYSTEM	\$850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
		MARKING			6	Oct 17, 2022	SYSTEM	\$850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					6	Oct 17, 2022	SYSTEM	(\$850.00)			
				- Total				\$850.00			
			Material - Tota	ıl				\$850.00			
			Material - Total MaterialCredit				7	Nov 2,	SYSTEM	\$850.00	
			MaterialCredit		2022						
			MaterialCredit	- Total		2022		\$850.00			
			MaterialCredit MaterialCredit			2022		\$850.00 \$850.00			
					9	Dec 2, 2022	corrij1		This Line Adjustment is being made to counter act \$850 of Line Item 5004 being paid twice in estimate 6 for a total of \$1700.		
			MaterialCredit Other Item	- Total		Dec 2,	corrij1	\$850.00			
			MaterialCredit Other Item	- Total MDPA	al	Dec 2,	corrij1	\$850.00 (\$1,700.00)			
			MaterialCredit Other Item	- Total MDPA MDPA - Tot	15	Dec 2, 2022		\$850.00 (\$1,700.00) (\$1,700.00)	being paid twice in estimate 6 for a total of \$1700. This \$850.00 adjustment has been added in order to offset the		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6l3489	5004	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Overrun	Overrun	18	Apr 17, 2023	SYSTEM	(\$4,216.00)	
					23	Jun 30, 2023	SYSTEM	\$4,216.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',0.50000 - 0.50000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - Total					\$0.00	
	5004 -	- Total						\$850.00	
	5005	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		18	Apr 17, 2023	SYSTEM	\$2,026.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user corrij1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					18	Apr 17, 2023	SYSTEM	(\$2,026.00)	
					19	May 2, 2023	SYSTEM	\$2,026.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user corrij1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					19	May 2, 2023	SYSTEM	(\$2,026.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
			Overrun	Overrun	18	Apr 17, 2023	SYSTEM	(\$1,626.00)	
					23	Jun 30, 2023	SYSTEM	\$1,626.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',0.50000 - 0.50000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - Total					\$0.00	
	5005 -	005 - Total						\$0.00	
	5009	TYPE 5 AGGREGATE FOR BASE	Material		19	May 2, 2023	SYSTEM	\$11,215.91	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					19	May 2, 2023	SYSTEM	(\$11,215.91)	
					20	May 16, 2023	SYSTEM	\$11,215.91	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					20	May 16, 2023	SYSTEM	(\$11,215.91)	
					21	Jun 2, 2023	SYSTEM	\$11,215.91	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					21	Jun 2, 2023	SYSTEM	(\$11,215.91)	
					22	Jun 19, 2023	SYSTEM	\$11,215.91	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					22	Jun 16, 2023	SYSTEM	(\$11,215.91)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5009 -	5009 - Total					\$0.00		
	5014	MISC.	Overrun	Overrun	27	Sep 5, 2023	SYSTEM	(\$4,765.95)	
					29	Oct 2, 2023	SYSTEM	\$4,765.95	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3.57000 - 3.57000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - Total					\$0.00	
	5014 - Total						\$0.00		
J6I3489 -	J6I3489 - Total							\$850.00	
Overall -	Total							\$850.00	

MoDOT

Contract Adjustments for Contract - 220415-F01

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 19 of 19