

Pay Estimate Created Date: May 16, 2024

Progress E	Estimate Number	Contract II Prime Contractor	Custor	Lighting Services	s, LLC dba B	Black &	Pay Period Start Pay Period End	May 2, 2024 May 15, 2024	Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,738,800.00 \$11,847.79 \$1,750,647.79
Approval Date										By User
May 16, 2024				Generated and A	pproved (ar	id should b	oe considered [Draft) at the	Project Office Level by	sandis1
May 16, 2024			Rev	iewed and Approv	ed (and sh	ould be co	nsidered Draft)	at the Resi	dent Engineer Level by	sandis1
May 17, 2024				R	eviewed an	d Approve	fice Level by ramses1			
Original Completion Date Current Completion Date Ad					Actua	Complet	ion Date	% of	Current Contract Amour	nt Complete
May 31,	May 31, 2023		May 31	, 2024					76.95%	
	Co	ontract Inform	national Dat	es			Milestones			
Date Descripti	on Oi	riginal Comp	letion Date	Current Comple	tion Date	No Miles	tones Exist for	Contract		
Acceptance Date										
Awarded Date	Ju	ine 2, 2022		June 2, 2022						
Letting Date	Ma	ay 20, 2022		May 20, 2022						
Notice to Proceed	Date Ju	ine 6, 2022		June 6, 2022						
Open to Traffic Da	ite									
Work Began Date										

Contract Total Pay	For Estimate No. 17			
		This Estimate	Previous	To Date
220520-C07				
	Total Posted Items Pay	\$50,447.67	\$1,296,596.37	\$1,347,044.04
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$1,296,596.37	\$1,347,044.04
Contract Total Paya	able This Estimate:	\$50,447.67		

Contract Total Payable This Estimate: Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
J4P3271	0010	9019902	MISC.LABOR/EQUIPMENT FOR TROUBLE SHOOTING/INVESTIGATION/REPAIR WORK ADJUSTMENT FACTOR	EA	\$1.127	23,941.32	\$26,981.87		
	0020 9019902 MISC.MATERIAL FOR REPAIR WORK ADJUSTMENT FACTOR EA \$1.830 11,421.2								
	0030	9019902	MISC.TRAFFIC CONTROL ADJUSTMENT FACTOR	EA	\$2.850	900	\$2,565.00		
Project J4	Project J4P3271 - Total								
Overall - Total									

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3271	5015	MISC.	Material			-1	\$79.20	(\$79.20)
	5015	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user sandis1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	1	\$79.20	\$79.20
	5016	MISC.	Material			-1	\$756.00	(\$756.00)
	5016	MISC.	Material		This adjustment offsets the original system-	1	\$756.00	\$756.00



Pay Estimate Created Date: May 16, 2024

Progress Estimate Number 17			Contract ID Prime Contractor	220520-C07 Custom Lightin McDonald	g Services, Ll	LC dba Black &	Pay Period Start Pay Period End	2024 May 15, 2024	Original Cont Amount Net Change C Amount Current Cont Amount	ه Drder _{\$1}	1,738,800.00 11,847.79 1,750,647.79
Project Number	Line No.	Item	Description	Adjustment Type	Other Item Adjustment Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3271						Adjustme overridding Pay	aterial Payment ent (0001) due to ment Estimate E the current Payr	o user sandis1 Exception 1 on			
	5017		MIS	C. Material					-1	\$198.00	(\$198.00
	5017		MIS	C. Material		generated M Adjustme overridding Pay	ent offsets the or aterial Payment ent (0002) due to ment Estimate E the current Payn	Estimate Item o user sandis1 Exception 2 on		\$198.00	\$198.00
	5018		MIS	C. Material					-1	\$792.00	(\$792.00
	5018		MIS	C. Material		generated M Adjustme overridding Pay	ent offsets the or aterial Payment ent (0003) due to ment Estimate E the current Payn	Estimate Item o user sandis1 Exception 3 on		\$792.00	\$792.00
	5019		MIS	C. Material					-1	\$225.00	(\$225.00
	5019		MIS	C. Material		generated M Adjustme overridding Pay	ent offsets the or aterial Payment ent (0004) due to ment Estimate E the current Payr	Estimate Item o user sandis1 Exception 4 on		\$225.00	\$225.00
	5020		MIS	C. Material					-1	\$484.65	(\$484.65)
	5020		MIS	C. Material		generated M Adjustme overridding Pay	ent offsets the or aterial Payment ent (0006) due to ment Estimate E the current Payr	Estimate Item user sandis1 Exception 6 on		\$484.65	\$484.65
Total											\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information											
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J4P3271		Job Order Contract for lighting repair	Various	VARIOUS	at various locations in the Kansas City District							

Totals by Job Numbers

	This Estimate	Previous	To Date
Posted Item Pay	\$50,447.67	\$1,296,596.37	\$1,347,044.04
Gross Item Adjustments	\$0.00	\$0.00	\$0.00
Gross Item Pay	\$50,447.67	\$1,296,596.37	\$1,347,044.04
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3271, Item 9019901, Project Item Line Number 5016, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with the contractor and district materials staff to resolve exception.	sandis1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3271, Item 9019901, Project Item Line Number 5017, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with the contractor and district materials staff to resolve exception.	sandis1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3271, Item 9019901, Project Item Line Number 5018, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with the contractor and district materials staff to resolve exception.	sandis1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3271, Item 9019901, Project Item Line Number 5019, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with the contractor and district materials staff to resolve exception.	sandis1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3271, Item 9019901, Project Item Line Number 5015, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with the contractor and district materials staff to resolve exception.	sandis1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3271, Item 9019901, Project Item Line Number 5020, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with the contractor and district materials staff to resolve exception.	sandis1	Overridden

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
								. ,		Qty		, ,
)520-C07	J4P3271	0020	0010	9019902	MISC.LABOR/EQUIPMENT FOR TROUBLE SHOOTING/INVESTIGATION/REPAIR WORK ADJUSTMENT FACTOR	720,000.00	0.00	720,000.00	EA	611,251.96	\$1.13	\$688,880.96
		0020	0020	9019902	MISC.MATERIAL FOR REPAIR WORK ADJUSTMENT FACTOR	432,000.00	0.00	432,000.00	EA	278,423.66	\$1.83	\$509,515.30
		0020	0030	9019902	MISC.TRAFFIC CONTROL ADJUSTMENT FACTOR	48,000.00	0.00	48,000.00	EA	48,000.00	\$2.85	\$136,800.00
		0020	5001	9019901	MISC.WORK ORDER NUMBER 3634510	0.00	1.00	1.00	LS	1.00	\$1,223.52	\$1,223.52
		0020	5002	9019901	MISC.WORK ORDER NUMBER 3689704	0.00	1.00	1.00	LS	1.00	\$123.41	\$123.41
		0020	5003	9019901	MISC.WORK ORDER NUMBER 3684769	0.00	1.00	1.00	LS	1.00	\$1,350.56	\$1,350.56
		0020	5004	9019901	MISC.Lighting (Work Order 76-1396152, WO3734267) I-70 & Lee's Summit Rd	0.00	1.00	1.00	LS	1.00	\$464.74	\$464.74
		0020	5005	9019901	MISC.Lighting (Work Order 76-1394252, WO3749944) at I-29 & Mexico City	0.00	1.00	1.00	LS	1.00	\$990.00	\$990.00
		0020	5006	9019901	MISC. Lighting (Work Order 76-1394261, WO3756596) at I-29 & NW 56 St	0.00	1.00	1.00	LS	1.00	\$630.00	\$630.00
		0020	5007	9019901	MISC. Lighting (Work Order 76-1394267, WO3801884) N Barry Rd and Hwy 169	0.00	1.00	1.00	LS	1.00	\$882.00	\$882.00
		0020	5008	9019901	MISC.Lighting (Work Order 76-1469107, WO3752368) I-29 & I-635	0.00	1.00	1.00	LS	1.00	\$524.45	\$524.45
		0020	5009	9019901	MISC.Lighting (Work Order 76-1469108, WO3763041) 50 Hwy & Chipman Rd	0.00	1.00	1.00	LS	1.00	\$525.00	\$525.00
		0020	5010	9019901	MISC Lighting (Work Order 76-1469265, WO3711330) I-70 & Stadium Dr	0.00	1.00	1.00	LS	1.00	\$1,912.45	\$1,912.45
		0020	5011	9019901	MISC.Lighting (Work Order 76-1470405, WO3794812) I-70 & Admiral	0.00	1.00	1.00	LS	1.00	\$49.92	\$49.92
		0020	5012	9019901	MISC.Lighting (Work Order 76-1470406, WO3826955) I-435 & 350 Hwy	0.00	1.00	1.00	LS	1.00	\$343.20	\$343.20
		0020	5013	9019901	MISC.Lighting (Work Order 76-1470407, WO3828043) WB 152 Hwy & I-29	0.00	1.00	1.00	LS	1.00	\$225.00	\$225.00
		0020	5014	9019901	MISC.Lighting (Work Order 76-1470412, WO3923108) I-70 & Jackson Ave	0.00	1.00	1.00	LS	1.00	\$68.69	\$68.69
		0020	5015	9019901	MISC.Lighting (Work Order 76-1507210, WO3967896) 50 Hwy & Chipman Rd	0.00	1.00	1.00	LS	1.00	\$79.20	\$79.20
		0020	5016	9019901	MISC.Lighting (Work Order 76-1507216, WO4011473) 169 & Englewood	0.00	1.00	1.00	LS	1.00	\$756.00	\$756.00
		0020	5017	9019901	MISC.Lighting (Work Order 76-1540188, WO4080447) SB I-35 Exit 6	0.00	1.00	1.00	LS	1.00	\$198.00	\$198.00
		0020	5018	9019901	MISC.Lighting (Work Order 76-1540195, WO4113528) 29 St & Brooklyn Ave	0.00	1.00	1.00	LS	1.00	\$792.00	\$792.00
		0020	5019	9019901	MISC.Lighting (Work Order 76-1545819, WO4090719) Rte 1 & 152 Hwy	0.00	1.00	1.00	LS	1.00	\$225.00	\$225.00
		0020	5020	9019901	MISC.Lighting (Work Order 76-1569247, WO4113516) I-435 & Parvin	0.00	1.00	1.00	LS	1.00	\$484.65	\$484.65
		0020	9000	6189916	MISC.Liquidated Damages	0.00			DLR		(\$1.00)	
		0020	9100	6189916	MISC.Additional Items	0.00			DLR	0.00	\$1.00	\$0.00
	Project J4	4P3271 - To	otal Value	Posted to	Date as of Report Generated Date							\$1,347,044.05
0520-C07 Ove	erall - Total	Value Pos	ted to Da	te as of Re	port Generated Date							\$1,347,044.0



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line lumber	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	9019902	MISC. HIGHWAY LIGHTING	5/15/24	5/15/24	585.00	EA		0		0		76-1631154, WO4309269, NB I-29 & 64th St, Invoice Received 5/8/2024
				5/15/24	585.00	EA		0		0		76-1631155, WO4309272, NB I-29 Exit, Invoice Received 5/8/2024
				5/15/24	585.52	EA		0		0		76-1631153, WO4309262, 6th St & Broadway Blvd, Invoice Received 5/8/2024
				5/15/24	1,170.00	EA	K24C9379	0		0		76-1631149, WO4304141, 150 Hwy & White, Invoice Received 5/8/2024
				5/15/24	1,757.08	EA	K24C9380	0		0		76-1631151, WO4306812, I-435 & 40 Hwy, Invoice Received 5/8/2024
				5/15/24	3,042.00	EA		0		0		76-1631152, WO4309258, I-435 & 23rd St, Invoice Received 5/8/2024
				5/15/24	3,510.00	EA		0		0		76-1631150, WO4306810, I-70 I-435 Interchange, Invoic Received 5/8/2024
				5/15/24	4,216.16	EA		0		0		76-1631146, WO4113514, I-70 & State Line Rd., Invoice Received 5/8/2024
				5/15/24	4,216.16	EA		0		0		76-1631148, WO4298540, I-435 & Wornall, Invoice Received 5/8/2024
				5/15/24	4,274.40	EA		0		0		76-1631147, WO4295645, Kit Bond Bridge, Invoice Received 5/8/2024
0020	9019902	MISC. HIGHWAY LIGHTING	5/15/24	5/15/24	108.00	EA		0		0		76-1631147, WO4295645, Kit Bond Bridge, Invoice Received 5/8/2024
				5/15/24	268.20	EA		0		0		76-1631155, WO4309272, NB I-29 Exit, Invoice Receiver 5/8/2024
				5/15/24	490.00	EA		0		0		76-1631154, WO4309269, NB I-29 & 64th St, Invoice Received 5/8/2024
				5/15/24	701.00	EA	K24C9379	0		0		76-1631149, WO4304141, 150 Hwy & White, Invoice Received 5/8/2024
				5/15/24	759.00	EA		0		0		76-1631150, WO4306810, I-70 I-435 Interchange, Invoic Received 5/8/2024
				5/15/24	3,036.00	EA		0		0		76-1631146, WO4113514, I-70 & State Line Rd., Invoice Received 5/8/2024
				5/15/24	6,059.00	EA	K24C9380	0		0		76-1631151, WO4306812, I-435 & 40 Hwy, Invoice Received 5/8/2024
0030	9019902	MISC. HIGHWAY LIGHTING	5/15/24	5/15/24	900.00	EA		0		0		76-1631146, WO4113514, I-70 & State Line Rd., Invoice Received 5/8/2024

The information below this line are details for Construction Signs (if applicable). No Data Available



APP 2019 Visit of the second sec		Remarks	Amount	Created By	Created Date	Est. Number	Other Adjustment	Adjustment Type	Description	Line
HIGHWAY LIGHTING HIGHWAY LIGHTING Image: second se				29	Duto			.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
View View <th< td=""><td></td><td>This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0001) due to user weathc1 overridding Estimate Exception 1 on the current Payment Estimate.</td><td>\$77,415.88</td><td>SYSTEM</td><td></td><td>1</td><td></td><td>Material</td><td>HIGHWAY</td><td>0010</td></th<>		This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0001) due to user weathc1 overridding Estimate Exception 1 on the current Payment Estimate.	\$77,415.88	SYSTEM		1		Material	HIGHWAY	0010
Visit Visit <th< td=""><td></td><td></td><td>(\$77,415.88)</td><td>SYSTEM</td><td></td><td>1</td><td></td><td></td><td></td><td></td></th<>			(\$77,415.88)	SYSTEM		1				
Image: Problem in the stand in therest in the stand in the stand in the stand in the stand in the s		This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0001) due to user weathc1 overridding Estimate Exception 1 on the current Payment Estimate.	\$99,045.45	SYSTEM		2				
Image: Problem in the second			(\$99,045.45)	SYSTEM		2				
Image: Control of Contrect of Contrect of Control of Control of Control of Control of C		This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0001) due to user sandis1 overridding Estimate Exception 4 on the current Payment Estimate.	\$99,045.45	SYSTEM		3				
Material - Total S0.00 0010 - Total 50.00 0020 MiSC. HIGHWAY LIGHTING Material Nov 2, 2 SYSTEM \$85,116.59 This adjustment offsets the original system-generated Material F 2 Dec 2, 2022 SYSTEM \$85,116.59 Stistinate Exception 2 on the current Payment Estimate. 2 Dec 2, 2022 SYSTEM \$107,728.81 This adjustment offsets the original system-generated Material F 3 Jan 17, 2023 SYSTEM \$107,728.81 This adjustment offsets the original system-generated Material F 4 Jan 17, 2023 SYSTEM \$107,728.81 This adjustment offsets the original system-generated Material F 0 Total SYSTEM \$107,728.81 This adjustment offsets the original system-generated Material F 1 Nov 2, 2023 SYSTEM \$107,728.81 This adjustment offsets the original system-generated Material F 0 Total SYSTEM \$107,728.81 This adjustment offsets the original system-generated Material F 0 Total SYSTEM \$20.00 SYSTEM \$20.00 0 Total SYSTEM			(\$99,045.45)	SYSTEM		3				
O010 - Total S0.00 0020 MISC. HIGHWAY LIGHTINS Material 1 Nov 2, 2022 SYSTEM \$85,116.59 This adjustment (0002) due to user weathrd overdiding Estimate Exception 2 on the current Payment Estimate. 1 Nov 2, 2022 SYSTEM \$85,116.59 This adjustment offsets the original system-generated Material F Estimate Exception 2 on the current Payment Estimate. 2 Dec 2, 2022 SYSTEM \$107,728.81 This adjustment offsets the original system-generated Material F Estimate tem Adjustment (0002) due to user weathrd overdiding Estimate Exception 2 on the current Payment Estimate. 2 Dec 2, 2022 SYSTEM \$107,728.81 This adjustment offsets the original system-generated Material F Estimate tem Adjustment (0002) due to user weathrd overdiding Estimate Exception 5 on the current Payment Estimate. 3 Jan 17, 2023 SYSTEM \$107,728.81 This adjustment offsets the original system-generated Material F Estimate tem Adjustment (0002) due to user sendis 1 overriddin Estimate Exception 5 on the current Payment Estimate. 0020 - Total - Total \$0.00 013 Material - Total \$0.00 014 Nov 2, 2022 SYSTEM \$26,077.50 This adjustment offsets the original system-generated Material F Estimate Item Adjustment (0003) due to user wea			\$0.00				- Total			
0020 MISC. HIGHWAY LIGHTING Material HIGHWAY LIGHTING Nov 2, LIGHTING SYSTEM \$85,116.59 This adjustment offsets the original system-generated Material F Estimate Exception 2 on the current Payment Estimate. 1 Nov 2, 2022 SYSTEM \$85,116.59 This adjustment offsets the original system-generated Material F Estimate Exception 2 on the current Payment Estimate. 2 Dec 2, 2022 SYSTEM \$107,728.81 This adjustment offsets the original system-generated Material F Estimate Exception 2 on the current Payment Estimate. 2 Dec 2, 2023 SYSTEM \$107,728.81 This adjustment offsets the original system-generated Material F Estimate Exception 2 on the current Payment Estimate. 0 Jan 17, 2023 SYSTEM \$107,728.81 This adjustment offsets the original system-generated Material F Estimate Exception 5 on the current Payment Estimate. 0 Jan 17, 2023 SYSTEM \$107,728.81 This adjustment offsets the original system-generated Material F Estimate Exception 5 on the current Payment Estimate. 0 Material - Total Total SYSTEM \$26,077.50 This adjustment offsets the original system-generated Material F Estimate Exception 3 on the current Payment Estimate. 0 MiGC, HIGHWAY Nov 2, 2022 SYSTEM \$26,077.50<			\$0.00				otal	Material - To		
HIGHWAY LIGHTING HIGHWAY LIGHTING Image: Second seco			\$0.00						Total	0010 -
0020 -Total 0020 </td <td></td> <td>This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0002) due to user weathc1 overridding Estimate Exception 2 on the current Payment Estimate.</td> <td>\$85,116.59</td> <td>SYSTEM</td> <td></td> <td>1</td> <td></td> <td>Material</td> <td>HIGHWAY</td> <td>0020</td>		This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0002) due to user weathc1 overridding Estimate Exception 2 on the current Payment Estimate.	\$85,116.59	SYSTEM		1		Material	HIGHWAY	0020
022 0 0 Estimate Item Adjustment (0002) due to user weathc1 overriddin Estimate Exception 2 on the current Payment Estimate. 2 Dec 2, 2022 SYSTEM (\$107,728.81) 3 Jan 17, 2023 SYSTEM \$107,728.81 This adjustment offsets the original system-generated Material F Estimate Item Adjustment (0002) due to user sandis1 overriddin Estimate Exception 5 on the current Payment Estimate. 3 Jan 17, 2023 SYSTEM (\$107,728.81) • • • • • • • • • • • • • • • • • • •			(\$85,116.59)	SYSTEM		1				
0020 - Total 3 Jan 17, 2023 SYSTEM \$107,728.81 This adjustment offsets the original system-generated Material F Estimate Item Adjustment (0002) due to user sandis1 overriddin Estimate 0 - Total SYSTEM \$107,728.81 This adjustment offsets the original system-generated Material F Estimate 0 - Total SYSTEM \$107,728.81 This adjustment offsets the original system-generated Material F Estimate 0 - Total SYSTEM \$107,728.81 Structure \$0.00 0 - Total SYSTEM \$0.00 Structure \$0.00 0 OU20 - Total System \$0.00 Structure \$0.00 0 MISC, HIGHWAY HIGHWAY 1 Nov 2, 2022 SYSTEM \$26,077.50 This adjustment offsets the original system-generated Material F Estimate Item Adjustment (0003) due to user weathc1 overridding Estimate 1 Nov 2, 2022 SYSTEM \$26,077.50 This adjustment offsets the original system-generated Material F 2 Dec 2, 2022 SYSTEM \$30,637.50 This adjustment offsets the original system-generated Material F 2 Dec 2, 2022 SYSTEM \$30,637.50 This adjustment offsets the original system-generated Material F </td <td></td> <td>This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0002) due to user weathc1 overridding Estimate Exception 2 on the current Payment Estimate.</td> <td>\$107,728.81</td> <td>SYSTEM</td> <td></td> <td>2</td> <td></td> <td></td> <td></td> <td></td>		This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0002) due to user weathc1 overridding Estimate Exception 2 on the current Payment Estimate.	\$107,728.81	SYSTEM		2				
0203 2023 2023 Estimate Item Adjustment (0002) due to user sandis1 overriddin Estimate Exception 5 on the current Payment Estimate. 3 Jan 17, 2023 SYSTEM (\$107,728.81) • • • • • • • • • • • • • • • • • • •			(\$107,728.81)	SYSTEM		2				
Image: Constraint of the constraint		This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0002) due to user sandis1 overridding Estimate Exception 5 on the current Payment Estimate.	\$107,728.81	SYSTEM		3				
Material - Total \$0.00 \$0.00 0020 - Total \$0.00 0030 MISC. HIGHWAY LIGHTING Material Nov 2, 2022 SYSTEM \$26,077.50 This adjustment offsets the original system-generated Material F Estimate Item Adjustment (0003) due to user weathc1 overriddin Estimate Exception 3 on the current Payment Estimate. 1 Nov 2, 2022 SYSTEM \$26,077.50 This adjustment offsets the original system-generated Material F Estimate Exception 3 on the current Payment Estimate. 2 Dec 2, 2022 SYSTEM \$30,637.50 This adjustment offsets the original system-generated Material F Estimate Item Adjustment (0003) due to user weathc1 overriddin Estimate Exception 3 on the current Payment Estimate. 2 Dec 2, 2022 SYSTEM \$30,637.50 This adjustment offsets the original system-generated Material F Estimate Exception 3 on the current Payment Estimate. 3 Jan 17, SYSTEM \$30,637.50 This adjustment offsets the original system-generated Material F Estimate Item Adjustment (0003) due to user sandis1 overriddin Estimate Item Adjustment (0003) due to user sandis1 overriddin			(\$107,728.81)	SYSTEM		3				
O020 - Total \$0.00 0030 MISC. HIGHWAY LIGHTING Material 1 Nov 2, 2022 SYSTEM \$26,077.50 This adjustment offsets the original system-generated Material F Estimate Item Adjustment (0003) due to user weathc1 overridding Estimate Exception 3 on the current Payment Estimate. 1 Nov 2, 2022 SYSTEM (\$26,077.50) 2 Dec 2, 2022 SYSTEM (\$26,077.50) 2 Dec 2, 2022 SYSTEM \$30,637.50) This adjustment offsets the original system-generated Material F Estimate Exception 3 on the current Payment Estimate. 2 Dec 2, 2022 SYSTEM \$30,637.50) This adjustment offsets the original system-generated Material F Estimate Exception 3 on the current Payment Estimate. 3 Jan 17, SYSTEM \$30,637.50) This adjustment offsets the original system-generated Material F Estimate Item Adjustment (0003) due to user sandis1 overridding Estimate Exception 3 on the current Payment Estimate.			\$0.00				- Total			
0030 MISC. HIGHWAY LIGHTING Material HIGHWAY IGHTING Material I Nov 2, 2022 SYSTEM \$26,077.50 This adjustment offsets the original system-generated Material F Estimate Item Adjustment (0003) due to user weathc1 overriddin Estimate Exception 3 on the current Payment Estimate. 1 Nov 2, 2022 SYSTEM (\$26,077.50) This adjustment offsets the original system-generated Material F Estimate Item Adjustment (0003) due to user weathc1 overriddin Estimate Item Adjustment (0003) due to user weathc1 overriddin Estimate Item Adjustment (0003) due to user weathc1 overriddin Estimate Exception 3 on the current Payment Estimate. 2 Dec 2, 2022 SYSTEM \$30,637.50 This adjustment offsets the original system-generated Material F Estimate Exception 3 on the current Payment Estimate. 3 Jan 17, 2023 SYSTEM \$30,637.50 This adjustment offsets the original system-generated Material F Estimate Item Adjustment (0003) due to user sandis1 overriddin Estimate Item Adjustment (0003) due to user sandis1 overriddin			\$0.00				otal	Material - To		
HIGHWAY LIGHTING HIGHWAY LIGHTING 2022 2022 SYSTEM Estimate Item Adjustment (0003) due to user weathc1 overriddir Estimate Exception 3 on the current Payment Estimate. 1 Nov 2, 2022 SYSTEM (\$26,077.50) 2 Dec 2, 2022 SYSTEM \$30,637.50 This adjustment offsets the original system-generated Material F Estimate Item Adjustment (0003) due to user weathc1 overriddir Estimate Exception 3 on the current Payment Estimate. 2 Dec 2, 2022 SYSTEM (\$30,637.50) 3 Jan 17, 2023 SYSTEM \$30,637.50 This adjustment offsets the original system-generated Material F Estimate Item Adjustment (0003) due to user sandis1 overriddir			\$0.00		_				Total	0020 -
2022 2023 2023 2023 2023 2023 2023 2023 2023 2023 2024 2023 2024 2023 2024	rial Payment ridding Payment	This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0003) due to user weathc1 overridding Estimate Exception 3 on the current Payment Estimate.	\$26,077.50	SYSTEM		1		Material	HIGHWAY	0030
2022 Estimate Item Adjustment (0003) due to user weathc1 overriddir Estimate Exception 3 on the current Payment Estimate. 2 Dec 2, 2022 SYSTEM (\$30,637.50) 3 Jan 17, 2023 SYSTEM \$30,637.50 This adjustment offsets the original system-generated Material Festimate Item Adjustment (0003) due to user sandis1 overriddin			(\$26,077.50)	SYSTEM		1				
2022 3 Jan 17, 2023 SYSTEM \$30,637.50 This adjustment offsets the original system-generated Material F Estimate Item Adjustment (0003) due to user sandis1 overriddin		This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0003) due to user weathc1 overridding Estimate Exception 3 on the current Payment Estimate.	\$30,637.50	SYSTEM		2				
2023 Estimate Item Adjustment (0003) due to user sandis1 overriddin			(\$30,637.50)	SYSTEM		2				
		This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0003) due to user sandis1 overridding Estimate Exception 6 on the current Payment Estimate.	\$30,637.50	SYSTEM		3				
3 Jan 17, SYSTEM (\$30,637.50) 2023				SYSTEM		3				
- Total \$0.00			\$0.00				- Total			
Material - Total \$0.00			\$0.00				otal	Material - To		
0030 - Total \$0.00			\$0.00						Total	0030 -
		This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0004) due to user sandis1 overridding Estimate Exception 1 on the current Payment Estimate.	\$1,223.52	SYSTEM		3		Material	HIGHWAY	5001
3 Jan 17, 2023 SYSTEM (\$1,223.52)			(\$1,223.52)	SYSTEM		3				
- Total \$0.00			\$0.00				- Total			
			\$0.00				otal	Material - To		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
4P3271	5001 -	Total						\$0.00	
	5002	MISC. HIGHWAY LIGHTING	Material		3	Jan 17, 2023	SYSTEM	\$123.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sandis1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Jan 17, 2023	SYSTEM	(\$123.41)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5002 -	Total						\$0.00	
	5003	MISC. HIGHWAY LIGHTING	Material		3	Jan 17, 2023	SYSTEM	\$1,350.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sandis1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Jan 17, 2023	SYSTEM	(\$1,350.56)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5003 -	Total						\$0.00	
	5004	MISC. HIGHWAY LIGHTING	Material		5	May 16, 2023	SYSTEM	\$464.74	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	May 16, 2023	SYSTEM	(\$464.74)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5004 -	Total						\$0.00	
	5005	MISC. HIGHWAY LIGHTING	Material		5	May 16, 2023	SYSTEM	\$990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user yostj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	May 16, 2023	SYSTEM	(\$990.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5005 -	Total						\$0.00	
	5006	MISC. HIGHWAY LIGHTING	Material		5	May 16, 2023	SYSTEM	\$630.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user yostj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	May 16, 2023	SYSTEM	(\$630.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5006 -	Total						\$0.00	
	5007	MISC. HIGHWAY LIGHTING	Material		5	May 16, 2023	SYSTEM	\$882.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user yostj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	May 16, 2023	SYSTEM	(\$882.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5007 -	Total						\$0.00	
	5015	MISC. HIGHWAY LIGHTING	Material		13	Jan 3, 2024	SYSTEM	\$79.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					13	Jan 3, 2024	SYSTEM	(\$79.20)	
					14	Feb 2, 2024	SYSTEM	\$79.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					14	Feb 2,	SYSTEM	(\$79.20)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
I4P3271	5015	MISC. HIGHWAY LIGHTING	Material			2024			
					15	Mar 19, 2024	SYSTEM	\$79.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					15	Mar 19, 2024	SYSTEM	(\$79.20)	
					16	May 2, 2024	SYSTEM	\$79.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sandis1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					16	May 1, 2024	SYSTEM	(\$79.20)	
					17	May 16, 2024	SYSTEM	\$79.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sandis1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					17	May 16, 2024	SYSTEM	(\$79.20)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5015 -	Total						\$0.00	
	5016	MISC. HIGHWAY LIGHTING	Material		13	Jan 3, 2024	SYSTEM	\$756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Jan 3, 2024	SYSTEM	(\$756.00)	
					14	Feb 2, 2024	SYSTEM	\$756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Feb 2, 2024	SYSTEM	(\$756.00)	
					15	Mar 19, 2024	SYSTEM	\$756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Mar 19, 2024	SYSTEM	(\$756.00)	
					16	May 2, 2024	SYSTEM	\$756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sandis1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					16	May 1, 2024	SYSTEM	(\$756.00)	
					17	May 16, 2024	SYSTEM	\$756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sandis1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					17	May 16, 2024	SYSTEM	(\$756.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5016 -	Total						\$0.00	
	5017	7 MISC. HIGHWAY LIGHTING	Material		13	Jan 3, 2024	SYSTEM	\$198.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user yostj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Jan 3, 2024	SYSTEM	(\$198.00)	
					14	Feb 2, 2024	SYSTEM	\$198.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user yostj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Feb 2, 2024	SYSTEM	(\$198.00)	
					15	Mar 19, 2024	SYSTEM	\$198.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user yostj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					15	Mar 19, 2024	SYSTEM	(\$198.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3271	5017	MISC. HIGHWAY LIGHTING	Material		16	May 2, 2024	SYSTEM	\$198.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sandis1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					16	May 1, 2024	SYSTEM	(\$198.00)	
					17	May 16, 2024	SYSTEM	\$198.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sandis1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					17	May 16, 2024	SYSTEM	(\$198.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5017 -	- Total						\$0.00	
	5018	MISC. HIGHWAY LIGHTING	Material		13	Jan 3, 2024	SYSTEM	\$792.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user yostj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	Jan 3, 2024	SYSTEM	(\$792.00)	
					14	Feb 2, 2024	SYSTEM	\$792.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user yostj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Feb 2, 2024	SYSTEM	(\$792.00)	
					15	Mar 19, 2024	SYSTEM	\$792.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user yostj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					15	Mar 19, 2024	SYSTEM	(\$792.00)	
					16	May 2, 2024	SYSTEM	\$792.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandis1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					16	May 1, 2024	SYSTEM	(\$792.00)	
					17	May 16, 2024	SYSTEM	\$792.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandis1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					17	May 16, 2024	SYSTEM	(\$792.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5018 -	- Total						\$0.00	
	5019	MISC. HIGHWAY LIGHTING	Material		13	Jan 3, 2024	SYSTEM	\$225.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user yostj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					13	Jan 3, 2024	SYSTEM	(\$225.00)	
					14	Feb 2, 2024	SYSTEM	\$225.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user yostj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					14	Feb 2, 2024	SYSTEM	(\$225.00)	
					15	Mar 19, 2024	SYSTEM	\$225.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user yostj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					15	Mar 19, 2024	SYSTEM	(\$225.00)	
					16	May 2, 2024	SYSTEM	\$225.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user sandis1 overridding Payment
									Estimate Exception 4 on the current Payment Estimate.
					16	May 1, 2024	SYSTEM	(\$225.00)	Estimate Exception 4 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J4P3271	5019	MISC. HIGHWAY LIGHTING	Material	Туре		2024			Estimate Item Adjustment (0004) due to user sandis1 overridding Payment
					17	May 40	SYSTEM	(\$225.00)	Estimate Exception 4 on the current Payment Estimate.
					17	May 16, 2024	STSTEIN	(\$225.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5019 -	Total	_					\$0.00	
	5020	MISC. HIGHWAY LIGHTING	Material		13	Jan 3, 2024	SYSTEM	\$484.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user yostj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					13	Jan 3, 2024	SYSTEM	(\$484.65)	
					14	Feb 2, 2024	SYSTEM	\$484.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user yostj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					14	Feb 2, 2024	SYSTEM	(\$484.65)	
					15	Mar 19, 2024	SYSTEM	\$484.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user yostj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					15	Mar 19, 2024	SYSTEM	(\$484.65)	
					16	May 2, 2024	SYSTEM	\$484.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sandis1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					16	May 1, 2024	SYSTEM	(\$484.65)	
					17	May 16, 2024	SYSTEM	\$484.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sandis1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					17	May 16, 2024	SYSTEM	(\$484.65)	
			- Total					\$0.00	
			Material - Total					\$0.00	
	5020 -	Total						\$0.00	
J4P3271	- Total							\$0.00	
Overall -	Total							\$0.00	



There are no contract adjustments to display for this contract.