

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 17, 2023

Progress Estimate Number	Contract ID	220520-C07	Pay Period Start	December 2, 2022	Original Contract Amount	\$1,738,800.00
3	Prime Contractor	Custom Lighting Services, LLC dba Black	Pay Period En	<b>nd</b> January 15, 202	<sup>3</sup> Net Change Order Amount	\$2,697.49
					Current Contract Amount	\$1,741,497.49

Approval Date					By User		
January 17, 2023		Generated and	Approved (and should be considere	d Draft) at the Project Office Level by	sandis1		
January 17, 2023		Reviewed and Appr	oved (and should be considered Dra	aft) at the Resident Engineer Level by	r Level by sandis1		
January 18, 2023			Reviewed and Approved at the Cen	tral Office Controllers Office Level by	ramses1		
Original Comp	riginal Completion Date Current Completion Date Actual Completion Date % of Current Contract						
May 31,	2023	May 31, 2024		13.79%			

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	June 2, 2022	June 2, 2022	
Letting Date	May 20, 2022	May 20, 2022	
Notice to Proceed Date	June 6, 2022	June 6, 2022	
Open to Traffic Date			
Work Began Date			

Contract Total P	ay For Estimate No. 3				
		This Estimate	Previous	To Date	
220520-C07					
	Total Posted Items Pay	\$2,697.49	\$237,411.74	\$240,109.23	
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$237,411.74	\$240,109.23	
Contract Total P	avable This Estimate:	\$2 697 49			

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4P3271	5001	9019901	MISC.WORK ORDER NUMBER 3634510	LS	\$1,223.520	1	\$1,223.52
	5002	9019901	MISC.WORK ORDER NUMBER 3689704	LS	\$123.410	1	\$123.41
	5003	9019901	MISC.WORK ORDER NUMBER 3684769	LS	\$1,350.560	1	\$1,350.56
Project J4P3271	- Total						\$2,697.49
Overall - Total							\$2,697.49

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3271	0010	MISC.	Material			-87,884.16	\$1.13	(\$99,045.45)
	0010	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user sandis1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	87,884.16	\$1.13	\$99,045.45
	0020	MISC.	Material			-58,868.2	\$1.83	(\$107,728.81)
	0020	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user sandis1 overridding Payment Estimate Exception 5 on	58,868.2	\$1.83	\$107,728.81

Revision 4/1/2020 Page 1 of 8



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 17, 2023

Progress Estimate Number	Contract ID	220520-C07	Pay Period Start	December 2, 2022	Original Contract Amount	\$1,738,800.00
3	Prime Contractor	Custom Lighting Services, LLC dba Black	Pay Period Er	<b>nd</b> January 15, 202	Net Change Order Amount	\$2,697.49
					Current Contract Amount	\$1,741,497.49

						Amount		
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3271					the current Payment Estimate.			
	0030	MISC.	Material			-10,750	\$2.85	(\$30,637.50)
	0030	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user sandis1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	10,750	\$2.85	\$30,637.50
	5001	MISC.	Material			-1	\$1,223.52	(\$1,223.52)
	5001	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user sandis1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1	\$1,223.52	\$1,223.52
	5002	MISC.	Material			-1	\$123.41	(\$123.41)
	5002	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user sandis1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	1	\$123.41	\$123.41
	5003	MISC.	Material			-1	\$1,350.56	(\$1,350.56)
	5003	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user sandis1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1	\$1,350.56	\$1,350.56
Total								\$0.00

Revision 4/1/2020 Page 2 of 8



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	ı
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4P3271		Job Order Contract for lighting repair	Various	VARIOUS	at various locations in the	e Kansas City District	
Totals by .	Job Numb	ers					
J4P3271					This Estimate	Previous	To Date
		ed Item Pay			\$2,697.49	\$237,411.74	\$240,109.23
	Gros	s Item Adjustn			\$0.00	\$0.00	\$0.00
			Gross	Item Pay	\$2,697.49	\$237,411.74	\$240,109.23
	Incer	ntive			\$0.00	\$0.00	\$0.00
	Disir	centive			\$0.00	\$0.00	\$0.00
	Liqui	idated Damage	s		\$0.00	\$0.00	\$0.00
	Othe	r Contract Adia	intmonto		\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 3 of 8



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3271, Item 9019901, Project Item Line Number 5001, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with the Contractor and MoDOT Materials staff to resolve exception.	sandis1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3271, Item 9019901, Project Item Line Number 002, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with the Contractor and MoDOT Materials staff to resolve exception.	sandis1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3271, Item 9019901, Project Item Line Number 5003, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with the Contractor and MoDOT Materials staff to resolve exception.	sandis1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3271, Item 9019902, Project Item Line Number 0010, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with the Contractor and MoDOT Materials staff to resolve exception.	sandis1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3271, Item 9019902, Project Item Line Number 0020, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with the Contractor and MoDOT Materials staff to resolve exception.	sandis1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3271, Item 9019902, Project Item Line Number 0030, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with the Contractor and MoDOT Materials staff to resolve exception.	sandis1	Overridden

Revision 4/1/2020 Page 4 of 8



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220520-C07	J4P3271	0020	0010	9019902	MISC.LABOR/EQUIPMENT FOR TROUBLE SHOOTING/INVESTIGATION/REPAIR WORK ADJUSTMENT FACTOR	720,000.00	0.00	720,000.00	EA	87,884.16	\$1.13	\$99,045.45
		0020	0020	9019902	MISC.MATERIAL FOR REPAIR WORK ADJUSTMENT FACTOR	432,000.00	0.00	432,000.00	EA	58,868.20	\$1.83	\$107,728.81
		0020	0030	9019902	MISC.TRAFFIC CONTROL ADJUSTMENT FACTOR	48,000.00	0.00	48,000.00	EA	10,750.00	\$2.85	\$30,637.50
		0020	5001	9019901	MISC.WORK ORDER NUMBER 3634510	0.00	1.00	1.00	LS	1.00	\$1,223.52	\$1,223.52
		0020	5002	9019901	MISC.WORK ORDER NUMBER 3689704	0.00	1.00	1.00	LS	1.00	\$123.41	\$123.41
		0020	5003	9019901	MISC.WORK ORDER NUMBER 3684769	0.00	1.00	1.00	LS	1.00	\$1,350.56	\$1,350.56
		0020	9000	6189916	MISC.Liquidated Damages	0.00			DLR		(\$1.00)	
		0020	9100	6189916	MISC.Additional Items	0.00			DLR	0.00	\$1.00	\$0.00
	Project J	4P3271 - To	tal Value	Posted to	Date as of Report Generated Date							\$240,109.24
220520-C07 Ove	rall - Total	Value Post	ted to Dat	te as of Rep	port Generated Date							\$240,109.24

Revision 4/1/2020 Page 5 of 8



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: J4P3271

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
5001	9019901	MISC. HIGHWAY LIGHTING	1/13/23	1/17/23	1.00	LS		0		0		76-1354986, WO3634510, Front St. & 435 Hwy
5002	9019901	MISC. HIGHWAY LIGHTING	1/13/23	1/17/23	1.00	LS		0		0		76-1355003, WO3689704, I-435 & Front St.
5003	9019901	MISC. HIGHWAY LIGHTING	1/13/23	1/17/23	1.00	LS	K22C6823	0		0		76-1364257, WO3684769, I-70 from I-435 to Jackson Curve

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 6 of 8



## Line Item Adjustments by Estimate

Contract ID: 220520-C07

				_		_			_
ject	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
			.,,,,,	Туре			_,		
271	0010	MISC. HIGHWAY LIGHTING	Material		1	Nov 2, 2022	SYSTEM	\$77,415.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Nov 2, 2022	SYSTEM	(\$77,415.88)	
					2	Dec 2, 2022	SYSTEM	\$99,045.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Dec 2, 2022	SYSTEM	(\$99,045.45)	
					3	Jan 17, 2023	SYSTEM	\$99,045.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sandis1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Jan 17, 2023	SYSTEM	(\$99,045.45)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0010 - Total							\$0.00	
0	0020	MISC. HIGHWAY LIGHTING	Material		1	Nov 2, 2022	SYSTEM	\$85,116.59	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Nov 2, 2022	SYSTEM	(\$85,116.59)	
					2	Dec 2, 2022	SYSTEM	\$107,728.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Dec 2, 2022	SYSTEM	(\$107,728.81)	
					3	Jan 17, 2023	SYSTEM	\$107,728.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sandis1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Jan 17, 2023	SYSTEM	(\$107,728.81)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0020 -	Total						\$0.00	
0030	0030	MISC. HIGHWAY LIGHTING	Material		1	Nov 2, 2022	SYSTEM	\$26,077.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Nov 2, 2022	SYSTEM	(\$26,077.50)	
					2	Dec 2, 2022	SYSTEM	\$30,637.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Dec 2, 2022	SYSTEM	(\$30,637.50)	
					3	Jan 17, 2023	SYSTEM	\$30,637.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandis1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	Jan 17, 2023	SYSTEM	(\$30,637.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0030 -	Total						\$0.00	
	5001	MISC. HIGHWAY LIGHTING	Material		3	Jan 17, 2023	SYSTEM	\$1,223.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user sandis1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Jan 17, 2023	SYSTEM	(\$1,223.52)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	





## Line Item Adjustments by Estimate

Contract ID: 220520-C07

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3271	5001 - Total							\$0.00	
	5002	MISC. HIGHWAY LIGHTING	Material		3	Jan 17, 2023	SYSTEM	\$123.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sandis1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Jan 17, 2023	SYSTEM	(\$123.41)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5002 - Total							\$0.00	
	5003	MISC. HIGHWAY LIGHTING	Material		3	Jan 17, 2023	SYSTEM	\$1,350.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sandis1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Jan 17, 2023	SYSTEM	(\$1,350.56)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5003 -	Total						\$0.00	
J4P3271	- Total							\$0.00	
Overall - Total								\$0.00	