

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 16, 2022

	Progress Estimate Number	Contract ID	220715-D01	Pay Period Start	November 2, 2022	Original Contract Amount	\$690,823.20
	5	Prime Contractor	H.R. Quadri Contractors, LLC	Pay Period End	November 15, 2022		
	· ·					Current Contract Amount	\$690,823.20
H							

Approval Date		By User
November 16, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	snells1
November 16, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	grahac1
November 17, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
April 28, 2023	April 28, 2023		95.11%

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	August 3, 2022	August 3, 2022	
Letting Date	July 15, 2022	July 15, 2022	
Notice to Proceed Date	September 6, 2022	September 6, 2022	
Open to Traffic Date			
Work Began Date			

Contract Total P	ay For Estimate No. 5				
		This Estimate	Previous	To Date	
220715-D01					
	Total Posted Items Pay	\$8,709.00	\$648,353.20	\$657,062.20	
	Gross Item Adjustments	(\$3,965.00)	(\$5,982.25)	(\$9,947.25)	
	Incentive	\$0.00	\$50,000.00	\$50,000.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$692,370.95	\$697,114.95	
Contract Total Pa	avable This Estimate:	\$4 744 00			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
JCD0046	0030	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$10.000	12	\$120.00
	0050	5021310	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. JOINTS)	SQYD	\$100.000	30.4	\$3,040.00
	0090	6085008	PAVED APPROACH, 8 IN.	SQYD	\$100.000	0.1	\$10.00
	0160	6161025	CHANNELIZER (TRIM LINE)	EA	\$15.000	53	\$795.00
	0280	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	EA	\$1,250.000	-1	(\$1,250.00)
	0320	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$6.000	-1	(\$6.00)
	0350	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$6,000.000	1	\$6,000.00
Project JCI	00046 - Tot	al					\$8,709.00
Overall - To	otal						\$8,709.00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item A	ne Item Adjustments This Estimate												
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount					
JCD0046	0030	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)				-12	\$10.00	(\$120.00)					

Revision 4/1/2020 Page 1 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 16, 2022

Progress Estimate Number Contract ID 220715-D01 Pay Period Start November 2, 2022 Original Contract Amount \$690,823.20 Prime Contractor H.R. Quadri Contractors, LLC Pay Period End November 15, 2022 Net Change Order Amount \$0.00 Current Contract Amount \$690,823.20

oject Imber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
D0046	0030	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-250	\$10.00	(\$2,500.00
	0030	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	250	\$10.00	\$2,500.00
	0050	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. JOINTS)	Overrun			-30.4	\$100.00	(\$3,040.00
	0050	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. JOINTS)	Material			-2,369.2	\$100.00	(\$236,920.00
	0050	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user snells1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	2,369.2	\$100.00	\$236,920.00
	0060	CONCRETE CURB RAMP	Material			-78.1	\$125.00	(\$9,762.50
	0060	CONCRETE CURB RAMP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	78.1	\$125.00	\$9,762.50
	0070	TRUNCATED DOMES	Material			-60	\$50.00	(\$3,000.00
	0070	TRUNCATED DOMES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	60	\$50.00	\$3,000.00
	0800	6 IN. CONCRETE MEDIAN STRIP	Material			-42.7	\$100.00	(\$4,270.00
	0080	6 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	42.7	\$100.00	\$4,270.00
	0090	PAVED APPROACH, 8 IN.	Overrun			-0.1	\$100.00	(\$10.00
	0090	PAVED APPROACH, 8 IN.	Material			-171.6	\$100.00	(\$17,160.00
	0090	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user snells1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	171.6	\$100.00	\$17,160.00
	0100	CURB AND GUTTER TYPE B	Material			-140	\$50.00	(\$7,000.00
	0100	CURB AND GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	140	\$50.00	\$7,000.00
	0160	CHANNELIZER (TRIM LINE)	Overrun			-53	\$15.00	(\$795.00
	0400	MISC.	Material			-1	\$1.00	(\$1.00
	0400	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user snells1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	1	\$1.00	\$1.00
	0410	MISC.	Material			-1	\$34,550.00	(\$34,550.00)

Revision 4/1/2020 Page 2 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 16, 2022

Progre	ss Esti	mate Number	Contract ID Prime Contra	220715-l ctor H.R. Qua	 Pay Period Start November 2, 2022 Original Contract Amount \$690,823.20 tors, LLC Pay Period End November 15, 2022 Net Change Order Amount \$0.00 Current Contract Amount \$690,823.20					
Project Number	Line No.	Item De	Item Description		Item Description Adjustment Type Other Item Adjustment Type Type		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
JCD0046	0410		MISC.	Material	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	1	\$34,550.00	\$34,550.00		
	0430	2.5 IN. PSST	POST - 12 GA.	Material		-28	\$30.00	(\$840.00)		
	0430	2.5 IN. PSST	POST - 12 GA.	Material	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user snells1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	28	\$30.00	\$840.00		
Total								(\$3,965.00		

Revision 4/1/2020 Page 3 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
JCD0046	FAF-5-2(38)	Pavement replacement	5	LACLEDE	from Commercial St to	Pierce St in Lebanon	
Totals by J	Job Numbers						
JCD0046					This Estimate	Previous	To Date
	Posted It	em Pay			\$8,709.00	\$648,353.20	\$657,062.20
	Gross Item Adjustments				(\$3,965.00)	(\$5,982.25)	(\$9,947.25)
		iii Aujustiiieiit					
	Gross ite		Gross Ite	m Pay	\$4,744.00	\$642,370.95	\$647,114.95
	Incentive	- (m Pay		i i	\$647,114.95
				m Pay	\$4,744.00 \$0.00 \$0.00	\$642,370.95 \$50,000.00 \$0.00	
	Incentive Disincent			em Pay	\$0.00	\$50,000.00	\$64 7,114.95 \$50,000.00

Revision 4/1/2020 Page 4 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 3040504, Project Item Line Number 0030, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Working with District Materials to resolve exception.	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 3040504, Project Item Line Number 0030, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with District Materials to resolve exception	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 5021310, Project Item Line Number 0050, Material Set 502131096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	This is a concrete item and final testing has not been completed.	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 5021310, Project Item Line Number 0050, Material Set 502131096, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	This is a concrete item and final testing has not been completed.	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 5021310, Project Item Line Number 0050, Material Set 502131096, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	This is a concrete item and final testing has not been completed.	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 5021310, Project Item Line Number 0050, Material Set 502131096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	This is a concrete item and final testing has not been completed.	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 5021310, Project Item Line Number 0050, Material Set 502131096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	This is a concrete item and final testing has not been completed.	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 6081010, Project Item Line Number 0060, Material Set 608101096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	This is a concrete item and final testing has not been completed.	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 6081012, Project Item Line Number 0070, Material Set 608101296, Material 1067TRDO - Truncated Domes for ADA, Acceptance Action Generic 1067TRDO is insufficient.	Working with the contractor to gather required information to resolve exception	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 6083006, Project Item Line Number 0080, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	This is a concrete item and final testing has not been completed.	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 6085008, Project Item Line Number 0090, Material Set 608500896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	This is a concrete item and final testing has not been completed.	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 6085008, Project Item Line Number 0090, Material Set 608500896, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	This is a concrete item and final testing has not been completed.	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 6085008, Project Item Line Number 0090, Material Set 608500896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	This is a concrete item and final testing has not been completed.	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 6085008, Project Item Line Number 0090, Material Set 608500896, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	This is a concrete item and final testing has not been completed.	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 6091052, Project Item Line Number 0100, Material Set 609105296, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	This is a concrete item and final testing has not been completed.	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 9029901, Project Item Line Number 0400, Material Set 9029901, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with District Materials to resolve exception	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 9029902, Project Item Line Number 0410, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with the contractor to gather the required information to resolve exception.	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0046, Item 9031280, Project Item Line Number 0430, Material Set 903128096, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Working with the contractor to gather the required information to resolve exception	snells1	Overridden
Estimate Exception Type: Item Overrun: Contract 220715-D01, Contract Project JCD0046, Project Item Line Number 0050, Contract Line Item Number 0050, Item 5021310, Minor Item.	A Change Order has been drafted and sent to the contractor for signature.	snells1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220715-D01, Contract Project JCD0046, Project Item Line Number 0090, Contract Line Item Number 0090, Item 6085008, Minor Item.	A Change Order has been drafted and sent to the contractor for signature.	snells1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220715-D01, Contract Project JCD0046, Project Item Line Number 0160, Contract Line Item Number 0160, Item 6161025, Minor Item.	A Change Order has been drafted and sent to the contractor for signature.	snells1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220715-D01, Contract Project JCD0046, Project Item Line Number 0140, Contract Line Item Number 0140, Item 6161005, Minor Item.	A Change Order has been drafted and sent to the contractor for signature.	snells1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220715-D01, Contract Project JCD0046, Project Item Line Number 0170, Contract Line Item Number 0170, Item 6161030, Minor Item.	A Change Order has been drafted and sent to the contractor for signature.	snells1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220715-D01, Contract Project JCD0046, Project Item Line Number 0290, Contract Line Item Number 0290, Item 6205301B, Minor Item.	A Change Order has been drafted and sent to the contractor for signature.	snells1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220715-D01, Contract Project JCD0046, Project Item Line Number 0300, Contract Line Item Number 0300, Item 6205303B, Minor Item.	A Change Order has been drafted and sent to the contractor for signature.	snells1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220715-D01, Contract Project JCD0046, Project Item Line Number 0030, Contract Line Item Number 0030, Item 3040504, Minor Item.	A Change Order has been drafted and sent to the contractor for signature.	snells1	Acknowledged

Revision 4/1/2020 Page 5 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
20715-D01	JCD0046	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	•	\$154,800.00	\$154,800.0
		0001	0020	2071000	LINEAR GRADING CLASS 1	1.40	0.00	1.40	STA	1.40	\$1,000.00	\$1,400.0
		0001	0030	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	238.00	0.00	238.00	SQYD	250.00	\$10.00	\$2,500.0
		0001	0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	2,379.00	0.00	2,379.00	SQYD	0.00	\$12.00	\$0.0
		0001	0050	5021310	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. JOINTS)	2,331.30	0.00	2,331.30	SQYD	2,369.20	\$100.00	\$236,920.0
		0001	0060	6081010	CONCRETE CURB RAMP	78.10	0.00	78.10	SQYD	78.10	\$125.00	\$9,762.5
		0001	0070	6081012	TRUNCATED DOMES	60.00	0.00	60.00	SQFT	60.00	\$50.00	\$3,000.0
		0001	0800	6083006	6 IN. CONCRETE MEDIAN STRIP	42.70	0.00	42.70	SQYD	42.70	\$100.00	\$4,270.0
		0001	0090	6085008	PAVED APPROACH, 8 IN.	159.80	0.00	159.80	SQYD	171.60	\$100.00	\$17,160.0
		0001	0100	6091052	CURB AND GUTTER TYPE B	140.00	0.00	140.00	LF	140.00	\$50.00	\$7,000.0
		0001	0110	6122008	IMPACT ATTENUATOR 40 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	0.00	\$2,850.00	\$0.0
		0001	0120	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	2.00	\$1,250.00	\$2,500.0
		0001	0130	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	2,331.00	0.00	2,331.00	SQYD	2,331.00	\$1.00	\$2,331.0
		0001	0140	6161005	CONSTRUCTION SIGNS	865.00	0.00	865.00	SQFT	874.00	\$7.00	\$6,118.0
		0001	0150	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	2.00	\$100.00	\$200.0
		0001	0160	6161025	CHANNELIZER (TRIM LINE)	47.00	0.00	47.00	EA	100.00	\$15.00	\$1,500.0
		0001	0170	6161030	TYPE III MOVEABLE BARRICADE	20.00	0.00	20.00	EA	27.00	\$175.00	\$4,725.0
		0001	0180	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000.
		0001	0190	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	5.00	0.00	5.00	EA	5.00	\$3,500.00	\$17,500.0
		0001	0200	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	352.00	0.00	352.00	LF	352.00	\$22.00	\$7,744.
		0001	0210	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	725.00	0.00	725.00	LF	725.00	\$28.00	\$20,300.
		0001	0220	6174000A	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.
		0001	0230	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	1,077.00	0.00	1,077.00	LF	1,077.00	\$10.00	\$10,770.
		0001	0240	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$66,200.00	\$66,200
		0001	0250	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	114.00	0.00	114.00	LF	114.00	\$22.50	\$2,565.
		0001	0260	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	2.00	0.00	2.00	EA	2.00	\$325.00	\$650.
		0001	0270	6200031	COLD APPLIED TAPE PAVEMENT MARKING, R/R CROSSING MARKER	6.00	0.00	6.00	EA	2.00	\$525.00	\$1,050.
		0001	0280	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	4.00	0.00	4.00	EA	3.00	\$1,250.00	\$3,750.
		0001	0290	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	890.00	0.00	890.00	LF	1,579.00	\$2.25	\$3,552.
		0001	0300	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	3,072.00	0.00	3,072.00	LF	3,616.00	\$2.25	\$8,136.
		0001	0310	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT. TYPE L BEADS	1,767.00	0.00	1,767.00	LF	1,767.00	\$2.25	\$3,975.
		0001	0320	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	926.00	0.00	926.00	LF	706.00	\$6.00	\$4,236.
		0001	0330	6207001	PAVEMENT MARKING REMOVAL	1,609.00	0.00	1,609.00	LF	1,112.00	\$2.75	\$3,058.
		0001	0340	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	7.00	0.00	7.00	EA	2.00	\$300.00	\$600.
		0001	0350	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$6,000.00	\$6,000.
		0001	0360	8031000A	TURF TYPE TALL FESCUE SODDING	110.00	0.00	110.00	SQYD	0.00	\$10.00	\$0.
		0001	0370	8061007A	CURB INLET CHECK	9.00	0.00	9.00	EA	0.00	\$50.00	\$0.
		0001	0380	8061016	SEDIMENT REMOVAL	11.00	0.00	11.00	CUYD	0.00	\$1.00	\$0.
		0001	0390	8061019	SILT FENCE	145.00	0.00	145.00	LF	0.00	\$2.50	\$0.
		0001	0400	9029901	MISC.POT HOLING FOR UTILITY FACILITIES	1.00	0.00	1.00	LS	1.00	\$1.00	\$1.
		0030	0410	9029902	MISC.VIDEO DETECTION SYSTEM	1.00	0.00	1.00	EA	1.00	\$34,550.00	\$34,550.
		0040	0420	9031010	CONCRETE FOOTINGS, EMBEDDED	0.20	0.00	0.20	CUYD	0.20	\$3,900.00	\$780.0
		0040	0430	9031280	2.5 IN. PSST POST - 12 GA.	28.00	0.00	28.00	LF	28.00	\$30.00	\$840.

Revision 4/1/2020 Page 6 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

140to. 1 ootou Q	uuniiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiii	ana valac	o are b	acca on re	sport contrated date and earl affer from the posted affer	ant at the	o unito une	Louinate W	uo con	oratoa.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220715-D01	JCD0046	0040	0440	9031285	CONCRETE POST ANCHOR FOR 2.5 IN. PSST 7 GA.	2.00	0.00	2.00	EA	2.00	\$490.00	\$980.00
		0040	0450	9035004A	SH-FLAT SHEET	18.00	0.00	18.00	SQFT	18.00	\$35.40	\$637.20
Project JCD0046 - Total Value Posted to Date as of Report Generated Date											\$657,062.20	
220715-D01 Overall - Total Value Posted to Date as of Report Generated Date										\$657,062.20		

Revision 4/1/2020 Page 7 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: JCD0046

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0030	3040504	TYPE 5 AGGREGATE FOR BASE	11/4/22	11/16/22	12.00	SQYD	Entrances Rt. and Lt. = Plan Qty. after Change Order	851+50.19		851+53.79		
0050	5021310	CONCRETE PAVEMENT (10 IN. NON-REINFORCED	11/4/22	11/16/22	30.40	SQYD	Jefferson Street rt. / It. Plan Qty. after Change Order					
0090	6085008	PAVED APPROACH, 8 IN.	11/4/22	11/16/22	0.10	SQYD	Plan Qty. after Change Order					
0160	6161025	CHANNELIZER (TRIM LINE)	11/4/22	11/16/22	53.00	EA	Plan Qty. after Change Order					
0280	6200033	PREF THERMO PVMT MARK, R/R XING	11/3/22	11/16/22	-1.00	EA	NB Route 5 Driving Lane. existing RR Crossing was still in good shape and was not disturbed during construction.					
0320	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	11/4/22	11/16/22	-1.00	LF	Plan Qty. after Change Order					
0350	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	11/4/22	11/16/22	1.00	LS	Project Limits.					

The information	h = = 4h ! =	1:	detelle f.	 Signs (if applicable)	

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to
CD0046		October 26, 2022	555	Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		0.250 EB - 0.893 WB	N. Adams Ave.	19.50	1.00	Commercial St. Closed at Jefferson St. (78x36)	19.50	19.
		2022		R11-2 48x30 10.00 ROAD CLOSED		250.592	Sb Route 5 Parking lot Entrance to MFA	1.00	10.00	(76X30)		10.
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		0.360 WB - 0.857 EB	S. Madison Ave.	19.50	1.00	Commercial St. Closed at Jefferson St. (78x36)	19.50	19.
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.368 EB - 0.849 WB	N.Madison Ave @ W third St.	1.00	15.00	50G - Detour West Commercial St Straight Arrow		15.
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.397 EB - 0.796 WB	N. Adams Ave. @ W. 3rd St.	1.00	15.00	50H - Detour East Commercial St. Straight Arrow		15.
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		0.415 EB - 0167 WB	E. Commercial St.	19.50	1.00	Commercial St. Closed at Jefferson St. (78x36)	19.50	19.
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.433 EB - 0.710 WB	N. Adams Ave @ W 2nd St.	1.00	15.00	50H - Detour East Commercial St. Straight Arrow		15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.441 WB - 0.702 EB	S. Adams Ave @ E Pierce St.	1.00	15.00	50H - Detour East Commercial St. Straight Arrow		15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.458 EB - 0.759 WB	N. Madison Ave @ W Second St.	1.00	15.00	50G - Detour West Commercial St. Straight Arrow		15.
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		0.465 WB - 0.117 EB	W. Commercial St.	19.50	1.00	Commercial St. Closed at Jefferson St. (78x36)	19.50	19.
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.476 EB - 0.239 WbB	E Hayes St. @ S. Madison Ave.	1.00	15.00	50F - Detour West Commercial St. Right Arrow		15.
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.511 EB - 0.632 WB	N. Adams Ave. @ W Commercial St.	1.00	15.00	50D - Detour East Commercial St. (Arrow)		15.
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.514 WB - 0.703 EB	S. Madison Ave @ W. Pierce St.	1.00	15.00	50G - Detour West Commercial St. Straight Arrow		15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.553 EB - 0.664 WB	N. madison Ave @ Commercial St.	1.00	15.00	50E - Detour West Commercial St. Left Arrow		15.
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.582 Eb - 0.635 WB	S. Madison Ave. @ Commercial St.	1.00	15.00	50F - Detour West Commercial St. Right Arrow		15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.586 WB - 0.557 EB	S. Adams Ave. @ Commercial St.	1.00	15.00	50C - Detour east Commercial St. Left Arrow		15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.593 EB - 0.122 WB	W. Hayes St. @ S. Adams Ave.	1.00	15.00	50C - Detour East Commercial St. Left Arrow		15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.596 EB - 0.220 WB	W. fourth St @ N. Madison Ave.	1.00	15.00	50E - Detour West Commercial St. Left Arrow		15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.695 EB - 0.121 WB	W. Fourth St.	1.00	15.00	50D Detour East Commercial St. Arrow		15
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		0.786 EB - 0.357 WB	S. Adams Ave @ E Hayes St.	19.50	1.00	Commercial St. Closed at Jefferson St. (78x36)	19.50	19
				WO20-2 48x48 16.00 DETOUR AHEAD		101.825	NB Route 5 right Shoulder	1.00	16.00			16
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		101.851	NB Route 5 right Shoulder	19.50	1.00	Commercial St. Closed at Jefferson St. (78x36)	19.50	19.
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		101.915	NB Route 5 right Shoulder	33.25	1.00	50A Detour Commercial East/West (42x114)	33.25	33
				R11-2 48x30 10.00 ROAD CLOSED		102.124	NB Route 5 Choice Health Life Insurance	1.00	10.00			10
				R11-2 48x30 10.00 ROAD CLOSED		102.142	NB Route 5 Farmers Market Entrance	1.00	10.00			10.
				R11-2 48x30 10.00 ROAD CLOSED		102.180	NB Route 5 Parking Lot Entrance	1.00	10.00			10.
				R11-2 48x30 10.00 ROAD CLOSED		102.208	Commercial St @ NB Rte. 5	2.00	10.00			20.
				WO20-2 48x48 16.00 DETOUR AHEAD		250.138	SB Route 5 Right Shoulder	1.00	16.00			16.
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		250.187	SB Route 5 Right Shoulder	19.50	1.00	Commercial St. Closed at Jefferson St. (78x36)	19.50	19.
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		250.238	SB Route 5 Right Shoulder	33.25	1.00	50B Detour Commercial East/west (42x114)	33.25	33.
				R11-2 48x30 10.00 ROAD CLOSED		250.536	Commercial St @ SB Route 5	2.00	10.00			20.
				R11-2 48x30 10.00 ROAD CLOSED		250.569	SB Route 5 Entrance to Parking Lot	1.00	10.00			10.
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		0.294 EB - 0.923 WB	N Madison Ave @ W Fourth St.	19.50	1.00	Commercial St. Closed at Jefferson St. (78x36)	19.50	19.

Revision 4/1/2020 Page 8 of 14



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
ICD0046	0030	TYPE 5 AGGREGATE FOR BASE	Material		4	Nov 2, 2022	SYSTEM	\$2,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					4	Nov 2, 2022	SYSTEM	(\$2,380.00)				
					5	Nov 16, 2022	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					5	Nov 16, 2022	SYSTEM	(\$2,500.00)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
			Overrun	Overrun	5	Nov 16, 2022	SYSTEM	(\$120.00)				
				Overrun - T	otal	2022		(\$120.00)				
			Overrun - T					(\$120.00)				
	0000		Overruit - 1	Utai								
	0030 -							(\$120.00)				
	0050	CONCRETE PAVEMENT (10 IN. NON- REINFORCED	Material		2	Oct 3, 2022	SYSTEM	\$121,976.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user geldmk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
		0.1025					2	Oct 3, 2022	SYSTEM	(\$121,976.00)		
											3	Oct 17, 2022
						3	Oct 17, 2022	SYSTEM	(\$195,338.00)			
					4	Nov 2, 2022	SYSTEM	\$233,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					4	Nov 2, 2022	SYSTEM	(\$233,880.00)				
					5	Nov 16, 2022	SYSTEM	\$236,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user snells1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					5	Nov 16, 2022	SYSTEM	(\$236,920.00)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
			Overrun	Overrun	4	Nov 2, 2022	SYSTEM	(\$750.00)				
					5	Nov 16, 2022	SYSTEM	(\$3,040.00)				
				Overrun - T	otal			(\$3,790.00)				
			Overrun - To					(\$3,790.00)				
	0050 -	Total	or or or or	-				(\$3,790.00)				
	0060	CONCRETE CURB RAMP	Material		4	Nov 2, 2022	SYSTEM	\$9,762.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					4	Nov 2, 2022	SYSTEM	(\$9,762.50)				
					5	Nov 16, 2022	SYSTEM	\$9,762.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
					5	Nov 16, 2022	SYSTEM	(\$9,762.50)				
				- Total				\$0.00				
			Material - To									
			waterial - To	otal				\$0.00				
	0060 -							\$0.00				
	0070	TRUNCATED DOMES	Material		4	Nov 2, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
					4	Nov 2,	SYSTEM	(\$3,000.00)				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
JCD0046	0070	TRUNCATED	Material			2022						
		DOMES			5	Nov 16, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					5	Nov 16, 2022	SYSTEM	(\$3,000.00)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0070 -	Total						\$0.00				
	0080	6 IN. CONCRETE MEDIAN STRIP	Material		4	Nov 2, 2022	SYSTEM	\$4,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					4	Nov 2, 2022	SYSTEM	(\$4,270.00)				
					5	Nov 16, 2022	SYSTEM	\$4,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate.			
					5	Nov 16, 2022	SYSTEM	(\$4,270.00)				
				- Total		2022		\$0.00				
			Material - To					\$0.00				
	0080 -	Total						\$0.00				
	0090	PAVED APPROACH, 8 IN.	Material		3	Oct 17, 2022	SYSTEM	\$9,570.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user snells1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					3	Oct 17, 2022	SYSTEM	(\$9,570.00)	·			
					4	Nov 2, 2022	SYSTEM	\$17,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate.			
							4	Nov 2, 2022	SYSTEM	(\$17,150.00)		
						5	Nov 16, 2022	SYSTEM	\$17,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user snells1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		
					5	Nov 16, 2022	SYSTEM	(\$17,160.00)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
			Overrun	Overrun	4	Nov 2, 2022	SYSTEM	(\$1,170.00)				
					5	Nov 16, 2022	SYSTEM	(\$10.00)				
				Overrun - Total								
			Overrun - T	otal				(\$1,180.00)				
	0090 -	Total						(\$1,180.00)				
	0100	CURB AND GUTTER TYPE B	Material		3	Oct 17, 2022	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user snells1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					3	Oct 17, 2022	SYSTEM	(\$4,000.00)				
					4	Nov 2, 2022	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment Estimate Exception 14 on the current Payment Estimate.			
					4	Nov 2, 2022	SYSTEM	(\$7,000.00)				
					5	5	5	Nov 16, 2022	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
					5	Nov 16, 2022	SYSTEM	(\$7,000.00)	, , , , , , , , , , , , , , , , , , , ,			
				- Total				\$0.00				



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
D0046	0100 -	Total						\$0.00	
	0140	CONSTRUCTION SIGNS	Material		1	Sep 16, 2022	SYSTEM	\$1,701.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Sep 16, 2022	SYSTEM	(\$1,701.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun		Nov 2, 2022	SYSTEM	(\$63.00)	
				Overrun - T	otal			(\$63.00)	
			Overrun - T	otal				(\$63.00)	
	0140 -	Total						(\$63.00)	
	0150	ADVANCED WARNING RAIL SYSTEM	Material		1	Sep 16, 2022	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Sep 16, 2022	SYSTEM	(\$200.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0150 -	Total						\$0.00	
	0160	CHANNELIZER (TRIM LINE)	Material		1	Sep 16, 2022	SYSTEM	\$705.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user snells1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Sep 16, 2022	SYSTEM	(\$705.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
			Overrun	Overrun	5	Nov 16, 2022	SYSTEM	(\$795.00)	
				Overrun - T	otal			(\$795.00)	
			Overrun - T	otal				(\$795.00)	
	0160 -	Total						(\$795.00)	
	0170	TYPE III MOVEABLE BARRICADE	Material		1	Sep 16, 2022	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user snells1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					1	Sep 16, 2022	SYSTEM	(\$700.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun		Nov 2, 2022	SYSTEM	(\$1,225.00)	
				Overrun - T	otal			(\$1,225.00)	
			Overrun - T	otal				(\$1,225.00)	
	0170 -							(\$1,225.00)	
	0180	FLASHING ARROW PANEL	Material		1	Sep 16, 2022	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					1	Sep 16, 2022	SYSTEM	(\$2,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0180 -	Total						\$0.00	
	0190	CMS WITH COMMUNICATION INTERFACE,	Material		1	Sep 16, 2022	SYSTEM	\$17,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user snells1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		CONT F			1	Sep 16, 2022	SYSTEM	(\$17,500.00)	
				- Total				\$0.00	



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
46 (0190	CMS WITH COMMUNICATION INTERFACE, CONT F	Material - To	otal				\$0.00			
0	0190 -	Total						\$0.00			
(0210	TEMP. TRAFFIC BARRIER ANCHORED.,	Material		1	Sep 16, 2022	SYSTEM	\$20,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user snells1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
		CONT			1	Sep 16, 2022	SYSTEM	(\$20,300.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
9	0210 -							\$0.00			
(0220	TEMP. TRAFFIC BARRIER HEIGHT TRANSITION	Material		1	Sep 16, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
					1	Sep 16, 2022	SYSTEM	(\$3,000.00)			
					2	Oct 3, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Paymer Estimate Item Adjustment (0002) due to user geldmk1 overridding Payr Estimate Exception 6 on the current Payment Estimate.		
					2	Oct 3, 2022	SYSTEM	(\$3,000.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0220 -							\$0.00			
0	0250	PREF THERMO PVMT MARK, 24 IN WHIT	Material		4	Nov 2, 2022	SYSTEM	\$2,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user snells1 overridding Payment Estimate Exception 15 on the current Payment Estimate.		
					4	Nov 2, 2022	SYSTEM	(\$2,565.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0250 -							\$0.00			
(0260	PREF THERMO PVMT MARK, LT/RT ARROW	Material		4	Nov 2, 2022	SYSTEM	\$650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Exception 16 on the current Payment Estimate.		
					4	Nov 2, 2022	SYSTEM	(\$650.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0260 -	Total						\$0.00			
(0270	COLD APPLIED TAPE PVMT MARK, R/R XING	Material		3	Oct 17, 2022	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate.		
					3	Oct 17, 2022	SYSTEM	(\$1,050.00)			
					4	Nov 2, 2022	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user snells1 overridding Payment Estimate Exception 17 on the current Payment Estimate.		
					4	Nov 2, 2022	SYSTEM	(\$1,050.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0270 -							\$0.00			
(0280	PREF THERMO PVMT MARK, R/R XING	Material		4	Nov 2, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user snells1 overridding Payment Estimate Exception 18 on the current Payment Estimate.		
					4	Nov 2, 2022	SYSTEM	(\$5,000.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			



TEMPORARY No.	ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
REMOVABLE	46	0280 -	Total						\$0.00	
Common Total Common Total Common Total Common Total Common Commo		0290	REMOVABLE	Overrun	Overrun	3		SYSTEM	(\$1,550.25)	
1 Sep 16, SYSTEM					Overrun - To	otal			(\$1,550.25)	
TEMPORAPY Material				Overrun - T	otal				(\$1,550.25)	
REMOVABLE		0290 -	Total						(\$1,550.25)	
Part		0300	REMOVABLE	Material		1		SYSTEM	\$4,074.75	Estimate Item Adjustment (0009) due to user snells1 overridding Payment
Material - Total September						1		SYSTEM	(\$4,074.75)	
Overrun Overrun 3					- Total				\$0.00	
2022				Material - To	otal				\$0.00	
1930 - Total				Overrun				SYSTEM		
1						otal				
All NY ELLOW Material				Overrun - T	otal				(\$1,224.00)	
High Bull D WATERBORNE										
A		0310	HIGH BUILD WATERBORNE	Material		4		SYSTEM	\$3,975.75	Estimate Item Adjustment (0016) due to user snells1 overridding Payment
Substitute Sub						4		SYSTEM	(\$3,975.75)	
					- Total				\$0.00	
Since Waterial - Total Support				Material - To	otal				\$0.00	
Sull D WaterBorne 2022 System Estimate Exception 21 on the current Payment Estimate Exception 21 on the current Payment Estimate Individual Estimate Exception 21 on the current Payment Estimate Individual Estimate Exception 21 on the current Payment Estimate Individual Payment		0310 -	Total						\$0.00	
4		BL WATERBOR	BUILD WATERBORNE	Material		4		SYSTEM	\$4,242.00	Estimate Item Adjustment (0017) due to user snells1 overridding Payment
Material - Total S0.00			LAINT			4		SYSTEM	(\$4,242.00)	
Nov 2					- Total				\$0.00	
Misc. Material 4				Material - To	otal				\$0.00	
2022 Estimate Item Adjustment (0018) due to user snells1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	J	0320 -	Total						\$0.00	
2022		0400	MISC.	Material		4		SYSTEM	\$1.00	Estimate Item Adjustment (0018) due to user snells1 overridding Payment
Estimate tem Adjustment (0012) due to user snells1 overridding Payment Estimate Exception 16 on the current Payment Estimate. Total						4		SYSTEM	(\$1.00)	
Additional						5		SYSTEM	\$1.00	Estimate Item Adjustment (0012) due to user snells1 overridding Payment
Material - Total S0.00 MISC. Material Material Material Material Material Material Material Material Misc. Material Material A Nov 2, 2022 SYSTEM \$34,550.00 SYSTEM \$34,550.00 SYSTEM \$34,550.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 24 on the current Payment Estimate. Nov 2, 2022 SYSTEM \$34,550.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Item Adjustment (0013) due to user snells1 overridding Payment Item Adjustment (0013) due to user snells1 overridding Payment Item Adjustment (0013) due to user snells1 overridding Payment Item Adjustment (0013) due to user snells1 overridding Payment Item Adjustment (0013) due to user snells1 overridding Payment Item Adjustment (0013) due to user snells1 overridding Payment Item Adjustment (0013) due to user snells1 overridding Payment Item Adjustment (0013) due to user snells1 overridding Payment Item Adjustment (0013) due to user snells1 overridding Payment Item Adjustment (0013) due to user snells1 overridding Payment Item Adjustment (0013) due to user snells1 overridding Payment Item Adjustment (0013) due to user snells1 overr						5		SYSTEM	(\$1.00)	
NISC. Material MISC. Material Material Material Material Material Material Solution System solution										
MISC. Material				Material - To	otal					
Estimate Item Adjustment (0019) due to user snells1 overridding Payment Estimate Exception 24 on the current Payment Estimate. 4 Nov 2, 2022 5 Nov 16, 2022 SYSTEM \$34,550.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Exception 17 on the current Payment Estimate. 5 Nov 16, 2022 SYSTEM \$34,550.00 Waterial - Total \$0.00	J	0400 -	Total						\$0.00	
2022 5 Nov 16, 2022 5 Nov 16, 2022 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Exception 17 on the current Payment Estimate. 5 Nov 16, 2022 System (\$34,550.00) - Total So.00 Material - Total So.00		0410	MISC.	Material		4		SYSTEM	\$34,550.00	Estimate Item Adjustment (0019) due to user snells1 overridding Payment
2022 Estimate Item Adjustment (0013) dué to user snells1 overridding Payment Estimate Exception 17 on the current Payment Estimate. 5 Nov 16, 2022 \$\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \						4		SYSTEM	(\$34,550.00)	
2022 \$0.00						5		SYSTEM	\$34,550.00	Estimate Item Adjustment (0013) due to user snells1 overridding Payment
Material - Total \$0.00						5		SYSTEM	(\$34,550.00)	
					- Total				\$0.00	
0410 - Total \$0.00				Material - To	otal				\$0.00	
		0410 -	Total						\$0.00	

Nov 18, 2022



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
CD0046	0430	2.5 IN. PSST POST - 12 GA.	Material		4	Nov 2, 2022	SYSTEM	\$840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user snells1 overridding Payment Estimate Exception 25 on the current Payment Estimate.			
								4	Nov 2, 2022	SYSTEM	(\$840.00)	
					5	Nov 16, 2022	SYSTEM	\$840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user snells1 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
					5	Nov 16, 2022	SYSTEM	(\$840.00)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0430 -	Total						\$0.00				
	0450	SH-FLAT SHEET	Material		4	Nov 2, 2022	SYSTEM	\$637.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user snells1 overridding Payment Estimate Exception 26 on the current Payment Estimate.			
					4	Nov 2, 2022	SYSTEM	(\$637.20)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0450 -	Total						\$0.00				
CD0046 -	- Total							(\$9,947.25)				