

Pay Estimate Created Date: May 16, 2023

Progress Estimate N 8	lumber	Contract ID Prime Contractor	220819-H03 r Emery Sapp & S		Pay Period Start Pay Period End		3 Original Contract Amount 23 Net Change Order Amount Current Contract Amount	\$2,451,654.55 \$0.00 \$2,451,654.55
Approval Date								By User
May 16, 2023			Generated and A	pproved (a	nd should be cons	idered Draft	at the Project Office Level by	thomar1
May 16, 2023		Rev	viewed and Approv	ved (and sh	nould be considere	d Draft) at th	e Resident Engineer Level by	stottt1
May 17, 2023			F	Reviewed a	nd Approved at the	e Central Off	ice Controllers Office Level by	ramses1
Original Completion	n Date	Current Com	pletion Date	Actua	I Completion Dat	e	% of Current Contract Amou	nt Complete
October 1, 202	3	October	1, 2023				85.14%	
	Contrac	t Informational Dat	ies		Miles	tones		
Date Description	Original	Completion Date	Current Comple	tion Date	No Milestones E	xist for Cont	ract	
Acceptance Date								
Awarded Date	Septemb	per 7, 2022	September 7, 20	22				
Letting Date	August 1	9, 2022	August 19, 2022					
Notice to Proceed Date	October	11, 2022	October 11, 2022	2				
Open to Traffic Date								
Work Began Date								

Contract Total Pay For	r Estimate No. 8				
		This Estimate	Previous	To Date	
220819-H03					
	Total Posted Items Pay	\$222,118.00	\$1,865,297.14	\$2,087,415.14	
	Gross Item Adjustments	\$47,160.00	(\$47,160.00)	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	-		\$1,818,137.14	\$2,087,415.14	
Contract Total Payable	e This Estimate:	\$269,278.00			

Contract Total Payable This Estimate:

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9P3586	0200	6223010	DIAMOND GRINDING (CONCRETE PAVEMENT)	SQYD	\$5.950	30,850	\$183,557.50
	0210	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	LB	\$4.500	8,569	\$38,560.50
Project J9P35	i86 - Total						\$222,118.00
Overall - Tota	1						\$222,118.00

Contract Adjustments This Estimate

Ν

ine Item Adjustments This Estimate	
Io Contract Adjustments Exist on Contract	

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3586	0120	CROSS STITCH TIE BAR	Other Item Adjustment	Material Discrepancy Payment Adjustment	Sapp provided the certification for the epoxy bonding agent.			\$47,160.00
Total								\$47,160.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Co	ontract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9P3586	FAF 412-1(18)	Pavement rehabilitation	412	DUNKLIN	from Route 25 to I-155		
Totals by .	Job Numbe	ſS					
J9P3586					This Estimate	Previous	To Date
J9P3586	Posted	l Item Pay			This Estimate \$222,118.00	Previous \$1,865,297.14	To Date \$2,087,415.14
J9P3586		l Item Pay Item Adjustme	ents				
J9P3586				Item Pay	\$222,118.00	\$1,865,297.14	\$2,087,415.14
J9P3586		Item Adjustme		Item Pay	\$222,118.00 \$47,160.00	\$1,865,297.14 (\$47,160.00)	\$2,087,415.14 \$0.00
J9P3586	Gross	Item Adjustme		Item Pay	\$222,118.00 \$47,160.00 \$269,278.00	\$1,865,297.14 (\$47,160.00) \$1,818,137.14	\$2,087,415.14 \$0.00 \$2,087,415.14
J9P3586	Gross Incent Disinc	Item Adjustme	Gross	Item Pay	\$222,118.00 \$47,160.00 \$269,278.00 \$0.00	\$1,865,297.14 (\$47,160.00) \$1,818,137.14 \$0.00	\$2,087,415.14 \$0.00 \$2,087,415.14 \$0.00



Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
319-H03	J9P3586	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.25	\$35,000.00	\$8,750.00
		0001	0020	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	4,486.70	0.00	4,486.70	SQYD	3,272.77	\$195.00	\$638,190.15
		0001	0030	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	3,261.00	0.00	3,261.00	SQYD	2,829.45	\$8.00	\$22,635.60
		0001	0040	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	3,261.00	0.00	3,261.00	SQYD	2,829.35	\$23.00	\$65,075.05
		0001	0050	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	11,198.00	0.00	11,198.00	LF	7,727.00	\$2.50	\$19,317.50
		0001	0060	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	740.00	0.00	740.00	EA	406.00	\$8.75	\$3,552.50
		0001	0070	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	1,496.00	0.00	1,496.00	EA	1,036.00	\$12.00	\$12,432.00
		0001	0080	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	720.00	0.00	720.00	EA	555.00	\$5.00	\$2,775.00
		0001	0090	6132018	FURNISHING AND PLACING CONCRETE MATERIAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	11.20	0.00	11.20	CUYD	0.80	\$1,331.00	\$1,064.80
		0001	0100	6132019	REMOVAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	80.00	0.00	80.00	SQYD	4.11	\$364.00	\$1,496.04
		0001	0110	6134001	DOWEL BAR RETROFIT	9,303.00	0.00	9,303.00	EA	9,303.00	\$64.00	\$595,392.00
		0001	0120	6134002	CROSS STITCH TIE BAR	1,242.00	0.00	1,242.00	EA	1,071.00	\$60.00	\$64,260.00
		0001	0130	6161005	CONSTRUCTION SIGNS	660.00	0.00	660.00	SQFT	368.00	\$10.00	\$3,680.00
		0001	0140	6161025	CHANNELIZER (TRIM LINE)	200.00	0.00	200.00	EA	200.00	\$21.00	\$4,200.00
		0001	0150	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	1.00	\$995.00	\$995.00
		0001	0160	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,746.00	\$7,492.00
		0001	0170	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$237,000.00	\$237,000.00
		0001	0180	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	14,636.00	0.00	14,636.00	LF	0.00	\$0.47	\$0.00
		0001	0190	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	11,569.00	0.00	11,569.00	LF	0.00	\$0.47	\$0.0
		0001	0200	6223010	DIAMOND GRINDING (CONCRETE PAVEMENT)	30,850.00	0.00	30,850.00	SQYD	30,850.00	\$5.95	\$183,557.50
		0001	0210	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	47,900.00	0.00	47,900.00	LB	47,900.00	\$4.50	\$215,550.0
	Project J	9P3586 - To	otal Value	Posted to D	late as of Report Generated Date							\$2,087,415.14
319-H03 Ove	erall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$2,087,415.14



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line lumber	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0200	6223010	DIAMOND GRINDING (CONCRETE PAVEMENT)	5/11/23	5/12/23	0.70	SQYD	Rounding	0		0		
				5/12/23	2,478.10	SQYD	WBL	24.218		24.394		
				5/12/23	6,969.60	SQYD	WBL	23.192		23.687		
				5/12/23	8,898.60	SQYD	WBL	25.589		26.221		
				5/12/23	12,503.00	SQYD	WBL	24.518		25.406		
0210	6252003	SLAB JACKING MATL HIGH DENSITY POLYURETH	5/2/23	5/4/23	5,010.00	LB	Bridge A6602 EBL.	36.463		0		
			5/3/23	5/4/23	-12,386.00	LB	Over run Need Change order for this.	0		0		
				5/4/23	7,845.00	LB	Bridge A6186 WBL	11.132		0		
				5/4/23	8,100.00	LB	Bridge A6185 EBL.	39.601		0		

The information below this line are details for Construction Signs (if applicable), No Data Available



Ductorst	1.1.4.4	Description	A	Others	E-4	One stand	One start	A	Demester
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
9P3586	0020	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		3	Feb 2, 2023	SYSTEM	\$345,797.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user thomar1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Feb 2, 2023	SYSTEM	(\$345,797.40)	
					4	Mar 1, 2023	SYSTEM	\$598,254.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user thomar1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Mar 1, 2023	SYSTEM	(\$598,254.15)	
					5	Mar 16, 2023	SYSTEM	\$605,430.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user thomar1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Mar 16, 2023	SYSTEM	(\$605,430.15)	
					6	Apr 3, 2023	SYSTEM	\$638,190.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user thomar1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Apr 3, 2023	SYSTEM	(\$638,190.15)	
					7	May 2, 2023	SYSTEM	\$638,190.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	May 2, 2023	SYSTEM	(\$638,190.15)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0020 -	Total						\$0.00	
	0040	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN.	Material		3	Feb 2, 2023	SYSTEM	\$30,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		TH			3	Feb 2, 2023	SYSTEM	(\$30,590.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0040 -	Total						\$0.00	
	0060	DOWEL BAR (DRILLING, FURNISHING AND	Material		3	Feb 2, 2023	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thomar1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		INST			3	Feb 2, 2023	SYSTEM	(\$1,050.00)	
					4				
					4	Mar 1, 2023	SYSTEM	\$2,415.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4		SYSTEM SYSTEM	\$2,415.00 (\$2,415.00)	Estimate Item Adjustment (0002) due to user thomar1 overridding Payment
						2023 Mar 1,			Estimate Item Adjustment (0002) due to user thomar1 overridding Payment
					4	2023 Mar 1, 2023 Mar 16,	SYSTEM	(\$2,415.00)	Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment
					4	2023 Mar 1, 2023 Mar 16, 2023 Mar 16,	SYSTEM SYSTEM	(\$2,415.00) \$3,097.50	Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment
					4 5 5	2023 Mar 1, 2023 Mar 16, 2023 Mar 16, 2023 Apr 3,	SYSTEM SYSTEM SYSTEM	(\$2,415.00) \$3,097.50 (\$3,097.50)	Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment
					4 5 5 6	2023 Mar 1, 2023 Mar 16, 2023 Mar 16, 2023 Apr 3, 2023 Apr 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,415.00) \$3,097.50 (\$3,097.50) \$3,552.50	Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment
					4 5 5 6 6	2023 Mar 1, 2023 Mar 16, 2023 Mar 16, 2023 Apr 3, 2023 Apr 3, 2023 May 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,415.00) \$3,097.50 (\$3,097.50) \$3,552.50 (\$3,552.50)	Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.
				- Total	4 5 5 6 7	2023 Mar 1, 2023 Mar 16, 2023 Mar 16, 2023 Apr 3, 2023 Apr 3, 2023 May 2, 2023 May 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,415.00) \$3,097.50 (\$3,097.50) \$3,552.50 (\$3,552.50) \$3,552.50	Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.
			Material - T		4 5 5 6 7	2023 Mar 1, 2023 Mar 16, 2023 Mar 16, 2023 Apr 3, 2023 Apr 3, 2023 May 2, 2023 May 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,415.00) \$3,097.50 (\$3,097.50) \$3,552.50 (\$3,552.50) \$3,552.50 (\$3,552.50)	Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.



Image: Constraint of the state of	nent ayment
INSTALL WITH BASK 3 Feb 2, 2023 SYSTEM (\$7,392.00) 4 Mar 1, 2023 SYSTEM \$12,432.00 This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0003) due to user thomar1 overridding Payr Estimate Exception 5 on the current Payment Estimate. 4 Mar 1, 2023 SYSTEM \$12,432.00 This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0003) due to user thomar1 overridding Payr Estimate Exception 5 on the current Payment Estimate. 5 Mar 16, 2023 SYSTEM \$12,432.00 This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0003) due to user thomar1 overridding Payr Estimate Item Adjustment (0003) due to user thomar1 overridding Payr Estimate Item Adjustment (0003) due to user thomar1 overridding Payr Estimate Item Adjustment (0003) due to user thomar1 overridding Payr Estimate Item Adjustment (0003) due to user thomar1 overridding Payr Estimate Exception 3 on the current Payment Estimate. 5 Mar 16, SYSTEM \$12,432.00	nent ayment
4 Mar 1, 2023 SYSTEM \$\$12,432.00 This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0003) due to user thomar1 overridding Payr Estimate Exception 5 on the current Payment Estimate. 4 Mar 1, 2023 SYSTEM (\$12,432.00) 5 Mar 16, SYSTEM \$12,432.00 This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0003) due to user thomar1 overridding Payr 2023 5 Mar 16, SYSTEM \$\$12,432.00 This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0003) due to user thomar1 overridding Payr Estimate Item Adjustment (0003) due to user thomar1 overridding Payr 2023	ayment nent
2023 2023 Estimate Item Adjustment (0003) due to user thomar1 overridding P 4 Mar 1, 2023 SYSTEM (\$12,432.00) 5 Mar 16, 2023 SYSTEM \$12,432.00 5 Mar 16, SYSTEM (\$12,432.00)	ayment nent
5 Mar 16, 2023 SYSTEM \$12,432.00 This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0003) due to user thomar1 overridding Payr Estimate Exception 3 on the current Payment Estimate. 5 Mar 16, SYSTEM (\$12,432.00)	
2023 Estimate Item Adjustment (0003) due to user thomar1 overridding P 5 Mar 16, SYSTEM (\$12,432.00)	
6 Apr 3, 2023 SYSTEM \$12,432.00 This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0003) due to user thomar1 overridding P Estimate Exception 3 on the current Payment Estimate.	
6 Apr 3, SYSTEM (\$12,432.00)	
7 May 2, 2023 SYSTEM \$12,432.00 This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0004) due to user thomar1 overridding P Estimate Exception 3 on the current Payment Estimate.	
7 May 2, 2023 SYSTEM (\$12,432.00)	
- Total \$0.00	
Material - Total \$0.00	
0070 - Total \$0.00	
0080 TIE BAR (DRILL, FURN & INSTAL) (TYPE L Material 3 Feb 2, 2023 SYSTEM \$1,400.00 This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0005) due to user thomar1 overridding Payr Estimate Exception 8 on the current Payment Estimate.	
3 Feb 2, SYSTEM (\$1,400.00) 2023	
4 Mar 1, 2023 SYSTEM \$2,455.00 This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0004) due to user thomar1 overridding P Estimate Exception 7 on the current Payment Estimate.	
4 Mar 1, SYSTEM (\$2,455.00) 2023	
5 Mar 16, 2023 SYSTEM \$2,695.00 This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0004) due to user thomar1 overridding P Estimate Exception 6 on the current Payment Estimate.	
5 Mar 16, SYSTEM (\$2,695.00) 2023	
6 Apr 3, 2023 SYSTEM \$2,775.00 This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0004) due to user thomar1 overridding P Estimate Exception 5 on the current Payment Estimate.	
6 Apr 3, SYSTEM (\$2,775.00)	
7 May 2, 2023 SYSTEM \$2,775.00 This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0005) due to user thomar1 overridding P Estimate Exception 4 on the current Payment Estimate.	
7 May 2, SYSTEM (\$2,775.00) 2023	
- Total \$0.00	
Material - Total \$0.00	
0080 - Total \$0.00	
0090 FURN & PLACE CONC MATL FOR CL A PARTIAL Material 4 Mar 1, 2023 SYSTEM \$1,064.80 This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0005) due to user thomar1 overridding Payr Estimate Exception 9 on the current Payment Estimate.	
4 Mar 1, SYSTEM (\$1,064.80) 2023	
5 Mar 16, 2023 SYSTEM 21,064.80 \$1,064.80 This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0005) due to user thomar1 overridding Payr Estimate Exception 7 on the current Payment Estimate.	
5 Mar 16, SYSTEM (\$1,064.80) 2023	



ct									
	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
86	0090	FURN & PLACE CONC MATL FOR CL A PARTIAL	Material		6	Apr 3, 2023	SYSTEM	\$1,064.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user thomar1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					6	Apr 3, 2023	SYSTEM	(\$1,064.80)	
					7	May 2, 2023	SYSTEM	\$1,064.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user thomar1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	May 2, 2023	SYSTEM	(\$1,064.80)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
- 1	0090 -	Total						\$0.00	
ſ	0110	DOWEL BAR RETROFIT	Material		2	Jan 3, 2023	SYSTEM	\$151,664.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Jan 3, 2023	SYSTEM	(\$151,664.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0110 -	Total						\$0.00	
- 6	0120	CROSS STITCH TIE BAR	Material		3	Feb 2, 2023	SYSTEM	\$7,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user thomar1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					3	Feb 2, 2023	SYSTEM	(\$7,920.00)	
					4	Mar 1, 2023	SYSTEM	\$17,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user thomar1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	Mar 1, 2023	SYSTEM	(\$17,100.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	MDPA	6	Apr 3, 2023	thomar1	(\$47,160.00)	Contractor has not provided the materials inspection. I have contacted them on multiple occasions.
					7	May 2, 2023	SYSTEM	\$47,160.00	Contractor has not provided the materials inspection. I have contacted them on multiple occasions.
					7	May 2,	stottt1		
						2023		(\$47,160.00)	Material inspection has not been received from contractor as requested.
					8		thomar1	\$47,160.00	Material inspection has not been received from contractor as requested. Sapp provided the certification for the epoxy bonding agent.
				MDPA - Tot	al	2023 May 16,		\$47,160.00	
			Other Item /	MDPA - Tot Adjustment -	al	2023 May 16,		\$47,160.00	
	0120 -	Total	Other Item A		al	2023 May 16,		\$47,160.00	
	0120 - 0130		Other Item A Material		al	2023 May 16,		\$47,160.00 \$0.00 \$0.00	
- 5		CONSTRUCTION			al Total	2023 May 16, 2023 Dec 15,	thomar1	\$47,160.00 \$0.00 \$0.00 \$0.00	Sapp provided the certification for the epoxy bonding agent.
- 5		CONSTRUCTION			al Total 1	2023 May 16, 2023 Dec 15, 2022 Dec 15,	thomar1 SYSTEM	\$47,160.00 \$0.00 \$0.00 \$0.00 \$1,800.00	Sapp provided the certification for the epoxy bonding agent.
		CONSTRUCTION		Adjustment -	al Total 1	2023 May 16, 2023 Dec 15, 2022 Dec 15, 2022 Jan 3,	thomar1 SYSTEM SYSTEM	\$47,160.00 \$0.00 \$0.00 \$1,800.00 \$1,800.00 \$2,080.00 \$2,080.00	Sapp provided the certification for the epoxy bonding agent. Sapp provided the certification for the epoxy bonding agent. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user thomar1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thomar1 overridding Payment
- 5		CONSTRUCTION	Material	Adjustment -	al Total 1 1 2	2023 May 16, 2023 Dec 15, 2022 Dec 15, 2022 Jan 3, 2023 Jan 3,	thomar1 SYSTEM SYSTEM SYSTEM	\$47,160.00 \$0.00 \$0.00 \$1,800.00 \$1,800.00 \$2,080.00	Sapp provided the certification for the epoxy bonding agent. Sapp provided the certification for the epoxy bonding agent. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user thomar1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thomar1 overridding Payment
- 5		CONSTRUCTION		Adjustment -	al Total 1 1 2	2023 May 16, 2023 Dec 15, 2022 Dec 15, 2022 Jan 3, 2023 Jan 3,	thomar1 SYSTEM SYSTEM SYSTEM	\$47,160.00 \$0.00 \$0.00 \$1,800.00 \$1,800.00 \$2,080.00 \$2,080.00	Sapp provided the certification for the epoxy bonding agent. Sapp provided the certification for the epoxy bonding agent. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user thomar1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thomar1 overridding Payment
		CONSTRUCTION SIGNS	Material	Adjustment -	al Total 1 1 2	2023 May 16, 2023 Dec 15, 2022 Dec 15, 2022 Jan 3, 2023 Jan 3,	thomar1 SYSTEM SYSTEM SYSTEM	\$47,160.00 \$0.00 \$0.00 \$1,800.00 (\$1,800.00) \$2,080.00 (\$2,080.00) \$0.00	Sapp provided the certification for the epoxy bonding agent. Sapp provided the certification for the epoxy bonding agent. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user thomar1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thomar1 overridding Payment
	0130	CONSTRUCTION SIGNS	Material Material - To	Adjustment -	al Total 1 1 2	2023 May 16, 2023 Dec 15, 2022 Dec 15, 2022 Jan 3, 2023 Jan 3,	thomar1 SYSTEM SYSTEM SYSTEM	\$47,160.00 \$0.00 \$0.00 \$1,800.00 (\$1,800.00) \$2,080.00 (\$2,080.00) \$0.00 \$0.00	Sapp provided the certification for the epoxy bonding agent. Sapp provided the certification for the epoxy bonding agent. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user thomar1 overridding Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thomar1 overridding Payment



May 18, 2023

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3586	0140	CHANNELIZER (TRIM LINE)	Material		2	Jan 3, 2023	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user thomar1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Jan 3, 2023	SYSTEM	(\$4,200.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0140 -	Total						\$0.00	
	0150	FLASHING ARROW PANEL	Material		1	Dec 15, 2022	SYSTEM	\$995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thomar1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Dec 15, 2022	SYSTEM	(\$995.00)	
					2	Jan 3, 2023	SYSTEM	\$995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user thomar1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Jan 3, 2023	SYSTEM	(\$995.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0150 -	Total						\$0.00	
	0160	CMS W/O	Material		2	Jan 3, 2023	SYSTEM	\$7,492.00	This adjustment offsets the original system-generated Material Payment
		COMMUNICATION INTERFACE,				2020			Estimate Item Adjustment (0001) due to user thomar1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	Jan 3, 2023	SYSTEM	(\$7,492.00)	
		INTERFACE,		- Total	2	Jan 3,	SYSTEM	(\$7,492.00) \$0.00	
		INTERFACE,	Material - To		2	Jan 3,	SYSTEM		
	0160 -	INTERFACE, CONT F/	Material - To		2	Jan 3,	SYSTEM	\$0.00	
	0160 - 0210	INTERFACE, CONT F/ Total SLAB JACKING MATL HIGH DENSITY	Material - To Material		2	Jan 3,	SYSTEM	\$0.00 \$0.00	
		INTERFACE, CONT F/ Total SLAB JACKING MATL HIGH				Jan 3, 2023 May 2,		\$0.00 \$0.00 \$0.00	Estimate Exception 5 on the current Payment Estimate.
		INTERFACE, CONT F/ Total SLAB JACKING MATL HIGH DENSITY			7	Jan 3, 2023 May 2, 2023 May 2,	SYSTEM	\$0.00 \$0.00 \$0.00 \$176,989.50	Estimate Exception 5 on the current Payment Estimate.
		INTERFACE, CONT F/ Total SLAB JACKING MATL HIGH DENSITY		- Total	7	Jan 3, 2023 May 2, 2023 May 2,	SYSTEM	\$0.00 \$0.00 \$176,989.50 (\$176,989.50)	Estimate Exception 5 on the current Payment Estimate.
		INTERFACE, CONT F/ Total SLAB JACKING MATL HIGH DENSITY POLYURETH	Material	- Total	7	Jan 3, 2023 May 2, 2023 May 2,	SYSTEM	\$0.00 \$0.00 \$176,989.50 (\$176,989.50) \$0.00	Estimate Exception 5 on the current Payment Estimate.
J9P3586 -	0210 0210 -	INTERFACE, CONT F/ Total SLAB JACKING MATL HIGH DENSITY POLYURETH	Material	- Total	7	Jan 3, 2023 May 2, 2023 May 2,	SYSTEM	\$0.00 \$0.00 \$176,989.50 (\$176,989.50) \$0.00	Estimate Exception 5 on the current Payment Estimate.



There are no contract adjustments to display for this contract.