

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 1, 2024

Progress Estimate Number	Contract ID	220916-C01	Pay Period Start	June 16, 2024	Original Contract Amount	\$2,243,622.58
17	Prime Contractor	Radmacher Brothers Excavating Co.,Inc.	Pay Period End	June 30, 2024	Net Change Order Amount Current Contract Amount	\$5,096.30 \$2,248,718.88

By User		Approval Date
woodwj1	Generated and Approved (and should be considered Draft) at the Project Office Level by	July 1, 2024
wilsor2	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	July 1, 2024
ramses1	Reviewed and Approved at the Central Office Controllers Office Level by	July 2, 2024

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2023	September 4, 2024		94.88%

Co	ntract Informational	Dates			Milestones		
Date Description	Original Completion Date	Current Completion Date	Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days
Acceptance Date			Milestone - Calendar Time	July 18, 2024	July 18, 2024	16	
Awarded Date	October 5, 2022	October 5, 2022	Milestone - Closure	July 11, 2024	July 11, 2024	9	
Letting Date	September 16, 2022	September 16, 2022	Calendar Time				
Notice to Proceed Date	July 5, 2023	July 5, 2023					
Open to Traffic Date							

Contract Total Pa	ay For Estimate No. 17				
		This Estimate	Previous	To Date	
220916-C01	Total Posted Items Pay Gross Item Adjustments Incentive	\$337,087.56 (\$10,567.80) \$0.00	\$1,796,497.10 \$0.00 \$0.00	\$2,133,584.66 (\$10,567.80) \$0.00	
	Disincentive Liquidated Damage Other Contract Adjustments	\$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00	
Contract Total Pa	ayable This Estimate:	\$326,519.76	\$1,796,497.10	\$2,123,016.86	

Items Paid This Estimate Period

Work Began

Date

October 23, 2023

October 23, 2023

Duningt	Lina	la	Itana Daganintian	Lineia	Unit Duine	Cumant	Comment In stelled
Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4P3295	0020	2031000	CLASS A EXCAVATION	CUYD	\$8.800	1,344	\$11,827.20
	0030	2036000	COMPACTING EMBANKMENT	CUYD	\$1.400	2,691	\$3,767.40
	0040	2037075	COMPACTING IN CUT	STA	\$1,257.000	2	\$2,514.00
	0070	2072000	LINEAR GRADING CLASS 2	STA	\$1,118.000	4.8	\$5,366.40
	0800	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$11.300	90	\$1,017.00
	0090	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$14.700	461	\$6,776.70
	0100	3105003	GRAVEL (A) OR CRUSHED STONE (B)	SQYD	\$11.700	906	\$10,600.20
	0180	6085008	PAVED APPROACH, 8 IN.	SQYD	\$82.400	90	\$7,416.00
	0230	6099903	MISC.APWA CURB & GUTTER TYPE CG-1	LF	\$37.200	21	\$781.20
	0250	6161005	CONSTRUCTION SIGNS	SQFT	\$6.300	36.5	\$229.95
	0330	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.150	4,968	\$745.20
	0340	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.150	5,647	\$847.05
	0360	6269909	MISC.OPTIONAL RUMBLE STRIPS	STA	\$86.900	29.7	\$2,580.93

Revision 3/23/2023 Page 1 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 1, 2024

Progress Estimate Pay Period June 16, Original Contract Amount \$2,243,622.58 Contract ID 220916-C01 Start 2024 Number Pay Period End June 30, 2024 Prime Radmacher Brothers Excavating Net Change Order 17 \$5,096.30 Contractor Co.,Inc. Amount **Current Contract Amount \$2,248,718.88**

Project Number	Line Number	Item Code	Item Description	Unit Price	Current Installed Qty	Current Installed Amount	
J4P3295	0420	8025006	MULCHING	ACRE	\$842.500	2.25	\$1,895.63
	0430	8051000A	SEEDING - COOL SEASON GRASSES	ACRE	\$2,317.000	2.25	\$5,213.25
	0510	8064129	TYPE 2 TURF REINFORCEMENT MAT	SQYD	\$4.150	3,641	\$15,110.15
	0540	5029905	MISC.Concrete Pavement	SQYD	\$72.100	3,578	\$257,973.80
	5001	6161030	TYPE III MOVEABLE BARRICADE	EA	\$173.250	14	\$2,425.50
Project J4P	3295 - Tota	al					\$337,087.56
Overall - To	otal						\$337,087.56

Contract Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
4P3295	0030	COMPACTING EMBANKMENT	Material			-2,692	\$1.40	(\$3,768.80)
	0030	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	2,692	\$1.40	\$3,768.80
	0800	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-90	\$11.30	(\$1,017.00)
	0800	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	90	\$11.30	\$1,017.00
	0090	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-11,472	\$14.70	(\$168,638.40
	0090	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	11,472	\$14.70	\$168,638.40
	0100	GRAVEL (A) OR CRUSHED STONE (B)	Material			-906	\$11.70	(\$10,600.20
	0100	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user woodwj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	906	\$11.70	\$10,600.20
	0180	PAVED APPROACH, 8 IN.	Overrun			-32	\$82.40	(\$2,636.80
	0180	PAVED APPROACH, 8 IN.	Material			-90	\$82.40	(\$7,416.00
(0180	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	90	\$82.40	\$7,416.00
	0230	MISC.	Material			-21	\$37.20	(\$781.20
	0230	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user woodwj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	21	\$37.20	\$781.20

Revision 3/23/2023 Page 2 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 1, 2024

Pay Period Start **Progress Estimate** June 16, Original Contract Amount \$2,243,622.58 Contract ID 220916-C01 2024 Number Pay Period End June 30, 2024 Prime Radmacher Brothers Excavating Net Change Order 17 \$5,096.30 Contractor Co.,Inc. Amount **Current Contract Amount** \$2,248,718.88

Number No. Type Adjustment Type									
CLASS B-1 CONCRETE Material This adjustment offsets the original system-generated Material Payment Estimate Item (CULVERTS) CULVERTS) Material This adjustment (005) due to user woodylf overridding Payment Estimate Exception 11 on the current Payment Estimate Item (CULVERTS) CULVERTS) This adjustment offsets the original system-generated Material Payment Estimate Item (CULVERTS) Single Payment Estimate Exception 12 overridding Payment Estimate Exception 13 overridding Payment Estimate Exception 14 on the current Payment Estimate Item (CULVERTS) Single Payment Item (CULVERTS) Single Payme	Project Number		Item Description		Adjustment	Comments		Adjustment	Adjustment amount
GCULVERTS generated Material Payment Estimate Item Adjustment (0005) due to user wood/vij overridding Payment Estimate Exception 11 on the current Payment Estimate Item Adjustment (0006) due to user wood/vij overridding Payment Estimate Item Adjustment (0006) due to user wood/vij overridding Payment Estimate Item Adjustment (0006) due to user wood/vij overridding Payment Estimate Item Adjustment (0006) due to user wood/vij overridding Payment Estimate Item Adjustment (0006) due to user wood/vij overridding Payment Estimate Item Adjustment (0007) due to user wood/vij overridding Payment Estimate Item Adjustment (0007) due to user wood/vij overridding Payment Estimate Exception 17 on the current Payment Estimate Item Adjustment (0007) due to user wood/vij overridding Payment Estimate Exception 17 on the current Payment Estimate Item Adjustment (0007) due to user wood/vij overridding Payment Estimate Exception 17 on the current Payment Estimate Item Adjustment (0007) due to user wood/vij overridding Payment Estimate Item Adjustment (0014) due to user wood/vij overridding Payment Estimate Item Adjustment (0014) due to user wood/vij overridding Payment Estimate Item Adjustment (0016) due to user wood/vij overridding Payment Estimate Item Adjustment (0016) due to user wood/vij overridding Payment Estimate Item Adjustment (0016) due to user wood/vij overridding Payment Estimate Item Adjustment (0016) due to user wood/vij overridding Payment Estimate Item Adjustment (0016) due to user wood/vij overridding Payment Estimate Item Adjustment (0016) due to user wood/vij overridding Payment Estimate Item Adjustment (0016) due to user wood/vij overridding Payment Estimate Item Adjustment (0016) due to user wood/vij overridding	J4P3295	0380		Material			-60	\$1,460.00	(\$87,600.00)
CULVERTS Material This adjustment offsets the original system overridding Payment Estimate Item Adjustment Estimate Esception 14 on the current Payment Estimate Item Adjustment Estimate Esception 14 on the current Payment Estimate Item Adjustment Estimate Esception 14 on the current Payment Estimate Esception 14 on the current Payment Estimate Item Adjustment (0007) due to user woodwij overridding Payment Estimate Item Adjustment Estimate Item Adjustment (0013) due to user woodwij overridding Payment Estimate Item Adjustment (0013) due to user woodwij overridding Payment Estimate Item Adjustment (014) due to user woodwij overridding Payment Estimate Item Adjustment (014) due to user woodwij overridding Payment Estimate Item Adjustment (014) due to user woodwij overridding Payment Estimate Item Adjustment (015) due to user woodwij overridding Payment Estimate Item Adjustment (015) due to user woodwij overridding Payment Estimate Item Adjustment (015) due to user woodwij overridding Payment Estimate Item Adjustment (015) due to user woodwij overridding Payment Estimate Item Adjustment (015) due to user woodwij overridding Payment Estimate Item Adjustment (015) due to user woodwij overridding Payment Estimate Item Adjustment (015) due to user woodwij overridding Payment Estimate Item Adjustment (015) due to user woodwij overridding Payment Estimate Item Adjustment (0105) due to user woodwij ove		0380		Material		generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 11		\$1,460.00	\$87,600.00
GULVERTS generated Material Payment Estimate Item Adjustment (0009) due to user woodwij overridding Payment Estimate Exception 14 on the current Payment Estimate Exception 14 on the current Payment Estimate Exception 15 FLARED END SECTION		0390		Material			-8,100	\$1.95	(\$15,795.00)
SUBSTITUTE GROUP B FLARED END SECTION		0390		Material		generated Material Payment Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 14	8,100	\$1.95	\$15,795.00
SUBSTITUTE GROUP B Generated Material Payment Estimate Lendon		0410	SUBSTITUTE GROUP B	Material			-2	\$1,011.00	(\$2,022.00)
GRASSES Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodwj1 overridding Payment Estimate Exception 18 on the current Payment Estimate Item Adjustment (0013) due to user woodwj1 overridding Payment Estimate Exception 18 on the current Payment Estimate Exception 18 on the current Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 21 on the current Payment Estimate Exception 21 on the current Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment Offsets the original system-generated Material Payment Estimate Item Adjustment Offsets the original system-generated Material Payment Estimate Item Adjustment Offset offset on user woodwj1 overridding Payment Estimate Exception 21 on the current Payment Estimate Exception 22 on the current Payment Estimate Exception 22 on the current Payment Estimate Exception 3 (\$7.931.00 (\$7		0410	SUBSTITUTE GROUP B	Material		generated Material Payment Estimate Item Adjustment (0007) due to user woodwj1 overridding Payment Estimate Exception 17	2	\$1,011.00	\$2,022.00
GRASSES GRASCES GRASSES GRASCHARL SALIS GRACHARL SALIS GRASCHARL SALIS GRASCHARL SALIS GRASCHARL SALIS GRASCHARL SALIS GRACHARL S		0430		Material			-2.25	\$2,317.00	(\$5,213.25)
REINFORCEMENT MAT 0510 TYPE 2 TURF REINFORCEMENT MAT 0520 MISC. Material This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 0520 MISC. Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment Estimate Exception 22 on the current Payment Estimate. 0540 MISC. Overrun This adjustment offsets the original system-generated Material Payment Estimate. 0540 MISC. Material This adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate Item Adjustment (0020) due to user woodwj1 overridding Payment Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		0430		Material		generated Material Payment Estimate Item Adjustment (0013) due to user woodwj1 overridding Payment Estimate Exception 18	2.25	\$2,317.00	\$5,213.25
REINFORCEMENT MAT generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 520 MISC. Material This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment Estimate Exception 22 on the current Payment Estimate. MISC. Overrun MISC. Overrun This adjustment offsets the original system- generated Material Payment Estimate. 540 MISC. Overrun This adjustment offsets the original system- generated Material Payment Estimate Exception 22 on the current Payment Estimate Item Adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		0510		Material			-3,641	\$4.15	(\$15,110.15)
MISC. Material This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment Estimate Exception 22 on the current Payment Estimate. MISC. Overrun		0510		Material		generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 21	3,641	\$4.15	\$15,110.15
generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment Estimate Exception 22 on the current Payment Estimate. 540 MISC. Overrun 540 MISC. Material 540 Misc. Misc		0520	MISC.	Material			-16	\$206.00	(\$3,296.00)
0540 MISC. Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate. 10,669 \$72.10 (\$769,234.90) \$769,234.90 \$769,234.90		0520	MISC.	Material		generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment Estimate Exception 22	16	\$206.00	\$3,296.00
0540 MISC. Material This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		0540	MISC.	Overrun			-110	\$72.10	(\$7,931.00)
generated Material Payment Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		0540	MISC.	Material			-10,669	\$72.10	(\$769,234.90)
Total (\$10,567.8)		0540	MISC.	Material		generated Material Payment Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate Exception 6 on	10,669	\$72.10	\$769,234.90
	Total								(\$10,567.80)

Revision 3/23/2023 Page 3 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information						
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work					
J4P3295	FAF 169-1(115)	Pavement improvements	169	CLAY	US 169 at 188th Street	69 at 188th Street intersection						
Totals by J	Job Numbers	•										
J4P3295		Item Pay tem Adjustment	ts <mark>Gross Ite</mark>	em Pay	This Estimate \$337,087.56 (\$10,567.80) \$326,519.76	Previous \$1,796,497.10 \$0.00 \$1,796,497.10	To Date \$2,133,584.66 (\$10,567.80) \$2,123,016.86					
			nents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					

Revision 3/23/2023 Page 4 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 2036000, Project Item Line Number 0030, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Material testing results will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 3040504, Project Item Line Number 0080, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Material testing results will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 3040506, Project Item Line Number 0090, Material Set 304050696, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Material testing results will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 3040506, Project Item Line Number 0090, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Material testing results will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 3105003, Project Item Line Number 0100, Material Set 310500396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Material testing results will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 5029905, Project Item Line Number 0540, Material Set 502990596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Material testing results will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 5029905, Project Item Line Number 0540, Material Set 502990596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Material testing results will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 5029905, Project Item Line Number 0540, Material Set 502990596, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Material testing results will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 6085008, Project Item Line Number 0180, Material Set 608500896, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Material testing results will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 6099903, Project Item Line Number 0230, Material Set 6099903, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Material testing results will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 7034041, Project Item Line Number 0380, Material Set 703404196, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Material testing results and Pal Form will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 7034041, Project Item Line Number 0380, Material Set 703404196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Material testing results and Pal Form will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 7034041, Project Item Line Number 0380, Material Set 703404196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Material testing results and Pal Form will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 7061030, Project Item Line Number 0390, Material Set 706103096, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	PAL form will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 7061030, Project Item Line Number 0390, Material Set 706103096, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	PAL form will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 7061030, Project Item Line Number 0390, Material Set 706103096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	PAL form will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 7320018A, Project Item Line Number 0410, Material Set 7320018A96, Material 1020ESAC - Flared End Section Aluminum coated steel, Acceptance Action Generic 1020ESAC is insufficient.	Material certification will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 8051000A, Project Item Line Number 0430, Material Set 8051000A96, Material 0802MLSP - Overspray Slick Paper, Acceptance Action Generic 0802MLSP is insufficient.	Material certification will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 8051000A, Project Item Line Number 0430, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.	Material certification will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 8051000A, Project Item Line Number 0430, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Material certification will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 8064129, Project Item Line Number 0510, Material Set 806412996, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Material certification will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3295, Item 9039902, Project Item Line Number 0520, Material Set 9039902, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient.	Material testing results will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Item Overrun: Contract 220916-C01, Contract Project J4P3295, Project Item Line Number 0540, Contract Line Item Number 0540, Item 5029905, Minor Item.	Item overrun will be addressed in a later Change Order	woodwj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 220916-C01, Contract Project J4P3295, Project Item Line Number 0180, Contract Line Item Number 0180, Item 6085008, Minor Item.	Item overrun will be addressed in a later Change Order	woodwj1	Acknowledged

Revision 3/23/2023 Page 5 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category		Item Code	teport Generated date and can differ from the posted am Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220916-C01	J4P3295	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$77,430.00	\$77,430.00
		0001	0020	2031000	CLASS A EXCAVATION	22,868.00	0.00	22,868.00	CUYD	22,868.00	\$8.80	\$201,238.40
		0001	0030	2036000	COMPACTING EMBANKMENT	2,692.00	0.00	2,692.00	CUYD	2,692.00	\$1.40	\$3,768.80
		0001	0040	2037075	COMPACTING IN CUT	20.00	0.00	20.00	STA	20.00	\$1,257.00	\$25,140.00
		0001	0050	2063000	CLASS 3 EXCAVATION	42.00	0.00	42.00	CUYD	42.00	\$11.80	\$495.60
		0001	0060	2063300	CLASS 4 EXCAVATION	215.00	0.00	215.00	CUYD	215.00	\$24.60	\$5,289.00
		0001	0070	2072000	LINEAR GRADING CLASS 2	7.50	0.00	7.50	STA	4.80	\$1,118.00	\$5,366.40
		0001	0080	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	106.00	0.00	106.00	SQYD	90.00	\$11.30	\$1,017.00
		0001	0090	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	11,472.00	0.00	11,472.00	SQYD	11,472.00	\$14.70	\$168,638.4
		0001	0100	3105003	GRAVEL (A) OR CRUSHED STONE (B)	913.00	0.00	913.00	SQYD	906.00	\$11.70	\$10,600.20
		0001	0110	6029902	MISC.REESTABLISH SECTION CORNER	1.00	0.00	1.00	EA	0.00	\$368.75	\$0.00
		0001	0120	6029902	MISC.WITNESS POST ASSEMBLIES	1.00	0.00	1.00	EA	0.00	\$79.00	\$0.00
		0060	0130	6039903	WATER	2,435.00	0.00	2,435.00	LF	2,435.00	\$144.50	\$351,857.50
		0060	0140	6039902	WATER	11.00	0.00	11.00	EA	11.00	\$6,219.00	\$68,409.00
		0060	0150	6039903	WATER	183.00	0.00	183.00	LF	183.00	\$252.00	\$46,116.00
		0060	0160	6039902		4.00	0.00	00 4.00	EA	4.00	\$4,585.00	\$18,340.00
		0060	0170	6039902	WATER	3.00	0.00	3.00	EA	3.00	\$10,810.00	\$32,430.00
		0001	0180	6085008	PAVED APPROACH, 8 IN.	58.00	0.00	58.00	SQYD	90.00	\$82.40	\$7,416.00
		0001	0190	6089902	MISC.RELOCATE MAILBOX	1.00	0.00	1.00	EA	1.00	\$304.50	\$304.50
		0001	0200	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	150.00	0.00	150.00	CUYD	0.00	\$92.20	\$0.00
		0001	0210	6096041	PLACING TYPE 1 ROCK DITCH LINER	150.00	0.00	150.00	CUYD	0.00	\$42.20	\$0.00
		0001	0220	6097000	ROCK LINING	146.00	0.00	146.00	CUYD	0.00	\$131.50	\$0.00
		0001	0230	6099903	MISC.APWA CURB & GUTTER TYPE CG-1	214.00	0.00	214.00	LF	21.00	\$37.20	\$781.20
		0001	0240	6149902	MISC.MONUMENT BOX	1.00	0.00	1.00	EA	0.00	\$794.50	\$0.00
		0001	0250	6161005	CONSTRUCTION SIGNS	1,805.00	6.00	1,811.00	SQFT	1,305.50	\$6.30	\$8,224.65
		0001	0260	6161096	CHANGEABLE MESSAGE SIGN, COMMISSION FURNISHED / RETAINED	5.00	1.00	6.00	EA	6.00	\$2,633.00	\$15,798.00
		0001	0270	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	1.00	\$5,266.00	\$5,266.0
		0001	0280	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$128,030.00	\$128,030.00
		0001	0290	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN.,	219.00	0.00	219.00	LF	0.00	\$4.75	\$0.00
		0001	0300	6200015	WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	119.00	0.00	119.00	LF	0.00	\$21.10	\$0.00
		0001	0310	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	175.00	0.00	175.00	LF	0.00	\$21.10	\$0.00
		0001	0320	6200021	YELLOW PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	8.00	0.00	8.00	EA	0.00	\$237.00	\$0.00
		0001	0330	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	5,389.00	0.00	5,389.00	LF	4,968.00	\$0.15	\$745.20
		0001	0340	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6,325.00	0.00	6,325.00	LF	5,647.00	\$0.15	\$847.05
		0001	0350	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	670.00	0.00	670.00	SQYD	0.00	\$5.25	\$0.00
		0001	0360	6269909	MISC.OPTIONAL RUMBLE STRIPS	29.70	0.00	29.70	STA	29.70	\$86.90	\$2,580.93
		0001	0370	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$26,750.00	\$26,750.00
		0001	0380	7034041	CLASS B-1 CONCRETE (CULVERTS)	60.00	0.00	60.00	CUYD	60.00	\$1,460.00	\$87,600.00
		0001	0390	7061030	REINFORCING STEEL (CULVERTS)	8,100.00	0.00	8,100.00	LB	8,100.00	\$1.95	\$15,795.0
		0001	0400	7250318A	18 IN. PIPE GROUP B	82.00	0.00	82.00	LF	82.00	\$84.20	\$6,904.4
		0001	0410	7320018A	18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END	2.00	0.00	2.00	EA	2.00	\$1,011.00	\$2,022.00
		0001	0420	8025006	SECTION MULCHING	5.50	0.00	5.50	ACRE	2.25	\$842.50	\$1,895.63
		0001	0430	8051000A	SEEDING - COOL SEASON GRASSES	2.80	0.00	2.80	ACRE	2.25	\$2,317.00	\$5,213.25
									CUYD			\$3,990.00
		0001	0430	8051000A 8061004	SEEDING - COOL SEASON GRASSES SEDIMENT TRAP ROCK	2.80	0.00	2.80				

Revision 3/23/2023 Page 6 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220916-C01	J4P3295	0001	0450	8061005	ROCK DITCH CHECK	90.00	0.00	90.00	LF	90.00	\$36.80	\$3,312.00
		0001	0460	8061006	ALTERNATE DITCH CHECK	4,140.00	0.00	4,140.00	LF	0.00	\$6.05	\$0.00
		0001	0470	8061007A	CURB INLET CHECK	2.00	0.00	2.00	EA	0.00	\$210.75	\$0.00
		0001	0480	8061016	SEDIMENT REMOVAL	352.00	0.00	352.00	CUYD	0.00	\$17.70	\$0.00
		0040	0485	9031280	2.5 IN. PSST POST - 12 GA.	229.00	0.00	229.00	LF	0.00	\$17.10	\$0.00
		0040	0486	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	24.00	0.00	24.00	EA	0.00	\$137.00	\$0.00
		0040	0487	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	24.00	0.00	24.00	EA	0.00	\$407.75	\$0.00
		0001	0490	8061017	TEMPORARY SEEDING	2.70	0.00	2.70	ACRE	0.00	\$1,053.00	\$0.00
		0001	0500	8061019	SILT FENCE	4,247.00	0.00	4,247.00	LF	2,520.00	\$1.55	\$3,906.00
		0001	0510	8064129	TYPE 2 TURF REINFORCEMENT MAT	3,641.00	0.00	3,641.00	SQYD	3,641.00	\$4.15	\$15,110.15
		0040	0520	9039902	MISC.RELOCATION OF EXISTING SIGN ASSEMBLIES	18.00	0.00	18.00	EA	16.00	\$206.00	\$3,296.00
		0003	0540	5029905	MISC.Concrete Pavement	10,559.00	0.00	10,559.00	SQYD	10,669.00	\$72.10	\$769,234.90
		0001	5001	6161030	TYPE III MOVEABLE BARRICADE	0.00	14.00	14.00	EA	14.00	\$173.25	\$2,425.50
	Project J	4P3295 - To	otal Value	Posted to D	late as of Report Generated Date							\$2,133,584.66
220916-C01 Ove	rall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$2,133,584.66

Revision 3/23/2023 Page 7 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4P3295

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	2031000	CLASS A EXCAVATION	6/27/24	7/1/24	1,344.00	CUYD	Permanent Entrance					Paid per plan per agreement with contractor
0030	2036000	COMPACTING EMBANKMENT	6/7/24	7/1/24	2,691.00	CUYD	US 169 / 188th St					2680 CY - US 169 11 CY - 188th St East
0040	2037075	COMPACTING IN CUT	6/27/24	7/1/24	2.00	STA	Permanent Entrance					Paid per plan per agreement with contractor
0070	2072000 LINEAR GRADING CLASS 2		6/24/24	7/1/24	1.10	STA	Culvert Inlet and Outlet	12+00		12+85		Partial Payment - 0.4 STA Culvert Inlet - 0.7 STA Culvert Outlet
			6/27/24	7/1/24	3.70	STA	Herzog Driveway Ditch South of Church					Herzog Driveway - 0.1 STA Ditch South of Church - 3.6 STA
0080	3040504	TYPE 5 AGGREGATE FOR BASE	6/27/24	7/1/24	90.00	SQYD	Herzog Entrance					Entrance was shown to have an area of 58 SY but in the field the entrance was 90 SY. 23 FT long, average width of 35 FT for an area of 90 SY
0090	2040500	TYPE & ACCRECATE FOR BACE (C.IN. THICK)	6/27/24	7/4/04	461.00	COVD	Permanent Entrance					4. 4
		TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)										Paid per plan per agreement with contractor
0100	3105003	GRAVEL (A) OR CRUSHED STONE (B)	6/24/24	7/1/24	806.00	SQYD	US 169 N US 169 S Curve Returns					Partial Payment - 460 SY - Mainline US 169 N - 82 SY - Curve Returns - 264 SY - Mainline US 169 S
			6/27/24	7/1/24	100.00	SQYD	188th St West	0+78		3+29		Partial Payment for 188th St West
0180	6085008	PAVED APPROACH, 8 IN.	6/27/24	7/1/24	90.00	SQYD	Herzog Private Entrance					Entrance was shown to have an area of 58 SY but in the field the entrance was 90 SY.
												23 FT long, average width of 35 FT for an area of 90 SY
0230	6099903	MISC. PAVED DRAINAGE	6/27/24	7/1/24	21.00	LF	West Radius at Herzog Entrance					Partial Payment for Curb and Gutter Replacement
0250	6161005	CONSTRUCTION SIGNS	6/24/24	7/1/24	36.50	SQFT	US 169/188th					- 1/29 - Entered at 65 SQFT instead of 67.5 SQFT - Adding 2.5 SQFT - 5/7 - Missing 2 RCTT signs placed on the roadside to the north and south - 25 SQFT - 6/5 - No Outlet Sign - 9 SQFT
0330	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	6/27/24	7/1/24	4,968.00	LF	US 169 at 188th St					Partial Payment for White Pavement Marking
0340	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	6/27/24	7/1/24	5,647.00	LF	US 169 at 188th St					Partial Payment for White Pavement Marking
0360	6269909	MISC.	6/26/24	7/1/24	29.70	STA	US 169 at 188th St	9+15		26+78		Paid Per Plan
0420	8025006	MULCHING	6/26/24	7/1/24	2.25	ACRE	US 169 188th St West	9+15		26+78		Partial Payment for Mulching US 169 - 1.94 Acre 188th St West - 0.31 Acre
0430	8051000A	SEEDING - COOL SEASON GRASSES	6/26/24	7/1/24	2.25	ACRE	US 169 188th St West	9+15		26+78		Partial Payment for Seeding US 169 - 1.94 Acre 188th St West - 0.31 Acre
0510	8064129	TYPE 2 TURF REINFORCEMENT MAT	6/27/24	7/1/24	3,641.00	SQYD	US 169 188th St West Private Entrance					3641 SY Plan Quantity pending Field Measurement
0540	5029905	MISC.	6/17/24	7/1/24	2,067.00	SQYD	US 169 NB Lane North of 188th St	8+87		19+51		2067 SY STA 8+87 to 19+51 at 16 FT wide
			6/24/24	7/1/24	1,401.00	SQYD	US 169/188th St					Partial Payment - 335 SY - Curve Returns - 325 SY - Walninine US 169 South - 351 SY - 188th St East WB Lane - 133 SY - 188th St West Approach Pavement Subtracting 744 SY to match plan per agreement with contractor
			6/25/24	7/1/24	110.00	SQYD	North Limits Tapered Area at Church Entrance to the South					Line 0540 - Additional Concrete Pavement - 23x32 at the north end to match existing joint - 82 SY - 2FT and 7FT wide and 55 FT long Tapered section at church entrance - 28 SY
5001	6161030	TYPE III MOVEABLE BARRICADE	6/27/24	7/1/24	14.00	EA	US 169/188th St					Additional Type III Barricades needed for full road closur and detour

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023 Page 8 of 16



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J4P3295	0030	COMPACTING EMBANKMENT	Material		17	Jul 1, 2024	SYSTEM	\$3,768.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					17	Jul 1, 2024	SYSTEM	(\$3,768.80)								
				- Total				\$0.00								
			Material - To	otal				\$0.00								
	0030 -	Total						\$0.00								
	0800	TYPE 5 AGGREGATE FOR BASE	Material		17	Jul 1, 2024	SYSTEM	\$1,017.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.							
					17	Jul 1, 2024	SYSTEM	(\$1,017.00)								
				- Total				\$0.00								
			Material - To	otal				\$0.00								
	0080 -	Total						\$0.00								
	0090	TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		15	Jun 3, 2024	SYSTEM	\$12,171.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
		THICK)			15	Jun 3, 2024	SYSTEM	(\$12,171.60)								
						16	Jun 17, 2024	SYSTEM	\$161,861.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					16	Jun 17, 2024	SYSTEM	(\$161,861.70)								
													17	Jul 1, 2024	SYSTEM	\$168,638.40
					17	Jul 1, 2024	SYSTEM	(\$168,638.40)								
				- Total				\$0.00								
			Material - To	I - Total				\$0.00								
	0090 -	Total						\$0.00								
	0100	GRAVEL (A) OR CRUSHED STONE (B)	Material		17	Jul 1, 2024	SYSTEM	\$10,600.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodwj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.							
					17	Jul 1, 2024	SYSTEM	(\$10,600.20)								
				- Total				\$0.00								
			Material - To	Total				\$0.00								
	0100 -	Total						\$0.00								
	0130	WATER - UTILITY ITEM	Material		2	Nov 15, 2023	SYSTEM	\$105,774.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.							
					2	Nov 15, 2023	SYSTEM	(\$105,774.00)								
					3	Dec 4, 2023	SYSTEM	\$213,571.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.							
					3	Dec 4, 2023	SYSTEM	(\$213,571.00)								
					4	Dec 15, 2023	SYSTEM	\$213,571.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.							
					4	Dec 15, 2023	SYSTEM	(\$213,571.00)								
					5	Jan 2, 2024	SYSTEM	\$213,571.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.							
					5	Jan 2, 2024	SYSTEM	(\$213,571.00)								
					6	Jan 16,	SYSTEM	\$213,571.00	This adjustment offsets the original system-generated Material Payment							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																			
J4P3295	0130	WATER - UTILITY ITEM	Material			2024			Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																			
					6	Jan 16, 2024	SYSTEM	(\$213,571.00)																				
					7	Feb 2, 2024	SYSTEM	\$213,571.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																			
					7	Feb 2, 2024	SYSTEM	(\$213,571.00)																				
						8	Feb 16, 2024	SYSTEM	\$351,857.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																		
					8	Feb 16, 2024	SYSTEM	(\$351,857.50)																				
				- Total				\$0.00																				
			Material - To	otal				\$0.00																				
	0130 -	Total						\$0.00																				
	0140	WATER - UTILITY ITEM	Material		2	Nov 15, 2023	SYSTEM	\$12,438.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																			
					2	Nov 15, 2023	SYSTEM	(\$12,438.00)																				
					3	Dec 4, 2023	SYSTEM	\$49,752.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																			
					3	Dec 4, 2023	SYSTEM	(\$49,752.00)																				
					4	Dec 15, 2023	SYSTEM	\$49,752.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																			
					4	Dec 15, 2023	SYSTEM	(\$49,752.00)																				
						5	Jan 2, 2024	SYSTEM	\$49,752.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																		
					5	Jan 2, 2024	SYSTEM	(\$49,752.00)																				
							-	6 6 7 7 8		6	Jan 16, 2024	SYSTEM	\$49,752.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.														
										7 8	6	Jan 16, 2024	SYSTEM	(\$49,752.00)														
																	7	7			7			7	Feb 2, 2024	SYSTEM	\$49,752.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
																	7	Feb 2, 2024	SYSTEM	(\$49,752.00)								
													8	Feb 16, 2024	SYSTEM	\$68,409.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					8	Feb 16, 2024	SYSTEM	(\$68,409.00)																				
				- Total				\$0.00																				
			Material - To	otal				\$0.00																				
	0140 -	Total						\$0.00																				
	0150	WATER - UTILITY ITEM	Material		2	Nov 15, 2023	SYSTEM	\$19,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																			
					2	Nov 15, SYSTEM (\$1 2023	(\$19,656.00)																					
					3	Dec 4, 2023	SYSTEM	\$19,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																			
					3	Dec 4, 2023	SYSTEM	(\$19,656.00)																				



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3295	0150	WATER - UTILITY ITEM	Material		4	Dec 15, 2023	SYSTEM	\$19,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Dec 15, 2023	SYSTEM	(\$19,656.00)	
					5	Jan 2, 2024	SYSTEM	\$19,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Jan 2, 2024	SYSTEM	(\$19,656.00)	
					6	Jan 16, 2024	SYSTEM	\$19,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Jan 16, 2024	SYSTEM	(\$19,656.00)	
					7	Feb 2, 2024	SYSTEM	\$19,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Feb 2, 2024	SYSTEM	(\$19,656.00)	
					8	Feb 16, 2024	SYSTEM	\$46,116.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Feb 16, 2024	SYSTEM	(\$46,116.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0150 -	- Total						\$0.00	
	0160	WATER - UTILITY ITEM	Material		8	Feb 16, 2024	SYSTEM	\$18,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Feb 16, 2024	SYSTEM	(\$18,340.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0160 -	Total						\$0.00	
		- I Olai	Material						
	0170	WATER - UTILITY ITEM	Material		2	Nov 15, 2023	SYSTEM	\$10,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
	0170	WATER - UTILITY	Material		2		SYSTEM SYSTEM		Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment
	0170	WATER - UTILITY	Material			2023 Nov 15,		\$10,810.00	Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment
	0170	WATER - UTILITY	Material		2	2023 Nov 15, 2023 Dec 4,	SYSTEM	\$10,810.00 (\$10,810.00)	Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment
	0170	WATER - UTILITY	Material		2	2023 Nov 15, 2023 Dec 4, 2023	SYSTEM SYSTEM	\$10,810.00 (\$10,810.00) \$21,620.00	Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment
	0170	WATER - UTILITY	Material		3	2023 Nov 15, 2023 Dec 4, 2023 Dec 4, 2023 Dec 15,	SYSTEM SYSTEM SYSTEM	\$10,810.00 (\$10,810.00) \$21,620.00 (\$21,620.00)	Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment
	0170	WATER - UTILITY	Material		2 3 3 4	2023 Nov 15, 2023 Dec 4, 2023 Dec 4, 2023 Dec 15, 2023	SYSTEM SYSTEM SYSTEM SYSTEM	\$10,810.00 (\$10,810.00) \$21,620.00 (\$21,620.00) \$21,620.00	Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment
	0170	WATER - UTILITY	Material		2 3 3 4	2023 Nov 15, 2023 Dec 4, 2023 Dec 15, 2023 Dec 15, 2023 Jan 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$10,810.00 (\$10,810.00) \$21,620.00 (\$21,620.00) \$21,620.00	Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment
	0170	WATER - UTILITY	Material		2 3 3 4 4 5	2023 Nov 15, 2023 Dec 4, 2023 Dec 15, 2023 Dec 15, 2023 Jan 2, 2024 Jan 2, 2015	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$10,810.00 (\$10,810.00) \$21,620.00 (\$21,620.00) \$21,620.00 (\$21,620.00)	Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment
	0170	WATER - UTILITY	Material		2 3 3 4 4 5 5 5 5	2023 Nov 15, 2023 Dec 4, 2023 Dec 15, 2023 Dec 15, 2023 Jan 2, 2024 Jan 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$10,810.00 (\$10,810.00) \$21,620.00 (\$21,620.00) \$21,620.00 (\$21,620.00) (\$21,620.00)	Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.
	0170	WATER - UTILITY	Material		2 3 3 4 4 5 5 5 6 6	2023 Nov 15, 2023 Dec 4, 2023 Dec 15, 2023 Dec 15, 2023 Jan 2, 2024 Jan 16, 2024 Jan 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$10,810.00 (\$10,810.00) \$21,620.00 (\$21,620.00) \$21,620.00 (\$21,620.00) \$21,620.00 (\$21,620.00)	Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J4P3295	0170	WATER - UTILITY ITEM	Material		8	Feb 16, 2024	SYSTEM	\$32,430.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
					8	Feb 16, 2024	SYSTEM	(\$32,430.00)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
	0170 -	· Total						\$0.00													
	0180	PAVED APPROACH, 8 IN.	Material		17	Jul 1, 2024	SYSTEM	\$7,416.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.												
					17	Jul 1, 2024	SYSTEM	(\$7,416.00)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
			Overrun	Overrun	17	Jul 1, 2024	SYSTEM	(\$2,636.80)													
				Overrun - To	otal			(\$2,636.80)													
			Overrun - T	otal				(\$2,636.80)													
	0180 -	· Total						(\$2,636.80)													
	0180 -	MISC. PAVED DRAINAGE	Material		17	Jul 1, 2024	SYSTEM	\$781.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodwj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.												
					17	Jul 1, 2024	SYSTEM	(\$781.20)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
	0230 -	· Total						\$0.00													
	0260	CHANGEABLE MESSAGE SIGN, COMM. FURNISHED	Overrun	Overrun	8	Feb 16, 2024	SYSTEM	(\$2,633.00)													
					12	Apr 17, 2024	SYSTEM	\$2,633.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2633.00000 - 2633.00000, 'is applied (if non-zero).												
				Overrun - To	otal			\$0.00													
			Overrun - T	otal				\$0.00													
	0260 -	Total						\$0.00													
	0380	CLASS B-1 CONCRETE (CULVERTS)	Material		16	Jun 17, 2024	SYSTEM	\$87,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodwj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.												
					16	Jun 17, 2024	SYSTEM	(\$87,600.00)													
																	17	Jul 1, 2024	SYSTEM	\$87,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					17	Jul 1, 2024	SYSTEM	(\$87,600.00)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
	0380 -	Total						\$0.00													
	0390	REINFORCING STEEL (CULVERTS)	Material		16	Jun 17, 2024	SYSTEM	\$15,795.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.												
					16	Jun 17, 2024	SYSTEM	(\$15,795.00)													
					17	Jul 1, 2024	SYSTEM	\$15,795.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.												
					17	Jul 1, 2024	SYSTEM	(\$15,795.00)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3295	0390 -	Total						\$0.00	
	0410	18 IN. GROUP B FLARED END SEC	Material		16	Jun 17, 2024	SYSTEM	\$2,022.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					16	Jun 17, 2024	SYSTEM	(\$2,022.00)	
					17	Jul 1, 2024	SYSTEM	\$2,022.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodwj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					17	Jul 1, 2024	SYSTEM	(\$2,022.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0410 -	Total						\$0.00	
		SEEDING - COOL SEASON GRASSES	Material		17	Jul 1, 2024	SYSTEM	\$5,213.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodwj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					17	Jul 1, 2024	SYSTEM	(\$5,213.25)	
				- Total				\$0.00	
			Material - To					\$0.00	
	0430 -	Total						\$0.00	
	0440	SEDIMENT TRAP ROCK	Material		16	Jun 17, 2024	SYSTEM	\$3,990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					16	Jun 17, 2024	SYSTEM	(\$3,990.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0440 -	Total						\$0.00	
	0450	ROCK DITCH CHECK	Material		16	Jun 17, 2024	SYSTEM	\$3,312.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodwj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					16	Jun 17, 2024	SYSTEM	(\$3,312.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0450 -	Total						\$0.00	
	0500	SILT FENCE	Material		2	Nov 15, 2023	SYSTEM	\$3,906.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodwj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	Nov 15, 2023	SYSTEM	(\$3,906.00)	
					3	Dec 4, 2023	SYSTEM	\$3,906.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodwj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Dec 4, 2023	SYSTEM	(\$3,906.00)	
					4	Dec 15, 2023	SYSTEM	\$3,906.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodwj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Dec 15, 2023	SYSTEM	(\$3,906.00)	
					5	Jan 2, 2024	SYSTEM	\$3,906.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodwj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Jan 2, 2024	SYSTEM	(\$3,906.00)	
						6	Jan 16, 2024	SYSTEM	\$3,906.00
					6	Jan 16, 2024	SYSTEM	(\$3,906.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J4P3295	0500	SILT FENCE	Material		7	Feb 2, 2024	SYSTEM	\$3,906.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodwj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.								
					7	Feb 2, 2024	SYSTEM	(\$3,906.00)									
					8	Feb 16, 2024	SYSTEM	\$3,906.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.								
					8	Feb 16, 2024	SYSTEM	(\$3,906.00)									
					9	Mar 1, 2024	SYSTEM	\$3,906.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					9	Mar 1, 2024	SYSTEM	(\$3,906.00)									
					10	Mar 15, 2024	SYSTEM	\$3,906.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					10	Mar 15, 2024	SYSTEM	(\$3,906.00)									
					11	Apr 1, 2024	SYSTEM	\$3,906.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					11	Apr 1, 2024	SYSTEM	(\$3,906.00)									
					12	Apr 17, 2024	SYSTEM	\$3,906.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					12	Apr 17, 2024	SYSTEM	(\$3,906.00)									
					13	May 1, 2024	SYSTEM	\$3,906.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					13	May 1, 2024	SYSTEM	(\$3,906.00)									
					14	May 16, 2024	SYSTEM	\$3,906.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					14	May 16, 2024	SYSTEM	(\$3,906.00)									
											1	15	15	Jun 3, 2024	SYSTEM	\$3,906.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					15	Jun 3, 2024	SYSTEM	(\$3,906.00)									
				- Total				\$0.00									
	0500	Total	Material - To	otal				\$0.00									
	0500 - 0510	TYPE 2 TURF REINFORCEMENT MAT	Material		17	Jul 1, 2024	SYSTEM	\$0.00 \$15,110.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.								
					17	Jul 1, 2024	SYSTEM	(\$15,110.15)									
				- Total				\$0.00									
			Material - To	otal				\$0.00									
	0510 -	Total						\$0.00									
	0520	MISC.	Material		16	Jun 17, 2024	SYSTEM	\$3,296.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodwj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.								
				16	16	Jun 17, 2024	SYSTEM	(\$3,296.00)									
						Jul 1, 2024	SYSTEM	\$3,296.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.								
					17	Jul 1, 2024	SYSTEM	(\$3,296.00)									

Jul 3, 2024



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4P3295	0520	MISC.	Material	- Total				\$0.00		
			Material - To	otal				\$0.00		
	0520 -	Total						\$0.00		
	0540	MISC.	Material		15	Jun 3, 2024	SYSTEM	\$26,388.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					15	Jun 3, 2024	SYSTEM	(\$26,388.60)		
					16	Jun 17, 2024	SYSTEM	\$511,261.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					16	Jun 17, 2024	SYSTEM	(\$511,261.10)		
							17	Jul 1, 2024	SYSTEM	\$769,234.90
					17	Jul 1, 2024	SYSTEM	(\$769,234.90)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
			Overrun	Overrun	17	Jul 1, 2024	SYSTEM	(\$7,931.00)		
				Overrun - T	otal			(\$7,931.00)		
			Overrun - To	otal				(\$7,931.00)		
	0540 -	· Total						(\$7,931.00)		
J4P3295	Total							(\$10,567.80)		
Overall -	Total							(\$10,567.80)		

MoDOT

Contract Adjustments for Contract - 220916-C01

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 16 of 16