

Pay Estimate Created Date: June 30, 2023

Progress Estimate Number	Contract ID	221021-C02	Pay Period Start	June 16, 2023	Original Contract Amoun	nt \$4,918,576.89
8	Prime Contractor	Radmacher Brothers Excavating Co.,Inc.	Pay Period End	June 30, 2023	Net Change Order Amount Current Contract Amoun	\$44,623.40 at \$4,963,200.29

By User		Approval Date
frizzm	Generated and Approved (and should be considered Draft) at the Project Office Level by	June 30, 2023
sandis1	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	July 3, 2023
ramses1	Reviewed and Approved at the Central Office Controllers Office Level by	July 5, 2023

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2023	December 1, 2023		63.55%

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	November 2, 2022	November 2, 2022	
Letting Date	October 21, 2022	October 21, 2022	
Notice to Proceed Date	December 21, 2022	December 21, 2022	
Open to Traffic Date			
Work Began Date			

Contract Total P	ay For Estimate No. 8			
		This Estimate	Previous	To Date
221021-C02				
	Total Posted Items Pay	\$290,266.45	\$2,863,840.37	\$3,154,106.82
	Gross Item Adjustments	\$954.00	\$330,345.52	\$331,299.52
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	·		\$3,194,185.89	\$3,485,406.34
Contract Total P	avable This Estimate:	\$291 220 45		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4I3451	0280	6161033	DIRECTIONAL INDICATOR BARRICADE	EA	\$106.000	17	\$1,802.00
	0330	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	LF	\$212.500	140	\$29,750.00
	0930	7011206	ROCK SOCKETS (4 FT 0 IN. DIA.)	LF	\$615.500	63	\$38,776.50
	0940	7011300	VIDEO CAMERA INSPECTION	EA	\$53.000	3	\$159.00
	0960	7011600	SONIC LOGGING TESTING	EA	\$1,589.500	3	\$4,768.50
	0970	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	LF	\$135.500	280	\$37,940.00
	0980	7025002	PILE WAVE ANALYSIS	EA	\$530.000	2	\$1,060.00
	0990	7026000	PRE-BORE FOR PILING	LF	\$84.750	210	\$17,797.50
	1000	7027000	PILE POINT REINFORCEMENT	EA	\$133.000	14	\$1,862.00
	1010	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	CUYD	\$1,058.500	54.5	\$57,688.25
	1020	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	CUYD	\$1,131.000	49.3	\$55,758.30
	1060	7061060	REINFORCING STEEL (BRIDGES)	LB	\$2.000	4,940	\$9,880.00
	1070	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$2.000	11,720	\$23,440.00
	5005	6161055	SEQUENTIAL FLASHING WARNING LIGHT	EA	\$171.150	56	\$9,584.40
Project J4I3451	- Total						\$290,266.45
Overall - Total							\$290,266.45

Contract Adjustments This Estimate



Pay Estimate Created Date: June 30, 2023

Pay Period Start June 16, 2023 **Progress Estimate** Original Contract Amount \$4,918,576.89 **Contract ID** 221021-C02 Number Pay Period End June 30, 2023 Prime Radmacher Brothers Excavating Net Change Order 8 \$44,623.40 Amount \$44,623.40

Current Contract Amount \$4,963,200.29 Contractor Co.,Inc.

	Lin	Itania Dania ili	A disease of	Oth !!	0	A disease of	Line U	A disease
ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
451	0090	MISC.	Material			-2,783	\$22.75	(\$63,313.25)
	0090	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.	2,783	\$22.75	\$63,313.25
	0130	TACK COAT - LOW OR NON-TRACKING	Material			-241	\$5.25	(\$1,265.25)
	0130	TACK COAT - LOW OR NON-TRACKING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.	241	\$5.25	\$1,265.25
	0150	CONCRETE APPROACH PAVEMENT	Material			-351.2	\$157.00	(\$55,138.40)
	0150	CONCRETE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.	351.2	\$157.00	\$55,138.40
	0280	DIRECTIONAL INDICATOR BARRICADE	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',106.00000 - 106.00000, 'is applied (if non-zero).	9	\$106.00	\$954.00
	0330	CONCRETE TRAFFIC BARRIER, TYPE B	Material			-140	\$212.50	(\$29,750.00
	0330	CONCRETE TRAFFIC BARRIER, TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 21 on the current Payment Estimate.	140	\$212.50	\$29,750.00
	0350	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material			-3,352.5	\$16.50	(\$55,316.25)
	0350	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 23 on the current Payment Estimate.	3,352.5	\$16.50	\$55,316.25
	0410	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-24,409	\$0.50	(\$12,204.50)
	0410	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 24 on the current Payment Estimate.	24,409	\$0.50	\$12,204.50
	0420	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-20,558	\$0.50	(\$10,279.00)
	0420	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 26	20,558	\$0.50	\$10,279.00

Revision 3/23/2023 Page 2 of 28



Pay Estimate Created Date: June 30, 2023

Progress Estimate Number 8 Contract ID 221021-C02 Pay Period Start 2023 Original Contract Amount \$4,918,576.89

Prime Radmacher Brothers Excavating Co.,Inc. Pay Period End June 16, 2023 Original Contract Amount \$4,918,576.89

Pay Period End June 16, 2023 Original Contract Amount \$4,918,576.89

Pay Period End June 16, 2023 Original Contract Amount \$4,918,576.89

Pay Period End June 16, 2023 Original Contract Amount \$4,918,576.89

Pay Period End June 30, 2023 Original Contract Amount \$4,963,200.29

er	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
1					on the current Payment Estimate.			
	0590	MGS GUARDRAIL	Material			-1,162.5	\$28.50	(\$33,131.25
	0590	MGS GUARDRAIL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 15 on the current Payment Estimate.	1,162.5	\$28.50	\$33,131.25
	0600	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	Material			-2	\$3,932.00	(\$7,864.00
	0600	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 17 on the current Payment Estimate.	2	\$3,932.00	\$7,864.00
	0610	MGS END ANCHOR	Material			-1	\$1,430.50	(\$1,430.50
	0610	MGS END ANCHOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 18 on the current Payment Estimate.	1	\$1,430.50	\$1,430.50
	0620	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material			-1	\$3,410.50	(\$3,410.50
	0620	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 19 on the current Payment Estimate.	1	\$3,410.50	\$3,410.50
	0700	BRIDGE APPROACH SLAB (MAJOR)	Material			-252	\$299.50	(\$75,474.00
	0700	BRIDGE APPROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.	252	\$299.50	\$75,474.00
	0710	ROCK SOCKETS (4 FT 0 IN. DIA.)	Material			-75	\$564.00	(\$42,300.00
	0710	ROCK SOCKETS (4 FT 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 28 on the current Payment Estimate.	75	\$564.00	\$42,300.00
	0790	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-58.5	\$999.50	(\$58,470.75
	0790	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user frizzm overridding Payment Estimate Exception 29 on the current Payment Estimate.	58.5	\$999.50	\$58,470.75
	0800	CLASS B-1 CONCRETE (SUBSTRUCTURE)	Material			-51.8	\$1,086.00	(\$56,254.80
	0800	CLASS B-1 CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user frizzm overridding Payment Estimate Exception 35 on the current Payment Estimate.	51.8	\$1,086.00	\$56,254.80
	0810	TYPE D BARRIER	Material			-416	\$102.50	(\$42,640.00



Pay Estimate Created Date: June 30, 2023

Progress Estimate Number 8 Contract ID 221021-C02 Pay Period Start 2023 Original Contract Amount \$4,918,576.89

Prime Radmacher Brothers Excavating Co.,Inc. Pay Period End June 16, 2023 Original Contract Amount \$4,918,576.89

Pay Period End June 16, 2023 Original Contract Amount \$4,918,576.89

Pay Period End June 16, 2023 Original Contract Amount \$4,918,576.89

Pay Period End June 16, 2023 Original Contract Amount \$4,918,576.89

Pay Period End June 30, 2023 Original Contract Amount \$4,963,200.29

	Lina	Itam Description	A diverse of	Oth It - · ·	0	Adirect	l in - lt	۸ ما:۰۰-۱
	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
51 (0810	TYPE D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user frizzm overridding Payment Estimate Exception 38 on the current Payment Estimate.	416	\$102.50	\$42,640.00
(0820	SLAB ON CONCRETE NU- GIRDER	Material			-1,230	\$397.00	(\$488,310.00
(0820	SLAB ON CONCRETE NU- GIRDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user frizzm overridding Payment Estimate Exception 39 on the current Payment Estimate.	1,230	\$397.00	\$488,310.00
(0850	REINFORCING STEEL (EPOXY COATED)	Material			-11,770	\$2.00	(\$23,540.00
(0850	REINFORCING STEEL (EPOXY COATED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user frizzm overridding Payment Estimate Exception 43 on the current Payment Estimate.	11,770	\$2.00	\$23,540.00
(0860	VERTICAL DRAIN AT END BENTS	Material			-2	\$3,959.00	(\$7,918.00
	0860	VERTICAL DRAIN AT END BENTS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user frizzm overridding Payment Estimate Exception 45 on the current Payment Estimate.	2	\$3,959.00	\$7,918.00
(0870	PLAIN NEOPRENE BEARING PAD	Material			-12	\$152.00	(\$1,824.00
(0870	PLAIN NEOPRENE BEARING PAD	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user frizzm overridding Payment Estimate Exception 46 on the current Payment Estimate.	12	\$152.00	\$1,824.00
(0880	LAMINATED NEOPRENE BEARING PAD	Material			-12	\$188.00	(\$2,256.00
(0880	LAMINATED NEOPRENE BEARING PAD	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment Estimate Exception 47 on the current Payment Estimate.	12	\$188.00	\$2,256.00
	1010	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-54.5	\$1,058.50	(\$57,688.25
	1010	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 32 on the current Payment Estimate.	54.5	\$1,058.50	\$57,688.25
	1020	CLASS B-1 CONCRETE (SUBSTRUCTURE)	Material			-49.3	\$1,131.00	(\$55,758.30
	1020	CLASS B-1 CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user frizzm overridding Payment Estimate Exception 37 on the current Payment Estimate.	49.3	\$1,131.00	\$55,758.30
	1060	REINFORCING STEEL (BRIDGES)	Material			-4,940	\$2.00	(\$9,880.00
	1060	REINFORCING STEEL	Material		This adjustment offsets the original system-	4,940	\$2.00	\$9,880.00

Revision 3/23/2023 Page 4 of 28



Pay Estimate Created Date: June 30, 2023

Progress Estimate Number 8

Contract ID 221021-C02 Pay Period Start 2023 Original Contract Amount \$4,918,576.89

Prime Radmacher Brothers Excavating Contractor Co.,Inc.

Pay Period Start 2023 Original Contract Amount \$4,918,576.89

Pay Period End June 30, 2023 Net Change Order Amount \$44,623.40

Current Contract Amount \$4,963,200.29

ψ 4 ,905,200.29	i uot 7 ii ii oui it							
Adjustment amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	Item Description	Line No.	Project Number
			generated Material Payment Estimate Item Adjustment (0025) due to user frizzm overridding Payment Estimate Exception 42 on the current Payment Estimate.			(BRIDGES)		J4I3451
(\$23,440.00	\$2.00	-11,720			Material	REINFORCING STEEL (EPOXY COATED)	1070	
\$23,440.00	\$2.00	11,720	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user frizzm overridding Payment Estimate Exception 44 on the current Payment Estimate.		Material	REINFORCING STEEL (EPOXY COATED)	1070	
(\$9,584.40	\$171.15	-56			Material	SEQUENTIAL FLASHING WARNING LIGHT	5005	
\$9,584.40	\$171.15	56	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user frizzm overridding Payment Estimate Exception 20 on the current Payment Estimate.		Material	SEQUENTIAL FLASHING WARNING LIGHT	5005	
\$954.00							,	Total

Revision 3/23/2023 Page 5 of 28



					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J4I3451	I 435-1(333)	2 Bridge replacements	I-435	JACKSON	over 87th Street, 1.1 miles north of Route W and 2.2 miles south of Gregory Boulevard near Raytown

J41343 I	435-1(333)	replacements	1-435	JACKSON	over orth Sheet, 1.1 h	niles notified foote wand 2.2	miles south of Gregory Boulevard
otals by	Job Numbers						
J4I3451					This Estimate	Previous	To Date
	Posted	Item Pay			\$290,266.45	\$2,863,840.37	\$3,154,106.82
	Gross It	em Adjustment	ts		\$954.00	\$330,345.52	\$331,299.52
		Gross Item Pay			\$291,220.45	\$3,194,185.89	\$3,485,406.34
	Incentiv	Incentive			\$0.00	\$0.00	\$0.00
	Disince	ntive			\$0.00	\$0.00	\$0.00
	Liquidat	ted Damages			\$0.00	\$0.00	\$0.00
	Other C	ontract Adjustn	nents		\$0.00	\$0.00	\$0.00

Revision 3/23/2023 Page 6 of 28



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 3049905, Project Item Line Number 0090, Material Set 304990596, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 3049905, Project Item Line Number 0090, Material Set 304990596, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 4071007, Project Item Line Number 0130, Material Set 407100796, Material 1015EASS1VH - Emulsified Asphalt - Trackless Tack, Acceptance Action Generic AspEmulsion is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 5031010A, Project Item Line Number 0700, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 5031010A, Project Item Line Number 0700, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 5031010A, Project Item Line Number 0700, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 5031010A, Project Item Line Number 0700, Material Set 5031010A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 5031010A, Project Item Line Number 0700, Material Set 5031010A96, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 5041000, Project Item Line Number 0150, Material Set 504100096, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 5041000, Project Item Line Number 0150, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 5041000, Project Item Line Number 0150, Material Set 504100096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 5041000, Project Item Line Number 0150, Material Set 504100096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action 0501CCPAQCQA Pavement is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 5041000, Project Item Line Number 0150, Material Set 504100096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 5041000, Project Item Line Number 0150, Material Set 504100096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 6061060, Project Item Line Number 0590, Material Set 606106096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 6061060, Project Item Line Number 0590, Material Set 606106096, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 6061068, Project Item Line Number 0600, Material Set 606106896, Material 1040GRAB - Bridge Anchor Section, Acceptance Action Generic 1040GRAB is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 6061080, Project Item Line Number 0610, Material Set 606108096, Material 1040GRBEESCAT2 - Breakaway End Anchor End Sect Cl A Typ 2, Acceptance Action Generic 1040GRBEESCAT2 is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 6063014, Project Item Line Number 0620, Material Set 606301496, Material 1040GRCWA - Crashworthy End Terminal Type A, Acceptance Action Generic 1040GRCWA is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve	frizzm	Overridden

Revision 3/23/2023 Page 7 of 28



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepencies	Explanation	Entered By	Status
	exception. frizzm 6/30/23		
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 6161055, Project Item Line Number 5005, Material Set 616105596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 6172000, Project Item Line Number 0330, Material Set 617200096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 6172000, Project Item Line Number 0330, Material Set 617200096, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 6173600D, Project Item Line Number 0350, Material Set 6173600D96, Material 0617TCRCTF - Type F Concrete Traffic Barrier, Acceptance Action Generic 0617TCRCTF is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 6205902A, Project Item Line Number 0410, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 6205902A, Project Item Line Number 0410, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 6205903A, Project Item Line Number 0420, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 6205903A, Project Item Line Number 0420, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 7011206, Project Item Line Number 0710, Material Set 701120696, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 7032003, Project Item Line Number 0790, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 7032003, Project Item Line Number 0790, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 7032003, Project Item Line Number 0790, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 7032003, Project Item Line Number 1010, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 7032003, Project Item Line Number 1010, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 7032003, Project Item Line Number 1010, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 7034003, Project Item Line Number 0800, Material Set 703400396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 7034003, Project Item Line Number 0800, Material Set 703400396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 7034003, Project Item Line Number 1020, Material Set 703400396, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 7034219A, Project Item Line	M. Frizzell met with D. Allred (MoDOT Material Inspector) on	frizzm	Overridden

Revision 3/23/2023 Page 8 of 28



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Number 0810, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23		
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 7034221, Project Item Line Number 0820, Material Set 703422196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 7034221, Project Item Line Number 0820, Material Set 703422196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 7034221, Project Item Line Number 0820, Material Set 703422196, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 7061060, Project Item Line Number 1060, Material Set 706106096, Material 1036RSDFPL42M29 - Reinforcing Steel No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 7101000, Project Item Line Number 0850, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 7101000, Project Item Line Number 1070, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 7151001, Project Item Line Number 0860, Material Set 715100196, Material 0715DRVT - Vertical Drain at End Bents, Acceptance Action Generic 0715DRVT is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 7161000, Project Item Line Number 0870, Material Set 716100096, Material 1038BBPD - Bridge Bearing Pad, Acceptance Action Generic 1038BBPD is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 7161002, Project Item Line Number 0880, Material Set 716100296, Material 1038BBPD - Bridge Bearing Pad, Acceptance Action Generic 1038BBPD is insufficient.	M. Frizzell met with D. Allred (MoDOT Material Inspector) on 6/23/23 to discuss material exception. Project Office staff will continue to work with KC Materials and RBE QC to resolve exception. frizzm 6/30/23	frizzm	Overridden
Estimate Exception Type: Item Overrun: Contract 221021-C02, Contract Project J4l3451, Project Item Line Number 0120, Contract Line Item Number 0120, Item 4030206, Minor Item.	A change order will be processed to address the overrun. frizzm 6/30/23	frizzm	Acknowledged
Estimate Exception Type: Item Overrun: Contract 221021-C02, Contract Project J4l3451, Project Item Line Number 0410, Contract Line Item Number 0410, Item 6205902A, Minor Item.	A change order will be processed to address the overrun. frizzm 6/30/23	frizzm	Acknowledged
Estimate Exception Type: Item Overrun: Contract 221021-C02, Contract Project J4l3451, Project Item Line Number 0420, Contract Line Item Number 0420, Item 6205903A, Minor Item.	A change order will be processed to address the overrun. frizzm 6/30/23	frizzm	Acknowledged

Revision 3/23/2023 Page 9 of 28



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See report generated date)
1021-C02	J4I3451	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.70	\$44,107.50	\$30,875.
		0001	0020	2031000	CLASS A EXCAVATION	672.00	0.00	672.00	CUYD	0.00	\$10.75	\$0.
		0001	0030	2036000	COMPACTING EMBANKMENT	580.00	0.00	580.00	CUYD	0.00	\$1.25	\$0.
		0001	0040	2063000	CLASS 3 EXCAVATION	8.00	0.00	8.00	CUYD	0.00	\$12.00	\$0.
		0001	0050	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	18.00	0.00	18.00	100F	0.00	\$441.50	\$0.
		0001	0060	2153000	SHAPING SLOPES, CLASS III	23.00	0.00	23.00	100F	0.00	\$770.50	\$0.
		0001	0070	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	624.00	0.00	624.00	SQYD	0.00	\$11.00	\$0.
		0001	0080	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	702.00	0.00	702.00	SQYD	0.00	\$13.75	\$0.
		0001	0090	3049905	MISC.TYPE 5 AGGREGATE 8 IN. THICK	2,783.00	0.00	2,783.00	SQYD	2,783.00	\$22.75	\$63,313
		0001	0100	4019905	MISC.OPTIONAL PAVEMENT	2,783.30	0.00	2,783.30	SQYD	2,783.30	\$82.75	\$230,318
		0001	0110	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	619.00	0.00	619.00	TONS	553.46	\$175.00	\$96,855
		0001	0120	4030206	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP190C MIX)	979.30	0.00	979.30	TONS	1,054.53	\$166.50	\$175,579
		0001	0130	4071007	TACK COAT - LOW OR NON-TRACKING	979.00	0.00	979.00	GAL	241.00	\$5.25	\$1,265
		0001	0140	5029905	MISC.4 IN. CONCRETE PAVEMENT (DECORATIVE)	324.70	0.00	324.70	SQYD	0.00	\$70.00	\$0
		0001	0150	5041000	CONCRETE APPROACH PAVEMENT	702.40	0.00	702.40	SQYD	351.20	\$157.00	\$55,138
			0160	6083008	8 IN. CONCRETE MEDIAN STRIP	139.40	0.00	139.40	SQYD	0.00	\$74.00	\$00,100
		0001	0170	6086004	CONCRETE SIDEWALK, 4 IN.	159.70	0.00	159.40	SQYD	0.00	\$48.25	\$(
		0001			MISC.FURNISHING ROCK SLOPE PROTECTION							
		0001	0180	6099907		242.00	0.00	242.00	CUYD	0.00	\$58.00	\$1
		0001	0190	6099907	MISC.PLACING ROCK SLOPE PROTECTION	242.00	0.00	242.00	CUYD	0.00	\$56.00	\$
		0001	0200	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	3.00	0.00	3.00	EA	3.00	\$4,239.00	\$12,71
		0001	0210	6122030	IMPACT ATTENUATOR (RELOCATION)	4.00	0.00	4.00	EA	2.00	\$1,854.50	\$3,70
		0001	0220	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$2,490.50	\$
		0001	0230	6141028	GRATE AND BEARING PLATE (5 FT. 1 IN. X 3 FT. 1 IN. OR 1549 MM X 940 MM)	1.00	0.00	1.00	EA	0.00	\$2,692.00	\$1
		0001	0240	6161005	CONSTRUCTION SIGNS	1,479.00	0.00	1,479.00	SQFT	1,479.00	\$10.50	\$15,529
		0001	0250	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$132.50	\$53
		0001	0260	6161025	CHANNELIZER (TRIM LINE)	434.00	0.00	434.00	EA	206.00	\$39.25	\$8,08
		0001	0270	6161030	TYPE III MOVEABLE BARRICADE	28.00	0.00	28.00	EA	26.00	\$286.00	\$7,43
		0001	0280	6161033	DIRECTIONAL INDICATOR BARRICADE	30.00	26.00	56.00	EA	56.00	\$106.00	\$5,93
		0001	0290	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	4.00	\$2,596.50	\$10,38
		0001	0300	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$10,333.00	\$41,33
		0001	0310	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	7.00	0.00	7.00	EA	7.00	\$1,430.50	\$10,01
		0001	0320	6169902	MISC.ADA COMPLIANT MOVEABLE BARRICADE	4.00	0.00	4.00	EA	4.00	\$106.00	\$42
		0001	0330	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	350.00	0.00	350.00	LF	140.00	\$212.50	\$29,75
		0001	0340	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	794.00	0.00	794.00	LF	0.00	\$99.25	\$
		0001	0350	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	5,135.00	-750.00	4,385.00	LF	3,352.50	\$16.50	\$55,31
		0001	0360	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	10,438.00	-750.00	9,688.00	LF	3,580.00	\$9.25	\$33,11
		0001	0370	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$191,409.50	\$191,40
		0001	0380	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	2.00	0.00	2.00	EA	0.00	\$600.00	\$
		0001	0390	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	41,586.00	0.00	41,586.00	LF	0.00	\$1.50	\$
		0001	0400	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	35,833.00	0.00	35,833.00	LF	0.00	\$1.50	\$
		0001	0410	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	21,622.00	0.00	21,622.00	LF	24,409.00	\$0.50	\$12,20
		0001	0420	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	13,614.00	0.00	13,614.00	LF	20,558.00	\$0.50	\$10,27
		0001	0430	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,578.00	0.00	2,578.00	LF	0.00	\$2.75	\$1
		0001	0440	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	1,102.00	0.00	1,102.00	LF	0.00	\$0.40	\$1

Revision 3/23/2023 Page 10 of 28



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See repor- generated date)
221021-C02	J4I3451	0001	0450	6207001	PAVEMENT MARKING REMOVAL	38,029.00	0.00	38,029.00	LF	10,608.00	\$0.40	\$4,243.2
		0001	0460	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	6,525.00	0.00	6,525.00	SQYD	4,869.10	\$13.25	\$64,515.5
		0001	0470	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	58.10	0.00	58.10	STA	0.00	\$96.75	\$0.0
		0001	0480	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.70	\$18,016.50	\$12,611.5
		0001	0490	7261018	18 IN. PIPE GROUP A	650.00	0.00	650.00	LF	650.00	\$53.00	\$34,450.0
		0001	0500	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	2.00	0.00	2.00	FT	0.00	\$2,371.00	\$0.0
		0001	0510	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	0.00	\$387.00	\$0.0
		0001	0520	8025006	MULCHING	0.60	0.00	0.60	ACRE	0.00	\$2,584.50	\$0.
		0001	0530	8051000A	SEEDING - COOL SEASON GRASSES	0.50	0.00	0.50	ACRE	0.00	\$3,075.00	\$0.
		0001	0540	8061005	ROCK DITCH CHECK	8.00	0.00	8.00	LF	0.00	\$15.25	\$0.
		0001	0550	8061007A	CURB INLET CHECK	4.00	0.00	4.00	EA	0.00	\$95.50	\$0.
		0001	0560	8061016	SEDIMENT REMOVAL	28.00	0.00	28.00	CUYD	0.00	\$94.50	\$0.
		0001	0570	8061017	TEMPORARY SEEDING	0.10	0.00	0.10	ACRE	0.00	\$2,295.50	\$0.
		0001	0580	8061019	SILT FENCE	2,553.00	0.00	2,553.00	LF	0.00	\$1.75	\$0.
		0010	0590	6061060	MGS GUARDRAIL	2,100.00	0.00	2,100.00	LF	1,162.50	\$28.50	\$33,131.
		0010	0600	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	6.00	0.00	6.00	EA	2.00	\$3,932.00	\$7,864.
		0010	0610	6061080	MGS END ANCHOR	3.00	0.00	3.00	EA	1.00	\$1,430.50	\$1,430
		0010	0620	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3.00	0.00	3.00	EA	1.00	\$3,410.50	\$3,410
		0010	0630	6069902	MISC.CABLE TO GUARDRAIL TRANSITION	3.00	0.00	3.00	EA	0.00	\$4,815.50	\$0
		0010	0640	6069902	MISC.HTGC ANCHOR ASSEMBLY	3.00	0.00	3.00	EA	0.00	\$4,345.00	\$0
		0010	0650	6069903	MISC.HIGH TENSION GUARD CABLE	840.00	0.00	840.00	LF	0.00	\$39.25	\$0
		0040	0660	9039902	MISC.RELOCATION OF EXISTING SIGN ASSEMBLIES	4.00	0.00	4.00	EA	0.00	\$106.00	\$0
		0070	0675	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	18.00	0.00	18.00	SQFT	18.00	\$153.50	\$2,763
		0070	0680	2061000	CLASS 1 EXCAVATION	110.00	0.00	110.00	CUYD	110.00	\$68.75	\$7,562
		0070	0690	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS		\$105,929.00	\$105,929
		0070	0700	5031010A	BRIDGE APPROACH SLAB (MAJOR)	252.00	0.00	252.00	SQYD	252.00	\$299.50	\$75,474
		0070	0710	7011206	ROCK SOCKETS (4 FT 0 IN. DIA.)	75.00	0.00	75.00	LF	75.00	\$564.00	\$42,300
		0070	0720	7011300	VIDEO CAMERA INSPECTION	3.00	0.00	3.00	EA	3.00	\$53.00	\$159
		0070	0730	7011400	FOUNDATION INSPECTION HOLES	105.00	0.00	105.00	LF	105.00	\$204.00	\$21,420
		0070	0740	7011600	SONIC LOGGING TESTING	3.00	0.00	3.00	EA	0.00	\$1,589.50	\$0
		0070	0750	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	280.00	0.00	280.00	LF	280.00	\$135.50	\$37,940
		0070	0760	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	2.00	\$530.00	\$1,060
		0070	0770	7026000	PRE-BORE FOR PILING	210.00	0.00	210.00	LF	210.00	\$84.75	\$17,797
		0070	0780	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	14.00	\$133.00	\$1,862
		0070	0790	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	58.50	0.00	58.50	CUYD	58.50	\$999.50	\$58,470
		0070	0800	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	51.80	0.00	51.80	CUYD	51.80	\$1,086.00	\$56,254
		0070	0810	7034219A	TYPE D BARRIER	416.00	0.00	416.00	LF	416.00	\$102.50	\$42,640
		0070	0820	7034221	SLAB ON CONCRETE NU-GIRDER	1,230.00	0.00	1,230.00	SQYD	1,230.00	\$397.00	\$488,310
			0830	7056022	NU 43. PRESTRESSED CONCRETE NU-GIRDER	1,116.00	0.00	1,116.00	LF	1,116.00	\$414.00	\$462,024
		0070	0840	7061060	REINFORCING STEEL (BRIDGES)	5,740.00	0.00	5,740.00	LB	5,740.00	\$2.00	\$11,480
		0070	0850	7101000	REINFORCING STEEL (EPOXY COATED)	11,770.00	0.00	11,770.00	LB	11,770.00	\$2.00	\$23,540
		0070	0860	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$3,959.00	\$7,918
			0870	7161000	PLAIN NEOPRENE BEARING PAD	12.00	0.00	12.00	EA	12.00	\$3,959.00	\$1,824
		0070	0880	7161000	LAMINATED NEOPRENE BEARING PAD	12.00	0.00	12.00	EA	12.00	\$188.00	\$2,256
		0070	UUUU	1101002	LAWINATED INCOLNERS DEARLING FAD	12.00	0.00	12.00	EA	12.00	φ100.00	\$2,250

Page 11 of 28 Revision 3/23/2023



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
)21-C02	J4I3451	0071	0900	2061000	CLASS 1 EXCAVATION	110.00	0.00	110.00	CUYD	0.00	\$68.75	\$0.0
		0071	0910	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$105,929.00	\$105,929.0
		0071	0920	5031010A	BRIDGE APPROACH SLAB (MAJOR)	252.00	0.00	252.00	SQYD	0.00	\$299.50	\$0.0
		0071	0930	7011206	ROCK SOCKETS (4 FT 0 IN. DIA.)	63.00	0.00	63.00	LF	63.00	\$615.50	\$38,776.5
		0071	0940	7011300	VIDEO CAMERA INSPECTION	3.00	0.00	3.00	EA	3.00	\$53.00	\$159.0
		0071	0950	7011400	FOUNDATION INSPECTION HOLES	93.00	0.00	93.00	LF	93.00	\$209.50	\$19,483.5
		0071	0960	7011600	SONIC LOGGING TESTING	3.00	0.00	3.00	EA	3.00	\$1,589.50	\$4,768.5
		0071	0970	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	280.00	0.00	280.00	LF	280.00	\$135.50	\$37,940.0
		0071	0980	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	2.00	\$530.00	\$1,060.0
		0071	0990	7026000	PRE-BORE FOR PILING	210.00	0.00	210.00	LF	210.00	\$84.75	\$17,797.5
		0071	1000	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	14.00	\$133.00	\$1,862.0
		0071	1010	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	54.50	0.00	54.50	CUYD	54.50	\$1,058.50	\$57,688.2
		0071	1020	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	49.30	0.00	49.30	CUYD	49.30	\$1,131.00	\$55,758.3
		0071	1030	7034219A	TYPE D BARRIER	416.00	0.00	416.00	LF	0.00	\$102.50	\$0.0
		0071	1040	7034221	SLAB ON CONCRETE NU-GIRDER	1,230.00	0.00	1,230.00	SQYD	0.00	\$396.00	\$0.0
		0071	1050	7056022	NU 43, PRESTRESSED CONCRETE NU-GIRDER	1,116.00	0.00	1,116.00	LF	0.00	\$414.00	\$0.0
		0071	1060	7061060	REINFORCING STEEL (BRIDGES)	4,940.00	0.00	4,940.00	LB	4,940.00	\$2.00	\$9,880.0
		0071	1070	7101000	REINFORCING STEEL (EPOXY COATED)	11,720.00	0.00	11,720.00	LB	11,720.00	\$2.00	\$23,440.0
		0071	1080	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$3,959.00	\$0.0
		0071	1090	7161000	PLAIN NEOPRENE BEARING PAD	12.00	0.00	12.00	EA	0.00	\$152.00	\$0.0
		0071	1100	7161002	LAMINATED NEOPRENE BEARING PAD	12.00	0.00	12.00	EA	0.00	\$188.00	\$0.0
		0001	5001	6173706	TEMPORARY TRAFFIC BARRIER STIFFNESS TRANSITION SECTION, CONTRACTOR FURNISHED / RETAINED	0.00	50.00	50.00	LF	50.00	\$29.88	\$1,494.0
		0001	5002	6175013	RELOCATING TEMPORARY TRAFFIC BARRIER STIFFNESS TRANSITION SECTION	0.00	50.00	50.00	LF	50.00	\$17.28	\$864.0
		0001	5003	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	0.00	750.00	750.00	LF	750.00	\$43.60	\$32,700.0
		0001	5004	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	0.00	750.00	750.00	LF	0.00	\$22.05	\$0.0
		0001	5005	6161055	SEQUENTIAL FLASHING WARNING LIGHT	0.00	56.00	56.00	EA	56.00	\$171.15	\$9,584.4
	Broject	 4 3451 - To	tal Value	Posted to D	ate as of Report Generated Date							\$3,154,106.

Revision 3/23/2023 Page 12 of 28



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4I3451

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0280	6161033	DIRECTIONAL INDICATOR BARRICADE	6/29/23	6/30/23	17.00	EA	Double lane closures on NB/SB 435 to implement stage construction.	726+00		747+00		
0330	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	6/21/23	6/27/23	140.00	LF		9+94.25		10+00		This was broken into section pours underneath Bridge A9236. 65 feet of it is on the south end of the columns and includes the end cap. The other 75 feet of it is the barrier poured on the north end of the columns. Ending station is a little before 10+00 they did not pour quite all the way there.
0930	7011206	ROCK SOCKETS (4 FT 0 IN. DIA.)	6/22/23	6/27/23	63.00	LF	intermediate Bent 2	737+54.37				the three rock sockets in intermediate bent 2
0940	7011300	VIDEO CAMERA INSPECTION	6/30/23	6/30/23	3.00	EA	bent 2	737+36.45				Video camera inspection of the three drilled shafts
0960	7011600	SONIC LOGGING TESTING	6/30/23	6/30/23	3.00	EA	bent 2	737+36.45				Testing after the drilled shafts are poured
0970	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN	6/30/23	6/30/23	280.00	LF	end bents one and three	736+59.44		738+49.31		
0980	7025002	PILE WAVE ANALYSIS	6/21/23	6/27/23	2.00	EA		736+59.44		738+49.31		Station 736+59.44 is for end bent 1, pile 7. Station 738+49.31 is for end bent 3, pile 14.
0990	7026000	PRE-BORE FOR PILING	6/20/23	6/26/23	210.00	LF		736+59.44		738+49.31		Station 736+59.44 is for the pre-bores in end bent 1. Station 738+49.31 is for the pre-bores in end bent 3.
1000	7027000	PILE POINT REINFORCEMENT	6/21/23	6/27/23	14.00	EA		736+59.44		738+49.31		Station 736+59.44 is for the 7 pile in end bent 1. Station 738+49.31 is for the 7 pile in end bent 3.
1010	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	6/30/23	6/30/23	54.50	CUYD	end bents 1 and 3	736+59.44		738+49.31		Abutments
1020	7034003	CLASS B-1 CONCRETE (SUBSTR)	6/30/23	6/30/23	49.30	CUYD	bent 2	737+36.45				Concrete for the cap
1060	7061060	REINFORCING STEEL (BRIDGES)	6/22/23	6/27/23	4,940.00	LB		737+54.37				Steel in rock sockets
1070	7101000	REINFORCING STEEL (EPOXY COATED)	6/30/23	6/30/23	11,720.00	LB	bent 2	737+36.45				Reinforcing steel for the columns and cap.
5005	6161055	SEQUENTIAL FLASHING WARNING LIGHT	6/29/23	6/30/23	56.00	EA	Double lane closures on NB/SB 435 to implement stage construction.	726+00		747+00		

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023 Page 13 of 28



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
151	0090	MISC. AGGREGATE FOR BASE	Material		2	Apr 4, 2023	SYSTEM	\$63,313.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Apr 4, 2023	SYSTEM	(\$63,313.25)	
					3	Apr 17, 2023	SYSTEM	\$63,313.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Apr 17, 2023	SYSTEM	(\$63,313.25)	
					4	May 3, 2023	SYSTEM	\$63,313.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 3, 2023	SYSTEM	(\$63,313.25)	
					5	May 16, 2023	SYSTEM	\$63,313.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user baiamf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	May 16, 2023	SYSTEM	(\$63,313.25)	
					6	Jun 2, 2023	SYSTEM	\$17,813.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 2, 2023	SYSTEM	(\$17,813.25)	
					7	Jun 16, 2023	SYSTEM	\$17,813.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$17,813.25)	
					8	Jun 30, 2023	SYSTEM	\$63,313.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$63,313.25)	
				- Total				\$0.00	
	0000	T-4-1	Material - To	tal				\$0.00	
	0100	MISC.		4040	2	Apr 4,		\$0.00	10 5 4 16 14 140 1 14
		WIICO.	Other Item	ACAD	_		frizzm	(\$6,033.61)	AC adjustment for March 16 to April 1.
		wilde.	Other Item Adjustment			2023	frizzm		AC adjustment for March 16 to April 1.
		wide.	Adjustment	ACAD - Tot	al		frizzm	(\$6,033.61) (\$6,033.61) (\$6,033.61)	AC adjustment for March 16 to April 1.
	0100 -		Adjustment	ACAD - Tota	al		frizzm	(\$6,033.61)	AC adjustment for March 16 to April 1.
	0100 - 0110	Total ASPHALTIC CONCRETE	Other Item A	ACAD - Tota	al		frizzm	(\$6,033.61) (\$6,033.61) (\$6,033.61)	AC adjustment for March 1 to 15. AC adjustment for March 1 to 15.
		Total ASPHALTIC	Other Item A	ACAD - Tot djustment - T	al	2023 Mar 17,		(\$6,033.61) (\$6,033.61) (\$6,033.61)	
		Total ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	Other Item A	ACAD - Tot djustment - T	otal 1	Mar 17, 2023 Apr 4,	frizzm	(\$6,033.61) (\$6,033.61) (\$6,033.61) (\$547.10)	AC adjustment for March 1 to 15.
	0110	Total ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item A Other Item A Other Item Adjustment	ACAD - Tot djustment - T ACAD	otal 1 2	Mar 17, 2023 Apr 4,	frizzm	(\$6,033.61) (\$6,033.61) (\$6,033.61) (\$547.10) (\$1,420.87) (\$1,967.97)	AC adjustment for March 1 to 15.
	0110	Total ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX) Total	Adjustment Other Item A Other Item Adjustment Other Item A	ACAD - Tot ACAD ACAD - Tot djustment - T	1 2 al otal	Mar 17, 2023 Apr 4,	frizzm	(\$6,033.61) (\$6,033.61) (\$6,033.61) (\$547.10) (\$1,420.87)	AC adjustment for March 1 to 15. AC adjustment for March 16 to April 1.
	0110	Total ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX) Total ASPHALTIC CONCRETE MIXTURE PG	Other Item A Other Item A Other Item Adjustment	ACAD - Tot	otal 1 2 al otal	Mar 17, 2023 Apr 4, 2023 Mar 17, 2023	frizzm frizzm	(\$6,033.61) (\$6,033.61) (\$6,033.61) (\$547.10) (\$1,420.87) (\$1,967.97) (\$1,967.97) (\$1,967.97) (\$824.84)	AC adjustment for March 1 to 15. AC adjustment for March 16 to April 1. AC adjustment for March 1 to 15.
	0110	Total ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX) Total ASPHALTIC CONCRETE	Other Item A Other Item A Other Item A Other Item A	ACAD - Tot ACAD - Tot djustment - T ACAD - Tot ACAD - ACAD	1 2 al lotal 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2023 Mar 17, 2023 Apr 4, 2023	frizzm frizzm	(\$6,033.61) (\$6,033.61) (\$6,033.61) (\$547.10) (\$1,420.87) (\$1,967.97) (\$1,967.97) (\$1,967.97) (\$824.84) (\$2,964.89)	AC adjustment for March 1 to 15. AC adjustment for March 16 to April 1.
	0110	Total ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX) Total ASPHALTIC CONCRETE MIXTURE PG	Adjustment Other Item A	ACAD - Tot ACAD - Tot	1 2 al cotal 1 2 2 al cotal 2 al cotal 2 2 a	Mar 17, 2023 Mar 17, 2023 Mar 17, 2023 Apr 4, 2023	frizzm frizzm	(\$6,033.61) (\$6,033.61) (\$6,033.61) (\$547.10) (\$1,420.87) (\$1,967.97) (\$1,967.97) (\$1,967.97) (\$824.84) (\$2,964.89)	AC adjustment for March 1 to 15. AC adjustment for March 16 to April 1. AC adjustment for March 1 to 15.
	0110	Total ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX) Total ASPHALTIC CONCRETE MIXTURE PG	Adjustment Other Item A	ACAD - Tot ACAD - Tot djustment - T ACAD - Tot ACAD - ACAD	1 2 al otal 2 al	Mar 17, 2023 Apr 4, 2023 Mar 17, 2023 Apr 4, 2023	frizzm frizzm	(\$6,033.61) (\$6,033.61) (\$6,033.61) (\$547.10) (\$1,420.87) (\$1,967.97) (\$1,967.97) (\$1,967.97) (\$824.84) (\$2,964.89)	AC adjustment for March 1 to 15. AC adjustment for March 16 to April 1. AC adjustment for March 1 to 15.
	0110	Total ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX) Total ASPHALTIC CONCRETE MIXTURE PG	Other Item A	ACAD - Tot djustment - T ACAD ACAD - Tot djustment - T ACAD ACAD - Tot djustment - T	1 2 al otal 2 al	Mar 17, 2023 Apr 4, 2023 Mar 17, 2023 Apr 4, 2023	frizzm frizzm frizzm	(\$6,033.61) (\$6,033.61) (\$6,033.61) (\$547.10) (\$1,420.87) (\$1,967.97) (\$1,967.97) (\$1,967.97) (\$824.84) (\$2,964.89) (\$3,789.73)	AC adjustment for March 1 to 15. AC adjustment for March 16 to April 1. AC adjustment for March 1 to 15.
	0110	Total ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX) Total ASPHALTIC CONCRETE MIXTURE PG	Other Item A	ACAD - Tot djustment - T ACAD ACAD - Tot djustment - T ACAD ACAD - Tot djustment - T	1 2 al otal 2 2 7	Mar 17, 2023 Mar 17, 2023 Mar 17, 2023 Apr 4, 2023 Apr 4, 2023 Jun 16,	frizzm frizzm frizzm SYSTEM	(\$6,033.61) (\$6,033.61) (\$6,033.61) (\$547.10) (\$1,420.87) (\$1,967.97) (\$1,967.97) (\$1,967.97) (\$824.84) (\$2,964.89) (\$3,789.73) (\$4,542.12)	AC adjustment for March 1 to 15. AC adjustment for March 16 to April 1. AC adjustment for March 1 to 15.



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3451	0120 -	Total						(\$16,315.53)	
	0130	TACK COAT - LOW OR NON- TRACKING	Material		1	Mar 17, 2023	SYSTEM	\$609.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Mar 17, 2023	SYSTEM	(\$609.00)	
					2	Apr 4, 2023	SYSTEM	\$609.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Apr 4, 2023	SYSTEM	(\$609.00)	
					3	Apr 17, 2023	SYSTEM	\$609.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Apr 17, 2023	SYSTEM	(\$609.00)	
					4	May 3, 2023	SYSTEM	\$609.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	May 3, 2023	SYSTEM	(\$609.00)	
					5	May 16, 2023	SYSTEM	\$609.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user baiamf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	May 16, 2023	SYSTEM	(\$609.00)	
					6	Jun 2, 2023	SYSTEM	\$609.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jun 2, 2023	SYSTEM	(\$609.00)	
					7	Jun 16, 2023	SYSTEM	\$1,265.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$1,265.25)	
					8	Jun 30, 2023	SYSTEM	\$1,265.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$1,265.25)	
				- Total				\$0.00	
	0100		Material - Tot	al				\$0.00	
	0130 - 0150	CONCRETE APPROACH PAVEMENT	Material		6	Jun 2, 2023	SYSTEM	\$0.00 \$55,138.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.
		I VAFIMENI			6	Jun 2, 2023	SYSTEM	(\$55,138.40)	Executed Exception 6 on the outletter ayment Estimate.
					7	Jun 16, 2023	SYSTEM	\$55,138.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$55,138.40)	Example 2.00pton 0 on the serious ayriont Estimate.
					8	Jun 30, 2023	SYSTEM	\$55,138.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$55,138.40)	,
				- Total				\$0.00	
			Material - Tot					\$0.00	
	0150 -	Total						\$0.00	
	0200	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	Material		2	Apr 4, 2023	SYSTEM	\$8,478.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.



SIGNS	ect	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks							
2022 3	451	0200	IMPACT			2	Apr 4.	·	(\$8.478.00)								
BARREL ARRAY			ATTENUATOR 65				2023										
Total Substitute Total						3		SYSTEM	\$8,478.00	Estimate Item Adjustment (0004) due to user frizzm overridding Payment							
						3		SYSTEM	(\$8,478.00)								
1					- Total				\$0.00								
CONSTRUCTION Material				Material - Tot	tal				\$0.00								
SIGNS		0200 -	Total						\$0.00								
2023 3		0240		Material		2		SYSTEM	\$8,377.95	Estimate Item Adjustment (0007) due to user frizzm overridding Payment							
2023 System Estimate Exception 5 on the current Payment Estimate.						2		SYSTEM	(\$8,377.95)								
2023 50.00 1.00						3		SYSTEM	\$15,529.50	Estimate Item Adjustment (0005) due to user frizzm overridding Payment							
						3		SYSTEM	(\$15,529.50)								
					- Total				\$0.00								
ADVANCED WARNING RAIL				Material - Tot	tal				\$0.00								
WARNING RAIL		0240 -	Total						\$0.00								
2023 3 Apr 17, 27 27 27 27 27 27 27		0250	WARNING RAIL	Material		2		SYSTEM	\$530.00	Estimate Item Adjustment (0008) due to user frizzm overridding Payment							
September Sept						2		SYSTEM	(\$530.00)								
2023 \$0.00 -Total \$0.00 -Total \$0.00														3		SYSTEM	\$530.00
Material - Total S0.00								SYSTEM	(\$530.00)								
					- Total				\$0.00								
CHANNELIZER (TRIM LINE)				Material - To	tal				\$0.00								
(TRIM LINE) 2023 SYSTEM Stimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate. 2																	
2023 SYSTEM \$8,085.50 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate. 3		0260		Material		2		SYSTEM	\$8,085.50	Estimate Item Adjustment (0009) due to user frizzm overridding Payment							
2023 Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate. 3						2		SYSTEM	(\$8,085.50)								
TYPE III MOVEABLE BARRICADE Material - Total Summer System System System System Stimate S						3		SYSTEM	\$8,085.50	Estimate Item Adjustment (0007) due to user frizzm overridding Payment							
Material - Total \$0.00 TYPE III MOVEABLE BARRICADE Apr 17, 2023 Apr						3		SYSTEM	(\$8,085.50)								
Source S									\$0.00								
TYPE III MOVEABLE BARRICADE System				Material - To	tal												
MOVEABLE BARRICADE 2023 SYSTEM (\$7,436.00) -Total \$0.00 Material - Total \$0.00 DIRECTIONAL INDICATOR BARRICADE DIRECTIONAL INDICATOR BARRICADE Material - Z023 Apr 4, 2023 SYSTEM (\$4,134.00) SYSTEM \$4,134.00 SYSTEM \$4,134.00 SYSTEM \$4,134.00 SYSTEM \$4,134.00 SYSTEM SYSTEM Estimate Exception 8 on the current Payment Estimate.																	
-Total \$0.00 Material - Total \$0.00 Material - Total \$0.00 DIRECTIONAL INDICATOR BARRICADE \$2 Apr 4, 2023 \$YSTEM \$4,134.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.		0270	MOVEABLE	Material		3		SYSTEM	\$7,436.00	Estimate Item Adjustment (0008) due to user frizzm overridding Payment							
Material - Total \$0.00 DIRECTIONAL INDICATOR BARRICADE Material 2 Apr 4, 2023 SYSTEM \$4,134.00 System Standard Restrict the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.						3		SYSTEM	(\$7,436.00)								
DIRECTIONAL INDICATOR BARRICADE Solution Solution \$0.00 SYSTEM \$4,134.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.																	
DIRECTIONAL INDICATOR BARRICADE DIRECTIONAL INDICATOR BARRICADE Apr 4, SYSTEM \$4,134.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.				Material - To	tal				\$0.00								
INDICATOR BARRICADE 2023 Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.		0270 -	Total						\$0.00								
0 0.001714 (0.4404.00)		0280	INDICATOR	Material		2		SYSTEM	\$4,134.00	Estimate Item Adjustment (0003) due to user frizzm overridding Payment							
2 Apr 4, 2023 (\$4,134.00)						2	Apr 4, 2023	SYSTEM	(\$4,134.00)								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
413451	0280	DIRECTIONAL INDICATOR BARRICADE	Material		3	Apr 17, 2023	SYSTEM	\$4,134.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					3	Apr 17, 2023	SYSTEM	(\$4,134.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
			Overrun	Overrun	2	Apr 4, 2023	SYSTEM	(\$954.00)		
					8	Jun 30, 2023	SYSTEM	\$954.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',106.00000 - 106.00000, 'is applied (if non-zero).	
				Overrun - T	otal			\$0.00		
			Overrun - To	tal				\$0.00		
	0280 -	Total						\$0.00		
	0290	FLASHING ARROW PANEL	Material		2	Apr 4, 2023	SYSTEM	\$10,386.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					2	Apr 4, 2023	SYSTEM	(\$10,386.00)		
					3	Apr 17, 2023	SYSTEM	\$10,386.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					3	Apr 17, 2023	SYSTEM	(\$10,386.00)		
				- Total				\$0.00		
		Material - 0290 - Total	Material - To	tal				\$0.00		
		Total						\$0.00		
	0300		Material		1	Mar 17, 2023	SYSTEM	\$41,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					1	Mar 17, 2023	SYSTEM	(\$41,332.00)		
							2	Apr 4, 2023	SYSTEM	\$41,332.00
					2	Apr 4, 2023	SYSTEM	(\$41,332.00)		
					3	Apr 17, 2023	SYSTEM	\$41,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate.	
					3	Apr 17, 2023	SYSTEM	(\$41,332.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0300 -	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		2	Apr 4, 2023	SYSTEM	\$0.00 \$2,861.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate.	
					2	Apr 4, 2023	SYSTEM	(\$2,861.00)		
					3	Apr 17, 2023	SYSTEM	\$10,013.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					3	Apr 17, 2023	SYSTEM	(\$10,013.50)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0310 -	Total						\$0.00		
	0330	CONCRETE TRAFFIC BARRIER, TYPE B	Material		8	Jun 30, 2023	SYSTEM	\$29,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 21 on the current Payment Estimate.	
		BARRIER, TYPE B			8	Jun 30,	SYSTEM	(\$29,750.00)		



March Sept	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
Section Sect	J4I3451	0330		Material			2023						
1935 Total 1935									\$0.00				
Control Cont				Material - To	tal								
PARTICIPATION PARTICIPATION Part Par			Total						\$0.00				
2		0350	TRAFFIC BARRIER, CONT.	Material		2		SYSTEM	\$55,316.25	Estimate Item Adjustment (0013) due to user frizzm overridding Payment			
2023 Estimate Item Adjustment (0713) due to user fitzern coendiding Payment Estimate.			TOTAL			2		SYSTEM	(\$55,316.25)				
4						3		SYSTEM	\$55,316.25	Estimate Item Adjustment (0013) due to user frizzm overridding Payment			
2023 SYSTEM 255.316.25						3		SYSTEM	(\$55,316.25)				
2023 5							4		SYSTEM	\$55,316.25	Estimate Item Adjustment (0004) due to user frizzm overridding Payment		
Settomate Exception 4 on the current Payment Estimate.								4		SYSTEM	(\$55,316.25)		
2023 SYSTEM \$55,316.25 This adjustment offsets the original system-generated Material Payment Estimate Estimate Exception 14 on the current Payment Estimate.							5	May 16,	SYSTEM	\$55,316.25	Estimate Item Adjustment (0005) due to user baiamf1 overridding Payment		
2023 SySTEM (\$55,316.25)									5		SYSTEM	(\$55,316.25)	
2023 SYSTEM S55,316.25 This adjustment offsets the original system-generated Material Payment Estimate Exception 19 on the current Payment Estimate Estimate Exception 19 on the current Payment Estimate Estimate Exception 19 on the current Payment Estimate Inhabitation Inhabitat									6		SYSTEM	\$55,316.25	Estimate Item Adjustment (0004) due to user frizzm overridding Payment
2023 Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 19 on the current Payment Estimate.						6		SYSTEM	(\$55,316.25)				
2023 8						7		SYSTEM	\$55,316.25	Estimate Item Adjustment (0006) due to user frizzm overridding Payment			
Estimate Item Adjustment (006) due to user frizzm overridding Payment Estimate Exception 23 on the current Payment Estimate. **Total*** **So.00*** **Material - Total*** **So.00*** **Outstand TemPORARY REMOVABLE MARKING TAPE** **Material - Total*** **Material - Total** **So.00*** **SySTEM** **SySTEM** **SySTEM** **SySTEM** **So.00*** **SySTEM** **So.00*** **SySTEM** **So.00*** **So.00*** **Double Summer (0014) due to user frizzm overridding Payment Estimate Exception 13 on the current Payment Estimate.* **So.00*** **Outstand Testimate Item Adjustment (014) due to user frizzm overridding Payment Estimate Exception 13 on the current Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 14 on the current Payment Estimate Exception 14 on the current Payment Estimate Estimate Exception 14 on the current Payment Estimate Estimate Exception 15 on the current Payment Estimate Estimate Exception 15 on the current Payment Estimate Estimate Exception 16 on the current Payment Estimate Estimate Exception 5 on the current Payment Estimate Estimate Estimate Exception 5 on the current Payment Estimate Estimate Estimate Exception 5 on the current Payment Estimate Estimate Estimate Estimate Exception 6 on the current Payment Estimate Estimate Estimate Estimate Exception 6 on the current Payment Estimate.* **System** **System** **Sys						7		SYSTEM	(\$55,316.25)				
2023 \$0.00						8		SYSTEM	\$55,316.25	Estimate Item Adjustment (0006) due to user frizzm overridding Payment			
Material - Total S0.00						8		SYSTEM	(\$55,316.25)				
Solid State Stat					- Total				\$0.00				
TEMPORARY REMOVABLE MARKING TAPE Material REMOVABLE MARKING TAPE 2				Material - To	tal				\$0.00				
REMOVABLE MARKING TAPE 2		0350 -	Total						\$0.00				
Company		0400	REMOVABLE	Material		2		SYSTEM	\$16,221.00	Estimate Item Adjustment (0014) due to user frizzm overridding Payment			
Material - Total S0.00						2		SYSTEM	(\$16,221.00)				
O410 - Total O410 6 IN. WHITE HIGH BUILD WATERBORNE PAINT O410 7 SYSTEM \$6,372.50 O410 7 SYSTEM \$6,372.50 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate. O410 7 SYSTEM \$6,372.50					- Total				\$0.00				
0410 6 IN. WHITE HIGH BUILD WATERBORNE PAINT				Material - To	tal				\$0.00				
BUILD WATERBORNE PAINT 2023 Apr 17, 2023		0400 -	Total						\$0.00				
Apr 17, 2023 Apr 17, 2023 May 3, 2023 SYSTEM \$6,372.50 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate. May 3, 2023 SYSTEM \$6,372.50 May 16, 2023 SYSTEM \$6,372.50 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user baiamf1 overridding Payment Estimate Item Adjustment (0006) due to user baiamf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		0410	BUILD WATERBORNE	Material	terial 3		Material 3			SYSTEM	\$6,372.50	Estimate Item Adjustment (0014) due to user frizzm overridding Payment	
Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate. 4 May 3, 2023 5 May 16, 2023 SYSTEM (\$6,372.50) \$6,372.50 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user baiamf1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 5 May 16, SYSTEM (\$6,372.50)			PAINI			3		SYSTEM	(\$6,372.50)				
5 May 16, 2023 SySTEM \$6,372.50 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user baiamf1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 5 May 16, SYSTEM (\$6,372.50)						4		SYSTEM	\$6,372.50	Estimate Item Adjustment (0005) due to user frizzm overridding Payment			
Estimate Item Adjustment (0006) due to user baiamf1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 5 May 16, SYSTEM (\$6,372.50)						4		SYSTEM	(\$6,372.50)				
						5		SYSTEM	\$6,372.50	Estimate Item Adjustment (0006) due to user baiamf1 overridding Payment			
						5		SYSTEM	(\$6,372.50)				



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
451	0410	6 IN. WHITE HIGH BUILD WATERBORNE	Material		6	Jun 2, 2023	SYSTEM	\$6,372.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 16 on the current Payment Estimate.
		PAINT			6	Jun 2, 2023	SYSTEM	(\$6,372.50)	
					7	Jun 16, 2023	SYSTEM	\$12,204.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 21 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$12,204.50)	
					8	Jun 30, 2023	SYSTEM	\$12,204.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 24 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$12,204.50)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
			Overrun	Overrun	7	Jun 16, 2023	SYSTEM	(\$1,393.50)	
				Overrun - T	otal			(\$1,393.50)	
	0.00		Overrun - To	tal				(\$1,393.50)	
	0410 -		Material 1		0	A	OVOTE:	(\$1,393.50)	This adjustment offset the science of the science o
	0420	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material		3	Apr 17, 2023	SYSTEM	\$7,363.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user frizzm overridding Payment Estimate Exception 16 on the current Payment Estimate.
		7744			3	Apr 17, 2023	SYSTEM	(\$7,363.00)	
					4	May 3, 2023	SYSTEM	\$7,363.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	May 3, 2023	SYSTEM	(\$7,363.00)	
					5	May 16, 2023	SYSTEM	\$7,363.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user baiamf1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	May 16, 2023	SYSTEM	(\$7,363.00)	
					6	Jun 2, 2023	SYSTEM	\$7,363.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 18 on the current Payment Estimate.
					6	Jun 2, 2023	SYSTEM	(\$7,363.00)	
					7	Jun 16, 2023	SYSTEM	\$10,279.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 23 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$10,279.00)	
					8	Jun 30, 2023	SYSTEM	\$10,279.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 26 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$10,279.00)	
				- Total				\$0.00	
			Material - To		2	Ann 47	CVCTCA	\$0.00	
			Overrun	Overrun		Apr 17, 2023	SYSTEM	(\$556.00)	
					7	Jun 16, 2023	SYSTEM	(\$2,916.00)	
				Overrun - T	otal			(\$3,472.00)	
	0.400		Overrun - To	tal				(\$3,472.00)	
	0420 - 0590	MGS GUARDRAIL	Construction		7	Jun 16,	SYSTEM	(\$3,472.00) (\$16,751.63)	Payment Estimate Item Adjustment generated Stockpile Transaction
			Stockpile	Total		2023		(\$16. 754.60)	
				- Total				(\$16,751.63)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3451	0590	MGS GUARDRAIL	Construction	Stockpile - 1	Γotal			(\$16,751.63)	
			Construction Stockpile STMI		3	Apr 17, 2023	SYSTEM	\$30,261.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			OTIVII	- Total				\$30,261.00	
			Construction	Stockpile S	ГМI - Total			\$30,261.00	
			Material		7	Jun 16, 2023	SYSTEM	\$33,131.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$33,131.25)	
					8	Jun 30, 2023	SYSTEM	\$33,131.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 15 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$33,131.25)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0590 -	Total						\$13,509.37	
	0600	MGS BRIDGE APP. TRANS SEC	Construction Stockpile		7	Jun 16, 2023	SYSTEM	(\$4,080.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(EXT CURB)		- Total				(\$4,080.00)	
			Construction	Stockpile - 1	Гotal			(\$4,080.00)	
			Construction Stockpile STMI		3	Apr 17, 2023	SYSTEM	\$6,120.00	Payment Estimate Item Adjustment generated Stockpile Transaction
					3	Apr 17, 2023	SYSTEM	\$6,120.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$12,240.00	
			Construction	Stockpile S	ΓMI - Total			\$12,240.00	
			Material		7	Jun 16, 2023	SYSTEM	\$7,864.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 16 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$7,864.00)	
					8	Jun 30, 2023	SYSTEM	\$7,864.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 17 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$7,864.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0600 -	Total						\$8,160.00	
	0610	MGS END ANCHOR	Construction Stockpile		7	Jun 16, 2023	SYSTEM	(\$830.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$830.00)	
			Construction	Stockpile - 1	Γotal			(\$830.00)	
			Construction Stockpile STMI		3	Apr 17, 2023	SYSTEM	\$2,490.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			J 1 1411	- Total				\$2,490.00	
			Construction	Stockpile S	TMI - Total			\$2,490.00	
			Material		7	Jun 16, 2023	SYSTEM	\$1,430.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user frizzm overridding Payment Estimate Exception 17 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$1,430.50)	
					8	Jun 30, 2023	SYSTEM	\$1,430.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 18 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$1,430.50)	•
				- Total				\$0.00	
			Material - Tot					\$0.00	
			100						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																		
J4I3451	0610 -	Total						\$1,660.00																			
	0620	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		7	Jun 16, 2023	SYSTEM	(\$1,875.00)	Payment Estimate Item Adjustment generated Stockpile Transaction																		
		(MASH)		- Total				(\$1,875.00)																			
				Stockpile - 1				(\$1,875.00)																			
			Construction Stockpile STMI	Takal	3	Apr 17, 2023	SYSTEM	\$5,625.00	Payment Estimate Item Adjustment generated Stockpile Transaction																		
				- Total				\$5,625.00																			
				Stockpile S				\$5,625.00																			
			Material		7	Jun 16, 2023	SYSTEM	\$3,410.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user frizzm overridding Payment Estimate Exception 18 on the current Payment Estimate.																		
					7	Jun 16, 2023	SYSTEM	(\$3,410.50)																			
					8	Jun 30, 2023	SYSTEM	\$3,410.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 19 on the current Payment Estimate.																		
					8	Jun 30, 2023	SYSTEM	(\$3,410.50)																			
				- Total				\$0.00																			
			Material - To	tal				\$0.00																			
	0620 -	Total						\$3,750.00																			
	0700	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		6	Jun 2, 2023	SYSTEM	\$75,474.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.																		
					6	Jun 2, 2023	SYSTEM	(\$75,474.00)																			
					7	Jun 16, 2023	SYSTEM	\$75,474.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.																		
					7	Jun 16, 2023	SYSTEM	(\$75,474.00)																			
					8	Jun 30, 2023	SYSTEM	\$75,474.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.																		
					8	Jun 30, 2023	SYSTEM	(\$75,474.00)																			
				- Total				\$0.00																			
			Material - To	tal				\$0.00																			
	0700 -	Total						\$0.00																			
	0710	ROCK SOCKETS (4 FT 0 IN. DIA.)	Material		3	Apr 17, 2023	SYSTEM	\$42,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user frizzm overridding Payment Estimate Exception 18 on the current Payment Estimate.																		
					3	Apr 17, 2023	SYSTEM	(\$42,300.00)																			
																							4	May 3, 2023	SYSTEM	\$42,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.
					4	May 3, 2023	SYSTEM	(\$42,300.00)																			
					5	May 16, 2023	SYSTEM	\$42,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user baiamf1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																		
					5	May 16, 2023	SYSTEM	(\$42,300.00)																			
					6	Jun 2, 2023	SYSTEM	\$42,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 20 on the current Payment Estimate.																		
					6	Jun 2, 2023	SYSTEM	(\$42,300.00)																			
					7	Jun 16, 2023	SYSTEM	\$42,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user frizzm overridding Payment Estimate Exception 25 on the current Payment Estimate.																		
					7	Jun 16,	SYSTEM	(\$42,300.00)																			



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
451	0710	ROCK SOCKETS	Material			2023					
		(4 FT 0 IN. DIA.)			8	Jun 30, 2023	SYSTEM	\$42,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 28 on the current Payment Estimate.		
					8	Jun 30, 2023	SYSTEM	(\$42,300.00)			
				- Total				\$0.00			
			Material - To	tal				\$0.00			
	0710 -	Total						\$0.00			
	0750	GALVANIZED STRUCTURAL STEEL PILES (12	Material		4	May 3, 2023	SYSTEM	\$37,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.		
		IN			4	May 3, 2023	SYSTEM	(\$37,940.00)			
					5	May 16, 2023	SYSTEM	\$37,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user baiamf1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		
					5	May 16, 2023	SYSTEM	(\$37,940.00)			
					6	Jun 2, 2023	SYSTEM	\$37,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 21 on the current Payment Estimate.		
					6	Jun 2, 2023	SYSTEM	(\$37,940.00)			
							7	Jun 16, 2023	SYSTEM	\$37,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user frizzm overridding Payment Estimate Exception 26 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$37,940.00)			
				- Total				\$0.00			
			Material - To	al				\$0.00			
	0750 -	Total						\$0.00			
	0780	PILE POINT REINFORCEMENT						£4.000.00	This adjustment effects the original quoteen generated Metaviel Dayment		
	0700		Material		4	May 3, 2023	SYSTEM	\$1,862.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate.		
	0700		Material		4		SYSTEM	(\$1,862.00)	Estimate Item Adjustment (0009) due to user frizzm overridding Payment		
	0700		Material			2023 May 3,			Estimate Item Adjustment (0009) due to user frizzm overridding Payment		
	0700		Material		4	2023 May 3, 2023 May 16,	SYSTEM	(\$1,862.00)	Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment		
	0700		Material		5	2023 May 3, 2023 May 16, 2023	SYSTEM SYSTEM	(\$1,862.00) \$1,862.00	Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment		
	0700		Material		5	2023 May 3, 2023 May 16, 2023 May 16, 2023 Jun 2,	SYSTEM SYSTEM SYSTEM	(\$1,862.00) \$1,862.00 (\$1,862.00)	Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment		
	0760		Material		4 5 5	2023 May 3, 2023 May 16, 2023 May 16, 2023 Jun 2, 2023	SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,862.00) \$1,862.00 (\$1,862.00) \$1,862.00	Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment		
	0760		Material		45566	2023 May 3, 2023 May 16, 2023 May 16, 2023 Jun 2, 2023 Jun 2, 2023 Jun 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,862.00) \$1,862.00 (\$1,862.00) \$1,862.00	Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment		
	07.60		Material	- Total	4 5 5 6 6 7 7	2023 May 3, 2023 May 16, 2023 May 16, 2023 Jun 2, 2023 Jun 16, 2023 Jun 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,862.00) \$1,862.00 (\$1,862.00) \$1,862.00 (\$1,862.00)	Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment		
	07.60		Material - To		4 5 5 6 6 7 7	2023 May 3, 2023 May 16, 2023 May 16, 2023 Jun 2, 2023 Jun 16, 2023 Jun 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,862.00) \$1,862.00 (\$1,862.00) \$1,862.00 (\$1,862.00) (\$1,862.00)	Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment		
	0780 -	REINFORCEMENT			4 5 5 6 6 7 7	2023 May 3, 2023 May 16, 2023 May 16, 2023 Jun 2, 2023 Jun 16, 2023 Jun 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,862.00) \$1,862.00 (\$1,862.00) \$1,862.00 (\$1,862.00) \$1,862.00 (\$1,862.00)	Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment		
		REINFORCEMENT	Material - To		4 5 5 6 6 7 7	2023 May 3, 2023 May 16, 2023 May 16, 2023 Jun 2, 2023 Jun 16, 2023 Jun 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,862.00) \$1,862.00 (\$1,862.00) \$1,862.00 (\$1,862.00) \$1,862.00 (\$1,862.00)	Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment		
	0780 -	Total CLASS B CONCRETE	Material - To		4 5 5 6 6 7	2023 May 3, 2023 May 16, 2023 May 16, 2023 Jun 2, 2023 Jun 16, 2023 Jun 16, 2023 May 18, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,862.00) \$1,862.00 (\$1,862.00) \$1,862.00 (\$1,862.00) \$1,862.00 \$0.00 \$0.00	Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment Estimate Exception 27 on the current Payment Estimate.		
	0780 -	Total CLASS B CONCRETE	Material - To		4 5 5 6 6 7 7	2023 May 3, 2023 May 16, 2023 Jun 2, 2023 Jun 16, 2023 Jun 16, 2023 May 3, 2023 May 3, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,862.00) \$1,862.00 (\$1,862.00) \$1,862.00 (\$1,862.00) \$1,862.00 (\$1,862.00) \$0.00 \$0.00 \$58,470.75	Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment Estimate Exception 27 on the current Payment Estimate.		



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3451	0790	CLASS B CONCRETE (SUBSTRUCTURE)	Material		6	Jun 2, 2023	SYSTEM	\$58,470.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 23 on the current Payment Estimate.
					6	Jun 2, 2023	SYSTEM	(\$58,470.75)	
					7	Jun 16, 2023	SYSTEM	\$58,470.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 28 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$58,470.75)	
					8	Jun 30, 2023	SYSTEM	\$58,470.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user frizzm overridding Payment Estimate Exception 29 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$58,470.75)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		Total						\$0.00	
	0800	CLASS B-1 CONCRETE (SUBSTR)	Material		4	May 3, 2023	SYSTEM	\$56,254.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 15 on the current Payment Estimate.
					4	May 3, 2023	SYSTEM	(\$56,254.80)	
					5	May 16, 2023	SYSTEM	\$56,254.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user baiamf1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					5	May 16, 2023	SYSTEM	(\$56,254.80)	
					6	Jun 2, 2023	SYSTEM	\$56,254.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 26 on the current Payment Estimate.
					6	Jun 2, 2023	SYSTEM	(\$56,254.80)	
					7	Jun 16, 2023	SYSTEM	\$56,254.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user frizzm overridding Payment Estimate Exception 31 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$56,254.80)	
					8	Jun 30, 2023	SYSTEM	\$56,254.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user frizzm overridding Payment Estimate Exception 35 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$56,254.80)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0800 -							\$0.00	
	0810	TYPE D BARRIER	Material		6	Jun 2, 2023	SYSTEM	\$42,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 28 on the current Payment Estimate.
					6	Jun 2, 2023	SYSTEM	(\$42,640.00)	
					7	Jun 16, 2023	SYSTEM	\$42,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$42,640.00)	
					8	Jun 30, 2023	SYSTEM	\$42,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user frizzm overridding Payment Estimate Exception 38 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$42,640.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0810 -	Total						\$0.00	
	0820	SLAB ON	Construction		5	May 16,	SYSTEM	(\$111,690.00)	Payment Estimate Item Adjustment generated Stockpile Transaction



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3451	0820	CONCRETE NU- GIRDER	Stockpile			2023			
		OIRDER		- Total				(\$111,690.00)	
			Construction	Stockpile - 1	Total			(\$111,690.00)	
			Construction Stockpile		1	Mar 17, 2023	SYSTEM	\$111,690.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$111,690.00	
			Construction	Stockpile S	TMI - Total			\$111,690.00	
			Material		5	May 16, 2023	SYSTEM	\$219,739.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user baiamf1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					5	May 16, 2023	SYSTEM	(\$219,739.50)	
					6	Jun 2, 2023	SYSTEM	\$488,310.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 29 on the current Payment Estimate.
					6	Jun 2, 2023	SYSTEM	(\$488,310.00)	
					7	Jun 16, 2023	SYSTEM	\$488,310.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user frizzm overridding Payment Estimate Exception 34 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$488,310.00)	
					8	Jun 30, 2023	SYSTEM	\$488,310.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user frizzm overridding Payment Estimate Exception 39 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$488,310.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0820 -	Total						\$0.00	
	0830	NU 43, PRESTRESSED CONC NU-GIRDER	Construction Stockpile		4	May 3, 2023	SYSTEM	(\$336,860.76)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$336,860.76)	
			Construction	Stockpile - 1		Man 47	OVOTEM	(\$336,860.76)	December 5 of the state bear Adjustment as a control Observation
			Stockpile STMI		1	Mar 17, 2023	SYSTEM	\$336,860.76	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$336,860.76	
			Construction	stockpile STMI - Total				\$336,860.76	
	0830 - 0850		Material		4	May 3, 2023	SYSTEM	\$0.00 \$23,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 18 on the current Payment Estimate.
					4	May 3, 2023	SYSTEM	(\$23,540.00)	
					5	May 16, 2023	SYSTEM	\$23,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user baiamf1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					5	May 16, 2023	SYSTEM	(\$23,540.00)	
					6	Jun 2, 2023	SYSTEM	\$23,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.
					6	Jun 2, 2023	SYSTEM	(\$23,540.00)	
					7	Jun 16, 2023	SYSTEM	\$23,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user frizzm overridding Payment Estimate Exception 38 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$23,540.00)	
					8	Jun 30, 2023	SYSTEM	\$23,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user frizzm overridding Payment Estimate Exception 43 on the current Payment Estimate.
					8	Jun 30,	SYSTEM	(\$23,540.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3451	0850	REINFORCING STEEL (EPOXY	Material			2023			
		COATED)		- Total				\$0.00	
			Material - To	tal				\$0.00	
	0850 - 0860	VERTICAL DRAIN AT END BENTS	Material		6	Jun 2, 2023	SYSTEM	\$0.00 \$7,918.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user frizzm overridding Payment
					6	Jun 2,	SYSTEM	(\$7,918.00)	Estimate Exception 34 on the current Payment Estimate.
					7	2023 Jun 16,	SYSTEM	\$7,918.00	This adjustment offsets the original system-generated Material Payment
						2023			Estimate Item Adjustment (0028) due to user frizzm overridding Payment Estimate Exception 39 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$7,918.00)	
					8	Jun 30, 2023	SYSTEM	\$7,918.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user frizzm overridding Payment Estimate Exception 45 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$7,918.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0860 -	Total						\$0.00	
	0870	PLAIN NEOPRENE BEARING PAD	Material		4	May 3, 2023	SYSTEM	\$1,824.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 19 on the current Payment Estimate.
					4	May 3, 2023	SYSTEM	(\$1,824.00)	
					5	May 16, 2023	SYSTEM	\$1,824.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user baiamf1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					5	May 16, 2023	SYSTEM	(\$1,824.00)	
					6	Jun 2, 2023	SYSTEM	\$1,824.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user frizzm overridding Payment Estimate Exception 35 on the current Payment Estimate.
					6	Jun 2, 2023	SYSTEM	(\$1,824.00)	
					7	Jun 16, 2023	SYSTEM	\$1,824.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user frizzm overridding Payment Estimate Exception 40 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$1,824.00)	
					8	Jun 30, 2023	SYSTEM	\$1,824.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user frizzm overridding Payment Estimate Exception 46 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$1,824.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0870 -	Total						\$0.00	
	0880	LAMINATED NEOPRENE BEARING PAD	Material		4	May 3, 2023	SYSTEM	\$2,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 20 on the current Payment Estimate.
					4	May 3, 2023	SYSTEM	(\$2,256.00)	
					5	May 16, 2023	SYSTEM	\$2,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user baiamf1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					5	May 16, 2023	SYSTEM	(\$2,256.00)	
					6	Jun 2, 2023	SYSTEM	\$2,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user frizzm overridding Payment Estimate Exception 36 on the current Payment Estimate.
					6	Jun 2, 2023	SYSTEM	(\$2,256.00)	



August	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2023 2023	1413451	0880	NEOPRENE	Material		7		SYSTEM	\$2,256.00	Estimate Item Adjustment (0030) due to user frizzm overridding Payment
2023 Estimate libra Adjustment (002) as is to sair fizzor overarding Playment Estimate.						7		SYSTEM	(\$2,256.00)	
100 CLASS Construction Support Suppo						8		SYSTEM	\$2,256.00	Estimate Item Adjustment (0022) due to user frizzm overridding Payment
Material - Total						8		SYSTEM	(\$2,256.00)	
					- Total				\$0.00	
1010 CLASS Meterial				Material - To	tal				\$0.00	
CONCRETE SUBSTRUCTURE 2023 Estimate Item Adjustment (DC23) use to user fizzer overridding Psyment		0880 -	Total						\$0.00	
100 Total		1010	CONCRETE	Material		8		SYSTEM	\$57,688.25	Estimate Item Adjustment (0023) due to user frizzm overridding Payment
Material - Total So 00						8		SYSTEM	(\$57,688.25)	
1010 - Total					- Total				\$0.00	
1020 CLASS B-1 CONCRETE (SUBSTR)				Material - To	tal				\$0.00	
CONCRETE (SUBSTR)		1010 -	Total						\$0.00	
1020 - Total		1020	CONCRETE			8		SYSTEM	\$55,758.30	Estimate Item Adjustment (0024) due to user frizzm overridding Payment
1020 - Total						8		SYSTEM	(\$55,758.30)	
1050 NU 43, Construction PRESTRESSED Stockpile CONC NU-GIRDER STMI Total S333,402.76 S333,402.					- Total				\$0.00	
1050				Material - Tot	tal				\$0.00	
PRESTRESSED Stockpile 2023 - Total - Total - S333,402.76		1020 -	Total						\$0.00	
1050 - Total \$333,402.76		1050	PRESTRESSED	Stockpile		7		SYSTEM	\$333,402.76	Payment Estimate Item Adjustment generated Stockpile Transaction
STEEL (BRIDGES) Material Sun 30, 2023 SYSTEM Sy,880.00 STEEL (BRIDGES) STEEL (BRIDGES) STEEL (BRIDGES) SUN 30, 2023 SYSTEM Sy,880.00 STEEL (BRIDGES) SUN 30, 2023 SYSTEM Sy,880.00 Sy,880.00 Sy,880.00 Sy,880.00 SYSTEM Sy,880.00 Sy,980.00 Sy,980.0			CONC NO-GIRDER	STIVII	- Total				\$333,402.76	
1060 REINFORCING STEEL (BRIDGES) Material				Construction	Stockpile S	TMI - Total			\$333,402.76	
2023 Estimate Item Adjustment (0025) due to user frizzm overridding Payment Estimate Exception 42 on the current Payment Estimate.		1050 -	Total						\$333,402.76	
Total S0.00		1060		Material		8		SYSTEM	\$9,880.00	Estimate Item Adjustment (0025) due to user frizzm overridding Payment
1060 - Total S0.00						8		SYSTEM	(\$9,880.00)	
1070 REINFORCING STEEL (EPOXY COATED) Material 8 Jun 30, 2023 SYSTEM \$23,440.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 44 on the current Payment Estimate.					- Total				\$0.00	
REINFORCING STEEL (EPOXY COATED) Material 8				Material - Tot	tal				\$0.00	
STEEL (EPOXY COATED) 8 Jun 30, 2VSTEM (\$23,440.00) - Total S0.00 Material - Total S0.00		1060 -	Total						\$0.00	
Total S0.00 Material - Total \$0.00 1070 - Total \$0.00 TEMP. TRAFFIC BARRIER ANCHORED., CONT CONT Solution S		1070	STEEL (EPOXY	Material		8		SYSTEM	\$23,440.00	Estimate Item Adjustment (0026) due to user frizzm overridding Payment
Material - Total \$0.00						8		SYSTEM	(\$23,440.00)	
TEMP. TRAFFIC BARRIER ANCHORED., CONT Total Temp. TRAFFIC BARRIER ANCHORED., CONT Total Temp. Traffic BARRIER ANCHORED., CONT Total Temp. Traffic BARRIER ANCHORED., CONT Temp. Traffic BARRIER STATE BA					- Total				\$0.00	
TEMP. TRAFFIC BARRIER ANCHORED., CONT To be a control of the current Payment Estimate Item Adjustment (0016) due to user baiamf1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. May 16, 2023 SYSTEM (\$32,700.00) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user frizzm overridding Payment Estimate Item Adjustment (0019) due to user frizzm overridding Payment Estimate Exception 15 on the current Payment Estimate. Jun 2, 2023 SYSTEM (\$32,700.00) This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate.				Material - To	tal				\$0.00	
BARRIER ANCHORED., CONT 5 May 16, 2023 Estimate Exception 5 on the current Payment Estimate. 5 May 16, 2023 This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate. 6 Jun 2, 2023 This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate Exception 15 on the current Payment Estimate. 6 Jun 2, 2023 SYSTEM (\$32,700.00) 7 Jun 16, SYSTEM \$32,700.00 This adjustment offsets the original system-generated Material Payment		1070 -	Total						\$0.00	
5 May 16, 2023 (\$32,700.00) 6 Jun 2, 2023 (\$32,700.00) 6 Jun 2, 2023 (\$32,700.00) 7 Jun 16, SYSTEM (\$32,700.00) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user frizzm overridding Payment Estimate Exception 15 on the current Payment Estimate. 7 Jun 16, SYSTEM (\$32,700.00) This adjustment offsets the original system-generated Material Payment		5003	BARRIER ANCHORED.,	Material		5		SYSTEM	\$32,700.00	Estimate Item Adjustment (0016) due to user baiamf1 overridding Payment
2023 Estimate Item Adjustment (00 19) due to user frizzm overridding Payment Estimate Exception 15 on the current Payment Estimate. 6 Jun 2, 2023 (\$32,700.00) 7 Jun 16, SYSTEM \$32,700.00 This adjustment offsets the original system-generated Material Payment			CONT			5		SYSTEM	(\$32,700.00)	
2023 7 Jun 16, SYSTEM \$32,700.00 This adjustment offsets the original system-generated Material Payment						6		SYSTEM	\$32,700.00	Estimate Item Adjustment (0019) due to user frizzm overridding Payment
						6		SYSTEM	(\$32,700.00)	
						7		SYSTEM	\$32,700.00	

Jul 6, 2023



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3451	5003	TEMP. TRAFFIC	Material						Estimate Exception 20 on the current Payment Estimate.
		ANCHORED., CONT			7	Jun 16, 2023	SYSTEM	(\$32,700.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	5003 - Total							\$0.00	
	5005	SEQUENTIAL FLASHING WARNING LIGHT	Material		8	Jun 30, 2023	SYSTEM	\$9,584.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user frizzm overridding Payment Estimate Exception 20 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$9,584.40)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	5005 - Total								
J4I3451 -	3451 - Total								
Overall -	Total						\$331,299.52		

MoDOT

Contract Adjustments for Contract - 221021-C02

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 28 of 28