Progress Estimate N 15	lumber	Contract ID Prime Contracto	221021-F01 r Kozeny-Wagner		y Period Start y Period End			Original Contract Amount Net Change Order Amount Current Contract Amount	\$13,400,000.00 \$344,544.28 \$13,744,544.28	
Approval Date									By User	
August 16, 2023			Generated and	Approved	(and should be	considered	d Draft)	at the Project Office Level by	fernam1	
August 17, 2023		F	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by						amburs1	
August 17, 2023			Reviewed and Approved at the Central Office Controllers Office Level by						ramses1	
Original Completion	Original Completion Date Current C				ual Completion Date			% of Current Contract Amou	unt Complete	
December 1, 202	Decemb	er 1, 2023				67.47%				
	Contract	Informational Dat	es		Mil	estones				
Date Description	Original	Completion Date	Current Complet	ion Date	No Milestones Exist for Cont		Contrac	t		
Acceptance Date										
Awarded Date	Novembe	r 2, 2022	November 2, 2022	2						
Letting Date	October 2	21, 2022	October 21, 2022							
Notice to Proceed Date	January 2	2, 2023	January 2, 2023							
Open to Traffic Date										
Work Began Date	January 1	8, 2023	January 18, 2023							

Contract Total Pay For Estimate No. 15			
	This Estimate	Previous	To Date
221021-F01			
Total Posted Items Pay	\$682,693.85	\$8,590,976.46	\$9,273,670.31
Gross Item Adjustments	(\$83,875.50)	\$483,007.08	\$399,131.58
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	(\$4,000.00)	(\$4,000.00)
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
		<mark>\$9,069,983.54</mark>	\$9,668,801.89
Contract Total Payable This Estimate:	\$598,818.35		

Contract Total Payable This Estimate:

Items	Paid This	Estimate	Period
Items		Loundle	<u>I enou</u>

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3501	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$278,226.990	0.04	\$11,129.08
	0100	6046018A	18 IN. SLOTTED DRAIN	LF	\$408.000	470	\$191,760.00
	0400	6061060	MGS GUARDRAIL	LF	\$28.000	312.5	\$8,750.00
	0410	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	LF	\$32.000	450	\$14,400.00
	0430	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$3,700.000	3	\$11,100.00
	0460	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$3,100.000	1	\$3,100.00
	0830	7040163	CONCRETE CRACK FILLER	SQYD	\$34.730	151	\$5,244.23
	0850	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	SQFT	\$14.000	2,750	\$38,500.00
	0870	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	SQFT	\$4.000	2,750	\$11,000.00
	0880	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	SQFT	\$2.000	4,600	\$9,200.00
	1000	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	SQFT	\$14.000	1,600	\$22,400.00
	1020	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	SQFT	\$4.000	1,600	\$6,400.00
	1030	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	SQFT	\$2.000	3,275	\$6,550.00
	1070	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER/SEALER	SQYD	\$37.850	2,725	\$103,141.25
	1150	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	SQFT	\$14.000	5,000	\$70,000.00
	1170	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	SQFT	\$4.000	5,000	\$20,000.00
	1180	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	SQFT	\$2.000	4,250	\$8,500.00
	1300	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	SQFT	\$14.000	1,725	\$24,150.00



Progress Estimate Number 15		e Number	Contract ID221021-F01Pay Period StartAugustPrime ContractorKozeny-Wagner, Inc.Pay Period EndAugust	Ind August 15, 2023		Original Contract Amount Net Change Order Amount Current Contract Amount		
Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount	
J6I3501	1320	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	SQFT	\$4.000	1,725	\$6,900.00	
	1420	6233000	EPOXY POLYMER WEARING SURFACE	SQYD	\$33.200	661	\$21,945.20	
	1450	6233000	EPOXY POLYMER WEARING SURFACE	SQYD	\$33.100	1,160	\$38,396.00	
	1480	6233000	EPOXY POLYMER WEARING SURFACE	SQYD	\$39.950	587	\$23,450.65	
	5006	7040163	CONCRETE CRACK FILLER	SQYD	\$28.880	259	\$7,479.92	
	5007	7040163	CONCRETE CRACK FILLER	SQYD	\$28.880	129	\$3,725.52	
Project J6	<mark>13501 - Tot</mark>	tal					\$667,221.85	
J6I3653	1660	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	SQYD	\$321.000	32	\$10,272.00	
	1690	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	LF	\$8.000	520	\$4,160.00	
	1700	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$13.000	80	\$1,040.00	
Project J6	<mark>13653 - Tot</mark>	tal					\$15,472.00	
Overall - T	otal						\$682,693.85	

Contract Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3501	0100	18 IN. SLOTTED DRAIN	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$60,630.00)
	0270	TEMPORARY TRAFFIC Material BARRIER, CONTRACTOR FURNISHED / RETAINED					\$30.72	(\$62,208.00
	0270	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	2,025	\$30.72	\$62,208.00
	0400	MGS GUARDRAIL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$4,934.38
	0410	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$8,559.00
	0430	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$6,462.00
	0460	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$1,875.00)
	0580	MISC.	Material			-18	\$29.50	(\$531.00
	0580	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	18	\$29.50	\$531.00
	0590	MISC.	Material			-64	\$69.00	(\$4,416.00
	0590	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user fernam1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	64	\$69.00	\$4,416.00
	0680	MISC.	Material			-4	\$680.00	(\$2,720.00



No. Ocantly Adjustment Window Countly Window Adjustment Window Countly Window Adjustment Window Countly Window Adjustment Window Countly Window Adjustment Window Countly Window Adjustment Window Mile Window Adjustment Window Countly Window Adjustment Window Countly Window Adjustment Window Adjustment Window Adjustment Window Adjustment Window Mile Window Status Window Window Status Window Status Wind	Prog	ress Es		Contract II Prime Con		21-F01 ny-Wagner, Inc	Pay Period End August 15, 2023 Net	inal Contract A Change Order ent Contract A	Amount \$3	3,400,000.00 44,544.28 3,744,544.28
Image: Constraint of the constra	Project Number		Item Descripti	ion		Adjustment	Comments		Adjustment	Adjustment amount
0750MISC.MaterialThe adjustment official the original system. Adjustment (0010) due to user fermant. Original pystem. Serial Estimate Isonate I	J6I3501	0680		MISC.	Material		generated Material Payment Estimate Iter Adjustment (0009) due to user fernam overridding Payment Estimate Exception 1	n 1 0	\$680.00	\$2,720.00
Image: Section of the section of th		0750		MISC.	Material			-8,770	\$2.00	(\$17,540.00)
0760MISC.MaterialThis adjustment offsets the original system- Adjustment (001) due to user fearmatic term Adjustment (001) due to user fearmatic term andjustment (011) due to user fearmatic term adjustment (011) due to user fearmatic adjustment (011) due to user fearmatic the oursert Payment Estimate term adjustment (012) due to user fearmatic the ourser terms of the ourser term adjustment (013) due to user fearmatic the ourser terms of the ourser terms of adjustment (012) due to user fearmatic the ourser terms of adjustment (013) due to user fearmatic the ourser terms of the ourser terms of<		0750		MISC.	Material		generated Material Payment Estimate Iter Adjustment (0010) due to user fernam overridding Payment Estimate Exception 1	n 1 1	\$2.00	\$17,540.00
Image: Constraint of the second sec		0760		MISC.	Material			-9,030	\$2.50	(\$22,575.00)
1070MISC.MaterialThis adjustment offsets the original system dystment (DC1) due to user fermant overridding Payment Estimate termant overridding Payment Estimate termant overridding Payment Estimate termant overridding Payment Estimate termant the current Payment Estimate termant dystment (DC1) due to user fermant overridding Payment Estimate termant dystment (DC1) due to user fermant overridding Payment Estimate termant overridding Payment Estimate termant overridding Payment Estimate termant 		0760		MISC.	Material		generated Material Payment Estimate Iter Adjustment (0011) due to user fernam overridding Payment Estimate Exception 1	n 1 2	\$2.50	\$22,575.00
Image: Section of the current Payment Estimate Item Adjustment (012) due to user fremant overridding Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate Item Adjustment (013) due to user fremant overridding Payment Estimate Item 		1070		MISC.	Material			-7,602	\$37.85	(\$287,735.70)
Image: Note of the control of the c		1070		MISC.	Material		generated Material Payment Estimate Itel Adjustment (0012) due to user fernam overridding Payment Estimate Exception 5 c	n 1 n	\$37.85	\$287,735.70
WEARING SURFACEMeterialgenerated Material Payment Estimate Item Adjustment (0013) due to user fermant overridding Payment Estimate Exception 2 on the current Payment Estimate Item Adjustment (0014) due to user fermant overridding Payment Estimate Exception 2 ore the current Payment Estimate Item Adjustment offsets the original system- overridding Payment Estimate Exception 2 ore the current Payment Estimate Item Adjustment offsets the original system- overridding Payment Estimate Item Adjustment (0014) due to user fermant 		1420			Material			-661	\$33.20	(\$21,945.20)
IndexSEALIndexIndexIndex1440OPEN CELL FOAM JOINT SEALMaterial SEALThis adjustment offsets the original system- depended Material Payment Estimate Exception 6 on overridding Payment Estimate Exception 6 on the current Payment Estimate Exception 6 on overridding Payment Estimate Exception 6 on the current Payment Estimate Exception 7 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 7 on the current Payment Estimate Exception 4 on the current Payment Estimate Estimate Except		1420			Material		generated Material Payment Estimate Itel Adjustment (0013) due to user fernam overridding Payment Estimate Exception 2 of	n 1 n	\$33.20	\$21,945.20
SEALSEALgenerated Material Payment Estimate Item Adjustment (0014) due to user fernami overridding Payment Estimate Exception 6 on the current Payment Estimate Exception 6 on the current Payment Estimate Exception 6 on the current Payment Estimate Item Adjustment (0016) due to user fernami overridding Payment Estimate Item Adjustment (0016) due to user fernami overridding Payment Estimate Item Adjustment (0016) due to user fernami overridding Payment Estimate Item Adjustment (0016) due to user fernami 		1440	OPEN CELL FOA		Material			-76	\$101.00	(\$7,676.00)
WEARING SURFACEMaterialThis adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user fernan1 overridding Payment Estimate Exception 3 on the current Payment Estimate.1,160\$33.10\$38,396.001470OPEN CELL FOAM JOINT SEALMaterialMaterialThis adjustment offsets the original system- overridding Payment Estimate106\$96.00\$10,176.001470OPEN CELL FOAM JOINT SEALMaterialThis adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user fernam1 overridding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0016) due to user fernam1 overridding SURFACE\$39.95\$23,450.651480EPOXY POLYMER WEARING SURFACEMaterialThis adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user fernam1 overridding Payment Estimate Exception 4 on the current Payment Estimate Exception 4 on the current Payment Estimate.\$89.95\$23,450.65		1440	OPEN CELL FOA		Material		generated Material Payment Estimate Iter Adjustment (0014) due to user fernam overridding Payment Estimate Exception 6 d	n 1 n	\$101.00	\$7,676.00
WEARING SURFACEweak and a second		1450			Material			-1,160	\$33.10	(\$38,396.00)
Image: Seal seal seal seal seal seal seal seal s		1450			Material		generated Material Payment Estimate Itel Adjustment (0015) due to user fernam overridding Payment Estimate Exception 3 of	n 1 n	\$33.10	\$38,396.00
SEALSEALgenerated Material Payment Estimate Item Adjustment (0016) due to user fernam1 overridding Payment Estimate Exception 7 on the current Payment Estimate.dial1480EPOXY POLYMER WEARING SURFACEMaterialMaterial-587\$39.95(\$23,450.65)1480EPOXY POLYMER WEARING SURFACEMaterialThis adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user fernam1 overridding Payment Estimate Exception 4 on the current Payment Estimate.587\$39.95\$23,450.65)		1470	OPEN CELL FOA		Material			-106	\$96.00	(\$10,176.00)
WEARING SURFACE WEARING SURFACE Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user fernam1 overridding Payment Estimate Exception 4 on the current Payment Estimate. \$87.9000000000000000000000000000000000000		1470	OPEN CELL FOA		Material		generated Material Payment Estimate Itel Adjustment (0016) due to user fernam overridding Payment Estimate Exception 7 o	n 1 n	\$96.00	\$10,176.00
WEARING SURFACE generated Material Payment Estimate Item Adjustment (0017) due to user fernam1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		1480			Material			-587	\$39.95	(\$23,450.65)
5006 CONCRETE CRACK FILLER Overrun -49 \$28.88 (\$1,415.12)		1480			Material		generated Material Payment Estimate Itel Adjustment (0017) due to user fernam overridding Payment Estimate Exception 4 o	n 1 n	\$39.95	\$23,450.65
		5006	CONCRETE CRAC	K FILLER	Overrun		-		\$28.88	(\$1,415.12)



			Contract ID 221021-F01 Prime Contractor Kozeny-Wagner, Inc			Pay Period StartAugust 2, 2023OrPay Period EndAugust 15, 2023NoCurrentCurrent				Amount	\$13,400,000.00 \$344,544.28 \$13,744,544.28	
Project Number	Line No.			Adjustment Type Adjustment Type		Co	mments		Adjustment Quantity	Line Item Adjustmer Unit Price	nt amount	
Total											(\$83,875.50)	



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information											
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J6I3501	l 64-1(95)	8 Bridge rehabilitations, drainage, and ITS	I-64	ST LOUIS	at I-64 and I-270 interchange							
J6I3653	l 270-5(368)	Pavement repair	I-270	ST LOUIS	from Route 340 to Manchester Road							

Totals by Job Numbers

00504			
\$13501	This Estimate	Previous	To Date
Posted Item Pay	\$667,221.85	\$6,463,433.76	\$7,130,655.61
Gross Item Adjustments	(\$83,875.50)	\$483,007.08	\$399,131.58
Gross Item Pay	\$583,346.35	\$6,946,440.84	\$7,529,787.19
Incentive	\$0.00	\$0.00	\$0.00
		\$0.00	\$0.00
Disincentive	\$0.00		• • • • •
Liquidated Damages	\$0.00	(\$3,410.00)	(\$3,410.00)
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
013653	This Estimate	Previous	To Date
Posted Item Pay	This Estimate \$15,472.00	Previous \$2,127,542.70	To Date \$2,143,014.70
Posted Item Pay	\$15,472.00	\$2,127,542.70	\$2,143,014.70
Posted Item Pay Gross Item Adjustments Gross Item Pay	\$15,472.00 \$0.00 \$15,472.00	\$2,127,542.70 \$0.00 \$2,127,542.70	\$2,143,014.70 \$0.00 \$2,143,014.70
Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive	\$15,472.00 \$0.00 \$15,472.00 \$0.00	\$2,127,542.70 \$0.00 \$2,127,542.70 \$0.00	\$2,143,014.70 \$0.00 \$2,143,014.70 \$0.00
Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive Disincentive	\$15,472.00 \$0.00 \$15,472.00 \$0.00 \$0.00	\$2,127,542.70 \$0.00 \$2,127,542.70 \$0.00 \$0.00	\$2,143,014.70 \$0.00 \$2,143,014.70 \$0.00 \$0.00
Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive	\$15,472.00 \$0.00 \$15,472.00 \$0.00	\$2,127,542.70 \$0.00 \$2,127,542.70 \$0.00	\$2,143,014.70 \$0.00 \$2,143,014.70 \$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Ferrou			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6I3501, Item 6173600D, Project Item Line Number 0270, Material Set 6173600D96, Material 0617TCRCTF - Type F Concrete Traffic Barrier, Acceptance Action Generic 0617TCRCTF is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3501, Item 6233000, Project Item Line Number 1420, Material Set 623300096, Material 1039AGPC - Aggregate for Epoxy Polymer Conc Overlay, Acceptance Action Generic 1039AGPC is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3501, Item 6233000, Project Item Line Number 1450, Material Set 623300096, Material 1039AGPC - Aggregate for Epoxy Polymer Conc Overlay, Acceptance Action Generic 1039AGPC is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3501, Item 6233000, Project Item Line Number 1480, Material Set 623300096, Material 1039AGPC - Aggregate for Epoxy Polymer Conc Overlay, Acceptance Action Generic 1039AGPC is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3501, Item 6239905, Project Item Line Number 1070, Material Set 6239905, Material 1039AGPC - Aggregate for Epoxy Polymer Conc Overlay, Acceptance Action Generic 1039AGPC is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3501, Item 7172054, Project Item Line Number 1440, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3501, Item 7172054, Project Item Line Number 1470, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3501, Item 9109902, Project Item Line Number 0580, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3501, Item 9109902, Project Item Line Number 0590, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3501, Item 9109902, Project Item Line Number 0680, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3501, Item 9109903, Project Item Line Number 0750, Material Set 9109903, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3501, Item 9109903, Project Item Line Number 0760, Material Set 9109903, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Item Overrun: Contract 221021-F01, Contract Project J6l3501, Project Item Line Number 5006, Contract Line Item Number 5006, Item 7040163, Minor Item.	Waiting on Change Order.	fernam1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 221021-F01, Contract Project J6I3501, Project Item Line Number 0820, Contract Line Item Number 0820, Item 7040104, Minor Item.	Waiting on Change Order.	fernam1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 221021-F01, Contract Project J6I3501, Project Item Line Number 0970, Contract Line Item Number 0970, Item 7040104, Minor Item.	Waiting on Change Order.	fernam1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 221021-F01, Contract Project J6I3501, Project Item Line Number 1110, Item 7040104, Minor Item.	Waiting on Change Order.	fernam1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 221021-F01, Contract Project J6I3501, Project Item Line Number 1430, Contract Line Item Number 1430, Item 7040104, Minor Item.	Waiting on Change Order.	fernam1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 221021-F01, Contract Project J6I3501, Project Item Line Number 1490, Contract Line Item Number 1490, Item 7040104, Minor Item.	Waiting on Change Order.	fernam1	Acknowledged



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Q					Report Generated date and can differ from the posted am	ount at the	time the Es	stimate was	Generat	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
221021-F01	J6I3501	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.40	\$278,226.99	\$111,290.80
		0001	0020	2063000	CLASS 3 EXCAVATION	1,233.00	0.00	1,233.00	CUYD	326.00	\$54.00	\$17,604.00
		0001	0030	2063500	CULVERT CLEANOUT	1.00	0.00	1.00	EA	0.00	\$3,300.00	\$0.00
		0001	0040	2153000	SHAPING SLOPES, CLASS III	2.00	0.00	2.00	100F	0.00	\$3,000.00	\$0.00
		0001	0050	3030600	FURNISHING ROCK BASE MATERIAL	2,574.00	0.00	2,574.00	SQYD	0.00	\$11.00	\$0.00
		0001	0060	3030610A	PLACING ROCK BASE	2,574.00	0.00	2,574.00	SQYD	0.00	\$8.00	\$0.00
		0001	0070	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	40.00	0.00	40.00	SQYD	0.00	\$13.75	\$0.00
		0001	0080	4138000	PCCP CRACK FILLING	7,650.00	0.00	7,650.00	LF	0.00	\$4.50	\$0.00
		0001	0090	5021334	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	2,573.60	0.00	2,573.60	SQYD	0.00	\$103.85	\$0.00
		0001	0100	6046018A	18 IN. SLOTTED DRAIN	1,867.00	0.00	1,867.00	LF	550.00	\$408.00	\$224,400.00
		0001	0110	6046024A	24 IN. SLOTTED DRAIN	491.00	0.00	491.00	LF	0.00	\$468.00	\$0.00
		0001	0120	6086004	CONCRETE SIDEWALK, 4 IN.	40.00	0.00	40.00	SQYD	0.00	\$91.00	\$0.00
		0001	0130	6091052	CURB AND GUTTER TYPE B	60.00	0.00	60.00	LF	0.00	\$73.60	\$0.00
		0001	0140	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	100.00	0.00	100.00	LF	0.00	\$54.00	\$0.00
		0001	0150	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	35.00	0.00	35.00	CUYD	0.00	\$55.00	\$0.00
		0001	0160	6096042	PLACING TYPE 2 ROCK DITCH LINER	35.00	0.00	35.00	CUYD	0.00	\$55.00	\$0.00
		0001	0170	6116010A	SLOPE PROTECTION	53.00	0.00	53.00	SQYD	0.00	\$197.00	\$0.00
		0001	0180	6122014	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	4.00	0.00	4.00	EA	2.00	\$3,355.00	\$6,710.00
		0001	0190	6122020	REPLACEMENT SAND BARREL	68.00	0.00	68.00	EA	0.00	\$195.00	\$0.00
		0001	0200	6122030	IMPACT ATTENUATOR (RELOCATION)	4.00	0.00	4.00	EA	0.00	\$722.00	\$0.00
		0001	0210	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.00
		0001	0220	6139911	MISC.FURNISHING & PLACING HOT POLYMER CONCRETE PATCHING FOR CLASS A PARTIAL DEPT PVMT REPAIR	33,307.00	-33,307.00	0.00	LB	0.00	\$3.50	\$0.00
		0001	0230	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	24.00	0.00	24.00	EA	0.00	\$1,000.00	\$0.00
		0001	0240	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$680,000.00	\$340,000.00
		0001	0250	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	2.00	0.00	2.00	EA	0.00	\$2,800.00	\$0.00
		0001	0260	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	1,501.00	0.00	1,501.00	LF	0.00	\$129.00	\$0.00
		0001	0270	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED /	3,766.00	0.00	3,766.00	LF	2,025.00	\$30.72	\$62,208.00
		0001	0280	6175010A	RETAINED RELOCATING TEMPORARY TRAFFIC BARRIER	2,953.00	0.00	2,953.00	LF	0.00	\$13.08	\$0.00
		0001	0290	6181000	MOBILIZATION	1.00	-1.00	0.00	LS		\$1,000,000.00	\$0.00
		0001	0291	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$920,945.00	\$920,945.00
		0001	0300		TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	19,406.00	0.00	19,406.00	LF	0.00	\$2.00	\$0.00
		0001	0310		TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	7,997.00	0.00	7,997.00	LF	0.00	\$2.00	\$0.00
		0001	0320		6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	34,828.00	0.00	34.828.00	LF	0.00	\$0.30	\$0.00
		0001	0330	6205903A	PAINT, TYPE L BEADS 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT	25,162.00	0.00	25,162.00	LF	0.00	\$0.30	\$0.00
		0001	0340	6205906A	MARKING PAINT, TYPE L BEADS 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT	7,243.00	0.00	7,243.00	LF	0.00	\$1.00	\$0.00
		0001	0350	6207001	MARKING PAINT, TYPE L BEADS PAVEMENT MARKING REMOVAL	48,044.00	0.00	48,044.00	LF	0.00	\$1.00	\$0.00
		0001	0360	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	21,087.00	0.00	21,087.00	LF	0.00	\$1.00	\$0.00
		0001	0370	6214600A	FLOWABLE BACKFILL	75.00	0.00	75.00	CUYD	14.00	\$300.00	\$4,200.00
		0001	0380	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	13.600.00	0.00	13.600.00	LB	3,235.00	\$3.85	\$12,454.75
		0001	0390	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$13,000.00	\$0.00
		0001	0395	9019901	MISC. TEMPORARY REMOVE AND REPLACE LIGHTING	1.00	0.00	1.00	LS	0.00	\$44,759.00	\$0.00
		0010	0400	6061060	MGS GUARDRAIL	4,050.00	0.00	4,050.00	LF	2,250.00	\$28.00	\$63,000.00
		0010	0400	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	3,400.00	0.00	3,400.00	LF	775.00	\$32.00	\$24,800.00
		0010	0420	6061063	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	625.00	0.00	625.00	LF	75.00	\$45.00	\$3,375.00
		0010	0430	6061069	MGS BRIDGE APPROACH TRANSITION SECTION	19.00	0.00	19.00	EA	8.00	\$3,700.00	\$29,600.00
					(REGULAR/NO CURB)							



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q					ount at the	time the Es	timate was	Generat	ed.			
Contract Nm.CONTRACT				Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)	
221021-F01	J6I3501	0010	0440	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	7.00	0.00	7.00	EA	3.00	\$3,600.00	\$10,800.00
		0010	0450	6061080	MGS END ANCHOR	9.00	0.00	9.00	EA	4.00	\$1,500.00	\$6,000.00
		0010	0460	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	9.00	0.00	9.00	EA	6.00	\$3,100.00	\$18,600.00
		0010	0470	6063019	TYPE E CRASHWORTHY END TERMINAL	1.00	0.00	1.00	EA	0.00	\$78,000.00	\$0.00
		0040	0480	9039902	MISC.COVER EXISITING OVERHEAD SIGNS	12.00	0.00	12.00	EA	10.00	\$5,000.61	\$50,006.10
		0050	0490	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE & PROGRAMMING	1.00	0.00	1.00	LS	0.75	\$21,562.00	\$16,171.50
		0050	0500	9103700	CCTV CAMERA ASSEMBLY, INSTALLED	1.00	0.00	1.00	EA	0.00	\$1,098.00	\$0.00
		0050	0510	9104965	DETECTOR, MICROWAVE, INSTALLED	1.00	0.00	1.00	EA	0.00	\$1,083.00	\$0.00
		0050	0520	9108202	CABLE, 2 AWG, 1 CONDUCTOR, POWER	40.00	0.00	40.00	LF	0.00	\$5.60	\$0.00
		0050	0530	9108206	CABLE, 6 AWG, 1 CONDUCTOR, POWER	60.00	0.00	60.00	LF	0.00	\$3.10	\$0.00
		0050	0540	9108406	WIRE, 6 AWG, BARE NEUTRAL	60.00	0.00	60.00	LF	0.00	\$3.10	\$0.00
		0050	0550	9109901	MISC.ITS ASSET MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$1,420.00	\$0.00
		0050	0560	9109902	MISC.CCTV 60 FOOT POLE	1.00	0.00	1.00	EA	0.00	\$38,051.00	\$0.00
		0050	0570	9109902	109902 MISC.FIBER OPTIC JUMPER	24.00	0.00	24.00	EA	0.00	\$40.00	\$0.00
		0050	0580	9109902	MISC.FIBER OPTIC PIGTAIL	26.00	0.00	26.00	EA	18.00	\$29.50	\$531.00
		0050	0590	9109902	MISC.FUSIION SPLICE	244.00	0.00	244.00	EA	64.00	\$69.00	\$4,416.00
		0050	0600	9109902	MISC.INSTALL COMMUNICATIONS EQUIPMENT	1.00	0.00	1.00	EA	0.00	\$588.00	\$0.00
		0050	0610	9109902	MISC.INSTALL CONDUIT INTO EXISTING BOX	7.00	0.00	7.00	EA	0.00	\$512.00	\$0.00
		0050	0620	9109902	MISC.INSTALL MODOT FURNISHED IP-ADDRESSABLE POWER STRIP	1.00	0.00	1.00	EA	0.00	\$179.00	\$0.00
		0050	0630	9109902	MISC.ITS PULL BOX WITH CONCRETE PAD	15.00	0.00	15.00	EA	15.00	\$3,255.00	\$48,825.00
		0050	0640	9109902	MISC.MODOT BURIED CABLE DRIVEABLE DELINEATOR POST	21.00	0.00	21.00	EA	0.00	\$94.50	\$0.00
		0050	0650	9109902	MISC.PAD MOUNTED POWER SUPPLY, 120V ITS	1.00	0.00	1.00	EA	0.00	\$7,334.00	\$0.00
		0050	0660	9109902	MISC.RACK-MOUNT FIBER INTERCONNECT CENTER	1.00	0.00	1.00	EA	0.00	\$1,163.00	\$0.00
		0050	0670	9109902	MISC.UNDERGROUND SPLICE ENCLOSURE	2.00	0.00	2.00	EA	0.00	\$2,329.00	\$0.00
		0050	0680	9109902	MISC.WALL MOUNTED FIBER INTERCONNECT CENTER	4.00	0.00	4.00	EA	4.00	\$680.00	\$2,720.00
				9109903	MISC.CONDUIT REPAIR	500.00	0.00	500.00	LF	0.00	\$13.00	\$0.00
		0050	0700	9109903	MISC.CONDUIT, HDPE, DRILL 2 INCHES	1,217.00	0.00	1,217.00	LF	110.00	\$17.25	\$1,897.50
		0050	0710	9109903	MISC.CONDUIT, HDPE, DRILL 2-2 INCHES	17,335.00	0.00	17,335.00	LF	17,335.00	\$12.75	\$221,021.25
		0050	0720	9109903	MISC.CONDUIT, PVC, TRENCH, 2 INCHES	164.00	0.00	164.00	LF	0.00	\$17.25	\$0.00
		0050	0730	9109903	MISC.CONDUIT, RIGID, DRILL, 2 INCHES	180.00	0.00	180.00	LF	0.00	\$17.50	\$0.00
		0050	0740	9109903	MISC.DRILLED SHAFT (3FT.0 IN. DIA.)	16.00	0.00	16.00	LF	0.00	\$476.00	\$0.00
		0050	0750	9109903	MISC.FIBER OPTIC CABLE, 24 STRAND, SINGLE MODE	12,190.00	0.00	12,190.00	LF	8,770.00	\$2.00	\$17,540.00
		0050	0760	9109903	MISC.FIBER OPTIC CABLE, 72 STRAND, SINGLE MODE	9,892.00	0.00	9,892.00	LF	9,030.00	\$2.50	\$22,575.00
		0050	0770	9109903	MISC.MoDOT ITS ASSET RELOCATION	1,125.00	0.00	1,125.00	LF	0.00	\$2.50	\$0.00
		0070	0780	2169902	MISC.REMOVAL OF EXISTING BEARINGS	12.00	0.00	12.00	EA	0.00	\$10,000.00	\$0.00
		0070	0790	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER/SEALER	7,397.00	0.00	7,397.00	SQYD	0.00	\$38.70	\$0.00
		0070	0800	7040101	SUBSTRUCTURE REPAIR (FORMED)	200.00	0.00	200.00	SQFT	200.00	\$210.00	\$42,000.00
		0070	0810	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	445.00	0.00	445.00	SQFT	343.50	\$210.00	\$72,135.00
		0070	0820	7040104	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	160.00	\$175.00	\$28,000.00
		0070				268.00	0.00	268.00	SQYD	151.00	\$34.73	\$5,244.23
	0070 0840 7110200 PROTECTIVE COATING - CONCRETE BENTS AND PIERS				1.00	0.00	1.00	LS	0.00	\$33,000.00	\$0.00	
	0070 0850 7125200 SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL				14,500.00	0.00	14,500.00	SQFT	14,500.00	\$14.00	\$203,000.00	
	0070 0860 7125201 SURFACE PREPARATION FOR OVERCOATING STRUCTURAL STEEL (SYSTEM G)				48,700.00	0.00	48,700.00	SQFT	48,700.00	\$7.75	\$377,425.00	
	0070 0870 7125210 FIELD APPLICATION OF INORGANIC ZINC PRIMER				14,500.00	0.00	14,500.00	SQFT	14,500.00	\$4.00	\$58,000.00	
		0070	0880	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	63,200.00	0.00	63,200.00	SQFT	63,200.00	\$2.00	\$126,400.00
	0070 0890 7125370A FINISH FIELD COAT (SYSTEM G)					23,500.00	0.00	23,500.00	SQFT	21,750.00	\$2.00	\$43,500.00



Total Paid / All Items / All Estimates (Including this Estimate)

I total Pall (I All terms / All Estimates (including uns Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					Report Generated date and can differ from the posted am	ount at the	time the Es	stimate was	Generat	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
221021-F01	J6I3501	0070	0900	7129901	MISC.CLEAN AND FLUSH DRAINAGE SYSTEM	1.00	0.00	1.00	LS	0.00	\$5,550.00	\$0.00
		0070	0910	7129902	MISC.CLEAN AND FLUSH EXISTING EXPANSION JOINT SEAL	4.00	0.00	4.00	EA	0.00	\$720.00	\$0.00
		0070	0920	7161002	LAMINATED NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	0.00	\$2,250.00	\$0.00
		0070	0930	7163000	TYPE N PTFE BEARING	6.00	-6.00	0.00	EA	0.00	\$3,025.00	\$0.00
		0071	0940	6239905	MISC.EPOXY URETHAN POLYMER CONCRETE WEARING SURFACE WITH HEALER/SEALER	4,677.00	0.00	4,677.00	SQYD	4,677.00	\$36.80	\$172,113.60
		0071	0950	7040101	SUBSTRUCTURE REPAIR (FORMED)	185.00	0.00	185.00	SQFT	0.00	\$210.00	\$0.00
		0071	0960	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	315.00	0.00	315.00	SQFT	225.50	\$210.00	\$47,355.00
		0071	0970	7040104	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	131.00	\$220.00	\$28,820.00
		0071	0980	7040163	CONCRETE CRACK FILLER	131.00	0.00	131.00	SQYD	131.00	\$41.67	\$5,458.77
		0071	0990	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$20,000.00	\$0.00
		0071	1000	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	8,200.00	0.00	8,200.00	SQFT	8,150.00	\$14.00	\$114,100.00
		0071	1010	7125201	SURFACE PREPARATION FOR OVERCOATING STRUCTURAL STEEL (SYSTEM G)	32,600.00	0.00	32,600.00	SQFT	27,700.00	\$7.75	\$214,675.00
		0071	1020	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	8,200.00	0.00	8,200.00	SQFT	8,150.00	\$4.00	\$32,600.00
		0071	1030	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	40,800.00	0.00	40,800.00	SQFT	40,800.00	\$2.00	\$81,600.00
		0071	1040	7125370A	FINISH FIELD COAT (SYSTEM G)	20,300.00	0.00	20,300.00	SQFT	17,150.00	\$2.00	\$34,300.00
		0071	1050	7129902	MISC.CLEAN AND FLUSH EXISTING EXPANSION JOINT SEAL	5.00	0.00	5.00	EA	5.00	\$760.00	\$3,800.00
		0072	1060	2169902	MISC.REMOVAL OF EXISTING BEARINGS	21.00	0.00	21.00	EA	0.00	\$9,650.00	\$0.00
		0072	1070	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER/SEALER	11,149.00	0.00	11,149.00	SQYD	7,602.00	\$37.85	\$287,735.70
		0072	1080	7040101	SUBSTRUCTURE REPAIR (FORMED)	440.00	0.00	440.00	SQFT	387.00	\$210.00	\$81,270.00
		0072	1090	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	280.00	0.00	280.00	SQFT	128.00	\$210.00	\$26,880.00
		0072	1100	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	10.00	0.00	10.00	SQFT	0.00	\$320.00	\$0.00
		0072	1110	7040104	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	101.00	\$190.00	\$19,190.00
		0072	1120	7040163	CONCRETE CRACK FILLER	278.00	0.00	278.00	SQYD	190.00	\$34.73	\$6,598.70
		0072	1130	7049903	MISC.BARRIER CURB REPAIR	3.00	0.00	3.00	LF	0.00	\$400.00	\$0.00
		0072	1140	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$31,000.00	\$0.00
		0072	1150	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	21,000.00	0.00	21,000.00	SQFT	21,000.00	\$14.00	\$294,000.00
		0072	1160	7125201	SURFACE PREPARATION FOR OVERCOATING STRUCTURAL STEEL (SYSTEM G)	102,700.00	0.00	102,700.00	SQFT	102,700.00	\$7.75	\$795,925.00
		0072	1170	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	21,000.00	0.00	21,000.00	SQFT	21,000.00	\$4.00	\$84,000.00
		0072	1180	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	123,700.00	0.00	123,700.00	SQFT	123,700.00	\$2.00	\$247,400.00
		0072	1190	7125370A	FINISH FIELD COAT (SYSTEM G)	35,800.00	0.00	35,800.00	SQFT	32,800.00	\$2.00	\$65,600.00
		0072	1200	7129901	MISC.CLEAN AND FLUSH DRAINAGE SYSTEM	1.00	0.00	1.00	LS	0.00	\$11,000.00	\$0.00
		0072	1210	7129902	MISC.CLEAN AND FLUSH EXISTING EXPANSION JOINT SEAL	5.00	0.00	5.00	EA	5.00	\$575.00	\$2,875.00
		0072	1220	7163000	TYPE N PTFE BEARING	21.00	-21.00	0.00	EA	0.00	\$2,725.00	\$0.00
		0073	1230	2161503	REMOVAL OF EXISTING DECK REPAIR	50.00	0.00	50.00	SQFT	8.00	\$77.00	\$616.00
		0073	1240	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER/SEALER	3,573.00	0.00	3,573.00	SQYD	3,573.00	\$36.52	\$130,485.96
		0073	1250	7040101	SUBSTRUCTURE REPAIR (FORMED)	70.00	0.00	70.00	SQFT	0.00	\$210.00	\$0.00
		0073	1260	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	135.00	0.00	135.00	SQFT	51.90	\$210.00	\$10,899.00
		0073	1270	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	24.00	\$210.00	\$5,040.00
		0073	1280	7040163	CONCRETE CRACK FILLER	188.00	0.00	188.00	SQYD	188.00	\$41.67	\$7,833.96
		0073	1290	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$14,000.00	\$0.00
		0073	1300	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	8,300.00	0.00	8,300.00	SQFT	8,250.00	\$14.00	\$115,500.00
		0073	1310	7125201	SURFACE PREPARATION FOR OVERCOATING STRUCTURAL STEEL (SYSTEM G)	26,100.00	0.00	26,100.00	SQFT	24,350.00	\$7.75	\$188,712.50
		0073	1320	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	8,300.00	0.00	8,300.00	SQFT	8,250.00	\$4.00	\$33,000.00
		0073	1330	/ 120305A	INTERMEDIATE FIELD COAT (SYSTEM G)	34,400.00	0.00	34,400.00	SQFT	29,350.00	\$2.00	\$58,700.00



Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	ies are	based on F	Report Generated date and can differ from the posted am	ount at the	time the Es	stimate was	Generat	ted.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
221021-F01	J6I3501	0073	1340	7125370A	FINISH FIELD COAT (SYSTEM G)	18,200.00	0.00	18,200.00	SQFT	16,700.00	\$2.00	\$33,400.00
		0073	1350	7129902	MISC.CLEAN AND FLUSH EXISTING EXPANSION JOINT SEAL	4.00	0.00	4.00	EA	4.00	\$950.00	\$3,800.00
		0074	1360	7125201	SURFACE PREPARATION FOR OVERCOATING STRUCTURAL STEEL (SYSTEM G)	9,900.00	0.00	9,900.00	SQFT	9,900.00	\$7.75	\$76,725.00
		0074	1370	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	9,900.00	0.00	9,900.00	SQFT	9,900.00	\$2.00	\$19,800.00
		0074	1380	7125370A	FINISH FIELD COAT (SYSTEM G)	1,600.00	0.00	1,600.00	SQFT	0.00	\$2.00	\$0.00
		0075	1390	7125201	SURFACE PREPARATION FOR OVERCOATING STRUCTURAL STEEL (SYSTEM G)	9,900.00	0.00	9,900.00	SQFT	9,900.00	\$7.75	\$76,725.00
		0075	1400	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	9,900.00	0.00	9,900.00	SQFT	9,900.00	\$2.00	\$19,800.00
		0075	1410	7125370A	FINISH FIELD COAT (SYSTEM G)	1,600.00	0.00	1,600.00	SQFT	0.00	\$2.00	\$0.00
		0076	1420	6233000	EPOXY POLYMER WEARING SURFACE	1,201.00	-320.00	881.00	SQYD	661.00	\$33.20	\$21,945.20
		0076	1430	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	99.00	\$220.00	\$21,780.00
		0076	1440	7172054	OPEN CELL FOAM JOINT SEAL	94.00	0.00	94.00	LF	76.00	\$101.00	\$7,676.00
		0077	1450	6233000	EPOXY POLYMER WEARING SURFACE	1,792.00	-210.00	1,582.00	SQYD	1,160.00	\$33.10	\$38,396.00
		0077	1460	7040104	HALF-SOLE REPAIR	150.00	0.00	150.00	SQFT	112.00	\$170.00	\$19,040.00
		0077	1470	7172054	OPEN CELL FOAM JOINT SEAL	142.00	0.00	142.00	LF	106.00	\$96.00	\$10,176.00
		0078	1480	6233000	EPOXY POLYMER WEARING SURFACE	1,329.00	-260.00	1,069.00	SQYD	587.00	\$39.95	\$23,450.65
		0078	1490	7040104	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	138.00	\$190.00	\$26,220.00
		0079	1500	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE	1,363.00	-150.00	1,213.00	SQYD	0.00	\$37.50	\$0.00
		0079	1510	7029902	MISC.PILE ENCASEMENT	11.00	0.00	11.00	EA	11.00	\$5,400.00	\$59,400.00
		0079	1520	7040101	SUBSTRUCTURE REPAIR (FORMED)	16.00	0.00	16.00	SQFT	12.00	\$500.00	\$6,000.00
		0079	1530	7040104	HALF-SOLE REPAIR	200.00	0.00	200.00	SQFT	0.00	\$185.00	\$0.00
		0079	1540	7049903	MISC.TYPE B BARRIER REPAIR (FORMED)	15.00	0.00	15.00	LF	0.00	\$260.00	\$0.00
		0079	1550	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$6,200.00	\$0.00
		0079	1560	7125102	SURFACE PREPARATION FOR APPLYING EPOXY-MASTIC	1.00	0.00	1.00	LS	0.00	\$4,000.00	\$0.00
		0079	1570	7125200	PRIMER SURFACE PREPARATION FOR RECOATING STRUCTURAL	900.00	0.00	900.00	SQFT	900.00	\$14.00	\$12,600.00
		0079	1580	7125201	STEEL SURFACE PREPARATION FOR OVERCOATING STRUCTURAL STEEL (SYSTEM G)	20,100.00	0.00	20,100.00	SQFT	15,000.00	\$7.75	\$116,250.00
		0079	1590	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	900.00	0.00	900.00	SQFT	900.00	\$4.00	\$3,600.00
		0079	1600	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	21,000.00	0.00	21,000.00	SQFT	15,000.00	\$2.00	\$30,000.00
		0079	1610	7125370A	FINISH FIELD COAT (SYSTEM G)	6,400.00	0.00	6,400.00	SQFT	5,400.00	\$2.00	\$10,800.00
		0079	1620	7125961	GRAY EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	0.00	\$4,000.00	\$0.00
		0079	1630	7172054	OPEN CELL FOAM JOINT SEAL	65.00	0.00	65.00	LF	0.00	\$91.00	\$0.00
		0001	5001	6189901	MISC.MOBILIZATION Adjust Mobilization for Contract Bond	0.00	1.00	1.00	LS	1.00	\$79,055.00	\$79,055.00
		0001	5002	6061065	MGS GUARDRAIL, 6 FT. POSTS, 1 FT 6.75 IN. SPACING	0.00	162.50	162.50	LF	0.00	\$77.27	\$0.00
		0070	5003	7163000	TYPE N PTFE BEARING	0.00	6.00	6.00	EA	0.00	\$5,407.67	\$0.00
		0072	5004	7163000	TYPE N PTFE BEARING	0.00	21.00	21.00	EA	0.00	\$5,107.67	\$0.00
		0076	5005	7040163	CONCRETE CRACK FILLER	0.00	320.00	320.00	SQYD	150.00	\$28.88	\$4,332.00
		0077	5006	7040163	CONCRETE CRACK FILLER	0.00	210.00	210.00	SQYD	259.00	\$28.88	\$7,479.92
		0078	5007	7040163	CONCRETE CRACK FILLER	0.00	260.00	260.00	SQYD	129.00	\$28.88	\$3,725.52
		0079	5008	7040163	CONCRETE CRACK FILLER	0.00	150.00	150.00	SQYD	0.00	\$28.88	\$0.00
	Project J	613501 - To	otal Value	Posted to D	Date as of Report Generated Date							\$7,130,655.61
	J6I3653	0001	1640	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$20,000.00	\$20,000.00
		0001	1650	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	3.00	\$2,000.00	\$6,000.00
	000			6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	682.70	445.10	1,127.80	SQYD	710.90	\$321.00	\$228,198.90
		0001	1670	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	171.00	0.00	171.00	SQYD	0.00	\$5.00	\$0.00
		0001	1680	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)	171.00	0.00	171.00	SQYD	0.00	\$10.00	\$0.00
					(PAVEMENT REPAIR)							



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note. Fosted Q	uanuues	anu vait	les ale i	based on i	Report Generated date and can differ from the posted an	iounit at the	ume me E	sumate was	Genera	leu.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
221021-F01	J6I3653	0001	1700	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	1,386.00	624.00	2,010.00	EA	1,014.00	\$13.00	\$13,182.00
		0001	1710	6139911	MISC.REMOVAL, FURNISHING & PLACING HOT POLYMER CONC PATCHING FOR CLASS A PARTIAL DEPTH PVMT REPAIRS	389,480.00	60,967.00	450,447.00	LB	450,447.00	\$3.40	\$1,531,519.80
		0001	1720	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.75	\$195,000.00	\$146,250.00
		0001	1730	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN CONTRACTOR FURNISHED AND RETAINED	7.00	0.00	7.00	EA	2.00	\$2,800.00	\$5,600.00
		0001	1740	6171000	CONCRETE TRAFFIC BARRIER, TYPE A	145.00	3.00	148.00	LF	148.00	\$392.00	\$58,016.00
		0001	1750	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$100,000.00	\$100,000.00
		0001	5101	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	0.00	124.00	124.00	EA	0.00	\$9.45	\$0.00
		0001	5102	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	0.00	60.00	60.00	EA	0.00	\$11.29	\$0.00
	Project J	J6I3653 - To	otal Value	Posted to I	Date as of Report Generated Date							\$2,143,014.70
221021-F01 Ove	rall - Tota	I Value Pos	ted to Da	te as of Rep	oort Generated Date							\$9,273,670.31



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6I3501

Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	8/3/23	8/16/23	0.04	LS		705+00				
0100	6046018A	18 IN. SLOTTED DRAIN	8/8/23	8/16/23	170.00	LF	EB I-64 Slotted Drain	705+00		713+40		
			8/14/23	8/16/23	300.00	LF	EB I-64	705+00		713+40		
0400	6061060	MGS GUARDRAIL	8/3/23	8/16/23	312.50	LF	GR Run #3	673+40		676+52		
0410	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	8/6/23	8/16/23	450.00	LF	GR #18	694+38		698+88		
0430	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	8/3/23	8/16/23	1.00	EA	GR Run #3	676+52		676+90		
			8/6/23	8/16/23	2.00	EA	GR #18	694+00		699+25		
0460	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8/3/23	8/16/23	1.00	EA	GR Run #3	672+90		673+40		
0830	7040163	CONCRETE CRACK FILLER	8/14/23	8/16/23	151.00	SQYD	A4650, Lanes 2 & 3	688+50		676+13		
0850	7125200	SURFACE PREPARATION FOR RECOATING	8/6/23	8/16/23	2,750.00	SQFT	Span 7-8, A4650	683+00				
0870	7125210	FIELD APPLICATION OF INORGANIC ZINC	8/6/23	8/16/23	2,750.00	SQFT	Span 7-8, A4650	683+00				
0880	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	8/6/23	8/16/23	4,600.00	SQFT	Span 7-8, A4650	682+50		683+20		
1000	7125200	SURFACE PREPARATION FOR RECOATING	8/6/23	8/16/23	1,600.00	SQFT	Span 6-7, A4651	14+50				
1020	7125210	FIELD APPLICATION OF INORGANIC ZINC	8/6/23	8/16/23	1,600.00	SQFT	Span 6-7, A4651	14+50				
1030	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	8/6/23	8/16/23	3,275.00	SQFT	Span 6-7, A4651	14+30		14+00		
1070	6239905	MISC.	8/4/23	8/16/23	545.00	SQYD	A4652 Lane 2	684+00		694+05		
			8/7/23	8/16/23	734.00	SQYD	A4652 Lane 3	684+00		690+00		
			8/8/23	8/16/23	1,073.00	SQYD	A4652 Lane 3	690+00		694+05		
			8/10/23	8/16/23	373.00	SQYD	A4652 Lane 4	688+00		690+00		
1150	7125200	SURFACE PREPARATION FOR RECOATING	8/6/23	8/16/23	5,000.00	SQFT	Span 7-8, A4652	683+00				
1170	7125210	FIELD APPLICATION OF INORGANIC ZINC	8/6/23	8/16/23	5,000.00	SQFT	Span 7-8, A4652	683+00				
1180	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	8/6/23	8/16/23	4,250.00	SQFT	Span 7-8, A4652	683+00		684+50		
1300	7125200	SURFACE PREPARATION FOR RECOATING	8/6/23	8/16/23	1,725.00	SQFT	Span 6-7, A4653	13+20				
1320	7125210	FIELD APPLICATION OF INORGANIC ZINC	8/6/23	8/16/23	1,725.00	SQFT	Span 6-7, A4653	13+20				
1420	6233000	EPOXY POLYMER WEARING SURFACE	8/4/23	8/16/23	241.00	SQYD	EB A4580 Lane 2	699+19		700+00		
			8/10/23	8/16/23	420.00	SQYD	EB A4580 Lane 3	699+19		700+99		
1450	6233000	EPOXY POLYMER WEARING SURFACE	8/15/23	8/16/23	1,160.00	SQYD	WB I-64 over Ballas, A4580 Lane 3, 4, & 5	700+99		699+19		
1480	6233000	EPOXY POLYMER WEARING SURFACE	8/9/23	8/16/23	587.00	SQYD	A4581 Lanes 1 & 2	699+19		700+99		
5006	7040163	CONCRETE CRACK FILLER	8/14/23	8/16/23	259.00	SQYD	WB A4580, Lanes 2, 3, 4, & 5	700+99		699+19		
5007	7040163	CONCRETE CRACK FILLER	8/9/23	8/16/23	129.00	SQYD	A4581 Lanes 1 & 2	699+19		700+99		

Project: J6I3653

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
1660	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	8/15/23	8/16/23	32.00	SQYD	SB I-260 Lanes 3 & 4	449+30		468+00		
1690	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	8/14/23	8/16/23	520.00	LF	SB I-270 Lanes 3 & 4	449+30		545+00		
1700	6131015	DOWEL BAR (DRILLING, FURNISHING AND INST	8/15/23	8/16/23	80.00	EA	SB I-270 Lanes 3 & 4	449+30		468+00		

The information below this line are details for Construction Signs (if applicable). No Data Available



Aug 18, 2023

ect	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
501	0100	18 IN. SLOTTED DRAIN	Construction Stockpile	Туре	14	Aug 2, 2023	SYSTEM	(\$10,320.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		DIAN	otockpile		15	Aug 16, 2023	SYSTEM	(\$60,630.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total		2020		(\$70,950.00)	
			Construction		Total			(\$70,950.00)	
			Construction	Stockpile - I	6	Apr 2	SYSTEM		Baumont Estimate Item Adjustment generated Stocknile Transaction
			Stockpile			Apr 3, 2023		\$80,238.00	Payment Estimate Item Adjustment generated Stockpile Transaction
					7	Apr 17, 2023	SYSTEM	\$109,005.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$189,243.00	
			Construction	Stockpile S	TMA - Tota	ıl		\$189,243.00	
			Construction Stockpile		4	Mar 2, 2023	SYSTEM	\$51,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$51,600.00	
			Construction	Stockpile S	TMI - Total			\$51,600.00	
	0100 -	Total						\$169,893.00	
	0110	24 IN. SLOTTED DRAIN	Construction Stockpile		6	Apr 3, 2023	SYSTEM	\$71,686.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$71,686.00	
			Construction	Stockpile S	TMI - Total			\$71,686.00	
	0110 -	Total						\$71,686.00	
	0270	TEMPORARY TRAFFIC BARRIER, CONT.	Material		14	Aug 2, 2023	SYSTEM	\$62,208.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		FURN/RE			14	Aug 2, 2023	SYSTEM	(\$62,208.00)	
					15	Aug 16, 2023	SYSTEM	\$62,208.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Aug 16, 2023	SYSTEM	(\$62,208.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0270 -	Total						\$0.00	
	0380	SLAB JACKING MATL HIGH DENSITY	Material		6	Apr 4, 2023	SYSTEM	\$12,454.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Paymen Estimate Exception 10 on the current Payment Estimate.
		POLYURETH			6	Apr 3, 2023	SYSTEM	(\$12,454.75)	
					7	Apr 17, 2023	SYSTEM	\$12,454.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Apr 17, 2023	SYSTEM	(\$12,454.75)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0380 -	Total						\$0.00	
	0400	MGS GUARDRAIL			6	Apr 3, 2023	SYSTEM	(\$9,079.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
					7	Apr 17, 2023	SYSTEM	(\$21,513.87)	Payment Estimate Item Adjustment generated Stockpile Transaction
					15	Aug 16, 2023	SYSTEM	(\$4,934.38)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$35,527.50)	
			Construction		[otal			(\$35,527.50)	
			Construction Stockpile	-eteotopiie-	2	Feb 1, 2023	SYSTEM	\$63,949.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	Total		2023		\$62.040.50	
				- Total				\$63,949.50	



Aug 18, 2023

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3501	0400	MGS GUARDRAIL	Construction	Stockpile ST	MI - Total			\$63,949.50	
	0400 -	Total						\$28,422.00	
	0410	MGS GUARDRAIL, 8	Construction Stockpile		11	Jun 18, 2023	SYSTEM	(\$6,181.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
		FT. POSTS, 6 FT. - 3 IN			15	Aug 16, 2023	SYSTEM	(\$8,559.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$14,740.50)	
			Construction	Stockpile - T	otal			(\$14,740.50)	
			Construction Stockpile		2	Feb 1, 2023	SYSTEM	\$64,668.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$64,668.00	
			Construction	Stockpile ST	MI - Total			\$64,668.00	
	0410 -	Total						\$49,927.50	
	0420	MGS GUARDRAIL, 6	Construction Stockpile		6	Apr 3, 2023	SYSTEM	(\$658.60)	Payment Estimate Item Adjustment generated Stockpile Transaction
		FT. POSTS, 3 FT. - 1.5			7	Apr 17, 2023	SYSTEM	(\$1,317.20)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$1,975.80)	
			Construction	Stockpile - T	otal			(\$1,975.80)	
			Construction Stockpile STMI		1	Jan 17, 2023	SYSTEM	\$16,465.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			5 TWI	- Total				\$16,465.00	
		420 - Total	Construction	Stockpile ST	MI - Total			\$16,465.00	
	0420 -	Total						\$14,489.20	
	0430	MGS BRIDGE APP. TRANS SEC (REG/NO	Construction Stockpile		6	Apr 3, 2023	SYSTEM	(\$6,462.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		CURB)			11	Jun 18, 2023	SYSTEM	(\$4,308.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					15	Aug 16, 2023	SYSTEM	(\$6,462.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$17,232.00)	
				Stockpile - T				(\$17,232.00)	
			Construction Stockpile STMI		2	Feb 1, 2023	SYSTEM	\$40,926.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$40,926.00	
			Construction	Stockpile ST	MI - Total			\$40,926.00	
	0430 - 0440	MGS VERTICAL	Construction		7	Apr 17,	SYSTEM	\$23,694.00 (\$6,690.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		CONCRETE BARRIER	Stockpile	- Total		2023		(\$6,690.00)	
		TRANSITION	Construction	Stockpile - T	otal			(\$6,690.00)	
				Stockpile - I		lan 17	SVETEM		Payment Estimate Item Adjustment generated Stackails Transaction
			Construction Stockpile STMI	Totol	1	Jan 17, 2023	SYSTEM	\$15,610.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total	MI Todat			\$15,610.00	
	0.4.40	Total	Construction	Stockpile ST	wii - Total			\$15,610.00	
	0440 -		Oanata ii		0	A	OVOTEN	\$8,920.00	
	0450	MGS END ANCHOR	Construction Stockpile		6 7	Apr 3, 2023	SYSTEM	(\$820.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total	1	Apr 17, 2023	STOLEM	(\$2,460.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	Stockpile - T	otal			(\$3,280.00)	
			Construction Stockpile	-otockpile - I	2	Feb 1, 2023	SYSTEM	(\$3,280.00) \$7,380.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total		2020		\$7,380.00	
			Construction	Stockpile ST	MI - Total			\$7,380.00	
			Sonstruction	-otoexpile 3 l	-inTotal			\$1,500.00	



Aug 18, 2023

	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
)1 0	0450 -	Total		.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				\$4,100.00	
	0460	TYPE A CRASHWORTHY	Construction Stockpile		6	Apr 3, 2023	SYSTEM	(\$1,875.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		END TERMINAL (MASH)			7	Apr 17, 2023	SYSTEM	(\$7,500.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					15	Aug 16, 2023	SYSTEM	(\$1,875.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$11,250.00)	
			Construction	Stockpile - 1	rotal			(\$11,250.00)	
			Construction Stockpile STMI		1	Jan 17, 2023	SYSTEM	\$16,875.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$16,875.00	
			Construction	Stockpile S	TMI - Total			\$16,875.00	
0	0460 -	Total						\$5,625.00	
0	0470	TYPE E CRASHWORTHY END TERMINAL	Construction Stockpile STMI		2	Feb 1, 2023	SYSTEM	\$59,300.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			01111	- Total				\$59,300.00	
			Construction	Stockpile S	TMI - Total			\$59,300.00	
0	0470 -	Total						\$59,300.00	
0	0480	MISC.	Material		6	Apr 4, 2023	SYSTEM	\$10,001.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fernam1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Apr 3, 2023	SYSTEM	(\$10,001.22)	
					7	Apr 17, 2023	SYSTEM	\$30,003.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fernam1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					7	Apr 17, 2023	SYSTEM	(\$30,003.66)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
0									
	0480 -	Total						\$0.00	
G	0480 - 0580	Total MISC. ITS	Material		13	Jul 17, 2023	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
C			Material		13 13		SYSTEM	\$0.00	Estimate Item Adjustment (0002) due to user fernam1 overridding Payment
C			Material			2023 Jul 17,		\$0.00 \$531.00	Estimate Item Adjustment (0002) due to user fernam1 overridding Payment
C			Material		13	2023 Jul 17, 2023 Aug 2,	SYSTEM	\$0.00 \$531.00 (\$531.00)	Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment
C			Material		13	2023 Jul 17, 2023 Aug 2, 2023 Aug 2,	SYSTEM SYSTEM	\$0.00 \$531.00 (\$531.00) \$531.00	Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment
C			Material		13 14 14	2023 Jul 17, 2023 Aug 2, 2023 Aug 2, 2023 Aug 16,	SYSTEM SYSTEM SYSTEM	\$0.00 \$531.00 (\$531.00) \$531.00 (\$531.00)	Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fernam1 overridding Payment
C			Material	- Total	13 14 14 15	2023 Jul 17, 2023 Aug 2, 2023 Aug 2, 2023 Aug 16, Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$531.00 (\$531.00) \$531.00 (\$531.00) \$531.00	Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fernam1 overridding Payment
C			Material Material - Tot	- Total	13 14 14 15	2023 Jul 17, 2023 Aug 2, 2023 Aug 2, 2023 Aug 16, Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$531.00 (\$531.00) \$531.00 (\$531.00) \$531.00 (\$531.00)	Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fernam1 overridding Payment
		MISC. ITS		- Total	13 14 14 15	2023 Jul 17, 2023 Aug 2, 2023 Aug 2, 2023 Aug 16, Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$531.00 (\$531.00) \$531.00 (\$531.00) \$531.00 (\$531.00) (\$531.00) \$0.00	Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fernam1 overridding Payment
0	0580	MISC. ITS		- Total	13 14 14 15	2023 Jul 17, 2023 Aug 2, 2023 Aug 2, 2023 Aug 16, Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$531.00 (\$531.00) \$531.00 (\$531.00) \$531.00 (\$531.00) (\$531.00) \$0.00	Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fernam1 overridding Payment
0	0580 -	MISC. ITS	Material - To	- Total	13 14 14 15 15	2023 Jul 17, 2023 Aug 2, 2023 Aug 16, 2023 Aug 16, 2023 Jul 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$531.00 (\$531.00) \$531.00 (\$531.00) \$531.00 (\$531.00) (\$531.00) (\$531.00) \$0.00 \$0.00	Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fernam1 overridding Payment Estimate Item Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
0	0580 -	MISC. ITS	Material - To	- Total	13 14 14 15 15 15	2023 Jul 17, 2023 Aug 2, 2023 Aug 16, 2023 Aug 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$531.00 (\$531.00) \$531.00 (\$531.00) \$531.00 (\$531.00) (\$531.00) \$0.00 \$0.00 \$4,416.00	Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
0	0580 -	MISC. ITS	Material - To	- Total	13 14 14 15 15 13 13	2023 Jul 17, 2023 Aug 2, 2023 Aug 16, 2023 Aug 16, 2023 Jul 17, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$531.00 (\$531.00) \$531.00 (\$531.00) \$531.00 (\$531.00) (\$531.00) \$0.00 \$0.00 \$4,416.00 (\$4,416.00)	Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate.



Aug 18, 2023

Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
,			Туре	Adjustment Type	Number	Date	Ву		
J6I3501	0590	MISC. ITS	Material	51					Estimate Exception 9 on the current Payment Estimate.
					15	Aug 16,	SYSTEM	(\$4,416.00)	
				- Total		2023		00.03	
			Material - Tot					\$0.00 \$0.00	
	0590 -	Total	Material - 10	lai				\$0.00	
	0680		Matarial		13	Jul 17	OVOTEM		This adjustment effects the original system generated Material Dayment
	0000	MISC. ITS	Material		15	Jul 17, 2023	SYSTEM	\$2,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					13	Jul 17, 2023	SYSTEM	(\$2,720.00)	
					14	Aug 2, 2023	SYSTEM	\$2,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fernam1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					14	Aug 2, 2023	SYSTEM	(\$2,720.00)	
					15		SYSTEM	¢0.700.00	This adjustment effects the original system reported Material Devices (
					15	Aug 16, 2023	SYSTEM	\$2,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fernam1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					15	Aug 16, 2023	SYSTEM	(\$2,720.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0680 -	Total						\$0.00	
	0750	MISC. ITS	Material		12	Jun 30, 2023	SYSTEM	\$17,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fernam1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Jun 30, 2023	SYSTEM	(\$17,540.00)	
					13	Jul 17, 2023	SYSTEM	\$17,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fernam1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					13	Jul 17, 2023	SYSTEM	(\$17,540.00)	
					14	Aug 2, 2023	SYSTEM	\$17,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fernam1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					14	Aug 2, 2023	SYSTEM	(\$17,540.00)	
					15	Aug 16, 2023	SYSTEM	\$17,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user fernam1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					15	Aug 16, 2023	SYSTEM	(\$17,540.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0750 -	Total						\$0.00	
	0760	MISC. ITS	Material		12	Jun 30, 2023	SYSTEM	\$22,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Jun 30, 2023	SYSTEM	(\$22,575.00)	
					13	Jul 17, 2023	SYSTEM	\$22,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fernam1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					13	Jul 17, 2023	SYSTEM	(\$22,575.00)	
					14	Aug 2, 2023	SYSTEM	\$22,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					14	Aug 2, 2023	SYSTEM	(\$22,575.00)	
					15	Aug 16, 2023	SYSTEM	\$22,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user fernam1 overridding Payment



Aug 18, 2023

t I	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1 0	0760	MISC. ITS	Material						Estimate Exception 12 on the current Payment Estimate.
					15	Aug 16, 2023	SYSTEM	(\$22,575.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0760 -		-	-				\$0.00	
	0820	HALF-SOLE REPAIR	Overrun	Overrun	13	Jul 17, 2023 Aug 2,	SYSTEM	(\$6,650.00)	
				Overrun - T		2023	OTOTEM	(\$10,500.00)	
			Overrun - To		Utai			(\$10,500.00)	
6	0820 -	Total	overrain re					(\$10,500.00)	
	0940	MISC.	Material		11	Jun 18, 2023	SYSTEM	\$172,113.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Jun 18, 2023	SYSTEM	(\$172,113.60)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
C	0940 -	Total						\$0.00	
C	0960	SUBSTRUCTURE REPAIR (UNFORMED)	Material		9	May 16, 2023	SYSTEM	\$17,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	May 16, 2023	SYSTEM	(\$17,850.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0960 -							\$0.00	
C	0970	HALF-SOLE REPAIR	Overrun	Overrun		Jun 18, 2023	SYSTEM	(\$6,820.00)	
			Overrun - To	Overrun - T	otal			(\$6,820.00)	
	0970 -	Total	Overruit - To					(\$6,820.00)	
	1070	MISC.	Material		14	Aug 2, 2023	SYSTEM	\$184,594.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fernam1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Aug 2, 2023	SYSTEM	(\$184,594.45)	
					15	Aug 16, 2023	SYSTEM	\$287,735.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					15	Aug 16, 2023	SYSTEM	(\$287,735.70)	
				- Total				\$0.00	
								\$0.00	
			Material - To	tal					
	1070 -			tal				\$0.00	
		Total SUBSTRUCTURE REPAIR (UNFORMED)		tal	9	May 16, 2023	SYSTEM	\$0.00 \$26,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		SUBSTRUCTURE REPAIR			9 9			\$26,880.00 (\$26,880.00)	Estimate Item Adjustment (0003) due to user fernam1 overridding Payment
		SUBSTRUCTURE REPAIR	Material	- Total		2023 May 16,		\$26,880.00 (\$26,880.00) \$0.00	Estimate Item Adjustment (0003) due to user fernam1 overridding Payment
1	1090	SUBSTRUCTURE REPAIR (UNFORMED)		- Total		2023 May 16,		\$26,880.00 (\$26,880.00) \$0.00 \$0.00	Estimate Item Adjustment (0003) due to user fernam1 overridding Payment
1	1090 1090 -	SUBSTRUCTURE REPAIR (UNFORMED)	Material Material - To	- Total tal	9	2023 May 16, 2023	SYSTEM	\$26,880.00 (\$26,880.00) \$0.00 \$0.00	Estimate Item Adjustment (0003) due to user fernam1 overridding Payment
1	1090	SUBSTRUCTURE REPAIR (UNFORMED)	Material Material - To	- Total tal Overrun	9 12	2023 May 16,		\$26,880.00 (\$26,880.00) \$0.00 \$0.00 (\$190.00)	Estimate Item Adjustment (0003) due to user fernam1 overridding Payment
1	1090 1090 -	SUBSTRUCTURE REPAIR (UNFORMED) Total HALF-SOLE	Material Material - To	- Total tal Overrun Overrun - T	9 12	2023 May 16, 2023 Jun 30,	SYSTEM	\$26,880.00 (\$26,880.00) \$0.00 \$0.00	Estimate Item Adjustment (0003) due to user fernam1 overridding Payment



Aug 18, 2023

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3501	1110 -	Total						(\$190.00)	
	1240	MISC.	Material		7	Apr 17, 2023	SYSTEM	\$130,485.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Apr 17, 2023	SYSTEM	(\$130,485.96)	
					8	May 2, 2023	SYSTEM	\$130,485.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	May 2, 2023	SYSTEM	(\$130,485.96)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1240 -	Total						\$0.00	
	1260	SUBSTRUCTURE REPAIR (UNFORMED)	Material		8	May 2, 2023	SYSTEM	\$10,899.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	May 2, 2023	SYSTEM	(\$10,899.00)	
					9	May 16, 2023	SYSTEM	\$10,899.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	May 16, 2023	SYSTEM	(\$10,899.00)	
				- Total				\$0.00	
			Material - Tot					\$0.00	
	1260 -	Total						\$0.00	
	1280	CONCRETE CRACK FILLER	Material		7	Apr 17, 2023	SYSTEM	\$7,833.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user fernam1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Apr 17, 2023	SYSTEM	(\$7,833.96)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1280 -	Total						\$0.00	
	1420	EPOXY POLYMER WEARING	Material		15	Aug 16, 2023	SYSTEM	\$21,945.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user fernam1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		SURFACE			15	Aug 16, 2023	SYSTEM	(\$21,945.20)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1420 -	Total						\$0.00	
	1430	HALF-SOLE REPAIR	Overrun	Overrun	12	Jun 30, 2023	SYSTEM	(\$4,180.00)	
					14	Aug 2, 2023	SYSTEM	(\$6,600.00)	
				Overrun - T	otal			(\$10,780.00)	
			Overrun - To	tal				(\$10,780.00)	
	1430 -	Total						(\$10,780.00)	
	1440	OPEN CELL FOAM JOINT SEAL	Material		12	Jun 30, 2023	SYSTEM	\$4,141.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Jun 30, 2023	SYSTEM	(\$4,141.00)	
					13	Jul 17, 2023	SYSTEM	\$4,141.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Jul 17, 2023	SYSTEM	(\$4,141.00)	
					14	Aug 2, 2023	SYSTEM	\$7,676.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user fernam1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3501	1440	OPEN CELL	Material						Estimate Exception 3 on the current Payment Estimate.
		FOAM JOINT SEAL			14	Aug 2, 2023	SYSTEM	(\$7,676.00)	
					15	Aug 16, 2023	SYSTEM	\$7,676.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user fernam1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					15	Aug 16, 2023	SYSTEM	(\$7,676.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1440 -	Total						\$0.00	
	1450	EPOXY POLYMER WEARING SURFACE	Material		15	Aug 16, 2023	SYSTEM	\$38,396.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fernam1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					15	Aug 16, 2023	SYSTEM	(\$38,396.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1450 -	Total						\$0.00	
	1470	OPEN CELL FOAM JOINT SEAL	Material		13	Jul 17, 2023	SYSTEM	\$10,176.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fernam1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				1.	13	Jul 17, 2023	SYSTEM	(\$10,176.00)	
					14	Aug 2, 2023	SYSTEM	\$10,176.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user fernam1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					14	Aug 2, 2023	SYSTEM	(\$10,176.00)	
					15	Aug 16, 2023	SYSTEM	\$10,176.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user fernam1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					15	Aug 16, 2023	SYSTEM	(\$10,176.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1470 -							\$0.00	
	1480	EPOXY POLYMER WEARING SURFACE	Material		15	Aug 16, 2023	SYSTEM	\$23,450.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user fernam1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					15	Aug 16, 2023	SYSTEM	(\$23,450.65)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1480 -	Total						\$0.00	
	1490	HALF-SOLE REPAIR	Overrun	Overrun	11	Jun 18, 2023	SYSTEM	(\$7,220.00)	
				Overrun - T	Total		(\$7,220.00)		
			Overrun - Total					(\$7,220.00)	
	1490 -	Total						(\$7,220.00)	
	5006	CONCRETE CRACK FILLER	Overrun	Overrun		Aug 16, 2023	SYSTEM	(\$1,415.12)	
				Overrun - T	otal			(\$1,415.12)	
			Overrun - To	tal				(\$1,415.12)	
								(\$1,415.12)	
	5006 -	Total							
J6I3501 -		Total						\$399,131.58	
		Total FURN & PLACE CONC MATL FOR FULL DEPTH	Material		6	Apr 4, 2023	SYSTEM	\$399,131.58 \$161,848.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
53	1660	FURN & PLACE	Material			2023			
		CONC MATL FOR FULL DEPTH			7	Apr 17, 2023	SYSTEM	\$161,848.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Apr 17, 2023	SYSTEM	(\$161,848.20)	
					8	May 2, 2023	SYSTEM	\$199,950.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	May 2, 2023	SYSTEM	(\$199,950.90)	
					9	May 16, 2023	SYSTEM	\$199,950.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	May 16, 2023	SYSTEM	(\$199,950.90)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1660 -	Total						\$0.00	
	1690	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	Overrun	Overrun	6	Apr 3, 2023	SYSTEM	(\$6,856.00)	
					8	May 2, 2023	SYSTEM	(\$4,328.00)	
					12	Jun 30, 2023	SYSTEM	(\$2,216.00)	
					14	Aug 2, 2023	SYSTEM	\$13,400.00	Unit price based on averaged overrun adjustments for installed quantity on previous payment estimates. Price Adjustments of ',8.00000 - 8.00000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - To	ıtal				\$0.00	
	1690 -	Total						\$0.00	
	1700	DOWEL BAR (DRILLING, FURNISHING AND INST	Material		6	Apr 4, 2023	SYSTEM	\$9,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user fernam1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Apr 3, 2023	SYSTEM	(\$9,360.00)	
					7	Apr 17, 2023	SYSTEM	\$9,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user fernam1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Apr 17, 2023	SYSTEM	(\$9,360.00)	
					8	May 2, 2023	SYSTEM	\$11,180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fernam1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	May 2, 2023	SYSTEM	(\$11,180.00)	
				- Total				\$0.00	
		Material - Total							
	1700 -	Total						\$0.00	
	1710	MISC.	Construction Stockpile	-	4	Mar 2, 2023	SYSTEM	(\$39,324.32)	Payment Estimate Item Adjustment generated Stockpile Transaction
					5	Mar 16, 2023	SYSTEM	(\$66,124.84)	Payment Estimate Item Adjustment generated Stockpile Transaction
					6	Apr 3, 2023	SYSTEM	(\$49,449.32)	Payment Estimate Item Adjustment generated Stockpile Transaction
					7	Apr 17, 2023	SYSTEM	(\$18,889.41)	Payment Estimate Item Adjustment generated Stockpile Transaction
					8	May 2, 2023	SYSTEM	(\$17,254.09)	Payment Estimate Item Adjustment generated Stockpile Transaction
						1	0.000000	(\$47,404,77)	Devenent Estimate Item Adjustment generated Steelwile Transaction
					9	May 16, 2023	SYSTEM	(\$47,161.77)	Payment Estimate Item Adjustment generated Stockpile Transaction



Aug 18, 2023

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3653	1710	MISC.	Construction	Stockpile - 1	ſotal			(\$238,203.75)	
			Construction Stockpile STMI		1	Jan 17, 2023	SYSTEM	\$238,203.75	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$238,203.75	
			Construction	Stockpile STMI - Total				\$238,203.75	
			Overrun	Overrun	12	Jun 30, 2023	SYSTEM	(\$123,307.80)	
					14	Aug 2, 2023	SYSTEM	\$123,307.80	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3.40000 - 3.40000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Total					\$0.00	
	1710 -	Total						\$0.00	
	1740	CONCRETE TRAFFIC BARRIER, TYPE A	Material		6	Apr 4, 2023	SYSTEM	\$58,016.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fernam1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Apr 3, 2023	SYSTEM	(\$58,016.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
			Overrun	Overrun	6	Apr 3, 2023	SYSTEM	(\$1,176.00)	
					14	Aug 2, 2023	SYSTEM	\$1,176.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',392.00000 - 392.00000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - To	tal				\$0.00	
	1740 -	Total						\$0.00	
J6I3653 -	Total							\$0.00	
Overall -	Overall - Total								



Contract Adjustments for Contract - 221021-F01

Estimate Number	Project	Adjustment Type	Other Adjustment Type	Adjustment Amount	Adjustment Percentage by Project	Created Date	Created By	Comments
4	J6I3501	Liquidated Damage	OTHR	(\$3,410.00)	85.25000000	Mar 2, 2023	fernam1	Contractor did not remove lane drop from roadway by designated contract time of 5:00. Lane drop was completely removed by 6:10 AM, per J6I3653 JSP C. \$1,0000 per 15-minute increments will be charged for a total of \$4,000.
	J6I3653	Liquidated Damage	OTHR	(\$590.00)	14.75000000	Mar 2, 2023	fernam1	Contractor did not remove lane drop from roadway by designated contract time of 5:00. Lane drop was completely removed by 6:10 AM, per J6I3653 JSP C. \$1,0000 per 15-minute increments will be charged for a total of \$4,000.
4 - Total					(\$4,000.00)			
Overall -	Total				(\$4,000.00)			