

Pay Estimate Created Date: October 17, 2023

Progress Estimate Number 17		Contract ID 221021-F02 Prime Contractor KCI Construction		r 1, 2023 Original Contract Amount r 15, 2023 Net Change Order Amount Current Contract Amount	t \$505,887.88		
Approval Date							
October 17, 2023		Generated and	d Approved (and should be considere	ed Draft) at the Project Office Level by	gummer1		
October 17, 2023		Reviewed and App	proved (and should be considered Dra	aft) at the Resident Engineer Level by	amburs1		
October 18, 2023			Reviewed and Approved at the Cer	ntral Office Controllers Office Level by	ramses1		
Original Completion Date		Current Completion Date	Actual Completion Date	% of Current Contract Amou	nt Complete		
January 1, 2024 January 1, 2024				75.59%			

	Milestones		
Date Description	Original Completion Date		No Milestones Exist for Contract
Acceptance Date			
Awarded Date	November 2, 2022	November 2, 2022	
Letting Date	October 21, 2022	October 21, 2022	
Notice to Proceed Date	January 2, 2023	January 2, 2023	
Open to Traffic Date			
Work Began Date	February 13, 2023	February 13, 2023	

Contract Total Pay For Estimate No. 17										
		This Estimate	Previous	To Date						
221021-F02										
	Total Posted Items Pay	\$645,614.38	\$11,301,224.98	\$11,946,839.36						
	Gross Item Adjustments	(\$122,047.50)	\$94,075.01	(\$27,972.49)						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
			\$11,395,299.99	\$11,918,866.87						
Contract Total Pay	able This Estimate:	\$523,566.88								

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3534	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$65,000.000	0.1	\$6,500.00
0060 6096042			PLACING TYPE 2 ROCK DITCH LINER	CUYD	\$210.000	163	\$34,230.00
	0130	6169901	MISC.TEMPORARY TRAFFIC CONTROL	LS	\$30,189.300	0.25	\$7,547.33
	0250	7172054	OPEN CELL FOAM JOINT SEAL	LF	\$160.000	154	\$24,640.00
	0340	2169902	MISC.REMOVAL OF EXISTING BEARINGS	EA	\$25,500.000	3	\$76,500.00
	0360	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	SQFT	\$605.000	18	\$10,890.00
	0460	7163000	TYPE N PTFE BEARING	EA	\$7,900.000	4	\$31,600.00
	0470	7173002	SILICONE EXPANSION JOINT SEALANT	LF	\$130.000	128	\$16,640.00
	0640	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	SQFT	\$575.000	-21	(\$12,075.00)
	5006	2169902	MISC.REMOVAL OF EXISTING BEARING ASSEMBLY (Bridge A48811)	EA	\$2,212.840	5	\$11,064.20
	5007	7169902	MISC.INSTALL TYPE N PTFE BEARING ASSEMBLY (Bridge A48811)	EA	\$2,676.350	5	\$13,381.75
	5012	1094000	FORCE ACCOUNT	EA	\$1.000	5,400	\$5,400.00
Project J6I3	534 - Total						\$226,318.28
J6S3556	0990	6169901	MISC.TEMPORARY TRAFFIC CONTROL	LS	\$26,595.000	0.25	\$6,648.75
	1080	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	LB	\$6.000	1,062	\$6,372.00
	1090	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$127,000.000	0.1	\$12,700.00
	1100	7172054	OPEN CELL FOAM JOINT SEAL	LF	\$400.000	50	\$20,000.00
	1110	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE, PROGRAMMING, AND ADJUSTMENT	LS	\$10,000.000	0.25	\$2,500.00

Revision 3/23/2023 Page 1 of 28



Pay Estimate Created Date: October 17, 2023

Progress Estimate Number	Contract ID	221021-F02	Pay Period Start	October 1, 2023	Original Contract Amount	\$15,299,000.00
17	Prime Contractor	KCI Construction Company	Pay Period End	October 15, 2023	Net Change Order Amount	\$505,887.88
17					Current Contract Amount	\$15,804,887.88

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3556	1120	9039902	MISC.COVER EXISTING OVERHEAD SIGNS	EA	\$3,672.000	1	\$3,672.00
	1130	6061060	MGS GUARDRAIL	LF	\$28.560	3,050	\$87,108.00
	1140	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	LF	\$36.720	100	\$3,672.00
	1150	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	EA	\$4,284.000	3	\$12,852.00
	1160	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$4,080.000	7	\$28,560.00
	1170	6061074	MGS HEIGHT AND BLOCK TRANSITION	EA	\$816.000	4	\$3,264.00
	1180	6061080	MGS END ANCHOR	EA	\$1,530.000	8	\$12,240.00
	1190	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$3,264.000	8	\$26,112.00
	1260	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER/SEALER	SQYD	\$46.810	600	\$28,086.00
	1280	7040163	CONCRETE CRACK FILLER	SQYD	\$25.000	100	\$2,500.00
	1370	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	SQFT	\$1,075.000	81	\$87,075.00
	1480	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER/SEALER	SQYD	\$38.230	1,845	\$70,534.35
	1500	7040163	CONCRETE CRACK FILLER	SQYD	\$25.000	216	\$5,400.00
Project J6S	3556 - Tota	ıl					\$419,296.10
Overall - To	tal						\$645,614,38

Contract Adjustments This Estimate

		stments Exist on Contract ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3534	0040	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material			-49	\$215.00	(\$10,535.00
	0040	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	49	\$215.00	\$10,535.00
	0070	SLOPE PROTECTION	Material			-160	\$330.00	(\$52,800.00)
	0070	SLOPE PROTECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user gummer1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	160	\$330.00	\$52,800.00
	0230	FLOWABLE BACKFILL	Material			-5	\$2,900.00	(\$14,500.00)
	0230	FLOWABLE BACKFILL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user gummer1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	5	\$2,900.00	\$14,500.00
	0360	SUBSTRUCTURE REPAIR (UNFORMED)	Material			-281	\$605.00	(\$170,005.00)
	0360	SUBSTRUCTURE REPAIR (UNFORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user gummer1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	281	\$605.00	\$170,005.00
	0460	TYPE N PTFE BEARING	Material			-5	\$7,900.00	(\$39,500.00)
	0460	TYPE N PTFE BEARING	Material		This adjustment offsets the original system-	5	\$7,900.00	\$39,500.00

Page 2 of 28 Revision 3/23/2023



Pay Estimate Created Date: October 17, 2023

Progress Estimate Number
17

Contract ID 221021-F02 Pay Period Start October 1, 2023 Original Contract Amount \$15,299,000.00
Pay Period End October 15, 2023 Original Contract Amount \$505,887.88
Current Contract Amount \$15,894,887.88

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3534					generated Material Payment Estimate Item Adjustment (0006) due to user gummer1 overridding Payment Estimate Exception 22 on the current Payment Estimate.			
	0470	SILICONE EXPANSION JOINT SEALANT	Material			-128	\$130.00	(\$16,640.00)
	0500	SUBSTRUCTURE REPAIR (UNFORMED)	Material			-210	\$520.00	(\$109,200.00)
	0500	SUBSTRUCTURE REPAIR (UNFORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user gummer1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	210	\$520.00	\$109,200.00
	0640	SUBSTRUCTURE REPAIR (UNFORMED)	Material			-86	\$575.00	(\$49,450.00)
	0640	SUBSTRUCTURE REPAIR (UNFORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user gummer1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	86	\$575.00	\$49,450.00
	0770	SUBSTRUCTURE REPAIR (UNFORMED)	Material			-75	\$840.00	(\$63,000.00)
	0770	SUBSTRUCTURE REPAIR (UNFORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user gummer1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	75	\$840.00	\$63,000.00
	0780	HALF-SOLE REPAIR	Material			-20	\$720.00	(\$14,400.00)
	0780	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user gummer1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	20	\$720.00	\$14,400.00
	5004	CLEANING AND EPOXY COATING	Material			-414	\$9.89	(\$4,094.46)
	5004	CLEANING AND EPOXY COATING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user gummer1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	414	\$9.89	\$4,094.46
J6S3556	0950	CONCRETE SIDEWALK, 4 IN.	Material			-26.6	\$910.00	(\$24,206.00)
	0950	CONCRETE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	26.6	\$910.00	\$24,206.00
	0960	SLOPE PROTECTION	Material			-42	\$680.00	(\$28,560.00)
	0960	SLOPE PROTECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user gummer1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	42	\$680.00	\$28,560.00
	1060	FLOWABLE BACKFILL	Material			-5	\$5,000.00	(\$25,000.00)
	1060	FLOWABLE BACKFILL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user gummer1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	5	\$5,000.00	\$25,000.00

Revision 3/23/2023 Page 3 of 28



Pay Estimate Created Date: October 17, 2023

Progress Estimate Number
17

Contract ID 221021-F02 Pay Period Start October 1, 2023 Original Contract Amount \$15,299,000.00\$
Prime Contractor KCI Construction Company Pay Period End October 15, 2023 Net Change Order Amount Current Contract Amount \$15,804,887.88\$

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3556	1080	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	Material			-1,062	\$6.00	(\$6,372.00
	1120	MISC.	Material			-1	\$3,672.00	(\$3,672.00)
	1120	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user gummer1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	1	\$3,672.00	\$3,672.00
	1130	MGS GUARDRAIL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$47,854.50)
	1140	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$1,891.00)
	1150	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$6,795.00)
	1160	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$15,855.00
	1180	MGS END ANCHOR	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$6,680.00
	1190	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$15,000.00
	1370	SUBSTRUCTURE REPAIR (UNFORMED)	Material			-95	\$1,075.00	(\$102,125.00)
	1370	SUBSTRUCTURE REPAIR (UNFORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user gummer1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	95	\$1,075.00	\$102,125.00
	1470	SILICONE EXPANSION JOINT SEALANT	Material			-16	\$310.00	(\$4,960.00
otal								(\$122,047.50)

Revision 3/23/2023 Page 4 of 28



					(Contract Project Information					
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work				
J6I3534	I-55-3(102)	6 Bridge rehabilitations	Various	ST LOUIS	I-55 and I-270						
J6S3556	FAS S503(9)	4 Bridge rehabilitations	Various	ST LOUIS	on Mattis Rd. over I-55, Geyer Rd. over I-44, Craigwold Rd. over I-270 and on I-270 over I-44						
Totals by J	Job Numbers	3									
J6l3534		Item Pay tem Adjustmen	ts <mark>Gross Ite</mark>	m Pay	This Estimate \$226,318.28 (\$16,640.00) \$209,678.28	Previous \$9,181,871.91 \$0.00 \$9,181,871.91	To Date \$9,408,190.19 (\$16,640.00) \$9,391,550.19				
			nents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
J6S3556		Item Pay tem Adjustmen	ts <mark>Gross Ite</mark> i	m Pay	This Estimate \$419,296.10 (\$105,407.50) \$313,888.60	Previous \$2,119,353.07 \$94,075.01 \$2,213,428.08	To Date \$2,538,649.17 (\$11,332.49) \$2,527,316.68				
			ments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				

Revision 3/23/2023 Page 5 of 28



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepencies	Explanation	Entered	Status
Exceptione / Diestopoliole	<u> </u>	Ву	Status
Estimate Exception Type: Insufficient Materials: Project J6S3556, Item 6086004, Project Item Line Number 0950, Material Set 608600496, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on cure to be reported by PAL, need 1.2 gallon of cure, Need QC - sand and rock, Contractor to correct by next pay period.	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3534, Item 6092011, Project Item Line Number 0040, Material Set 609201196, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is Insufficient.	Waiting on cure to be reported by PAL, need 0.4 gallon of cure, Need QC - sand and rock, Need QA concrete report air slump and cylinder.	gummer1	Overridden
	Contractor to correct by next pay period, October 31.		
Estimate Exception Type: Insufficient Materials: Project J613534, Item 6116010A, Project Item Line Number 0070, Material Set 6116010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Waiting on cure to be reported by PAL, need 9.6 gallon of cure, Need QC - sand and rock, Need QC/QA concrete report air slump and cylinder. Need preformed expansion joint Contractor to correct by next pay period, October 31.	gummer1	Overridden
	Weiting on 20 day brook		
Estimate Exception Type: Insufficient Materials: Project J6l3534, Item 6116010A, Project Item Line Number 0070, Material Set 6116010A96, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on 28-day break Waiting on cure to be reported by PAL, need 9.6 gallon of cure, Need QC - sand and rock, Need QC/QA concrete report air slump and cylinder. Need preformed expansion joint	gummer1	Overridden
	Contractor to correct by next pay period, October 31. Waiting on 28-day break		
Estimate Exception Type: Insufficient Materials: Project J6S3556, Item 6116010A, Project Item Line Number 0960, Material Set 6116010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Waiting on cure to be reported by PAL, need 2.5 gallon of cure, Need QC - sand and rock, Need fiber joint on pal Contractor to correct by next pay period.	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3556, Item 6116010A, Project Item Line Number 0960, Material Set 6116010A96, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on cure to be reported by PAL, need 2.5 gallon of cure, Need QC - sand and rock, Need fiber joint on pal Contractor to correct by next pay period.	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3534, Item 6214600A, Project Item Line Number 0230, Material Set 6214600A96, Material 0621FB - Flowable Backfill, Acceptance Action Generic 0621FB is insufficient.	QC/QA - concrete report	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3556, Item 6214600A, Project Item Line Number 1060, Material Set 6214600A96, Material 0621FB - Flowable Backfill, Acceptance Action Generic 0621FB is insufficient.	QC/QA - concrete report	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3556, Item 6252003, Project Item Line Number 1080, Material Set 625200396, Material 0625PLUTUS - Polyurethane for UnderSealing of PVMT, Acceptance Action Generic 0625PLUTUS is insufficient.	QA needs to add preform with Certification from contractor, waiting on certification.	gummer1	Acknowledge
Estimate Exception Type: Insufficient Materials: Project J6l3534, Item 7040102, Project Item Line Number 0360, Material Set 704010296, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	QC/QA - sand and rock QA - strength needed. no cure set up 28 day strength	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3534, Item 7040102, Project Item Line Number 0360, Material Set 704010296, Material 1005CMGV04 - Masonry 0-3/8" Max Gravel, Acceptance Action Generic 1005CMGV04 is insufficient.	QC/QA - sand and rock QA - strength needed. no cure set up 28 day strength	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3534, Item 7040102, Project Item Line Number 0360, Material Set 704010296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	QC/QA - sand and rock QA - strength needed. no cure set up 28 day strength	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3534, Item 7040102, Project Item Line Jumber 0500, Material Set 704010296, Material 1005CMGV04 - Masonry 0-3/8" Max Gravel, Acceptance Action Generic 1005CMGV04 is insufficient.	need to sort out % of E stone and Torpedo stone for substructure concrete Need QA - sand need QA/QC - sand and rock, Contractor to correct by next pay period.	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3534, Item 7040102, Project Item Line Number 0640, Material Set 704010296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	substructure repair required items QA - strength QA/QC rock QA/QC sand	gummer1	Overridden
estimate Exception Type: Insufficient Materials: Project J6l3534, Item 7040102, Project Item Line Item 5040, Material Set 704010296, Material 1005CMGV04 - Masonry 0-3/8" Max Gravel, Acceptance Action Generic 1005CMGV04 is insufficient.	substructure repair required items QA - strength QA/QC rock QA/QC sand correct by oct 30	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3534, Item 7040102, Project Item Line Number 0770, Material Set 704010296, Material 1005CMGV04 - Masonry 0-3/8" Max Gravel, Acceptance Action Generic 1005CMGV04 is insufficient.	substructure repair required items QA - strength QA/QC rock	gummer1	Overridden

Revision 3/23/2023 Page 6 of 28



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
	QA/QC sand correct by oct 30		
Estimate Exception Type: Insufficient Materials: Project J6S3556, Item 7040102, Project Item Line Number 1370, Material Set 704010296, Material 1005CMGV04 - Masonry 0-3/8" Max Gravel, Acceptance Action Generic 1005CMGV04 is insufficient.	substructure repair required items QA - strength QA/QC rock QA/QC sand correct by oct 30	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3556, Item 7040102, Project Item Line Number 1370, Material Set 704010296, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	substructure repair required items QA - strength QA/QC rock QA/QC sand correct by oct 30	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3556, Item 7040102, Project Item Line Number 1370, Material Set 704010296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	substructure repair required items QA - strength QA/QC rock QA/QC sand correct by oct 30	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3534, Item 7040104, Project Item Line Number 0780, Material Set 704010496, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	deck repair Free Form cert by QA may need to change items to required mortar or concrete. nothing been reported	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3534, Item 7040113, Project Item Line Number 5004, Material Set 704011396, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	QA needs to enter free form cert required and not entered for Epoxy used. Need certification for epoxy.	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3534, Item 7163000, Project Item Line Number 0460, Material Set 716300096, Material 1038BBPD - Bridge Bearing Pad, Acceptance Action Generic 1038BBPD is insufficient.	type ptfe bearing pads requires certs Dpro item needed bridge anchor bolts / free form steel has been reported by bridge on steel	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3534, Item 7163000, Project Item Line Number 0460, Material Set 716300096, Material 1080BRSTBTSW - Bridge Material Swedge Anchor	type ptfe bearing pads requires certs Dpro item needed	gummer1	Overridden
Bolts, Acceptance Action Generic 1080BRSTBTSW is insufficient.	bridge anchor bolts / free form steel has been reported by bridge on steel		
Estimate Exception Type: Insufficient Materials: Project J6l3534, Item 7173002, Project Item Line Number 0470, Material Set 717300296, Material 1057JMJCSS - Silicon Sealant for Sawed/Formed Jnts @, Acceptance Action Generic 1057JMJCSS is insufficient.	joint sealant for exp joint 0.8 gallons needed 0870 - needed 0.29 gal which is all was reported from pal 0470 - needed 0.28 gal	gummer1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6l3534, Item 7173002, Project Item Line Number 0740, Material Set 717300296, Material 1057JMJCSS - Silicon Sealant for Sawed/Formed Jnts @, Acceptance Action Generic 1057JMJCSS is insufficient.	need 0.28 gallons of sealant under PAL	gummer1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6l3534, Item 7173002, Project Item Line Number 0870, Material Set 717300296, Material 1057JMJCSS - Silicon Sealant for Sawed/Formed Jnts @, Acceptance Action Generic 1057JMJCSS is insufficient.	need 0.28 gallons of sealant under pal	gummer1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3556, Item 7173002, Project Item Line Number 1470, Material Set 717300296, Material 1057JMJCSS - Silicon Sealant for Sawed/Formed Jnts @, Acceptance Action Generic 1057JMJCSS is insufficient.	need 0.2 gallons of sealant under PAL	gummer1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3556, Item 9039902, Project Item Line Number 1120, Material Set 9039902, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient.	correct check list doe cert which is not needed for covering signs	gummer1	Overridden

Revision 3/23/2023 Page 7 of 28



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
21021-F02	J6I3534	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$65,000.00	\$65,000.0
		0001	0020	2153000	SHAPING SLOPES, CLASS III	20.00	0.00	20.00	100F	20.00	\$1,428.00	\$28,560.0
		0001	0030	4138000	PCCP CRACK FILLING	4,400.00	0.00	4,400.00	LF	0.00	\$4.25	\$0.0
		0001	0040	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	60.00	0.00	60.00	LF	49.00	\$215.00	\$10,535.0
		0001	0050	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	254.00	0.00	254.00	CUYD	254.00	\$140.00	\$35,560.0
		0001	0060	6096042	PLACING TYPE 2 ROCK DITCH LINER	254.00	0.00	254.00	CUYD	254.00	\$210.00	\$53,340.0
		0001	0070	6116010A	SLOPE PROTECTION	160.00	0.00	160.00	SQYD	160.00	\$330.00	\$52,800.0
		0001	0080	6122008	IMPACT ATTENUATOR 40 MPH (SAND BARREL ARRAY)	1.00	0.00	1.00	EA	1.00	\$2,380.00	\$2,380.0
		0001	0090	6122020	REPLACEMENT SAND BARREL	1.00	0.00	1.00	EA	0.00	\$510.00	\$0.0
		0001	0100	6122030	IMPACT ATTENUATOR (RELOCATION)	1.00	0.00	1.00	EA	1.00	\$1,075.00	\$1,075.0
		0001	0110	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	EA	1.00	\$10,000.00	\$10,000.0
		0001	0120	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	2.00	4.00	EA	4.00	\$3,200.00	\$12,800.0
		0001	0130	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	1.00	\$30,189.30	\$30,189.3
		0001	0140	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	490.00	0.00	490.00	LF	490.00	\$32.80	\$16,072.0
		0001	0150	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	490.00	0.00	490.00	LF	490.00	\$12.85	\$6,296.5
		0001	0160	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$855,020.22	\$855,020.2
		0001	0170	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	441.00	0.00	441.00	LF	0.00	\$4.00	\$0.0
		0001	0180	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	763.00	0.00	763.00	LF	0.00	\$4.00	\$0.0
		0001	0190	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	12,561.00	0.00	12,561.00	LF	6,473.00	\$0.40	\$2,589.2
		0001	0200	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	9,803.00	0.00	9,803.00	LF	299.00	\$0.40	\$119.
		0001	0210	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	314.00	0.00	314.00	LF	299.00	\$2.00	\$598.0
		0001	0220	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	15,856.00	0.00	15,856.00	LF	0.00	\$1.50	\$0.0
		0001	0230	6214600A	FLOWABLE BACKFILL	15.00	0.00	15.00	CUYD	5.00	\$2,900.00	\$14,500.0
		0001	0240	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$12,000.00	\$12,000.
		0001	0250	7172054	OPEN CELL FOAM JOINT SEAL	266.00	0.00	266.00	LF	266.00	\$160.00	\$42,560.0
		0001	0260	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE, PROGRAMMING, AND ADJUSTMENT	1.00	0.00	1.00	LS	1.00	\$22,482.00	\$22,482.
		0001	0270	9039902	MISC.COVER EXISTING OVERHEAD SIGNS	26.00	0.00	26.00	EA	26.00	\$3,672.00	\$95,472.
		0010	0280	6061060	MGS GUARDRAIL	1,588.00	0.00	1,588.00	LF	1,588.00	\$28.56	\$45,353
		0010	0290	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	1.00	0.00	1.00	EA	1.00	\$4,284.00	\$4,284.
		0010	0300	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULARINO CURB)	6.00	0.00	6.00	EA	6.00	\$4,080.00	\$24,480.
		0010	0310	6061080	MGS END ANCHOR	3.00	0.00	3.00	EA	3.00	\$1,530.00	\$4,590.
		0010	0320	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	2.00	\$3,264.00	\$6,528.0
		0050	0330	9109903	MISC.MODOT ITS ASSETS RELOCATION	160.00	0.00	160.00	LF	0.00	\$25.00	\$0.
		0070	0340	2169902	MISC.REMOVAL OF EXISTING BEARINGS	30.00	0.00	30.00	EA	5.00	\$25,500.00	\$127,500.0
		0070	0350	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER/SEALER	6,386.00	0.00	6,386.00	SQYD	6,286.00	\$39.00	\$245,154.
		0070	0360	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	350.00	0.00	350.00	SQFT	281.00	\$605.00	\$170,005.
		0070	0370	7040104	HALF-SOLE REPAIR	250.00	0.00	250.00	SQFT	144.50	\$675.00	\$97,537.
		0070	0380	7040113	CLEANING AND EPOXY COATING	400.00	0.00	400.00	SQFT	0.00	\$6.00	\$0.0
		0070	0390	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$30,000.00	\$30,000.0
		0070	0400	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	60,100.00	0.00	60,100.00	SQFT	60,100.00	\$17.00	\$1,021,700.
			0410	7125201	SURFACE PREPARATION FOR OVERCOATING STRUCTURAL STEEL (SYSTEM G)	30,800.00	0.00	30,800.00	SQFT	30,800.00	\$9.50	\$292,600.
		0070	0420	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	60,100.00	0.00	60,100.00	SQFT	60,100.00	\$4.00	\$240,400.0
		0070	0430	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	90,900.00	0.00	90,900.00	SQFT	90,900.00	\$2.00	\$181,800.0

Page 8 of 28 Revision 3/23/2023



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted ame Description	Bid Quantity	Net Change	Total Current	Unit	Total Posted	Unit Price	Total Value POSTED To Date (See report
							Order	Quantity		Approved Qty		generated date)
221021-F02	J6I3534	0070	0440	7125370A	FINISH FIELD COAT (SYSTEM G)	22,900.00	0.00	22,900.00	SQFT	20,100.00	\$2.00	\$40,200.00
		0070	0450	7129902	MISC.EXPANSION DEVICE DRAINAGE TROUGH SYSTEM	3.00	0.00	3.00	EA	0.00		\$0.00
		0070	0460	7163000	TYPE N PTFE BEARING	30.00	0.00	30.00	EA	5.00	\$7,900.00	\$39,500.00
		0070	0470	7173002	SILICONE EXPANSION JOINT SEALANT	128.00	0.00	128.00	LF	128.00	\$130.00	\$16,640.00
		0071	0480	2169902	MISC.REMOVAL OF EXISTING BEARINGS	10.00	0.00	10.00	EA	0.00	\$36,000.00	\$0.00
		0071	0490	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER/SEALER	6,455.00	0.00	6,455.00	SQYD	6,455.00	\$38.98	\$251,615.90
		0071	0500	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	210.00	0.00	210.00	SQFT	210.00	\$520.00	\$109,200.00
		0071	0510	7040104	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	6.00	\$670.00	\$4,020.00
		0071	0520	7040113	CLEANING AND EPOXY COATING	4,400.00	0.00	4,400.00	SQFT	4,400.00	\$6.00	\$26,400.00
		0071	0530	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$30,000.00	\$0.00
		0071	0540	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	37,800.00	0.00	37,800.00	SQFT	37,800.00	\$17.00	\$642,600.00
		0071	0550	7125201	SURFACE PREPARATION FOR OVERCOATING STRUCTURAL STEEL (SYSTEM G)	41,100.00	0.00	41,100.00	SQFT	41,100.00	\$9.50	\$390,450.00
		0071	0560	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	37,800.00	0.00	37,800.00	SQFT	37,800.00	\$4.00	\$151,200.00
		0071	0570	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	78,900.00	0.00	78,900.00	SQFT	78,900.00	\$2.00	\$157,800.00
		0071	0580	7125370A	FINISH FIELD COAT (SYSTEM G)	19,400.00	0.00	19,400.00	SQFT	19,400.00	\$2.00	\$38,800.00
		0071	0590	7129902	MISC.EXPANSION DEVICE DRAINAGE TROUGH SYSTEM	2.00	0.00	2.00	EA	0.00	\$245,000.00	\$0.00
		0071	0600	7163000	TYPE N PTFE BEARING	10.00	0.00	10.00	EA	0.00	\$8,000.00	\$0.00
		0071	0610	7173002	SILICONE EXPANSION JOINT SEALANT	128.00	0.00	128.00	LF	0.00	\$160.00	\$0.00
		0072	0620	2169902	MISC.REMOVAL OF EXISTING BEARINGS	5.00	-1.00	4.00	EA	0.00	\$28,000.00	\$0.00
		0072	0630	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER/SEALER	5,130.00	0.00	5,130.00	SQYD	5,001.00	\$39.27	\$196,389.27
		0072	0640	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	140.00	0.00	140.00	SQFT	86.00	\$575.00	\$49,450.00
		0072	0650	7040104	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	15.00	\$650.00	\$9,750.00
		0072	0660	7040113	CLEANING AND EPOXY COATING	400.00	0.00	400.00	SQFT	400.00	\$6.00	\$2,400.00
		0072	0670	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.97	\$36,000.00	\$34,920.00
		0072	0680	7125201	SURFACE PREPARATION FOR OVERCOATING STRUCTURAL STEEL (SYSTEM G)	88,600.00	0.00	88,600.00	SQFT	88,600.00	\$9.50	\$841,700.00
		0072	0690	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	88,600.00	0.00	88,600.00	SQFT	88,600.00	\$2.00	\$177,200.00
		0072	0700	7125370A	FINISH FIELD COAT (SYSTEM G)	41,300.00	0.00	41,300.00	SQFT	41,300.00	\$2.00	\$82,600.00
		0072	0710	7129901	MISC.CLEAN AND FLUSH EXISTING DRAINAGE SYSTEM	1.00	0.00	1.00	LS	1.00	\$76,000.00	\$76,000.00
		0072	0720	7163000	TYPE N PTFE BEARING	5.00	-1.00	4.00	EA	0.00	\$9,800.00	\$0.00
		0072	0730	7172054	OPEN CELL FOAM JOINT SEAL	54.00	0.00	54.00	LF	54.00	\$215.00	\$11,610.00
		0072	0740	7173002	SILICONE EXPANSION JOINT SEALANT	44.00	0.00	44.00	LF	44.00	\$170.00	\$7,480.00
		0073	0750	2169903	MISC.REMOVE AND REPLACE BARRIER	10.00	0.00	10.00	LF	10.00	\$5,500.00	\$55,000.00
		0073	0760	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER/SEALER	5,322.00	0.00	5,322.00	SQYD	5,222.00	\$38.99	\$203,605.78
		0073	0770	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	75.00	0.00	75.00	SQFT	75.00	\$840.00	\$63,000.00
		0073	0780	7040104	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	20.00	\$720.00	\$14,400.00
		0073	0790	7040113	CLEANING AND EPOXY COATING	400.00	0.00	400.00	SQFT	400.00	\$6.00	\$2,400.00
		0073	0800	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.44	\$42,000.00	\$18,480.00
		0073	0810	7125201	SURFACE PREPARATION FOR OVERCOATING STRUCTURAL STEEL (SYSTEM G)	97,600.00	0.00	97,600.00	SQFT	97,600.00	\$9.50	\$927,200.00
		0073	0820	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	97,600.00	0.00	97,600.00	SQFT	97,600.00	\$2.00	\$195,200.00
		0073	0830	7125370A	FINISH FIELD COAT (SYSTEM G)	44,000.00	0.00	44,000.00	SQFT	44,000.00	\$2.00	\$88,000.00
		0073	0840	7129901	MISC.CLEAN AND FLUSH EXISTING DRAINAGE SYSTEM	1.00	0.00	1.00	LS	1.00	\$76,000.00	\$76,000.00
		0073	0850	7129902	MISC.REPLACE SEISMIC ANCHOR ROD	1.00	0.00	1.00	EA	0.00	\$17,000.00	\$0.00
		0073	0860	7172054	OPEN CELL FOAM JOINT SEAL	54.00	0.00	54.00	LF	54.00	\$250.00	\$13,500.00
		0073	0870	7173002	SILICONE EXPANSION JOINT SEALANT	44.00	0.00	44.00	LF	44.00	\$210.00	\$9,240.00

Page 9 of 28 Revision 3/23/2023



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Va	alues are based on Repo	rt Generated date an	and can differ from the posted amount at the time the Estimate was Generated.

vote: Posted Q	uantities	and valu	es are c	ased on R	eport Generated date and can differ from the posted amo	ount at the	time the Es	sumate was	Genera	tea.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
221021-F02	J6I3534	0074	0880	7040163	CONCRETE CRACK FILLER	11,800.00	0.00	11,800.00	SQYD	11,800.00	\$15.50	\$182,900.00
		0075	0890	7040163	CONCRETE CRACK FILLER	10,200.00	0.00	10,200.00	SQYD	10,200.00	\$15.50	\$158,100.00
		0070	5001	7169901	MISC.FURNISH TYPE N PTFE BEARINGS AND ANCHOR BOLTS	0.00	1.00	1.00	LS	1.00	\$81,683.18	\$81,683.18
		0071	5002	7169901	(STRUCTURE A48811) MISC.FURNISH TYPE N PTFE BEARINGS AND ANCHOR BOLTS (STRUCTURE A48821)	0.00	1.00	1.00	LS	1.00	\$27,935.73	\$27,935.73
		0072	5003	7169901	MISC.FURNISH TYPE N PTFE BEARINGS AND ANCHOR BOLTS (STRUCTURE A54111)	0.00	1.00	1.00	LS	1.00	\$14,054.29	\$14,054.29
		0070	5004	7040113	CLEANING AND EPOXY COATING	0.00	414.00	414.00	SQFT	414.00	\$9.89	\$4,094.46
		0072	5005	1094000A	FORCE ACCOUNT	0.00	23,745.46	23,745.46	EA	23,745.00	\$1.00	\$23,745.00
		0070	5006	2169902	MISC.REMOVAL OF EXISTING BEARING ASSEMBLY (Bridge A48811)	0.00	30.00	30.00	EA	5.00	\$2,212.84	\$11,064.20
		0070	5007	7169902	MISC.INSTALL TYPE N PTFE BEARING ASSEMBLY (Bridge A48811)	0.00	30.00	30.00	EA	5.00	\$2,676.35	\$13,381.75
		0071	5008	2169902	MISC.REMOVAL OF EXISTING BEARING ASSEMBLY (Bridge A48821)	0.00	10.00	10.00	EA	0.00	\$2,212.84	\$0.00
		0071	5009	7169902	MISC.INSTALL TYPE N PTFE BEARING ASSEMBLY (Bridge A48821)	0.00	10.00	10.00	EA	0.00	\$2,676.35	\$0.00
		0072	5010	2169902	MISC.REMOVAL OF EXISTING BEARING ASSEMBLY (Bridge A54111)	0.00	4.00	4.00	EA	0.00	\$2,212.84	\$0.00
		0072	5011	7169902	MISC.INSTALL TYPE N PTFE BEARING ASSEMBLY (Bridge A54111)	0.00	4.00	4.00	EA	0.00	\$2,676.35	\$0.00
		0070	5012	1094000	FORCE ACCOUNT	0.00	140,650.40	140,650.40	EA	5,400.00	\$1.00	\$5,400.00
	Project J	6l3534 - To	tal Value	Posted to Da	ate as of Report Generated Date							\$9,408,190.16
	J6S3556	0001	0900	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.80	\$27,500.00	\$22,000.00
		0001	0910	2153000	SHAPING SLOPES, CLASS III	44.00	0.00	44.00	100F	22.00	\$1,224.00	\$26,928.00
		0001	0920	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	27.00	0.00	27.00	SQYD	27.00	\$260.00	\$7,020.00
		0001	0930	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	303.10	0.00	303.10	TONS	0.00	\$150.02	\$0.00
		0001	0940	4071005	TACK COAT	16.00	0.00	16.00	GAL	0.00	\$10.00	\$0.00
		0001	0950	6086004	CONCRETE SIDEWALK, 4 IN.	26.60	0.00	26.60	SQYD	26.60	\$910.00	\$24,206.00
		0001	0960	6116010A	SLOPE PROTECTION	50.00	0.00	50.00	SQYD	42.00	\$680.00	\$28,560.00
		0001	0970	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	EA	1.00	\$10,000.00	\$10,000.00
		0001	0980	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$3,200.00	\$12,800.00
		0001	0990	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.75	\$26,595.00	\$19,946.25
		0001	1000	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$446,700.00	\$446,700.00
		0001	1010	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	3,363.00	0.00	3,363.00	LF	0.00	\$3.00	\$0.00
		0001	1020	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	3,060.00	0.00	3,060.00	LF	0.00	\$3.00	\$0.00
		0001	1030	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,764.00	0.00	2,764.00	LF	0.00	\$1.00	\$0.00
		0001	1040	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,189.00	0.00	4,189.00	LF	2,461.00	\$1.00	\$2,461.00
		0001	1050	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	779.00	0.00	779.00	LF	779.00	\$1.00	\$779.00
		0001	1060	6214600A	FLOWABLE BACKFILL	5.00	0.00	5.00	CUYD	5.00	\$5,000.00	\$25,000.00
		0001	1070	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	156.00	0.00	156.00	SQYD	0.00	\$14.00	\$0.00
		0001	1080	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	10,000.00	0.00	10,000.00	LB	1,062.00	\$6.00	\$6,372.00
		0001	1090	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$127,000.00	\$127,000.00
		0001	1100	7172054	OPEN CELL FOAM JOINT SEAL	50.00	0.00	50.00	LF	50.00	\$400.00	\$20,000.00
		0001	1110	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE, PROGRAMMING, AND ADJUSTMENT	1.00	0.00	1.00	LS	0.75	\$10,000.00	\$7,500.00
		0001	1120	9039902	MISC.COVER EXISTING OVERHEAD SIGNS	1.00	0.00	1.00	EA	1.00	\$3,672.00	\$3,672.00
		0010	1130	6061060	MGS GUARDRAIL	3,400.00	0.00	3,400.00	LF	3,400.00	\$28.56	\$97,104.00
		0010	1140	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	100.00	0.00	100.00	LF	100.00	\$36.72	\$3,672.00
		0010	1150	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	3.00	0.00	3.00	EA	3.00	\$4,284.00	\$12,852.00
		0010	1160	6061069	MGS BRIDGE APPROACH TRANSITION SECTION	10.00	0.00	10.00	EA	10.00	\$4,080.00	\$40,800.00
		00.10			(REGULAR/NO CURB)							

Revision 3/23/2023 Page 10 of 28



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are	e based on Report G	enerated date and can differ	from the posted amount at the tin	ne the Estimate was Generated

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See report generated date)
1021-F02	J6S3556	0010	1180	6061080	MGS END ANCHOR	9.00	0.00	9.00	EA	9.00	\$1,530.00	\$13,770.0
		0010	1190	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	10.00	0.00	10.00	EA	10.00	\$3,264.00	\$32,640.0
		0050	1200	9109903	MISC.MODOT ITS ASSETS RELOCATION	378.00	0.00	378.00	LF	0.00	\$22.00	\$0.0
		0070	1210	7125201	SURFACE PREPARATION FOR OVERCOATING STRUCTURAL	22,600.00	0.00	22,600.00	SQFT	22,600.00	\$9.50	\$214,700.0
		0070	1220	7125365A	STEEL (SYSTEM G) INTERMEDIATE FIELD COAT (SYSTEM G)	22,600.00	0.00	22,600.00	SQFT	22,600.00	\$2.00	\$45,200.
		0070	1230	7125370A	FINISH FIELD COAT (SYSTEM G)	7,000.00	0.00	7,000.00	SQFT	6,800.00	\$2.00	\$13,600.
		0071	1240	7040163	CONCRETE CRACK FILLER	5,855.00	0.00	5,855.00	SQYD	5,855.00	\$15.50	\$90,752.
		0071	1250	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	1.00	\$40,000.00	\$40,000.
		0072	1260	6239905	(EPOXY) MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH	1,366.00	0.00	1,366.00	SQYD	600.00	\$46.81	\$28,086.
		0072	1270	7040102	HEALER/SEALER SUBSTRUCTURE REPAIR (UNFORMED)	20.00	0.00	20.00	SQFT	0.00	\$1,000.00	\$0.
		0072	1280	7040163	CONCRETE CRACK FILLER	240.00	0.00	240.00	SQYD	100.00	\$25.00	\$2,500.
		0072	1290	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	1.00	\$40,000.00	\$40,000.
		0072	1300	7125201	(EPOXY) SURFACE PREPARATION FOR OVERCOATING STRUCTURAL	19,800.00	0.00	19,800.00	SQFT	19,800.00	\$9.50	\$188,100.
				7125365A	STEEL (SYSTEM G)			19,800.00	SQFT	19,800.00		
		0072	1310	7125305A	INTERMEDIATE FIELD COAT (SYSTEM G) FINISH FIELD COAT (SYSTEM G)	19,800.00 4,400.00	0.00	4,400.00	SQFT	4,200.00	\$2.00 \$2.00	\$39,600. \$8,400.
		0072	1330	7129902	MISC.CLEAN AND FLUSH EXISTING EXPANSION GAP	1.00	0.00	1.00	EA	0.00	\$5,100.00	\$0,400.
		0072	1340	7173002	SILICONE EXPANSION JOINT SEALANT	59.00	0.00	59.00	LF	0.00	\$210.00	\$0.
		0072	1350	2161502	REMOVAL OF CONCRETE WEARING SURFACE	10,244.00	0.00	10,244.00	SQFT	10,244.00	\$1.50	\$15,366.
		0073	1360	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH	1,545.00	0.00	1,545.00	SQYD	1,511.70	\$43.51	\$65,774.
					HEALER/SEALER							
		0073	1370	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	107.00	0.00	107.00	SQFT	95.00	\$1,075.00	\$102,125
		0073	1380	7040113 7040163	CLEANING AND EPOXY COATING CONCRETE CRACK FILLER	120.00	0.00	120.00	SQFT	120.00	\$6.00 \$25.00	\$720
		0073	1400	7049163	MISC.BARRIER CURB REPAIR	187.00	0.00	150.00	LF	28.00	\$470.00	\$4,675
		0073	1410	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	150.00	0.00	1.00	LF	1.00	\$12,000.00	\$13,160 \$12,000
		0073			(EPOXY)							
		0073	1420	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	12,500.00	0.00	12,500.00	SQFT	12,500.00	\$17.00	\$212,500
		0073	1430	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	12,500.00	0.00	12,500.00	SQFT	12,500.00	\$4.00	\$50,000
		0073	1440	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	12,500.00	0.00	12,500.00	SQFT	12,500.00	\$2.00	\$25,000
		0073	1450	7125370A	FINISH FIELD COAT (SYSTEM G)	3,500.00	0.00	3,500.00	SQFT	3,500.00	\$2.00	\$7,000.
		0073	1460	7129902	MISC.CLEAN AND FLUSH EXISTING EXPANSION GAP	1.00	0.00	1.00	EA	1.00	\$5,100.00	\$5,100.
		0073	1470	7173002	SILICONE EXPANSION JOINT SEALANT	16.00	0.00	16.00	LF	16.00	\$310.00	\$4,960
		0074	1480	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER/SEALER	1,945.00	0.00	1,945.00	SQYD	1,845.00	\$38.23	\$70,534.
		0074	1490	7040113	CLEANING AND EPOXY COATING	300.00	0.00	300.00	SQFT	300.00	\$6.00	\$1,800
		0074	1500	7040163	CONCRETE CRACK FILLER	216.00	0.00	216.00	SQYD	216.00	\$25.00	\$5,400
		0074	1510	7049903	MISC.BARRIER CURB REPAIR	20.00	0.00	20.00	LF	20.00	\$1,110.00	\$22,200
		0074	1520	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$12,000.00	\$12,000
		0074	1530	7125201	SURFACE PREPARATION FOR OVERCOATING STRUCTURAL STEEL (SYSTEM G)	16,500.00	0.00	16,500.00	SQFT	16,500.00	\$9.50	\$156,750
	0074 1540 7125365A INTERMEDIATE FIELD COAT (SYSTEM G)						0.00	16,500.00	SQFT	16,500.00	\$2.00	\$33,000
	0074 1550 7125370A FINISH FIELD COAT (SYSTEM G)						0.00	3,800.00	SQFT	3,800.00	\$2.00	\$7,600
	0001 5101 1094000 FORCE ACCOUNT						30,000.00	30,000.00	EA	5,000.00	\$1.00	\$5,000
					late as of Report Generated Date							\$2,538,649

Revision 3/23/2023 Page 11 of 28



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6l3534

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	10/13/23	10/17/23	0.10	LS	bent1 at bridge A 4881 and bent 17 at bridge A5408	26.63.62		31.81.49		
0060	6096042	PLACING TYPE 2 ROCK DITCH LINER	10/13/23	10/17/23	163.00	CUYD	At the exit ramp from 270 NB to 44WB	25.62.97		31.81.49		
0130	6169901	MISC.	10/13/23	10/17/23	0.25	LS	270 and 55 area	25.62.97		31.81.49		
0250	7172054	OPEN CELL FOAM JOINT SEAL	10/13/23	10/17/23	154.00	LF	Craigwold Rd overpass					
0340	2169902	MISC. REMOVALS	10/13/23	10/17/23	3.00	EA	Bridge A4881 all 3 removed 10/12/23	26.63.62		31.40.92		
0360	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	10/13/23	10/17/23	18.00	SQFT	Bridge A8841 bent 11 6 sqft and bent 12 -12 sqft placed on 6-2-23					
0460	7163000	TYPE N PTFE BEARING	10/13/23	10/17/23	4.00	EA	Bridge A4881 bent 6 replaced on 10/13/23	25.62.97		31.40.92		
0470	7173002	SILICONE EXPANSION JOINT SEALANT	10/13/23	10/17/23	128.00	LF	Bridge A4881 installed on 10/12/23 nights both ends of bridge	26.63.62		31.40.92		
0640	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	10/13/23	10/17/23	-21.00	SQFT	Bridge A5411 deduct for miscalculation	25.62.97		31.40.92		
5006	2169902	MISC. REMOVALS	10/13/23	10/17/23	5.00	EA	Bridge A4881 bent 7 work completed 10/13/23	25.62.97		31.40.92		
5007	7169902	MISC.	10/13/23	10/17/23	5.00	EA	Bridge A4881 bent 7 work completed 10/13/23	25.62.97		31.40.92		
5012	1094000	FORCE ACCOUNT	10/13/23	10/17/23	5,400.00	EA	Bridge A4881 bents 6 and 7	25.62.97		31.40.92		

Project: J6S3556

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0990	6169901	MISC.	10/13/23	10/17/23	0.25	LS	270 and 44 area	26.63.62		31.81.49		
1080	6252003	SLAB JACKING MATL HIGH DENSITY POLYURETH	10/13/23	10/17/23	1,062.00	LB	Bridge A54101 north approach slab					
1090	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	10/13/23	10/17/23	0.10	LS	270 and 44 area					
1100	7172054	OPEN CELL FOAM JOINT SEAL	10/13/23	10/17/23	50.00	LF	Bridge A54101 north end approach joint work completed 10/13/23	26.63.62		31.81.49		
1110	9029901	MISC.	10/13/23	10/17/23	0.25	LS	270 and 44 area					
1120	9039902	MISC.	10/13/23	10/17/23	1.00	EA	270 and 44 area					
1130	6061060	MGS GUARDRAIL	10/13/23	10/17/23	3,050.00	LF	Bridges A 5408, A54101 A4909					
1140	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	10/13/23	10/17/23	100.00	LF	Bridges A49091, A5408, A5410					
1150	6061068	MGS BRIDGE APP. TRANS SEC (EXT CURB)	10/13/23	10/17/23	3.00	EA	Bridges A49091, A5408, A5410					
1160	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	10/13/23	10/17/23	7.00	EA	Bridges A49091, A5408, A5410					
1170	6061074	MGS HEIGHT AND BLOCK TRANSITION	10/13/23	10/17/23	4.00	EA	Bridges A49091, A5408, A5410					
1180	6061080	MGS END ANCHOR	10/13/23	10/17/23	8.00	EA	Bridges A49091, A5408, A5410					
1190	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	10/13/23	10/17/23	8.00	EA	Bridges A49091, A5408, A5410					
1260	6239905	MISC.	10/13/23	10/17/23	600.00	SQYD	Bridge A4909					
1280	7040163	CONCRETE CRACK FILLER	10/13/23	10/17/23	100.00	SQYD	Bridge A4909					
1370	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	10/13/23	10/17/23	81.00	SQFT	Bridge A5408					
1480	6239905	MISC.	10/13/23	10/17/23	1,845.00	SQYD	Bridge A5410					
				10/17/23		SQYD	Bridge A5410 Geyer rd completed 10/12/23	1845				
1500	7040163	CONCRETE CRACK FILLER	10/13/23	10/17/23	216.00	SQYD	Bridge A5410 Geyer rd completed 10/12/23					

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023 Page 12 of 28



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J6I3534	0020	SHAPING SLOPES, CLASS III	Material		6	May 2, 2023	SYSTEM	\$23,747.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stgemr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					6	May 2, 2023	SYSTEM	(\$23,747.64)						
				- Total				\$0.00						
			Material - Tota					\$0.00						
	0020 -	Total						\$0.00						
	0040	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		12	Aug 2, 2023	SYSTEM	\$6,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user pansag1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					12	Aug 2, 2023	SYSTEM	(\$6,880.00)						
					13	Aug 17, 2023	SYSTEM	\$6,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					13	Aug 17, 2023	SYSTEM	(\$6,880.00)						
					14	Sep 5, 2023	SYSTEM	\$6,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user pansag1 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					14	Sep 5, 2023	SYSTEM	(\$6,880.00)						
					15	Sep 18, 2023	SYSTEM	\$10,535.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user pansag1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					15	Sep 17, 2023	SYSTEM	(\$10,535.00)						
					16	Oct 2, 2023	SYSTEM	\$10,535.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user pansag1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
										16	Oct 2, 2023	SYSTEM	(\$10,535.00)	
					17	Oct 17, 2023	SYSTEM	\$10,535.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					17	Oct 17, 2023	SYSTEM	(\$10,535.00)						
				- Total				\$0.00						
			Material - Tota	<u> </u>				\$0.00						
	0040 -	Total						\$0.00						
	0050	FURN. TYPE 2 ROCK DITCH LINER	Material		15	Sep 18, 2023	SYSTEM	\$2,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user pansag1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					15	Sep 17, 2023	SYSTEM	(\$2,520.00)						
				- Total				\$0.00						
			Material - Tota					\$0.00						
	0050 - 0070	SLOPE PROTECTION	Material		16	Oct 2, 2023	SYSTEM	\$0.00 \$52,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user pansag1 overridding Payment					
					16	Oct 2, 2023	SYSTEM	(\$52,800.00)	Estimate Exception 3 on the current Payment Estimate.					
					17	Oct 17, 2023	SYSTEM	\$52,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user gummer1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					17	Oct 17, 2023	SYSTEM	(\$52,800.00)						
				- Total				\$0.00						
			Material - Tota					\$0.00						
	0070 -	Total						\$0.00						
	0110	TRUCK OR TRAILER MOUNTED ATTEN	Material		2	Mar 2, 2023	SYSTEM	\$10,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user krausm2 overridding Payment Estimate Exception 1 on the current Payment Estimate.					



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks						
			Type	Adjustment Type	Number	Date	Ву								
J6I3534	0110	(TMA)	Material		2	Mar 2, 2023	SYSTEM	(\$10,000.00)							
				- Total				\$0.00							
			Material - Tota					\$0.00							
	0110 -	Total						\$0.00							
	0120	CMS WITH COMMUNICATION INTERFACE,	Material		2	Mar 2, 2023	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user krausm2 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
		CONT F			2	Mar 2, 2023	SYSTEM	(\$9,600.00)							
				- Total				\$0.00							
			Material - Tota	ı				\$0.00							
			Overrun	Overrun	2	Mar 2, 2023	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user krausm2 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
					2	Mar 2, 2023	SYSTEM	(\$3,200.00)							
					3	Mar 17, 2023	SYSTEM	(\$3,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
					4	Apr 3, 2023	SYSTEM	\$3,200.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3200.00000 - 3200.00000, 'is applied (if non-zero).						
				Overrun - To	otal			\$0.00							
			Overrun - Tota					\$0.00							
	0120 -	Total						\$0.00							
	0140	TEMPORARY TRAFFIC	Material		8	Jun 2, 2023	SYSTEM	(\$13,120.00)							
				- Total				(\$13,120.00)							
			TORIVIL	FURIN/RE	FURN/RE	FURN/RE	FURN/RE	FURN/RE	T OTTIVITE	Material - Tota					(\$13,120.00)
			MaterialCredit		9	Jun 16, 2023	SYSTEM	\$13,120.00							
				- Total				\$13,120.00							
			MaterialCredit	Total				\$13,120.00							
	0140 -	Total													
	0190	6 IN. WHITE HIGH BUILD WATERBORNE	Material		15	Sep 18, 2023	SYSTEM	\$2,589.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user pansag1 overridding Payment Estimate Exception 4 on the current Payment Estimate.						
		PAINT			15	Sep 17, 2023	SYSTEM	(\$2,589.20)							
				- Total				\$0.00							
			Material - Tota					\$0.00							
	0190 -	Total						\$0.00							
	0200	6 IN. YELLOW HIGH BUILD WATERBORNE	Material		15	Sep 18, 2023	SYSTEM	\$119.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user pansag1 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
		PAINT			15	Sep 17, 2023	SYSTEM	(\$119.60)							
				- Total				\$0.00							
			Material - Tota					\$0.00							
	0200 -	Total						\$0.00							
	0210	12 IN. WHITE HIGH BUILD WATERBORNE PAINT	Material		15	Sep 18, 2023	SYSTEM	\$598.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user pansag1 overridding Payment Estimate Exception 12 on the current Payment Estimate.						
		FAINI			15	Sep 17, 2023	SYSTEM	(\$598.00)							
				- Total				\$0.00							
			Material - Tota					\$0.00							
	0210 -	Total						\$0.00							
	0230	FLOWABLE BACKFILL	Material		16	Oct 2, 2023	SYSTEM	\$14,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user pansag1 overridding Payment Estimate Exception 7 on the current Payment Estimate.						



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
534	0230	FLOWABLE BACKFILL	Material		16	Oct 2, 2023	SYSTEM	(\$14,500.00)											
					17	Oct 17, 2023	SYSTEM	\$14,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user gummer1 overridding Payment Estimate Exception 7 on the current Payment Estimate.										
					17	Oct 17, 2023	SYSTEM	(\$14,500.00)											
				- Total				\$0.00											
			Material - Tota	ı				\$0.00											
	0230 -	Total						\$0.00											
	0250	OPEN CELL FOAM JOINT SEAL	Material		12	Aug 2, 2023	SYSTEM	\$8,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user pansag1 overridding Payment Estimate Exception 24 on the current Payment Estimate.										
					12	Aug 2, 2023	SYSTEM	(\$8,640.00)											
					13	Aug 17, 2023	SYSTEM	\$8,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 15 on the current Payment Estimate.										
					13	Aug 17, 2023	SYSTEM	(\$8,640.00)											
				- Total				\$0.00											
			Material - Tota	ıl				\$0.00											
	0250 -	Total						\$0.00											
	0260	MISC.	Material		10	Jul 5, 2023	SYSTEM	\$5,620.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user krausm2 overridding Payment Estimate Exception 14 on the current Payment Estimate.										
					10	Jul 5, 2023	SYSTEM	(\$5,620.50)											
															11	Jul 17, 2023	SYSTEM	\$5,620.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user pansag1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
																	11	Jul 17, 2023	SYSTEM
					12	Aug 2, 2023	SYSTEM	\$11,241.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user pansag1 overridding Payment Estimate Exception 27 on the current Payment Estimate.										
					12	Aug 2, 2023	SYSTEM	(\$11,241.00)											
				- Total				\$0.00											
			Material - Tota	ıl				\$0.00											
J	0260 -	Total						\$0.00											
	0270	MISC.	Material		10	Jul 5, 2023	SYSTEM	\$47,736.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user krausm2 overridding Payment Estimate Exception 15 on the current Payment Estimate.										
					10	Jul 5, 2023	SYSTEM	(\$47,736.00)											
					11	Jul 17, 2023	SYSTEM	\$47,736.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user pansag1 overridding Payment Estimate Exception 21 on the current Payment Estimate.										
					11	Jul 17, 2023	SYSTEM	(\$47,736.00)											
					12	Aug 2, 2023	SYSTEM	\$66,096.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user pansag1 overridding Payment Estimate Exception 29 on the current Payment Estimate.										
					12	Aug 2, 2023	SYSTEM	(\$66,096.00)											
				- Total				\$0.00											
			Material - Tota	ıl				\$0.00											
	0270 -	Total						\$0.00											
	0280	MGS GUARDRAIL	Construction Stockpile		6	May 2, 2023	SYSTEM	(\$20,710.80)	Payment Estimate Item Adjustment generated Stockpile Transaction										
					14	Sep 5, 2023	SYSTEM	(\$4,204.92)	Payment Estimate Item Adjustment generated Stockpile Transaction										
				- Total				(\$24,915.72)											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3534	0280	MGS GUARDRAIL	Construction	Stockpile - To	otal			(\$24,915.72)	
			Construction Stockpile STMI		3	Mar 17, 2023	SYSTEM	\$24,915.72	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$24,915.72	
			Construction	Stockpile STI	MI - Total			\$24,915.72	
	0280 -	Total						\$0.00	
	0290	MGS BRIDGE APP. TRANS SEC (EXT CURB)	Construction Stockpile		14	Sep 5, 2023	SYSTEM	(\$2,265.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(271. 00.12)		- Total				(\$2,265.00)	
			Construction	Stockpile - To	otal			(\$2,265.00)	
			Construction Stockpile STMI		3	Mar 17, 2023	SYSTEM	\$2,265.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$2,265.00	
			Construction	Stockpile STI	VII - Total			\$2,265.00	
	0290 - 0300	MGS BRIDGE	Construction		6	May 2,	SYSTEM	\$0.00 (\$13,590.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		APP. TRANS SEC (REG/NO CURB)	Stockpile			2023		(0.40, 500, 00)	
		•		- Total				(\$13,590.00)	
			Construction	Stockpile - To				(\$13,590.00)	
			Construction Stockpile STMI		3	Mar 17, 2023	SYSTEM	\$13,590.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$13,590.00	
			Construction	Stockpile STI	MI - Total			\$13,590.00	
			Overrun	Overrun	6	May 2, 2023	SYSTEM	(\$4,080.00)	
					14	Sep 5, 2023	SYSTEM	\$4,080.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',4080.00000 - 4080.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0300 -	Total						\$0.00	
	0310	MGS END ANCHOR	Construction Stockpile		6	May 2, 2023	SYSTEM	(\$2,505.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$2,505.00)	
			Construction	Stockpile - To				(\$2,505.00)	
			Construction Stockpile STMI		3	Mar 17, 2023	SYSTEM	\$2,505.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$2,505.00	
			Construction	Stockpile STI	VII - Total			\$2,505.00	
	0310 -							\$0.00	
	0320	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		6	May 2, 2023	SYSTEM	(\$3,750.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)		- Total				(\$3,750.00)	
			Construction	Stockpile - To				(\$3,750.00)	
			Construction Stockpile STMI		3	Mar 17, 2023	SYSTEM	\$3,750.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$3,750.00	
			Construction	Stockpile STI				\$3,750.00	
			Material		6	May 2, 2023	SYSTEM	(\$6,528.00)	
					7	May 16, 2023	SYSTEM	(\$6,528.00)	
					8	Jun 2, 2023	SYSTEM	(\$6,528.00)	
					9	Jun 16, 2023	SYSTEM	(\$6,528.00)	
					10	Jul 5, 2023	SYSTEM	\$6,528.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user krausm2 overridding Payment Estimate Exception 2 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J6I3534	0320	TYPE A CRASHWORTHY	Material		10	Jul 5, 2023	SYSTEM	(\$6,528.00)						
		END TERMINAL (MASH)			11	Jul 17, 2023	SYSTEM	\$6,528.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user pansag1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					11	Jul 17, 2023	SYSTEM	(\$6,528.00)						
					12	Aug 2, 2023	SYSTEM	\$6,528.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user pansag 1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					12	Aug 2, 2023	SYSTEM	(\$6,528.00)						
				- Total				(\$26,112.00)						
			Material - Tota					(\$26,112.00)						
			MaterialCredit		7	May 16, 2023	SYSTEM	\$6,528.00						
					8	Jun 2, 2023	SYSTEM	\$6,528.00						
					9	Jun 16, 2023	SYSTEM	\$6,528.00						
					10	Jul 5, 2023	SYSTEM	\$6,528.00						
				- Total				\$26,112.00						
		- Total	MaterialCredit	- Total				\$26,112.00						
	0320 -							\$0.00						
	0350	MISC.	c. Material		10	Jul 5, 2023	SYSTEM	\$134,862.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user krausm2 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
										10	Jul 5, 2023	SYSTEM	(\$134,862.00)	
					11	Jul 17, 2023	SYSTEM	\$245,154.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user pansag1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
										11	Jul 17, 2023	SYSTEM	(\$245,154.00)	
					12	Aug 2, 2023	SYSTEM	\$245,154.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user pansag1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
					12	Aug 2, 2023	SYSTEM	(\$245,154.00)						
				- Total				\$0.00						
			Material - Tota	ıl				\$0.00						
	0350 -	Total						\$0.00						
	0360	SUBSTRUCTURE REPAIR (UNFORMED)	Material		8	Jun 2, 2023	SYSTEM	\$2,722.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user krausm2 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					8	8	8	Jun 2, 2023	SYSTEM	(\$2,722.50)				
					10	Jul 5, 2023	SYSTEM	\$15,427.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user krausm2 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					10	10	Jul 5, 2023	SYSTEM	(\$15,427.50)					
					11	Jul 17, 2023	SYSTEM	\$22,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user pansag1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
					11	Jul 17, 2023	SYSTEM	(\$22,687.50)						
					12	Aug 2, 2023	SYSTEM	\$39,022.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user pansag1 overridding Payment Estimate Exception 7 on the current Payment Estimate.					
					12	Aug 2, 2023	SYSTEM	(\$39,022.50)						
					13	Aug 17, 2023	SYSTEM	\$102,547.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user gummer1 overridding Payment					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3534	0360	SUBSTRUCTURE	Material						Estimate Exception 3 on the current Payment Estimate.
		REPAIR (UNFORMED)			13	Aug 17, 2023	SYSTEM	(\$102,547.50)	
					14	Sep 5, 2023	SYSTEM	\$140,965.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user pansag1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Sep 5, 2023	SYSTEM	(\$140,965.00)	
					15	Sep 18, 2023	SYSTEM	\$159,115.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user pansag1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					15	Sep 17, 2023	SYSTEM	(\$159,115.00)	
					16	Oct 2, 2023	SYSTEM	\$159,115.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user pansag1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					16	Oct 2, 2023	SYSTEM	(\$159,115.00)	
					17	Oct 17, 2023	SYSTEM	\$170,005.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user gummer1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					17	Oct 17, 2023	SYSTEM	(\$170,005.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0360 -	Total						\$0.00	
	0370	HALF-SOLE REPAIR	Material		8	Jun 2, 2023	SYSTEM	\$97,537.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user krausm2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Jun 2, 2023	SYSTEM	(\$97,537.50)	
					9	Jun 16, 2023	SYSTEM	(\$97,537.50)	
					10	Jul 5, 2023	SYSTEM	\$97,537.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user krausm2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					10	Jul 5, 2023	SYSTEM	(\$97,537.50)	
					11	Jul 17, 2023	SYSTEM	\$97,537.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user pansag1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					11	Jul 17, 2023	SYSTEM	(\$97,537.50)	
					12	Aug 2, 2023	SYSTEM	\$97,537.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user pansag1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					12	Aug 2, 2023	SYSTEM	(\$97,537.50)	
				- Total				(\$97,537.50)	
			Material - Tota	ıl				(\$97,537.50)	
			MaterialCredit		10	Jul 5, 2023	SYSTEM	\$97,537.50	
				- Total				\$97,537.50	
			MaterialCredit	- Total				\$97,537.50	
	0370 -							\$0.00	
	0420	FIELD APPLICATION OF INORGANIC ZINC	Material		2	Mar 2, 2023	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user krausm2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	Mar 2, 2023	SYSTEM	(\$800.00)	
				- Total				\$0.00	
			Material - Total				\$0.00		
	0420 -							\$0.00	
	0430	INTERMEDIATE	Material		2	Mar 2,	SYSTEM	\$33,400.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3534	0430	FIELD COAT (SYSTEM G)	Material			2023			Estimate Item Adjustment (0005) due to user krausm2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					2	Mar 2, 2023	SYSTEM	(\$33,400.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0430 -	Total						\$0.00	
	0440	FINISH FIELD COAT (SYSTEM G)	Material		3	Mar 17, 2023	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user krausm2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Mar 17, 2023	SYSTEM	(\$2,400.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0440 -	Total						\$0.00	
	0460	TYPE N PTFE BEARING	Material		16	Oct 2, 2023	SYSTEM	\$7,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user pansag1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					16	Oct 2, 2023	SYSTEM	(\$7,900.00)	
					17	Oct 17, 2023	SYSTEM	\$39,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user gummer1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					17	Oct 17, 2023	SYSTEM	(\$39,500.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0460 -	Total						\$0.00	
	0470	SILICONE EXPANSION JOINT SEALANT	Material		17	Oct 17, 2023	SYSTEM	(\$16,640.00)	
		JOINT SEALANT		- Total				(\$16,640.00)	
			Material - Tota	ı				(\$16,640.00)	
	0470 -	Total						(\$16,640.00)	
	0490	MISC.	MISC. Material		11	Jul 17, 2023	SYSTEM	\$122,280.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user pansag1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11	Jul 17, 2023	SYSTEM	(\$122,280.26)	
					12	Aug 2, 2023	SYSTEM	\$251,615.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user pansag1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					12	Aug 2, 2023	SYSTEM	(\$251,615.90)	
				- Total		2020		\$0.00	
			Material - Tota					\$0.00	
	0490 -	Total						\$0.00	
	0500	SUBSTRUCTURE REPAIR (UNFORMED)	Material		10	Jul 5, 2023	SYSTEM	\$69,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user krausm2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		(======================================			10	Jul 5, 2023	SYSTEM	(\$69,160.00)	
					11	Jul 17, 2023	SYSTEM	\$93,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user pansag1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					11	Jul 17, 2023	SYSTEM	(\$93,600.00)	
					12	Aug 2, 2023	SYSTEM	\$109,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user pansag1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					12	Aug 2, 2023	SYSTEM	(\$109,200.00)	
						13	Aug 17, 2023	SYSTEM	\$109,200.00



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
J6I3534	0500	SUBSTRUCTURE	Material						Estimate Exception 7 on the current Payment Estimate.																
		REPAIR (UNFORMED)			13	Aug 17, 2023	SYSTEM	(\$109,200.00)																	
					14	Sep 5, 2023	SYSTEM	\$109,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user pansag1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																
					14	Sep 5, 2023	SYSTEM	(\$109,200.00)																	
					15	Sep 18, 2023	SYSTEM	\$109,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user pansag1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																
					15	Sep 17, 2023	SYSTEM	(\$109,200.00)																	
					16	Oct 2, 2023	SYSTEM	\$109,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user pansag1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																
					16	Oct 2, 2023	SYSTEM	(\$109,200.00)																	
					17	Oct 17, 2023	SYSTEM	\$109,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user gummer1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																
					17	Oct 17, 2023	SYSTEM	(\$109,200.00)																	
				- Total				\$0.00																	
			Material - Tota					\$0.00																	
	0500 -	Total		•				\$0.00																	
	0560	FIELD APPLICATION OF INORGANIC ZINC	:		2	Mar 2, 2023	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user krausm2 overridding Payment Estimate Exception 4 on the current Payment Estimate.																
					2	Mar 2, 2023	SYSTEM	(\$400.00)																	
				- Total				\$0.00																	
			Material - Tota					\$0.00																	
	0560 -	Total						\$0.00																	
	0570	INTERMEDIATE FIELD COAT (SYSTEM G)	IELD COAT		2	Mar 2, 2023	SYSTEM	\$20,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user krausm2 overridding Payment Estimate Exception 6 on the current Payment Estimate.																
					2	Mar 2, 2023	SYSTEM	(\$20,200.00)																	
				- Total				\$0.00																	
			Material - Tota					\$0.00																	
	0570 -	Total						\$0.00																	
	0640	SUBSTRUCTURE REPAIR (UNFORMED)	Material		11	Jul 17, 2023	SYSTEM	\$12,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user pansag1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																
				1	1		1	1	11	Jul 17, 2023	SYSTEM	(\$12,650.00)													
																					12	Aug 2, 2023	SYSTEM	\$16,675.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user pansag1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
																								12	12
					13	Aug 17, 2023	SYSTEM	\$61,525.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user gummer1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																
					13	Aug 17, 2023	SYSTEM	(\$61,525.00)																	
					14	Sep 5, 2023	SYSTEM	\$61,525.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user pansag1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																
					14	Sep 5, 2023	SYSTEM	(\$61,525.00)	·																
									15	Sep 18, 2023	SYSTEM	\$61,525.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user pansag1 overridding Payment Estimate Exception 20 on the current Payment Estimate.												



Section Sect	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
10	J6I3534	0640	REPAIR	Material		15		SYSTEM	(\$61,525.00)	
17			(UNFORMED)			16		SYSTEM	\$61,525.00	Estimate Item Adjustment (0007) due to user pansag1 overridding Payment
2023 Estimate Benn Adjustment (0029) due to user gamment coverabiling Payment Estimate. 1						16		SYSTEM	(\$61,525.00)	
Total						17		SYSTEM	\$49,450.00	Estimate Item Adjustment (0024) due to user gummer1 overridding Payment
Material - Total 12 Aug 2, SYSTEM \$0,000						17		SYSTEM	(\$49,450.00)	
12 Aug 2 SYSTEM SPOON This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Represent Cellerated Exception 2 on the current Represent Estimate Secretary					- Total				\$0.00	
Name				Material - Tota	ıl				\$0.00	
SEPAIR 2023 SYSTEM 30,750.00 STRIME		0640 -	Total						\$0.00	
Total S0.00 Material - Total S0.00 S0.00 S		0650		Material		12		SYSTEM	\$9,750.00	Estimate Item Adjustment (0012) due to user pansag1 overridding Payment
						12		SYSTEM	(\$9,750.00)	
10,00					- Total				\$0.00	
			Material - Tota	ıl				\$0.00		
COAT (SYSTEM COA		0650 -	Total						\$0.00	
2023 SYSTEM \$28,600.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate Exception 6 on the current Payment Estimate Estimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate.		0700	COAT (SYSTEM	Material		7		SYSTEM	\$5,600.00	Estimate Item Adjustment (0003) due to user krausm2 overridding Payment
2023 Sestimate Item Adjustment (006) due to user krausm2 overridding Payment Estimate Exception 6 on the current Payment Estimate Payment Estimate Exception 5 on the current Payment Estimate Payment Estimate Exception 5 on the current Payment Estimate Payment Paymen						7		SYSTEM	(\$5,600.00)	
2023 9 Jun 16, 2023 23 23						8		SYSTEM	\$28,600.00	Estimate Item Adjustment (0006) due to user krausm2 overridding Payment
2023 Estimate Item Adjustment (0005) due to user stgernr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.						8		SYSTEM	(\$28,600.00)	
Aug 17, System Sum Sum						9		SYSTEM	\$28,600.00	Estimate Item Adjustment (0005) due to user stgemr1 overridding Payment
12						9		SYSTEM	(\$28,600.00)	
O730 OPEN CELL FOAM JOINT SEAL Material FOAM JOINT SEAL 12 Aug 2, 2023 SYSTEM \$11,610.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user pansag1 overridding Payment Estimate Item Adjustment (0013) due to user pansag1 overridding Payment Estimate Item Adjustment (0006) due to user gummer1 overridding Payment Estimate Item Adjustment (0006) due to user gummer1 overridding Payment Estimate Item Adjustment (0006) due to user gummer1 overridding Payment Estimate Exception 16 on the current Payment Estimate. 13					- Total			\$0.00		
12				Material - Tota	ıl				\$0.00	
Comparison Com		0700 -	Total						\$0.00	
13		0730	FOAM JOINT	Material		12		SYSTEM	\$11,610.00	Estimate Item Adjustment (0013) due to user pansag1 overridding Payment
Estimate Item Adjustment (0006) due to user gummer1 overridding Payment Estimate Exception 16 on the current Payment Estimate. 13 Aug 17, 2023 Total S0.00 Material - Total S0.00 SILICONE EXPANSION JOINT SEALANT 12 Aug 2, 2023 SYSTEM (\$7,480.00) 13 Aug 17, 2023 13 Aug 17, SYSTEM (\$7,480.00) This adjustment offsets the original system-generated Material Payment Estimate Exception 26 on the current Payment Estimate. 14 Aug 2, 2023 This adjustment (0014) due to user pansag1 overridding Payment Estimate Exception 26 on the current Payment Estimate. 15 Aug 17, 2023 16 Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Exception 26 on the current Payment Estimate. 18 Aug 17, SYSTEM (\$7,480.00) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user gummer1 overridding Payment Estimate Item Adjustment (0007) due to user gummer1 overridding Payment Estimate Exception 17 on the current Payment Estimate.						12		SYSTEM	(\$11,610.00)	
- Total \$0.00 Material - Total \$0.00 0730 - Total \$0.00 0740 SILICONE EXPANSION JOINT SEALANT 12 Aug 2, 2023 SYSTEM \$7,480.00 Estimate ltem Adjustment (0014) due to user pansag1 overridding Payment Estimate Exception 26 on the current Payment Estimate. 12 Aug 2, 2023 SYSTEM \$7,480.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 26 on the current Payment Estimate. 13 Aug 17, SYSTEM \$7,480.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user gummer1 overridding Payment Estimate Exception 17 on the current Payment Estimate. 13 Aug 17, SYSTEM (\$7,480.00)						13		SYSTEM	\$11,610.00	Estimate Item Adjustment (0006) due to user gummer1 overridding Payment
Material - Total \$0.00						13		SYSTEM	(\$11,610.00)	
SILICONE EXPANSION JOINT SEALANT SYSTEM S7,480.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user pansag1 overridding Payment Estimate Exception 26 on the current Payment Estimate. 12					- Total				\$0.00	
12 Aug 2, 2023 SYSTEM \$7,480.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user pansag1 overridding Payment Estimate Exception 26 on the current Payment Estimate. 12 Aug 2, 2023 SYSTEM (\$7,480.00) 13 Aug 17, 2023 SYSTEM \$7,480.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user gummer1 overridding Payment Estimate Item Adjustment (0007) due to user gummer1 overridding Payment Estimate Exception 17 on the current Payment Estimate.				Material - Tota	ıl				\$0.00	
ESTIMATE Item Adjustment (0014) due to user pansag1 overridding Payment Estimate Exception 26 on the current Payment Estimate. 12 Aug 2, 2023 13 Aug 17, 2023 14 SYSTEM (\$7,480.00) 15 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user gummer1 overridding Payment Estimate Exception 17 on the current Payment Estimate.		0730 -	Total						\$0.00	
2023 13 Aug 17, 2023 SYSTEM \$7,480.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user gummer1 overridding Payment Estimate Exception 17 on the current Payment Estimate. 13 Aug 17, SYSTEM (\$7,480.00)		0740	EXPANSION	Material		12		SYSTEM	\$7,480.00	Estimate Item Adjustment (0014) due to user pansag1 overridding Payment
Estimate Item Adjustment (0007) due to user gummer1 overridding Payment Estimate Exception 17 on the current Payment Estimate. 13 Aug 17, SYSTEM (\$7,480.00)						12		SYSTEM	(\$7,480.00)	
						13		SYSTEM	\$7,480.00	Estimate Item Adjustment (0007) due to user gummer1 overridding Payment
						13		SYSTEM	(\$7,480.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																					
J6l3534	0740	SILICONE EXPANSION JOINT SEALANT	Material		14	Sep 5, 2023	SYSTEM	\$7,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user pansag1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																					
					14	Sep 5, 2023	SYSTEM	(\$7,480.00)																						
					15	Sep 18, 2023	SYSTEM	\$7,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user pansag1 overridding Payment Estimate Exception 25 on the current Payment Estimate.																					
					15	Sep 17, 2023	SYSTEM	(\$7,480.00)																						
				- Total				\$0.00																						
			Material - Tota	ıl				\$0.00																						
	0740 -	Total						\$0.00																						
	0770	SUBSTRUCTURE REPAIR (UNFORMED)	Material		10	Jul 5, 2023	SYSTEM	\$53,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user krausm2 overridding Payment Estimate Exception 10 on the current Payment Estimate.																					
					10	Jul 5, 2023	SYSTEM	(\$53,760.00)																						
						11	Jul 17, 2023	SYSTEM	\$53,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user pansag1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																				
						11	Jul 17, 2023	SYSTEM	(\$53,760.00)																					
					12	Aug 2, 2023	SYSTEM	\$63,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user pansag1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																					
						12	Aug 2, 2023	SYSTEM	(\$63,000.00)																					
					13	Aug 17, 2023	SYSTEM	\$63,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user gummer1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																					
							13	Aug 17, 2023	SYSTEM	(\$63,000.00)																				
					14	Sep 5, 2023	SYSTEM	\$63,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user pansag1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																					
										14	Sep 5, 2023	SYSTEM	(\$63,000.00)																	
					15	Sep 18, 2023	SYSTEM	\$63,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user pansag1 overridding Payment Estimate Exception 23 on the current Payment Estimate.																					
					15	Sep 17, 2023	SYSTEM	(\$63,000.00)																						
					16	Oct 2, 2023	SYSTEM	\$63,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user pansag1 overridding Payment Estimate Exception 17 on the current Payment Estimate.																					
																		16	2023 17 Oct 17, SYSTEM \$63,000.00 This adjustment offsets the original system-generated Estimate Item Adjustment (0009) due to user gumme							16		SYSTEM	(\$63,000.00)	
																				This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user gummer1 overridding Payment Estimate Exception 16 on the current Payment Estimate.										
					17	Oct 17, 2023	SYSTEM	(\$63,000.00)																						
				- Total				\$0.00																						
			Material - Tota	ı				\$0.00																						
	0770 -	Total						\$0.00																						
	0780	HALF-SOLE REPAIR	Material		16	Oct 2, 2023	SYSTEM	\$14,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user pansag1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																					
					16	Oct 2, 2023	SYSTEM	(\$14,400.00)																						
						17	Oct 17, 2023	SYSTEM	\$14,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user gummer1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																				
					17	Oct 17, 2023	SYSTEM	(\$14,400.00)																						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3534	0780	HALF-SOLE REPAIR	Material	- Total				\$0.00	
		TELLY	Material - Tota	1				\$0.00	
	0780 -	- Total						\$0.00	
	0830	FINISH FIELD COAT (SYSTEM G)	Material		9	Jun 16, 2023	SYSTEM	\$18,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stgemr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Jun 16, 2023	SYSTEM	(\$18,800.00)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
	0830 -	- Total						\$0.00	
	0870	SILICONE EXPANSION JOINT SEALANT	Material		14	Sep 5, 2023	SYSTEM	\$9,240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user pansag1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					14	Sep 5, 2023	SYSTEM	(\$9,240.00)	
					15	Sep 18, 2023	SYSTEM	\$9,240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user pansag1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					15	Sep 17, 2023	SYSTEM	(\$9,240.00)	
				- Total				\$0.00	
			Material - Tota	l				\$0.00	
	0870 -	- Total						\$0.00	
	5004	CLEANING AND EPOXY COATING	Material		16	Oct 2, 2023	SYSTEM	\$4,094.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user pansag1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					16	Oct 2, 2023	SYSTEM	(\$4,094.46)	
					17	Oct 17, 2023	SYSTEM	\$4,094.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user gummer1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					17	Oct 17, 2023	SYSTEM	(\$4,094.46)	
				- Total				\$0.00	
			Material - Tota	l .				\$0.00	
	5004	- Total						\$0.00	
J6I3534 -	Total							(\$16,640.00)	
J6S3556	0910	SHAPING SLOPES, CLASS III	Material		10	Jul 5, 2023	SYSTEM	\$7,344.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user krausm2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Jul 5, 2023	SYSTEM	(\$7,344.00)	
					11	Jul 17, 2023	SYSTEM	\$7,344.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user pansag1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Jul 17, 2023	SYSTEM	(\$7,344.00)	
					12	Aug 2, 2023	SYSTEM	\$7,344.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user pansag1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Aug 2, 2023	SYSTEM	(\$7,344.00)	
				- Total				\$0.00	
			Material - Tota	l e				\$0.00	
	0910 -	- Total						\$0.00	
	0920	TYPE 5 AGGREGATE FOR BASE	Price FUEL		15	Sep 17, 2023	SYSTEM	(\$0.49)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		I ON DASE		- Total				(\$0.49)	
			Price FUEL - T	otal				(\$0.49)	
	0920	- Total						(\$0.49)	
	0950	CONCRETE	Material		15	Sep 17,	SYSTEM	\$24,206.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks	
1 Toject	LIIIC	Безеприон	Туре	Adjustment Type	Number	Date	By	Amount	Remarks	
J6S3556	0950	SIDEWALK, 4 IN.	Material			2023			Estimate Item Adjustment (0013) due to user pansag1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					15	Sep 17, 2023	SYSTEM	(\$24,206.00)		
					16	Oct 2, 2023	SYSTEM	\$24,206.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user pansag1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					16	Oct 2, 2023	SYSTEM	(\$24,206.00)		
					17	Oct 17, 2023	SYSTEM	\$24,206.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					17	Oct 17, 2023	SYSTEM	(\$24,206.00)		
				- Total				\$0.00		
			Material - Total					\$0.00		
	0950 -	Total						\$0.00		
	0960	SLOPE PROTECTION	Material		16	Oct 2, 2023	SYSTEM	\$28,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user pansag1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					16	Oct 2, 2023	SYSTEM	(\$28,560.00)		
						17	Oct 17, 2023	SYSTEM	\$28,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user gummer1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					17	Oct 17, 2023	SYSTEM	(\$28,560.00)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	0960 -	Total						\$0.00		
	0970	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	Material		2	Mar 2, 2023	SYSTEM	\$10,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user krausm2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					2	Mar 2, 2023	SYSTEM	(\$10,000.00)		
				- Total				\$0.00		
			Material - Tota	l de la companya de				\$0.00		
	0970 -	Total						\$0.00		
	1040	6 IN. WHITE HIGH BUILD WATERBORNE	Material		15	Sep 18, 2023	SYSTEM	\$2,461.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user pansag1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
		PAINT			15	Sep 17, 2023	SYSTEM	(\$2,461.00)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	1040 -	Total						\$0.00		
	1050	6 IN. YELLOW HIGH BUILD WATERBORNE	Material		15	Sep 18, 2023	SYSTEM	\$779.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user pansag1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
		PAINT			15	Sep 17, 2023	SYSTEM	(\$779.00)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	1050 -	Total						\$0.00		
	1060	FLOWABLE BACKFILL	Material		12	Aug 2, 2023	SYSTEM	\$25,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user pansag1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					12	Aug 2, 2023	SYSTEM	(\$25,000.00)		
						13	Aug 17, 2023	SYSTEM	\$25,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user gummer1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
						13	Aug 17,	SYSTEM	(\$25,000.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3556	1060	FLOWABLE	Material			2023			
		BACKFILL			14	Sep 5, 2023	SYSTEM	\$25,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user pansag1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Sep 5, 2023	SYSTEM	(\$25,000.00)	
					15	Sep 18, 2023	SYSTEM	\$25,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user pansag1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					15	Sep 17, 2023	SYSTEM	(\$25,000.00)	
					16	Oct 2, 2023	SYSTEM	\$25,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user pansag1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					16	Oct 2, 2023	SYSTEM	(\$25,000.00)	
					17	Oct 17, 2023	SYSTEM	\$25,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user gummer1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					17	Oct 17, 2023	SYSTEM	(\$25,000.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	1060 -	Total						\$0.00	
	1080	SLAB JACKING MATL HIGH	Material		17	Oct 17, 2023	SYSTEM	(\$6,372.00)	
		DENSITY POLYURETH		- Total				(\$6,372.00)	
			Material - Tota	ıl				(\$6,372.00)	
	1080 -	Total						(\$6,372.00)	
	1110	MISC.	. Material		11	Jul 17, 2023	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user pansag1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					11	Jul 17, 2023	SYSTEM	(\$2,500.00)	
					12	Aug 2, 2023	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user pansag1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					12	Aug 2, 2023	SYSTEM	(\$5,000.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	1110 -	Total						\$0.00	
	1120	MISC.	Material		17	Oct 17, 2023	SYSTEM	\$3,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user gummer1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					17	Oct 17, 2023	SYSTEM	(\$3,672.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	1120 -	Total						\$0.00	
	1130	MGS GUARDRAIL	Construction Stockpile		10	Jul 5, 2023	SYSTEM	(\$5,491.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
					17	Oct 17, 2023	SYSTEM	(\$47,854.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$53,346.00)	
			Construction	Stockpile - To	otal			(\$53,346.00)	
			Construction Stockpile		3	Mar 17, 2023	SYSTEM	\$53,346.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$53,346.00	
			Construction	Stockpile STI	MI - Total			\$53,346.00	
	1130 -	otal						\$0.00	
	1140	MGS GUARDRAIL,	Construction		17	Oct 17,	SYSTEM	(\$1,891.00)	Payment Estimate Item Adjustment generated Stockpile Transaction



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
556	1140	8 FT. POSTS, 6 FT 3 IN	Stockpile			2023				
				- Total				(\$1,891.00)		
			Construction	Stockpile - To		Man 47	OVOTEM	(\$1,891.00)	Description to the Adjustment consists of Ottoballia Transaction	
			Construction Stockpile		3	Mar 17, 2023	SYSTEM	\$1,891.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			STMI	- Total				\$1,891.00		
			Construction	Stockpile STI	VII - Total			\$1,891.00		
	1140 -		0 1 1		47	0.147	OVOTEM	\$0.00		
	1150	MGS BRIDGE APP. TRANS SEC (EXT CURB)	Construction Stockpile	- Total	17	Oct 17, 2023	SYSTEM	(\$6,795.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
			Construction		otal			(\$6,795.00)		
			Construction	otoonpiio t	3	Mar 17,	SYSTEM	\$6,795.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			Stockpile STMI	- Total			\$6,795.00			
			Construction	Stockpile STI	VII - Total			\$6,795.00		
	1150 -	Total						\$0.00		
	1160	MGS BRIDGE APP. TRANS SEC	Construction Stockpile		10	Jul 5, 2023	SYSTEM	(\$6,795.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		(REG/NO CURB)			17	Oct 17, 2023	SYSTEM	(\$15,855.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$22,650.00)		
			Construction	Stockpile - To	otal			(\$22,650.00)		
			Construction Stockpile STMI		3	Mar 17, 2023	SYSTEM	\$22,650.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			STIVII	- Total				\$22,650.00		
			Construction	Stockpile STI	VII - Total			\$22,650.00		
ı	1160 -							\$0.00		
	1180	MGS END ANCHOR		Construction Stockpile		10	Jul 5, 2023	SYSTEM	(\$835.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					17	Oct 17, 2023	SYSTEM	(\$6,680.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$7,515.00)		
			Construction	Stockpile - To				(\$7,515.00)		
			Construction Stockpile STMI		3	Mar 17, 2023	SYSTEM	\$7,515.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$7,515.00		
			Construction	Stockpile STI	VII - Total			\$7,515.00		
	1180 -		Construct		10	lut 5	CVOTE:	\$0.00	Decrease Februarie Home Additionary and add Co. 1, 2, 7	
	1190	CRASHWORTHY END TERMINAL	Construction Stockpile		10	Jul 5, 2023	SYSTEM	(\$3,750.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		(MASH)			17	Oct 17, 2023	SYSTEM	(\$15,000.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$18,750.00)		
			Construction	Stockpile - To			a) (==	(\$18,750.00)		
			Construction Stockpile STMI		3	Mar 17, 2023	SYSTEM	\$18,750.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$18,750.00		
	1190 -	Total	Construction	Stockpile STI	VII - Total			\$18,750.00		
	1250	PROTECTIVE COATING -	Material		8	Jun 2, 2023	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user krausm2 overridding Payment	
	55	CONCRETE BENTS AND			8	Jun 2,	SYSTEM	(\$8,000.00)	Estimate Exception 5 on the current Payment Estimate.	
					9	2023 Jun 16,	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment	
						2023			Estimate Item Adjustment (0007) due to user stgemr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J6S3556	1250	PROTECTIVE COATING - CONCRETE	Material		9	Jun 16, 2023	SYSTEM	(\$8,000.00)				
		BENTS AND		- Total				\$0.00				
			Material - Tota	ıl				\$0.00				
	1250 -	Total						\$0.00				
	1320	FINISH FIELD COAT (SYSTEM G)	Material		6	May 2, 2023	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user krausm2 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					6	May 2, 2023	SYSTEM	(\$3,000.00)				
				- Total				\$0.00				
			Material - Tota	ıl				\$0.00				
	1320 -	Total						\$0.00				
	1370	SUBSTRUCTURE REPAIR (UNFORMED)	Material		15	Sep 18, 2023	SYSTEM	\$15,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user pansag1 overridding Payment Estimate Exception 24 on the current Payment Estimate.			
					15	Sep 17, 2023	SYSTEM	(\$15,050.00)				
						16	Oct 2, 2023	SYSTEM	\$15,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user pansag1 overridding Payment Estimate Exception 18 on the current Payment Estimate.		
									16	Oct 2, 2023	SYSTEM	(\$15,050.00)
					17	Oct 17, 2023	SYSTEM	\$102,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user gummer1 overridding Payment Estimate Exception 17 on the current Payment Estimate.			
					17	Oct 17, 2023	SYSTEM	(\$102,125.00)				
				- Total				\$0.00				
			Material - Tota	ıl				\$0.00				
	1370 -	Total						\$0.00				
	1380	CLEANING AND EPOXY COATING	Material		11	Jul 17, 2023	SYSTEM	\$300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user pansag1 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
					11	Jul 17, 2023	SYSTEM	(\$300.00)				
					12	Aug 2, 2023	SYSTEM	\$303.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user pansag1 overridding Payment Estimate Exception 23 on the current Payment Estimate.			
					12	Aug 2, 2023	SYSTEM	(\$303.00)				
				- Total				\$0.00				
			Material - Tota	ıl				\$0.00				
	1380 -	Total						\$0.00				
	1470	SILICONE EXPANSION JOINT SEALANT	Material		16	Oct 2, 2023	SYSTEM	\$4,960.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user pansag1 overridding Payment Estimate Exception 25 on the current Payment Estimate.			
					16	Oct 2, 2023	SYSTEM	(\$4,960.00)				
					17	Oct 17, 2023	SYSTEM	(\$4,960.00)				
				- Total				(\$4,960.00)				
			Material - Tota	ıl				(\$4,960.00)				
	1470 -	Total						(\$4,960.00)				
J6S3556 -	Total							(\$11,332.49)				
Overall -	Total						(\$27,972.49)					

MoDOT

Contract Adjustments for Contract - 221021-F02

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 28 of 28