

# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 18, 2023

Progress Estim	Progress Estimate Number 11		221021-F07 Concrete Strategies		ay Period Start ay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	\$5,631,445.13 (\$72,647.25) \$5,558,797.88
Approval Date								By User
July 18, 2023			Generated and Ap	oproved (a	nd should be co	nsidered Draft	at the Project Office Level by	canadt2
July 18, 2023		R	eviewed and Approv	ed (and sh	ould be conside	red Draft) at th	e Resident Engineer Level by	amburs1
July 18, 2023	Reviewed and Approved at the Central Office Controllers Office Level by							
Original Comp	letion Date	Current Com	nletion Date	Actual	Completion Da	to	% of Current Contract Amou	nt Complete

Original Completion Date	<b>Current Completion Date</b>	Actual Completion Date	% of Current Contract Amount Complete				
December 15, 2023	December 15, 2023		41.71%				

Date Description	Original Completion Date	Current Completion Date
Acceptance Date		
Awarded Date	November 2, 2022	November 2, 2022
Letting Date	October 21, 2022	October 21, 2022
Notice to	January 3, 2023	January 3, 2023

January 23, 2023 January 23, 2023

**Contract Informational Dates** 

Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days
J6S3532 Per JSP G - East Bound Route 30 Bridge Closure	August 1, 2023	August 1, 2023	14	

Milestones

Contract Total Pay For Estimate No. 11				
	This Estimate	Previous	To Date	
221021-F07				
Total Posted Items Pay	\$237,834.84	\$2,080,713.40	\$2,318,548.24	
Gross Item Adjustments	(\$7,800.21)	\$182,418.84	\$174,618.63	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
_		\$2,263,132.24	\$2,493,166.87	
Contract Total Payable This Estimate:	\$230,034.63			

### Items Paid This Estimate Period

Proceed Date
Open to
Traffic Date
Work Began

Date

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3532	0800	6122030	IMPACT ATTENUATOR (RELOCATION)	EA	\$1,605.430	1	\$1,605.43
	0570	7040101	SUBSTRUCTURE REPAIR (FORMED)	SQFT	\$288.970	11	\$3,178.67
	0610	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$3.360	2,320	\$7,795.20
	0630	7120900	EXPANSION DEVICE (FINGER PLATE)	LF	\$2,997.910	36	\$107,924.76
	0690	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	LF	\$607.040	18	\$10,926.72
	5003	7039907	MISC.HIGH PERFORMANCE CONCRETE (HCSC)	CUYD	\$10,231.160	10.4	\$106,404.06
Project J6S353	2 - Total						\$237,834.84
Overall - Total							\$237,834.84

### **Contract Adjustments This Estimate**

No Contract Adjustments Exist on Contract

Line Item	ine Item Adjustments This Estimate													
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount						
J6S3532	0430	PROTECTIVE COATING - CONCRETE BENTS AND	Material			-0.4	\$32,108.65	(\$12,843.46)						

Revision 3/23/2023 Page 1 of 13



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 18, 2023

Progress Estimate Number
11 Contract ID 221021-F07 Pay Period Start July 1, 2023 Original Contract Amount (\$5,631,445.13 Pay Period End July 15, 2023 Original Contract Amount (\$72,647.25) Original Contract Amount (\$72,647.

ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
532	0430	PIERS (EPOXY)  PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user canadt2 overridding Payment Estimate Exception 9 on the current Payment Estimate.	0.4	\$32,108.65	\$12,843.4
	0540	MISC.	Material			-74	\$3,752.15	(\$277,659.1
	0540	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user canadt2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	74	\$3,752.15	\$277,659.1
	0570	SUBSTRUCTURE REPAIR (FORMED)	Overrun			-11	\$288.97	(\$3,178.6
	0600	MECHANICAL BAR SPLICE	Material			-74	\$69.83	(\$5,167.4
	0600	MECHANICAL BAR SPLICE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user canadt2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	74	\$69.83	\$5,167.4
	0610	REINFORCING STEEL (EPOXY COATED)	Material			-4,820	\$3.36	(\$16,195.2
	0610	REINFORCING STEEL (EPOXY COATED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user canadt2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	4,820	\$3.36	\$16,195.2
	0620	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material			-0.4	\$25,686.92	(\$10,274.7
	0620	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user canadt2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	0.4	\$25,686.92	\$10,274.7
	0630	EXPANSION DEVICE (FINGER PLATE)	Material			-76	\$2,997.91	(\$227,841.1
	0630	EXPANSION DEVICE (FINGER PLATE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user canadt2 overridding Payment Estimate Exception 11 on the current Payment Estimate.	76	\$2,997.91	\$227,841.10
	0690	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$4,621.5
	0690	STRIP SEAL EXPANSION JOINT SYSTEM	Material			-76	\$607.04	(\$46,135.0
	0690	STRIP SEAL EXPANSION JOINT SYSTEM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user canadt2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	76	\$607.04	\$46,135.04
	5003	MISC.	Material			-20.9	\$10,231.16	(\$213,831.24
	5003	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user canadt2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	20.9	\$10,231.16	\$213,831.2

Revision 3/23/2023 Page 2 of 13



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					С	ontract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6S3532	FAF 30-1(49)	2 Bridge rehabilitations	30	ST LOUIS	over the Meramec River		
Totals by .	Job Numbe	ers					
J6S3532					This Estimate	Previous	To Date
J6S3532	Poste	ed Item Pay			This Estimate \$237,834.84	Previous \$2,080,713.40	<b>To Date</b> \$2,318,548.24
J6S3532		ed Item Pay s Item Adjustme	ents				
J6S3532				Item Pay	\$237,834.84	\$2,080,713.40	\$2,318,548.24
J6S3532		s Item Adjustme		Item Pay	\$237,834.84 (\$7,800.21)	\$2,080,713.40 \$182,418.84	\$2,318,548.24 \$174,618.63
J6S3532	Gross	s Item Adjustme		Item Pay	\$237,834.84 (\$7,800.21) <b>\$230,034.63</b>	\$2,080,713.40 \$182,418.84 <b>\$2,263,132.24</b>	\$2,318,548.24 \$174,618.63 <b>\$2,493,166.87</b>
J6S3532	Incen Disin	s Item Adjustme	Gross	Item Pay	\$237,834.84 (\$7,800.21) <b>\$230,034.63</b> \$0.00	\$2,080,713.40 \$182,418.84 <b>\$2,263,132.24</b> \$0.00	\$2,318,548.24 \$174,618.63 <b>\$2,493,166.87</b> \$0.00

Revision 3/23/2023 Page 3 of 13



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3532, Item 5029907, Project Item Line Number 0540, Material Set 502990796, Material 1039PEPCWS - Polyester Polymer Concrete Wearing Surface, Acceptance Action Generic 1039PEPCWS is insufficient.	Sampling & Testing has not yet been completed in Cognos (will complete Monday). Material passed adhesion pull test per product data sheet.	canadt2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3532, Item 7039907, Project Item Line Number 5003, Material Set 703990796, Material 1039ERPCPC - Polymer Concrete, Acceptance Action Generic 1039ERPCPC is insufficient.	Sampling & Testing has not yet been completed in Cognos (will complete Monday). Compressive Strength testing shows satisfactory results.	canadt2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3532, Item 7061070, Project Item Line Number 0600, Material Set 706107096, Material 1036RSMBS - Mechanical Bar Splice for Reinf Steel @, Acceptance Action Generic ReinforcingMisc is insufficient.	PAL information has not yet been completed for this line item. Inspector to work with MoDOT Materials to get these tests completed.	canadt2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3532, Item 7101000, Project Item Line Number 0610, Material Set 710100096, Material 1036RSDFEC42M25 - Rein Steel EC No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	PAL information has not yet been completed for this line item. Inspector to work with MoDOT Materials to get these tests completed	canadt2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3532, Item 7101000, Project Item Line Number 0610, Material Set 710100096, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	canadt2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3532, Item 7101000, Project Item Line Number 0610, Material Set 710100096, Material 1036RSDFEC42M22 - Rein Steel EC No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	canadt2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3532, Item 7101000, Project Item Line Number 0610, Material Set 710100096, Material 1036RSDFEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	canadt2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3532, Item 7101000, Project Item Line Number 0610, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	canadt2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3532, Item 7110200, Project Item Line Number 0430, Material Set 711020096, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	This payment was based on the removal of old coating from concrete @ Abut 1 & Abut 12. Sampling will be completed when contractor applies epoxy to abut's and bent's.	canadt2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3532, Item 7110200, Project Item Line Number 0620, Material Set 711020096, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	This payment was based on the removal of old coating from concrete @ Abut 1 & Abut 12. Sampling will be completed when contractor applies epoxy to abut's and bent's.	canadt2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3532, Item 7120900, Project Item Line Number 0630, Material Set 712090096, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	PAL information has not yet been completed for this line item. Inspector to work with MoDOT Materials to get these tests completed	canadt2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3532, Item 7172001, Project Item Line Number 0690, Material Set 717200196, Material 1073JMSS - Strip Seal @, Acceptance Action Generic 1073JMSS is insufficient.	PAL information has not yet been completed for this line item. Inspector to work with MoDOT Materials to get these tests completed	canadt2	Overridden
Estimate Exception Type: Item Overrun: Contract 221021-F07, Contract Project J6S3532, Project Item Line Number 0570, Contract Line Item Number 0570, Item 7040101, Minor Item.	Contract quantity of this line item is 20 SF, of which 25 SF has been placed. Agreement with the Prime has been made to Change Order the overrun amount after substructure repairs have been completed on this bridge.	canadt2	Acknowledged

Revision 3/23/2023 Page 4 of 13



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
21021-F07	J6S3532	0001	0010	2019901	MISC.VEGETATION, CLEARING AND TRIMMING	1.00	0.00	1.00	LS	0.88	\$89,825.78	\$78,597.5
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.75	\$149,537.57	\$112,153.1
		0001	0030	2072000	LINEAR GRADING CLASS 2	14.40	0.00	14.40	STA	0.00	\$2,215.21	\$0.0
		0001	0040	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	3,079.00	0.00	3,079.00	SQYD	0.00	\$10.69	\$0.0
		0001	0050	4019905	MISC.OPTIONAL SHOULDER	3,079.30	0.00	3,079.30	SQYD	0.00	\$62.86	\$0.0
		0001	0060	6122014	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	1.00	\$3,210.86	\$3,210.8
		0001	0070	6122020	REPLACEMENT SAND BARREL	4.00	0.00	4.00	EA	0.00	\$256.87	\$0.0
		0001	0080	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	1.00	\$1,605.43	\$1,605.4
		0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	1.00	\$10,702.88	\$10,702.8
		0001	0100	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	8.00	0.00	8.00	EA	4.00	\$428.12	\$1,712.4
		0001	0110	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$89,593.30	\$44,796.6
		0001	0120	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN	7.00	0.00	7.00	EA	4.00	\$1,605.43	\$6,421.7
		0001	0130	6173600D	(CONTRACTOR FURNISHED AND RETAINED) TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED /	3,513.00	0.00	3.513.00	LF	1,813.00	\$40.67	\$73,734.7
					RETAINED			.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
		0001	0140	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	3,513.00	0.00	3,513.00	LF	1,750.00	\$21.41	\$37,467.5
		0001	0150	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$803,955.20	\$602,966.4
		0001	0160	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	2.00	0.00	2.00	EA	0.00	\$600.00	\$0.0
		0001	0170	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	4.00	0.00	4.00	EA	0.00	\$294.33	\$0.0
		0001	0180	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	13,550.00	0.00	13,550.00	LF	0.00	\$0.20	\$0.0
		0001	0190	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	10,276.00	0.00	10,276.00	LF	0.00	\$0.19	\$0.0
		0001	0200	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	326.00	0.00	326.00	LF	0.00	\$1.07	\$0.0
		0001	0210	6209901	MISC.OPTIONAL TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.25	\$4,816.30	\$1,204.0
		0001	0220	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE DROP ARROW	1.00	0.00	1.00	EA	0.00	\$856.23	\$0.0
		0001	0230	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	30.10	0.00	30.10	STA	0.00	\$317.10	\$0.0
		0001	0240	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$6,421.73	\$0.0
		0001	0250	8025006	MULCHING	4.80	0.00	4.80	ACRE	0.00	\$1,177.32	\$0.0
		0001	0260	8051000A	SEEDING - COOL SEASON GRASSES	3.20	0.00	3.20	ACRE	0.00	\$2,568.69	\$0.0
		0001	0270	8061006	ALTERNATE DITCH CHECK	476.00	0.00	476.00	LF	476.00	\$12.84	\$6,111.8
		0001	0280	8061007A	CURB INLET CHECK	1.00	0.00	1.00	EA	1.00	\$214.06	\$214.0
		0001	0290	8061016	SEDIMENT REMOVAL	63.00	0.00	63.00	CUYD	0.00	\$42.18	\$0.0
		0001	0300	8061017	TEMPORARY SEEDING	1.60	0.00	1.60	ACRE	0.00	\$2,140.58	\$0.0
		0001	0310	8061019	SILT FENCE	4,645.00	0.00	4,645.00	LF	1,231.00	\$3.75	\$4,616.2
		0070	0320	2161000	SCARIFICATION OF BRIDGE DECK	5,327.00	0.00	5,327.00	SQYD	0.00	\$6.57	\$0.0
		0070	0330	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	152.00	0.00	152.00	LF	0.00	\$575.43	\$0.0
		0070	0340	2169903	CONCRETE MISC.REMOVE AND REPLACE BARRIER	40.00	0.00	40.00	LF	0.00	\$696.87	\$0.0
		0070	0350	5029907	MISC.FURNISH POLYESTER POLYMER CONCRETE WEARING	148.00	0.00	148.00	CUYD	0.00	\$3,752.15	\$0.0
					SURFACE							
		0070	0360	5059905	MISC.PLACE POLYESTER POLYMER CONCRETE WEARING SURFACE	5,327.00	0.00	5,327.00	SQYD	0.00	\$35.25	\$0.0
		0070	0370	7039907	MISC.HIGH PERFORMANCE CONCRETE	20.90	-20.90	0.00	CUYD	0.00	\$14,030.19	\$0.0
		0070	0380	7040101	SUBSTRUCTURE REPAIR (FORMED)	10.00	0.00	10.00	SQFT	0.00	\$288.97	\$0.0
		0070	0390	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	810.00	0.00	810.00	SQFT	228.50	\$130.15	\$29,739.2
		0070	0400	7040104	HALF-SOLE REPAIR	1,800.00	0.00	1,800.00	SQFT	0.00	\$46.61	\$0.0
		0070	0410	7061070	MECHANICAL BAR SPLICE	74.00	0.00	74.00	EA	0.00	\$69.83	\$0.0
		0070	0420	7101000	REINFORCING STEEL (EPOXY COATED)	4,820.00	0.00	4,820.00	LB	0.00	\$3.36	\$0.0
		0070	0430	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.40	\$32,108.65	\$12,843.4
		0070	0440	7120900	EXPANSION DEVICE (FINGER PLATE)	76.00	0.00	76.00	LF	0.00	\$2,997.91	\$0.0

Revision 3/23/2023 Page 5 of 13



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
221021-F07	J6S3532	0070	0450	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	1.00	0.00	1.00	LS	0.00	\$21,498.60	\$0.00
		0070	0460	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	4,300.00	0.00	4,300.00	SQFT	4,128.00	\$36.39	\$150,217.92
		0070	0470	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	4,300.00	0.00	4,300.00	SQFT	4,300.00	\$4.28	\$18,404.00
		0070	0480	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	4,300.00	0.00	4,300.00	SQFT	0.00	\$2.14	\$0.00
		0070	0490	7125370A	FINISH FIELD COAT (SYSTEM G)	4,300.00	0.00	4,300.00	SQFT	0.00	\$2.14	\$0.00
		0070	0500	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	76.00	0.00	76.00	LF	0.00	\$607.04	\$0.00
		0071	0510	2161000	SCARIFICATION OF BRIDGE DECK	5,327.00	0.00	5,327.00	SQYD	5,327.00	\$6.57	\$34,998.39
		0071	0520	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	152.00	0.00	152.00	LF	152.00	\$575.43	\$87,465.36
		0071	0530	2169903	MISC.REMOVE AND REPLACE BARRIER	40.00	0.00	40.00	LF	25.00	\$696.87	\$17,421.75
		0071	0540	5029907	MISC.FURNISH POLYESTER POLYMER CONCRETE WEARING SURFACE	148.00	0.00	148.00	CUYD	74.00	\$3,752.15	\$277,659.10
		0071	0550	5059905	MISC.PLACE POLYESTER POLYMER CONCRETE WEARING SURFACE	5,327.00	0.00	5,327.00	SQYD	2,663.50	\$35.25	\$93,888.38
		0071	0560	7039907	MISC.HIGH PERFORMANCE CONCRETE	20.90	-20.90	0.00	CUYD	0.00	\$14,030.19	\$0.00
		0071	0570	7040101	SUBSTRUCTURE REPAIR (FORMED)	20.00	0.00	20.00	SQFT	36.00	\$288.97	\$10,402.92
		0071	0580	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	585.00	0.00	585.00	SQFT	188.90	\$130.15	\$24,585.34
		0071	0590	7040104	HALF-SOLE REPAIR	3,800.00	0.00	3,800.00	SQFT	0.00	\$46.61	\$0.00
		0071	0600	7061070	MECHANICAL BAR SPLICE	74.00	0.00	74.00	EA	74.00	\$69.83	\$5,167.42
		0071	0610	7101000	REINFORCING STEEL (EPOXY COATED)	4,820.00	0.00	4,820.00	LB	4,820.00	\$3.36	\$16,195.20
		0071	0620	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.40	\$25,686.92	\$10,274.77
		0071	0630	7120900	EXPANSION DEVICE (FINGER PLATE)	76.00	0.00	76.00	LF	76.00	\$2,997.91	\$227,841.16
		0071	0640	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	1.00	0.00	1.00	LS	0.00	\$21,498.60	\$0.00
		0071	0650	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	4,300.00	0.00	4,300.00	SQFT	1,376.00	\$36.39	\$50,072.64
		0071	0660	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	4,300.00	0.00	4,300.00	SQFT	1,376.00	\$4.28	\$5,889.28
		0071	0670	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	4,300.00	0.00	4,300.00	SQFT	0.00	\$2.14	\$0.00
		0071	0680	7125370A	FINISH FIELD COAT (SYSTEM G)	4,300.00	0.00	4,300.00	SQFT	0.00	\$2.14	\$0.00
		0071	0690	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	76.00	0.00	76.00	LF	76.00	\$607.04	\$46,135.04
		0070	5001	6214600A	FLOWABLE BACKFILL	0.00	8.00	8.00	CUYD	0.00	\$844.06	\$0.00
		0070	5002	7039907	MISC.HIGH PERFORMANCE CONCRETE (HCSC)	0.00	20.90	20.90	CUYD	0.00	\$10,231.16	\$0.00
		0071	5003	7039907	MISC.HIGH PERFORMANCE CONCRETE (HCSC)	0.00	20.90	20.90	CUYD	20.90	\$10,231.16	\$213,831.24
		0001	5004	1046002	VALUE ENGINEERING	0.00	79,399.73	79,399.73	EA	0.00	\$1.00	\$0.00
					late as of Report Generated Date							\$2,318,548.23
221021-F07 Ove	rall - Total	Value Post	ted to Dat	e as of Repo	ort Generated Date							\$2,318,548.23

Revision 3/23/2023 Page 6 of 13



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6S3532

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0080	6122030	IMPACT ATTENUATOR (RELOCATION)	7/15/23	7/18/23	1.00	EA	East Bound					Lane switch from Right Lane closure to Left Lane closure. (Forgot to pay on previous estimate, when barrier wall was relocated)
0570	7040101	SUBSTRUCTURE REPAIR (FORMED)	7/15/23	7/18/23	11.00	SQFT	Bent # 7 Cap					2 Repairs
0610	7101000	REINFORCING STEEL (EPOXY COATED)	7/15/23	7/18/23	2,320.00	LB	Stege 2					Payment being made to satisfy bid quantity for all Rebar installed for East Bound stage one and two.
0630	7120900	EXPANSION DEVICE (FINGER PLATE)	7/15/23	7/18/23	36.00	LF	Bent # 5 and Bent # 8					Payment being made to satisfy bid quantity for all Finger Joints installed for East Bound stage one and two.
0690	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	7/15/23	7/18/23	18.00	LF	Abut # 1 and Abut # 12					Payment being made to satisfy bid quantity for all Strip Seal Joints installed for East Bound stage one and two.
5003	7039907	MISC. CONCRETE CONSTRUCTION	7/15/23	7/18/23	10.40	CUYD	Abut # 1, Bent # 5, Bent # 8 and Abut 12.					Payment being made to satisfy bid quantity for HCSC installed for East Bound stage one and two.

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023 Page 7 of 13



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
2 (	0430	PROTECTIVE COATING - CONCRETE	Material		2	Mar 2, 2023	SYSTEM	\$6,421.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
		BENTS AND			2	Mar 2, 2023	SYSTEM	(\$6,421.73)							
					3	Mar 16, 2023	SYSTEM	\$6,421.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					3	Mar 16, 2023	SYSTEM	(\$6,421.73)							
					4	Apr 3, 2023	SYSTEM	\$6,421.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					4	Apr 3, 2023	SYSTEM	(\$6,421.73)							
					5	Apr 17, 2023	SYSTEM	\$12,843.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					5	Apr 17, 2023	SYSTEM	(\$12,843.46)							
					6	May 2, 2023	SYSTEM	\$12,843.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
						6	May 2, 2023	SYSTEM	(\$12,843.46)						
											7	May 16, 2023	SYSTEM	\$12,843.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
						7	May 16, 2023	SYSTEM	(\$12,843.46)						
					8	Jun 5, 2023	SYSTEM	\$12,843.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sawyej2 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
								8	Jun 5, 2023	SYSTEM	(\$12,843.46)				
										9	Jun 16, 2023	SYSTEM	\$12,843.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					9	Jun 16, 2023	SYSTEM	(\$12,843.46)							
					10	Jul 3, 2023	SYSTEM	\$12,843.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user canadt2 overridding Payment Estimate Exception 9 on the current Payment Estimate.						
					10	Jul 3, 2023	SYSTEM	(\$12,843.46)							
						11	11	11	11	Jul 18, 2023	SYSTEM	\$12,843.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user canadt2 overridding Payment Estimate Exception 9 on the current Payment Estimate.		
					11	Jul 18, 2023	SYSTEM	(\$12,843.46)							
				- Total				\$0.00							
	0.420	Total	Material - To	tal				\$0.00							
	0430 - 0440	EXPANSION			9	Jun 16,	SYSTEM	\$0.00 \$159,729.00	Payment Estimate Item Adjustment generated Stockpile Transaction						
		DEVICE (FINGER PLATE)	Stockpile STMI	- Total		2023		\$159,729.00							
			Construction	1 Stockpile S	TMI - Total			\$159,729.00							
	0440 -	Total						\$159,729.00							
	0500	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile STMI	- Total	7	May 16, 2023	SYSTEM	\$19,513.15 \$19,513.15	Payment Estimate Item Adjustment generated Stockpile Transaction						
			Construction	- Fotal 1 Stockpile S	IMI - Total			\$19,513.15							
			- Johnstruction	r otockpile 3	-mr- Total			ψ10,010.10							
	0500 -	Total						\$19,513.15							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J6S3532	0540	MISC.	Material			2023			Estimate Item Adjustment (0003) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					9	Jun 16, 2023	SYSTEM	(\$277,659.10)			
					10	Jul 3, 2023	SYSTEM	\$277,659.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user canadt2 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					10	Jul 3, 2023	SYSTEM	(\$277,659.10)			
					11	Jul 18, 2023	SYSTEM	\$277,659.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user canadt2 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					11	Jul 18, 2023	SYSTEM	(\$277,659.10)			
				- Total				\$0.00			
			Material - To	al				\$0.00	Estimate Item Adjustment (0003) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user canadt2 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user canadt2 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user canadt2 overridding Payment Estimate Item Adjustment (0006) due to user canadt2 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate.		
	0540 -	Total						\$0.00			
	0570	SUBSTRUCTURE REPAIR	Overrun	Overrun	6	May 2, 2023	SYSTEM	(\$1,444.85)			
		(FORMED)			11	Jul 18, 2023	SYSTEM	(\$3,178.67)			
				Overrun - To	otal			(\$4,623.52)	Estimate Item Adjustment (0003) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user canadt2 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user canadt2 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user canadt2 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user canadt2 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.		
			Overrun - To	tal				(\$4,623.52)			
	0570 -	Total						(\$4,623.52)			
	0600	MECHANICAL BAR SPLICE			10	Jul 3, 2023	SYSTEM	\$5,167.42	Estimate Item Adjustment (0005) due to user canadt2 overridding Payment		
					10	Jul 3, 2023	SYSTEM	(\$5,167.42)			
					11	Jul 18, 2023	SYSTEM	\$5,167.42	Estimate Item Adjustment (0006) due to user canadt2 overridding Payment		
					11	Jul 18, 2023	SYSTEM	(\$5,167.42)			
				- Total				\$0.00			
			Material - To	al							
	0600 -							\$0.00			
	0610	REINFORCING STEEL (EPOXY COATED)	Material		8	Jun 5, 2023	SYSTEM	\$8,400.00	Estimate Item Adjustment (0004) due to user sawyej2 overridding Payment		
					8	Jun 5, 2023	SYSTEM	(\$8,400.00)	This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user canadt2 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.		
					9	Jun 16, 2023	SYSTEM	\$8,400.00			
					9	Jun 16, 2023	SYSTEM	(\$8,400.00)			
					10	Jul 3, 2023	SYSTEM	\$8,400.00	Estimate Item Adjustment (0006) due to user canadt2 overridding Payment		
					10	Jul 3, 2023	SYSTEM	(\$8,400.00)			
					11	Jul 18, 2023	SYSTEM	\$16,195.20	Estimate Item Adjustment (0007) due to user canadt2 overridding Payment		
					11	Jul 18, 2023	SYSTEM	(\$16,195.20)			
				- Total							
			Material - To	al				\$0.00			
	0610 -	Total						\$0.00			
	0620	PROTECTIVE COATING - CONCRETE BENTS AND	Material		2	Mar 2, 2023	SYSTEM	\$5,137.38	Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment		



Droinot	Lino	Description	Adjustment	Other	Eat	Created	Created	Amount	Pamarka								
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J6S3532	6S3532 0620	PROTECTIVE COATING -	Material		2	Mar 2, 2023	SYSTEM	(\$5,137.38)									
		CONCRETE BENTS AND			3	Mar 16, 2023	SYSTEM	\$5,137.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					3	Mar 16, 2023	SYSTEM	(\$5,137.38)									
					4	Apr 3, 2023	SYSTEM	\$5,137.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					4	Apr 3, 2023	SYSTEM	(\$5,137.38)									
					5	Apr 17, 2023	SYSTEM	\$5,137.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					5	Apr 17, 2023	SYSTEM	(\$5,137.38)									
					6	May 2, 2023	SYSTEM	\$10,274.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sawyej2 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					6	May 2, 2023	SYSTEM	(\$10,274.77)									
					7	May 16, 2023	SYSTEM	\$10,274.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sawyej2 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					7	May 16, 2023	SYSTEM	(\$10,274.77)									
								8	Jun 5, 2023	SYSTEM	\$10,274.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Payment Estimate Exception 7 on the current Payment Estimate.					
					8	Jun 5, 2023	SYSTEM	(\$10,274.77)									
					9	Jun 16, 2023	SYSTEM	\$10,274.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Payment Estimate Exception 9 on the current Payment Estimate.								
													9	9	Jun 16, 2023	SYSTEM	(\$10,274.77)
					10	Jul 3, 2023	SYSTEM	\$10,274.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user canadt2 overridding Payment Estimate Exception 10 on the current Payment Estimate.								
						10	Jul 3, 2023	SYSTEM	(\$10,274.77)								
										11	11	Jul 18, 2023	SYSTEM	\$10,274.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user canadt2 overridding Payment Estimate Exception 10 on the current Payment Estimate.		
					11	Jul 18, 2023	SYSTEM	(\$10,274.77)									
				- Total				\$0.00									
			Material - To	tal				\$0.00									
	0620 -		Motorial		0	lup F	CVCTENA	\$0.00	This adjustment affects the original quoteen generated Material Desirem								
	0630	EXPANSION DEVICE (FINGER PLATE)	Material		8	Jun 5, 2023	SYSTEM	\$119,916.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sawyej2 overridding Payment Estimate Exception 8 on the current Payment Estimate.								
					9 10	9	8	Jun 5, 2023	SYSTEM	(\$119,916.40)							
									9	Jun 16, 2023	SYSTEM	\$119,916.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sawyej2 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
										10	9	Jun 16, 2023	SYSTEM	(\$119,916.40)			
												10	Jul 3, 2023	SYSTEM	\$119,916.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user canadt2 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
					10	Jul 3, 2023	SYSTEM	(\$119,916.40)									
					11	Jul 18,	SYSTEM	\$227,841.16	This adjustment offsets the original system-generated Material Payment								



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks		
J6S3532	0630	EXPANSION	Material	Туре		2023			Estimate Item Adjustment (0009) due to user canadt2 overridding Payment		
		DEVICE (FINGER PLATE)			11	Jul 18,	SYSTEM	(\$227,841.16)	Estimate Exception 11 on the current Payment Estimate.		
						2023					
			Metaviel To	- Total				\$0.00			
	2000		Material - To	tal				\$0.00			
	0630 -							\$0.00			
	0690	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		7	May 16, 2023	SYSTEM	(\$5,135.04)	Payment Estimate Item Adjustment generated Stockpile Transaction		
					8	Jun 5, 2023	SYSTEM	(\$5,135.04)	Payment Estimate Item Adjustment generated Stockpile Transaction		
					10	Jul 3, 2023	SYSTEM	(\$4,621.53)	Payment Estimate Item Adjustment generated Stockpile Transaction		
					11	Jul 18, 2023	SYSTEM	(\$4,621.54)	Payment Estimate Item Adjustment generated Stockpile Transaction		
				- Total				(\$19,513.15)			
			Construction	Stockpile - 1	<b>Total</b>			(\$19,513.15)			
			Construction Stockpile		7	May 16, 2023	SYSTEM	\$19,513.15	Payment Estimate Item Adjustment generated Stockpile Transaction		
			STMI	- Total				\$19,513.15			
			Construction		[M] - Total			\$19,513.15			
			Material	r otookpiio o	7	May 16,	SYSTEM	\$12,140.80	This adjustment offsets the original system-generated Material Payment		
			waterial		,	2023	STSTEM	\$12,140.00	Estimate Item Adjustment (0006) due to user sawyej2 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					7	May 16, 2023	SYSTEM	(\$12,140.80)			
					8	Jun 5, 2023	SYSTEM	\$24,281.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment Estimate Exception 9 on the current Payment Estimate.		
					8	Jun 5, 2023	SYSTEM	(\$24,281.60)			
					9	Jun 16, 2023	SYSTEM	\$24,281.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user sawyej2 overridding Payment Estimate Exception 11 on the current Payment Estimate.		
					9	Jun 16, 2023	SYSTEM	(\$24,281.60)			
					10	Jul 3, 2023	SYSTEM	\$35,208.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user canadt2 overridding Payment Estimate Exception 12 on the current Payment Estimate.		
					10	Jul 3, 2023	SYSTEM	(\$35,208.32)			
							11	Jul 18, 2023	SYSTEM	\$46,135.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user canadt2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					11	Jul 18, 2023	SYSTEM	(\$46,135.04)			
				- Total				\$0.00			
			Material - To	tal				\$0.00			
	0690 -	Total						\$0.00			
	5003	MISC. CONCRETE CONSTRUCTION	Material		9	Jun 16, 2023	SYSTEM	\$107,427.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user sawyej2 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					9	Jun 16, 2023	SYSTEM	(\$107,427.18)			
						10	Jul 3, 2023	SYSTEM	\$107,427.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user canadt2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					10	Jul 3, 2023	SYSTEM	(\$107,427.18)			
					11	Jul 18, 2023	SYSTEM	\$213,831.24	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user canadt2 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					11	Jul 18,	SYSTEM	(\$213,831.24)			

Jul 19, 2023



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3532	5003	MISC.				2023			
	CONCRETE CONSTRUCTION			- Total				\$0.00	
			Material - To	laterial - Total					
	5003 - Total								
J6S3532 -	- Total						\$174,618.63		
Overall -	Overall - Total								

# MoDOT

## Contract Adjustments for Contract - 221021-F07

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 13 of 13