#### Pay Estimate Created Date: July 17, 2023

Progress Estimate Nu 5			221216-D04 Capital Paving & Co	onstruction			23 Original Contract Amount 023 Net Change Order Amount Current Contract Amount	t (\$13,230.12)	
Approval Date								By User	
July 17, 2023			Generated and	Approved	d (and should be considere	d Draft) a	at the Project Office Level by	HOPKIM1	
July 17, 2023	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level								
July 18, 2023	23 Reviewed and Approved at the Central Office Controllers Office Level								
Original Completion	Current Co	mpletion Date	Act	ual Completion Date	Int Complete				
December 1, 202	23	Decemb	er 1, 2023				53.61%		
	Contract I	nformational Dat	es Milestones						
Date Description	Original C	Completion Date	Current Completion Date		No Milestones Exist for C	Contract			
Acceptance Date									
Awarded Date	January 4,	, 2023	January 4, 2023						
Letting Date	December	16, 2022	December 16, 202	2					
Notice to Proceed Date	February 6	6, 2023	February 6, 2023						
Open to Traffic Date									
Work Began Date	June 12, 2	2023	June 12, 2023						

#### Contract Total Pay For Estimate No. 5

Liquidated Damage Other Contract Adjustments	\$0.00 \$0.00	\$0.00 \$0.00 \$576,423.15	\$0.00 \$0.00 \$658,080.80
Liquidated Damage	\$0.00	\$0.00	\$0.00
		• • • •	-
Bioincontare	φ0.00	<b>\$0.00</b>	<b>\$</b> 0.00
Disincentive	\$0.00	\$0.00	\$0.00
Incentive	\$0.00	\$0.00	\$0.00
Gross Item Adjustments	(\$33,644.50)	\$5,861.30	(\$27,783.20)
Total Posted Items Pay	\$115,302.15	\$570,561.85	\$685,864.00
	This Estimate	Previous	To Date
	Gross Item Adjustments Incentive	Total Posted Items Pay\$115,302.15Gross Item Adjustments(\$33,644.50)Incentive\$0.00	Total Posted Items Pay         \$115,302.15         \$570,561.85           Gross Item Adjustments         (\$33,644.50)         \$5,861.30

## Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5S3510	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$10,000.000	0.2	\$2,000.00
	0020	2153000	SHAPING SLOPES, CLASS III	100F	\$500.000	1	\$500.00
	0030	6161005	CONSTRUCTION SIGNS	SQFT	\$10.000	24	\$240.00
	0100	6169901	MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	LS	\$30,000.000	0.2	\$6,000.00
	0130	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	LF	\$9.000	965	\$8,685.00
	0140	6181000	MOBILIZATION	LS	\$122,000.000	0.25	\$30,500.00
	0170	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	LF	\$2.000	1,400	\$2,800.00
	0180	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	LF	\$2.000	1,340	\$2,680.00
	0210	6207001	PAVEMENT MARKING REMOVAL	LF	\$2.500	500	\$1,250.00
	0290	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$4,500.000	1	\$4,500.00
	0320	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$3,650.000	1	\$3,650.00
	0430	7040113	CLEANING AND EPOXY COATING	SQFT	\$6.000	1,927	\$11,562.00
	0440	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	LS	\$8,000.000	0.4	\$3,200.00
	0550	7040113	CLEANING AND EPOXY COATING	SQFT	\$6.000	1,562	\$9,372.00
	0560	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	LS	\$8,000.000	0.4	\$3,200.00
	5005	4071005	TACK COAT	GAL	\$5.250	72	\$378.00
	5006	6189902	MISC.ASPHALT MOBILIZATION	EA	\$3,150.000	1	\$3,150.00
	5007	4019905	MISC.BITUMINOUS PAVEMENT MIXTURE	SQYD	\$25.730	515	\$13,250.95
	5008	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$16.280	515	\$8,384.20



#### Pay Estimate Created Date: July 17, 2023

Progress	Estimate   5	Number	Contract ID         221216-D04         Pay Period Start           Prime Contractor Capital Paving & Construction, LLC         Pay Period End		2023 Net Chan	ge Order Amou	t \$1,292,600.50 nt (\$13,230.12) t \$1,279,370.38				
Project Number	Line Number	Item Code	Item Description Unit Unit Price Current Unit Installed Qty								
Project J5	<mark>S3510 - To</mark>	tal					\$115,302.15				
Overall - Total \$11											
Contract Ad	ontract Adjustments This Estimate										

#### No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3510	0030	CONSTRUCTION SIGNS	Overrun			-24	\$10.00	(\$240.00
	0120	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	Material			-2	\$1,500.00	(\$3,000.00)
	0120	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user hopkim1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	2	\$1,500.00	\$3,000.00
	0170	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material			-4,020	\$2.00	(\$8,040.00)
	0170	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user hopkim1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	4,020	\$2.00	\$8,040.00
	0180	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Overrun			-375	\$2.00	(\$750.00)
	0180	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material			-3,850	\$2.00	(\$7,700.00)
	0180	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user hopkim1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	3,850	\$2.00	\$7,700.00
	0210	PAVEMENT MARKING REMOVAL	Overrun			-500	\$2.50	(\$1,250.00)
	0290	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$2,080.00)
	0320	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$1,875.00)
	0430	CLEANING AND EPOXY COATING	Material			-1,927	\$6.00	(\$11,562.00)
	0440	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material			-0.4	\$8,000.00	(\$3,200.00)
	0550	CLEANING AND EPOXY COATING	Material			-1,562	\$6.00	(\$9,372.00)
	0560	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material			-0.4	\$8,000.00	(\$3,200.00)
	5002	LATEX MODIFIED CONCRETE WEARING SURFACE	Material			-454	\$235.46	(\$106,898.84)
	5002	LATEX MODIFIED CONCRETE WEARING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	454	\$235.46	\$106,898.84



#### Pay Estimate Created Date: July 17, 2023

Progre	ss Estir 5	nate Number	Contract ID Prime Contra	221216-D <b>ctor</b> Capital Pa		Pay Period Start July 1, 2023 Ori ruction, LLC Pay Period End July 15, 2023 Ne Cu		ler Amount (	\$1,292,600.50 \$13,230.12) \$1,279,370.38
Project Number	Line No.	Item Des	scription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3510			SURFACE			Adjustment (0021) due to user hopkim1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
	CONCRETE WI		EX MODIFIED TE WEARING SURFACE	Material			-456	\$235.46	(\$107,369.76)
	5004		EX MODIFIED TE WEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user hopkim1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	456	\$235.46	\$107,369.76
	5005		TACK COAT	Overrun			-22	\$5.25	(\$115.50)
	5005		TACK COAT	Material			-72	\$5.25	(\$378.00)
5005 TAC			TACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user hopkim1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	72	\$5.25	\$378.00
Total	· · ·								(\$33,644.50)



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Con	tract Project Informat	on		
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work		
J5S3510	FAS- S402(096)     Bridge rehabilitation     Y     PULASKI     over I-44 in Pulaski County								
Totals by J	Job Number	s							
J5S3510		ltem Pay Item Adjustme		Item Pay	This Estimate \$115,302.15 (\$33,644.50) <b>\$81,657.65</b>	Previous \$570,561.85 \$5,861.30 \$576,423.15	To Date \$685,864.00 (\$27,783.20) \$658,080.80		
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00		



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Ferrou			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3510, Item 4071005, Project Item Line Number 5005, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Working with Materials to resolve this exception.	HOPKIM1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3510, Item 5052000, Project Item Line Number 5002, Material Set 505200096, Material 1054CXLE - Latex Emulsion Admixture @, Acceptance Action Generic 1054CXLE is insufficient.	Awaiting 28 day results to resolve this exception.	HOPKIM1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3510, Item 5052000, Project Item Line Number 5002, Material Set 505200096, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	Working with the contractor to identify the PAL record for this material.	HOPKIM1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3510, Item 5052000, Project Item Line Number 5004, Material Set 505200096, Material 1054CXLE - Latex Emulsion Admixture @, Acceptance Action Generic 1054CXLE is insufficient.	Awaiting 28 day results to resolve this exception.	HOPKIM1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3510, Item 5052000, Project Item Line Number 5004, Material Set 505200096, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	Working with the contractor to identify the PAL record for this material.	HOPKIM1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3510, Item 6174000A, Project Item Line Number 0120, Material Set 6174000A96, Material 0617MBPKBT.1PC - One Piece Barrier Height-Transition Sect, Acceptance Action Generic 0617MBPKBT.1PC is insufficient.	There are two options for material, and the testing for the one not chosen needs to be eliminated. Working with Materials to resolve this exception.	HOPKIM1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3510, Item 6205301B, Project Item Line Number 0170, Material Set 6205301B96, Material 1048PMRPMTWH - Marking Tape Removable White, Acceptance Action Generic 1048PMRPMTWH is insufficient.	Certifications have been submitted, but both paint and tape were used to do this work. Working with Materials to resolve this exception.	HOPKIM1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3510, Item 6205303B, Project Item Line Number 0180, Material Set 6205303B96, Material 1048PMRPMTYL - Marking Tape Removable Yellow, Acceptance Action Generic 1048PMRPMTYL is insufficient.	Certifications have been submitted, but both paint and tape were used to do this work. Working with Materials to resolve this exception.	HOPKIM1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3510, Item 7040113, Project Item Line Number 0430, Material Set 704011396, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	Certifications needed for this material. Working with the contractor to resolve this exception.	HOPKIM1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5S3510, Item 7040113, Project Item Line Number 0550, Material Set 704011396, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	Certifications needed for this material. Working with the contractor to resolve this exception.	HOPKIM1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5S3510, Item 7110200, Project Item Line Number 0440, Material Set 711020096, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	Certifications needed for this material. Working with the contractor to resolve this exception.	HOPKIM1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5S3510, Item 7110200, Project Item Line Number 0560, Material Set 711020096, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	Certifications needed for this material. Working with the contractor to resolve this exception.	HOPKIM1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 221216-D04, Contract Project J5S3510, Project Item Line Number 0030, Contract Line Item Number 0030, Item 6161005, Minor Item.	A change order is needed to resolve this exception.	HOPKIM1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 221216-D04, Contract Project J5S3510, Project Item Line Number 0180, Contract Line Item Number 0180, Item 6205303B, Minor Item.	A change order is needed to resolve this exception.	HOPKIM1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 221216-D04, Contract Project J5S3510, Project Item Line Number 0210, Contract Line Item Number 0210, Item 6207001, Minor Item.	A change order is needed to resolve this exception.	HOPKIM1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 221216-D04, Contract Project J5S3510, Project Item Line Number 5005, Contract Line Item Number 5005, Item 4071005, Minor Item.	A change order is needed to resolve this exception.	HOPKIM1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 221216-D04, Contract Project J5S3510, Project Item Line Number 0060, Contract Line Item Number 0060, Item 6161025, Minor Item.	A change order is needed to resolve this exception.	HOPKIM1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 221216-D04, Contract Project J5S3510, Project Item Line Number 0090, Contract Line Item Number 0090, Item 6161098A, Minor Item.	A change order is needed to resolve this exception.	HOPKIM1	Acknowledged

#### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

### Total Paid / All Items / All Estimates (Including this Estimate)

lotar ratio / An terms / An Estimates (including units Estimate) lote: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted amo	ount at th	e time the	Estimate w	as Gene	erated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
221216-D04	J5S3510	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.20	\$10,000.00	\$2,000.00
		0001	0020	2153000	SHAPING SLOPES, CLASS III	5.00	0.00	5.00	100F	1.00	\$500.00	\$500.00
		0001	0030	6161005	CONSTRUCTION SIGNS	646.00	0.00	646.00	SQFT	939.00	\$10.00	\$9,390.00
		0001	0040	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$100.00	\$400.00
		0001	0050	6161010	RELOCATED SIGNS	154.00	0.00	154.00	SQFT	0.00	\$10.00	\$0.00
		0001	0060	6161025	CHANNELIZER (TRIM LINE)	220.00	0.00	220.00	EA	275.00	\$25.00	\$6,875.00
		0001	0070	6161030	TYPE III MOVEABLE BARRICADE	29.00	0.00	29.00	EA	29.00	\$225.00	\$6,525.00
		0001	0080	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	4.00	\$1,000.00	\$4,000.00
		0001	0090	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	3.00	\$4,500.00	\$13,500.00
		0001	0100	6169901	MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	1.00	0.00	1.00	LS	0.80	\$30,000.00	\$24,000.00
		0001	0110	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,000.00	0.00	1,000.00	LF	975.00	\$19.00	\$18,525.00
		0001	0120	6174000A	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
		0001	0130	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	1,000.00	0.00	1,000.00	LF	965.00	\$9.00	\$8,685.00
		0001	0140	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$122,000.00	\$122,000.00
		0001	0150	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	165.00	0.00	165.00	LF	0.00	\$28.00	\$0.00
		0001	0160	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	3.00	0.00	3.00	EA	0.00	\$350.00	\$0.00
		0001	0170	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	4,550.00	0.00	4,550.00	LF	4,020.00	\$2.00	\$8,040.00
		0001	0180	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	3,475.00	0.00	3,475.00	LF	3,850.00	\$2.00	\$7,700.00
		0001	0190	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	5,185.00	0.00	5,185.00	LF	0.00	\$1.20	\$0.00
		0001	0200	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,020.00	0.00	1,020.00	LF	0.00	\$1.40	\$0.00
		0001	0210	6207001	PAVEMENT MARKING REMOVAL	1,300.00	0.00	1,300.00	LF	1,930.00	\$2.50	\$4,825.00
		0001	0220	8025006	MULCHING	0.30	0.00	0.30	ACRE	0.00	\$10,000.00	\$0.00
		0001	0230	8051000A	SEEDING - COOL SEASON GRASSES	0.30	0.00	0.30	ACRE	0.00	\$10,000.00	\$0.00
		0001	0240	8061006	ALTERNATE DITCH CHECK	40.00	0.00	40.00	LF	0.00	\$11.50	\$0.00
		0001	0250	8061016	SEDIMENT REMOVAL	9.00	0.00	9.00	CUYD	0.00	\$15.00	\$0.00
		0001	0260	8061019	SILT FENCE	470.00	0.00	470.00	LF	0.00	\$3.20	\$0.00
		0010	0270	6061010	GUARDRAIL TYPE A	125.00	0.00	125.00	LF	0.00	\$40.00	\$0.00
		0010	0280	6061060	MGS GUARDRAIL	75.00	0.00	75.00	LF	0.00	\$39.00	\$0.00
		0010	0290	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	2.00	0.00	2.00	EA	1.00	\$4,500.00	\$4,500.00
		0010	0300	6062200A	BRIDGE ANCHOR SECTION, 6.5 FT. POSTS (SAFETY BARRIER CURB) (ROADWAY AND REHABILITATION WORK ONLY)	2.00	0.00	2.00	EA	0.00	\$3,250.00	\$0.00
		0010	0310	6062303	ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS	2.00	0.00	2.00	EA	0.00	\$710.00	\$0.00
		0010	0320	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	1.00	\$3,650.00	\$3,650.00
		0030	0330	9029902	MISC.VIDEO DETECTION SYSTEM	1.00	0.00	1.00	EA	1.00	\$32,000.00	\$32,000.00
		0070	0340	2161001	TOTAL SURFACE HYDRO DEMOLITION	949.00	0.00	949.00	SQYD	478.00	\$77.00	\$36,806.00
		0070	0350	2161502	REMOVAL OF CONCRETE WEARING SURFACE	8,543.00	0.00	8,543.00	SQFT	4,306.00	\$2.75	\$11,841.50
		0070	0360	2161503	REMOVAL OF EXISTING DECK REPAIR	132.00	0.00	132.00	SQFT	53.00	\$35.00	\$1,855.00
		0070	0370	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	8.00	-8.00	0.00	CY	0.00	\$900.00	\$0.00
		0070	0380	5054000	LATEX MODIFIED VERY EARLY STRENGTH CONCRETE WEARING SURFACE	949.00	-949.00	0.00	SQYD	0.00	\$255.00	\$0.00
		0070	0390	7031004	DIAMOND GRINDING	949.00	-949.00	0.00	SQYD	0.00	\$12.00	\$0.00
		0070	0400	7040104	HALF-SOLE REPAIR	650.00	0.00	650.00	SQFT	119.00	\$70.00	\$8,330.00
		0070	0410	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$125.00	\$0.00
		0070	0420	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	350.00	0.00	350.00	SQFT	0.00	\$110.00	\$0.00
		0070	0430	7040113	CLEANING AND EPOXY COATING	1,984.00	0.00	1,984.00	SQFT	1,927.00	\$6.00	\$11,562.00



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
221216-D04	J5S3510	0070	0440	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.40	\$8,000.00	\$3,200.00
		0071	0450	2161001	TOTAL SURFACE HYDRO DEMOLITION	949.00	0.00	949.00	SQYD	481.00	\$77.00	\$37,037.00
		0071	0460	2161502	REMOVAL OF CONCRETE WEARING SURFACE	8,543.00	0.00	8,543.00	SQFT	4,325.00	\$2.75	\$11,893.75
		0071	0470	2161503	REMOVAL OF EXISTING DECK REPAIR	131.00	0.00	131.00	SQFT	128.00	\$35.00	\$4,480.00
		0071	0480	2169903	MISC.Remove and Replace Barrier	5.00	0.00	5.00	LF	0.00	\$3,000.00	\$0.00
		0071	0490	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	8.00	-8.00	0.00	CY	0.00	\$900.00	\$0.00
		0071	0500	5054000	LATEX MODIFIED VERY EARLY STRENGTH CONCRETE WEARING SURFACE	949.00	-949.00	0.00	SQYD	0.00	\$255.00	\$0.00
		0071	0510	7031004	DIAMOND GRINDING	949.00	-949.00	0.00	SQYD	0.00	\$12.00	\$0.00
		0071	0520	7040104	HALF-SOLE REPAIR	650.00	0.00	650.00	SQFT	261.00	\$70.00	\$18,270.00
		0071	0530	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$125.00	\$0.00
		0071	0540	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	350.00	0.00	350.00	SQFT	0.00	\$110.00	\$0.00
		0071	0550	7040113	CLEANING AND EPOXY COATING	1,984.00	0.00	1,984.00	SQFT	1,562.00	\$6.00	\$9,372.00
		0071	0560	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.40	\$8,000.00	\$3,200.00
		0070	5001	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	0.00	8.00	8.00	CY	6.00	\$700.00	\$4,200.00
		0070	5002	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	0.00	949.00	949.00	SQYD	454.00	\$235.46	\$106,898.84
		0071	5003	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	0.00	8.00	8.00	CY	6.10	\$700.00	\$4,270.00
		0071	5004	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	0.00	949.00	949.00	SQYD	456.00	\$235.46	\$107,369.76
		0001	5005	4071005	TACK COAT	0.00	50.00	50.00	GAL	72.00	\$5.25	\$378.00
		0001	5006	6189902	MISC.ASPHALT MOBILIZATION 0.00 2.00 2.00 EA 1.00 \$3,						\$3,150.00	\$3,150.00
		0001	5007	4019905	MISC.BITUMINOUS PAVEMENT MIXTURE         0.00         1,030.00         1,030.00         SQYD						\$25.73	\$13,250.95
		0001	5008	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	0.00	1,030.00	1,030.00	SQYD	515.00	\$16.28	\$8,384.20
	Project J	5S3510 - To	otal Value	e Posted to I	Date as of Report Generated Date							\$685,864.00
221216-D04 Ove	erall - Total	Value Pos	ted to Da	te as of Rep	ort Generated Date							\$685,864.00



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	7/5/23	7/14/23	0.20	LS	RTYS	6.679	LT	6.695	LT	Removal of existing guardrail at SE corner of A08023.
0020	2153000	SHAPING SLOPES, CLASS III	7/5/23	7/14/23	1.00	100F	RTYS	6.679	LT	6.695	LT	Grading for guardrail at SE corner of A08023.
0030	6161005	CONSTRUCTION SIGNS	7/10/23	7/17/23	24.00	SQFT	IS 44	Various				Movable Signs (for IS 44 lane drops): 2 EA - Gore Exit (12SQFT/EA) = 24 SQFT
0100	6169901	MISC.	7/13/23	7/17/23	0.20	LS	IS 44 W	130.635				Third installment, after 30 days of operation, per JSP K.
0130	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	7/13/23	7/17/23	357.50	LF	RTYN	0.008		0.072		Relocate temporary barrier for Phase 2. Barrier plus transition. 337.5 + 20 = 357.5
				7/17/23	607.50	LF	RTYS	6.581		6.692		Relocate temporary barrier for Phase 2. Barrier plus transition. 587.5 + 20 = 607.5
0140	6181000	MOBILIZATION	7/14/23	7/17/23	0.25	LS	RTY					Four partial payment after completion of 50% of the contract value. Since the item value was less than 10% of the contract, this will be the final payment.
0170	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	7/13/23	7/17/23	1,400.00	LF	Various	Various				Temporary stripe for Phase 2.
0180	6205303B	TEMPORARY REMOVABLE MARKING TAPE	7/13/23	7/17/23	1,340.00	LF	Various	Various				Temporary stripe for Phase 2.
0210	6207001	PAVEMENT MARKING REMOVAL	7/13/23	7/17/23	500.00	LF	Various	Various				Removals for Phase 2.
0290	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	7/11/23	7/17/23	1.00	EA	RT Y S	6.679	LT	6.695	LT	Guardrail at SE corner of bridge A08023.
0320	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	7/11/23	7/17/23	1.00	EA	RTYS	6.679	LT	6.695	LT	Guardrail at SE corner of bridge A08023.
0430	7040113	CLEANING AND EPOXY COATING	7/11/23	7/17/23	158.00	SQFT	RTYN	0.022		0.064		NB Bridge A08023, 35' X 4.5' = 158 SQFT.
			7/12/23	7/17/23	675.00	SQFT	RTYN	0.022		0.064		NB Bridge A08023, 150' X 4.5' = 675 SQFT.
			7/13/23	7/17/23	1,094.00	SQFT	RTYN	0.022		0.064		NB Bridge A09023, all but 2 small pieces have been completed. 1984 SQFT - 675 SQFT - 158 SQFT - 10' x 4.5' - 5' x 2.5' = 1094 SQFT
0440	7110200	PROTECTIVE COATING - CONCRETE BENTS AND	7/11/23	7/17/23	0.40	LS	RTYN	0.022		0.064		NB Bridge A08023, columns and barrier wall under bent 4. Estimated as 40% of the total area.
0550	7040113	CLEANING AND EPOXY COATING	7/11/23	7/17/23	720.00	SQFT	RTYS	6.637		6.679		SB Bridge A08024, 160' X 4.5' = 720 SQFT.
			7/12/23	7/17/23	135.00	SQFT	RTYS	6.637		6.679		SB Bridge A08024, 30' X 4.5' = 135 SQFT.
			7/13/23	7/17/23	707.00	SQFT	RTYS	6.637		6.679		SB Bridge A09024, all but 2 areas have been completed. 1984 SQFT - 720 SQFT - 135 SQFT - 55' x 2' - 125' x 2.5 = 707 SQFT
0560	7110200	PROTECTIVE COATING - CONCRETE BENTS AND	7/11/23	7/17/23	0.40	LS	RTYS	6.637		6.679		SB Bridge A08024, columns and barrier wall under bent 4 Estimated as 40% of the total area.
5005	4071005	TACK COAT	7/10/23	7/17/23	72.00	GAL	RTYN	0		0.085		Tack for additional asphalt work in Phase 1. All four corners.
5006	6189902	MISC.	7/10/23	7/17/23	1.00	EA	RTYN	0				Mobilization for additional asphalt work in Phase 1. All four corners.
5007	4019905	MISC.	7/10/23	7/17/23	515.00	SQYD	RTYN	0		0.085		Asphalt for additional asphalt work in Phase 1. All four corners.
5008	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	7/10/23	7/17/23	515.00	SQYD	RTYN	0		0.085		Milling for additional asphalt work in Phase 1. All four corners.

The information below this line are details for Construction Signs (if applicable), No Data Available



Jul 19, 2023

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
5S3510	0030	CONSTRUCTION SIGNS	Overrun	Overrun	3	Jun 16, 2023	SYSTEM	(\$2,690.00)			
					5	Jul 17, 2023	SYSTEM	(\$240.00)			
				Overrun - T	otal	1		(\$2,930.00)			
			Overrun - To	tal				(\$2,930.00)			
	0030 -	Total						(\$2,930.00)			
	0060	CHANNELIZER (TRIM LINE)	Overrun	Overrun	3	Jun 16, 2023	SYSTEM	(\$1,375.00)			
				Overrun - T	otal			(\$1,375.00)			
			Overrun - To	tal				(\$1,375.00)			
	0060 -	Total						(\$1,375.00)			
	0090	COMMUNICATION	Overrun	Overrun	2	Jun 2, 2023	SYSTEM	(\$4,500.00)			
		INTERFACE, CONT F/		Overrun - T	otal			(\$4,500.00)			
			Overrun - Total					(\$4,500.00)			
	0090 -	Total						(\$4,500.00)			
	0120	TEMP. TRAFFIC BARRIER HEIGHT TRANSITION	Material		3	Jun 16, 2023	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hopkin1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					3	Jun 16, 2023	SYSTEM	(\$3,000.00)			
					4	Jun 30, 2023	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hopkim1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
					4	Jun 30, 2023	SYSTEM	(\$3,000.00)			
							5	Jul 17, 2023	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hopkim1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Jul 17, 2023	SYSTEM	(\$3,000.00)			
				- Total				\$0.00			
			Material - Tot	tal				\$0.00			
	0120 -	Total						\$0.00			
	0170	TEMPORARY REMOVABLE MARKING TAPE 4	Material		4	Jun 30, 2023	SYSTEM	\$5,240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hopkim1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
		IN.,			4	Jun 30, 2023	SYSTEM	(\$5,240.00)			
					5	Jul 17, 2023	SYSTEM	\$8,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hopkim1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
					5	Jul 17, 2023	SYSTEM	(\$8,040.00)			
				- Total				\$0.00			
			Material - Tot	tal				\$0.00			
	0170 -	Total						\$0.00			
	0180	TEMPORARY REMOVABLE MARKING TAPE	Material		4	Jun 30, 2023	SYSTEM	\$5,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hopkim1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
					4	Jun 30, 2023	SYSTEM	(\$5,020.00)			
					5	Jul 17, 2023	SYSTEM	\$7,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hopkim1 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
					5	Jul 17, 2023	SYSTEM	(\$7,700.00)			
				- Total				\$0.00			
			- Total				\$0.00				
			Overrun	Overrun	5	Jul 17,	SYSTEM	(\$750.00)			
						2023		,			



Jul 19, 2023

t I	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
10 0	0180	TEMPORARY	Overrun Overrun - Total					(\$750.00)	
		REMOVABLE MARKING TAPE	Overrun - Total					(\$750.00)	
C	0180 -	Total						(\$750.00)	
C	0200	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Overrun	Overrun	3	Jun 16, 2023	SYSTEM	(\$2,086.00)	
					4	Jun 30, 2023	SYSTEM	\$2,086.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1.40000 - 1.40000, 'is applied (if non-zero).
			Overrun - Total					\$0.00	
		Overrun - Total						\$0.00	
0	0200 -	Total						\$0.00	
C	0210	PAVEMENT MARKING REMOVAL	Overrun	Overrun		Jun 16, 2023	SYSTEM	(\$325.00)	
					5	Jul 17, 2023	SYSTEM	(\$1,250.00)	
			Overrun - Total					(\$1,575.00)	
			Overrun - To	tal				(\$1,575.00)	
	0210 -							(\$1,575.00)	
C	0270	GUARDRAIL TYPE A	Construction Stockpile STMI		1	Mar 16, 2023	SYSTEM	\$1,821.55	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,821.55	
			Construction	Stockpile S	TMI - Total			\$1,821.55	
	0270 -						-	\$1,821.55	
	0280 MGS GUARDRAIL	MGS GUARDRAIL	Construction Stockpile STMI		1	Mar 16, 2023	SYSTEM	\$1,149.75 \$1,149.75	Payment Estimate Item Adjustment generated Stockpile Transaction
		Ormethoustion		- Total					
		<b>T</b> -4-1	Construction	Stockpile S	IMI - Iotal			\$1,149.75	
		) - Total						\$1,149.75	Devenuest Estimate Item Adjustment concreted Stealwile Transaction
	0290	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile	- Total	5	Jul 17, 2023	SYSTEM	(\$2,080.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	n Stockpile - Total				(\$2,080.00)	
			Construction		1	Mar 16,	SYSTEM	\$4,160.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Stockpile STMI	- Total		2023		\$4,160.00	
			Construction	Stockpile STMI - Total				\$4,160.00	
C	0290 -	Total						\$2,080.00	
C	0300	BRIDGE ANCHOR SECTION, 6 5 FT. POSTS	FT. Stockpile		1	Mar 16, 2023	SYSTEM	\$3,440.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$3,440.00	
			Construction Stockpile STMI - Total					\$3,440.00	
C	0300 -	Total						\$3,440.00	
C	0310	ASYMMETRICAL TRNS. SEC., 6.5 FT. POSTS	Stockpile		1	Mar 16, 2023	SYSTEM	\$430.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$430.00	
			Construction	Stockpile S	ockpile STMI - Total				
C	0310 -	Total						\$430.00	
(	0320	CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		5	Jul 17, 2023	SYSTEM	(\$1,875.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$1,875.00)	
			Construction	Stockpile - 1	Fotal			(\$1,875.00)	
			Construction Stockpile		1	Mar 16, 2023	SYSTEM	\$3,750.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$3,750.00	
	0320 -		STMI	- Total Stockpile S <sup>-</sup>	TMI - Total			\$3,750.00 \$3,750.00 \$1,875.00	



Jul 19, 2023

ject	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
3510	0430	CLEANING AND EPOXY COATING	Material		5	Jul 17, 2023	SYSTEM	(\$11,562.00)	
							(\$11,562.00)		
			Material - To	tal				(\$11,562.00)	
	0430 -	- Total						(\$11,562.00)	
	0440	PROTECTIVE COATING - CONCRETE BENTS AND			5	Jul 17, 2023	SYSTEM	(\$3,200.00)	
				- Total				(\$3,200.00)	
			Material - To				(\$3,200.00)		
	0440 -							(\$3,200.00)	
	0550	CLEANING AND EPOXY COATING	Material		5	Jul 17, 2023	SYSTEM	(\$9,372.00)	
				- Total				(\$9,372.00)	
			Material - Total					(\$9,372.00)	
	0550 -							(\$9,372.00)	
	0560	PROTECTIVE COATING - CONCRETE	Material		5	Jul 17, 2023	SYSTEM	(\$3,200.00)	
		BENTS AND			- Total			(\$3,200.00)	
			Material - To	tal				(\$3,200.00)	
	0560 -	Total						(\$3,200.00)	
	5002	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		4	Jun 30, 2023	SYSTEM	\$106,898.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hopkim1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jun 30, 2023	SYSTEM	(\$106,898.84)	
					5	Jul 17, 2023	SYSTEM	\$106,898.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hopkim1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Jul 17, 2023	SYSTEM	(\$106,898.84)	
				- Total	- Total			\$0.00	
			Material - To	tal				\$0.00	
		Total							
	5002 -					_	_	\$0.00	
	<b>5002</b> - 5004	LATEX MODIFIED CONCRETE WEARING	Material		4	Jun 30, 2023	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hopkim1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		CONCRETE	Material		4		SYSTEM	\$0.00	Estimate Item Adjustment (0006) due to user hopkim1 overridding Payment
		CONCRETE WEARING	Material			2023 Jun 30,		<b>\$0.00</b> \$107,369.76	Estimate Item Adjustment (0006) due to user hopkim1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
		CONCRETE WEARING	Material		4	2023 Jun 30, 2023 Jul 17,	SYSTEM	\$0.00 \$107,369.76 (\$107,369.76)	Estimate Item Adjustment (0006) due to user hopkim1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hopkim1 overridding Payment
		CONCRETE WEARING	Material	- Total	4	2023 Jun 30, 2023 Jul 17, 2023 Jul 17,	SYSTEM SYSTEM	\$0.00 \$107,369.76 (\$107,369.76) \$107,369.76	Estimate Item Adjustment (0006) due to user hopkim1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hopkim1 overridding Payment
		CONCRETE WEARING	Material Material - To		4	2023 Jun 30, 2023 Jul 17, 2023 Jul 17,	SYSTEM SYSTEM	\$0.00 \$107,369.76 (\$107,369.76) \$107,369.76 (\$107,369.76)	Estimate Item Adjustment (0006) due to user hopkim1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hopkim1 overridding Payment
		CONCRETE WEARING SURFACE			4	2023 Jun 30, 2023 Jul 17, 2023 Jul 17,	SYSTEM SYSTEM	\$0.00 \$107,369.76 (\$107,369.76) \$107,369.76 (\$107,369.76) \$0.00	Estimate Item Adjustment (0006) due to user hopkim1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hopkim1 overridding Payment
I	5004	CONCRETE WEARING SURFACE	Material - To		4	2023 Jun 30, 2023 Jul 17, 2023 Jul 17,	SYSTEM SYSTEM	\$0.00 \$107,369.76) (\$107,369.76) \$107,369.76 (\$107,369.76) (\$107,369.76) \$0.00	Estimate Item Adjustment (0006) due to user hopkim1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hopkim1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	5004 5004 -	CONCRETE WEARING SURFACE	Material - To		4 5 5	2023 Jun 30, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17, 2023	SYSTEM SYSTEM SYSTEM	\$0.00 \$107,369.76) (\$107,369.76) \$107,369.76) (\$107,369.76) (\$107,369.76) \$0.00	Estimate Item Adjustment (0006) dué to user hopkim1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hopkim1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
I	5004 5004 -	CONCRETE WEARING SURFACE	Material - To		4 5 5 5 5 5	2023 Jun 30, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17,	SYSTEM SYSTEM SYSTEM	\$0.00 \$107,369.76) (\$107,369.76) \$107,369.76 (\$107,369.76) (\$107,369.76) \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user hopkim1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hopkim1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
I	5004 5004 -	CONCRETE WEARING SURFACE	Material - To	tal - Total	4 5 5 5 5 5	2023 Jun 30, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17,	SYSTEM SYSTEM SYSTEM	\$0.00 \$107,369.76) (\$107,369.76) \$107,369.76 (\$107,369.76) (\$107,369.76) \$0.00 \$0.00 \$0.00 \$378.00 (\$378.00)	Estimate Item Adjustment (0006) due to user hopkim1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hopkim1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	5004 5004 -	CONCRETE WEARING SURFACE	Material - To Material	tal - Total	4 5 5 5 5 5	2023 Jun 30, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17,	SYSTEM SYSTEM SYSTEM	\$0.00 \$107,369.76) (\$107,369.76) (\$107,369.76) (\$107,369.76) (\$107,369.76) \$0.00 \$0.00 \$0.00 (\$378.00) (\$378.00)	Estimate Item Adjustment (0006) due to user hopkim1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hopkim1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
I	5004 5004 -	CONCRETE WEARING SURFACE	Material - To Material Material - To	tal - Total tal	4 5 5 5 5 5 5	2023 Jun 30, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$107,369.76) (\$107,360.76) (\$107,360.76)\\(\$107,360.76)\\(\$107,360.7	Estimate Item Adjustment (0006) due to user hopkim1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hopkim1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	5004 5004 -	CONCRETE WEARING SURFACE	Material - To Material Material - To	tal - Total tal Overrun - T	4 5 5 5 5 5 5	2023 Jun 30, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$107,369.76) (\$107,369.76) (\$107,369.76) (\$107,369.76) (\$107,369.76) (\$107,369.76) (\$107,369.76) (\$107,369.76) (\$115.50)	Estimate Item Adjustment (0006) dué to user hopkim1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hopkim1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	5004 5004 -	Total TACK COAT	Material - To Material Material - To Overrun	tal - Total tal Overrun - T	4 5 5 5 5 5 5	2023 Jun 30, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17, 2023 Jul 17, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$107,369.76) (\$107,369.76) \$107,369.76) (\$107,369.76) (\$107,369.76) \$0.00 \$0.00 \$0.00 \$378.00 \$378.00 \$378.00 \$378.00 \$0.00	Estimate Item Adjustment (0006) due to user hopkim1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hopkim1 overridding Payment Estimate Exception 5 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Overall - Total									



There are no contract adjustments to display for this contract.