

#### **Missouri Department of Transportation Contractor's Pay Estimate Summary**

Pay Estimate Created Date: October 16, 2023

| Progress Estimate Number | Contract ID     | 221216-H01       | Pay Period StartOctober 1, 2023 Original Contract Amount \$5,325,000.00           |
|--------------------------|-----------------|------------------|---|
| 9                        | Prime Contracto | orPace Construct | ion Company, LLCPay Period End October 15, 2023Net Change Order Amount\$55,400.00 |
| 9                        |                 |                  | Current Contract Amount \$5,380,400.00  |

| Approval Date    |  | By User |
|------------------|--|---------|
| October 16, 2023 | Generated and Approved (and should be considered Draft) at the Project Office Level by   | WILESR  |
| October 16, 2023 | Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by | PULLIA  |
| October 17, 2023 | Reviewed and Approved at the Central Office Controllers Office Level by                  | ramses1 |

| Original Completion Date | Current Completion Date | Actual Completion Date | % of Current Contract Amount Complete |
|--------------------------|-------------------------|------------------------|---------------------------------------|
| November 1, 2023         | November 1, 2023        |                        | 97.47%                                |

|                        | Milestones               |                                |                                  |
|------------------------|--------------------------|--------------------------------|----------------------------------|
| Date Description       | Original Completion Date | <b>Current Completion Date</b> | No Milestones Exist for Contract |
| Acceptance Date        |                          |                                |                                  |
| Awarded Date           | January 4, 2023          | January 4, 2023                |                                  |
| Letting Date           | December 16, 2022        | December 16, 2022              |                                  |
| Notice to Proceed Date | February 6, 2023         | February 6, 2023               |                                  |
| Open to Traffic Date   |                          |                                |                                  |
| Work Began Date        |                          |                                |                                  |

| Contract Total Pay For Estimate No. 9 |                            |               |                |                |  |  |  |  |  |  |
|---------------------------------------|----------------------------|---------------|----------------|----------------|--|--|--|--|--|--|
|                                       |                            | This Estimate | Previous       | To Date        |  |  |  |  |  |  |
| 221216-H01                            |                            |               |                |                |  |  |  |  |  |  |
|                                       | Total Posted Items Pay     | \$323,362.10  | \$4,920,836.37 | \$5,244,198.47 |  |  |  |  |  |  |
|                                       | Gross Item Adjustments     | \$0.00        | (\$88,534.45)  | (\$88,534.45)  |  |  |  |  |  |  |
|                                       | Incentive                  | \$0.00        | \$0.00         | \$0.00         |  |  |  |  |  |  |
|                                       | Disincentive               | \$0.00        | \$0.00         | \$0.00         |  |  |  |  |  |  |
|                                       | Liquidated Damage          | \$0.00        | \$0.00         | \$0.00         |  |  |  |  |  |  |
|                                       | Other Contract Adjustments | \$0.00        | \$0.00         | \$0.00         |  |  |  |  |  |  |
|                                       |                            |               | \$4,832,301.92 | \$5,155,664.02 |  |  |  |  |  |  |
| <b>Contract Total Pa</b>              | ayable This Estimate:      | \$323,362,10  |                |                |  |  |  |  |  |  |

#### Items Paid This Estimate Period

| Project<br>Number | Line<br>Number | Item<br>Code | Item Description   | Unit | Unit Price  | Current<br>Installed Qty | Current Installed<br>Amount |
|-------------------|----------------|--------------|--|------|-------------|--------------------------|-----------------------------|
| J9P3599           | 0030           | 2129900      | MISC.SHOULDER GRADING  | 100F | \$765.000   | 180                      | \$137,700.00                |
|                   | 0150           | 6113010      | FURNISHING TYPE 1 ROCK BLANKET   | CUYD | \$1.000     | 25.7                     | \$25.70                     |
|                   | 0160           | 6113030      | PLACING TYPE 1 ROCK BLANKET  | CUYD | \$75.000    | 25.7                     | \$1,927.50                  |
|                   | 0260           | 6261000A     | BITUMINOUS SHOULDER RUMBLE STRIP   | STA  | \$23.000    | 703.8                    | \$16,187.40                 |
|                   | 0270           | 6274000      | CONTRACTOR FURNISHED SURVEYING AND STAKING                                     | LS   | \$4,000.000 | 1                        | \$4,000.00                  |
|                   | 0380           | 8025006      | MULCHING   | ACRE | \$1,650.000 | 16.8                     | \$27,720.00                 |
|                   | 0390           | 8051000A     | SEEDING - COOL SEASON GRASSES  | ACRE | \$2,950.000 | 16.8                     | \$49,560.00                 |
|                   | 0460           | 9031270A     | 2 IN. PSST POST - 12 GA.   | LF   | \$19.880    | 1,860                    | \$36,976.80                 |
|                   | 0470           | 9031271A     | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.                                     | EA   | \$69.290    | 155                      | \$10,739.95                 |
|                   | 0480           | 9035004A     | SH-FLAT SHEET  | SQFT | \$45.950    | 465                      | \$21,366.75                 |
| Project J9        | P3599 - To     | tal          |  |      |             |                          | \$306,204.10                |
| J9S3379           | 0490           | 2022010      | REMOVAL OF IMPROVEMENTS  | LS   | \$7,500.000 | 1                        | \$7,500.00                  |
|                   | 0520           | 6123000A     | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)                                      | EA   | \$500.000   | 2                        | \$1,000.00                  |
|                   | 0580           | 6221001      | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) | SQYD | \$9.250     | 936                      | \$8,658.00                  |
| Project J9        | S3379 - To     | tal          |  |      |             |                          | \$17,158.00                 |
| Overall - T       | otal           |              |  |      |             |                          | \$323,362.10                |

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Revision 3/23/2023 Page 1 of 15



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 16, 2023

Progress Estimate Number

9

Contract ID 221216-H01 Pay Period StartOctober 1, 2023 Original Contract Amount \$5,325,000.00
Prime ContractorPace Construction Company, LLCPay Period End October 15, 2023Net Change Order Amount \$5,380,400.00
Current Contract Amount \$5,380,400.00

| Project<br>Number | Line<br>No. | Item Description  | Adjustment<br>Type | Other Item<br>Adjustment<br>Type | Comments  | Adjustment<br>Quantity | Line Item<br>Adjustment<br>Unit Price | Adjustment<br>amount |
|-------------------|-------------|---|--------------------|----------------------------------|---|------------------------|---------------------------------------|----------------------|
| J9P3599           | 0050        | MISC.   | Material           |                                  |   | -427.3                 | \$60.00                               | (\$25,638.00)        |
|                   | 0050        | MISC.   | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0006) due to user wilesr<br>overridding Payment Estimate Exception 1 on<br>the current Payment Estimate.  | 427.3                  | \$60.00                               | \$25,638.00          |
|                   | 0100        | TACK COAT   | Material           |                                  |   | -10,550                | \$3.05                                | (\$32,177.50)        |
|                   | 0100        | TACK COAT   | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0007) due to user wilesr<br>overridding Payment Estimate Exception 3 on<br>the current Payment Estimate.  | 10,550                 | \$3.05                                | \$32,177.50          |
|                   | 0150        | FURNISHING TYPE 1 ROCK<br>BLANKET   | Material           |                                  |   | -25.7                  | \$1.00                                | (\$25.70)            |
|                   | 0150        | FURNISHING TYPE 1 ROCK<br>BLANKET   | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0001) due to user wilesr<br>overridding Payment Estimate Exception 8 on<br>the current Payment Estimate.  | 25.7                   | \$1.00                                | \$25.70              |
|                   | 0380        | MULCHING  | Material           |                                  |   | -16.8                  | \$1,650.00                            | (\$27,720.00)        |
|                   | 0380        | MULCHING  | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0002) due to user wilesr<br>overridding Payment Estimate Exception 13<br>on the current Payment Estimate. | 16.8                   | \$1,650.00                            | \$27,720.00          |
|                   | 0390        | SEEDING - COOL SEASON<br>GRASSES  | Material           |                                  |   | -16.8                  | \$2,950.00                            | (\$49,560.00)        |
|                   | 0390        | SEEDING - COOL SEASON<br>GRASSES  | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0003) due to user wilesr<br>overridding Payment Estimate Exception 14<br>on the current Payment Estimate. | 16.8                   | \$2,950.00                            | \$49,560.00          |
|                   | 0410        | SEDIMENT TRAP ROCK  | Material           |                                  |   | -192                   | \$30.00                               | (\$5,760.00)         |
|                   | 0410        | SEDIMENT TRAP ROCK  | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0004) due to user wilesr<br>overridding Payment Estimate Exception 17<br>on the current Payment Estimate. | 192                    | \$30.00                               | \$5,760.00           |
|                   | 0420        | ROCK DITCH CHECK  | Material           |                                  |   | -4,500                 | \$17.50                               | (\$78,750.00)        |
|                   | 0420        | ROCK DITCH CHECK  | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0005) due to user wilesr<br>overridding Payment Estimate Exception 18<br>on the current Payment Estimate. | 4,500                  | \$17.50                               | \$78,750.00          |
| J9S3379           | 0510        | TACK COAT   | Material           |                                  |   | -16,590                | \$3.00                                | (\$49,770.00)        |
|                   | 0510        | TACK COAT   | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0008) due to user wilesr<br>overridding Payment Estimate Exception 4 on<br>the current Payment Estimate.  | 16,590                 | \$3.00                                | \$49,770.00          |
|                   | 0560        | 4 IN. WHITE STANDARD<br>WATERBORNE PAVEMENT<br>MARKING PAINT, TYPE P<br>BEADS | Material           |                                  |   | -153,330               | \$0.13                                | (\$19,932.90)        |
|                   | 0560        | 4 IN. WHITE STANDARD<br>WATERBORNE PAVEMENT<br>MARKING PAINT, TYPE P<br>BEADS | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0009) due to user wilesr<br>overridding Payment Estimate Exception 9 on                                   | 153,330                | \$0.13                                | \$19,932.90          |

Revision 3/23/2023 Page 2 of 15



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 16, 2023

Progress Estimate Number

9

Contract ID 221216-H01 Pay Period StartOctober 1, 2023 Original Contract Amount \$5,325,000.00
Prime ContractorPace Construction Company, LLCPay Period End October 15, 2023Net Change Order Amount \$5,380,400.00
Current Contract Amount \$5,380,400.00

| Project<br>Number | Line<br>No. | Item Description   | Adjustment<br>Type | Other Item<br>Adjustment<br>Type | Comments  | Adjustment<br>Quantity | Line Item<br>Adjustment<br>Unit Price | Adjustment<br>amount |
|-------------------|-------------|--|--------------------|----------------------------------|---|------------------------|---------------------------------------|----------------------|
| J9S3379           |             |  |                    |                                  | the current Payment Estimate.   |                        |                                       |                      |
|                   | 0570        | 4 IN. YELLOW STANDARD<br>WATERBORNE PAVEMENT<br>MARKING PAINT, TYPE P<br>BEADS | Material           |                                  |   | -153,154               | \$0.12                                | (\$18,378.48         |
|                   | 0570        | 4 IN. YELLOW STANDARD<br>WATERBORNE PAVEMENT<br>MARKING PAINT, TYPE P<br>BEADS | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0010) due to user wilesr<br>overridding Payment Estimate Exception 11<br>on the current Payment Estimate. | 153,154                | \$0.12                                | \$18,378.48          |
|                   | 0600        | MGS GUARDRAIL  | Material           |                                  |   | -638                   | \$35.16                               | (\$22,432.08)        |
|                   | 0600        | MGS GUARDRAIL  | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0011) due to user wilesr<br>overridding Payment Estimate Exception 5 on<br>the current Payment Estimate.  | 638                    | \$35.16                               | \$22,432.08          |
|                   | 0610        | TYPE A CRASHWORTHY<br>END TERMINAL (MASH)                                      | Material           |                                  |   | -4                     | \$3,750.00                            | (\$15,000.00)        |
|                   | 0610        | TYPE A CRASHWORTHY<br>END TERMINAL (MASH)                                      | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0012) due to user wilesr<br>overridding Payment Estimate Exception 7 on<br>the current Payment Estimate.  | 4                      | \$3,750.00                            | \$15,000.00          |
| Total             |             |  |                    |                                  |   |                        |                                       | \$0.00               |

Revision 3/23/2023 Page 3 of 15



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

|                   |                            |  |       |          | (  | Contract Project Information   |  |  |  |  |  |  |
|-------------------|----------------------------|--|-------|----------|--|--|--|--|--|--|--|--|
| Project<br>Number | Federal<br>Proj.<br>Number | Project<br>Description   | Route | County   |  |  | Location of Work   |  |  |  |  |  |
| J9P3599           | FAF<br>5-1(26)             | Resurface  | 5, T  | OZARK    | on Route 5 from Route 160 road 512 near Gainesville          | Route 5 from Route 160 to Arkansas State line and on Route T from 0.1 miles east of county road 527 to 0.1 miles west of county d 512 near Gainesville |  |  |  |  |  |  |
| J9S3379           | FAS-<br>S703(095)          | Resurface  | 181   | OZARK    | from Route H to Route 160                                    | om Route H to Route 160 near Gainesville   |  |  |  |  |  |  |
| otals by J        | lob Number                 | s  |       |          |  |  |  |  |  |  |  |  |
| J9P3599           |                            | Item Pay<br>Item Adjustme  |       | Item Pay | This Estimate<br>\$306,204.10<br>\$0.00<br>\$306,204.10      | Previous<br>\$2,909,918.41<br>(\$83,918.03)<br>\$2,826,000.38  | To Date<br>\$3,216,122.51<br>(\$83,918.03)<br>\$3,132,204.48 |  |  |  |  |  |
|                   | Disince<br>Liquida         | Incentive Disincentive Liquidated Damages Other Contract Adjustments |       |          | \$0.00<br>\$0.00<br>\$0.00<br>\$0.00                         | \$0.00<br>\$0.00<br>\$0.00<br>\$0.00   | \$0.00<br>\$0.00<br>\$0.00<br>\$0.00                         |  |  |  |  |  |
| J9S3379           |                            | Posted Item Pay Gross Item Adjustments Gross Item Pay                |       |          | This Estimate<br>\$17,158.00<br>\$0.00<br><b>\$17,158.00</b> | Previous<br>\$2,010,917.96<br>(\$4,616.42)<br>\$2,006,301.54   | To Date<br>\$2,028,075.96<br>(\$4,616.42)<br>\$2,023,459.54  |  |  |  |  |  |
|                   | Disince                    | Incentive<br>Disincentive<br>Liquidated Damages                      |       |          | \$0.00<br>\$0.00<br>\$0.00<br>\$0.00                         | \$0.00<br>\$0.00<br>\$0.00<br>\$0.00   | \$0.00<br>\$0.00<br>\$0.00<br>\$0.00                         |  |  |  |  |  |

Revision 3/23/2023 Page 4 of 15



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

| Exceptions / Discrepencies   | Explanation                        | Entered | Status       |
|--|------------------------------------|---------|--------------|
|  |                                    | Ву      |              |
| Estimate Exception Type: Insufficient Materials: Project J9P3599, Item 3049907, Project Item Line<br>Number 0050, Material Set 304990796, Material 1007T1ABLDT5 - Agg Base Type 1 & 5<br>Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.   | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J9P3599, Item 3049907, Project Item Line<br>Number 0050, Material Set 304990796, Material 0304SBT15KP - Compacted Type 1 & 5 Base,<br>Acceptance Action Generic 0304SBT15KP is insufficient.                  | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J9P3599, Item 4071005, Project Item Line<br>Number 0100, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H,<br>Acceptance Action Generic AspEmulsion is insufficient.                    | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J9S3379, Item 4071005, Project Item Line<br>Number 0510, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H,<br>Acceptance Action Generic AspEmulsion is insufficient.                    | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J9S3379, Item 6061060, Project Item Line Number 0600, Material Set 606106096, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.  | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J9S3379, Item 6061060, Project Item Line<br>Number 0600, Material Set 606106096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2<br>Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient. | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J9S3379, Item 6063014, Project Item Line Number 0610, Material Set 606301496, Material 1040GRCWA - Crashworthy End Terminal Type A, Acceptance Action Generic 1040GRCWA is insufficient.                      | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J9P3599, Item 6113010, Project Item Line<br>Number 0150, Material Set 611301096, Material 0611EPM - Embankment Protection Material,<br>Acceptance Action Generic 0611EPM is insufficient.                     | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J9S3379, Item 6206000C, Project Item Line Number 0560, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.       | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J9S3379, Item 6206000C, Project Item Line Number 0560, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.          | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J9S3379, Item 6206001C, Project Item Line Number 0570, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.      | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J9S3379, Item 6206001C, Project Item Line Number 0570, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.          | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J9P3599, Item 8025006, Project Item Line<br>Number 0380, Material Set 8025006, Material 0802MLST - Mulch Straw (Vegetative Mulch),<br>Acceptance Action Generic 0802MLST is insufficient.                     | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J9P3599, Item 8051000A, Project Item Line Number 0390, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.                 | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J9P3599, Item 8051000A, Project Item Line Number 0390, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 1801FZ is insufficient.   | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J9P3599, Item 8051000A, Project Item Line Number 0390, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.   | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J9P3599, Item 8061004, Project Item Line<br>Aumber 0410, Material Set 806100496, Material 0806TEC - Temporary Erosion Control, Acceptance<br>Action Generic 0806TEC is insufficient.                          | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J9P3599, Item 8061005, Project Item Line<br>lumber 0420, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance<br>action Generic 0806TEC is insufficient.                          | Material OK - Reports not complete | WILESR  | Overridden   |
| Estimate Exception Type: Item Overrun: Contract 221216-H01, Contract Project J9P3599, Project Item<br>ine Number 0080, Contract Line Item Number 0080, Item 4020520, Minor Item.   | Change order in process            | WILESR  | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 221216-H01, Contract Project J9P3599, Project Item<br>ine Number 0090, Contract Line Item Number 0090, Item 4029910, Minor Item.   | Change order in process            | WILESR  | Acknowledged |

Revision 3/23/2023 Page 5 of 15



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

|                         |                |          |             |              | eport Generated date and can differ from the posted amo  |                             |                        |                              |       |                                    |              |  |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------------------|------------------------|------------------------------|-------|------------------------------------|--------------|--|
| Contract<br>Nm.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | Description  | Bid<br>Quantity             | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit  | Total<br>Posted<br>Approved<br>Qty | Unit Price   | Total Value POSTED<br>To Date (See report<br>generated date) |
| 221216-H01              | J9P3599        | 0001     | 0010        | 2022010      | REMOVAL OF IMPROVEMENTS  | 1.00                        | 0.00                   | 1.00                         | LS    |                                    | \$141,918.65 | \$141,918.65   |
|                         |                | 0001     | 0020        | 2063000      | CLASS 3 EXCAVATION   | 433.00                      | 0.00                   | 433.00                       | CUYD  | 433.00                             | \$20.00      | \$8,660.00   |
|                         |                | 0001     | 0030        | 2129900      | MISC.SHOULDER GRADING  | 905.00                      | 0.00                   | 905.00                       | 100F  | 905.00                             | \$765.00     | \$692,325.00   |
|                         |                | 0001     | 0040        | 3040163      | TYPE 1 AGGREGATE FOR BASE (6 IN. THICK)  | 621.00                      | 0.00                   | 621.00                       | SQYD  | 0.00                               | \$15.00      | \$0.00   |
|                         |                | 0001     | 0050        | 3049907      | MISC.TYPE 1 AGGREGATE  | 486.00                      | 0.00                   | 486.00                       | CUYD  | 427.30                             | \$60.00      | \$25,638.00  |
|                         |                | 0001     | 0060        | 3105002      | GRAVEL (A) OR CRUSHED STONE (B)  | 420.00                      | 0.00                   | 420.00                       | TONS  | 0.00                               | \$40.00      | \$0.00   |
|                         |                | 0001     | 0070        | 4011209      | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  | 344.80                      | 0.00                   | 344.80                       | TONS  | 132.70                             | \$135.00     | \$17,914.50  |
|                         |                | 0001     | 0080        | 4020520      | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)   | 8,344.60                    | 0.00                   | 8,344.60                     | TONS  | 8,440.30                           | \$114.00     | \$962,194.20   |
|                         |                | 0001     | 0090        | 4029910      | MISC.OPTIONAL SHOULDER BASE  | 4,545.10                    | 0.00                   | 4,545.10                     | TONS  | 5,190.20                           | \$100.00     | \$519,020.00   |
|                         |                | 0001     | 0100        | 4071005      | TACK COAT  | 10,656.20                   | 0.00                   | 10,656.20                    | GAL   | 10,550.00                          | \$3.05       | \$32,177.50  |
|                         |                | 0001     | 0110        | 5021108      | CONCRETE PAVEMENT ( 8 IN. NON-REINF)   | 176.40                      | 0.00                   | 176.40                       | SQYD  | 0.00                               | \$75.00      | \$0.00   |
|                         |                | 0001     | 0120        | 6044013      | PIPE COLLAR, TYPE C  | 5.00                        | 0.00                   | 5.00                         | EA    | 5.00                               | \$2,000.00   | \$10,000.00  |
|                         |                | 0001     | 0130        | 6091011      | CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S   | 541.00                      | 0.00                   | 541.00                       | LF    | 0.00                               | \$15.00      | \$0.00   |
|                         |                | 0001     | 0140        | 6097000      | ROCK LINING  | 52.00                       | 0.00                   | 52.00                        | CUYD  | 0.00                               | \$75.00      | \$0.00   |
|                         | 000            | 0001     | 0150        | 6113010      | FURNISHING TYPE 1 ROCK BLANKET   | 25.70                       | 0.00                   | 25.70                        | CUYD  | 25.70                              | \$1.00       | \$25.70  |
|                         |                | 0001     | 0001        | 0160         | 6113030  | PLACING TYPE 1 ROCK BLANKET | 25.70                  | 0.00                         | 25.70 | CUYD                               | 25.70        | \$75.00  |
|                         |                | 0001     | 0170        | 6123000A     | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  | 2.00                        | 0.00                   | 2.00                         | EA    | 0.00                               | \$500.00     | \$0.00   |
|                         | 0001           | 0001     | 0180        | 6161005      | CONSTRUCTION SIGNS   | 1,696.30                    | 0.00                   | 1,696.30                     | SQFT  | 1,696.30                           | \$6.00       | \$10,177.80  |
|                         |                | 0001     | 0190        | 6161025      | CHANNELIZER (TRIM LINE)  | 140.00                      | 0.00                   | 140.00                       | EA    | 140.00                             | \$20.00      | \$2,800.00   |
|                         |                | 0001     | 0200        | 6161098A     | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 2.00                        | 0.00                   | 2.00                         | EA    | 2.00                               | \$3,500.00   | \$7,000.00   |
|                         |                | 0001     | 0210        | 6181000      | MOBILIZATION   | 1.00                        | 0.00                   | 1.00                         | LS    | 1.00                               | \$350,000.00 | \$350,000.00   |
|                         |                | 0001     | 0220        | 6181020      | ADDITIONAL MOBILIZATION FOR SEEDING  | 4.00                        | 0.00                   | 4.00                         | EA    | 0.00                               | \$600.00     | \$0.00   |
|                         | 0001           | 0001     | 0230        | 6206000C     | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS                               | 90,510.00                   | 0.00                   | 90,510.00                    | LF    | 0.00                               | \$0.13       | \$0.00   |
|                         |                | 0001     | 0240        | 6206001C     | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS                              | 88,483.00                   | 0.00                   | 88,483.00                    | LF    | 0.00                               | \$0.12       | \$0.00   |
|                         |                | 0001     | 0250        | 6224010      | MODIFIED COLDMILLING (DEPTH TRANSITIONS)   | 859.00                      | 0.00                   | 859.00                       | SQYD  | 859.00                             | \$16.00      | \$13,744.00  |
|                         |                | 0001     | 0260        | 6261000A     | BITUMINOUS SHOULDER RUMBLE STRIP   | 703.80                      | 0.00                   | 703.80                       | STA   | 703.80                             | \$23.00      | \$16,187.40  |
|                         |                | 0001     | 0270        | 6274000      | CONTRACTOR FURNISHED SURVEYING AND STAKING   | 1.00                        | 0.00                   | 1.00                         | LS    | 1.00                               | \$4,000.00   | \$4,000.00   |
|                         |                | 0001     | 0280        | 7034001      | CLASS B-1 CONCRETE   | 1.65                        | 0.00                   | 1.65                         | CUYD  | 1.65                               | \$2,000.00   | \$3,300.00   |
|                         |                | 0001     | 0290        | 7250318A     | 18 IN. PIPE GROUP B  | 764.00                      | 0.00                   | 764.00                       | LF    | 764.00                             | \$75.00      | \$57,300.00  |
|                         |                | 0001     | 0300        | 7250324A     | 24 IN. PIPE GROUP B  | 35.00                       | 0.00                   | 35.00                        | LF    | 35.00                              | \$100.00     | \$3,500.00   |
|                         |                | 0001     | 0310        | 7250336A     | 36 IN. PIPE GROUP B  | 11.00                       | 0.00                   | 11.00                        | LF    | 11.00                              | \$125.00     | \$1,375.00   |
|                         |                | 0001     | 0320        | 7250415      | 15 IN. PIPE GROUP C  | 1,080.00                    | 98.00                  | 1,178.00                     | LF    | 1,178.00                           | \$50.00      | \$58,900.00  |
|                         |                | 0001     | 0330        | 7250418      | 18 IN. PIPE GROUP C  | 123.00                      | 50.00                  | 173.00                       | LF    | 173.00                             | \$50.00      | \$8,650.00   |
|                         |                | 0001     | 0340        | 7269903      | MISC.15 IN. CLASS IV REINFORCED CONCRETE PIPE CULVERT  | 216.00                      | 0.00                   | 216.00                       | LF    | 0.00                               | \$50.00      | \$0.00   |
|                         |                | 0001     | 0350        | 7320018A     | 18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION  | 34.00                       | 0.00                   | 34.00                        | EA    | 34.00                              | \$400.00     | \$13,600.00  |
|                         |                | 0001     | 0360        | 7320024A     | 24 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION  | 4.00                        | 0.00                   | 4.00                         | EA    | 4.00                               | \$500.00     | \$2,000.00   |
|                         |                | 0001     | 0370        | 7320036A     | 36 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION  | 1.00                        | 0.00                   | 1.00                         | EA    | 1.00                               | \$750.00     | \$750.00   |
|                         |                | 0001     | 0380        | 8025006      | MULCHING   | 20.80                       | 0.00                   | 20.80                        | ACRE  | 16.80                              | \$1,650.00   | \$27,720.00  |
|                         |                | 0001     | 0390        | 8051000A     | SEEDING - COOL SEASON GRASSES  | 20.80                       | 0.00                   | 20.80                        | ACRE  | 16.80                              | \$2,950.00   | \$49,560.00  |
|                         |                | 0001     | 0400        | 8061003      | SEDIMENT TRAP EXCAVATION   | 85.00                       | 0.00                   | 85.00                        | CUYD  | 85.00                              | \$1.00       | \$85.00  |
|                         |                | 0001     | 0410        | 8061004      | SEDIMENT TRAP ROCK   | 192.00                      | 0.00                   | 192.00                       | CUYD  | 192.00                             | \$30.00      | \$5,760.00   |
|                         |                | 0001     | 0420        | 8061005      | ROCK DITCH CHECK   | 2,300.00                    | 2,200.00               | 4,500.00                     | LF    | 4,500.00                           | \$17.50      | \$78,750.00  |
|                         |                | 0001     | 0430        | 8061016      | SEDIMENT REMOVAL   | 252.00                      | 0.00                   | 252.00                       | CUYD  | 165.00                             | \$20.50      | \$3,382.50   |
|                         |                | 0001     | 0440        | 8061019      | SILT FENCE   | 2,200.00                    | 2,000.00               | 4,200.00                     | LF    | 3,515.00                           | \$4.75       | \$16,696.25  |

Page 6 of 15 Revision 3/23/2023



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract<br>Nm.CONTRACT | Project<br>No.   | Category    | Line<br>No. | Item<br>Code | Description  | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit | Total<br>Posted<br>Approved<br>Qty | Unit Price     | Total Value POSTED<br>To Date (See report<br>generated date) |
|-------------------------|--|-------------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|----------------|--|
| 221216-H01              | J9P3599  | 0001        | 0450        | 9031260      | WOOD POST, 4 IN. BY 4 IN.  | 180.00          | 0.00                   | 180.00                       | LF   | 0.00                               | \$5.00         | \$0.00   |
|                         |  | 0040        | 0460        | 9031270A     | 2 IN. PSST POST - 12 GA.   | 2,112.00        | 0.00                   | 2,112.00                     | LF   | 1,860.00                           | \$19.88        | \$36,976.80  |
|                         |  | 0040        | 0470        | 9031271A     | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.                                     | 176.00          | 0.00                   | 176.00                       | EA   | 155.00                             | \$69.29        | \$10,739.95  |
|                         |  | 0040        | 0480        | 9035004A     | SH-FLAT SHEET  | 528.00          | 0.00                   | 528.00                       | SQFT | 465.00                             | \$45.95        | \$21,366.75  |
|                         | Project J9P3599 - Total Value Posted to Date as of Report Generated Date |             |             |              |  |                 |                        |                              |      |                                    | \$3,216,122.50 |  |
|                         | J9S3379  | 0001        | 0490        | 2022010      | REMOVAL OF IMPROVEMENTS  | 1.00            | 0.00                   | 1.00                         | LS   | 1.00                               | \$7,500.00     | \$7,500.00   |
|                         |  | 0001        | 0500        | 4020520      | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)                         | 15,325.90       | 0.00                   | 15,325.90                    | TONS | 14,976.30                          | \$115.00       | \$1,722,274.50   |
|                         |  | 0001        | 0510        | 4071005      | TACK COAT  | 19,163.00       | 0.00                   | 19,163.00                    | GAL  | 16,590.00                          | \$3.00         | \$49,770.00  |
|                         |  | 0001        | 0520        | 6123000A     | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)                                      | 2.00            | 0.00                   | 2.00                         | EA   | 2.00                               | \$500.00       | \$1,000.00   |
|                         |  | 0001        | 0530        | 6161005      | CONSTRUCTION SIGNS   | 3,204.00        | 0.00                   | 3,204.00                     | SQFT | 3,204.00                           | \$6.00         | \$19,224.00  |
|                         |  | 0001        | 0540        | 6161025      | CHANNELIZER (TRIM LINE)  | 200.00          | 0.00                   | 200.00                       | EA   | 200.00                             | \$20.00        | \$4,000.00   |
|                         |  | 0001        | 0550        | 6181000      | MOBILIZATION   | 1.00            | 0.00                   | 1.00                         | LS   | 1.00                               | \$120,000.00   | \$120,000.00   |
|                         |  | 0001        | 0560        | 6206000C     | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS           | 191,662.00      | 0.00                   | 191,662.00                   | LF   | 153,330.00                         | \$0.13         | \$19,932.90  |
|                         |  | 0001        | 0570        | 6206001C     | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS          | 191,442.00      | 0.00                   | 191,442.00                   | LF   | 153,154.00                         | \$0.12         | \$18,378.48  |
|                         |  | 0001        | 0580        | 6221001      | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) | 936.00          | 0.00                   | 936.00                       | SQYD | 936.00                             | \$9.25         | \$8,658.00   |
|                         |  | 0001        | 0590        | 6224010      | MODIFIED COLDMILLING (DEPTH TRANSITIONS)                                       | 2,152.00        | 0.00                   | 2,152.00                     | SQYD | 2,152.00                           | \$9.25         | \$19,906.00  |
|                         |  | 0010        | 0600        | 6061060      | MGS GUARDRAIL  | 638.00          | 0.00                   | 638.00                       | LF   | 638.00                             | \$35.16        | \$22,432.08  |
|                         |  | 0010        | 0610        | 6063014      | TYPE A CRASHWORTHY END TERMINAL (MASH)   | 4.00            | 0.00                   | 4.00                         | EA   | 4.00                               | \$3,750.00     | \$15,000.00  |
|                         | Project J  | 9S3379 - To | otal Value  | Posted to D  | late as of Report Generated Date   |                 |                        |                              |      |                                    |                | \$2,028,075.96   |
| 221216-H01 Ove          | 16-H01 Overall - Total Value Posted to Date as of Report Generated Date  |             |             |              |  |                 |                        |                              |      |                                    | \$5,244,198.46 |  |

Revision 3/23/2023 Page 7 of 15



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9P3599

| Line<br>Number | Item<br>Code | Description                                | DWR<br>Date | DWR<br>Approval<br>Date | Quantity<br>Posted | Units | Location                                  | From<br>Station/<br>Log<br>Mile | Offset/<br>Distance | To<br>Station/<br>Log<br>Mile | Offset/<br>Distance | Comments |
|----------------|--------------|--|-------------|-------------------------|--------------------|-------|---|---------------------------------|---------------------|-------------------------------|---------------------|----------|
| 0030           | 2129900      | MISC. SUBGRADING AND SHOULDERING           | 10/13/23    | 10/16/23                | 180.00             | 100F  | remaining 20%                             |                                 |                     |                               |                     |          |
| 0150           | 6113010      | FURNISHING TYPE 1 ROCK BLANKET             | 10/13/23    | 10/16/23                | 25.70              | CUYD  | Rock blanket at culvert wing walls        |                                 |                     |                               |                     |          |
| 0160           | 6113030      | PLACING TYPE 1 ROCK BLANKET                | 10/13/23    | 10/16/23                | 25.70              | CUYD  | Rock blanket at culvert wing walls        |                                 |                     |                               |                     |          |
| 0260           | 6261000A     | BITUMINOUS SHOULDER RUMBLE STRIP           | 10/10/23    | 10/16/23                | 351.90             | STA   |   | 344.191                         |                     | 352.762                       |                     |          |
|                |              |  | 10/11/23    | 10/16/23                | 351.90             | STA   |   | 352.762                         |                     | 344.191                       |                     |          |
| 0270           | 6274000      | CONTRACTOR FURNISHED SURVEYING AND STAKI   | 10/13/23    | 10/16/23                | 1.00               | LS    | No location                               |                                 |                     |                               |                     |          |
| 0380           | 8025006      | MULCHING                                   | 10/12/23    | 10/16/23                | 16.80              | ACRE  |   | 352.762                         |                     | 344.191                       |                     |          |
| 0390           | 8051000A     | SEEDING - COOL SEASON GRASSES              | 10/12/23    | 10/16/23                | 16.80              | ACRE  |   | 352.762                         |                     | 344.191                       |                     |          |
| 0460           | 9031270A     | 2 IN. PSST POST - 12 GA.                   | 10/13/23    | 10/16/23                | 1,860.00           | LF    | various - Chevron and object marker posts |                                 |                     |                               |                     |          |
| 0470           | 9031271A     | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. | 10/13/23    | 10/16/23                | 155.00             | EA    | chevron and object marker post anchors    |                                 |                     |                               |                     |          |
| 0480           | 9035004A     | SH-FLAT SHEET                              | 10/13/23    | 10/16/23                | 465.00             | SQFT  | chevron and object marker                 |                                 |                     |                               |                     |          |

#### Project: J9S3379

| Line<br>Number | Item<br>Code | Description                            | DWR<br>Date | DWR<br>Approval<br>Date | Quantity<br>Posted | Units | Location  | From<br>Station/<br>Log<br>Mile | Offset/<br>Distance | To<br>Station/<br>Log<br>Mile | Offset/<br>Distance | Comments |
|----------------|--------------|--|-------------|-------------------------|--------------------|-------|---|---------------------------------|---------------------|-------------------------------|---------------------|----------|
| 0490           | 2022010      | REMOVAL OF IMPROVEMENTS                | 10/13/23    | 10/16/23                | 1.00               | LS    | Removal of guardrail on 181   |                                 |                     |                               |                     |          |
| 0520           | 6123000A     | TRUCK OR TRAILER MOUNTED ATTEN (TMA)   | 10/13/23    | 10/16/23                | 2.00               | EA    | portable  |                                 |                     |                               |                     |          |
| 0580           | 6221001      | COLDMILLING BIT. PAVT FOR REM OF SURF. | 10/13/23    | 10/16/23                | 936.00             | SQYD  | Beginning and end of project and bridges at Zanoni and Bryant creek |                                 |                     |                               |                     |          |

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 8 of 15



|        |        | Б  | A 11                     | 011                 |                | 0 1 1           | 0 1 1           |               | B .   |   |        |             |   |
|--------|--------|--|--------------------------|---------------------|----------------|-----------------|-----------------|---------------|---|---|--------|-------------|---|
| roject | Line   | Description                                | Adjustment<br>Type       | Other<br>Adjustment | Est.<br>Number | Created<br>Date | Created<br>By   | Amount        | Remarks   |   |        |             |   |
| P3599  | 0050   | MISC.<br>AGGREGATE                         | Material                 | Туре                | 1              | Jun 1,<br>2023  | SYSTEM          | \$7,806.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesr overridding Payment   |   |        |             |   |
|        |        | FOR BASE                                   |                          |                     |                |                 |                 |               | Estimate Exception 1 on the current Payment Estimate.   |   |        |             |   |
|        |        |  |                          |                     | 1              | Jun 1,<br>2023  | SYSTEM          | (\$7,806.00)  |   |   |        |             |   |
|        |        |  |                          |                     | 2              | Jun 14,<br>2023 | SYSTEM          | \$25,638.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate. |   |        |             |   |
|        |        |  |                          |                     | 2              | Jun 14,<br>2023 | SYSTEM          | (\$25,638.00) |   |   |        |             |   |
|        |        |  |                          |                     |                | 3               | Jun 29,<br>2023 | SYSTEM        | \$25,638.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate. |        |             |   |
|        |        |  |                          |                     | 3              | Jun 29,<br>2023 | SYSTEM          | (\$25,638.00) |   |   |        |             |   |
|        |        |  |                          |                     | 4              | Aug 1,<br>2023  | SYSTEM          | \$25,638.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate. |   |        |             |   |
|        |        |  |                          |                     | 4              | Aug 1,<br>2023  | SYSTEM          | (\$25,638.00) |   |   |        |             |   |
|        |        |  |                          |                     | 5              | Aug 15,<br>2023 | SYSTEM          | \$25,638.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate. |   |        |             |   |
|        |        |  |                          |                     | 5              | Aug 15,<br>2023 | SYSTEM          | (\$25,638.00) |   |   |        |             |   |
|        |        |  |                          |                     | 6              | Sep 5,<br>2023  | SYSTEM          | \$25,638.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate. |   |        |             |   |
|        |        |  |                          |                     | 6              | Sep 5,<br>2023  | SYSTEM          | (\$25,638.00) |   |   |        |             |   |
|        |        |  |                          |                     | 7              | Sep 15,<br>2023 | SYSTEM          | \$25,638.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate. |   |        |             |   |
|        |        |  |                          |                     | 7              | Sep 15,<br>2023 | SYSTEM          | (\$25,638.00) |   |   |        |             |   |
|        |        |  |                          |                     |                |                 |                 |               | 8   | Oct 2,<br>2023  | SYSTEM | \$25,638.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate. |
|        |        |  |                          |                     | 8              | Oct 2,<br>2023  | SYSTEM          | (\$25,638.00) |   |   |        |             |   |
|        |        |  |                          |                     | 9              | Oct 16,<br>2023 | SYSTEM          | \$25,638.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate. |   |        |             |   |
|        |        |  |                          |                     | 9              | Oct 16,<br>2023 | SYSTEM          | (\$25,638.00) |   |   |        |             |   |
|        |        |  |                          | - Total             |                |                 |                 | \$0.00        |   |   |        |             |   |
|        |        |  | Material - To            | otal                |                |                 |                 | \$0.00        |   |   |        |             |   |
|        | 0050 - | Total                                      |                          |                     |                |                 |                 | \$0.00        |   |   |        |             |   |
|        | 0070   | BIT. PAVEMENT<br>MIXTURE<br>PG64-22 (BP-1) | Other Item<br>Adjustment | ACAD                | 2              | Jun 14,<br>2023 | WILESR          | (\$91.23)     | 132.7 tons of SL23-5<br>5.5% virgin<br>Backfill for crossroad pipe R&R  |   |        |             |   |
|        |        |  |                          | ACAD - Tot          | al             |                 |                 | (\$91.23)     |   |   |        |             |   |
|        |        |  | Other Item               | Adjustment -        | Total          |                 |                 | (\$91.23)     |   |   |        |             |   |
|        |        |  | Price<br>FUEL            |                     | 2              | Jun 14,<br>2023 | SYSTEM          | (\$193.85)    | Reference Item Price Adjustment Index Adjustment Type applied is FUEL   |   |        |             |   |
|        |        |  |                          | - Total             |                |                 |                 | (\$193.85)    |   |   |        |             |   |
|        |        |  | Price FUEL               | - Total             |                |                 |                 | (\$193.85)    |   |   |        |             |   |
|        | 0070 - | Total                                      |                          |                     |                |                 |                 | (\$285.08)    |   |   |        |             |   |
|        | 0800   | BITUMINOUS<br>PAVEMENT<br>MIXTURE          | Other Item<br>Adjustment | ACAD                |                | Sep 5,<br>2023  | WILESR          | (\$6,224.72)  | 8440.3 tons (SL23-41) at 5.9%   |   |        |             |   |
|        |        | PG64-22 (SUR                               |                          | ACAD - Tot          | al             |                 |                 | (\$6,224.72)  |   |   |        |             |   |
|        |        |  | Other Item               | Adjustment -        | Total          |                 |                 | (\$6,224.72)  |   |   |        |             |   |
|        |        |  | Overrun                  | Overrun             | 6              | Sep 5,          | SYSTEM          | (\$10,925.69) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL   |   |        |             |   |



| Project | Line   | Description                     | Adjustment<br>Type       | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By  | Amount                                    | Remarks   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|---------|--------|---------------------------------|--------------------------|-----------------------------|----------------|-----------------|----------------|---|---|-----------------|---|----------------|-----------------|---------------|-------------|---|--|--|--|--|--|
| J9P3599 | 0800   | BITUMINOUS<br>PAVEMENT          | Overrun                  |                             |                | 2023            |                |   |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        | MIXTURE<br>PG64-22 (SUR         |                          | Overrun - T                 | otal           |                 |                | (\$10,925.69)                             |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        | (                               | Overrun - To             | otal                        | 6              | Con F           | SYSTEM         | (\$10,925.69)                             | Peteranea Itam Price Adjustment Index Adjustment Type applied in EUEL   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 | FUEL                     |                             | 0              | Sep 5,<br>2023  | STSTEM         | \$1,401.09                                | Reference Item Price Adjustment Index Adjustment Type applied is FUEL   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 |                          | - Total                     |                |                 |                | \$1,401.09                                |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 | Price FUEL               | - Total                     |                |                 |                | \$1,401.09                                |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         | 0080 - |                                 |                          |                             |                |                 |                | (\$15,749.32)                             |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         | 0090   | MISC.<br>BITUMINOUS<br>PAVEMENT | Other Item<br>Adjustment | ACAD                        | 6              | Sep 5,<br>2023  | WILESR         | (\$3,373.63)                              | 5190.2 tons of Bit Base (BB23-31) @ 5.2%  |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        | (SURF. LEVEL)                   |                          | ACAD - Tot                  | al             |                 |                | (\$3,373.63)                              |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 | Other Item               | Adjustment -                | Total          |                 |                | (\$3,373.63)                              |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 | Overrun                  | Overrun                     | 6              | Sep 5,<br>2023  | SYSTEM         | (\$64,510.00)                             |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 |                          | Overrun - T                 | otal           |                 |                | (\$64,510.00)                             |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 | Overrun - T              | otal                        |                |                 |                | (\$64,510.00)                             |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         | 0090 - | Total                           |                          |                             |                |                 |                | (\$67,883.63)                             |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         | 0100   |                                 | Material                 |                             | 6              | Sep 5,<br>2023  | SYSTEM         | \$32,177.50                               | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate. |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 |                          |                             |                | 6               | Sep 5,<br>2023 | SYSTEM                                    | (\$32,177.50)   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 |                          |                             |                |                 | 7              | Sep 15,<br>2023                           | SYSTEM  | \$32,177.50     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate. |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 |                          |                             |                |                 |                |   | 7   | Sep 15,<br>2023 | SYSTEM  | (\$32,177.50)  |                 |               |             |   |  |  |  |  |  |
|         |        |                                 |                          |                             | 8              | Oct 2,<br>2023  | SYSTEM         | \$32,177.50                               | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate. |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 |                          |                             |                |                 |                |   |   |                 | 8   | Oct 2,<br>2023 | SYSTEM          | (\$32,177.50) |             |   |  |  |  |  |  |
|         |        |                                 |                          |                             |                |                 |                |   |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 |                          |                             | 9              | Oct 16,<br>2023 | SYSTEM         | (\$32,177.50)                             |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 |                          | - Total                     |                |                 |                | \$0.00                                    |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 | Material - To            | otal                        |                |                 |                | \$0.00                                    |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         | 0100 - |                                 |                          |                             |                |                 |                | \$0.00                                    |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         | 0120   | PIPE COLLAR,<br>TYPE C          | Material                 |                             | 1              | Jun 1,<br>2023  | SYSTEM         | \$10,000.00                               | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate. |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 |                          |                             | 1              | Jun 1,<br>2023  | SYSTEM         | (\$10,000.00)                             |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 |                          |                             |                |                 |                |   |   |                 |   | 2              | Jun 14,<br>2023 | SYSTEM        | \$10,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate. |  |  |  |  |  |
|         |        |                                 |                          |                             | 2              | Jun 14,<br>2023 | SYSTEM         | (\$10,000.00)                             |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 |                          |                             | 3              | Jun 29,<br>2023 | SYSTEM         | \$10,000.00                               | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate. |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 |                          |                             | 3              | Jun 29,<br>2023 | SYSTEM         | (\$10,000.00)                             |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 |                          |                             | 4              | Aug 1,<br>2023  | SYSTEM         | Estimate Item Adjustment (0004) due to us | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate. |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 |                          |                             | 4              | Aug 1,<br>2023  | SYSTEM         | (\$10,000.00)                             |   |                 |   |                |                 |               |             |   |  |  |  |  |  |
|         |        |                                 |                          | - Total                     |                |                 |                | \$0.00                                    |   |                 |   |                |                 |               |             |   |  |  |  |  |  |



| Project | Line   | Description                          | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks  |  |  |
|---------|--------|--------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|--|--|
| J9P3599 | 0120   | PIPE COLLAR,<br>TYPE C               | Material - To      | otal                        |                |                 |               | \$0.00        |  |  |  |
|         | 0120 - | Total                                |                    |                             |                |                 |               | \$0.00        |  |  |  |
|         | 0150   | FURNISHING<br>TYPE 1 ROCK<br>BLANKET | Material           |                             | 9              | Oct 16,<br>2023 | SYSTEM        | \$25.70       | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesr overridding Payment Estimate Exception 8 on the current Payment Estimate.  |  |  |
|         |        |                                      |                    |                             | 9              | Oct 16,<br>2023 | SYSTEM        | (\$25.70)     |  |  |  |
|         |        |                                      |                    | - Total                     |                |                 |               | \$0.00        |  |  |  |
|         |        |                                      | Material - To      | otal                        |                |                 |               | \$0.00        |  |  |  |
|         | 0150 - | Total                                |                    |                             |                |                 |               | \$0.00        |  |  |  |
|         | 0380   | MULCHING                             | Material           |                             | 9              | Oct 16,<br>2023 | SYSTEM        | \$27,720.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilesr overridding Payment Estimate Exception 13 on the current Payment Estimate. |  |  |
|         |        |                                      |                    |                             | 9              | Oct 16,<br>2023 | SYSTEM        | (\$27,720.00) |  |  |  |
|         |        |                                      |                    | - Total                     |                |                 |               | \$0.00        |  |  |  |
|         |        |                                      | Material - To      | otal                        |                |                 |               | \$0.00        |  |  |  |
|         | 0380 - | Total                                |                    |                             |                |                 |               | \$0.00        |  |  |  |
|         | 0390   | SEEDING -<br>COOL SEASON<br>GRASSES  | Material           |                             | 9              | Oct 16,<br>2023 | SYSTEM        | \$49,560.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 14 on the current Payment Estimate. |  |  |
|         |        |                                      |                    |                             | 9              | Oct 16,<br>2023 | SYSTEM        | (\$49,560.00) |  |  |  |
|         |        |                                      |                    | - Total                     |                |                 |               | \$0.00        |  |  |  |
|         |        |                                      | Material - To      | otal                        |                |                 |               | \$0.00        |  |  |  |
|         | 0390 - | Total                                |                    |                             |                |                 |               | \$0.00        |  |  |  |
|         | 0410   | SEDIMENT<br>TRAP ROCK                | Material           |                             | 4              | Aug 1,<br>2023  | SYSTEM        | \$5,760.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.  |  |  |
|         |        |                                      |                    |                             | 4              | Aug 1,<br>2023  | SYSTEM        | (\$5,760.00)  |  |  |  |
|         |        |                                      |                    | 6                           | 5              | Aug 15,<br>2023 | SYSTEM        | \$5,760.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.  |  |  |
|         |        |                                      |                    |                             | 5              | Aug 15,<br>2023 | SYSTEM        | (\$5,760.00)  |  |  |  |
|         |        |                                      |                    |                             | 6              | Sep 5,<br>2023  | SYSTEM        | \$5,760.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user wilesr overridding Payment Estimate Exception 9 on the current Payment Estimate.  |  |  |
|         |        |                                      |                    |                             | 6              | Sep 5,<br>2023  | SYSTEM        | (\$5,760.00)  |  |  |  |
|         |        |                                      |                    |                             | 7              | Sep 15,<br>2023 | SYSTEM        | \$5,760.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilesr overridding Payment Estimate Exception 9 on the current Payment Estimate.  |  |  |
|         |        |                                      |                    |                             | 7              | Sep 15,<br>2023 | SYSTEM        | (\$5,760.00)  |  |  |  |
|         |        |                                      |                    |                             | 8              | Oct 2,<br>2023  | SYSTEM        | \$5,760.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesr overridding Payment Estimate Exception 12 on the current Payment Estimate. |  |  |
|         |        |                                      |                    |                             | 8              | Oct 2,<br>2023  | SYSTEM        | (\$5,760.00)  |  |  |  |
|         |        |                                      |                    |                             | 9              | Oct 16,<br>2023 | SYSTEM        | \$5,760.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 17 on the current Payment Estimate. |  |  |
|         |        |                                      |                    |                             | 9              | Oct 16,<br>2023 | SYSTEM        | (\$5,760.00)  |  |  |  |
|         |        |                                      |                    | - Total                     |                |                 |               | \$0.00        |  |  |  |
|         |        |                                      | Material - To      | otal                        |                |                 |               | \$0.00        |  |  |  |
|         | 0410 - | Total                                |                    |                             |                |                 |               | \$0.00        |  |  |  |
|         | 0420   | ROCK DITCH<br>CHECK                  | Material           |                             | 2              | Jun 14,<br>2023 | SYSTEM        | \$6,125.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment  |  |  |



| Project | Line    | Description                       | Adjustment<br>Type       | Other<br>Adjustment | Est.<br>Number | Created<br>Date | Created<br>By | Amount          | Remarks  |             |  |
|---------|---------|-----------------------------------|--------------------------|---------------------|----------------|-----------------|---------------|-----------------|--|-------------|--|
|         |         |                                   |                          | Type                | Number         | Date            | Бу            |                 |  |             |  |
| J9P3599 | 0420    | ROCK DITCH<br>CHECK               | Material                 |                     |                |                 |               |                 | Estimate Exception 4 on the current Payment Estimate.  |             |  |
|         |         | OTILOR                            |                          |                     | 2              | Jun 14,<br>2023 | SYSTEM        | (\$6,125.00)    |  |             |  |
|         |         |                                   |                          |                     | 3              | Jun 29,<br>2023 | SYSTEM        | \$40,250.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.  |             |  |
|         |         |                                   |                          |                     | 3              | Jun 29,<br>2023 | SYSTEM        | (\$40,250.00)   |  |             |  |
|         |         |                                   |                          |                     | 4              | Aug 1,<br>2023  | SYSTEM        | \$40,250.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  |             |  |
|         |         |                                   |                          |                     | 4              | Aug 1,<br>2023  | SYSTEM        | (\$40,250.00)   |  |             |  |
|         |         |                                   |                          |                     | 5              | Aug 15,<br>2023 | SYSTEM        | \$40,250.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  |             |  |
|         |         |                                   |                          |                     | 5              | Aug 15,<br>2023 | SYSTEM        | (\$40,250.00)   |  |             |  |
|         |         |                                   |                          |                     | 6              | Sep 5,<br>2023  | SYSTEM        | \$78,750.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wilesr overridding Payment Estimate Exception 10 on the current Payment Estimate. |             |  |
|         |         |                                   |                          |                     | 6              | Sep 5,<br>2023  | SYSTEM        | (\$78,750.00)   |  |             |  |
|         |         |                                   |                          |                     | 7              | Sep 15,<br>2023 | SYSTEM        | \$78,750.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 10 on the current Payment Estimate. |             |  |
|         |         |                                   |                          |                     | 7              | Sep 15,<br>2023 | SYSTEM        | (\$78,750.00)   |  |             |  |
|         |         |                                   |                          |                     | 8              | Oct 2,<br>2023  | SYSTEM        | \$78,750.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilesr overridding Payment Estimate Exception 13 on the current Payment Estimate. |             |  |
|         |         |                                   |                          |                     | 8              | Oct 2,<br>2023  | SYSTEM        | (\$78,750.00)   |  |             |  |
|         |         |                                   |                          |                     |                |                 | 9             | Oct 16,<br>2023 | SYSTEM   | \$78,750.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilesr overridding Payment Estimate Exception 18 on the current Payment Estimate. |
|         |         |                                   |                          |                     | 9              | Oct 16,<br>2023 | SYSTEM        | (\$78,750.00)   |  |             |  |
|         |         |                                   |                          | - Total             |                |                 |               | \$0.00          |  |             |  |
|         |         |                                   | Material - To            | otal                |                |                 |               | \$0.00          |  |             |  |
|         | 0420 -  | Total                             |                          |                     |                |                 |               | \$0.00          |  |             |  |
|         | 0440    | SILT FENCE                        | Material                 |                     | 2              | Jun 14,<br>2023 | SYSTEM        | \$3,990.00      | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  |             |  |
|         |         |                                   |                          |                     | 2              | Jun 14,<br>2023 | SYSTEM        | (\$3,990.00)    |  |             |  |
|         |         |                                   |                          | - Total             |                |                 |               | \$0.00          |  |             |  |
|         |         |                                   | Material - To            | otal                |                |                 |               | \$0.00          |  |             |  |
|         | 0440 -  | Total                             |                          |                     |                |                 |               | \$0.00          |  |             |  |
| J9P3599 | - Total |                                   |                          |                     |                |                 |               | (\$83,918.03)   |  |             |  |
| J9S3379 | 0500    | BITUMINOUS<br>PAVEMENT<br>MIXTURE | Other Item<br>Adjustment | ACAD                | 5              | Aug 15,<br>2023 | WILESR        | (\$4,352.06)    | 5901.1 tons of surface level 5.9%  |             |  |
|         |         | PG64-22 (SUR                      |                          |                     | 6              | Sep 5,<br>2023  | WILESR        | (\$2,958.63)    | 1125.6 tons of SL23-41 @ 5.9%<br>3096.0 tons of SL23-5 @ 5.5%  |             |  |
|         |         |                                   |                          |                     | 7              | Sep 15,<br>2023 | WILESR        | (\$3,336.85)    | 4853.6 tons SL23-5 5.5%  |             |  |
|         |         |                                   |                          | ACAD - Tota         | al             |                 |               | (\$10,647.54)   |  |             |  |
|         |         |                                   | Other Item               | Adjustment -        | Total          |                 |               | (\$10,647.54)   |  |             |  |
|         |         |                                   |                          |                     |                |                 |               |                 |  |             |  |
|         |         |                                   | Price<br>FUEL            |                     | 5              | Aug 15,<br>2023 | SYSTEM        | \$979.58        | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |             |  |



|       | Line               | Description  | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number  | Created<br>Date   | Created<br>By                                    | Amount  | Remarks  |
|-------|--------------------|--|--------------------|-----------------------------|-----------------|---|--|---|--|
| S3379 | 0500               | BITUMINOUS<br>PAVEMENT<br>MIXTURE  | Price<br>FUEL      |                             | 7               | Sep 15,<br>2023   | SYSTEM   | \$4,350.76  | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |
|       |                    | PG64-22 (SUR   |                    | - Total                     |                 |   |  | \$6,031.12  |  |
|       |                    |  | Price FUEL         | - Total                     |                 |   |  | \$6,031.12  |  |
|       | 0500 -             | - Total  |                    |                             |                 |   |  | (\$4,616.42)  |  |
|       | 0510               | TACK COAT  | Material           |                             | 5               | Aug 15,<br>2023   | SYSTEM   | \$17,595.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate.  |
|       |                    |  |                    |                             | 5               | Aug 15,<br>2023   | SYSTEM   | (\$17,595.00)   |  |
|       |                    |  |                    |                             | 6               | Sep 5,<br>2023  | SYSTEM   | \$33,795.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.  |
|       |                    |  |                    |                             | 6               | Sep 5,<br>2023  | SYSTEM   | (\$33,795.00)   |  |
|       |                    |  |                    |                             | 7               | Sep 15,<br>2023   | SYSTEM   | \$49,770.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.  |
|       |                    |  |                    | 7                           | Sep 15,<br>2023 | SYSTEM  | (\$49,770.00)                                    |   |  |
|       |                    |  |                    |                             | 8               | Oct 2,<br>2023  | SYSTEM   | \$49,770.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.  |
|       |                    |  |                    |                             | 8               | Oct 2,<br>2023  | SYSTEM   | (\$49,770.00)   |  |
|       |                    |  |                    |                             | 9               | Oct 16,<br>2023   | SYSTEM   | \$49,770.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.  |
|       |                    |  |                    |                             | 9               | Oct 16,<br>2023   | SYSTEM   | (\$49,770.00)   |  |
|       |                    |  |                    | - Total                     |                 |   |  | \$0.00  |  |
|       |                    |  |                    |                             |                 |   |  |   |  |
|       |                    |  | Material - To      | otal                        |                 |   |  | \$0.00  |  |
|       | 0510 -             | - Total  | Material - To      | otal                        |                 |   |  | \$0.00<br>\$0.00  |  |
|       | <b>0510</b> - 0560 | 4 IN. WHITE<br>WATERBORNE<br>PAVEMENT  | Material - To      | otal                        | 6               | Sep 5,<br>2023  | SYSTEM   |   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  |
|       |                    | 4 IN. WHITE<br>WATERBORNE  |                    | otal                        | 6               |   | SYSTEM SYSTEM                                    | \$0.00  | Estimate Item Adjustment (0017) due to user wilesr overridding Payment   |
|       |                    | 4 IN. WHITE<br>WATERBORNE<br>PAVEMENT  |                    | otal                        |                 | 2023<br>Sep 5,  |  | <b>\$0.00</b><br><b>\$9,966.45</b>  | Estimate Item Adjustment (0017) due to user wilesr overridding Payment   |
|       |                    | 4 IN. WHITE<br>WATERBORNE<br>PAVEMENT  |                    | otal                        | 6               | 2023<br>Sep 5,<br>2023<br>Sep 15,   | SYSTEM   | \$0.00<br>\$9,966.45<br>(\$9,966.45)  | Estimate Item Adjustment (0017) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilesr overridding Payment  |
|       |                    | 4 IN. WHITE<br>WATERBORNE<br>PAVEMENT  |                    | otal                        | 6               | 2023<br>Sep 5,<br>2023<br>Sep 15,<br>2023   | SYSTEM SYSTEM                                    | \$0.00<br>\$9,966.45<br>(\$9,966.45)<br>\$19,932.90   | Estimate Item Adjustment (0017) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilesr overridding Payment  |
|       |                    | 4 IN. WHITE<br>WATERBORNE<br>PAVEMENT  |                    | otal                        | 6<br>7          | 2023<br>Sep 5,<br>2023<br>Sep 15,<br>2023<br>Sep 15,<br>2023<br>Oct 2,                                      | SYSTEM SYSTEM                                    | \$0.00<br>\$9,966.45<br>(\$9,966.45)<br>\$19,932.90<br>(\$19,932.90)  | Estimate Item Adjustment (0017) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment   |
|       |                    | 4 IN. WHITE<br>WATERBORNE<br>PAVEMENT  |                    | otal                        | 6 7 7 8 8       | 2023 Sep 5, 2023 Sep 15, 2023 Sep 15, 2023 Oct 2, 2023 Oct 2,   | SYSTEM SYSTEM SYSTEM SYSTEM                      | \$0.00<br>\$9,966.45<br>(\$9,966.45)<br>\$19,932.90<br>(\$19,932.90)<br>\$19,932.90   | Estimate Item Adjustment (0017) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment   |
|       |                    | 4 IN. WHITE<br>WATERBORNE<br>PAVEMENT  |                    |                             | 6 7 7 8 8 8     | 2023<br>Sep 5,<br>2023<br>Sep 15,<br>2023<br>Sep 15,<br>2023<br>Oct 2,<br>2023<br>Oct 2,<br>2023<br>Oct 16, | SYSTEM SYSTEM SYSTEM SYSTEM                      | \$0.00<br>\$9,966.45<br>(\$9,966.45)<br>\$19,932.90<br>(\$19,932.90)<br>(\$19,932.90)   | Estimate Item Adjustment (0017) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment |
|       |                    | 4 IN. WHITE<br>WATERBORNE<br>PAVEMENT  |                    | otal<br>- Total             | 6 7 7 8 8 8 9   | 2023 Sep 5, 2023 Sep 15, 2023 Sep 15, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023                            | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM        | \$0.00<br>\$9,966.45<br>(\$9,966.45)<br>\$19,932.90<br>(\$19,932.90)<br>\$19,932.90<br>(\$19,932.90)                                    | Estimate Item Adjustment (0017) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment |
|       |                    | 4 IN. WHITE<br>WATERBORNE<br>PAVEMENT  |                    | - Total                     | 6 7 7 8 8 8 9   | 2023 Sep 5, 2023 Sep 15, 2023 Sep 15, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023                            | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM        | \$0.00<br>\$9,966.45<br>(\$9,966.45)<br>\$19,932.90<br>(\$19,932.90)<br>\$19,932.90<br>(\$19,932.90)<br>(\$19,932.90)                   | Estimate Item Adjustment (0017) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment |
|       | 0560               | 4 IN. WHITE<br>WATERBORNE<br>PAVEMENT  | Material           | - Total                     | 6 7 7 8 8 8 9   | 2023 Sep 5, 2023 Sep 15, 2023 Sep 15, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023                            | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM        | \$0.00<br>\$9,966.45<br>(\$9,966.45)<br>\$19,932.90<br>(\$19,932.90)<br>\$19,932.90<br>(\$19,932.90)<br>\$19,932.90                     | Estimate Item Adjustment (0017) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment |
|       | 0560               | 4 IN. WHITE WATERBORNE PAVEMENT MARKING  Total  4 IN. YELLOW WATERBORNE PAVEMENT | Material           | - Total                     | 6 7 7 8 8 8 9   | 2023 Sep 5, 2023 Sep 15, 2023 Sep 15, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023                            | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM        | \$0.00<br>\$9,966.45<br>(\$9,966.45)<br>\$19,932.90<br>(\$19,932.90)<br>\$19,932.90<br>(\$19,932.90)<br>\$19,932.90<br>\$0.00           | Estimate Item Adjustment (0017) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment |
|       | 0560               | 4 IN. WHITE WATERBORNE PAVEMENT MARKING  Total  4 IN. YELLOW WATERBORNE          | Material - To      | - Total                     | 6 7 7 8 8 9 9   | 2023 Sep 5, 2023 Sep 15, 2023 Sep 15, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023                            | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00<br>\$9,966.45<br>(\$9,966.45)<br>\$19,932.90<br>(\$19,932.90)<br>\$19,932.90<br>(\$19,932.90)<br>\$19,932.90<br>\$0.00<br>\$0.00 | Estimate Item Adjustment (0017) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment Estimate Exception 9 on the current Payment Estimate.                  |





| roject  | Line   | Description   | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date                    | Created<br>By   | Amount                                 | Remarks  |   |  |  |   |                |        |               |  |
|---------|--------|---|--------------------|-----------------------------|----------------|------------------------------------|-----------------|--|--|---|--|--|---|----------------|--------|---------------|--|
| S3379   | 0570   | 4 IN. YELLOW  | Material           |                             |                |                                    |                 |  | Estimate Exception 7 on the current Payment Estimate.  |   |  |  |   |                |        |               |  |
|         |        | WATERBORNE<br>PAVEMENT<br>MARKING                     |                    |                             | 7              | Sep 15,<br>2023                    | SYSTEM          | (\$18,378.48)                          |  |   |  |  |   |                |        |               |  |
|         |        |   |                    |                             | 8              | Oct 2,<br>2023                     | SYSTEM          | \$18,378.48                            | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesr overridding Payment Estimate Exception 10 on the current Payment Estimate.   |   |  |  |   |                |        |               |  |
|         |        |   |                    |                             |                |                                    |                 |  |  |   |  |  | 8 | Oct 2,<br>2023 | SYSTEM | (\$18,378.48) |  |
|         |        |   |                    |                             | 9              | Oct 16,<br>2023                    | SYSTEM          | \$18,378.48                            | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilesr overridding Payment Estimate Exception 11 on the current Payment Estimate.   |   |  |  |   |                |        |               |  |
|         |        |   |                    |                             | 9              | Oct 16,<br>2023                    | SYSTEM          | (\$18,378.48)                          |  |   |  |  |   |                |        |               |  |
|         |        |   |                    | - Total                     |                |                                    |                 | \$0.00                                 |  |   |  |  |   |                |        |               |  |
|         |        |   | Material - To      | otal                        |                |                                    |                 | \$0.00                                 |  |   |  |  |   |                |        |               |  |
|         | 0570 - | - Total   |                    |                             |                |                                    |                 | \$0.00                                 |  |   |  |  |   |                |        |               |  |
|         | 0600   | MGS<br>GUARDRAIL                                      |                    | Material                    |                | 8                                  | Oct 2,<br>2023  | SYSTEM                                 | \$22,432.08  | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate. |  |  |   |                |        |               |  |
|         |        |   |                    |                             | 8              | Oct 2,<br>2023                     | SYSTEM          | (\$22,432.08)                          |  |   |  |  |   |                |        |               |  |
|         |        |   |                    |                             | 9              | Oct 16,<br>2023                    | SYSTEM          | \$22,432.08                            | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.  |   |  |  |   |                |        |               |  |
|         |        |   |                    |                             |                | 9                                  | Oct 16,<br>2023 | SYSTEM                                 | (\$22,432.08)  |   |  |  |   |                |        |               |  |
|         |        |   |                    | - Total                     |                |                                    |                 | \$0.00                                 |  |   |  |  |   |                |        |               |  |
|         |        |   | Material - To      | otal                        |                |                                    |                 | \$0.00                                 |  |   |  |  |   |                |        |               |  |
|         | 0600 - | - Total   |                    |                             |                |                                    |                 | \$0.00                                 |  |   |  |  |   |                |        |               |  |
|         | 0610   | 00 - Total  10 TYPE A CRASHWORTHY END TERMINAL (MASH) | Material           | Material                    |                | 8                                  | Oct 2,<br>2023  | SYSTEM                                 | \$15,000.00  | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment   |  |  |   |                |        |               |  |
|         |        |   |                    |                             |                |                                    |                 |  | Estimate Exception 7 on the current Payment Estimate.  |   |  |  |   |                |        |               |  |
|         |        | (MASH)  |                    |                             | 8              | Oct 2,<br>2023                     | SYSTEM          | (\$15,000.00)                          | Estimate Exception 7 on the current Payment Estimate.  |   |  |  |   |                |        |               |  |
|         |        | (MASH)  |                    |                             | 8              |                                    | SYSTEM          | (\$15,000.00)<br>\$15,000.00           | Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilesr overridding Payment Estimate Exception 7 on the current Payment Estimate. |   |  |  |   |                |        |               |  |
|         |        | (MASH)  |                    |                             |                | 2023<br>Oct 16,                    |                 | ,                                      | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilesr overridding Payment  |   |  |  |   |                |        |               |  |
|         |        | (MASH)  |                    | - Total                     | 9              | 2023<br>Oct 16,<br>2023<br>Oct 16, | SYSTEM          | \$15,000.00                            | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilesr overridding Payment  |   |  |  |   |                |        |               |  |
|         |        | (MASH)  | Material - To      |                             | 9              | 2023<br>Oct 16,<br>2023<br>Oct 16, | SYSTEM          | \$15,000.00<br>(\$15,000.00)           | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilesr overridding Payment  |   |  |  |   |                |        |               |  |
|         | 0610 - | (MASH)  | Material - To      |                             | 9              | 2023<br>Oct 16,<br>2023<br>Oct 16, | SYSTEM          | \$15,000.00<br>(\$15,000.00)<br>\$0.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilesr overridding Payment  |   |  |  |   |                |        |               |  |
| S3379 - |        |   | Material - To      |                             | 9              | 2023<br>Oct 16,<br>2023<br>Oct 16, | SYSTEM          | \$15,000.00<br>(\$15,000.00)<br>\$0.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilesr overridding Payment  |   |  |  |   |                |        |               |  |

## MoDOT

### Contract Adjustments for Contract - 221216-H01

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 15 of 15