

Progress	Estimate Numbe		ntract ID 2	30120-C03		Pay Period Start	Novemb 2023	per 16,	Original Contract Amount \$257,987.0		
2				apital Electric Line LC	pital Electric Line Builders, C		d Decemb	oer 1, 2023	Net Change Order Amount Current Contract Amou	\$4,102.00 unt \$262,089.00	
Approval Date										By User	
December 4, 2023	mber 4, 2023 Generated and Approved (and should be considered Draft) at the Project Office Lev									jamesc2	
December 4, 2023		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Lev								ilesb1	
December 5, 2023				ł	Reviewed a	and Approved at the	e Central	Office Con	trollers Office Level by	ramses1	
Original Comple	Original Completion Date Current Comple					pletion Date Actual Completion Date			urrent Contract Amount	t Complete	
December 31	, 2023		Decembe	er 31, 2023					58.64%		
	Cor	ntract I	nformational Da	tes		Milest	ones				
Date Description	n Orig	ginal C	completion Date	Current Comple	tion Date	No Milestones Ex	kist for Co	ntract			
Acceptance Date											
Awarded Date	Feb	oruary 8	3, 2023	February 8, 2023							
Letting Date	<b>j</b> -,			January 20, 2023							
Notice to Proceed D	ate Mar	rch 13,	2023	March 13, 2023							
Open to Traffic Date											
Work Began Date											

Contract Total Pay For	r Estimate No. 2				
		This Estimate	Previous	To Date	
230120-C03					
	Total Posted Items Pay	<mark>\$111,254.00</mark>	\$42,438.00	\$153,692.00	
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			<mark>\$42,438.00</mark>	\$153,692.00	
Contract Total Payable	e This Estimate:	\$111,254.00			

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J3P3118E	0020	6169902	MISC.Temporary Traffic Control Setup Type 1	EA	\$195.000	1	\$195.00
	0030	6169902	MISC.Temporary Traffic Control Setup Type 2	EA	\$245.000	1	\$245.00
	0060	6181000	MOBILIZATION	LS	\$25,000.000	0.75	\$18,750.00
	0070	9011311	LUMINAIRE, LED-A	EA	\$635.000	2	\$1,270.00
	0080	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	LF	\$10.000	130	\$1,300.00
	0090	9028302	CABLE, 12 AWG 2 CONDUCTOR	LF	\$6.000	230	\$1,380.00
	0100	9020213	SIGNAL HEAD, TYPE 3S	EA	\$1,067.000	2	\$2,134.00
	0110	9020413	SIGNAL HEAD, TYPE 3C	EA	\$1,095.000	6	\$6,570.00
	0120	9020414	SIGNAL HEAD, TYPE 4C	EA	\$1,495.000	2	\$2,990.00
	0140	9020833	SH-FLAT SHEET - SIGNAL SIGN	SQFT	\$39.000	25	\$975.00
	0150	9020834	SIGNAL SIGN, MOUNTING HARDWARE	EA	\$510.000	4	\$2,040.00
	0160	9023501	POST, STEEL SPAN WIRE	EA	\$9,400.000	2	\$18,800.00
	0170	9023502	POST, STEEL SPAN WIRE, FOR 30 FT. OR 9.0 M LUMINAIRE MOUNTING	EA	\$10,870.000	2	\$21,740.00
	0180	9023602	SPAN WIRE ASSEMBLY, MESSENGER WITH TETHER	LF	\$15.000	531	\$7,965.00
	0190	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	LF	\$42.000	107	\$4,494.00
	0210	9028308	CABLE, 16 AWG 2 CONDUCTOR	LF	\$1.400	1,400	\$1,960.00
	0220	9028310	CABLE, 16 AWG 5 CONDUCTOR	LF	\$1.900	1,400	\$2,660.00



Pr	Progress Estimate Number			230120-C03	Pay Period Start	Novemb 2023	er 16,	Original Contract A	mount \$257,987.00
2 Prime Contractor		Capital Electric Line Builders, LLC	Pay Period End	l Decemb	er 1, 2023	Net Change Order Amount Current Contract Ar	\$4,102.00 nount \$262,089.00		
Project Number	Line Number	Item Code		Item Description		Unit	Unit Price	e Current Installed Qty	Current Installed Amount
J3P3118E	0230	9028311	CABLE, 16	AWG 7 CONDUCTOR		LF	\$2.20	2,470	\$5,434.00
	0240	9028621	POWER SU CONTROL	PPLY ASSEMBLY, TYPE-2 WITH CABINET	120V LIGHTING	EA	\$4,500.00	00 1	\$4,500.00
	0250	9028810	PULL BOX,	PREFORMED CLASS 1		EA	\$1,750.00	00 1	\$1,750.00
	0270	9029100	BASE, CON	CRETE		CUYD	\$2,930.00	00 1.4	\$4,102.00
Project J3P	3118E - Tot	tal							\$111,254.00
Overall - To	tal								\$111,254.00

#### Contract Adjustments This Estimate

#### No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J3P3118E	0070	LUMINAIRE, LED-A	Material			-2	\$635.00	(\$1,270.00
	0070	LUMINAIRE, LED-A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user jamesc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	2	\$635.00	\$1,270.00
	0800	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material			-130	\$10.00	(\$1,300.00)
	0080	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user jamesc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	130	\$10.00	\$1,300.00
	0090	CABLE, 12 AWG 2 CONDUCTOR	Material			-230	\$6.00	(\$1,380.00)
	0090	CABLE, 12 AWG 2 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user jamesc2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	230	\$6.00	\$1,380.00
	0100	SIGNAL HEAD, TYPE 3S	Material			-2	\$1,067.00	(\$2,134.00)
	0100	SIGNAL HEAD, TYPE 3S	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user jamesc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	2	\$1,067.00	\$2,134.00
	0110	SIGNAL HEAD, TYPE 3C	Material			-6	\$1,095.00	(\$6,570.00)
	0110	SIGNAL HEAD, TYPE 3C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user jamesc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	6	\$1,095.00	\$6,570.00
	0120	SIGNAL HEAD, TYPE 4C	Material			-2	\$1,495.00	(\$2,990.00)
	0120	SIGNAL HEAD, TYPE 4C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user jamesc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	2	\$1,495.00	\$2,990.00
	0140	SH-FLAT SHEET - SIGNAL SIGN	Material			-25	\$39.00	(\$975.00)

	Progress		Contract ID	230120-C0	3	Pay Period November 16, Start 2023	Original Contr	act Amount	\$257,987.00		
	2	Number	Prime Contractor	Capital Elec LLC	ctric Line Buile		Net Change O Amount Current Contra		\$4,102.00 \$262,089.00		
Project Number	Line No.	Item D	Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount		
J3P3118E			SH-FLAT SHEET - SIGNAL SIGN					This adjustment offsets the original system generated Material Payment Estimate Iter Adjustment (0007) due to user jamesc overridding Payment Estimate Exception 6 o the current Payment Estimate	m :2 :n	\$39.00	\$975.00
	0150	SIGNAL SI	GN, MOUNTING HARDWARE	Material			-4	\$510.00	(\$2,040.00)		
	0150	SIGNAL SIGN, MOUNTING HARDWARE		Material		This adjustment offsets the original system generated Material Payment Estimate Iter Adjustment (0008) due to user jameso overridding Payment Estimate Exception 7 o the current Payment Estimate	m 2 n	\$510.00	\$2,040.00		
	0180		IRE ASSEMBLY, SSENGER WITH TETHER	Material			-531	\$15.00	(\$7,965.00)		
	0180		IRE ASSEMBLY, SSENGER WITH TETHER	Material		This adjustment offsets the original system generated Material Payment Estimate Iter Adjustment (0009) due to user jamesc overridding Payment Estimate Exception 8 o the current Payment Estimate	m :2 :n	\$15.00	\$7,965.00		
	0190		, 3 IN., TRENCH I TRACER WIRE	Material			-107	\$42.00	(\$4,494.00)		
	0190		, 3 IN., TRENCH I TRACER WIRE	Material		This adjustment offsets the original system generated Material Payment Estimate Ite Adjustment (0010) due to user jamesc overridding Payment Estimate Exception 9 o the current Payment Estimate	m 2 n	\$42.00	\$4,494.00		
	0210	C	ABLE, 16 AWG 2 CONDUCTOR	Material			-1,400	\$1.40	(\$1,960.00)		
	0210	C,	ABLE, 16 AWG 2 CONDUCTOR	Material		This adjustment offsets the original systen generated Material Payment Estimate Iter Adjustment (0011) due to user jamesc overridding Payment Estimate Exception 1 on the current Payment Estimate	m 2 1	\$1.40	\$1,960.00		
	0220	C	ABLE, 16 AWG 5 CONDUCTOR	Material			-1,400	\$1.90	(\$2,660.00)		
	0220	C	ABLE, 16 AWG 5 CONDUCTOR	Material		This adjustment offsets the original systen generated Material Payment Estimate Iter Adjustment (0012) due to user jameso overridding Payment Estimate Exception 1 on the current Payment Estimate	m :2 2	\$1.90	\$2,660.00		
	0230	C	ABLE, 16 AWG 7 CONDUCTOR	Material			-2,470	\$2.20	(\$5,434.00)		
	0230	C	ABLE, 16 AWG 7 CONDUCTOR	Material		This adjustment offsets the original system generated Material Payment Estimate Ite Adjustment (0013) due to user jamesc overridding Payment Estimate Exception 1 on the current Payment Estimate	m 2 3	\$2.20	\$5,434.00		
	0240	ASSEMBL	POWER SUPPLY Y, TYPE-2 WITH TING CONTROL CABINET	Material			-1	\$4,500.00	(\$4,500.00)		
	0240	ASSEMBL	POWER SUPPLY Y, TYPE-2 WITH TING CONTROL CABINET	Material		This adjustment offsets the original system generated Material Payment Estimate Ite Adjustment (0014) due to user jamesc overridding Payment Estimate Exception 1 on the current Payment Estimate	m :2 4	\$4,500.00	\$4,500.00		
	0250	PULL BO	X, PREFORMED	Material			-2	\$1,750.00	(\$3,500.00)		



I	Progres 2	s Estimate Number	Contract ID Prime Contractor	230120-C0 Capital Elec LLC	3 ctric Line Build	doro	Pay Period Start Pay Period End	November 16, 2023 d December 1, 2023	Original Contr Net Change O Amount Current Contr	rder	\$4,102.00
Project Number	Line No.	Item D	escription	Adjustment Type	Other Item Adjustment Type		Comm	nents	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J3P3118E			CLASS 1								
	0250	PULL BO	X, PREFORMED CLASS 1	Material		gene A	erated Material F Adjustment (001 idding Payment	ets the original syster Payment Estimate Ite 5) due to user james Estimate Exception ent Payment Estimat	m :2 15	\$1,750.00	\$3,500.00
	0260	PULL BO	X, PREFORMED CLASS 3	Material					-1	\$3,770.00	(\$3,770.00
	0260	PULL BO	X, PREFORMED CLASS 3	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user jamesc2 overridding Payment Estimate Exception 16 on the current Payment Estimate.			m 52 16	\$3,770.00	\$3,770.00
Total											\$0.00



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Informati	on					
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J3P3118E	E FAF Signal 13 LAFAYETTE from Fairground Avenue to Route FF in Higginsville											
Totals by Jo	b Number	S										
J3P3118E		l Item Pay Item Adjustmer		tem Pay	This Estimate \$111,254.00 \$0.00 <b>\$111,254.00</b>	Previous \$42,438.00 \$0.00 <b>\$42,438.00</b>	To Date \$153,692.00 \$0.00 <b>\$153,692.00</b>					
			ments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J3P3118E, Item 9011311, Project Item Line Number 0070, Material Set 9011311, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Certifications are on SharePoint, Test needs entered.	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3118E, Item 9017110, Project Item Line Number 0080, Material Set 901711096, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Certifications are on SharePoint, Test needs entered.	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3118E, Item 9020213, Project Item Line Number 0100, Material Set 902021396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certifications are on SharePoint, Test needs entered.	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3118E, Item 9020413, Project Item Line Number 0110, Material Set 902041396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certifications are on SharePoint, Test needs entered.	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3118E, Item 9020414, Project Item Line Number 0120, Material Set 902041496, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certifications are on SharePoint, Test needs entered.	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3118E, Item 9020833, Project Item Line Number 0140, Material Set 902083396, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Central Materials needs to enter test	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3118E, Item 9020834, Project Item Line Number 0150, Material Set 9020834, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certifications are on SharePoint, Test needs entered.	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3118E, Item 9023602, Project Item Line Number 0180, Material Set 902360296, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certifications are on SharePoint, Test needs entered.	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3118E, Item 9025300, Project Item Line Number 0190, Material Set 902530096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Certifications are on SharePoint, Test needs entered.	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3118E, Item 9028302, Project Item Line Number 0090, Material Set 902830296, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certifications are on SharePoint, Test needs entered.	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3118E, Item 9028308, Project Item Line Number 0210, Material Set 902830896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certifications are on SharePoint, Test needs entered.	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3118E, Item 9028310, Project Item Line Number 0220, Material Set 902831096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certifications are on SharePoint, Test needs entered.	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3118E, Item 9028311, Project Item Line Number 0230, Material Set 902831196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certifications are on SharePoint, Test needs entered.	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3118E, Item 9028621, Project Item Line Number 0240, Material Set 902862196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certifications are on SharePoint, Test needs entered.	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3118E, Item 9028810, Project Item Line Number 0250, Material Set 902881096, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	Certifications are on SharePoint, Test needs entered.	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3118E, Item 9028812, Project Item Line Number 0260, Material Set 902881296, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	Certifications are on SharePoint, Test needs entered.	jamesc2	Overridden



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
0120-C03	J3P3118E	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$7,360.00	\$0.0
		0001	0020	6169902	MISC.Temporary Traffic Control Setup Type 1	1.00	0.00	1.00	EA	1.00	\$195.00	\$195.0
		0001	0030	6169902	MISC.Temporary Traffic Control Setup Type 2	1.00	0.00	1.00	EA	1.00	\$245.00	\$245.0
		0001	0040	6169902	MISC.Temporary Traffic Control Setup Type 3	2.00	0.00	2.00	EA	0.00	\$283.00	\$0.0
		0001	0050	6169902	MISC.Temporary Traffic Control Setup Type 4	2.00	0.00	2.00	EA	0.00	\$283.00	\$0.0
		0001	0060	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$25,000.00	\$18,750.0
		0020	0070	9011311	LUMINAIRE, LED-A	5.00	0.00	5.00	EA	2.00	\$635.00	\$1,270.
		0020	0080	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	130.00	0.00	130.00	LF	130.00	\$10.00	\$1,300.
		0020	0090	9028302	CABLE, 12 AWG 2 CONDUCTOR	230.00	0.00	230.00	LF	230.00	\$6.00	\$1,380.
		0030	0100	9020213	SIGNAL HEAD, TYPE 3S	2.00	0.00	2.00	EA	2.00	\$1,067.00	\$2,134.
		0030	0110	9020413	SIGNAL HEAD, TYPE 3C	6.00	0.00	6.00	EA	6.00	\$1,095.00	\$6,570.
		0030	0120	9020414	SIGNAL HEAD, TYPE 4C	2.00	0.00	2.00	EA	2.00	\$1,495.00	\$2,990.
		0030	0130	9020514	SIGNAL HEAD, TYPE 4B	1.00	0.00	1.00	EA	0.00	\$1,750.00	\$0.
		0030	0140	9020833	SH-FLAT SHEET - SIGNAL SIGN	33.00	0.00	33.00	SQFT	25.00	\$39.00	\$975.
		0030	0150	9020834	SIGNAL SIGN, MOUNTING HARDWARE	5.00	0.00	5.00	EA	4.00	\$510.00	\$2,040.
		0030	0160	9023501	POST, STEEL SPAN WIRE	2.00	0.00	2.00	EA	2.00	\$9,400.00	\$18,800.
		0030	0170	9023502	POST, STEEL SPAN WIRE, FOR 30 FT. OR 9.0 M LUMINAIRE MOUNTING	2.00	0.00	2.00	EA	2.00	\$10,870.00	\$21,740.
		0030	0180	9023602	SPAN WIRE ASSEMBLY, MESSENGER WITH TETHER	531.00	0.00	531.00	LF	531.00	\$15.00	\$7,965
		0030	0190	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	107.00	0.00	107.00	LF	107.00	\$42.00	\$4,494
		0030	0200	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	50.00	0.00	50.00	LF	0.00	\$6.50	\$0.
		0030	0210	9028308	CABLE, 16 AWG 2 CONDUCTOR	1,400.00	0.00	1,400.00	LF	1,400.00	\$1.40	\$1,960
		0030	0220	9028310	CABLE, 16 AWG 5 CONDUCTOR	1,400.00	0.00	1,400.00	LF	1,400.00	\$1.90	\$2,660
		0030	0230	9028311	CABLE, 16 AWG 7 CONDUCTOR	2,750.00	0.00	2,750.00	LF	2,470.00	\$2.20	\$5,434
		0030	0240	9028621	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET	1.00	0.00	1.00	EA	1.00	\$4,500.00	\$4,500
		0030	0250	9028810	PULL BOX, PREFORMED CLASS 1	3.00	0.00	3.00	EA	2.00	\$1,750.00	\$3,500
		0030	0260	9028812	PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	1.00	\$3,770.00	\$3,770.
		0030	0270	9029100	BASE, CONCRETE	12.60	1.40	14.00	CUYD	14.00	\$2,930.00	\$41,020.
		0030	0280	9029902	MISC."TS2/EV CABINET ASSEMBLY HOUSING (WITHOUT CONTROLLER)	1.00	0.00	1.00	EA	0.00	\$2,770.00	\$0.
		0030	0290	9029902	MISC.AUDIBLE PEDESTRIAN DETECTOR BUTTON	4.00	0.00	4.00	EA	0.00	\$1,300.00	\$0.
		0030	0300	9029902	MISC.KC DISTRICT VIDEO DETECTION SYSTEM WITH 3 APPROACHES	1.00	0.00	1.00	EA	0.00	\$21,525.00	\$0.
		0030	0310	9029902	MISC.KC DISTRICT VIDEO DETECTION SYSTEM WITH 4 APPROACHES	1.00	0.00	1.00	EA	0.00	\$25,810.00	\$0.
		0030	0320	9029902	MISC.MMU2 SUPPLIED AND INSTALLED IN EXISTING CABINET	1.00	0.00	1.00	EA	0.00	\$1,800.00	\$0
		0040	0330	9031250A	U-CHANNEL POST, 3 LB	13.00	0.00	13.00	LF	0.00	\$74.00	\$0.
		0040	0340	9039902	MISC.RELOCATE EXISTING SIGN AND HARDWARE	1.00	0.00	1.00	EA	0.00	\$200.00	\$0
		0050 0350 9109902 MISC.CELL PHONE NETWORK ROUTER AND ALL ASSOCIATED EQUIPMENT					0.00	2.00	EA	0.00	\$4,000.00	\$0
		0050	0360	9109902	MISC.Dome CCTV Camera with Cable	2.00	0.00	2.00	EA	0.00	\$6,360.00	\$0
		0050	0370	9109902	MISC.OGL SWITCH, FURNISH AND INSTALL	2.00	0.00	2.00	EA	0.00	\$3,750.00	\$0.
						-						



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J3P3118E DWR DWR Approval Date Date Units To Offset/ Station/ Distance Log Mile Line Item Number Code Description Location From Offset/ Station/ Distance Comments Log Mile 0020 6169902 MISC. TRAFFIC CONTROL DEVICES 11/29/23 12/4/23 1.00 EA 0+00 0+00 0030 6169902 MISC. TRAFFIC CONTROL DEVICES 11/30/23 12/4/23 1.00 EA Turn Lanes 0+00 0+0 0060 6181000 MOBILIZATION 11/30/23 12/4/23 0+00 0.75 LS 0+00 0070 9011311 LUMINAIRE, LED-A 11/29/23 12/4/23 2.00 EA 0+00 0+00 0080 9017110 CABLE, 10 AWG 1 CONDUCTOR, POLE & BRACKE 11/29/23 12/4/23 130.00 LF 0+00 0+00 0090 9028302 CABLE, 12 AWG 2 CONDUCTOR 11/30/23 12/4/23 230.00 LE 0+00 0+00 EA SW corner on Pole 20 NE corner on Pole 40 0100 9020213 SIGNAL HEAD, TYPE 3S 11/28/23 12/4/23 2.00 0 0 0110 9020413 SIGNAL HEAD, TYPE 3C 11/29/23 12/4/23 3.00 FA 0+00 0+00 11/30/23 12/4/23 3.00 EA 0+00 0+00 0120 9020414 SIGNAL HEAD, TYPE 4C 11/29/23 12/4/23 1.00 0+00 EA 0+00 11/30/23 12/4/23 1.00 EA 0+00 0+00 0140 9020833 SH-FLAT SHEET - SIGNAL SIGN 11/29/23 12/4/23 12.50 SOFT 0+00 0+00 11/30/23 12/4/23 12.50 SQFT 0+00 0+00 0150 9020834 SIGNAL SIGN, MOUNTING HARDWARE 11/29/23 12/4/23 2.00 EA 0+00 0+00 11/30/23 12/4/23 2.00 EA 0+00 0+00 11/28/23 12/4/23 0160 9023501 POST, STEEL SPAN WIRE 2.00 EA 0 0 0170 9023502 POST. STEEL SPAN WIRE, FOR 30 FT, OR 9.0 11/28/23 12/4/23 2.00 EA 0 0 0180 9023602 SPAN WIRE ASSEMBLY, MESSENGER WITH TETHE 11/29/23 12/4/23 251.00 LE 0+00 0+00 11/30/23 12/4/23 280.00 LE 0+00 0+00 0190 9025300 CONDUIT, 3 IN., TRENCH WITH TRACER WIRE 11/16/23 12/4/23 107.00 LF 0+00 0+00 0210 9028308 CABLE, 16 AWG 2 CONDUCTOR 11/29/23 12/4/23 1,110.00 LF 0+00 0+00 11/30/23 12/4/23 290.00 LF 0+00 0+00 0220 9028310 CABLE, 16 AWG 5 CONDUCTOR 11/29/23 12/4/23 1 110 00 LE 0+00 0+00 11/30/23 12/4/23 290.00 LE 0+00 0+00 0230 9028311 CABLE, 16 AWG 7 CONDUCTOR 11/29/23 12/4/23 1,215.00 LF 0+00 0+00 11/30/23 12/4/23 1,255.00 LF 0+00 0+00 0240 9028621 POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V 11/16/23 12/4/23 1.00 EA 0 0 0250 9028810 PULL BOX, PREFORMED CLASS 1 11/16/23 12/4/23 1.00 EA 0 0 0270 9029100 BASE CONCRETE 12/1/23 12/4/23 1.40 CUYD 0+00 0+00

The information below this line are details for Construction Signs (if applicable). No Data Available



# Line Item Adjustments by Estimate

Dec 6, 2023

Contract ID: 230120-C03

oject	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks	
			Туре	Adjustment Type	Number	Date	Ву			
3118E	0070	LUMINAIRE, LED-A	Material		2	Dec 4, 2023	SYSTEM	\$1,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user jamesc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					2	Dec 4, 2023	SYSTEM	(\$1,270.00)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0070 -	Total						\$0.00		
	0080	CABLE, 10 AWG 1 CONDUCTOR,	Material		2	Dec 4, 2023	SYSTEM	\$1,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
		POLE & BRACKE			2	Dec 4, 2023	SYSTEM	(\$1,300.00)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0080 -	Total						\$0.00		
	0090	CABLE, 12 AWG 2 CONDUCTOR	Material		2	Dec 4, 2023	SYSTEM	\$1,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jamesc2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					2	Dec 4, 2023	SYSTEM	(\$1,380.00)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
- 1	0090 -	Total						\$0.00		
	0100		HEAD, TYPE	Material		2	Dec 4, 2023	SYSTEM	\$2,134.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user jamesc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Dec 4, 2023	SYSTEM	(\$2,134.00)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0100 -	Total						\$0.00		
	0110	SIGNAL HEAD, TYPE 3C	Material		2	Dec 4, 2023	SYSTEM	\$6,570.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user jamesc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					2	Dec 4, 2023	SYSTEM	(\$6,570.00)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0110 -	Total						\$0.00		
	0120	SIGNAL HEAD, TYPE 4C	Material		2	Dec 4, 2023	SYSTEM	\$2,990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user jamesc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					2	Dec 4, 2023	SYSTEM	(\$2,990.00)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0120 -	Total						\$0.00		
	0140	SH-FLAT SHEET - SIGNAL SIGN	Material		2	Dec 4, 2023	SYSTEM	\$975.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user jamesc2 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					2	Dec 4, 2023	SYSTEM	(\$975.00)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0140 -	Total						\$0.00		
	0150	SIGNAL SIGN, MOUNTING HARDWARE	Material		2	Dec 4, 2023	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user jamesc2 overridding Payment Estimate Exception 7 on the current Payment Estimate.	



# Line Item Adjustments by Estimate

Dec 6, 2023

Contract ID: 230120-C03

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
P3118E	0150	SIGNAL SIGN, MOUNTING	Material		2	Dec 4, 2023	SYSTEM	(\$2,040.00)	
		HARDWARE		- Total				\$0.00	
			Material - To	otal				\$0.00	
	0150 -	Total						\$0.00	
	0180	SPAN WIRE ASSEMBLY,	Material		2	Dec 4, 2023	SYSTEM	\$7,965.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user jamesc2 overridding Payment
		MESSENGER WITH TETHE			2	Dec 4, 2023	SYSTEM	(\$7,965.00)	Estimate Exception 8 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To					\$0.00	
	0180 -	Total		5101				\$0.00	
					0	D (	OVOTEN		
	0190	CONDUIT, 3 IN., TRENCH WITH TRACER	Material		2	Dec 4, 2023	SYSTEM	\$4,494.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		WIRE			2	Dec 4, 2023	SYSTEM	(\$4,494.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0190 -	Total						\$0.00	
	0210	CABLE, 16 AWG 2 CONDUCTOR	Material		2	Dec 4, 2023	SYSTEM	\$1,960.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					2	Dec 4, 2023	SYSTEM	(\$1,960.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0210 -	Total						\$0.00	
	0220	10 - Total 20 CABLE, 16 AWG 5 CONDUCTOR	CABLE, 16 Material AWG 5		2	Dec 4, 2023	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user jamesc2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					2	Dec 4, 2023	SYSTEM	(\$2,660.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0220 -	Total						\$0.00	
	0230	CABLE, 16 AWG 7 CONDUCTOR	Material		2	Dec 4, 2023	SYSTEM	\$5,434.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user jamesc2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					2	Dec 4, 2023	SYSTEM	(\$5,434.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0230 -	Total						\$0.00	
	0240	POWER SUPPLY ASSEMBLY,	Material		2	Dec 4, 2023	SYSTEM	\$4,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user jamesc2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
		TYPE-2 WITH 120V			2	Dec 4, 2023	SYSTEM	(\$4,500.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0240 -	Total						\$0.00	
	0250		Material		1	Nov 16, 2023	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user jamesc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Nov 16, 2023	SYSTEM	(\$1,750.00)	



# Line Item Adjustments by Estimate

Dec 6, 2023

#### Contract ID: 230120-C03

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3P3118E	0250	PULL BOX, PREFORMED CLASS 1	Material		2	Dec 4, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					2	Dec 4, 2023	SYSTEM	(\$3,500.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0250 -	Total						\$0.00	
	0260	PULL BOX, PREFORMED CLASS 3	Material		1	Nov 16, 2023	SYSTEM	\$3,770.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Nov 16, 2023	SYSTEM	(\$3,770.00)	
					2	Dec 4, 2023	SYSTEM	\$3,770.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user jamesc2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					2	Dec 4, 2023	SYSTEM	(\$3,770.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
0260 - Total							\$0.00		
J3P3118E - Total							\$0.00		
Overall - Total							\$0.00		



There are no contract adjustments to display for this contract.