

Pay Estimate Created Date: November 16, 2023

•		,								
Progress Esti	mato itamboi	Contract ID Prime Contractor	230120-C07 Miles Excavati		Period Start Period End			Net Cha	I Contract Amount ange Order Amount t Contract Amount	\$8,880,959.93 \$85,568.46 \$8,966,528.39
Approval Date										By User
November 16, 2023			Generated a	nd Approved (a	and should be	conside	red Draft) at	the Proj	ect Office Level by	terre
November 17, 2023		Re	eviewed and Ap	proved (and s	should be con	sidered D	raft) at the F	Resident	Engineer Level by	wilso
November 17, 2023				Reviewed a	and Approved	at the Co	entral Office	Controlle	ers Office Level by	ramses
Original Con	pletion Date	Current Com	pletion Date	Actua	al Completion	n Date	%	of Curre	ent Contract Amount	Complete
Decembe	r 15, 2023	December	15, 2023						68.17%	
Co	ontract Informatio	nal Dates					Milestone	es		
Date Description	Original Completion Da	Current te Completion		e Description	Origi Completio		Currer Completion		Days Remaining on Milestone	Diary Charge Days
Acceptance Date			Milest	tone - eletion Date	December 2023	15,	December 2023	15,	28	
Awarded Date	February 8, 2023	February 8, 20	23							
Letting Date	January 20, 2023	3 January 20, 20)23							
Notice to Proceed Date	March 13, 2023	March 13, 202	3							
Open to Traffic Date										
Work Began	March 13, 2023	March 13, 202	3							

Contract Total P	ay For Estimate No. 17			
		This Estimate	Previous	To Date
230120-C07				
	Total Posted Items Pay	\$523,555.29	\$5,588,509.67	\$6,112,064.96
	Gross Item Adjustments	(\$116,263.14)	\$214,336.52	\$98,073.38
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$5,802,846.19	\$6,210,138.34
Contract Total Page 1	ayable This Estimate:	\$407.292.15		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4I3450	0140	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$24.460	77	\$1,883.42
	0150	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$21.980	1,280.8	\$28,151.98
	0210	4039905	MISC.OPTIONAL PAVEMENT - RAMPS 1, 2 & 72ND STREET	SQYD	\$81.150	1,280.8	\$103,936.92
	0250	6071050	CHAIN-LINK FENCE (RETAINING WALLS)	LF	\$63.320	86.2	\$5,458.18
	0310	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$43.050	77	\$3,314.85
	0320	6091011	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	LF	\$39.090	200	\$7,818.00
	0340	6091052	CURB AND GUTTER TYPE B	LF	\$33.960	400	\$13,584.00
	1850	5031010A	BRIDGE APPROACH SLAB (MAJOR)	SQYD	\$267.070	241	\$64,363.87
	1970	7034222	SLAB ON CONCRETE BEAM	SQYD	\$355.120	533.45	\$189,438.76
	2000	7061060	REINFORCING STEEL (BRIDGES)	LB	\$2.980	11,320	\$33,733.60
	2010	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$2.750	15,560	\$42,790.00
	2030	7151001	VERTICAL DRAIN AT END BENTS	EA	\$3,613.270	2	\$7,226.54
	2050	7161002	LAMINATED NEOPRENE BEARING PAD	EA	\$241.930	14	\$3,387.02
	2080	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	LS	\$5,382.150	1	\$5,382.15

Revision 3/23/2023 Page 1 of 52



Pay Estimate Created Date: November 16, 2023

Progress Estimate Number	Contract ID	230120-C07	•	,	Original Contract Amount	. , ,
17	Prime Contractor	Miles Excavating, Inc.	Pay Period End	November 15, 2023	Net Change Order Amount	\$85,568.46
"					Current Contract Amount	\$8,966,528.39

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4I3450	2090	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	LS	\$3,165.970	1	\$3,165.97
	2120	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	LS	\$6,120.870	1	\$6,120.87
	2130	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	LS	\$3,799.160	1	\$3,799.16
Project J4I345	0 - Total						\$523,555.29
Overall - Total							\$523,555.29

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

roject umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
113450	0010	TEMPORARY SURFACING	Material			-55	\$58.39	(\$3,211.45
	0010	TEMPORARY SURFACING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0042) due to user terrej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	55	\$58.39	\$3,211.45
	0040	EMBANKMENT IN PLACE	Material			-6,459	\$13.27	(\$85,710.93)
	0040	EMBANKMENT IN PLACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0043) due to user terrej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	6,459	\$13.27	\$85,710.93
	0050	COMPACTING EMBANKMENT	Material			-2,293	\$4.93	(\$11,304.49)
	0050	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0044) due to user terrej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	2,293	\$4.93	\$11,304.49
	0140	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-1,712.15	\$24.46	(\$41,879.19)
	0140	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0045) due to user terrej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	1,712.15	\$24.46	\$41,879.19
	0150	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-7,156.1	\$21.98	(\$157,291.08)
	0150	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0046) due to user terrej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	7,156.1	\$21.98	\$157,291.08
	0170	MISC.	Material			-1,820.4	\$77.19	(\$140,516.68)
	0170	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0047) due to user terrej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	1,820.4	\$77.19	\$140,516.68
	0210	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$7,263.52)
	0230	CONCRETE APPROACH PAVEMENT	Material			-398.15	\$101.28	(\$40,324.63)
	0230	CONCRETE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0048) due to user terrej1	398.15	\$101.28	\$40,324.63

Revision 3/23/2023 Page 2 of 52



Pay Estimate Created Date: November 16, 2023

Contract ID 230120-C07 Pay Period Start November 2, 2023 Original Contract Amount \$8,880,959.

Prime Contractor Miles Excavating, Inc. Pay Period End November 15, 2023 Original Contract Amount \$85,568.46 Current Contract Amount \$8,966,528. **Progress Estimate Number** \$8,880,959.93 17 \$8,966,528.39

	_ine No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
60					overridding Payment Estimate Exception 14 on the current Payment Estimate.			
0	250	CHAIN-LINK FENCE (RETAINING WALLS)	Material			-86.2	\$63.32	(\$5,458.1)
0:	250	CHAIN-LINK FENCE (RETAINING WALLS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0049) due to user terrej1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	86.2	\$63.32	\$5,458.18
0	350	PAVED DITCH	Material			-29	\$138.15	(\$4,006.35
0	350	PAVED DITCH	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0050) due to user terrej1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	29	\$138.15	\$4,006.3
0	570	TEMPORARY TRAFFIC BARRIER STIFFNESS TRANSITION SECTION, CONTRACTOR FURNISHED / RETAINED	Material			-425	\$36.94	(\$15,699.50
0	570	TEMPORARY TRAFFIC BARRIER STIFFNESS TRANSITION SECTION, CONTRACTOR FURNISHED / RETAINED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0059) due to user terrej1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	425	\$36.94	\$15,699.50
0	0880	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material			-1,313	\$2.27	(\$2,980.5
0	680	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0060) due to user terrej1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	1,313	\$2.27	\$2,980.51
0	690	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material			-664	\$2.27	(\$1,507.28
0	690	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0061) due to user terrej1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	664	\$2.27	\$1,507.28
1	080	CONDUIT, 3 IN. RIGID, PUSHED	Material			-161	\$33.30	(\$5,361.30
1	080	CONDUIT, 3 IN. RIGID, PUSHED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0051) due to user terrej1 overridding Payment Estimate Exception 41 on the current Payment Estimate.	161	\$33.30	\$5,361.30
1	110	PULL BOX, PREFORMED CLASS 1	Material			-3	\$1,728.62	(\$5,185.86
1	110	PULL BOX, PREFORMED CLASS 1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0052) due to user terrej1 overridding Payment Estimate Exception 42 on the current Payment Estimate.	3	\$1,728.62	\$5,185.86
1	140	MISC.	Material			-6	\$1,259.00	(\$7,554.00
1	140	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0053) due to user terrej1 overridding Payment Estimate Exception 43	6	\$1,259.00	\$7,554.00

Page 3 of 52 Revision 3/23/2023

Pay Estimate Created Date: November 16, 2023

Contract ID 230120-C07 Pay Period Start November 2, 2023 Original Contract Amount \$8,880,959.

Prime Contractor Miles Excavating, Inc. Pay Period End November 15, 2023 Original Contract Amount \$85,568.46 Current Contract Amount \$8,966,528. \$8,880,959.93 **Progress Estimate Number** 17 \$8,966,528.39

ct er	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
50					on the current Payment Estimate.			
	1290	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material			-360	\$17.47	(\$6,289.20
	1290	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0054) due to user terrej1 overridding Payment Estimate Exception 44 on the current Payment Estimate.	360	\$17.47	\$6,289.20
	1300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material			-867	\$33.30	(\$28,871.10
	1300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0055) due to user terrej1 overridding Payment Estimate Exception 45 on the current Payment Estimate.	867	\$33.30	\$28,871.10
	1350	POWER SUPPLY ASSEMBLY, TYPE 2	Material			-1	\$6,151.48	(\$6,151.48
	1350	POWER SUPPLY ASSEMBLY, TYPE 2	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0056) due to user terrej1 overridding Payment Estimate Exception 46 on the current Payment Estimate.	1	\$6,151.48	\$6,151.48
	1360	PULL BOX, PREFORMED CLASS 2	Material			-10	\$2,124.36	(\$21,243.60
	1360	PULL BOX, PREFORMED CLASS 2	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0057) due to user terrej1 overridding Payment Estimate Exception 47 on the current Payment Estimate.	10	\$2,124.36	\$21,243.60
	1370	PULL BOX, PREFORMED CLASS 3	Material			-2	\$2,955.96	(\$5,911.92
	1370	PULL BOX, PREFORMED CLASS 3	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0058) due to user terrej1 overridding Payment Estimate Exception 48 on the current Payment Estimate.	2	\$2,955.96	\$5,911.92
	1520	CONDUIT, 2 IN., RIGID, IN TRENCH	Material			-364	\$13.30	(\$4,841.20
	1520	CONDUIT, 2 IN., RIGID, IN TRENCH	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0062) due to user terrej1 overridding Payment Estimate Exception 49 on the current Payment Estimate.	364	\$13.30	\$4,841.20
	1530	CONDUIT, 4 IN., RIGID, IN TRENCH	Material			-79	\$21.79	(\$1,721.41
	1530	CONDUIT, 4 IN., RIGID, IN TRENCH	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0063) due to user terrej1 overridding Payment Estimate Exception 50 on the current Payment Estimate.	79	\$21.79	\$1,721.41
	1540	CONDUIT, 3 IN., RIGID, PUSHED	Material			-151	\$33.30	(\$5,028.30
	1540	CONDUIT, 3 IN., RIGID, PUSHED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0064) due to user terrej1 overridding Payment Estimate Exception 51 on the current Payment Estimate.	151	\$33.30	\$5,028.30
	1560	PULL BOX, PREFORMED CLASS 5	Material			-2	\$2,898.97	(\$5,797.94)

Page 4 of 52 Revision 3/23/2023



Pay Estimate Created Date: November 16, 2023

Progress Estimate Number
17

Contract ID 230120-C07 Pay Period Start November 2, 2023 November 15, 2023 November 2, 2023 November 15, 2023 November 2, 2023 November 15, 2023 November 15, 2023 November 2, 2023 November 15, 2023 November 2, 2023 Nov

Line r No.		Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
156	PULL BOX, PREFORMED CLASS 5	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0065) due to user terrej1 overridding Payment Estimate Exception 52 on the current Payment Estimate.	2	\$2,898.97	\$5,797.94
162	BRIDGE APPROACH SLAB (MAJOR)	Material			-241	\$267.07	(\$64,363.87)
162	BRIDGE APPROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0066) due to user terrej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	241	\$267.07	\$64,363.87
174	FORM LINERS	Material			-34	\$251.94	(\$8,565.96
174) FORM LINERS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0067) due to user terrej1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	34	\$251.94	\$8,565.96
179	VERTICAL DRAIN AT END BENTS	Material			-2	\$3,613.27	(\$7,226.54)
179	VERTICAL DRAIN AT END BENTS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0068) due to user terrej1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	2	\$3,613.27	\$7,226.54
185	BRIDGE APPROACH SLAB (MAJOR)	Material			-241	\$267.07	(\$64,363.87)
185	BRIDGE APPROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0069) due to user terrej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	241	\$267.07	\$64,363.87
187	DRILLED SHAFTS (5 FT. 0 IN. DIA.)	Material			-45.1	\$513.14	(\$23,142.61)
187	D DRILLED SHAFTS (5 FT. 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0070) due to user terrej1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	45.1	\$513.14	\$23,142.61
192	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material			-545	\$88.48	(\$48,221.60)
192	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0071) due to user terrej1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	545	\$88.48	\$48,221.60
194	PILE POINT REINFORCEMENT	Material			-15	\$110.81	(\$1,662.15)
194	PILE POINT REINFORCEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0072) due to user terrej1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	15	\$110.81	\$1,662.15
195	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-106.2	\$1,148.95	(\$122,018.49)
195	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0073) due to user terrej1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	106.2	\$1,148.95	\$122,018.49

Revision 3/23/2023 Page 5 of 52



Pay Estimate Created Date: November 16, 2023

Contract ID 230120-C07 Pay Period Start November 2, 2023 Original Contract Amount \$8,880,959.

Prime Contractor Miles Excavating, Inc. Pay Period End November 15, 2023 Net Change Order Amount Current Contract Amount \$8,966,528. \$8,880,959.93 **Progress Estimate Number** 17 \$8,966,528.39

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3450	1970	SLAB ON CONCRETE BEAM	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$30,611.93)
	1970	SLAB ON CONCRETE BEAM	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$34,861.29)
	1970	SLAB ON CONCRETE BEAM	Material			-675.65	\$355.12	(\$239,936.83)
	1970	SLAB ON CONCRETE BEAM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0074) due to user terrej1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	675.65	\$355.12	\$239,936.83
	2010	REINFORCING STEEL (EPOXY COATED)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$41,846.40)
	2030	VERTICAL DRAIN AT END BENTS	Material			-2	\$3,613.27	(\$7,226.54)
	2030	VERTICAL DRAIN AT END BENTS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0075) due to user terrej1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	2	\$3,613.27	\$7,226.54
	2050	LAMINATED NEOPRENE BEARING PAD	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$1,680.00)
	2080	CONCRETE AND MASONRY PROTECTION SYSTEM	Material			-1	\$5,382.15	(\$5,382.15)
	2080	CONCRETE AND MASONRY PROTECTION SYSTEM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0076) due to user terrej1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	1	\$5,382.15	\$5,382.15
	2100	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-4,205	\$114.73	(\$482,439.65)
	2100	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0077) due to user terrej1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	4,205	\$114.73	\$482,439.65
	2120	CONCRETE AND MASONRY PROTECTION SYSTEM	Material			-1	\$6,120.87	(\$6,120.87)
	2120	CONCRETE AND MASONRY PROTECTION SYSTEM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0078) due to user terrej1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	1	\$6,120.87	\$6,120.87
	2140	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-3,804	\$113.98	(\$433,579.92)
	2140	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0079) due to user terrej1 overridding Payment Estimate Exception 39 on the current Payment Estimate.	3,804	\$113.98	\$433,579.92
	5007	MISC.	Material			-1,043	\$45.87	(\$47,842.41)
	5007	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0040) due to user terrej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	1,043	\$45.87	\$47,842.41
	5008	MISC.	Material			-1,043	\$3.19	(\$3,327.17)

Revision 3/23/2023 Page 6 of 52



Pay Estimate Created Date: November 16, 2023

Progr	ess Es	timate Number 17	Contract ID Prime Cont		0-C07 Excavating, Inc	. Pay Period End November 15, 2023 Net	inal Contrac Change Orde rent Contract	r Amount	\$8,880,959.93 \$85,568.46 \$8,966,528.39
Project Number	Line No.	Item Descri	ption	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3450	5008		MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0041) due to user terrej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	,	\$3.19	\$3,327.17
Total									(\$116,263.14)

Revision 3/23/2023 Page 7 of 52



					(Contract Project Information	on			
Project Number										
J4I3450	I 29-1(133)	2 Bridge replacements	I-29	PLATTE	at 72nd Street interchange	e in Platte Woods				
Totals by .	Job Numbe	ers								
J4I3450		ed Item Pay s Item Adjustme		Item Pay	This Estimate \$523,555.29 (\$116,263.14) \$407,292.15	Previous \$5,588,509.67 \$214,336.52 \$5,802,846.19	To Date \$6,112,064.96 \$98,073.38 \$6,210,138.34			
	Liqui	itive centive dated Damages r Contract Adjus			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			

Revision 3/23/2023 Page 8 of 52



Exceptions (Discrepancies) This Estimate Period

Name of 2010. Material Set 10100008, Material to 90115 - Temporary Surfacing, Accordance Action Genetic (1014) is in inflamental Exception Type Insulfacent Materials (1000008). The property of the 10100008 (Insulfacent Composition) is a surfacent of 10100008. The property of 10100008 (Insulfacent Composition) is a surfacent of 10100008. The property of 10100008 (Insulfacent Composition) is a surfacent of 10100008. The property of 10100008 (Insulfacent Composition) is a surfacent of 10100008. The property of 10100008 (Insulfacent Composition) is a surfacent of 10100008. The property of 10100008 (Insulfacent Composition) is a surfacent of 10100008. The property of 10100008 (Insulfacent Composition) is a surfacent of 101000008. The property of 10100008 (Insulfacent Composition) is a surfacent of 101000008. The property of 10100008 (Insulfacent Composition) is a surfacent of 101000008. The property of 10100008 (Insulfacent Composition) is a surfacent composition of 10100008 (Insulfacent Composition) is a surfacent composition of 101000008 (Insulfacent Composition) is a surfacent composition of 101000000000000000000000000000000000	Exceptions (Discrepancies) This Estimate Period			
Number 0010, Material Set 1344 (1000), Mater	Exceptions / Discrepencies	Explanation		Status
Namer (2004), Nameria Set 200500008, Mariani (20000005 - Compaced Soit No Silagado Frimmatinent, Augustina Anton Graner (2000005 - Sendandos) Frimmatinent, Augustina Anton Graner (20000005 - Sendandos) Frimmatinent Augustina (2000005 - Sendandos) Frimmatina (2000005 - Sendandos) Frimmatinent Augustina (2000005 - Sendandos) Frimm	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 1041000, Project Item Line Number 0010, Material Set 104100096, Material 0104TS - Temporary Surfacing, Acceptance Action Generic 0104TS is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number DOD, Material Sci 2000000000000000000000000000000000000	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 2035500, Project Item Line Number 0040, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Standard Exception Type: Insulficion Materials: Project Jul 500, The Description of Type: Insulficion Materials: Project Jul 500, The Description Type: Insulficion Materials: Description Type: Insulficion Material Dol 500, The Description Type: Insulficion Materials: Description Type: Insulficion Materials: Project Jul 500, The Description Type: Insulficion Materials: P	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 2036000, Project Item Line Number 0050, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 6005, Malerial Set 21 (1967) Per Instillician Malerials Project July 15 (1967) Per Instillician Malerial (1967) Per Instillician Maler	Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 2149907, Project Item Line Number 5007, Material Set 214990796, Material 0214STRF - Stone for Rock Fill, Acceptance Action Generic 0214STRF is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 1010, Malerials Sch 1540:600-68, Materials (2016-58511-14) For southflown). Estimate Exception Type: Insufficient Materials Project Julians 304:500-69, Project Item Line Literation of Control (2016-5811-169) For southflown). Literation School (2016-291-1691-1691-1691-1691-1691-1691-169	Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 2149907, Project Item Line Number 5008, Material Set 214990796, Material 0214STRF - Stone for Rock Fill, Acceptance Action Generic 0214STRF is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 1050, Material Set 300505668, Material 030548ET156P - Compacted Type 1 & 5 Base, Acceptance Action Generic 030548ET156P is institilicent. Estimate Exception Type: Institilicent Materials: Project Justine 1000 (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (19	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 3040504, Project Item Line Number 0140, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 1070, Material Set 401906968, Material 1057-MDBEC 3.11 – Dowel Bar Epoxy Cld Gr80 1 1/4 (A. Acceptance Action Generic ReinforcingMase is insufficient Estimate Exception Type: Insufficient Materials: Project 418450, Item 5031010A, Project Item Line No Remark was entered by Engineer No	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 3040506, Project Item Line Number 0150, Material Set 304050696, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 1920, Material Set 5031010A96, Material 1013DMCRPE_04 - Underdrain Corrupated PE (*100mm), Acceptance Action Genetic 1013DMCRPE_04 is insufficient. Estimate Exception Type: Insufficient Materials: Project 4II13450, Item 5031010A9, Project Item Line Number 1920, Material Set 5031010A96, Material 1058PSBB is insufficient. Estimate Exception Type: Insufficient Materials: Project 4II13450, Item 5031010A9, Project Item Line Number 1820, Material Set 5031010A96, Material 1058PSBB is insufficient. Estimate Exception Type: Insufficient Materials: Project 4II13450, Item 5031010A9, Project Item Line Number 1850, Material Set 5031010A96, Material 1058PSBB is insufficient. Estimate Exception Type: Insufficient Materials: Project 4II13450, Item 5031010A9, Project Item Line Number 1850, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Genetic 0158PSBB is insufficient. Estimate Exception Type: Insufficient Materials: Project 4II13450, Item 5031010A9, Project Item Line Number 1850, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Genetic 0158PSBB is insufficient. Estimate Exception Type: Insufficient Materials: Project 4II13450, Item 5041000, Project Item Line Number 1850, Material Set 50410008, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Genetic Genetic of Set 5041000, Project Item Line Number 1050, Material Set 50410008, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Genetic Genetic Genetic Action Set 50410009, Relaterial 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Genetic Relaterial Polyethylene Sheeting for Bond Breaker, Acceptance Action Genetic Relaterial Polyethylene Sheeting for Bond Breaker, Acceptance Action Genetic Relaterial Polyethylene Sheeting for Bond Breaker, Acceptance Action Genetic Relaterial Polyethylene Sheeting for Bond Breaker, Acceptance Action Genetic Relaterial Polyethylene Sheeting Breaker, A	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 4019905, Project Item Line Number 0170, Material Set 401990596, Material 1057JMDBEC6.11 - Dowel Bar Epoxy Ctd Gr60 1 1/4 @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 1820, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is institutional. White Public Proceedings of the Process of the Pro	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 5031010A, Project Item Line Number 1620, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 1850, Malerial Set 5031010A96, Material OSI CCPAQCQA - Concrete, Pawment contractor mix or COCA, Acceptance Action Generic 0501 CCPAQCQA is insufficient. Number 1850, Material Set 5031010A96, Material of 1030MCRPE. 04 is Insufficient. Number 1850, Material Set 5031010A96, Material of 1030MCRPE. 04 is Insufficient. Settlement (1950) Project Item Line Number 1850, Material Set 5031010A96, Material of 1030MCRPE. 04 is Insufficient. Settlement (1950) Project Item Line Number 1850, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1038PSB is Insufficient. Settlement (1950) Project Item Line Number 1850, Material Set 5031010A96, Material 1057AMTBE28019 - The Bar Ep Cit 40 No. 6MH9 Gr. No.	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 5031010A, Project Item Line Number 1620, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 1850, Material Set 5031010A96, Material 1013DMCRPE. 04 i Instificient. Estimate Exception Type: Insufficient Materials: Project, 1413450, Item 5031010A, Project Item Line Number 1850, Material Set 5031010A96, Material 1013DMCRPE. 04 is insufficient. Estimate Exception Type: Insufficient Materials: Project, 1413450, Item 5031010A, Project Item Line Number 1020, Material Set 5031010A96, Material 1057JMTBE28019 - The Bar Ep Cld 40°No. 6M19 Gr 40M280Q8, Acceptance Action Generic 1058PSBBS is insufficient. Estimate Exception Type: Insufficient Materials: Project 1413450, Item 5041000, Project Item Line Number 0230, Material Set 50410098, Material 1057JMTBE28019 - The Bar Ep Cld 40°No. 6M19 Gr 40M280Q8, Acceptance Action Generic National Materials Project 1413450, Item 5041000, Project Item Line Number 0230, Material Set 50410098, Material 1013DMCRPE. 04 insufficient. Estimate Exception Type: Insufficient Materials: Project 1413450, Item 5041000, Project Item Line Number 0230, Material Set 50410098, Material 1013DMCRPE. 04 insufficient. Estimate Exception Type: Insufficient Materials: Project 1413450, Item 5041000, Project Item Line Number 0230, Material Set 50410098, Material 1013DMCRPE. 04 insufficient. Estimate Exception Type: Insufficient Materials: Project 1413450, Item 5041000, Project Item Line Number 0230, Material Set 607105098, Material 1043FMCLFB2C60 - Chain Link Fence Fabric Galvin Stell 60°, Acceptance Action Generic 1043FMCLFB2C60 insufficient. Estimate Exception Type: Insufficient Materials: Project 1413450, Item 6071050, Project Item Line Number 0230, Material Set 607105098, Material 1043FMCLFB2C60 insufficient. Estimate Exception Type: Insufficient Materials: Project 1413450, Item 6071050, Project Item Line Number 0250, Material Set 607105098, Material 1043FMCLFB2C60 insufficient. Estimate Exception Type: Insufficient Materials: Project 1413450, Item 6071050, Project Item Line Number 0300, Material Set 607105098, Material 1043FMCLFB2C60 insufficient. Estimate Exception Type: Insuffic	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 5031010A, Project Item Line Number 1850, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 1850, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generio 1058PSBB is insufficient. Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 5041000, Project Item Line Number 0230, Material Set 504100096, Material Set 50410096, Material Set 5	Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 5031010A, Project Item Line Number 1850, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 0230, Material Set 504100096, Material 1057JMTBE28019 - Tie Bar Ep Cid 40" No. 6/M19 Gr 40/M280@, Acceptance Action Generic ReinforrigiMIsc is insufficient. Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 5041000, Project Item Line Number 0230, Material Set 504100096, Material 1013DMCRPE 04 - Underdrain Corrugated PE 4"(100mm), Acceptance Action Generic 1013DMCRPE 04 - Underdrain Corrugated PE 4"(100mm), Acceptance Action Generic 1013DMCRPE 04 - Underdrain Corrugated PE 4"(100mm), Acceptance Action Generic 1013DMCRPE 04 - Underdrain Corrugated PE 4"(100mm), Acceptance Action Generic 0103DMCRPE 04 - Underdrain Corrugated PE 4"(100mm), Acceptance Action Generic 0103DMCRPE 04 - Underdrain Corrugated PE 4"(100mm), Acceptance Action Generic 01045MCRPE 04 - Underdrain Corrugated PE 4"(100mm), Acceptance Action Generic 01045MCRPE 04 - Underdrain Corrugated PE 4"(100mm), Acceptance Action Generic 01045MCRPE 04 - Underdrain Corrugated PE 4"(100mm), Acceptance Action Generic 01045MCRPE 04 - Underdrain Corrugated PE 4"(100mm), Acceptance Action Generic 01045MCRPE 04 - Underdrain Corrugated PE 4"(100mm), Acceptance Action Generic 10435MCLFBAC60 - Chain Link Fence Fabric Alum Coated 60", Acceptance Action Generic 10435MCLFBAC60 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 6091060, Project Item Line Number 0350, Material Set 6173706, Material 1036RSWFPLVIV014 - W014 - Plain Welded Wire Fabric @, Acceptance Action Generic ReSteelFabric is insufficient. Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 6173706, Project Item Line Number 0570, Material Set 6173706, M	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 5031010A, Project Item Line Number 1850, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 0230, Material Set 504100096, Material 1013DMCRPE04 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6071050, Project Item Line Number 0230, Material Set 504100096, Material 10501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 1043FMCLFB2C60 - Chain Link Fence Fabric Galvin Steel 60°, Acceptance Action Generic 1043FMCLFB2C60 - Chain Link Fence Fabric Galvin Steel 60°, Acceptance Action Generic 1043FMCLFB2C60 - Chain Link Fence Fabric Galvin Steel 60°, Acceptance Action Generic 1043FMCLFB2C60 - Chain Link Fence Fabric Galvin Steel 60°, Acceptance Action Generic 1043FMCLFB2C60 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6071050, Project Item Line Number 0250, Material Set 607105096, Material 1043FMCLFBAC60 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6071050, Project Item Line Number 0350, Material Set 607105096, Material 1043FMCLFBAC60 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6091060, Project Item Line Number 0350, Material Set 609106096, Material 1036SSWFPLW014 - W01.4 Plain Welded Wire Fabric @, Acceptance Action Generic ReSteelFabric is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6173706, Project Item Line Number 0570, Material Set 6173706, Material 6017MBPKBT.1PC - Jone Piece Barrier Height-Transition Sect., Acceptance Action Generic 0017MBPKBT.1PC is mixificient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6173706, Project Item Line Number 0570, Material Set 6173706, Material 6017MBPKBT.1PC - Insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6205301B, Project Item Line Number 0570, Material Set 6105301B96, Material 5047MBPKBT.2PC - Two Piece Barrier Height-Transition Sect., Acceptance Action Generic 0017MBPKBT.2PC is mixificient. Estimate Exception Type: Insufficient Materials: Project J4I	Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 5041000, Project Item Line Number 0230, Material Set 504100096, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 0230, Material Set 504100096, Material S01CCPAQCA - Concrete, Pavment contractor mix or QCQA, Acceptance Action 0501CCPAQCQA Pavement is insufficient. Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 6071050, Project Item Line Number 0250, Material Set 607105096, Material O43FMCLFBZC60 - Chain Link Fence Fabric Galvin Steel 60°, Acceptance Action Generic 1043FMCLFBZC60 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 6071050, Project Item Line Number 0250, Material Set 607105096, Material 1043FMCLFBZC60 - Chain Link Fence Fabric Alum Coated 60°, Acceptance Action Generic 1043FMCLFBZC60 - Chain Link Fence Fabric Alum Coated 60°, Acceptance Action Generic 1043FMCLFBZC60 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 6091060, Project Item Line Number 0350, Material Set 609106096, Material 1036RSWFPLW014 - W01.4 Plain Welded Wire Fabric @, Acceptance Action Generic ReSteelFabric is insufficient. Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 6173706, Project Item Line Number 0370, Material Set 6173706, Material Set 61	Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 5041000, Project Item Line Number 0230, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 0250, Material Set 607105096, Material 1043FMCLFBZC60 - Chain Link Fence Fabric Galvin Steel 60°, Acceptance Action Generic 1043FMCLFBZC60 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6071050, Project Item Line Number 0250, Material Set 607105096, Material 1043FMCLFBAC60 - Chain Link Fence Fabric Alum Coated 60°, Acceptance Action Generic 1043FMCLFBAC60 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 607106, Project Item Line Number 0350, Material Set 609106096, Material 1043FMCLFBAC60 - Chain Link Fence Fabric Alum Coated 60°, Acceptance Action Generic 1043FMCLFBAC60 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6173706, Project Item Line Number 0570, Material Set 609106096, Material O617MBPKBT.1PC - One Piece Barrier Height-Transition Sect, Acceptance Action Generic 0617MBPKBT.1PC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6173706, Project Item Line Number 0570, Material Set 6173706, Material O617MBPKBT.2PC - Two Piece Barrier Height-Transition Sect, Acceptance Action Generic 0617MBPKBT.2PC - Two Piece Barrier Height-Transition Sect, Acceptance Action Generic 0617MBPKBT.2PC - Two Piece Barrier Height-Transition Sect, Acceptance Action Generic 0617MBPKBT.2PC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 62053018, Project Item Line Number 0680, Material Set 6205301896, Material 1048PMRPMTWH - Marking Tape Removable White, Acceptance Action Generic 1048PMRPMTWH is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 62053038, Project Item Line Number 0690, Material Set 6205303896, Material 1048PMRPMTYL - Marking Tape Removable Yellow, Acceptance Action Generic 1048PMRPMTYL is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 62053038, Project Item Line No Remark was entered by Engineer No Remark was entered by Engineer Vov	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 5041000, Project Item Line Number 0230, Material Set 504100096, Material 0501CCPAQCQA - Concrete, Payment contractor mix or QCQA, Acceptance Action 0501CCPAQCQA Payement is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 0250, Material Set 607105096, Material 1043FMCLFBAC60 - Chain Link Fence Fabric Alum Coated 60", Acceptance Action Generic 1043FMCLFBAC60 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6091060, Project Item Line Number 0350, Material Set 609106096, Material 1036RSWFPLW014 - W01.4 Plain Welded Wire Fabric @, Acceptance Action Generic ReSteelFabric is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6173706, Project Item Line Number 0570, Material Set 6173706, Material 0617MBPKBT.1PC - One Piece Barrier Height-Transition Sect, Acceptance Action Generic 0617MBPKBT.1PC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6173706, Project Item Line Number 0570, Material Set 6173706, Material 0617MBPKBT.2PC - Two Piece Barrier Height-Transition Sect, Acceptance Action Generic 0617MBPKBT.2PC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6205301B, Project Item Line Number 0680, Material Set 6205301B96, Material 1048PMRPMTWH - Marking Tape Removable White, Acceptance Action Generic 1048PMRPMTWH is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6205303B, Project Item Line Number 0690, Material Set 6205303B96, Material 1048PMRPMTYL - Marking Tape Removable Yellow, Acceptance Action Generic 1048PMRPMTYL is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6205303B, Project Item Line Number 0690, Material Set 6205303B96, Material 1048PMRPMTYL - Marking Tape Removable Yellow, Acceptance Action Generic 1048PMRPMTYL is insufficient. No Remark was entered by Engineer Voerridden No Remark was entered by Engineer Voerridden No Remark was entered by Engineer No Remark was entered by Engineer Voerridden No Remark was entered by Engineer	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6071050, Project Item Line Number 0250, Material Set 607105096, Material 1043FMCLFBZC60 - Chain Link Fence Fabric Galvin Steel 60", Acceptance Action Generic 1043FMCLFBZC60 is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 0350, Material Set 609106096, Material 1036RSWFPLW014 - W01.4 Plain Welded Wire Fabric @, Acceptance Action Generic ReSteelFabric is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6173706, Project Item Line Number 0570, Material Set 6173706, Material 0617MBPKBT.1PC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6173706, Project Item Line Number 0570, Material Set 6173706, Material 0617MBPKBT.2PC - Two Piece Barrier Height-Transition Sect, Acceptance Action Generic 0617MBPKBT.2PC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6205301B, Project Item Line Number 0680, Material Set 6205301B96, Material 1048PMRPMTVH - Marking Tape Removable White, Acceptance Action Generic 1048PMRPMTVH is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6205303B, Project Item Line Number 0680, Material Set 6205303B96, Material 1048PMRPMTVH - Marking Tape Removable White, Acceptance Action Generic 1048PMRPMTYL is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6205303B, Project Item Line Number 0690, Material Set 6205303B96, Material 1048PMRPMTYL - Marking Tape Removable Yellow, Acceptance Action Generic 1048PMRPMTYL is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6205303B, Project Item Line No Remark was entered by Engineer terrej1 Overridden Voerridden Voerridden Voerridden Voerridden Voerridden Voerridden	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6071050, Project Item Line Number 0250, Material Set 607105096, Material 1043FMCLFBAC60 - Chain Link Fence Fabric Alum Coated 60", Acceptance Action Generic 1043FMCLFBAC60 is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 0570, Material Set 6173706, Material 0617MBPKBT.1PC - One Piece Barrier Height-Transition Sect, Acceptance Action Generic 0617MBPKBT.1PC is insufficient. No Remark was entered by Engineer No Remark was entered by Engineer No Remark was entered by Engineer terrej1 Overridden No Remark was entered by Engineer No Remark was entered by Engineer Terrej1 Overridden No Remark was entered by Engineer No Remark was entered by Engineer Terrej1 Overridden	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6091060, Project Item Line Number 0350, Material Set 609106096, Material 1036RSWFPLW014 - W01.4 Plain Welded Wire Fabric @, Acceptance Action Generic ReSteelFabric is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 0570, Material Set 6173706, Material 0617MBPKBT.2PC - Two Piece Barrier Height-Transition Sect, Acceptance Action Generic 0617MBPKBT.2PC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6205301B, Project Item Line Number 0680, Material Set 6205301B96, Material 1048PMRPMTWH - Marking Tape Removable White, Acceptance Action Generic 1048PMRPMTWH is insufficient. Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6205303B, Project Item Line Number 0690, Material Set 6205303B96, Material 1048PMRPMTYL - Marking Tape Removable Yellow, Acceptance Action Generic 1048PMRPMTYL is insufficient. No Remark was entered by Engineer terrej1 Overridden No Remark was entered by Engineer terrej1	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6173706, Project Item Line Number 0570, Material Set 6173706, Material 0617MBPKBT.1PC - One Piece Barrier Height-Transition Sect, Acceptance Action Generic 0617MBPKBT.1PC is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 0680, Material Set 6205301B96, Material 1048PMRPMTWH - Marking Tape Removable White, Acceptance Action Generic 1048PMRPMTWH is insufficient. Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 6205303B, Project Item Line Number 0690, Material Set 6205303B96, Material 1048PMRPMTYL - Marking Tape Removable Yellow, Acceptance Action Generic 1048PMRPMTYL is insufficient. Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 7011108, Project Item Line No Remark was entered by Engineer terrej1 Overridden	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6173706, Project Item Line Number 0570, Material Set 6173706, Material 0617MBPKBT.2PC - Two Piece Barrier Height-Transition Sect, Acceptance Action Generic 0617MBPKBT.2PC is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Number 0690, Material Set 6205303B96, Material 1048PMRPMTYL - Marking Tape Řemovable Yellow, Acceptance Action Generic 1048PMRPMTYL is insufficient. Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 7011108, Project Item Line No Remark was entered by Engineer terrej1 Overridden	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6205301B, Project Item Line Number 0680, Material Set 6205301B96, Material 1048PMRPMTWH - Marking Tape Removable White, Acceptance Action Generic 1048PMRPMTWH is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 6205303B, Project Item Line Number 0690, Material Set 6205303B96, Material 1048PMRPMTYL - Marking Tape Removable Yellow, Acceptance Action Generic 1048PMRPMTYL is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
	Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 7011108, Project Item Line Number 1870, Material Set 701110896, Material 0701PLCA - Casing for Drilled Shafts, Acceptance	No Remark was entered by Engineer	terrej1	Overridden

Revision 3/23/2023 Page 9 of 52



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Action Generic 0701PLCA is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 7011108, Project Item Line Number 1870, Material Set 701110896, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 7021212, Project Item Line Number 1920, Material Set 702121296, Material 0702PLSSMAZC - Bearing Piles Struct Steel Galvd, Acceptance Action Generic 0702PLSSMAZC is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 7027000, Project Item Line Number 1940, Material Set 702700096, Material 0702PLPT - Pile Point Reinforcement, Acceptance Action Generic 0702PLPT is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 7032003, Project Item Line Number 1950, Material Set 703200396, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 7032003, Project Item Line Number 1950, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 7034222, Project Item Line Number 1970, Material Set 703422296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 7034620, Project Item Line Number 1740, Material Set 703462096, Material 3099XXAS - Aesthetic Items on Project, Acceptance Action Generic 3099XXAS is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 7110300, Project Item Line Number 2080, Material Set 711030096, Material 1059PCCCCMPS - Concrete - Masonry Protective Sealer, Acceptance Action Generic 1059PCCCCMPS is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 7110300, Project Item Line Number 2120, Material Set 711030096, Material 1059PCCCCMPS - Concrete - Masonry Protective Sealer, Acceptance Action Generic 1059PCCCCMPS is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 7151001, Project Item Line Number 1790, Material Set 715100196, Material 0715DRVT - Vertical Drain at End Bents, Acceptance Action Generic 0715DRVT is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 7151001, Project Item Line Number 2030, Material Set 715100196, Material 0715DRVT - Vertical Drain at End Bents, Acceptance Action Generic 0715DRVT is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 7201000, Project Item Line Number 2100, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved Design, Acceptance Action Generic 0720MSEW is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 7201000, Project Item Line Number 2100, Material Set 720100096, Material 1013DMCRPE06 - Underdrain Corrugated PE 6" (150mm), Acceptance Action Generic 1013DMCRPE06 is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 7201000, Project Item Line Number 2100, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 7201000, Project Item Line Number 2140, Material Set 720100096, Material 1013DMCRPE06 - Underdrain Corrugated PE 6" (150mm), Acceptance Action Generic 1013DMCRPE06 is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 7201000, Project Item Line Number 2140, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 9014003, Project Item Line Number 1080, Material Set 901400396, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 9016110, Project Item Line Number 1110, Material Set 901611096, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3450, Item 9019902, Project Item Line Number 1140, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 9025300, Project Item Line Number 1290, Material Set 902530096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 9027300, Project Item Line Number 1300, Material Set 902730096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 9028620, Project Item Line Number 1350, Material Set 902862096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 9028811, Project Item Line Number 1360, Material Set 902881196, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 9028812, Project Item Line	No Remark was entered by Engineer	terrej1	Overridden

Revision 3/23/2023 Page 10 of 52



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Number 1370, Material Set 902881296, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 9105200, Project Item Line Number 1520, Material Set 910520096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 9105202, Project Item Line Number 1530, Material Set 910520296, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 9107201, Project Item Line Number 1540, Material Set 910720196, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3450, Item 9108816, Project Item Line Number 1560, Material Set 910881696, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	No Remark was entered by Engineer	terrej1	Overridden
Estimate Exception Type: Item Overrun: Contract 230120-C07, Contract Project J4I3450, Project Item Line Number 1870, Contract Line Item Number 1870, Item 7011108, Minor Item.	No Remark was entered by Engineer	terrej1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230120-C07, Contract Project J4I3450, Project Item Line Number 0160, Contract Line Item Number 0160, Item 4010150, Minor Item.	No Remark was entered by Engineer	terrej1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230120-C07, Contract Project J4l3450, Project Item Line Number 0480, Contract Line Item Number 0480, Item 6161030, Minor Item.	No Remark was entered by Engineer	terrej1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230120-C07, Contract Project J4l3450, Project Item Line Number 1640, Contract Line Item Number 1640, Item 7011207, Minor Item.	No Remark was entered by Engineer	terrej1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230120-C07, Contract Project J4I3450, Project Item Line Number 5001, Contract Line Item Number 5001, Item 6208076, Minor Item.	No Remark was entered by Engineer	terrej1	Acknowledged

Revision 3/23/2023 Page 11 of 52



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q Contract	uantities Project	and Valu	les are	based on I	Report Generated date and can differ from the posted an Description	nount at the	Net	estimate was	S Gener Unit	ated. Total	Unit Price	Total Value POSTED
Nm.CONTRACT	No.	,	No.	Code	·	Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)
230120-C07	J4I3450	0001	0010	1041000	TEMPORARY SURFACING	475.00	0.00	475.00	CUYD	55.00	\$58.39	\$3,211.45
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.70	\$224,996.41	\$157,497.49
		0001	0030	2031000	CLASS A EXCAVATION	7,949.00	0.00	7,949.00	CUYD	6,776.00	\$11.44	\$77,517.44
		0001	0040	2035500	EMBANKMENT IN PLACE	14,131.00	0.00	14,131.00	CUYD	6,459.00	\$13.27	\$85,710.93
		0001	0050	2036000	COMPACTING EMBANKMENT	3,824.00	0.00	3,824.00	CUYD	2,293.00	\$4.93	\$11,304.49
		0001	0060	2061000	CLASS 1 EXCAVATION	2,086.00	0.00	2,086.00	CUYD	840.00	\$29.00	\$24,360.00
		0001	0070	2063000	CLASS 3 EXCAVATION	403.00	0.00	403.00	CUYD	372.00	\$25.14	\$9,352.08
		0001	0080	2063300	CLASS 4 EXCAVATION	6.00	0.00	6.00	CUYD	6.00	\$33.42	\$200.52
		0001	0090	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	40.00	0.00	40.00	100F	0.00	\$13.80	\$0.00
		0001	0100	2142000	FURNISHING ROCK FILL	2,086.00	-2,086.00	0.00	CUYD	0.00	\$34.44	\$0.00
		0001	0110	2143000	PLACING ROCK FILL	2,086.00	-2,086.00	0.00	CUYD	0.00	\$3.19	\$0.00
		0001	0120	3030600	FURNISHING ROCK BASE MATERIAL	5,282.00	0.00	5,282.00	SQYD	3,123.70	\$48.33	\$150,968.42
		0001	0130	3030610A	PLACING ROCK BASE	5,282.00	0.00	5,282.00	SQYD	3,123.70	\$3.19	\$9,964.60
		0001	0140	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	2,299.00	0.00	2,299.00	SQYD	1,712.15	\$24.46	\$41,879.19
		0001	0150	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	8,289.00	0.00	8,289.00	SQYD	7,156.10	\$21.98	\$157,291.08
		0001	0160	4010150	TYPE A2 SHOULDER	230.00	0.00	230.00	SQYD	332.60	\$23.60	\$7,849.36
		0001	0170	4019905	MISC.OPTIONAL PAVEMENT (CROSSOVER)	1,985.00	0.00	1,985.00	SQYD	1,820.40	\$77.19	\$140,516.68
		0001	0180	4030101	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	153.00	0.00	153.00	TONS	0.00	\$237.45	\$0.00
		0001	0190	4039905	MISC.OPTIONAL PAVEMENT - NW PRAIRIE VIEW	186.20	0.00	186.20	SQYD	186.00	\$77.53	\$14,420.58
		0001	0200	4039905	MISC.OPTIONAL PAVEMENT - I-29	5,281.20	0.00	5,281.20	SQYD	3,123.30	\$89.76	\$280,347.41
		0001	0210	4039905	MISC.OPTIONAL PAVEMENT - RAMPS 1, 2 & 72ND STREET	6,118.20	0.00	6,118.20	SQYD	5,731.40	\$81.15	\$465,103.11
		0001	0220	4071007	TACK COAT - LOW OR NON-TRACKING	652.00	0.00	652.00	GAL	0.00	\$4.75	\$0.00
		0001	0230	5041000	CONCRETE APPROACH PAVEMENT	796.30	0.00	796.30	SQYD	398.15	\$101.28	\$40,324.63
		0001	0240	6044011	PIPE COLLAR, TYPE A	1.00	0.00	1.00	EA	1.00	\$2,240.79	\$2,240.79
		0001	0250	6071050	CHAIN-LINK FENCE (RETAINING WALLS)	509.00	0.00	509.00	LF	86.20	\$63.32	\$5,458.18
		0001	0260	6071102	MODIFIED CONCRETE GUTTER TYPE B	509.00	0.00	509.00	LF	488.00	\$37.48	\$18,290.24
		0001	0270	6079903	MISC.(48 IN.) CHAIN-LINK FENCE (STRUCTURES)	2,507.00	0.00	2,507.00	LF	0.00	\$48.54	\$0.00
		0001	0280	6081010	CONCRETE CURB RAMP	63.50	0.00	63.50	SQYD	37.60	\$75.48	\$2,838.05
		0001	0290	6081012	TRUNCATED DOMES	96.00	0.00	96.00	SQFT	73.60	\$30.79	\$2,266.14
		0001	0300	6083008	8 IN. CONCRETE MEDIAN STRIP	447.50	0.00	447.50	SQYD	436.20	\$100.43	\$43,807.57
		0001	0310	6086004	CONCRETE SIDEWALK, 4 IN.	321.10	0.00	321.10	SQYD	255.59	\$43.05	\$11,003.15
		0001	0320	6091011	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	1,098.00	0.00	1,098.00	LF	924.00	\$39.09	\$36,119.16
		0001	0330	6091042	CONCRETE GUTTER TYPE B	11.00	0.00	11.00	LF	0.00	\$37.38	\$0.00
		0001	0340	6091052	CURB AND GUTTER TYPE B	2,013.00	0.00	2,013.00	LF	1,476.25	\$33.96	\$50,133.45
		0001	0350	6091060	PAVED DITCH	29.00	0.00	29.00	SQYD	29.00	\$138.15	\$4,006.35
		0001	0360	6113010	FURNISHING TYPE 1 ROCK BLANKET	370.00	0.00	370.00	CUYD	0.00	\$86.54	\$0.00
		0001	0370	6113030	PLACING TYPE 1 ROCK BLANKET	370.00	0.00	370.00	CUYD	0.00	\$28.82	\$0.00
		0001	0380	6122008	IMPACT ATTENUATOR 40 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	0.00	\$4,485.12	\$0.00
		0001	0390	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	4.00	0.00	4.00	EA	4.00	\$4,485.12	\$17,940.48
		0001	0400	6122020	REPLACEMENT SAND BARREL	6.00	0.00	6.00	EA	0.00	\$1,371.92	\$0.00
		0001	0410	6122030	IMPACT ATTENUATOR (RELOCATION)	8.00	0.00	8.00	EA	3.00	\$4,485.12	\$13,455.36
		0001	0420	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$23,744.76	\$0.00
		0001	0430	6143010	MANHOLE FRAME AND COVER, TYPE 1-A	1.00	0.00	1.00	EA	0.00	\$2,232.93	\$0.00
		0001	0440	6143013	MANHOLE FRAME AND COVER, TYPE 3	7.00	0.00	7.00	EA	6.00	\$2,232.93	\$13,397.58
		0001	0450	6161005	CONSTRUCTION SIGNS	1,931.00	0.00	1,931.00	SQFT	1,848.00	\$6.86	\$12,677.28
		0001	0460	6161008	ADVANCED WARNING RAIL SYSTEM	7.00	0.00	7.00	EA	4.00	\$68.60	\$274.40

Revision 3/23/2023 Page 12 of 52



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	ies are	based on I	Report Generated date and can differ from the posted am	ount at the	time the E	stimate was	s Gener	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230120-C07	J4I3450	0001	0470	6161025	CHANNELIZER (TRIM LINE)	236.00	0.00	236.00	EA	231.00	\$19.00	\$4,389.00
		0001	0480	6161030	TYPE III MOVEABLE BARRICADE	21.00	0.00	21.00	EA	28.00	\$174.13	\$4,875.64
		0001	0490	6161033	DIRECTIONAL INDICATOR BARRICADE	37.00	0.00	37.00	EA	30.00	\$89.70	\$2,691.00
		0001	0500	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	3.00	\$3,165.97	\$9,497.91
		0001	0510	6161055	SEQUENTIAL FLASHING WARNING LIGHT	30.00	0.00	30.00	EA	30.00	\$68.60	\$2,058.00
		0001	0520	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$5,271.34	\$21,085.36
		0001	0530	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	7.00	5.00	12.00	EA	12.00	\$1,371.92	\$16,463.04
		0001	0540	6169902	MISC.ADA COMPLIANT MOVEABLE BARRICADE	4.00	0.00	4.00	EA	4.00	\$100.26	\$401.04
		0001	0550	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	2,532.00	0.00	2,532.00	LF	25.00	\$129.55	\$3,238.75
		0001	0560	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	5,795.00	0.00	5,795.00	LF	3,600.00	\$25.86	\$93,096.00
		0001	0570	6173706	TEMPORARY TRAFFIC BARRIER STIFFNESS TRANSITION SECTION, CONTRACTOR FURNISHED / RETAINED	425.00	0.00	425.00	LF	425.00	\$36.94	\$15,699.50
		0001	0580	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	15,594.00	0.00	15,594.00	LF	11,725.00	\$8.44	\$98,959.00
		0001	0590	6175013	RELOCATING TEMPORARY TRAFFIC BARRIER STIFFNESS TRANSITION SECTION	213.00	0.00	213.00	LF	213.00	\$21.11	\$4,496.43
		0001	0600	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$416,406.80	\$208,203.40
		0001	0610	6191000	PAVEMENT EDGE TREATMENT	3,171.00	0.00	3,171.00	LF	0.00	\$5.27	\$0.00
		0001	0620	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	301.00	0.00	301.00	LF	0.00	\$21.11	\$0.00
		0001	0630	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	182.00	0.00	182.00	LF	0.00	\$21.11	\$0.00
		0001	0640	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	21.00	0.00	21.00	EA	0.00	\$342.98	\$0.00
		0001	0650	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	2.00	0.00	2.00	EA	0.00	\$474.90	\$0.00
		0001	0660	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	36.00	0.00	36.00	EA	0.00	\$237.45	\$0.00
		0001	0670	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	12.00	0.00	12.00	EA	0.00	\$68.60	\$0.00
		0001	0680	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	74,043.00	-21,500.00	52,543.00	LF	1,313.00	\$2.27	\$2,980.51
		0001	0690	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	33,648.00	-14,500.00	19,148.00	LF	664.00	\$2.27	\$1,507.28
		0001	0700	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	14,668.00	0.00	14,668.00	LF	0.00	\$0.22	\$0.00
		0001	0710	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	10,323.00	0.00	10,323.00	LF	0.00	\$0.22	\$0.00
		0001	0720	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,986.00	0.00	1,986.00	LF	0.00	\$0.53	\$0.00
		0001	0730	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,995.00	0.00	2,995.00	LF	0.00	\$0.26	\$0.00
		0001	0740	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	490.00	0.00	490.00	LF	0.00	\$0.26	\$0.00
		0001	0750	6206108A	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	116.00	0.00	116.00	LF	0.00	\$0.32	\$0.00
		0001	0760	6207001	PAVEMENT MARKING REMOVAL	28,283.00	0.00	28,283.00	LF	18,970.00	\$0.58	\$11,002.60
		0001	0770	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	2.00	0.00	2.00	EA	2.00	\$100.26	\$200.52
		0001	0780	6209902	MISC.SHARE THE ROAD SYMBOL	4.00	0.00	4.00	EA	0.00	\$580.43	\$0.00
		0001	0790	6209902	MISC.THERMOPLASTIC HELMETED BICYCLIST SYMBOL WITH CHERVON ARROWS	2.00	0.00	2.00	EA	0.00	\$580.43	\$0.00
		0001	0800	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	136.00	0.00	136.00	SQYD	0.00	\$60.15	\$0.00
		0001	0810	6240101A	SUBSURFACE DRAINAGE GEOTEXTILE	334.00	0.00	334.00	SQYD	0.00	\$15.34	\$0.00
		0001	0820	6240104A	SEPARATION GEOTEXTILE	554.00	0.00	554.00	SQYD	0.00	\$15.34	\$0.00
		0001	0830	6269909	MISC.OPTIONAL RUMBLE STRIP	84.00	0.00	84.00	STA	0.00	\$100.26	\$0.00
		0001	0840	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.40	\$31,659.68	\$12,663.87
		0001	0850	7034041	CLASS B-1 CONCRETE (CULVERTS)	8.60	0.00	8.60	CUYD	8.60	\$937.28	\$8,060.61
		0001	0860	7061030	REINFORCING STEEL (CULVERTS)	1,550.00	0.00	1,550.00	LB	1,550.00	\$1.06	\$1,643.00
		0001	0870	7250315A		23.00	0.00	23.00	LF	23.00	\$60.59	\$1,393.57
		0001	0880	7250318A	18 IN. PIPE GROUP B	697.00	0.00	697.00	LF	679.00	\$61.36	\$41,663.44

Revision 3/23/2023 Page 13 of 52



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					Report Generated date and can differ from the posted am							T
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230120-C07	J4I3450	0001	0890	7259903	MISC.4 IN. SCH. 80 PVC PROFORATED PIPE WITH FILTER SLEEVE	538.00	-538.00	0.00	LF	0.00	\$22.44	\$0.00
		0001	0900	7261030	30 IN. PIPE GROUP A	30.00	-30.00	0.00	LF	0.00	\$112.87	\$0.00
		0001	0910	7311030	PRECAST CONCRETE DROP INLET 3 FT X 2 FT-6 IN.	31.00	0.00	31.00	FT	26.00	\$900.92	\$23,423.92
		0001	0920	7319902	MISC.COVER, REMOVE AND REPLACE EXISTING MEDIAN INLETS	6.00	0.00	6.00	EA	0.00	\$4,258.06	\$0.00
		0001	0930	7319913	MISC.4 FT. X 4 FT. JUNCTION BOX	6.00	-6.00	0.00	FT	0.00	\$987.73	\$0.00
		0001	0940	7320015A	15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$1,877.70	\$1,877.70
		0001	0950	8051000A	SEEDING - COOL SEASON GRASSES	1.00	0.00	1.00	ACRE	0.00	\$3,165.97	\$0.00
		0001	0960	8061006	ALTERNATE DITCH CHECK	102.00	0.00	102.00	LF	0.00	\$10.55	\$0.00
		0001	0970	8061007A	CURB INLET CHECK	9.00	0.00	9.00	EA	0.00	\$73.87	\$0.00
		0001	0980	8061016	SEDIMENT REMOVAL	60.00	0.00	60.00	CUYD	0.00	\$36.80	\$0.00
		0001	0990	8061017	TEMPORARY SEEDING	0.30	0.00	0.30	ACRE	0.00	\$4,221.29	\$0.00
		0001	1000	8061019	SILT FENCE	3,483.00	0.00	3,483.00	LF	2,192.00	\$1.48	\$3,244.16
		0010	1010	6061060	MGS GUARDRAIL	1,250.00	0.00	1,250.00	LF	0.00	\$29.55	\$0.00
		0010	1020	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	4.00	0.00	4.00	EA	0.00	\$4,173.80	\$0.00
		0010	1030	6061080	MGS END ANCHOR	3.00	0.00	3.00	EA	0.00	\$1,567.15	\$0.00
		0010	1040	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3.00	0.00	3.00	EA	0.00	\$3,377.03	\$0.00
		0020	1050	9011110	BRACKET ARM, 10 FT. OR 3.0 M	1.00	0.00	1.00	EA	0.00	\$996.86	\$0.00
		0020	1060	9011312	LUMINAIRE, LED-B	15.00	0.00	15.00	EA	0.00	\$477.43	\$0.00
		0020	1070	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	21.00	0.00	21.00	LF	0.00	\$21.11	\$0.00
		0020	1080	9014003	CONDUIT, 3 IN. RIGID, PUSHED	161.00	105.00	266.00	LF	161.00	\$33.30	\$5,361.30
		0020	1090	9014502	CONDUIT, 2 IN. RIGID, EXTERNAL ON STRUCTURE	178.00	0.00	178.00	LF	0.00	\$55.62	\$0.00
		0020	1100	9015010	TRENCHING TYPE I	104.00	0.00	104.00	LF	0.00	\$8.76	\$0.00
		0020	1110	9016110	PULL BOX, PREFORMED CLASS 1	3.00	3.00	6.00	EA	3.00	\$1,728.62	\$5,185.86
		0020	1120	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	740.00	580.00	1,320.00	LF	0.00	\$9.66	\$0.00
		0020	1130	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	1.00	0.00	1.00	EA	0.00	\$1,902.75	\$0.00
		0020	1140	9019902	MISC.LUMINAIRE, 150 WATT EQUIVALENT LED (UNDERPASS)	8.00	0.00	8.00	EA	6.00	\$1,259.00	\$7,554.00
		0020	1150	9019902	MISC.REMOVE AND REINSTALL LIGHTING POLE	1.00	0.00	1.00	EA	0.00	\$1,133.42	\$0.00
		0030	1160	9020213	SIGNAL HEAD, TYPE 3S	7.00	0.00	7.00	EA	0.00	\$1,051.42	\$0.00
		0030	1170	9020513	SIGNAL HEAD, TYPE 3B	26.00	-2.00	24.00	EA	0.00	\$1,242.11	\$0.00
		0030	1180	9020514	SIGNAL HEAD, TYPE 4B	7.00	0.00	7.00	EA	0.00	\$1,739.17	\$0.00
		0030	1190	9020515	SIGNAL HEAD, TYPE 5B	1.00	0.00	1.00	EA	0.00	\$2,061.04	\$0.00
		0030	1200	9020811	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	6.00	0.00	6.00	EA	0.00	\$663.27	\$0.00
		0030	1210	9020833	SH-FLAT SHEET - SIGNAL SIGN	230.00	0.00	230.00	SQFT	0.00	\$21.05	\$0.00
		0030	1220	9020834	SIGNAL SIGN, MOUNTING HARDWARE	35.00	0.00	35.00	EA	0.00	\$320.18	\$0.00
		0030	1230	9022708	POST, SIGNAL 8 FT.	5.00	0.00	5.00	EA	0.00	\$1,338.15	\$0.00
		0030	1240	9023230	POST, TYPE C, 30 FT. ARM OR 9.1 M ARM	2.00	0.00	2.00	EA	0.00	\$12,182.64	\$0.00
		0030	1250	9023235	POST, TYPE C, 35 FT. ARM OR 10.7 M ARM	1.00	0.00	1.00	EA	0.00	\$12,878.10	\$0.00
		0030	1260	9023240	POST, TYPE C, 40 FT. ARM OR 12.2 M ARM	1.00	0.00	1.00	EA	0.00	\$15,731.69	\$0.00
		0030	1270	9023335	POST, TYPE B, LONGEST ARM 35 FT. OR 10.7 M	1.00	0.00	1.00	EA	0.00	\$20,153.49	\$0.00
		0030	1280	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	1.00	0.00	1.00	EA	0.00	\$20,004.69	\$0.00
		0030	1290	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	360.00	306.00	666.00	LF	360.00	\$17.47	\$6,289.20
		0030	1300	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	1,355.00	-306.00	1,049.00	LF	867.00	\$33.30	\$28,871.10
		0030	1310	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	570.00	0.00	570.00	LF	0.00	\$2.06	\$0.00
		0030	1320	9028308	CABLE, 16 AWG 2 CONDUCTOR	1,360.00	0.00	1,360.00	LF	0.00	\$1.69	\$0.00
		0030	1330	9028310	CABLE, 16 AWG 5 CONDUCTOR	1,360.00	0.00	1,360.00	LF	0.00	\$2.11	\$0.00

Revision 3/23/2023 Page 14 of 52



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Report Generated date and can differ from the posted am Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230120-C07	J4I3450	0030	1340	9028311	CABLE, 16 AWG 7 CONDUCTOR	8,020.00	0.00	8,020.00	LF	0.00	\$2.32	\$0.00
		0030	1350	9028620	POWER SUPPLY ASSEMBLY, TYPE 2	1.00	0.00	1.00	EA	1.00	\$6,151.48	\$6,151.48
		0030	1360	9028811	PULL BOX, PREFORMED CLASS 2	12.00	0.00	12.00	EA	10.00	\$2,124.36	\$21,243.60
		0030	1370	9028812	PULL BOX, PREFORMED CLASS 3	2.00	0.00	2.00	EA	2.00	\$2,955.96	\$5,911.92
		0030	1380	9029100	BASE, CONCRETE	24.30	0.00	24.30	CUYD	13.97	\$1,598.81	\$22,335.38
		0030	1390	9029902	MISC.ACCESSIBLE PEDESTRAIN SIGNALS (PUSHBUTTON)	6.00	0.00	6.00	EA	0.00	\$1,397.25	\$0.00
		0030	1400	9029902	MISC.CONTROLLOR ASSEMBLY HOUSING, DOUBLE NEMA TS2	1.00	0.00	1.00	EA	0.00	\$29,669.34	\$0.00
		0030	1410	9109902	MISC.KC DISTRICT VIDEO DETECTION SYSTEM	3.00	0.00	3.00	EA	0.00	\$51,102.94	\$0.00
		0040	1420	9031010	CONCRETE FOOTINGS, EMBEDDED	2.50	0.00	2.50	CUYD	0.00	\$1,480.62	\$0.00
		0040	1430	9031020	CONCRETE FOOTINGS, BOLT DOWN	10.10	0.00	10.10	CUYD	10.10	\$1,661.08	\$16,776.91
		0040	1440	9031210	STRUCTURAL STEEL POSTS	1,250.00	0.00	1,250.00	LB	0.00	\$6.23	\$0.00
		0040	1450	9031220	PIPE POSTS	1,120.00	0.00	1,120.00	LB	0.00	\$6.33	\$0.00
		0040	1460	9031280	2.5 IN. PSST POST - 12 GA.	64.00	0.00	64.00	LF	0.00	\$23.22	\$0.00
		0040	1470	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	4.00	0.00	4.00	EA	0.00	\$258.55	\$0.00
		0040	1480	9035004A	SH-FLAT SHEET	223.00	0.00	223.00	SQFT	0.00	\$23.85	\$0.00
		0040	1490	9035011A	ST-STRUCTURAL	516.00	0.00	516.00	SQFT	0.00	\$31.66	\$0.00
		0040	1500	9035069A	SHF-FLAT SHEET FLUORESCENT	20.00	0.00	20.00	SQFT	0.00	\$25.75	\$0.00
		0040	1510	9039902	MISC.S-27718 TYPE S TWO TUBE SIGN TRUSS	1.00	0.00	1.00	EA	0.00	\$94,374.33	\$0.00
		0050	1520	9105200	CONDUIT, 2 IN., RIGID, IN TRENCH	364.00	0.00	364.00	LF	364.00	\$13.30	\$4,841.20
		0050	1530	9105202	CONDUIT, 4 IN., RIGID, IN TRENCH	79.00	0.00	79.00	LF	79.00	\$21.79	\$1,721.41
		0050	1540	9107201	CONDUIT, 3 IN., RIGID, PUSHED	251.00	0.00	251.00	LF	151.00	\$33.30	\$5,028.30
		0050	1550	9108354	FIBER OPTIC CABLE, 48-STRAND, SINGLE MODE	1,020.00	0.00	1,020.00	LF	0.00	\$14.30	\$0.00
		0050	1560	9108816	PULL BOX, PREFORMED CLASS 5	3.00	0.00	3.00	EA	2.00	\$2,898.97	\$5,797.94
		0050	1570	9109902	MISC.MEDIA CONVERTER (INSTALLED)	1.00	0.00	1.00	EA	0.00	\$3,229.29	\$0.00
		0050	1580	9109902	MISC.PRE-TERMINATED FIBER PANEL	1.00	0.00	1.00	EA	0.00	\$493.26	\$0.00
		0050	1590	9109902	MISC.RELOCATE EXISTING FIBER/ITS EQUIPMENT TO NEW	2.00	0.00	2.00	EA	0.00	\$1,362.42	\$0.00
					CABINET							
		0070	1600	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	10.00	0.00	10.00	SQFT	0.00	\$422.13	\$0.00
		0070	1610	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$82,589.60	\$82,589.60
		0070	1620	5031010A		241.00	0.00	241.00	SQYD	241.00	\$267.07	\$64,363.87
		0070	1630	7011108	DRILLED SHAFTS (5 FT. 0 IN. DIA.)	51.00	0.00	51.00	LF	47.70	\$513.14	\$24,476.78
		0070	1640	7011207	ROCK SOCKETS (4 FT 6 IN. DIA.)	36.00	0.00	36.00	LF	39.30	\$751.14	\$29,519.80
		0070	1650	7011300	VIDEO CAMERA INSPECTION	3.00	0.00	3.00	EA	3.00	\$765.11	\$2,295.33
		0070	1660	7011400	FOUNDATION INSPECTION HOLES	66.00	0.00	66.00	LF	66.00	\$120.31	\$7,940.46
		0070	1670	7011600	SONIC LOGGING TESTING	3.00	0.00	3.00	EA	3.00	\$2,181.35	\$6,544.05
		0070	1680	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	570.00	0.00	570.00	LF	561.10	\$88.48	\$49,646.13
		0070	1690	7026000	PRE-BORE FOR PILING	338.00	0.00	338.00	LF	224.58	\$64.37	\$14,456.21
		0070	1700	7027000	PILE POINT REINFORCEMENT	15.00	0.00	15.00	EA	15.00	\$110.81	\$1,662.15
		0070	1710	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	102.50	0.00	102.50	CUYD	102.50	\$1,160.41	\$118,942.02
		0070	1720	7034219A	TYPE D BARRIER	290.00	0.00	290.00	LF	290.00	\$199.49	\$57,852.10
		0070	1730	7034222	SLAB ON CONCRETE BEAM	711.00	0.00	711.00	SQYD	711.00	\$363.10	\$258,164.10
		0070	1740	7034620	FORM LINERS	34.00	0.00	34.00	SQYD	34.00	\$251.94	\$8,565.96
		0070	1750	7056049	21 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	792.00	0.00	792.00	LF	792.00	\$465.19	\$368,430.48
		0070	1760	7061060	REINFORCING STEEL (BRIDGES)	12,050.00	0.00	12,050.00	LB	12,050.00	\$2.84	\$34,222.00
		0070	1770	7101000	REINFORCING STEEL (EPOXY COATED)	14,970.00	0.00	14,970.00	LB	14,970.00	\$2.79	\$41,766.30
		0070	1780	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$13,455.36	\$0.00
		0070	1790	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$3,613.27	\$7,226.54

Revision 3/23/2023 Page 15 of 52



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

No. No. Code Curenty Change Curenty Curent	EA SQFT SQYD LF LF LF LF LF LF EA	Appropriate Approp	14.00 \$ 15.00 \$ 1.00 \$ 82 241.00 \$ 0.00	\$273.59 \$241.93 \$539.44 \$422.13 ,589.60 \$267.07	To Date (See report generated date) \$3,830.26 \$3,837.02 \$8,091.60 \$0.00
0070 1810 7161002 LAMINATED NEOPRENE BEARING PAD 14.00 0.00 14.00 0070 1820 7201300 PIPE PILE SPACERS 15.00 0.00 15.00 0071 1830 2024043 REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) 10.00 0.00 10.00 0071 1840 2160500 REMOVAL OF BRIDGES 1.00 0.00 1.00 0071 1850 5031010A BRIDGE APPROACH SLAB (MAJOR) 241.00 0.00 241.00 0071 1860 6071060 PEDESTRIAN FENCE (STRUCTURES) 156.00 0.00 156.00 0071 1870 7011108 DRILLED SHAFTS (5 FT. 0 IN. DIA.) 45.00 0.00 45.00 0071 1880 7011207 ROCK SOCKETS (4 FT 6 IN. DIA.) 36.00 0.00 36.00 0071 1890 7011300 VIDEO CAMERA INSPECTION 3.00 0.00 3.00 0071 1990 7011400 FOUNDATION INSPECTION HOLES 66.00 0.00 30.00 0071<	EA SQFT SQYD LF LF LF LF LF LF EA	EA EA EA LS LS LF LF LF LF	14.00 \$ 15.00 \$ 1.00 \$ 82 241.00 \$ 0.00	\$241.93 \$539.44 \$422.13 ,589.60	\$3,387.02 \$8,091.60 \$0.00
0070 1820 7201300 PIPE PILE SPACERS 15.00 0.00 15.00 0071 1830 2024043 REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) 10.00 0.00 10.00 0071 1840 2160500 REMOVAL OF BRIDGES 1.00 0.00 1.00 0071 1850 5031010A BRIDGE APPROACH SLAB (MAJOR) 241.00 0.00 241.00 0071 1860 6071060 PEDESTRIAN FENCE (STRUCTURES) 156.00 0.00 156.00 0071 1870 7011108 DRILLED SHAFTS (5 FT. 0 IN. DIA.) 45.00 0.00 45.00 0071 1880 7011207 ROCK SOCKETS (4 FT 6 IN. DIA.) 36.00 0.00 36.00 0071 1890 7011300 VIDEO CAMERA INSPECTION 3.00 0.00 3.00 0071 1990 7011400 FOUNDATION INSPECTION HOLES 66.00 0.00 66.00 0071 1910 7011600 SONIC LOGGING TESTING 3.00 0.00 570.00 0071	EA SQFT LS SQYD LF LF LF LF EA C LF LF LF EA C	EA IFT LS YD 2 LF LF	15.00 \$ 0.00 \$ 1.00 \$82 241.00 \$ 0.00	\$539.44 \$422.13 ,589.60	\$8,091.60 \$0.00
0071 1830 2024043 REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) 10.00 0.00 10.00 0071 1840 2160500 REMOVAL OF BRIDGES 1.00 0.00 1.00 0071 1850 5031010A BRIDGE APPROACH SLAB (MAJOR) 241.00 0.00 241.00 0071 1860 6071060 PEDESTRIAN FENCE (STRUCTURES) 156.00 0.00 156.00 0071 1870 7011108 DRILLED SHAFTS (5 FT. 0 IN. DIA.) 45.00 0.00 45.00 0071 1880 7011207 ROCK SOCKETS (4 FT 6 IN. DIA.) 36.00 0.00 36.00 0071 1890 7011300 VIDEO CAMERA INSPECTION 3.00 0.00 3.00 0071 1900 701400 FOUNDATION INSPECTION HOLES 66.00 0.00 66.00 0071 1910 7011600 SONIC LOGGING TESTING 3.00 0.00 570.00 0071 1920 7021212 GALVANIZED STRUCTURAL STEEL PILES (12 IN) 570.00 0.00 570.00	SQFT LS SQYD LF LF EA LF EA EA	LS YD LF LF LF	0.00 \$ 1.00 \$82 241.00 \$ 0.00	,589.60	\$0.00
0071 1840 2160500 REMOVAL OF BRIDGES 1.00 0.00 1.00 0071 1850 5031010A BRIDGE APPROACH SLAB (MAJOR) 241.00 0.00 241.00 0071 1860 6071060 PEDESTRIAN FENCE (STRUCTURES) 156.00 0.00 156.00 0071 1870 7011108 DRILLED SHAFTS (5 FT. 0 IN. DIA.) 45.00 0.00 45.00 0071 1880 7011207 ROCK SOCKETS (4 FT 6 IN. DIA.) 36.00 0.00 36.00 0071 1890 7011300 VIDEO CAMERA INSPECTION 3.00 0.00 3.00 0071 1890 7011400 FOUNDATION INSPECTION HOLES 66.00 0.00 66.00 0071 1910 7011600 SONIC LOGGING TESTING 3.00 0.00 3.00 0071 1920 7021212 GALVANIZED STRUCTURAL STEEL PILES (12 IN) 570.00 0.00 570.00 0071 1930 7026000 PRE-BORE FOR PILING 309.00 0.00 15.00 0071	LS SQYD LF LF LF EA LF LF LF EA LF LF EA L	LS YD 2 LF LF LF	1.00 \$82 241.00 \$,589.60	
0071 1850 5031010A BRIDGE APPROACH SLAB (MAJOR) 241.00 0.00 241.00 0071 1860 6071060 PEDESTRIAN FENCE (STRUCTURES) 156.00 0.00 156.00 0071 1870 7011108 DRILLED SHAFTS (5 FT. 0 IN. DIA.) 45.00 0.00 45.00 0071 1880 7011207 ROCK SOCKETS (4 FT 6 IN. DIA.) 36.00 0.00 36.00 0071 1890 7011300 VIDEO CAMERA INSPECTION 3.00 0.00 3.00 0071 1900 7011400 FOUNDATION INSPECTION HOLES 66.00 0.00 66.00 0071 1910 7011600 SONIC LOGGING TESTING 3.00 0.00 3.00 0071 1920 7021212 GALVANIZED STRUCTURAL STEEL PILES (12 IN) 570.00 0.00 570.00 0071 1930 7026000 PRE-BORE FOR PILING 309.00 0.00 309.00 0071 1940 7027000 PILE POINT REINFORCEMENT 15.00 0.00 15.00 007	SQYD LF LF EA LF EA	YD 2	241.00 \$		\$82.580.60
0071 1860 6071060 PEDESTRIAN FENCE (STRUCTURES) 156.00 0.00 156.00 0071 1870 7011108 DRILLED SHAFTS (5 FT. 0 IN. DIA.) 45.00 0.00 45.00 0071 1880 7011207 ROCK SOCKETS (4 FT 6 IN. DIA.) 36.00 0.00 36.00 0071 1890 7011300 VIDEO CAMERA INSPECTION 3.00 0.00 3.00 0071 1990 7011400 FOUNDATION INSPECTION HOLES 66.00 0.00 66.00 0071 1910 7011600 SONIC LOGGING TESTING 3.00 0.00 3.00 0071 1920 7021212 GALVANIZED STRUCTURAL STEEL PILES (12 IN) 570.00 0.00 570.00 0071 1930 7026000 PRE-BORE FOR PILING 309.00 0.00 309.00 0071 1940 7027000 PILE POINT REINFORCEMENT 15.00 0.00 15.00 0071 1950 7032003 CLASS B CONCRETE (SUBSTRUCTURE) 106.20 0.00 106.20 0	LF LF EA LF EA	LF LF	0.00	\$267.07	φο∠,υου.00
0071 1870 7011108 DRILLED SHAFTS (5 FT. 0 IN. DIA.) 45.00 0.00 45.00 0071 1880 7011207 ROCK SOCKETS (4 FT 6 IN. DIA.) 36.00 0.00 36.00 0071 1890 7011300 VIDEO CAMERA INSPECTION 3.00 0.00 3.00 0071 1900 7011400 FOUNDATION INSPECTION HOLES 66.00 0.00 66.00 0071 1910 7011600 SONIC LOGGING TESTING 3.00 0.00 3.00 0071 1920 7021212 GALVANIZED STRUCTURAL STEEL PILES (12 IN) 570.00 0.00 570.00 0071 1930 7026000 PRE-BORE FOR PILING 309.00 0.00 309.00 0071 1940 7027000 PILE POINT REINFORCEMENT 15.00 0.00 15.00 0071 1950 7032003 CLASS B CONCRETE (SUBSTRUCTURE) 106.20 0.00 106.20 0071 1960 7034219A TYPE D BARRIER 290.00 0.00 711.00 0071	LF LF EA LF EA	LF LF			\$64,363.87
0071 1880 7011207 ROCK SOCKETS (4 FT 6 IN. DIA.) 36.00 0.00 36.00 0071 1890 7011300 VIDEO CAMERA INSPECTION 3.00 0.00 3.00 0071 1900 7011400 FOUNDATION INSPECTION HOLES 66.00 0.00 66.00 0071 1910 7011600 SONIC LOGGING TESTING 3.00 0.00 3.00 0071 1920 7021212 GALVANIZED STRUCTURAL STEEL PILES (12 IN) 570.00 0.00 570.00 0071 1930 7026000 PRE-BORE FOR PILING 309.00 0.00 309.00 0071 1940 7027000 PILE POINT REINFORCEMENT 15.00 0.00 15.00 0071 1950 7032003 CLASS B CONCRETE (SUBSTRUCTURE) 106.20 0.00 106.20 0071 1960 7034219A TYPE D BARRIER 290.00 0.00 290.00 0071 1980 7034222 SLAB ON CONCRETE BEAM 711.00 0.00 35.00 0071 1980	LF EA EA	LF	45.10 \$	\$84.43	\$0.00
0071 1890 7011300 VIDEO CAMERA INSPECTION 3.00 0.00 3.00 0071 1900 7011400 FOUNDATION INSPECTION HOLES 66.00 0.00 66.00 0071 1910 7011600 SONIC LOGGING TESTING 3.00 0.00 3.00 0071 1920 7021212 GALVANIZED STRUCTURAL STEEL PILES (12 IN) 570.00 0.00 570.00 0071 1930 7026000 PRE-BORE FOR PILING 309.00 0.00 309.00 0071 1940 7027000 PILE POINT REINFORCEMENT 15.00 0.00 15.00 0071 1950 7032003 CLASS B CONCRETE (SUBSTRUCTURE) 106.20 0.00 106.20 0071 1960 7034219A TYPE D BARRIER 290.00 0.00 290.00 0071 1970 7034222 SLAB ON CONCRETE BEAM 711.00 0.00 711.00 0071 1980 7034620 FORM LINERS 35.00 0.00 35.00 0071 1990	EA LF EA			\$513.14	\$23,142.61
0071 1900 7011400 FOUNDATION INSPECTION HOLES 66.00 0.00 66.00 0071 1910 7011600 SONIC LOGGING TESTING 3.00 0.00 3.00 0071 1920 7021212 GALVANIZED STRUCTURAL STEEL PILES (12 IN) 570.00 0.00 570.00 0071 1930 7026000 PRE-BORE FOR PILING 309.00 0.00 309.00 0071 1940 7027000 PILE POINT REINFORCEMENT 15.00 0.00 15.00 0071 1950 7032003 CLASS B CONCRETE (SUBSTRUCTURE) 106.20 0.00 106.20 0071 1960 7034219A TYPE D BARRIER 290.00 0.00 290.00 0071 1970 7034222 SLAB ON CONCRETE BEAM 711.00 0.00 711.00 0071 1980 7034620 FORM LINERS 35.00 0.00 35.00 0071 1990 7056049 21 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM 792.00 0.00 792.00	LF EA	EA	36.00 \$	\$751.14	\$27,041.04
0071 1910 7011600 SONIC LOGGING TESTING 3.00 0.00 3.00 0071 1920 7021212 GALVANIZED STRUCTURAL STEEL PILES (12 IN) 570.00 0.00 570.00 0071 1930 7026000 PRE-BORE FOR PILING 309.00 0.00 309.00 0071 1940 7027000 PILE POINT REINFORCEMENT 15.00 0.00 15.00 0071 1950 7032003 CLASS B CONCRETE (SUBSTRUCTURE) 106.20 0.00 106.20 0071 1960 7034219A TYPE D BARRIER 290.00 0.00 290.00 0071 1970 7034222 SLAB ON CONCRETE BEAM 711.00 0.00 711.00 0071 1980 7034620 FORM LINERS 35.00 0.00 35.00 0071 1990 7056049 21 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM 792.00 0.00 792.00) EA		3.00 \$	\$765.11	\$2,295.33
0071 1920 7021212 GALVANIZED STRUCTURAL STEEL PILES (12 IN) 570.00 0.00 570.00 0071 1930 7026000 PRE-BORE FOR PILING 309.00 0.00 309.00 0071 1940 7027000 PILE POINT REINFORCEMENT 15.00 0.00 15.00 0071 1950 7032003 CLASS B CONCRETE (SUBSTRUCTURE) 106.20 0.00 106.20 0071 1960 7034219A TYPE D BARRIER 290.00 0.00 290.00 0071 1970 7034222 SLAB ON CONCRETE BEAM 711.00 0.00 711.00 0071 1980 7034620 FORM LINERS 35.00 0.00 35.00 0071 1990 7056049 21 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM 792.00 0.00 792.00		LF	66.00 \$	\$120.31	\$7,940.46
0071 1930 7026000 PRE-BORE FOR PILING 309.00 0.00 309.00 0071 1940 7027000 PILE POINT REINFORCEMENT 15.00 0.00 15.00 0071 1950 7032003 CLASS B CONCRETE (SUBSTRUCTURE) 106.20 0.00 106.20 0071 1960 7034219A TYPE D BARRIER 290.00 0.00 290.00 0071 1970 7034222 SLAB ON CONCRETE BEAM 711.00 0.00 711.00 0071 1980 7034620 FORM LINERS 35.00 0.00 35.00 0071 1990 7056049 21 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM 792.00 0.00 792.00		EA	3.00 \$2	,181.35	\$6,544.05
0071 1940 7027000 PILE POINT REINFORCEMENT 15.00 0.00 15.00 0071 1950 7032003 CLASS B CONCRETE (SUBSTRUCTURE) 106.20 0.00 106.20 0071 1960 7034219A TYPE D BARRIER 290.00 0.00 290.00 0071 1970 7034222 SLAB ON CONCRETE BEAM 711.00 0.00 711.00 0071 1980 7034620 FORM LINERS 35.00 0.00 35.00 0071 1990 7056049 21 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM 792.00 0.00 792.00	LF	LF 5	545.00	\$88.48	\$48,221.60
0071 1950 7032003 CLASS B CONCRETE (SUBSTRUCTURE) 106.20 0.00 106.20 0071 1960 7034219A TYPE D BARRIER 290.00 0.00 290.00 0071 1970 7034222 SLAB ON CONCRETE BEAM 711.00 0.00 711.00 0071 1980 7034620 FORM LINERS 35.00 0.00 35.00 0071 1990 7056049 21 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM 792.00 0.00 792.00	LF	LF 1	174.00	\$64.37	\$11,200.38
0071 1960 7034219A TYPE D BARRIER 290.00 0.00 290.00 0071 1970 7034222 SLAB ON CONCRETE BEAM 711.00 0.00 711.00 0071 1980 7034620 FORM LINERS 35.00 0.00 35.00 0071 1990 7056049 21 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM 792.00 0.00 792.00	EA	EA	15.00 \$	\$110.81	\$1,662.15
0071 1970 7034222 SLAB ON CONCRETE BEAM 711.00 0.00 711.00 0071 1980 7034620 FORM LINERS 35.00 0.00 35.00 0071 1990 7056049 21 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM 792.00 0.00 792.00	CUYD	YD 1	106.20 \$1	,148.95	\$122,018.49
0071 1980 7034620 FORM LINERS 35.00 0.00 35.00 0071 1990 7056049 21 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM 792.00 0.00 792.00) LF	LF	0.00 \$	\$199.49	\$0.00
0071 1990 7056049 21 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM 792.00 0.00 792.00	SQYD	YD 6	675.65	\$355.12	\$239,936.83
	SQYD	YD	0.00 \$	\$251.60	\$0.00
0071 2000 7061060 REINFORCING STEEL (BRIDGES) 11,320.00 0.00 11,320.00	LF	LF 7	792.00 \$	\$470.94	\$372,984.48
	LB	LB 11,3	,320.00	\$2.98	\$33,733.60
0071 2010 7101000 REINFORCING STEEL (EPOXY COATED) 15,560.00 0.00 15,560.00	LB	LB 15,5	,560.00	\$2.75	\$42,790.00
0071 2020 7121060 FABRICATED SIGN SUPPORT BRACKETS 1.00 0.00 1.00	LS	LS	0.00 \$8	,970.24	\$0.00
0071 2030 7151001 VERTICAL DRAIN AT END BENTS 2.00 0.00 2.00	EA	EA	2.00 \$3	,613.27	\$7,226.54
0071 2040 7161000 PLAIN NEOPRENE BEARING PAD 14.00 0.00 14.00	EA	EA	14.00 \$	\$273.59	\$3,830.26
0071 2050 7161002 LAMINATED NEOPRENE BEARING PAD 14.00 0.00 14.00	EA	EA	14.00 \$	\$241.93	\$3,387.02
0071 2060 7201300 PIPE PILE SPACERS 15.00 0.00 15.00	EA	EA	15.00 \$	\$539.44	\$8,091.60
0072 2070 2065500 TEMPORARY SHORING 1.00 0.00 1.00	LS	LS	0.90 \$8	,104.73	\$7,294.26
0072 2080 7110300 CONCRETE AND MASONRY PROTECTION SYSTEM 1.00 0.00 1.00	LS	LS	1.00 \$5	,382.15	\$5,382.15
0072 2090 7110400 SACRIFICIAL GRAFFITI PROTECTION SYSTEM 1.00 0.00 1.00	LS	LS	1.00 \$3	,165.97	\$3,165.97
0072 2100 7201000 MECHANICALLY STABILIZED EARTH WALL SYSTEMS 4,205.00 0.00 4,205.00	SQFT	FT 4,2	,205.00 \$	\$114.73	\$482,439.65
0073 2110 2065500 TEMPORARY SHORING 1.00 0.00 1.00	LS	LS	0.90 \$8	,104.73	\$7,294.26
0073 2120 7110300 CONCRETE AND MASONRY PROTECTION SYSTEM 1.00 0.00 1.00	LS	LS	1.00 \$6	,120.87	\$6,120.87
0073 2130 7110400 SACRIFICIAL GRAFFITI PROTECTION SYSTEM 1.00 0.00 1.00	LS	LS	1.00 \$3	,799.16	\$3,799.16
0073 2140 7201000 MECHANICALLY STABILIZED EARTH WALL SYSTEMS 3,804.00 0.00 3,804.00	SQFT	FT 3,8	,804.00 \$	113.98	\$433,579.92
0001 5001 6208076 4 IN TEMPORARY PAVEMENT MARKING PAINT 0.00 36,000.00 36,000.00) LF	LF 61,1	,115.00	\$1.55	\$94,728.25
0030 5002 9021413 SIGNAL HEAD, OPTICALLY LIMITED, TYPE 3B 0.00 2.00	EA	EA	0.00 \$6	,191.85	\$0.00
0001 5003 6122040 WORK ZONE CRASH CUSHION (NARROW) 0.00 1.00 1.00	EA	EA	1.00 \$4	,987.50	\$4,987.50
0001 5004 7259903 MISC.6 IN. SCH. 80 PVC PERFORATED PIPE WITH FILTER 0.00 538.00 538.00) LF	LF 5	538.00	\$43.78	\$23,553.64
0001 5005 7319902 MISC.CONNECT NEW AND EXISTING DRAINAGE 0.00 1.00 1.00	EA.	EA	1.00 \$12	,152.47	\$12,152.47
0001 5006 6179901 MISC.TEMPORARY TRAFFIC BARRIER, ANCHORED 0.00 1.00 1.00) LS	LS	1.00 \$1	,877.53	\$1,877.53
0001 5007 2149907 MISC.FURNISH SELECT GRANULAR BACKFILL 0.00 2,086.00 2,086.00	CUYD	YD 1,0	,043.00	\$45.87	\$47,842.41
0001 5008 2149907 MISC.PLACING SELECT GRANULAR BACKFILL 0.00 2,086.00 2,086.00		YD 10	,043.00	\$3.19	\$3,327.17
0001 5009 7269903 MISC.30" X 19" ELLIPTICAL PIPE GROUP A 0.00 144.00 144.00		.,,	,070.00		
0020 5010 9019902 MISC.2-POLE BREAKER, 15 AMP, 480 VAC 0.00 1.00 1.00	CUYD			\$268.83	\$38,711.52
Project J4l3450 - Total Value Posted to Date as of Report Generated Date	CUYD LF	LF 1	144.00 \$		\$38,711.52 \$0.00

Revision 3/23/2023 Page 16 of 52



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230120-C07 Ove	rall - Tota	l Value Pos	ted to Da	te as of Rep	ort Generated Date							\$6,128,841.88

Revision 3/23/2023 Page 17 of 52



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4I3450

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0140	3040504	TYPE 5 AGGREGATE FOR BASE	11/15/23	11/16/23	77.00	SQYD	72nd street	14+00		16+00		South Side by MSE wall
0150	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	11/15/23	11/16/23	1,280.80	SQYD	72nd Street	14+00		18+00		
0210	4039905	MISC.	11/15/23	11/16/23	1,280.80	SQYD	72nd street	14+00		18+00		
0250	6071050	CHAIN-LINK FENCE (RETAINING WALLS)	11/15/23	11/16/23	86.20	LF	A9285/9286 East Side	764+89.36				
0310	6086004	CONCRETE SIDEWALK, 4 IN.	11/15/23	11/16/23	77.00	SQYD	72nd	14+00		16+00		South Side by MSE wall
0320	6091011	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	11/15/23	11/16/23	200.00	LF	72nd	14+00		16+00		
0340	6091052	CURB AND GUTTER TYPE B	11/15/23	11/16/23	400.00	LF		13+50		16+00		
1430	9031020	CONCRETE FOOTINGS, BOLT DOWN	11/15/23	11/16/23	0.00	CUYD	R2	10+00				Sign Truss footing
1850	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	11/15/23	11/16/23	241.00	SQYD	A9284	764+89.36				North and South
1970	7034222	SLAB ON CONCRETE BEAM	11/15/23	11/16/23	533.45	SQYD	I-29	764+14.29		765+29.93		
2000	7061060	REINFORCING STEEL (BRIDGES)	11/15/23	11/16/23	11,320.00	LB	A9284	764+89.36				
2010	7101000	REINFORCING STEEL (EPOXY COATED)	11/15/23	11/16/23	15,560.00	LB	A9284	764+89.36				
2030	7151001	VERTICAL DRAIN AT END BENTS	11/15/23	11/16/23	2.00	EA	A9284	764+89.36				
2040	7161000	PLAIN NEOPRENE BEARING PAD	11/15/23	11/16/23	0.00	EA	A9284	764+89.36				
2050	7161002	LAMINATED NEOPRENE BEARING PAD	11/15/23	11/16/23	14.00	EA	A9284	764+89.36				
2080	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	11/15/23	11/16/23	1.00	LS	A9285	764+89.36				
2090	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	11/15/23	11/16/23	1.00	LS	A9285	764+89.36				
2120	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	11/15/23	11/16/23	1.00	LS	A9286	764+89.36				
2130	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	11/15/23	11/16/23	1.00	LS	A9286	764+89.36				

The information below this line are details for Construction Signs (if applicable).
No Data Available

Revision 3/23/2023 Page 18 of 52



	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
450 0010	TEMPORARY SURFACING	Material	,,	14	Oct 2, 2023	SYSTEM	\$3,211.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				14	Oct 2, 2023	SYSTEM	(\$3,211.45)	
				15	Oct 16, 2023	SYSTEM	\$3,211.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				15	Oct 16, 2023	SYSTEM	(\$3,211.45)	
				16	Nov 1, 2023	SYSTEM	\$3,211.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user terrej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				16	Nov 1, 2023	SYSTEM	(\$3,211.45)	
				17	Nov 16, 2023	SYSTEM	\$3,211.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user terrej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				17	Nov 16, 2023	SYSTEM	(\$3,211.45)	·
			- Total				\$0.00	
		Material - To	tal				\$0.00	
0010	D - Total EMBANKMENT IN	Material		11	Aug 15,	SYSTEM	\$0.00 \$85,710.93	This adjustment offsets the original system-generated Material Payment
0040	PLACE	Material			2023			Estimate Item Adjustment (0002) due to user wilsor2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				11	Aug 15, 2023	SYSTEM	(\$85,710.93)	
				12	Sep 5, 2023	SYSTEM	\$85,710.93	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user terrej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				12	Sep 5, 2023	SYSTEM	(\$85,710.93)	
				13	Sep 18, 2023	SYSTEM	\$85,710.93	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				13	Sep 18, 2023	SYSTEM	(\$85,710.93)	
				14	Oct 2, 2023	SYSTEM	\$85,710.93	This adjustment effects the original system generated Material Dayment
					2023		, ,	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				14	Oct 2, 2023	SYSTEM	(\$85,710.93)	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment
				14	Oct 2,	SYSTEM SYSTEM		Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment
					Oct 2, 2023 Oct 16,		(\$85,710.93)	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment
				15	Oct 2, 2023 Oct 16, 2023	SYSTEM	(\$85,710.93) \$85,710.93	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment
				15	Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 1,	SYSTEM SYSTEM	(\$85,710.93) \$85,710.93 (\$85,710.93)	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user terrej1 overridding Payment
				15 15 16	Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 1, 2023	SYSTEM SYSTEM	(\$85,710.93) \$85,710.93 (\$85,710.93) \$85,710.93	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user terrej1 overridding Payment
				15 15 16	Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 1, 2023 Nov 1, 2023	SYSTEM SYSTEM SYSTEM SYSTEM	(\$85,710.93) \$85,710.93 (\$85,710.93) \$85,710.93 (\$85,710.93)	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user terrej1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user terrej1 overridding Payment Estimate Item Adjustment (0043) due to user terrej1 overridding Payment
			- Total	15 15 16 16 17	Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 1, 2023 Nov 1, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$85,710.93) \$85,710.93 (\$85,710.93) \$85,710.93 (\$85,710.93) \$85,710.93	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user terrej1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user terrej1 overridding Payment Estimate Item Adjustment (0043) due to user terrej1 overridding Payment
		Material - To		15 15 16 16 17	Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 1, 2023 Nov 1, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$85,710.93) \$85,710.93 (\$85,710.93) \$85,710.93 (\$85,710.93) \$85,710.93 (\$85,710.93)	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user terrej1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user terrej1 overridding Payment Estimate Item Adjustment (0043) due to user terrej1 overridding Payment
004 (D - Total COMPACTING EMBANKMENT			15 15 16 16 17	Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 1, 2023 Nov 1, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$85,710.93) \$85,710.93 (\$85,710.93) \$85,710.93 (\$85,710.93) \$85,710.93 (\$85,710.93)	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user terrej1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user terrej1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.
	COMPACTING			15 15 16 16 17	Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 1, 2023 Nov 1, 2023 Nov 16, 2023 Mov 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$85,710.93) \$85,710.93 (\$85,710.93) \$85,710.93 (\$85,710.93) \$85,710.93 (\$85,710.93) \$0.00 \$0.00	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user terre]1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user terrej1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3450	0050	COMPACTING EMBANKMENT	Material		6	Jun 2, 2023	SYSTEM	\$2,750.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 2, 2023	SYSTEM	(\$2,750.94)	
					7	Jun 16, 2023	SYSTEM	\$2,750.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user terrej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$2,750.94)	
					8	Jun 30, 2023	SYSTEM	\$2,750.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user terrej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$2,750.94)	
					9	Jul 17, 2023	SYSTEM	\$2,750.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user terrej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Jul 17, 2023	SYSTEM	(\$2,750.94)	
					10	Aug 2, 2023	SYSTEM	\$2,750.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user terrej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Aug 2, 2023	SYSTEM	(\$2,750.94)	
					11	Aug 15, 2023	SYSTEM	\$11,304.49	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Aug 15, 2023	SYSTEM	(\$11,304.49)	
					12	Sep 5, 2023	SYSTEM	\$11,304.49	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user terrej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Sep 5, 2023	SYSTEM	(\$11,304.49)	
					13	Sep 18, 2023	SYSTEM	\$11,304.49	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Sep 18, 2023	SYSTEM	(\$11,304.49)	
					14	Oct 2, 2023	SYSTEM	\$11,304.49	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Oct 2, 2023	SYSTEM	(\$11,304.49)	
					15	Oct 16, 2023	SYSTEM	\$11,304.49	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilsor2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					15	Oct 16, 2023	SYSTEM	(\$11,304.49)	
					16	Nov 1, 2023	SYSTEM	\$11,304.49	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user terrej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					16	Nov 1, 2023	SYSTEM	(\$11,304.49)	
					17	Nov 16, 2023	SYSTEM	\$11,304.49	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user terrej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					17	Nov 16, 2023	SYSTEM	(\$11,304.49)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0050 -				_		ava ==	\$0.00	
	0140	TYPE 5 AGGREGATE FOR BASE	Material		7	Jun 16, 2023	SYSTEM	\$1,467.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user terrej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Jun 16,	SYSTEM	(\$1,467.60)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3450	0140	TYPE 5	Material			2023			
		AGGREGATE FOR BASE			8	Jun 30, 2023	SYSTEM	\$5,381.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user terrej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$5,381.20)	
					9	Jul 17, 2023	SYSTEM	\$5,381.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user terrej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Jul 17, 2023	SYSTEM	(\$5,381.20)	
					10	Aug 2, 2023	SYSTEM	\$9,206.74	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user terrej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Aug 2, 2023	SYSTEM	(\$9,206.74)	
					11	Aug 15, 2023	SYSTEM	\$9,206.74	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Aug 15, 2023	SYSTEM	(\$9,206.74)	
					12	Sep 5, 2023	SYSTEM	\$9,206.74	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user terrej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Sep 5, 2023	SYSTEM	(\$9,206.74)	
					13	Sep 18, 2023	SYSTEM	\$39,995.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	Sep 18, 2023	SYSTEM	(\$39,995.77)	
					14	Oct 2, 2023	SYSTEM	\$39,995.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilsor2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					14	Oct 2, 2023	SYSTEM	(\$39,995.77)	
					15	Oct 16, 2023	SYSTEM	\$39,995.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilsor2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					15	Oct 16, 2023	SYSTEM	(\$39,995.77)	
					16	Nov 1, 2023	SYSTEM	\$39,995.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user terrej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					16	Nov 1, 2023	SYSTEM	(\$39,995.77)	
					17	Nov 16, 2023	SYSTEM	\$41,879.19	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user terrej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					17	Nov 16, 2023	SYSTEM	(\$41,879.19)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0140 -							\$0.00	
	0150	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		3	Apr 17, 2023	SYSTEM	\$40,012.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilsor2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		111101()			3	Apr 17, 2023	SYSTEM	(\$40,012.39)	
					4	May 2, 2023	SYSTEM	\$40,012.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilsor2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 1, 2023	SYSTEM	(\$40,012.39)	
					5	May 16, 2023	SYSTEM	\$40,012.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3450	0150	TYPE 5 AGGREGATE FOR	Material		5	May 16, 2023	SYSTEM	(\$40,012.39)	
		BASE (6 IN. THICK)			6	Jun 2, 2023	SYSTEM	\$40,012.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jun 2, 2023	SYSTEM	(\$40,012.39)	
					7	Jun 16, 2023	SYSTEM	\$63,201.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user terrej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$63,201.29)	
					8	Jun 30, 2023	SYSTEM	\$88,638.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user terrej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$88,638.75)	
					9	Jul 17, 2023	SYSTEM	\$88,638.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user terrej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Jul 17, 2023	SYSTEM	(\$88,638.75)	
					10	Aug 2, 2023	SYSTEM	\$88,638.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user terrej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Aug 2, 2023	SYSTEM	(\$88,638.75)	
					11	Aug 15, 2023	SYSTEM	\$115,014.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11	Aug 15, 2023	SYSTEM	(\$115,014.75)	
					12	Sep 5, 2023	SYSTEM	\$115,014.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user terrej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					12	Sep 5, 2023	SYSTEM	(\$115,014.75)	
					13	Sep 18, 2023	SYSTEM	\$119,399.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilsor2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					13	Sep 18, 2023	SYSTEM	(\$119,399.76)	
					14	Oct 2, 2023	SYSTEM	\$129,139.09	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilsor2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					14	Oct 2, 2023	SYSTEM	(\$129,139.09)	
					15	Oct 16, 2023	SYSTEM	\$129,139.09	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilsor2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					15	Oct 16, 2023	SYSTEM	(\$129,139.09)	
					16	Nov 1, 2023	SYSTEM	\$129,139.09	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user terrej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					16	Nov 1, 2023	SYSTEM	(\$129,139.09)	
					17	Nov 16, 2023	SYSTEM	\$157,291.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user terrej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					17	Nov 16, 2023	SYSTEM	(\$157,291.08)	
				- Total				\$0.00	
	0150 -	Total	Material - To	tal				\$0.00	
	0160	TYPE A2	Material		10	Aug 2,	SYSTEM	\$0.00 \$2,324.60	This adjustment offsets the original system-generated Material Payment
		SHOULDER				2023		,0200	Estimate Item Adjustment (0005) due to user terrej1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3450	0160	TYPE A2	Material						Estimate Exception 4 on the current Payment Estimate.
		SHOULDER			10	Aug 2, 2023	SYSTEM	(\$2,324.60)	
					11	Aug 15, 2023	SYSTEM	\$5,428.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilsor2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Aug 15, 2023	SYSTEM	(\$5,428.00)	
					12	Sep 5, 2023	SYSTEM	\$5,428.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user terrej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					12	Sep 5, 2023	SYSTEM	(\$5,428.00)	
					13	Sep 18, 2023	SYSTEM	\$7,849.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilsor2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					13	Sep 18, 2023	SYSTEM	(\$7,849.36)	
					14	Oct 2, 2023	SYSTEM	\$7,849.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					14	Oct 2, 2023	SYSTEM	(\$7,849.36)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	13	Sep 18, 2023	SYSTEM	(\$2,421.36)	
				Overrun - To	otal			(\$2,421.36)	
			Overrun - To	tal				(\$2,421.36)	
	0160 -	- Total						(\$2,421.36)	
	0170		Stockpile		6	Jun 2, 2023	SYSTEM	\$11,376.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$11,376.00	
			Construction	Stockpile S1	MI - Total			\$11,376.00	
			Material		3	Apr 17, 2023	SYSTEM	\$140,516.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Apr 17,			
						2023	SYSTEM	(\$140,516.68)	
					4		SYSTEM	(\$140,516.68) \$140,516.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
						2023 May 2,		· · · /	Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment
					4	2023 May 2, 2023 May 1,	SYSTEM	\$140,516.68	Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment
					4	2023 May 2, 2023 May 1, 2023 May 16,	SYSTEM SYSTEM	\$140,516.68 (\$140,516.68)	Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment
					4 5	2023 May 2, 2023 May 1, 2023 May 16, 2023	SYSTEM SYSTEM	\$140,516.68 (\$140,516.68) \$140,516.68	Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment
					4 5 5	2023 May 2, 2023 May 1, 2023 May 16, 2023 May 16, 2023 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$140,516.68 (\$140,516.68) \$140,516.68 (\$140,516.68)	Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilsor2 overridding Payment
					4 4 5 5 6	2023 May 2, 2023 May 1, 2023 May 16, 2023 May 16, 2023 Jun 2, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$140,516.68 (\$140,516.68) \$140,516.68 (\$140,516.68) \$140,516.68	Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilsor2 overridding Payment
					4 4 5 5 6	2023 May 2, 2023 May 1, 2023 May 16, 2023 May 16, 2023 Jun 2, 2023 Jun 2, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$140,516.68 (\$140,516.68) \$140,516.68 (\$140,516.68) \$140,516.68	Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilsor2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user terrej1 overridding Payment
					4 4 5 5 6 6 7 7	2023 May 2, 2023 May 1, 2023 May 16, 2023 May 16, 2023 Jun 2, 2023 Jun 2, 2023 Jun 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$140,516.68 (\$140,516.68) \$140,516.68 (\$140,516.68) \$140,516.68 (\$140,516.68) \$140,516.68	Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilsor2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user terrej1 overridding Payment
					4 4 5 5 6 6 7 7	2023 May 2, 2023 May 1, 2023 May 16, 2023 May 16, 2023 Jun 2, 2023 Jun 16, 2023 Jun 16, 2023 Jun 16, 2023 Jun 176, 2023 Jun 176, 2023 Jun 176, 2023 Jun 176, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$140,516.68 (\$140,516.68) \$140,516.68 (\$140,516.68) \$140,516.68 (\$140,516.68) \$140,516.68	Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilsor2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user terrej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user terrej1 overridding Payment Estimate Item Adjustment (0006) due to user terrej1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4I3450	0170	MISC.	Material			2023			Estimate Item Adjustment (0032) due to user terrej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					9	Jul 17, 2023	SYSTEM	(\$140,516.68)		
					10	Aug 2, 2023	SYSTEM	\$140,516.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user terrej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					10	Aug 2, 2023	SYSTEM	(\$140,516.68)		
					11	Aug 15, 2023	SYSTEM	\$140,516.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilsor2 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					11	Aug 15, 2023	SYSTEM	(\$140,516.68)		
					12	Sep 5, 2023	SYSTEM	\$140,516.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user terrej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					12	Sep 5, 2023	SYSTEM	(\$140,516.68)		
					13	Sep 18, 2023	SYSTEM	\$140,516.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wilsor2 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					13	Sep 18, 2023	SYSTEM	(\$140,516.68)		
					14	Oct 2, 2023	SYSTEM	\$140,516.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wilsor2 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					14	Oct 2, 2023	SYSTEM	(\$140,516.68)		
					15	Oct 16, 2023	SYSTEM	\$140,516.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					15	Oct 16, 2023	SYSTEM	(\$140,516.68)		
					16	Nov 1, 2023	SYSTEM	\$140,516.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user terrej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					16	Nov 1, 2023	SYSTEM	(\$140,516.68)		
					17	Nov 16, 2023	SYSTEM	\$140,516.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user terrej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					17	Nov 16, 2023	SYSTEM	(\$140,516.68)		
				- Total				\$0.00		
	0170 -	Total	Material - To	al				\$0.00 \$11,376.00		
	0190	MISC.	Material		7	Jun 16, 2023	SYSTEM	\$8,528.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user terrej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					7	Jun 16, 2023	SYSTEM	(\$8,528.30)		
					8	Jun 30, 2023	SYSTEM	\$8,528.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user terrej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					8	Jun 30, 2023	SYSTEM	(\$8,528.30)		
					9	Jul 17, 2023	SYSTEM	\$14,420.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user terrej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					9	Jul 17, 2023	SYSTEM	(\$14,420.58)		
					10	10	Aug 2, 2023	SYSTEM	\$14,420.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user terrej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					10	Aug 2, 2023	SYSTEM	(\$14,420.58)		



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
450	0190	MISC.	Material		11	Aug 15, 2023	SYSTEM	\$14,420.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
					11	Aug 15, 2023	SYSTEM	(\$14,420.58)							
					12	Sep 5, 2023	SYSTEM	\$14,420.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user terrej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
					12	Sep 5, 2023	SYSTEM	(\$14,420.58)							
					13	Sep 18, 2023	SYSTEM	\$14,420.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilsor2 overridding Payment Estimate Exception 7 on the current Payment Estimate.						
					13	Sep 18, 2023	SYSTEM	(\$14,420.58)							
					14	Oct 2, 2023	SYSTEM	\$14,420.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilsor2 overridding Payment Estimate Exception 10 on the current Payment Estimate.						
					14	Oct 2, 2023	SYSTEM	(\$14,420.58)							
				- Total				\$0.00							
	0190 -	Total	Material - To	tal				\$0.00 \$0.00							
	0200	MISC.	Material		2	Apr 3, 2023	SYSTEM	\$115,485.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilsor2 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					2	Apr 3, 2023	SYSTEM	(\$115,485.22)							
					3	Apr 17, 2023	SYSTEM	\$115,485.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
					3	Apr 17, 2023	SYSTEM	(\$115,485.22)							
					4	May 2, 2023	SYSTEM	\$115,485.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
											4	May 1, 2023	SYSTEM	(\$115,485.22)	
					5	May 16, 2023	SYSTEM	\$115,485.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilsor2 overridding Payment Estimate Exception 10 on the current Payment Estimate.						
					5	May 16, 2023	SYSTEM	(\$115,485.22)							
					6	Jun 2, 2023	SYSTEM	\$280,347.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment Estimate Exception 9 on the current Payment Estimate.						
					6	Jun 2, 2023	SYSTEM	(\$280,347.41)							
					7	Jun 16, 2023	SYSTEM	\$280,347.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user terrej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.						
					7	Jun 16, 2023	SYSTEM	(\$280,347.41)							
					8	Jun 30, 2023	SYSTEM	\$280,347.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user terrej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.						
					8	Jun 30, 2023	SYSTEM	(\$280,347.41)							
					9	Jul 17, 2023	SYSTEM	\$280,347.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user terrej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.						
					9	Jul 17, 2023	SYSTEM	(\$280,347.41)							
				- Total				\$0.00							
			Material - To	tal				\$0.00							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3450	0210	MISC.	Construction Stockpile		7	Jun 16, 2023	SYSTEM	(\$5,359.17)	Payment Estimate Item Adjustment generated Stockpile Transaction
					8	Jun 30, 2023	SYSTEM	(\$6,563.14)	Payment Estimate Item Adjustment generated Stockpile Transaction
					10	Aug 2, 2023	SYSTEM	(\$246.13)	Payment Estimate Item Adjustment generated Stockpile Transaction
					11	Aug 15, 2023	SYSTEM	(\$6,805.29)	Payment Estimate Item Adjustment generated Stockpile Transaction
					13	Sep 18, 2023	SYSTEM	(\$455.39)	Payment Estimate Item Adjustment generated Stockpile Transaction
					14	Oct 2, 2023	SYSTEM	(\$5,810.59)	Payment Estimate Item Adjustment generated Stockpile Transaction
					17	Nov 16, 2023	SYSTEM	(\$7,263.52)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$32,503.23)	
			Construction	Stockpile - 1	Total			(\$32,503.23)	
			Construction Stockpile		6	Jun 2, 2023	SYSTEM	\$34,696.80	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$34,696.80	
			Construction	Stockpile S	TMI - Tota			\$34,696.80	
			Material		7	Jun 16, 2023	SYSTEM	\$76,686.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user terrej1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					7	Jun 16, 2023	SYSTEM	(\$76,686.75)	
					8	Jun 30, 2023	SYSTEM	\$170,601.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user terrej1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$170,601.64)	
					9	Jul 17, 2023	SYSTEM	\$170,601.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user terrej1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					9	Jul 17, 2023	SYSTEM	(\$170,601.64)	
					10	Aug 2, 2023	SYSTEM	\$174,123.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user terrej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					10	Aug 2, 2023	SYSTEM	(\$174,123.56)	
					11	Aug 15, 2023	SYSTEM	\$271,503.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilsor2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					11	Aug 15, 2023	SYSTEM	(\$271,503.56)	
					12	Sep 5, 2023	SYSTEM	\$271,503.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user terrej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					12	Sep 5, 2023	SYSTEM	(\$271,503.56)	
					13	Sep 18, 2023	SYSTEM	\$278,019.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					13	Sep 18, 2023	SYSTEM	(\$278,019.90)	
					14	Oct 2, 2023	SYSTEM	\$361,166.19	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilsor2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					14	Oct 2, 2023	SYSTEM	(\$361,166.19)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0210 -	- Total						\$2,193.57	
	0230	CONCRETE APPROACH	Material		13	Sep 18, 2023	SYSTEM	\$40,324.63	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wilsor2 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3450	0230	PAVEMENT	Material						Estimate Exception 11 on the current Payment Estimate.
					13	Sep 18, 2023	SYSTEM	(\$40,324.63)	
					14	Oct 2, 2023	SYSTEM	\$40,324.63	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wilsor2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					14	Oct 2, 2023	SYSTEM	(\$40,324.63)	
					15	Oct 16, 2023	SYSTEM	\$40,324.63	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilsor2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					15	Oct 16, 2023	SYSTEM	(\$40,324.63)	
					16	Nov 1, 2023	SYSTEM	\$40,324.63	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user terrej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					16	Nov 1, 2023	SYSTEM	(\$40,324.63)	
					17	Nov 16, 2023	SYSTEM	\$40,324.63	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user terrej1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					17	Nov 16, 2023	SYSTEM	(\$40,324.63)	
				- Total				\$0.00	
			Material - To					\$0.00	
	0230 -	Total						\$0.00	
	0250	CHAIN-LINK FENCE (RETAINING WALLS)	E G		17	Nov 16, 2023	SYSTEM	\$5,458.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user terrej1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					17	Nov 16, 2023	SYSTEM	(\$5,458.18)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0250 -							\$0.00	
	0290	TRUNCATED DOMES	Material		12	Sep 5, 2023	SYSTEM	\$1,958.24	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user terrej1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					12	Sep 5, 2023	SYSTEM	(\$1,958.24)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0290 -							\$0.00	
	0300	8 IN. CONCRETE	Material		10	Aug 2			
		MEDIAN STRIP			10	Aug 2, 2023	SYSTEM	\$13,206.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user terrej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		MEDIAN STRIP			10		SYSTEM	\$13,206.54 (\$13,206.54)	Estimate Item Adjustment (0010) due to user terrej1 overridding Payment
		MEDIAN STRIP				2023 Aug 2,			Estimate Item Adjustment (0010) due to user terrej1 overridding Payment
		MEDIAN STRIP			10	2023 Aug 2, 2023 Aug 15,	SYSTEM	(\$13,206.54)	Estimate Item Adjustment (0010) due to user terrej1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wilsor2 overridding Payment
		MEDIAN STRIP			10	Aug 2, 2023 Aug 15, 2023 Aug 15,	SYSTEM SYSTEM	(\$13,206.54) \$13,206.54	Estimate Item Adjustment (0010) due to user terrej1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wilsor2 overridding Payment
		WEDIAN STRIP			10 11	Aug 2, 2023 Aug 15, 2023 Aug 15, 2023 Sep 5, 2023 Sep 5,	SYSTEM SYSTEM SYSTEM	(\$13,206.54) \$13,206.54 (\$13,206.54)	Estimate Item Adjustment (0010) due to user terrej1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wilsor2 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user terrej1 overridding Payment
		WEDIAN STRIP			10 11 11 12	Aug 2, 2023 Aug 15, 2023 Aug 15, 2023 Sep 5, 2023	SYSTEM SYSTEM SYSTEM SYSTEM	(\$13,206.54) \$13,206.54 (\$13,206.54) \$40,292.52	Estimate Item Adjustment (0010) due to user terrej1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wilsor2 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user terrej1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilsor2 overridding Payment Estimate Item Adjustment (0012) due to user wilsor2 overridding Payment
		WEDIAN STRIP			10 11 11 12	Aug 2, 2023 Aug 15, 2023 Aug 15, 2023 Sep 5, 2023 Sep 5, 2023 Sep 18,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$13,206.54) \$13,206.54 (\$13,206.54) \$40,292.52 (\$40,292.52)	Estimate Item Adjustment (0010) due to user terrej1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wilsor2 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user terrej1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																						
13450	0300	8 IN. CONCRETE MEDIAN STRIP	Material		14	Oct 2, 2023	SYSTEM	(\$43,807.57)																							
				- Total				\$0.00																							
			Material - To	tal				\$0.00																							
	0300 -							\$0.00																							
	0320	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	Material		9	Jul 17, 2023	SYSTEM	\$12,196.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user terrej1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																						
					9	Jul 17, 2023	SYSTEM	(\$12,196.08)																							
					14	Oct 2, 2023	SYSTEM	\$28,301.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user wilsor2 overridding Payment Estimate Exception 18 on the current Payment Estimate.																						
					14	Oct 2, 2023	SYSTEM	(\$28,301.16)																							
				- Total				\$0.00																							
			Material - To	tal				\$0.00																							
	0320 -	Total						\$0.00																							
	0340	CURB AND GUTTER TYPE B	Material		7	Jun 16, 2023	SYSTEM	\$6,070.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user terrej1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																						
							7	Jun 16, 2023	SYSTEM	(\$6,070.35)																					
																											8	Jun 30, 2023	SYSTEM	\$22,388.13	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user terrej1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
																										8	Jun 30, 2023	SYSTEM	(\$22,388.13)		
					9	Jul 17, 2023	SYSTEM	\$22,388.13	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user terrej1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																						
																				9	Jul 17, 2023	SYSTEM	(\$22,388.13)								
												10	Aug 2, 2023	SYSTEM	\$22,388.13	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user terrej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.															
						10	Aug 2, 2023	SYSTEM	(\$22,388.13)																						
					11	Aug 15, 2023	SYSTEM	\$27,753.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilsor2 overridding Payment Estimate Exception 11 on the current Payment Estimate.																						
					11	Aug 15, 2023	SYSTEM	(\$27,753.81)																							
																				12	Sep 5, 2023	SYSTEM	\$27,753.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user terrej1 overridding Payment Estimate Exception 15 on the current Payment Estimate.							
					12	Sep 5, 2023	SYSTEM	(\$27,753.81)																							
			1				13	Sep 18, 2023	SYSTEM	\$27,753.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user wilsor2 overridding Payment Estimate Exception 15 on the current Payment Estimate.																				
						13	Sep 18, 2023	SYSTEM	(\$27,753.81)																						
				14	Oct 2, 2023	SYSTEM	\$36,549.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user wilsor2 overridding Payment Estimate Exception 19 on the current Payment Estimate.																							
					14	Oct 2, 2023	SYSTEM	(\$36,549.45)																							
				- Total				\$0.00																							
			Material - To	tal				\$0.00																							
	0340 -	Total						\$0.00																							
	0350	PAVED DITCH	Material		13	Sep 18, 2023	SYSTEM	\$4,006.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user wilsor2 overridding Payment Estimate Exception 16 on the current Payment Estimate.																						
					13	Sep 18,	SYSTEM	(\$4,006.35)																							



Paved Ditch	
14 Oct 2, 2023 SYSTEM \$4,006.35 This adjustment offsets the original system-generated Material Parestimate Item Adjustment (0015) due to user wilsor2 overridding Estimate Exception 20 on the current Payment Estimate. 14 Oct 2, 2023 SYSTEM (\$4,006.35) 15 Oct 16, 2023 SYSTEM \$4,006.35 This adjustment offsets the original system-generated Material Parestimate. 16 SYSTEM \$4,006.35 This adjustment offsets the original system-generated Material Parestimate Item Adjustment (0011) due to user wilsor2 overridding	
2023 Estimate Item Adjustment (0015) due to user wilsor2 overridding Estimate Exception 20 on the current Payment Estimate. 14 Oct 2, 2023 (\$4,006.35) 15 Oct 16, SYSTEM \$4,006.35 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wilsor2 overridding	
2023 15 Oct 16, SYSTEM \$4,006.35 This adjustment offsets the original system-generated Material Prestrate Item Adjustment (0011) due to user wilsor2 overridding	
2023 Estimate Item Adjustment (0011) due to user wilsor2 overridding	
15 Oct 16, 2023 SYSTEM (\$4,006.35)	
16 Nov 1, 2023 \$4,006.35 This adjustment offsets the original system-generated Material Pr Estimate Item Adjustment (0009) due to user terrej1 overridding Estimate Exception 14 on the current Payment Estimate.	
16 Nov 1, 2023 SYSTEM (\$4,006.35)	
17 Nov 16, 2023 \$4,006.35 This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0050) due to user terrej1 overridding Estimate Exception 19 on the current Payment Estimate.	
17 Nov 16, 2023 (\$4,006.35)	
- Total \$0.00	
Material - Total \$0.00	
0350 - Total \$0.00	
0480 TYPE III Overrun Overrun 5 May 16, 2023 (\$1,218.91) MOVEABLE BARRICADE	
Overrun - Total (\$1,218.91)	
Overrun - Total (\$1,218.91)	
0480 - Total (\$1,218.91)	
0530 TEMPORARY Overrun Overrun 3 Apr 17, 2023 SYSTEM (\$6,859.60) Constitution Constitut	
4 May 1, 2023 SYSTEM \$6,859.60 Unit price based on averaged overrun adjustments for installed q previous payment estimates. Price Adjustments of ',1371.92000 - 'is applied (if non-zero).	
Overrun - Total \$0.00	
Overrun - Total \$0.00	
0530 - Total \$0.00	
0550 CONCRETE Construction TRAFFIC Stockpile BARRIER, TYPE C BARRIER, TYPE C STOCKPILL STOCKPILL STOCKPILL STOCKPILL STOCKPILL STOCKPILL STOCKPILL STOCKPILL SYSTEM (\$78.75) Payment Estimate Item Adjustment generated Stockpile Transaction (\$78.75) Payment Estimate Item Adjustment generated Stockpile Transaction (\$78.75) Payment Estimate Item Adjustment generated Stockpille Transaction (\$78.75) Payment generated Stockpi	ion
- Total (\$78.75)	
Construction Stockpile - Total (\$78.75) Construction 6 Jun 2, SYSTEM \$7,975.80 Payment Estimate Item Adjustment generated Stockpile Transact Stockpile 2023	ion
STMI - Total \$7,975.80	
Construction Stockpile STMI - Total \$7,975.80	
0550 - Total \$7,897.05	
0560 TEMPORARY Material 1 Mar 15, SYSTEM \$40,406.25 This adjustment offsets the original system-generated Material Prakfic BARRIER, CONT. SYSTEM \$40,406.25 Estimate Item Adjustment (0001) due to user wilsor2 overridding Estimate Exception 1 on the current Payment Estimate.	
FURN/RE 1 Mar 15, 2023 (\$40,406.25)	
- Total \$0.00	
Material - Total \$0.00	
0560 - Total \$0.00	
0570 TEMP. TRAF. BARR. STIFF. BARR. STIFF. TRNS. SEC, CONT STEM STAR STIFF. BARR. STIFF. BARR. STIFF. BARR. STIFF. BARR. STIFF. STEM STAR STIFF. STAR STAR STIFF. STAR STAR STAR STAR STAR STIFF. STAR STAR STAR STAR STAR STAR STAR STAR	
5 May 16, 2023 (\$15,699.50)	
6 Jun 2, 2023 SYSTEM \$15,699.50 This adjustment offsets the original system-generated Material Parestimate Item Adjustment (0008) due to user wilsor2 overridding Estimate Exception 14 on the current Payment Estimate.	



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
450	0570	TEMP. TRAF. BARR. STIFF.	Material		6	Jun 2, 2023	SYSTEM	(\$15,699.50)															
		TRNS. SEC, CONT			7	Jun 16, 2023	SYSTEM	\$15,699.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user terrej1 overridding Payment Estimate Exception 23 on the current Payment Estimate.														
					7	Jun 16, 2023	SYSTEM	(\$15,699.50)															
					8	Jun 30, 2023	SYSTEM	\$15,699.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user terrej1 overridding Payment Estimate Exception 20 on the current Payment Estimate.														
					8	Jun 30, 2023	SYSTEM	(\$15,699.50)															
					9	Jul 17, 2023	SYSTEM	\$15,699.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user terrej1 overridding Payment Estimate Exception 21 on the current Payment Estimate.														
					9	Jul 17, 2023	SYSTEM	(\$15,699.50)															
					10	Aug 2, 2023	SYSTEM	\$15,699.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user terrej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.														
					10	Aug 2, 2023	SYSTEM	(\$15,699.50)															
					11	Aug 15, 2023	SYSTEM	\$15,699.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user wilsor2 overridding Payment Estimate Exception 12 on the current Payment Estimate.														
					11	Aug 15, 2023	SYSTEM	(\$15,699.50)															
						12	Sep 5, 2023	SYSTEM	\$15,699.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user terrej1 overridding Payment Estimate Exception 16 on the current Payment Estimate.													
								12	Sep 5, 2023	SYSTEM	(\$15,699.50)												
					13	Sep 18, 2023	SYSTEM	\$15,699.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wilsor2 overridding Payment Estimate Exception 17 on the current Payment Estimate.														
					13	Sep 18, 2023	SYSTEM	(\$15,699.50)															
					14	Oct 2, 2023	SYSTEM	\$15,699.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user wilsor2 overridding Payment Estimate Exception 21 on the current Payment Estimate.														
					14	Oct 2, 2023	SYSTEM	(\$15,699.50)															
					15	Oct 16, 2023	SYSTEM	\$15,699.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilsor2 overridding Payment Estimate Exception 15 on the current Payment Estimate.														
					15	Oct 16, 2023	SYSTEM	(\$15,699.50)															
					16	Nov 1, 2023	SYSTEM	\$15,699.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user terrej1 overridding Payment Estimate Exception 15 on the current Payment Estimate.														
																			16	Nov 1, 2023	SYSTEM	(\$15,699.50)	
					17	Nov 16, 2023	SYSTEM	\$15,699.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user terrej1 overridding Payment Estimate Exception 20 on the current Payment Estimate.														
					17	Nov 16, 2023	SYSTEM	(\$15,699.50)															
			Material - To	- Total				\$0.00															
	0570 -	Total	Waterial - 10	lai				\$0.00															
	0680	TEMPORARY REMOVABLE MARKING TAPE 4	Material		15	Oct 16, 2023	SYSTEM	\$0.00 \$2,980.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user wilsor2 overridding Payment Estimate Exception 17 on the current Payment Estimate.														
		ĪN.,				1	15	Oct 16, 2023	SYSTEM	(\$2,980.51)													
						SYSTEM	\$2,980.51	This adjustment offsets the original system-generated Material Payment															



t Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
0680	TEMPORARY REMOVABLE	Material						Estimate Exception 17 on the current Payment Estimate.		
	MARKING TAPE 4			16	Nov 1, 2023	SYSTEM	(\$2,980.51)			
	,			17	Nov 16, 2023	SYSTEM	\$2,980.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user terrej1 overridding Payment Estimate Exception 22 on the current Payment Estimate.		
				17	Nov 16, 2023	SYSTEM	(\$2,980.51)	Estimate Exception 22 on the current rayment Estimate.		
			- Total				\$0.00			
		Material - Tot	tal				\$0.00			
0680	- Total						\$0.00			
0690	TEMPORARY REMOVABLE MARKING TAPE	Material		15	Oct 16, 2023	SYSTEM	\$1,507.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user wilsor2 overridding Payment Estimate Exception 18 on the current Payment Estimate.		
				15	Oct 16, 2023	SYSTEM	(\$1,507.28)			
				16	Nov 1, 2023	SYSTEM	\$1,507.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user terrej1 overridding Payment Estimate Exception 18 on the current Payment Estimate.		
				16	Nov 1, 2023	SYSTEM	(\$1,507.28)			
						17	Nov 16, 2023	SYSTEM	\$1,507.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user terrej1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				17	Nov 16, 2023	SYSTEM	(\$1,507.28)			
			- Total				\$0.00			
		Material - Tot	tal				\$0.00			
0690	- Total						\$0.00			
0940	15 IN. GROUP B FLARED END SEC	Material		7	Jun 16, 2023	SYSTEM	\$1,877.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user terrej1 overridding Payment Estimate Exception 28 on the current Payment Estimate.		
				7	Jun 16, 2023	SYSTEM	(\$1,877.70)			
		- Total					\$0.00			
		Material - To	tal				\$0.00			
	- Total						\$0.00			
1000	SILT FENCE	E Material		5	May 16, 2023	SYSTEM	\$3,244.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilsor2 overridding Payment Estimate Exception 18 on the current Payment Estimate.		
				5	May 16, 2023	SYSTEM	(\$3,244.16)			
				6	Jun 2, 2023	SYSTEM	\$3,244.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wilsor2 overridding Payment Estimate Exception 16 on the current Payment Estimate.		
				6	Jun 2, 2023	SYSTEM	(\$3,244.16)			
		7	-	Jun 16, 2023	SYSTEM	\$3,244.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user terrej1 overridding Payment Estimate Exception 29 on the current Payment Estimate.			
				7	Jun 16, 2023	SYSTEM	(\$3,244.16)			
			- Total				\$0.00			
		Material - To	tal				\$0.00			
	- Total					0)4275	\$0.00			
1010	MGS GUARDRAIL	Construction Stockpile STMI	Total	2	Apr 3, 2023	SYSTEM	\$20,515.25	Payment Estimate Item Adjustment generated Stockpile Transaction		
		Construction	- Total	TMI Total			\$20,515.25			
		Construction Stockpile STMI - Total					\$20,515.25			
1040	- Total									
1010 - 1020	- Total MGS BRIDGE	Construction		6	Jun 2,	SYSTEM	\$20,515.25 \$9,680.00	Payment Estimate Item Adjustment generated Stockpile Transaction		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
413450	1020	(EXT CURB)	STMI	- Total				\$9,680.00																		
			Construction	Stockpile S	TMI - Total			\$9,680.00																		
- 1	1020 -	Total						\$9,680.00																		
	1030	MGS END ANCHOR	Construction Stockpile		2	Apr 3, 2023	SYSTEM	\$840.00	Payment Estimate Item Adjustment generated Stockpile Transaction																	
			STMI	- Total				\$840.00																		
			Construction	Stockpile S	ΓMI - Total			\$840.00																		
	1030 -	Total						\$840.00																		
	1040	TYPE A CRASHWORTHY	Construction Stockpile		2	Apr 3, 2023	SYSTEM	\$5,775.00	Payment Estimate Item Adjustment generated Stockpile Transaction																	
		END TERMINAL (MASH)	STMI	- Total				\$5,775.00																		
			Construction	Stockpile S	ΓMI - Total			\$5,775.00																		
	1040 -	Total						\$5,775.00																		
	1080	CONDUIT, 3 IN. RIGID, PUSHED	Material		14	Oct 2, 2023	SYSTEM	\$5,361.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user wilsor2 overridding Payment Estimate Exception 41 on the current Payment Estimate.																	
					14	Oct 2, 2023	SYSTEM	(\$5,361.30)																		
													15	Oct 16, 2023	SYSTEM	\$5,361.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wilsor2 overridding Payment Estimate Exception 39 on the current Payment Estimate.									
								16	Nov 1, 2023	SYSTEM	\$5,361.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user terrej1 overridding Payment Estimate Exception 42 on the current Payment Estimate.														
											16	Nov 1, 2023	SYSTEM	(\$5,361.30)												
									17	Nov 16, 2023	SYSTEM	\$5,361.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user terrej1 overridding Payment Estimate Exception 41 on the current Payment Estimate.													
					17	Nov 16, 2023	SYSTEM	(\$5,361.30)																		
				- Total				\$0.00																		
			Material - Total					\$0.00																		
	1080 -	Total						\$0.00																		
	1110	PULL BOX, PREFORMED CLASS 1	Material		14	Oct 2, 2023	SYSTEM	\$5,185.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user wilsor2 overridding Payment Estimate Exception 42 on the current Payment Estimate.																	
					14	Oct 2, 2023	SYSTEM	(\$5,185.86)																		
					15	Oct 16, 2023	SYSTEM	\$5,185.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user wilsor2 overridding Payment Estimate Exception 40 on the current Payment Estimate.																	
										15	Oct 16, 2023	SYSTEM	(\$5,185.86)													
				16	16	Nov 1, 2023	SYSTEM	\$5,185.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user terrej1 overridding Payment Estimate Exception 43 on the current Payment Estimate.																	
					16	Nov 1, 2023	SYSTEM	(\$5,185.86)																		
				1	17	Nov 16, 2023	SYSTEM	\$5,185.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user terrej1 overridding Payment Estimate Exception 42 on the current Payment Estimate.																	
					17	Nov 16, 2023	SYSTEM	(\$5,185.86)																		
				- Total				\$0.00																		
			Material - Tot	tal				\$0.00																		
	1110 -	Total						\$0.00																		
	1140	MISC. HIGHWAY LIGHTING	Material		16	Nov 1, 2023	SYSTEM	\$7,554.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user terrej1 overridding Payment Estimate Exception 44 on the current Payment Estimate.																	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J4I3450	1140	MISC. HIGHWAY LIGHTING	Material	31-	16	Nov 1, 2023	SYSTEM	(\$7,554.00)					
					17	Nov 16, 2023	SYSTEM	\$7,554.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user terrej1 overridding Payment Estimate Exception 43 on the current Payment Estimate.				
					17	Nov 16, 2023	SYSTEM	(\$7,554.00)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	1140 -	Total						\$0.00					
	1290	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		8	Jun 30, 2023	SYSTEM	\$4,804.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user terrej1 overridding Payment Estimate Exception 34 on the current Payment Estimate.				
					8	Jun 30, 2023	SYSTEM	(\$4,804.25)					
					9	Jul 17, 2023	SYSTEM	\$4,804.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user terrej1 overridding Payment Estimate Exception 43 on the current Payment Estimate.				
					9	Jul 17, 2023	SYSTEM	(\$4,804.25)					
					10	Aug 2, 2023	SYSTEM	\$4,804.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user terrej1 overridding Payment Estimate Exception 30 on the current Payment Estimate.				
					10	Aug 2, 2023	SYSTEM	(\$4,804.25)					
					11	Aug 15, 2023	SYSTEM	\$4,804.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user wilsor2 overridding Payment Estimate Exception 32 on the current Payment Estimate.				
					11	Aug 15, 2023	SYSTEM	(\$4,804.25)					
					12	Sep 5, 2023	SYSTEM	\$4,804.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user terrej1 overridding Payment Estimate Exception 37 on the current Payment Estimate.				
					12	Sep 5, 2023	SYSTEM	(\$4,804.25)					
					13	Sep 18, 2023	SYSTEM	\$4,804.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user wilsor2 overridding Payment Estimate Exception 38 on the current Payment Estimate.				
					13	Sep 18, 2023	SYSTEM	(\$4,804.25)					
					14	Oct 2, 2023	SYSTEM	\$6,289.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user wilsor2 overridding Payment Estimate Exception 43 on the current Payment Estimate.				
					14	Oct 2, 2023	SYSTEM	(\$6,289.20)					
						15	Oct 16, 2023	SYSTEM	\$6,289.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user wilsor2 overridding Payment Estimate Exception 41 on the current Payment Estimate.			
							15	Oct 16, 2023	SYSTEM	(\$6,289.20)			
												16	Nov 1, 2023
					16	Nov 1, 2023	SYSTEM	(\$6,289.20)					
					17	Nov 16, 2023	SYSTEM	\$6,289.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user terrej1 overridding Payment Estimate Exception 44 on the current Payment Estimate.				
					17	Nov 16, 2023	SYSTEM	(\$6,289.20)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	1290 -	Total						\$0.00					
	1300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material		6	Jun 2, 2023	SYSTEM	\$17,316.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wilsor2 overridding Payment Estimate Exception 17 on the current Payment Estimate.				



		Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
413450 13	1300	CONDUIT, 3 IN., PUSHED WITH			6	Jun 2, 2023	SYSTEM	(\$17,316.00)							
		TRACER WIRE			7	Jun 16, 2023	SYSTEM	\$23,576.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user terrej1 overridding Payment Estimate Exception 30 on the current Payment Estimate.						
					7	Jun 16, 2023	SYSTEM	(\$23,576.40)							
					8	Jun 30, 2023	SYSTEM	\$23,576.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user terrej1 overridding Payment Estimate Exception 35 on the current Payment Estimate.						
					8	Jun 30, 2023	SYSTEM	(\$23,576.40)							
					9	Jul 17, 2023	SYSTEM	\$23,576.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user terrej1 overridding Payment Estimate Exception 44 on the current Payment Estimate.						
					9	Jul 17, 2023	SYSTEM	(\$23,576.40)							
					10	Aug 2, 2023	SYSTEM	\$23,576.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user terrej1 overridding Payment Estimate Exception 31 on the current Payment Estimate.						
					10	Aug 2, 2023	SYSTEM	(\$23,576.40)							
						11	Aug 15, 2023	SYSTEM	\$23,576.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wilsor2 overridding Payment Estimate Exception 33 on the current Payment Estimate.					
						11	Aug 15, 2023	SYSTEM	(\$23,576.40)						
						12	Sep 5, 2023	SYSTEM	\$23,576.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user terrej1 overridding Payment Estimate Exception 38 on the current Payment Estimate.					
					12	Sep 5, 2023	SYSTEM	(\$23,576.40)							
					13	Sep 18, 2023	SYSTEM	\$23,576.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user wilsor2 overridding Payment Estimate Exception 39 on the current Payment Estimate.						
					13	Sep 18, 2023	SYSTEM	(\$23,576.40)							
					14	Oct 2, 2023	SYSTEM	\$28,871.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user wilsor2 overridding Payment Estimate Exception 44 on the current Payment Estimate.						
					14	Oct 2, 2023	SYSTEM	(\$28,871.10)							
					15	Oct 16, 2023	SYSTEM	\$28,871.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user wilsor2 overridding Payment Estimate Exception 42 on the current Payment Estimate.						
					15 16 16 17 17	15	Oct 16, 2023	SYSTEM	(\$28,871.10)						
						16	Nov 1, 2023	SYSTEM	\$28,871.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user terrej1 overridding Payment Estimate Exception 46 on the current Payment Estimate.					
													16	Nov 1, 2023	SYSTEM
													17	17	Nov 16, 2023
						17	Nov 16, 2023	SYSTEM	(\$28,871.10)						
			Material - To	- Total				\$0.00							
	1300	Total	Waterial - 10	lai				\$0.00							
	1350	300 - Total POWER SUPPLY ASSEMBLY, TYPE 2	Material		14	Oct 2, 2023	SYSTEM	\$0.00 \$6,151.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user wilsor2 overridding Payment Estimate Exception 45 on the current Payment Estimate.						
					14	Oct 2, 2023	SYSTEM	(\$6,151.48)							
					15	Oct 16, 2023	SYSTEM	\$6,151.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user wilsor2 overridding Payment						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3450	1350	POWER SUPPLY	Material						Estimate Exception 43 on the current Payment Estimate.
		ASSEMBLY, TYPE 2			15	Oct 16, 2023	SYSTEM	(\$6,151.48)	
					16	Nov 1, 2023	SYSTEM	\$6,151.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user terrej1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					16	Nov 1, 2023	SYSTEM	(\$6,151.48)	
					17	Nov 16, 2023	SYSTEM	\$6,151.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user terrej1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					17	Nov 16, 2023	SYSTEM	(\$6,151.48)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1350 -	Total						\$0.00	
	1360	PULL BOX, PREFORMED CLASS 2	Material		8	Jun 30, 2023	SYSTEM	\$10,621.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user terrej1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					8	Jun 30, 2023	SYSTEM	(\$10,621.80)	
					9	Jul 17, 2023	SYSTEM	\$10,621.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user terrej1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					9	Jul 17, 2023	SYSTEM	(\$10,621.80)	
					10	Aug 2, 2023	SYSTEM	\$10,621.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user terrej1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					10	Aug 2, 2023	SYSTEM	(\$10,621.80)	
					11	Aug 15, 2023	SYSTEM	\$10,621.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user wilsor2 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					11	Aug 15, 2023	SYSTEM	(\$10,621.80)	
					12	Sep 5, 2023	SYSTEM	\$10,621.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user terrej1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					12	Sep 5, 2023	SYSTEM	(\$10,621.80)	
					13	Sep 18, 2023	SYSTEM	\$10,621.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user wilsor2 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					13	Sep 18, 2023	SYSTEM	(\$10,621.80)	
					14	Oct 2, 2023	SYSTEM	\$21,243.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user wilsor2 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					14	Oct 2, 2023	SYSTEM	(\$21,243.60)	
					15	Oct 16, 2023	SYSTEM	\$21,243.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user wilsor2 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					15	Oct 16, 2023	SYSTEM	(\$21,243.60)	
					16	Nov 1, 2023	SYSTEM	\$21,243.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user terrej1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					16	Nov 1, 2023	SYSTEM	(\$21,243.60)	
					17	Nov 16, 2023	SYSTEM	\$21,243.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user terrej1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					17	Nov 16, 2023	SYSTEM	(\$21,243.60)	



t Li	ne Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0 13	PULL BOX, PREFORMED		- Total				\$0.00		
10	CLASS 2	Material - To	tal			\$0.00			
	60 - Total			-	1 10	OVOTEM	\$0.00		
13	PULL BOX PREFORMEI CLASS	Material	rial	7	Jun 16, 2023	SYSTEM	\$2,955.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user terrej1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	
				7	Jun 16, 2023	SYSTEM	(\$2,955.96)		
				8	Jun 30, 2023	SYSTEM	\$2,955.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user terrej1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	
				8	Jun 30, 2023	SYSTEM	(\$2,955.96)		
				9	Jul 17, 2023	SYSTEM	\$2,955.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user terrej1 overridding Payment Estimate Exception 46 on the current Payment Estimate.	
				9	Jul 17, 2023	SYSTEM	(\$2,955.96)		
				10	Aug 2, 2023	SYSTEM	\$2,955.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user terrej1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	
				10	Aug 2, 2023	SYSTEM	(\$2,955.96)		
				11	Aug 15, 2023	SYSTEM	\$2,955.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user wilsor2 overridding Paymen Estimate Exception 35 on the current Payment Estimate.	
				11	Aug 15, 2023	SYSTEM	(\$2,955.96)		
				12	Sep 5, 2023	SYSTEM	\$2,955.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user terrej1 overridding Payment Estimate Exception 40 on the current Payment Estimate.	
				12	Sep 5, 2023	SYSTEM	(\$2,955.96)		
				13	Sep 18, 2023	SYSTEM	\$2,955.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user wilsor2 overridding Paymen Estimate Exception 41 on the current Payment Estimate.	
				13	Sep 18, 2023	SYSTEM	(\$2,955.96)		
				14	Oct 2, 2023	SYSTEM	\$5,911.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user wilsor2 overridding Paymen Estimate Exception 47 on the current Payment Estimate.	
				14	Oct 2, 2023	SYSTEM	(\$5,911.92)		
				15	Oct 16, 2023	SYSTEM	\$5,911.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user wilsor2 overridding Paymen Estimate Exception 45 on the current Payment Estimate.	
				15	Oct 16, 2023	SYSTEM	(\$5,911.92)		
					16	Nov 1, 2023	SYSTEM	\$5,911.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user terrej1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
		Material - Tot			16	Nov 1, 2023	SYSTEM	(\$5,911.92)	
				17	Nov 16, 2023	SYSTEM	\$5,911.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user terrej1 overridding Payment Estimate Exception 48 on the current Payment Estimate.	
				17	Nov 16, 2023	SYSTEM	(\$5,911.92)		
			- Total				\$0.00		
			tal				\$0.00		
13	70 - Total						\$0.00		
14	STRUCTURAL STEEL POSTS	Construction Stockpile STMI		9	Jul 17, 2023	SYSTEM	\$4,436.25	Payment Estimate Item Adjustment generated Stockpile Transaction	
			- Total				\$4,436.25		
		Construction	n Stockpile S	TMI - Tota			\$4,436.25		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																			
J4I3450	1440 -	Total						\$4,436.25																				
	1450	PIPE POSTS	Construction Stockpile STMI		9	Jul 17, 2023	SYSTEM	\$4,055.15	Payment Estimate Item Adjustment generated Stockpile Transaction																			
			STIVII	- Total				\$4,055.15																				
			Construction	Stockpile S	ГМI - Total			\$4,055.15																				
	1450 -	Total						\$4,055.15																				
	1510	MISC.	Construction Stockpile STMI		16	Nov 1, 2023	SYSTEM	\$63,840.00	Payment Estimate Item Adjustment generated Stockpile Transaction																			
			OTIVII	- Total				\$63,840.00																				
			Construction	Stockpile S	ΓMI - Total			\$63,840.00																				
	1510 -	Total						\$63,840.00																				
	1520	CONDUIT, 2 IN., RIGID, IN TRENCH	Material		6	Jun 2, 2023	SYSTEM	\$4,841.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilsor2 overridding Payment Estimate Exception 18 on the current Payment Estimate.																			
					6	Jun 2, 2023	SYSTEM	(\$4,841.20)																				
					7	Jun 16, 2023	SYSTEM	\$4,841.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user terrej1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																			
					7	Jun 16, 2023	SYSTEM	(\$4,841.20)																				
					8	Jun 30, 2023	SYSTEM	\$4,841.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user terrej1 overridding Payment Estimate Exception 38 on the current Payment Estimate.																			
					8	Jun 30, 2023	SYSTEM	(\$4,841.20)																				
					9	Jul 17, 2023	SYSTEM	\$4,841.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user terrej1 overridding Payment Estimate Exception 47 on the current Payment Estimate.																			
					9	Jul 17, 2023	SYSTEM	(\$4,841.20)																				
					10	Aug 2, 2023	SYSTEM	\$4,841.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user terrej1 overridding Payment Estimate Exception 34 on the current Payment Estimate.																			
						10	Aug 2, 2023	SYSTEM	(\$4,841.20)																			
					11	Aug 15, 2023	SYSTEM	\$4,841.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user wilsor2 overridding Payment Estimate Exception 36 on the current Payment Estimate.																			
					11	Aug 15, 2023	SYSTEM	(\$4,841.20)																				
										12	Sep 5, 2023	SYSTEM	\$4,841.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user terrej1 overridding Payment Estimate Exception 41 on the current Payment Estimate.														
								12	Sep 5, 2023	SYSTEM	(\$4,841.20)																	
																					13	Sep 18, 2023	SYSTEM	\$4,841.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user wilsor2 overridding Payment Estimate Exception 42 on the current Payment Estimate.			
						13	Sep 18, 2023	SYSTEM	(\$4,841.20)																			
																								14	Oct 2, 2023	SYSTEM	\$4,841.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user wilsor2 overridding Payment Estimate Exception 48 on the current Payment Estimate.
																						14	Oct 2, 2023	SYSTEM	(\$4,841.20)			
																	15	Oct 16, 2023	SYSTEM	\$4,841.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user wilsor2 overridding Payment Estimate Exception 46 on the current Payment Estimate.							
					15	Oct 16, 2023	SYSTEM	(\$4,841.20)																				
																	16	Nov 1, 2023	SYSTEM	\$4,841.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user terrej1 overridding Payment Estimate Exception 50 on the current Payment Estimate.							
									16	Nov 1,	SYSTEM	(\$4,841.20)																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J4I3450	1520	CONDUIT, 2 IN.,	Material			2023												
		RIGID, IN TRENCH			17	Nov 16, 2023	SYSTEM	\$4,841.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user terrej1 overridding Payment Estimate Exception 49 on the current Payment Estimate.									
					17	Nov 16, 2023	SYSTEM	(\$4,841.20)										
				- Total				\$0.00										
			Material - Tot	tal				\$0.00										
	1520 -	Total						\$0.00										
	1530	CONDUIT, 4 IN., RIGID, IN TRENCH	Material		14	Oct 2, 2023	SYSTEM	\$1,721.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user wilsor2 overridding Payment Estimate Exception 49 on the current Payment Estimate.									
					14	Oct 2, 2023	SYSTEM	(\$1,721.41)										
					15	Oct 16, 2023	SYSTEM	\$1,721.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user wilsor2 overridding Payment Estimate Exception 47 on the current Payment Estimate.									
					15	Oct 16, 2023	SYSTEM	(\$1,721.41)										
					16	Nov 1, 2023	SYSTEM	\$1,721.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user terrej1 overridding Payment Estimate Exception 51 on the current Payment Estimate.									
						16	Nov 1, 2023	SYSTEM	(\$1,721.41)									
					17	Nov 16, 2023	SYSTEM	\$1,721.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user terrej1 overridding Payment Estimate Exception 50 on the current Payment Estimate.									
					17	Nov 16, 2023	SYSTEM	(\$1,721.41)										
				- Total		2020		\$0.00										
			Material - Tot					\$0.00										
	1530 -	Total					\$0.00											
	1540	CONDUIT, 3 IN., RIGID, PUSHED			6	Jun 2, 2023	SYSTEM	\$5,028.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user wilsor2 overridding Payment Estimate Exception 19 on the current Payment Estimate.									
					6	Jun 2, 2023	SYSTEM	(\$5,028.30)										
					7	Jun 16, 2023	SYSTEM	\$5,028.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user terrej1 overridding Payment Estimate Exception 33 on the current Payment Estimate.									
					7	Jun 16, 2023	SYSTEM	(\$5,028.30)										
					8	Jun 30, 2023	SYSTEM	\$5,028.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user terrej1 overridding Payment Estimate Exception 39 on the current Payment Estimate.									
					8	Jun 30, 2023	SYSTEM	(\$5,028.30)										
										-				9	Jul 17, 2023	SYSTEM	\$5,028.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user terrej1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					9	Jul 17, 2023	SYSTEM	(\$5,028.30)										
														10	Aug 2, 2023	SYSTEM	\$5,028.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user terrej1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					10	Aug 2, 2023	SYSTEM	(\$5,028.30)										
					11	Aug 15, 2023	SYSTEM	\$5,028.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user wilsor2 overridding Payment Estimate Exception 37 on the current Payment Estimate.									
					11	Aug 15, 2023	SYSTEM	(\$5,028.30)										
					12	Sep 5, 2023	SYSTEM	\$5,028.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user terre]1 overridding Payment Estimate Exception 42 on the current Payment Estimate.									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J4I3450	1540	CONDUIT, 3 IN., RIGID, PUSHED	Material		12	Sep 5, 2023	SYSTEM	(\$5,028.30)													
					13	Sep 18, 2023	SYSTEM	\$5,028.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user wilsor2 overridding Payment Estimate Exception 43 on the current Payment Estimate.												
					13	Sep 18, 2023	SYSTEM	(\$5,028.30)													
					14	Oct 2, 2023	SYSTEM	\$5,028.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user wilsor2 overridding Payment Estimate Exception 50 on the current Payment Estimate.												
					14	Oct 2, 2023	SYSTEM	(\$5,028.30)													
					15	Oct 16, 2023	SYSTEM	\$5,028.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user wilsor2 overridding Payment Estimate Exception 48 on the current Payment Estimate.												
					15	Oct 16, 2023	SYSTEM	(\$5,028.30)													
					16	Nov 1, 2023	SYSTEM	\$5,028.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user terrej1 overridding Payment Estimate Exception 52 on the current Payment Estimate.												
					16	Nov 1, 2023	SYSTEM	(\$5,028.30)													
					17	Nov 16, 2023	SYSTEM	\$5,028.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user terrej1 overridding Payment Estimate Exception 51 on the current Payment Estimate.												
						17	Nov 16, 2023	SYSTEM	(\$5,028.30)												
				- Total				\$0.00													
	1510		Material - To	tal				\$0.00													
	1540 - 1560	PULL BOX,	Material	Material		6	Jun 2,	SYSTEM	\$0.00 \$5,797.94	This adjustment offsets the original system-generated Material Payment											
	1300	PREFORMED CLASS 5	Material			2023			Estimate Item Adjustment (0014) due to user wilsor2 overridding Payment Estimate Exception 20 on the current Payment Estimate.												
											6	Jun 2, 2023	SYSTEM	(\$5,797.94)							
					7	Jun 16, 2023	SYSTEM	\$5,797.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user terrej1 overridding Payment Estimate Exception 34 on the current Payment Estimate.												
					7	Jun 16, 2023	SYSTEM	(\$5,797.94)													
					8	Jun 30, 2023	SYSTEM	\$5,797.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user terrej1 overridding Payment Estimate Exception 40 on the current Payment Estimate.												
					8	Jun 30, 2023	SYSTEM	(\$5,797.94)													
								9	Jul 17, 2023	SYSTEM	\$5,797.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user terrej1 overridding Payment Estimate Exception 49 on the current Payment Estimate.									
																	9	Jul 17, 2023	SYSTEM	(\$5,797.94)	
											10	Aug 2, 2023	SYSTEM	\$5,797.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user terrej1 overridding Payment Estimate Exception 36 on the current Payment Estimate.						
									10	Aug 2, 2023	SYSTEM	(\$5,797.94)									
					11	Aug 15, 2023	SYSTEM	\$5,797.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user wilsor2 overridding Payment Estimate Exception 38 on the current Payment Estimate.												
														11	Aug 15, 2023	SYSTEM	(\$5,797.94)				
								12	Sep 5, 2023	SYSTEM	\$5,797.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user terrej1 overridding Payment Estimate Exception 43 on the current Payment Estimate.									
			1	12	Sep 5, 2023	SYSTEM	(\$5,797.94)														
					13	Sep 18,	SYSTEM	\$5,797.94	This adjustment offsets the original system-generated Material Payment												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J4I3450	1560	PULL BOX,	Material						Estimate Exception 44 on the current Payment Estimate.														
		PREFORMED CLASS 5			13	Sep 18, 2023	SYSTEM	(\$5,797.94)															
					14	Oct 2, 2023	SYSTEM	\$5,797.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user wilsor2 overridding Payment Estimate Exception 51 on the current Payment Estimate.														
					14	Oct 2, 2023	SYSTEM	(\$5,797.94)															
					15	Oct 16, 2023	SYSTEM	\$5,797.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user wilsor2 overridding Payment Estimate Exception 49 on the current Payment Estimate.														
					15	Oct 16, 2023	SYSTEM	(\$5,797.94)															
					16	Nov 1, 2023	SYSTEM	\$5,797.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user terrej1 overridding Payment Estimate Exception 53 on the current Payment Estimate.														
					16	Nov 1, 2023	SYSTEM	(\$5,797.94)															
					17	Nov 16, 2023	SYSTEM	\$5,797.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user terrej1 overridding Payment Estimate Exception 52 on the current Payment Estimate.														
					17	Nov 16, 2023	SYSTEM	(\$5,797.94)															
				- Total		2020		\$0.00															
			Material - To	tal				\$0.00															
	1560 -	Total						\$0.00															
	1620	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		12	Sep 5, 2023	SYSTEM	\$64,363.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user terrej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.														
					12	Sep 5, 2023	SYSTEM	(\$64,363.87)															
					13	Sep 18, 2023	SYSTEM	\$64,363.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user wilsor2 overridding Payment Estimate Exception 9 on the current Payment Estimate.														
					13	Sep 18, 2023	SYSTEM	(\$64,363.87)															
					14	Oct 2, 2023	SYSTEM	\$64,363.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user wilsor2 overridding Payment Estimate Exception 12 on the current Payment Estimate.														
					14	Oct 2, 2023	SYSTEM	(\$64,363.87)															
					15	Oct 16, 2023	SYSTEM	\$64,363.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user wilsor2 overridding Payment Estimate Exception 9 on the current Payment Estimate.														
																			15	Oct 16, 2023	SYSTEM	(\$64,363.87)	
										16	Nov 1, 2023	SYSTEM	\$64,363.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user terrej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.									
							16	Nov 1, 2023	SYSTEM	(\$64,363.87)													
					17	Nov 16, 2023	SYSTEM	\$64,363.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user terrej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.														
					17	Nov 16, 2023	SYSTEM	(\$64,363.87)															
				- Total				\$0.00															
			Material - To	tal				\$0.00															
	1620 -	Total						\$0.00															
	1630	DRILLED SHAFTS (5 FT. 0 IN. DIA.)	Construction Stockpile		7	Jun 16, 2023	SYSTEM	(\$2,533.71)	Payment Estimate Item Adjustment generated Stockpile Transaction														
					8	Jun 30, 2023	SYSTEM	(\$175.29)	Payment Estimate Item Adjustment generated Stockpile Transaction														
				- Total																			
			Construction	Stockpile - 1	Total .			(\$2,709.00)															



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
413450	1630	DRILLED SHAFTS (5 FT. 0 IN. DIA.)	Construction Stockpile		6	Jun 2, 2023	SYSTEM	\$2,709.00	Payment Estimate Item Adjustment generated Stockpile Transaction								
			STMI	- Total				\$2,709.00									
			Construction	Stockpile S	ΓΜΙ - Tota			\$2,709.00									
			Material		7	Jun 16, 2023	SYSTEM	\$24,476.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user terrej1 overridding Payment Estimate Exception 25 on the current Payment Estimate.								
					7	Jun 16, 2023	SYSTEM	(\$24,476.78)									
					8	Jun 30, 2023	SYSTEM	\$24,476.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user terrej1 overridding Payment Estimate Exception 22 on the current Payment Estimate.								
					8	Jun 30, 2023	SYSTEM	(\$24,476.78)									
					9	Jul 17, 2023	SYSTEM	\$24,476.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user terrej1 overridding Payment Estimate Exception 24 on the current Payment Estimate.								
					9	Jul 17, 2023	SYSTEM	(\$24,476.78)									
					10	Aug 2, 2023	SYSTEM	\$24,476.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user terrej1 overridding Payment Estimate Exception 13 on the current Payment Estimate.								
					10	Aug 2, 2023	SYSTEM	(\$24,476.78)									
					11	Aug 15, 2023	SYSTEM	\$24,476.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user wilsor2 overridding Payment Estimate Exception 14 on the current Payment Estimate.								
					11	Aug 15, 2023	SYSTEM	(\$24,476.78)									
					12	Sep 5, 2023	SYSTEM	\$24,476.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user terrej1 overridding Payment Estimate Exception 18 on the current Payment Estimate.								
														12	Sep 5, 2023	SYSTEM	(\$24,476.78)
					13	Sep 18, 2023	SYSTEM	\$24,476.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user wilsor2 overridding Payment Estimate Exception 19 on the current Payment Estimate.								
					13	Sep 18, 2023	SYSTEM	(\$24,476.78)									
				- Total				\$0.00									
			Material - Tot	al				\$0.00									
	1630 -	Total						\$0.00									
	1640	ROCK SOCKETS (4 FT 6 IN. DIA.)	Overrun	Overrun	7	Jun 16, 2023	SYSTEM	(\$2,478.76)									
				Overrun - T	otal			(\$2,478.76)									
			Overrun - To	tal				(\$2,478.76)									
	1640 -	Total						(\$2,478.76)									
	1680	GALVANIZED STRUCTURAL STEEL PILES (12	Material		8	Jun 30, 2023	SYSTEM	\$18,846.24	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user terrej1 overridding Payment Estimate Exception 25 on the current Payment Estimate.								
		IN			8	Jun 30, 2023	SYSTEM	(\$18,846.24)									
					9	Jul 17, 2023	SYSTEM	\$45,593.74	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user terrej1 overridding Payment Estimate Exception 26 on the current Payment Estimate.								
					9	Jul 17, 2023	SYSTEM	(\$45,593.74)									
				- Total				\$0.00									
			Material - Tot	al				\$0.00									
	1680 -	Total						\$0.00									
	1700	PILE POINT REINFORCEMENT	Material		8	Jun 30, 2023	SYSTEM	\$775.67	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user terrej1 overridding Payment								
					8	Jun 30,	SYSTEM	(\$775.67)	Estimate Exception 26 on the current Payment Estimate.								
								,									



Package	ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
1700 Total	50	1700		Material			2023					
Total Spot			REINFORGEMENT			9		SYSTEM	\$775.67	Estimate Item Adjustment (0048) due to user terrej1 overridding Payment		
1700 - Total 1700 - Total 1700 - Total 1700 - Total 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 2003 200						9		SYSTEM	(\$775.67)			
1710 CLASS					- Total				\$0.00			
1710 CALASE B Material 2023 2023 2024 2023 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025 2025				Material - To	tal				\$0.00			
CONCRETE SUBSTRUCTURE)		1700 -	Total						\$0.00			
10		1710	CONCRETE	Material		9		SYSTEM	\$64,634.84	Estimate Item Adjustment (0049) due to user terrej1 overridding Payment		
2023 SYSTEM Status Estimate Exception 14 on the current of promoting Payment Estimate Status						9		SYSTEM	(\$64,634.84)			
11						10		SYSTEM	\$118,942.02	Estimate Item Adjustment (0021) due to user terrej1 overridding Payment		
2023 September Set Set September Set						10		SYSTEM	(\$118,942.02)			
12						11		SYSTEM	\$118,942.02	Estimate Item Adjustment (0022) due to user wilsor2 overridding Payment		
2023 Estimate Exception 19 on the current Payment Estimate.								11		SYSTEM	(\$118,942.02)	
13									12		SYSTEM	\$118,942.02
Superior						12		SYSTEM	(\$118,942.02)			
1710 - Total							13		SYSTEM	\$2,901.02	Estimate Item Adjustment (0025) due to user wilsor2 overridding Payment	
1710 - Total							13		SYSTEM	(\$2,901.02)		
1730 CONCRETE BEAM					- Total				\$0.00			
1730 CONCRETE BEAM Material 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2023 2				Material - To	tal				\$0.00			
2023 Estimate Item Adjustment (0023) due to user wilsor2 overridding Payment Estimate Exception 16 on the current Payment Estimate.		1710 -	Total						\$0.00			
Total \$0.00		1730		Material		11		SYSTEM	\$219,312.40	Estimate Item Adjustment (0023) due to user wilsor2 overridding Payment		
1730 - Total 1740 FORM LINERS Material 12 Sep 5, 2023 SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate tem Adjustment (0023) due to user terrej1 overridding Payment Estimate Exception 20 on the current Payment Estimate. 12 Sep 5, 2023 SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate tem Adjustment (0026) due to user wilsor2 overridding Payment Estimate tem Adjustment (0026) due to user wilsor2 overridding Payment Estimate Exception 21 on the current Payment Estimate. 13 Sep 18, 2023 SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate Estimate tem Adjustment (0029) due to user wilsor2 overridding Payment Estimate Exception 24 on the current Payment Estimate. 14 Oct 2, 2023 SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate Exception 24 on the current Payment Estimate. 15 Oct 16, SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate tem Adjustment (0027) due to user wilsor2 overridding Payment Estimate ltem Adjustment (0027) due to user wilsor2 overridding Payment Estimate ltem Adjustment (0027) due to user wilsor2 overridding Payment Estimate tem Adjustment (0027) due to user wilsor2 overridding Payment Estimate Exception 22 on the current Payment Estimate. 15 Oct 16, SYSTEM \$8,565.96						11		SYSTEM	(\$219,312.40)			
1730 - Total 1740 FORM LINERS Material 12 Sep 5, 2023 SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate. 12 Sep 5, 2023 SYSTEM \$8,565.96 SySTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate. 13 Sep 18, 2023 SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user wilsor2 overridding Payment Estimate Exception 21 on the current Payment Estimate Item Adjustment (0029) due to user wilsor2 overridding Payment Estimate Item Adjustment (0029) due to user wilsor2 overridding Payment Estimate Exception 24 on the current Payment Estimate. 14 Oct 2, 2023 SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate Exception 24 on the current Payment Estimate. 15 Oct 16, SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user wilsor2 overridding Payment Estimate Item Adjustment (0027) due to user wilsor2 overridding Payment Estimate Item Adjustment (0027) due to user wilsor2 overridding Payment Estimate Item Adjustment (0027) due to user wilsor2 overridding Payment Estimate Exception 22 on the current Payment Estimate. 15 Oct 16, SYSTEM \$8,565.96 SYSTEM \$8,					- Total				\$0.00			
1740 FORM LINERS Material 12 Sep 5, 2023 SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user terrej1 overridding Payment Estimate Exception 20 on the current Payment Estimate. 12 Sep 5, 2023 SYSTEM \$8,565.96 SYSTEM SYSTEM SR,565.96 SR,565.96 SYSTEM SR,565.96 SR,565.96				Material - To	tal				\$0.00			
Estimate Item Adjustment (0023) due to user terrej1 overridding Payment Estimate Exception 20 on the current Payment Estimate. 12 Sep 5, 2023 13 Sep 18, 293 SYSTEM \$8,565.96 14 Sep 18, 2023 15 Sep 18, 2023 16 Sep 18, 2023 17 Sep 18, 293 SYSTEM \$8,565.96 18 Sep 18, 2023 19 Sep 18, 2023 10 Cot 2, 2023 11 Oct 2, 2023 12 SySTEM \$8,565.96 13 Sep 18, 2023 14 Sep 18, 2023 15 Oct 16, SySTEM \$8,565.96 16 Sep 18, 2023 17 Sep 18, 2023 18 Sep 18, 2023 18 Sep 18, 2023 19 Sep 18, 2023 10 Sep 18, 2023 11 Sep 18, 2023 12 SySTEM \$8,565.96 13 Sep 18, 2023 14 Sep 18, 2023 15 SySTEM \$8,565.96 16 Sep 18, 2023 17 Sep 18, 2023 18 Sep 18, 2023 19 Sep 18, 2023 10 Sep 18, 2023 10 Sep 18, 2023 11 Sep 18, 2023 12 SySTEM \$8,565.96 13 Sep 18, 2023 14 Sep 18, 2023 15 SySTEM \$8,565.96 16 SySTEM \$8,565.96 17 Sep 18, 2023 18 SySTEM \$8,565.96 18 SySTEM \$8,565.96 19 SySTEM \$8,565.96 10 SySTEM \$8,565.96		1730 -	Total						\$0.00			
13 Sep 18, 2023 SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user wilsor2 overridding Payment Estimate Exception 21 on the current Payment Estimate. 13 Sep 18, 2023 SYSTEM (\$8,565.96) 14 Oct 2, 2023 SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user wilsor2 overridding Payment Estimate Exception 24 on the current Payment Estimate. 14 Oct 2, 2023 SYSTEM (\$8,565.96) 15 Oct 16, 2023 SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate Exception 24 on the current Payment Estimate. 15 Oct 16, SYSTEM (\$8,565.96)		1740	FORM LINERS	Material		12		SYSTEM	\$8,565.96	Estimate Item Adjustment (0023) due to user terrej1 overridding Payment		
Estimate Item Adjustment (0026) due to user wilsor2 overridding Payment Estimate Exception 21 on the current Payment Estimate. 13 Sep 18, 2023 14 Oct 2, 2023 SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user wilsor2 overridding Payment Estimate Exception 24 on the current Payment Estimate. 14 Oct 2, 2023 SYSTEM (\$8,565.96) 15 Oct 16, 2023 SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate Exception 24 on the current Payment Estimate. 15 Oct 16, SYSTEM (\$8,565.96)						12		SYSTEM	(\$8,565.96)			
2023 14 Oct 2, 2023 SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user wilsor2 overridding Payment Estimate Exception 24 on the current Payment Estimate. 14 Oct 2, 2023 SYSTEM (\$8,565.96) 15 Oct 16, 2023 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user wilsor2 overridding Payment Estimate Item Adjustment (0027) due to user wilsor2 overridding Payment Estimate Exception 22 on the current Payment Estimate. 15 Oct 16, SYSTEM (\$8,565.96)						13		SYSTEM	\$8,565.96	Estimate Item Adjustment (0026) due to user wilsor2 overridding Payment		
2023 Estimate Item Adjustment (0029) due to user wilsor2 overridding Payment Estimate Exception 24 on the current Payment Estimate. 14 Oct 2, 2023 15 Oct 16, 2023 SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user wilsor2 overridding Payment Estimate Exception 22 on the current Payment Estimate. 15 Oct 16, SYSTEM (\$8,565.96)						13		SYSTEM	(\$8,565.96)			
2023 15 Oct 16, 2023 SYSTEM \$8,565.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user wilsor2 overridding Payment Estimate Exception 22 on the current Payment Estimate. 15 Oct 16, SYSTEM (\$8,565.96)						14		SYSTEM	\$8,565.96	Estimate Item Adjustment (0029) due to user wilsor2 overridding Payment		
Estimate Item Adjustment (0027) due to user wilsor2 overridding Payment Estimate Exception 22 on the current Payment Estimate. 15 Oct 16, SYSTEM (\$8,565.96)						14		SYSTEM	(\$8,565.96)			
					15		SYSTEM	\$8,565.96	Estimate Item Adjustment (0027) due to user wilsor2 overridding Payment			
						15	Oct 16, 2023	SYSTEM	(\$8,565.96)			



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
450	1740	FORM LINERS	Material		16	Nov 1, 2023	SYSTEM	\$8,565.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user terrej1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					16	Nov 1, 2023	SYSTEM	(\$8,565.96)	
					17	Nov 16, 2023	SYSTEM	\$8,565.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user terrej1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					17	Nov 16, 2023	SYSTEM	(\$8,565.96)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	1740 -	Total						\$0.00	
	1760	REINFORCING STEEL (BRIDGES)			7	Jun 16, 2023	SYSTEM	(\$10,183.32)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$10,183.32)	
			Construction	Stockpile - 1	Total .			(\$10,183.32)	
			Construction Stockpile STMI		6	Jun 2, 2023	SYSTEM	\$10,183.32	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$10,183.32	
			Construction	Stockpile S	ΓΜΙ - Total			\$10,183.32	
	1760 -	Total						\$0.00	
	1780	FAB. SIGN SUPPORT BRACKETS	Construction Stockpile STMI		9	Jul 17, 2023	SYSTEM	\$4,950.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		DIVACILLIO	OTIVII	- Total				\$4,950.00	
			Construction	Stockpile S	ГМI - Total			\$4,950.00	
	1780 -	Total						\$4,950.00	
	1790	VERTICAL DRAIN AT END BENTS	Material		12	Sep 5, 2023	SYSTEM	\$7,226.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user terrej1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					12	Sep 5, 2023	SYSTEM	(\$7,226.54)	
					13	Sep 18, 2023	SYSTEM	\$7,226.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user wilsor2 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					13				Estimate Exception 22 on the current rayment Estimate.
					13	Sep 18, 2023	SYSTEM	(\$7,226.54)	Estimate Exception 22 on the current rayment Estimate.
					14		SYSTEM	(\$7,226.54) \$7,226.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user wilsor2 overridding Payment Estimate Exception 25 on the current Payment Estimate.
						2023 Oct 2,			This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user wilsor2 overridding Payment
					14	2023 Oct 2, 2023 Oct 2,	SYSTEM	\$7,226.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user wilsor2 overridding Payment
					14	2023 Oct 2, 2023 Oct 2, 2023 Oct 16,	SYSTEM SYSTEM	\$7,226.54 (\$7,226.54)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user wilsor2 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user wilsor2 overridding Payment
					14 14 15	2023 Oct 2, 2023 Oct 2, 2023 Oct 16, 2023	SYSTEM SYSTEM	\$7,226.54 (\$7,226.54) \$7,226.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user wilsor2 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user wilsor2 overridding Payment
					14 14 15	2023 Oct 2, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$7,226.54 (\$7,226.54) \$7,226.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user wilsor2 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user wilsor2 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user terrej1 overridding Payment
					14 14 15 15	2023 Oct 2, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 1, 2023 Nov 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,226.54 (\$7,226.54) \$7,226.54 (\$7,226.54)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user wilsor2 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user wilsor2 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user terrej1 overridding Payment
					14 14 15 15 16 16	2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 1, 2023 Nov 1, 2023 Nov 1, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,226.54 (\$7,226.54) \$7,226.54 (\$7,226.54) \$7,226.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user wilsor2 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user wilsor2 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user terrej1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user terrej1 overridding Payment Estimate Item Adjustment (0068) due to user terrej1 overridding Payment
				- Total	14 14 15 15 16 16 17	2023 Oct 2, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 1, 2023 Nov 1, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,226.54 (\$7,226.54) \$7,226.54 (\$7,226.54) \$7,226.54 (\$7,226.54)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user wilsor2 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user wilsor2 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user terrej1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user terrej1 overridding Payment Estimate Item Adjustment (0068) due to user terrej1 overridding Payment
			Material - Tot		14 14 15 15 16 16 17	2023 Oct 2, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 1, 2023 Nov 1, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,226.54 (\$7,226.54) \$7,226.54 (\$7,226.54) \$7,226.54 (\$7,226.54)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user wilsor2 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user wilsor2 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user terrej1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user terrej1 overridding Payment Estimate Item Adjustment (0068) due to user terrej1 overridding Payment
	1790 -	Total	Material - Tot		14 14 15 15 16 16 17	2023 Oct 2, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 1, 2023 Nov 1, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,226.54 (\$7,226.54) \$7,226.54 (\$7,226.54) \$7,226.54 (\$7,226.54) \$7,226.54 (\$7,226.54)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user wilsor2 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user wilsor2 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user terrej1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user terrej1 overridding Payment Estimate Item Adjustment (0068) due to user terrej1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J4I3450	1800	PLAIN NEOPRENE BEARING PAD	Construction Stockpile	- Total				(\$1,260.00)																
			Construction	Stockpile - 1	Total			(\$1,260.00)																
			Construction Stockpile		7	Jun 16, 2023	SYSTEM	\$1,260.00	Payment Estimate Item Adjustment generated Stockpile Transaction															
			STMI	- Total				\$1,260.00																
			Construction	Stockpile S	ГМI - Total			\$1,260.00																
			Material		10	Aug 2, 2023	SYSTEM	\$3,830.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user terrej1 overridding Payment Estimate Exception 15 on the current Payment Estimate.															
					10	Aug 2, 2023	SYSTEM	(\$3,830.26)																
					11	Aug 15, 2023	SYSTEM	\$3,830.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user wilsor2 overridding Payment Estimate Exception 17 on the current Payment Estimate.															
					11	Aug 15, 2023	SYSTEM	(\$3,830.26)																
					12	Sep 5, 2023	SYSTEM	\$3,830.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user terrej1 overridding Payment Estimate Exception 22 on the current Payment Estimate.															
				12	Sep 5, 2023	SYSTEM	(\$3,830.26)																	
					13	Sep 18, 2023	SYSTEM	\$3,830.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user wilsor2 overridding Payment Estimate Exception 23 on the current Payment Estimate.															
								13	Sep 18, 2023	SYSTEM	(\$3,830.26)													
						14	Oct 2, 2023	SYSTEM	\$3,830.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user wilsor2 overridding Payment Estimate Exception 26 on the current Payment Estimate.														
								14	Oct 2, 2023	SYSTEM	(\$3,830.26)													
					15	Oct 16, 2023	SYSTEM	\$3,830.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user wilsor2 overridding Payment Estimate Exception 24 on the current Payment Estimate.															
					15	Oct 16, 2023	SYSTEM	(\$3,830.26)																
					16	Nov 1, 2023	SYSTEM	\$3,830.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user terrej1 overridding Payment Estimate Exception 28 on the current Payment Estimate.															
					16	Nov 1, 2023	SYSTEM	(\$3,830.26)																
				- Total				\$0.00																
			Material - Tot	tal				\$0.00																
		Total						\$0.00																
	1810	LAMINATED NEOPRENE BEARING PAD	Construction Stockpile		10	Aug 2, 2023	SYSTEM	(\$1,680.00)	Payment Estimate Item Adjustment generated Stockpile Transaction															
				- Total				(\$1,680.00)																
			Construction	Stockpile - 1		Inc. 45	OVCTT:	(\$1,680.00)	Demonstration to the Adjust and A															
			Construction Stockpile STMI	Total	7	Jun 16, 2023	SYSTEM	\$1,680.00	Payment Estimate Item Adjustment generated Stockpile Transaction															
			Construction	- Total	IMI Total			\$1,680.00																
				-otockpile S	10 10		SYSTEM	\$1,680.00 \$3,387.02	This adjustment offsets the original system-generated Material Payment															
				Material	Material					vlaterial	ateriai		teriai		епаі	//aterial					Aug 2, 2023			Estimate Item Adjustment (0025) due to user terrej1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					10	Aug 2, 2023	SYSTEM	(\$3,387.02)																
					11	11	Aug 15, 2023	SYSTEM	\$3,387.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user wilsor2 overridding Payment Estimate Exception 18 on the current Payment Estimate.														
							1	11	Aug 15, 2023	SYSTEM	(\$3,387.02)													
					12	Sep 5,	SYSTEM	\$3,387.02	This adjustment offsets the original system-generated Material Payment															



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3450	1810	LAMINATED NEOPRENE	Material			2023			Estimate Item Adjustment (0026) due to user terrej1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
		BEARING PAD			12	Sep 5, 2023	SYSTEM	(\$3,387.02)	
					13	Sep 18, 2023	SYSTEM	\$3,387.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user wilsor2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					13	Sep 18, 2023	SYSTEM	(\$3,387.02)	
					14	Oct 2, 2023	SYSTEM	\$3,387.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user wilsor2 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					14	Oct 2, 2023	SYSTEM	(\$3,387.02)	
					15	Oct 16, 2023	SYSTEM	\$3,387.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user wilsor2 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					15	Oct 16, 2023	SYSTEM	(\$3,387.02)	
					16	Nov 1, 2023	SYSTEM	\$3,387.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user terrej1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					16	Nov 1, 2023	SYSTEM	(\$3,387.02)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1810 -	Total						\$0.00	
	1820	PIPE PILE SPACERS	Construction Stockpile		8	Jun 30, 2023	SYSTEM	(\$2,220.40)	Payment Estimate Item Adjustment generated Stockpile Transaction
					10	Aug 2, 2023	SYSTEM	(\$2,537.60)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$4,758.00)	
			Construction	Stockpile - 1	Γotal			(\$4,758.00)	
			Construction Stockpile		6	Jun 2, 2023	SYSTEM	\$4,758.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$4,758.00	
			Construction	Stockpile S	TMI - Tota			\$4,758.00	
	1820 -	Total						\$0.00	
	1850	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		17	Nov 16, 2023	SYSTEM	\$64,363.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user terrej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					17	Nov 16, 2023	SYSTEM	(\$64,363.87)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1850 -	Total						\$0.00	
	1870	DRILLED SHAFTS (5 FT. 0 IN. DIA.)	Construction Stockpile		15	Oct 16, 2023	SYSTEM	(\$2,709.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$2,709.00)	
			Construction	Stockpile - 1	Γotal			(\$2,709.00)	
			Construction Stockpile		6	Jun 2, 2023	SYSTEM	\$2,709.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$2,709.00	
			Construction	Stockpile S	TMI - Tota			\$2,709.00	
			Material		15	Oct 16, 2023	SYSTEM	\$23,142.61	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					15	Oct 16, 2023	SYSTEM	(\$23,142.61)	
					16	Nov 1, 2023	SYSTEM	\$23,142.61	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user terrej1 overridding Payment Estimate Exception 19 on the current Payment Estimate.



	ine	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0 18	870	DRILLED SHAFTS (5 FT. 0 IN. DIA.)	Material		16	Nov 1, 2023	SYSTEM	(\$23,142.61)	
					17	Nov 16, 2023	SYSTEM	\$23,142.61	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0070) due to user terrej1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					17	Nov 16, 2023	SYSTEM	(\$23,142.61)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	15	Oct 16, 2023	SYSTEM	(\$51.31)	
				Overrun - T	otal			(\$51.31)	
			Overrun - To	tal				(\$51.31)	
18	870 -	Total						(\$51.31)	
19	920	GALVANIZED STRUCTURAL STEEL PILES (12	Material		14	Oct 2, 2023	SYSTEM	\$22,739.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user wilsor2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
		IN			14	Oct 2, 2023	SYSTEM	(\$22,739.36)	
					15	Oct 16, 2023	SYSTEM	\$22,739.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user wilsor2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					15	Oct 16, 2023	SYSTEM	(\$22,739.36)	
					16	Nov 1, 2023	SYSTEM	\$48,221.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user terrej1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					16	Nov 1, 2023	SYSTEM	(\$48,221.60)	
					17	Nov 16, 2023	SYSTEM	\$48,221.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0071) due to user terrej1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					17	Nov 16, 2023	SYSTEM	(\$48,221.60)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
19	920 -	Total							
_		Total						\$0.00	
19	940	PILE POINT REINFORCEMENT	Material		16	Nov 1, 2023	SYSTEM	\$0.00 \$1,662.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user terrej1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
15		PILE POINT	Material		16		SYSTEM		Estimate Item Adjustment (0033) due to user terrej1 overridding Payment
15		PILE POINT	Material			2023 Nov 1,		\$1,662.15	Estimate Item Adjustment (0033) due to user terrej1 overridding Payment
15		PILE POINT	Material		16	2023 Nov 1, 2023 Nov 16,	SYSTEM	\$1,662.15 (\$1,662.15)	Estimate Item Adjustment (0033) due to user terrej1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user terrej1 overridding Payment
15		PILE POINT	Material	- Total	16	Nov 1, 2023 Nov 16, 2023 Nov 16,	SYSTEM	\$1,662.15 (\$1,662.15) \$1,662.15	Estimate Item Adjustment (0033) due to user terrej1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user terrej1 overridding Payment
15		PILE POINT	Material Material - To		16	Nov 1, 2023 Nov 16, 2023 Nov 16,	SYSTEM	\$1,662.15 (\$1,662.15) \$1,662.15 (\$1,662.15)	Estimate Item Adjustment (0033) due to user terrej1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user terrej1 overridding Payment
	940	PILE POINT			16	Nov 1, 2023 Nov 16, 2023 Nov 16,	SYSTEM	\$1,662.15 (\$1,662.15) \$1,662.15 (\$1,662.15)	Estimate Item Adjustment (0033) due to user terrej1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user terrej1 overridding Payment
15	940	PILE POINT REINFORCEMENT			16	Nov 1, 2023 Nov 16, 2023 Nov 16,	SYSTEM	\$1,662.15 (\$1,662.15) \$1,662.15 (\$1,662.15) \$0.00	Estimate Item Adjustment (0033) due to user terrej1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user terrej1 overridding Payment
15	940 -	PILE POINT REINFORCEMENT Total CLASS B CONCRETE	Material - To		16 17 17	2023 Nov 1, 2023 Nov 16, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM	\$1,662.15 (\$1,662.15) \$1,662.15 (\$1,662.15) \$0.00 \$0.00	Estimate Item Adjustment (0033) due to user terrej1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user terrej1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user terrej1 overridding Payment
15	940 -	PILE POINT REINFORCEMENT Total CLASS B CONCRETE	Material - To		16 17 17	2023 Nov 1, 2023 Nov 16, 2023 Nov 16, 2023 Nov 1, 2023	SYSTEM SYSTEM SYSTEM	\$1,662.15 (\$1,662.15) \$1,662.15 (\$1,662.15) \$0.00 \$0.00 \$122,018.49	Estimate Item Adjustment (0033) due to user terrej1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user terrej1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user terrej1 overridding Payment
15	940 -	PILE POINT REINFORCEMENT Total CLASS B CONCRETE	Material - To		16 17 17 16	2023 Nov 1, 2023 Nov 16, 2023 Nov 16, 2023 Nov 1, 2023 Nov 1, 2023 Nov 1, 2023	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,662.15 (\$1,662.15) \$1,662.15 (\$1,662.15) \$0.00 \$0.00 \$122,018.49	Estimate Item Adjustment (0033) due to user terrej1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user terrej1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user terrej1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0073) due to user terrej1 overridding Payment Estimate Item Adjustment (0073) due to user terrej1 overridding Payment
15	940 -	PILE POINT REINFORCEMENT Total CLASS B CONCRETE	Material - To		16 17 17 16 16 16	2023 Nov 1, 2023 Nov 16, 2023 Nov 16, 2023 Nov 1, 2023 Nov 1, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,662.15 (\$1,662.15) \$1,662.15 (\$1,662.15) \$0.00 \$0.00 \$1.22,018.49 (\$122,018.49) \$122,018.49	Estimate Item Adjustment (0033) due to user terrej1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user terrej1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user terrej1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0073) due to user terrej1 overridding Payment Estimate Item Adjustment (0073) due to user terrej1 overridding Payment
15	940 -	PILE POINT REINFORCEMENT Total CLASS B CONCRETE	Material - To	tal - Total	16 17 17 16 16 16	2023 Nov 1, 2023 Nov 16, 2023 Nov 16, 2023 Nov 1, 2023 Nov 1, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,662.15 (\$1,662.15) \$1,662.15 (\$1,662.15) \$0.00 \$0.00 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000	Estimate Item Adjustment (0033) due to user terrej1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user terrej1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user terrej1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0073) due to user terrej1 overridding Payment Estimate Item Adjustment (0073) due to user terrej1 overridding Payment



t Lir	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0 19	70 SLAB ON CONCRETE BEAM	Construction Stockpile		16	Nov 1, 2023	SYSTEM	(\$17,452.98)	Payment Estimate Item Adjustment generated Stockpile Transaction
				17	Nov 16, 2023	SYSTEM	(\$65,473.22)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				(\$82,926.20)	
		Construction	Stockpile - 1	Γotal			(\$82,926.20)	
		Construction Stockpile STMI		10	Aug 2, 2023	SYSTEM	\$40,800.60	Payment Estimate Item Adjustment generated Stockpile Transaction
		STIMI		11	Aug 15, 2023	SYSTEM	\$46,464.30	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$87,264.90	
		Construction	Stockpile S	ΓMI - Total			\$87,264.90	
		Material		16	Nov 1, 2023	SYSTEM	\$50,498.06	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user terrej1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				16	Nov 1, 2023	SYSTEM	(\$50,498.06)	
				17	Nov 16, 2023	SYSTEM	\$239,936.83	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0074) due to user terrej1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				17	Nov 16, 2023	SYSTEM	(\$239,936.83)	
			- Total				\$0.00	
		Material - Tot	tal				\$0.00	
19	0 - Total						\$4,338.70	
199	PRESTRESSED CONC SPREAD	Construction Stockpile		16	Nov 1, 2023	SYSTEM	(\$316,890.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
	BOX BM		- Total onstruction Stockpile - Total				(\$316,890.50)	
			Stockpile - 1				(\$316,890.50)	
		Construction Stockpile STMI		11	Aug 15, 2023	SYSTEM	\$316,890.50	Payment Estimate Item Adjustment generated Stockpile Transaction
		0 1 11	- Total				\$316,890.50	
40	00 - Total	Construction	Stockpile S	I WII - I Otal			\$316,890.50	
20		Construction Stockpile		16	Nov 1, 2023	SYSTEM	\$0.00 (\$9,508.80)	Payment Estimate Item Adjustment generated Stockpile Transaction
	,		- Total				(\$9,508.80)	
		Construction	Stockpile - 1	Γotal			(\$9,508.80)	
		Construction Stockpile STMI		6	Jun 2, 2023	SYSTEM	\$9,508.80	Payment Estimate Item Adjustment generated Stockpile Transaction
		STIVII	- Total				\$9,508.80	
		Construction	Stockpile S	TMI - Total			\$9,508.80	
20	00 - Total						\$0.00	
20	REINFORCING STEEL (EPOXY COATED)	Construction Stockpile		17	Nov 16, 2023	SYSTEM	(\$41,846.40)	Payment Estimate Item Adjustment generated Stockpile Transaction
	,		- Total				(\$41,846.40)	
		Construction	Stockpile - 1			0) (0===	(\$41,846.40)	
		Construction Stockpile STMI	- Total	10	Aug 2, 2023	SYSTEM	\$41,846.40 \$41,846.40	Payment Estimate Item Adjustment generated Stockpile Transaction
		Construction		TMI - Total			\$41,846.40	
20	I0 - Total	Jonathuction		Total			\$0.00	
20	PAB. SIGN SUPPORT	Stockpile		9	Jul 17, 2023	SYSTEM	\$3,275.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	BRACKETS	STMI	- Total				\$3,275.00	
		Construction	Stockpile S	TMI - Total			\$3,275.00	
20	20 - Total						\$3,275.00	
20:		Material		17	Nov 16,	SYSTEM	\$7,226.54	This adjustment offsets the original system-generated Material Payment
					- '			. , , ,



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3450	2030	AT END BENTS	Material			2023			Estimate Item Adjustment (0075) due to user terrej1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					17	Nov 16, 2023	SYSTEM	(\$7,226.54)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	2030 -	Total						\$0.00	
	2040	PLAIN NEOPRENE BEARING PAD	Construction Stockpile		16	Nov 1, 2023	SYSTEM	(\$1,260.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$1,260.00)	
			Construction	Stockpile - 1	otal			(\$1,260.00)	
			Construction Stockpile STMI		7	Jun 16, 2023	SYSTEM	\$1,260.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,260.00	
			Construction	Stockpile S	MI - Total			\$1,260.00	
			Material		16	Nov 1, 2023	SYSTEM	\$3,830.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user terrej1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					16	Nov 1, 2023	SYSTEM	(\$3,830.26)	
				- Total				\$0.00	
			Material - To	al				\$0.00	
	2040 -	Total						\$0.00	
	2050	LAMINATED NEOPRENE BEARING PAD	Construction Stockpile		17	Nov 16, 2023	SYSTEM	(\$1,680.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$1,680.00)	
			Construction	Stockpile - 1	otal			(\$1,680.00)	
			Construction Stockpile STMI		7	Jun 16, 2023	SYSTEM	\$1,680.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,680.00	
			Construction	Stockpile S	MI - Total			\$1,680.00	
J	2050 -	Total						\$0.00	
	2060	PIPE PILE SPACERS	Construction Stockpile		16	Nov 1, 2023	SYSTEM	(\$4,758.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$4,758.00)	
			Construction	Stockpile - 1	otal			(\$4,758.00)	
			Construction Stockpile STMI		6	Jun 2, 2023	SYSTEM	\$4,758.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$4,758.00	
			Construction	Stockpile S	IVII - Total			\$4,758.00	
	2060 -							\$0.00	
	2080	CONCRETE AND MASONRY PROTECTION	Material		17	Nov 16, 2023	SYSTEM	\$5,382.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0076) due to user terrej1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
		SYSTEM			17	Nov 16, 2023	SYSTEM	(\$5,382.15)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	2080 -	Total						\$0.00	
	2100	MECHANICALLY STABILIZED EARTH WALL SYS	Construction Stockpile		9	Jul 17, 2023	SYSTEM	(\$31,838.15)	Payment Estimate Item Adjustment generated Stockpile Transaction
					11	Aug 15, 2023	SYSTEM	(\$48,693.64)	Payment Estimate Item Adjustment generated Stockpile Transaction
					15	Oct 16, 2023	SYSTEM	(\$22,286.70)	Payment Estimate Item Adjustment generated Stockpile Transaction
					16	Nov 1, 2023	STOLEM	(\$54,686.71)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$157,505.20)	



Stockpile 2023	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user terrej1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
Construction Stockpile STMI 6 Jun 2, 2023 SYSTEM \$157,505.20 Part	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user terrej1 overridding Payment
Total \$157,505.20	Estimate Item Adjustment (0050) due to user terrej1 overridding Payment
Material 9 Jul 17, 2023 SYSTEM \$97,520.50 THE ENTRY SYSTEM \$97,520.50 THE ENTRY SYSTEM (\$97,520.50)	Estimate Item Adjustment (0050) due to user terrej1 overridding Payment
9 Jul 17, 2023 (\$97,520.50)	Estimate Item Adjustment (0050) due to user terrej1 overridding Payment
2023	
10 Aug 2 SYSTEM \$97 520 50 Th	
2023	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user terrej1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
10 Aug 2, 2023 SYSTEM (\$97,520.50)	
2023	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user wilsor2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
11 Aug 15, 2023 SYSTEM (\$246,669.50)	
2023	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user terrej1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
12 Sep 5, 2023 SYSTEM (\$246,669.50)	
2023 Es	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user wilsor2 overridding Payment Estimate Exception 25 on the current Payment Estimate.
13 Sep 18, SYSTEM (\$246,669.50) 2023	
2023 Es	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user wilsor2 overridding Payment Estimate Exception 28 on the current Payment Estimate.
14 Oct 2, 2023 SYSTEM (\$246,669.50)	
2023 Es	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user wilsor2 overridding Payment Estimate Exception 26 on the current Payment Estimate.
15 Oct 16, SYSTEM (\$314,933.85) 2023	
2023 Es	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user terrej1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
16 Nov 1, SYSTEM (\$482,439.65)	
2023	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0077) due to user terrej1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
17 Nov 16, SYSTEM (\$482,439.65)	
-Total \$0.00	
Material - Total \$0.00	
2100 - Total \$0.00	This adjustment offsets the original system-generated Material Payment
2120 CONCRETE AND Material 17 Nov 16, SYSTEM \$6,120.87 THE SYSTEM	
2120 CONCRETE AND Material 17 Nov 16, SYSTEM \$6,120.87 THE T	Estimate Item Adjustment (0078) due to user terrej1 overridding Payment
2120 CONCRETE AND Material 17 Nov 16, SYSTEM \$6,120.87 THE Ex Concrete AND MASONRY PROTECTION SYSTEM 17 Nov 16, SYSTEM \$6,120.87 THE Ex Concrete AND SYSTEM \$6,120.87 THE Ex Concrete AND Material 17 Nov 16, SYSTEM \$6,120.87 THE SYSTEM \$6,120.87 THE	Estimate Item Adjustment (0078) due to user terrej1 overridding Payment
2120 CONCRETE AND MASONRY PROTECTION SYSTEM Material 17 Nov 16, 2023 SYSTEM \$6,120.87 THE ENTIRE SYSTEM 17 Nov 16, 2023 SYSTEM \$6,120.87 THE ENTIRE SYSTEM \$6,120.	Estimate Item Adjustment (0078) due to user terrej1 overridding Payment
2120 CONCRETE AND MASONRY PROTECTION SYSTEM S6,120.87 THE EST SYSTEM S6,120.87 THE EST SYSTEM S6,120.87 THE SYSTEM SYSTEM S6,120.87 THE SYSTEM SYSTEM SO,000 SYSTEM SYSTEM SO,000 SYSTEM SYSTEM SYSTEM SO,000 SYSTEM	Estimate Item Adjustment (0078) due to user terrej1 overridding Payment
2120 CONCRETE AND MASONRY PROTECTION SYSTEM Material 17 Nov 16, 2023 SYSTEM \$6,120.87 The Expression of	Estimate Item Adjustment (0078) due to user terrej1 overridding Payment



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks			
			Туре	Adjustment Type	Number	Date	Ву					
J413450	2140	MECHANICALLY STABILIZED EARTH WALL SYS	Stockpile		15	Oct 16, 2023	SYSTEM	(\$75,692.68)	Payment Estimate Item Adjustment generated Stockpile Transaction			
					16	Nov 1, 2023	SYSTEM	(\$9,659.47)	Payment Estimate Item Adjustment generated Stockpile Transaction			
				- Total				(\$145,812.00)				
				Stockpile - Total				(\$145,812.00)				
			Construction Stockpile STMI		6	Jun 2, 2023	SYSTEM	\$145,812.00	Payment Estimate Item Adjustment generated Stockpile Transaction			
				- Total				\$145,812.00				
				Stockpile STMI - Total				\$145,812.00				
			Material		8	Jun 30, 2023	SYSTEM	\$137,459.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user terrej1 overridding Payment Estimate Exception 27 on the current Payment Estimate.			
					8	Jun 30, 2023	SYSTEM	(\$137,459.88)				
					9	Jul 17, 2023	SYSTEM	\$179,780.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user terrej1 overridding Payment Estimate Exception 36 on the current Payment Estimate.			
					9	Jul 17, 2023	SYSTEM	(\$179,780.65)				
					10	Aug 2, 2023	SYSTEM	\$179,780.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user terrej1 overridding Payment Estimate Exception 24 on the current Payment Estimate.			
					10	Aug 2, 2023	SYSTEM	(\$179,780.65)				
					11	Aug 15, 2023	SYSTEM	\$179,780.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user wilsor2 overridding Payment Estimate Exception 26 on the current Payment Estimate.			
					11	Aug 15, 2023	SYSTEM	(\$179,780.65)				
					12	Sep 5, 2023	SYSTEM	\$179,780.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user terrej1 overridding Payment Estimate Exception 31 on the current Payment Estimate.			
					12	Sep 5, 2023	SYSTEM	(\$179,780.65)				
					13	Sep 18, 2023	SYSTEM	\$179,780.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user wilsor2 overridding Payment Estimate Exception 32 on the current Payment Estimate.			
					13	Sep 18, 2023	SYSTEM	(\$179,780.65)				
					14	Oct 2, 2023	SYSTEM	\$179,780.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user wilsor2 overridding Payment Estimate Exception 35 on the current Payment Estimate.			
					14	Oct 2, 2023	SYSTEM	(\$179,780.65)				
					15	Oct 16, 2023	SYSTEM	\$404,856.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user wilsor2 overridding Payment Estimate Exception 33 on the current Payment Estimate.			
					15	Oct 16, 2023	SYSTEM	(\$404,856.96)				
								16	Nov 1, 2023	SYSTEM	\$433,579.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user terrej1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					16	Nov 1, 2023	SYSTEM	(\$433,579.92)				
					17	Nov 16, 2023	SYSTEM	\$433,579.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0079) due to user terrej1 overridding Payment Estimate Exception 39 on the current Payment Estimate.			
					17	Nov 16, 2023	SYSTEM	(\$433,579.92)				
	2140 -	- Total	Material - Tot	- Total				\$0.00				
				tal				\$0.00				
								\$0.00				
	5001	4 IN TEMPORARY PAVEMENT	Material		2	Apr 3, 2023	SYSTEM	\$14,833.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3450	5001	MARKING PAINT	Material						Estimate Exception 6 on the current Payment Estimate.
					2	Apr 3, 2023	SYSTEM	(\$14,833.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	5	May 16, 2023	SYSTEM	(\$10,681.05)	
					15	Oct 16, 2023	SYSTEM	(\$28,247.20)	
				Overrun - Total				(\$38,928.25)	
			Overrun - Total					(\$38,928.25)	
	5001 -							(\$38,928.25)	
	5007	MISC.	Material		14	Oct 2, 2023	SYSTEM	\$47,842.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user wilsor2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					14	Oct 2, 2023	SYSTEM	(\$47,842.41)	
					15	Oct 16, 2023	SYSTEM	\$47,842.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user wilsor2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					15	Oct 16, 2023	SYSTEM	(\$47,842.41)	
					16	Nov 1, 2023	SYSTEM	\$47,842.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user terrej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					16	Nov 1, 2023	SYSTEM	(\$47,842.41)	
					17	Nov 16, 2023	SYSTEM	\$47,842.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user terrej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					17	Nov 16, 2023	SYSTEM	(\$47,842.41)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	5007 -	Total						\$0.00	
	5008	MISC.	Material		14	Oct 2, 2023	SYSTEM	\$3,327.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user wilsor2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					14	Oct 2, 2023	SYSTEM	(\$3,327.17)	
					15	Oct 16, 2023	SYSTEM	\$3,327.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user wilsor2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					15	Oct 16, 2023	SYSTEM	(\$3,327.17)	
					16	Nov 1, 2023	SYSTEM	\$3,327.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user terrej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					16	Nov 1, 2023	SYSTEM	(\$3,327.17)	
					17	Nov 16, 2023	SYSTEM	\$3,327.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user terrej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					17	Nov 16, 2023	SYSTEM	(\$3,327.17)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5008 -	Total						\$0.00	
J4I3450 -	Total							\$98,073.38	
Overall -	Total							\$98,073.38	

MoDOT

Contract Adjustments for Contract - 230120-C07

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 52 of 52