

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 3, 2023

Progress Estimate Number	Contract ID	230120-D01	Pay Period Start	October 16, 2023	Original Contract Amount	\$2,503,702.96
4	Prime Contractor	Olympus Painting Contractors, Inc.	Pay Period End	2023	Net Change Order Amount Current Contract Amount	(\$8,842.00) \$2,494,860.96

Approval Date		By User
November 3, 2023	Generated and Approved (and should be considered Draft) at the Project Office Level by	shankb1
November 3, 2023	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	gabelj3
November 3, 2023	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2023	December 1, 2023		25.92%

	Contract Informational Dates										
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract								
Acceptance Date											
Awarded Date	February 8, 2023	February 8, 2023									
Letting Date	January 20, 2023	January 20, 2023									
Notice to Proceed Date	March 13, 2023	March 13, 2023									
Open to Traffic Date											
Work Began Date											

Contract Total Pay For Estimate No. 4										
		This Estimate	Previous	To Date						
230120-D01										
	Total Posted Items Pay	\$361,072.45	\$285,554.80	\$646,627.25						
	Gross Item Adjustments	(\$30,980.93)	\$79,276.60	\$48,295.67						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
	·		\$364,831.40	\$694,922.92						
Contract Total P	ayable This Estimate:	\$330.091.52								

## Items Paid This Estimate Period

Project Number	Line Number	Item Code	ode Item Description Unit Unit Price		Current Installed Qty	Current Installed Amount						
J5I3483	0140	6181000	MOBILIZATION	LS	\$225,000.000	0.25	\$56,250.00					
	5001	4019905	MISC.OPTIONAL PAVEMENT	SQYD	\$117.280	2,599.1	\$304,822.45					
Project J5I3483 -	Project J5I3483 - Total											
Overall - Total	verall - Total											

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5I3483	0030	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	Material			-1	\$3,600.00	(\$3,600.00)
	0030	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1	\$3,600.00	\$3,600.00
	0060	CONSTRUCTION SIGNS	Material			-464	\$15.00	(\$6,960.00)
	0060	CONSTRUCTION SIGNS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user shankb1 overridding Payment Estimate Exception 2 on	464	\$15.00	\$6,960.00

Revision 3/23/2023 Page 1 of 11



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 3, 2023

Progress Estimate Number
4 Contract ID 230120-D01 Pay Period Start October 16, 2023 Original Contract Amount \$2,503,702.96
Prime Contractor Inc. Pay Period End November 1, Pay Period End 2023 November 1, Pay Period End 2023 November 1, October 16, 2023 Original Contract Amount \$2,503,702.96
Prime Contractor Inc. Pay Period End 2023 Original Contract Amount \$2,494,860.96

ADVANCED WARNING RAIL   STEED   SAROUR   SAROU	Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
ADVANCED WARNING PAIL   SYSTEM	J5I3483					the current Payment Estimate.			
SYSTEM		0070		Material			-4	\$120.00	(\$480.00)
This adjustment offsets the original system: generated Material programs Estimate tem Adjustment (DO28) due to user shankbit overridding Payment Estimate tem Adjustment (DO21) due to user shankbit overridding Payment Estimate tem Adjustment (DO21) due to user shankbit overridding Payment Estimate tem Adjustment (DO21) due to user shankbit overridding Payment Estimate tem Adjustment (DO21) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO22) due to user shankbit overridding Payment Estimate tem Adjustment (DO		0070		Material		generated Material Payment Estimate Item Adjustment (0027) due to user shankb1 overridding Payment Estimate Exception 3 on	4	\$120.00	\$480.00
		0800	CHANNELIZER (TRIM LINE)	Material			-112	\$38.40	(\$4,300.80)
DARRICADE  DIRECTIONAL INDICATOR BARRICADE  OND DIRECTIONAL Material DIRECTIONAL INDICATOR BARRICADE  OND DIRECTIONAL Material DIRECTIONAL INDICATOR BARRICADE  OND DIRECTIONAL INDICATOR  OND D		0800	CHANNELIZER (TRIM LINE)	Material		generated Material Payment Estimate Item Adjustment (0028) due to user shankb1 overridding Payment Estimate Exception 4 on	112	\$38.40	\$4,300.80
BARRICADE   September   Sept		0090		Material			-28	\$90.00	(\$2,520.00)
This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate Exception 6 on the current Payment Estimate Exception 6 on the current Payment Estimate Item Adjustment (0024) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate Item Adjustment (0023) due to user shankb1 overridding Payment Estimate Item Adjustment (0023) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate Exception 8 on the current Payment Estimate Item Adjustment (0024) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Payment Payment Payment Payme		0090		Material		generated Material Payment Estimate Item Adjustment (0021) due to user shankb1 overridding Payment Estimate Exception 5 on	28	\$90.00	\$2,520.00
generated Material Payment Estimate Item Adjustment (0022) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  -1,084 \$75.00 \$81,300.00  REMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED  120 TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED  131 TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE  132 WHITE  133 WHITE  134 White  135 White White  136 White  137 White  137 White  138 White  138 White  138 White  139 White  140 White  150 White White White  150 White W		0100	FLASHING ARROW PANEL	Material			-2	\$2,000.00	(\$4,000.00)
BARRIER, CONTRACTOR FURNISHED / RETAINED  0120 TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED  0150 TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE  0150 TEMPORARY REMOVABLE Material Payment Estimate Item Adjustment (0024) due to user shankb1 overridding Payment Estimate Item Adjustment Estimate Estimate Estimate Estimate Estimate Temporal Payment Estimate Temporal Estimate Temporal Payment Pa		0100	FLASHING ARROW PANEL	Material		generated Material Payment Estimate Item Adjustment (0022) due to user shankb1 overridding Payment Estimate Exception 6 on	2	\$2,000.00	\$4,000.00
BARRIER, CONTRACTOR FURNISHED / RETAINED  BARRIER, CONTRACTOR FURNISHED / RETAINED  STEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE  O150 TEMPORARY REMOVABLE Material Payment Estimate Item Adjustment (0024) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate Exception 8 on the current Payment Estimate.  O150 MISC. Other Item Adjustment  O150 TEMPORARY REMOVABLE Material Payment Estimate Item Adjustment Estimate Exception 8 on the current Payment Estimate Item Adjustment  O150 TEMPORARY REMOVABLE Material Payment Estimate Item Adjustment Estimate Item Asphalt Cement Price Adjustment Developed Payment Estimate Item Adjustment Item Adjustment Item Adjustment Item Adjustment Office Item Adjustment Item Adjustment Item Adjustment Item Adjustment Item Adjustment Item Adjustment Office Item Adjustment Item Adjustment Office Item Adjustment Item Adjustment Office Item Adjustment Office Item Adjustment Item Adjustment Office Item Adjustment Item Adjustment Office Item Adjustment Office Item Adjustment Office Item Adjustment Item Adjustment Office Item Adjustment Office Item Adjustment Item Adjustment Office Item Adju		0120	BARRIER, CONTRACTOR	Material			-1,084	\$75.00	(\$81,300.00)
MARKING TAPE 4 IN., WHITE  0150 TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE  0150 TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE  0150 TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE  0150 MISC. Other Item Adjustment (0024) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  0150 MISC. Other Item Adjustment  0150 MISC. Other Item Adjust		0120	BARRIER, CONTRACTOR	Material		generated Material Payment Estimate Item Adjustment (0023) due to user shankb1 overridding Payment Estimate Exception 7 on	1,084	\$75.00	\$81,300.00
MARKING TAPE 4 IN., WHITE    Generated Material Payment Estimate Item Adjustment (0024) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.    5001		0150	MARKING TAPE 4 IN.,	Material			-1,400	\$2.40	(\$3,360.00)
Adjustment Factor = \$2475.42  5001 MISC. Other Item Adjustment Price Adjustment  5001 MISC. Other Item Adjustment  5001 MISC. Other Item Adjustment  Asphalt Cement Price Adjustment  Cement Price Adjustment  Asphalt Cement Price Adjustment  Substandard Item Adjustment Adjustment Cement Price Adjustment  Substandard Item Adjustment Corrects payment for this. See Spreadsheet.		0150	MARKING TAPE 4 IN.,	Material		generated Material Payment Estimate Item Adjustment (0024) due to user shankb1 overridding Payment Estimate Exception 8 on	1,400	\$2.40	\$3,360.00
Adjustment Cement Price Adjustment  5001 MISC. Other Item Adjustment Cement Price Adjustment  5001 MISC. Other Item Adjustment Price Adjustment  5001 MISC. Other Item Adjustment  5001 MISC. Other Item Adjustment Substandard Item Misc Shoulder Pavement was laid thinner in areas. This adjustment corrects payment for this. See Spreadsheet.		5001	MISC.		Fuel Price				\$2,475.42
Adjustment Cement Price Adjustment  5001 MISC. Other Item Adjustment Item Adjustment Item Substandard Item Misc Shoulder Pavement was laid thinner in areas. This adjustment corrects payment for this. See Spreadsheet. (\$34,190.09)		5001	MISC.		Cement Price	2409.1 SY 11.5 Thick 3.7% AC			\$704.74
Adjustment Item areas. This adjustment corrects payment for this. See Spreadsheet.		5001	MISC.		Cement Price	190.0 SY 6" Thick 3.7% AC			\$29.00
Total (\$30,980.93		5001	MISC.			areas. This adjustment corrects payment for			(\$34,190.09) ( <b>\$30,980.93</b> )

Revision 3/23/2023 Page 2 of 11



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information										
Project Number											
J5I3483	I 44-2(331)	4 Bridge rehabilitations	I-44	PULASKI	over Gasconade River, Roubidoux Creek, and Big Piney River						

#### 

Revision 3/23/2023 Page 3 of 11



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5I3483, Item 6122019, Project Item Line Number 0030, Material Set 612201996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3483, Item 6161005, Project Item Line Number 0060, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3483, Item 6161008, Project Item Line Number 0070, Material Set 616100896, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3483, Item 6161025, Project Item Line Number 0080, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3483, Item 6161033, Project Item Line Number 0090, Material Set 616103396, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3483, Item 6161040, Project Item Line Number 0100, Material Set 616104096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3483, Item 6173600D, Project Item Line Number 0120, Material Set 6173600D96, Material 0617TCRCTF - Type F Concrete Traffic Barrier, Acceptance Action Generic 0617TCRCTF is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3483, Item 6205301B, Project Item Line Number 0150, Material Set 6205301B96, Material 1048PMRPMTWH - Marking Tape Removable White, Acceptance Action Generic 1048PMRPMTWH is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Item Overrun: Contract 230120-D01, Contract Project J5l3483, Project Item Line Number 0080, Contract Line Item Number 0080, Item 6161025, Minor Item.	Pending Change Order	shankb1	Acknowledged

Revision 3/23/2023 Page 4 of 11



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					Report Generated date and can differ from the posted am							
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230120-D01	J5I3483	0001	0005	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$76,200.00	\$76,200.00
		0001	0010	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	4,421.00	-4,421.00	0.00	SQYD	0.00	\$26.28	\$0.00
		0001	0020	4019905	MISC.OPTIONAL PAVEMENT	4,421.00	-4,421.00	0.00	SQYD	0.00	\$93.00	\$0.00
		0001	0030	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	1.00	0.00	1.00	EA	1.00	\$3,600.00	\$3,600.00
		0001	0040	6122020	0 REPLACEMENT SAND BARREL	1.00	0.00	1.00	EA	0.00	\$600.00	\$0.00
		0001	0050	6122030	IMPACT ATTENUATOR (RELOCATION)	5.00	0.00	5.00	EA	0.00	\$3,000.00	\$0.00
		0001	0060	6161005	CONSTRUCTION SIGNS	472.00	0.00	472.00	SQFT	464.00	\$15.00	\$6,960.00
		0001	0070	6161008	ADVANCED WARNING RAIL SYSTEM	5.00	0.00	5.00	EA	4.00	\$120.00	\$480.00
		0001	0080	6161025	CHANNELIZER (TRIM LINE)	56.00	0.00	56.00	EA	112.00	\$38.40	\$4,300.80
		0001	0090	6161033	DIRECTIONAL INDICATOR BARRICADE	58.00	0.00	58.00	EA	28.00	\$90.00	\$2,520.00
		0001	0100	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.00
		0001	0110	6169901	MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	1.00	0.00	1.00	LS	0.60	\$77,640.00	\$46,584.00
		0001	0120	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED /	1,105.00	0.00	1,105.00	LF	1,084.00	\$75.00	\$81,300.00
		0001	0130	6175010A	RETAINED RELOCATING TEMPORARY TRAFFIC BARRIER	5,228.00	0.00	5,228.00	LF	0.00	\$35.00	\$0.00
		0001	0140	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$225,000.00	\$112,500.00
		0001	0150	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	19,917.00	0.00	19,917.00	LF	1,400.00	\$2.40	\$3,360.00
		0001	0160	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	420.00	0.00	420.00	LF	0.00	\$2.00	\$0.00
			0170	6207001	PAINT, TYPE L BEADS	420.00	0.00	420.00	LF	0.00	\$4.00	\$0.00
	0001		0170	6269909	PAVEMENT MARKING REMOVAL  MISC.OPTIONAL SHOULDER RUMBLE STRIPS	30.60	0.00	30.60	STA	0.00	\$579.80	\$0.00
			0190	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$30,000.00	\$0.00
		0070			(EPOXY)							
			0200	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	0.00	\$66,925.00	\$0.00
		0070	0210	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	0.00	\$17,846.00	\$0.00
		0070	0220	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$17,846.00	\$0.00
		0070	0230	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$17,846.00	\$0.00
		0070	0240	7129902	MISC.CRACK ARREST HOLE	30.00	0.00	30.00	EA	0.00	\$1,200.00	\$0.00
		0070	0250	7172002	STRIP SEAL	64.00	64.00 0.00	64.00	LF	0.00	\$300.00	\$0.
		0071	0260	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$55,000.00	\$0.00
		0071	0270	7123250	RIVET REMOVAL AND REPLACEMENT	3.00	0.00	3.00	EA	0.00	\$1,500.00	\$0.00
		0071	0280	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	0.00	\$179,000.00	\$0.00
		0071	0290	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	0.00	\$28,265.00	\$0.00
		0071	0300	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$28,265.00	\$0.00
		0071	0310	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$28,265.00	\$0.00
		0071	0320	7129902	MISC.NEW STEEL DIAPHRAGM	5.00	0.00	5.00	EA	0.00	\$15,000.00	\$0.00
		0071	0330	7129902	MISC.REPLACE DIAPHRAGM CONNECTION ANGLE	25.00	0.00	25.00	EA	0.00	\$2,500.00	\$0.00
		0071	0340	7172002	STRIP SEAL	140.00	0.00	140.00	LF	0.00	\$300.00	\$0.00
		0072	0350	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$55,000.00	\$0.00
		0072	0360	7121251	(EPOXY) HINGE MODIFICATION	2.00	0.00	2.00	EA	0.00	\$35,000.00	\$0.00
		0072	0370	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL	1.00	0.00	1.00	LS	0.00	\$70,000.00	\$0.00
					STEEL							
		0072	0380	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0072	0390	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
		0072	0400	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
		0072	0410	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	2.00	0.00	2.00	EA	0.00	\$10,000.00	\$0.00
		0072	0420	7179903	MISC.ASHPALTIC PLUG EXPANSION JOINT SYSTEM	41.00	0.00	41.00	LF	0.00	\$450.00	\$0.00
		0073	0430	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$55,000.00	\$0.00

Revision 3/23/2023 Page 5 of 11



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)		
230120-D01	J5I3483	0073	0440	7121251	HINGE MODIFICATION	2.00	0.00	2.00	EA	0.00	\$35,000.00	\$0.00		
		0073	0450	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	0.00	\$70,000.00	\$0.00		
		0073	0460	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00		
		0073	0470	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00		
		0073	0480	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00		
		0073	0490	7129902	MISC.REPLACE DIAPHRAGM CONNECTION PLATE	1.00	0.00	1.00	EA	0.00	\$10,000.00	\$0.00		
				0073	0500	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	2.00	2.00 0.00	2.00	EA	0.00	\$10,000.00	\$0.00
		0073	0510	7179903	MISC.ASHPALTIC PLUG EXPANSION JOINT SYSTEM	41.00	0.00	41.00	LF	0.00	\$450.00	\$0.00		
		0001	5001	4019905	MISC.OPTIONAL PAVEMENT	0.00	4,421.00	4,421.00	SQYD	2,599.10	\$117.28	\$304,822.45		
	Project J5I3483 - Total Value Posted to Date as of Report Generated Date										\$646,627.25			
230120-D01 Ove	erall - Tota	I Value Pos	sted to Da	ate as of Rep	port Generated Date							\$646,627.25		

Page 6 of 11 Revision 3/23/2023



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5l3483

Line Number	Item Code	Description	DWR Date		Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0140	6181000	MOBILIZATION	11/1/23	11/3/23	0.25	LS	Mobilization installment.	.1				
5001	4019905	MISC.	10/4/23	11/2/23	2,599.10	SQYD	EB and WB Big Piney shoulder reconstruction	165.0				

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 7 of 11



## Line Item Adjustments by Estimate

Contract ID: 230120-D01

	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
513483	0030	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	Material		3	Oct 16, 2023	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Oct 16, 2023	SYSTEM	(\$3,600.00)	
					4	Nov 3, 2023	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Nov 3, 2023	SYSTEM	(\$3,600.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0030 -	- Total						\$0.00	
	0060	CONSTRUCTION SIGNS	Material		2	Oct 3, 2023	SYSTEM	\$4,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Oct 3, 2023	SYSTEM	(\$4,080.00)	
					3	Oct 16, 2023	SYSTEM	\$6,960.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Oct 16, 2023	SYSTEM	(\$6,960.00)	
					4	Nov 3, 2023	SYSTEM	\$6,960.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Nov 3, 2023	SYSTEM	(\$6,960.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0060 -	0060 - Total							
	0070	ADVANCED WARNING RAIL SYSTEM							
	00.0	WARNING RAIL	Material		2	Oct 3, 2023	SYSTEM	\$240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
	00.0	WARNING RAIL	Material		2		SYSTEM	\$240.00 (\$240.00)	Estimate Item Adjustment (0004) due to user shankb1 overridding Payment
		WARNING RAIL	Material			2023 Oct 3,			Estimate Item Adjustment (0004) due to user shankb1 overridding Payment
		WARNING RAIL	Material		2	2023 Oct 3, 2023 Oct 16,	SYSTEM	(\$240.00)	Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment
		WARNING RAIL	Material		2	2023 Oct 3, 2023 Oct 16, 2023 Oct 16,	SYSTEM SYSTEM	(\$240.00) \$480.00	Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment
		WARNING RAIL	Material		3	2023  Oct 3, 2023  Oct 16, 2023  Oct 16, 2023  Nov 3,	SYSTEM SYSTEM SYSTEM	(\$240.00) \$480.00 (\$480.00)	Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user shankb1 overridding Payment
		WARNING RAIL	Material	- Total	3 3 4	2023 Oct 3, 2023 Oct 16, 2023 Oct 16, 2023 Nov 3, 2023 Nov 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$240.00) \$480.00 (\$480.00) \$480.00	Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user shankb1 overridding Payment
		WARNING RAIL	Material - To		3 3 4	2023 Oct 3, 2023 Oct 16, 2023 Oct 16, 2023 Nov 3, 2023 Nov 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$240.00) \$480.00 (\$480.00) \$480.00	Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user shankb1 overridding Payment
	0070 -	WARNING RAIL SYSTEM			3 3 4	2023 Oct 3, 2023 Oct 16, 2023 Oct 16, 2023 Nov 3, 2023 Nov 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$240.00) \$480.00 (\$480.00) \$480.00 (\$480.00)	Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user shankb1 overridding Payment
		WARNING RAIL SYSTEM			3 3 4	2023 Oct 3, 2023 Oct 16, 2023 Oct 16, 2023 Nov 3, 2023 Nov 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$240.00) \$480.00 (\$480.00) \$480.00 (\$480.00) \$0.00	Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user shankb1 overridding Payment
	0070 -	WARNING RAIL SYSTEM  Total  CHANNELIZER	Material - To		2 3 3 4	2023 Oct 3, 2023 Oct 16, 2023 Oct 16, 2023 Nov 3, 2023 Oct 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$240.00) \$480.00 (\$480.00) \$480.00 (\$480.00) \$0.00 \$0.00	Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment
	0070 -	WARNING RAIL SYSTEM  Total  CHANNELIZER	Material - To		2 3 3 4 4 4	2023 Oct 3, 2023 Oct 16, 2023 Nov 3, 2023  Oct 3, 2023 Oct 3, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$240.00) \$480.00 (\$480.00) \$480.00 (\$480.00) \$0.00 \$0.00 \$2,150.40	Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment
	0070 -	WARNING RAIL SYSTEM  Total  CHANNELIZER	Material - To		2 3 4 4 2 2 2	2023 Oct 3, 2023 Oct 16, 2023 Nov 3, 2023 Nov 3, 2023 Oct 3, 2023 Oct 3, 2023 Oct 3, 2023 Oct 16, 16, 16, 16, 16, 16, 16, 16, 16, 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$240.00) \$480.00 (\$480.00) \$480.00 (\$480.00) \$0.00 \$0.00 \$2,150.40	Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment
	0070 -	WARNING RAIL SYSTEM  Total  CHANNELIZER	Material - To		2 3 4 4 2 2 3 3	2023  Oct 3, 2023  Oct 16, 2023  Nov 3, 2023  Oct 3, 2023  Oct 3, 2023  Oct 16, 2023  Oct 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$240.00) \$480.00 (\$480.00) \$480.00 (\$480.00) \$0.00 \$0.00 \$2,150.40 (\$2,150.40)	Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment



## Line Item Adjustments by Estimate

Contract ID: 230120-D01

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5I3483	0080	CHANNELIZER (TRIM LINE)	Material	- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	3	Oct 16, 2023	SYSTEM	(\$2,150.40)	
				Overrun - T	otal			(\$2,150.40)	
			Overrun - Total					(\$2,150.40)	
	0080 - Total							(\$2,150.40)	
	0090	DIRECTIONAL INDICATOR BARRICADE	Material		2	Oct 3, 2023	SYSTEM	\$1,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Oct 3, 2023	SYSTEM	(\$1,260.00)	
					3	Oct 16, 2023	SYSTEM	\$2,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Oct 16, 2023	SYSTEM	(\$2,520.00)	
					4	Nov 3, 2023	SYSTEM	\$2,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Nov 3, 2023	SYSTEM	(\$2,520.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0090 -	Total						\$0.00	
	0100	FLASHING ARROW PANEL	Material		2	Oct 3, 2023	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	Oct 3, 2023	SYSTEM	(\$2,000.00)	
					3	Oct 16, 2023	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	Oct 16, 2023	SYSTEM	(\$4,000.00)	
					4	Nov 3, 2023	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Nov 3, 2023	SYSTEM	(\$4,000.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0100 -	Total						\$0.00	
	0120	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material		3	Oct 16, 2023	SYSTEM	\$81,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	Oct 16, 2023	SYSTEM	(\$81,300.00)	
					4	Nov 3, 2023	SYSTEM	\$81,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Nov 3, 2023	SYSTEM	(\$81,300.00)	
				- Total					
			Material - Total					\$0.00	
	0120 -	Total						\$0.00	
	0150	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,			3	Oct 16, 2023	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Oct 16, 2023	SYSTEM	(\$3,360.00)	



## Line Item Adjustments by Estimate

Contract ID: 230120-D01

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5I3483	0150	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	Material		4	Nov 3, 2023	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Nov 3, 2023	SYSTEM	(\$3,360.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0150 -	Total						\$0.00	
	0320	MISC.	Construction Stockpile No Transaction Type		1	Aug 1, 2023	SYSTEM	\$6,690.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$6,690.00	
			Construction	Stockpile No	Transact	ion Type	- Total	\$6,690.00	
	0320 -	Total						\$6,690.00	
	0330	MISC.	Construction Stockpile No Transaction		1	Aug 1, 2023	SYSTEM	\$8,375.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Туре	- Total				\$8,375.00	
			Construction	Stockpile No	Transact	ion Type	- Total	\$8,375.00	
	0330 -	Total						\$8,375.00	
	0360	HINGE MODIFICATION	Construction Stockpile No Transaction Type		1	Aug 1, 2023	SYSTEM	\$29,826.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$29,826.00	
			Construction	Stockpile No	Transact	ion Type	- Total	\$29,826.00	
	0360 -	Total						\$29,826.00	
	0410	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	Construction Stockpile No Transaction		1	Aug 1, 2023	SYSTEM	\$3,000.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Туре	- Total				\$3,000.00	
			Construction	Stockpile No	Transact	ion Type	- Total	\$3,000.00	
	0410 -	Total						\$3,000.00	
	0440	HINGE MODIFICATION	Construction Stockpile No Transaction		1	Aug 1, 2023	SYSTEM	\$30,536.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Туре	- Total				\$30,536.00	
			Construction	Stockpile No	Transact	ion Type	- Total	\$30,536.00	
	0440 -	Total						\$30,536.00	
	0500	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	Construction Stockpile No Transaction		1	Aug 1, 2023	SYSTEM	\$3,000.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Туре	- Total				\$3,000.00	
			Construction	Stockpile No	Transact	ion Type	- Total	\$3,000.00	
	0500 -	Total						\$3,000.00	
	5001	MISC.	Other Item Adjustment	ACAD	4	Nov 3, 2023	shankb1	\$29.00	190.0 SY 6" Thick 3.7% AC
					4	Nov 3, 2023	shankb1	\$704.74	2409.1 SY 11.5 Thick 3.7% AC
				ACAD - Tota				\$733.74	
				FUEL		Nov 3, 2023	shankb1	\$2,475.42	(3.36-2.89) x 1586.4 Tons x 3.32 Usage Factor = \$2475.42
				FUEL - Tota				\$2,475.42	
				SUBI		Nov 3, 2023	shankb1	(\$34,190.09)	Misc Shoulder Pavement was laid thinner in areas. This adjustment corrects payment for this. See Spreadsheet.
				SUBI - Total				(\$34,190.09)	
			Other Item A	djustment - T	otal			(\$30,980.93)	
	5001 -	Total						(\$30,980.93)	
J5l3483 -	Total							\$48,295.67	
Overall -	Total							\$48,295.67	

# MoDOT

## Contract Adjustments for Contract - 230120-D01

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 11 of 11