#### Pay Estimate Created Date: April 15, 2024

Progress Estimate No 15	umber		230217-C06 Comanche Constru	Pay Period Start Februa Pay Period End April 1		24 Original Contract Amount Net Change Order Amount Current Contract Amount	\$198,671.90	
Approval Date								By User
April 16, 2024			Generated and	Approved	d (and should be considere	ed Draft) at	the Project Office Level by	kennec2
April 16, 2024			Reviewed and Appr	oved (and	d should be considered Dr	aft) at the F	Resident Engineer Level by	sandis1
April 17, 2024				Reviewe	d and Approved at the Cer	ntral Office	Controllers Office Level by	ramses1
Original Completion	n Date	Current Co	mpletion Date	Act	ual Completion Date	%	of Current Contract Amount	Complete
December 1, 202	23	May 2	22, 2024				89.71%	
	Contrac	t Informational Dat	tes		Milestones			
Date Description	Origina	I Completion Date	Current Completi	on Date	No Milestones Exist for	Contract		
Acceptance Date								
Awarded Date	March 8	, 2023	March 8, 2023					
Letting Date	Februar	y 17, 2023	February 17, 2023					
Notice to Proceed Date	May 1, 2	2023	May 1, 2023					
Open to Traffic Date								
Work Began Date	June 28	, 2023	June 28, 2023					

#### This Estimate Previous To Date 230217-C06 **\$29,313.10** (**\$12,633.60)** \$0.00 \$0.00 Total Posted Items Pay \$2,858,074.10 \$2,887,387.20 \$13,062.38 \$0.00 Gross Item Adjustments \$428.78 \$428.7 \$0.00 \$0.00 \$0.00 Incentive Disincentive Liquidated Damage \$0.00 \$0.00 \$0.00 \$0.00 Other Contract Adjustments \$0.00 \$0.00 \$0.00 \$2,871,136.48 \$2,887,815.98 Contract Total Payable This Estimate: \$16,679.50

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Qty							
J4S3383B	0090	6161040	FLASHING ARROW PANEL	EA	\$2,047.500	1	\$2,047.50				
	0130	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	LF	\$12.800	987	\$12,633.60				
	0760	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	LF	\$99.500	59	\$5,870.50				
	0770	7172054	OPEN CELL FOAM JOINT SEAL	LF	\$148.500	59	\$8,761.50				
Project J4S33	83B - Total						\$29,313.10				
Overall - Tota	I						\$29,313.10				

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment	Comments	Adjustment Quantity	Line Item Adjustment	Adjustment amount
				Туре			Unit Price	
J4S3383B	0130	RELOCATING TEMPORARY TRAFFIC BARRIER	Overrun			-493.5	\$12.80	(\$6,316.80)
	0130	RELOCATING TEMPORARY TRAFFIC BARRIER	Overrun			-493.5	\$12.80	(\$6,316.80)
	0320	OPTIONAL CONCRETE WEARING SURFACE	Material			-960.5	\$168.50	(\$161,844.25)
	0320	OPTIONAL CONCRETE WEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	960.5	\$168.50	\$161,844.25

#### Missouri Department of Transportation Contractor's Pay Estimate Summary

#### Pay Estimate Created Date: April 15, 2024

Progres	s Estim 15	ate Number	Contract ID Prime Contrac	230217-0 ctor Comanch			t Change Oro	der Amount	
Project Number	Line No.	Item De	escription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3383B	0360	HALF	-SOLE REPAIR	Material			-6,776	\$66.20	(\$448,571.20
	0360	HALF	-SOLE REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	6,776	\$66.20	\$448,571.20
	0390		AND COATING NG BEARINGS	Material			-10	\$3,981.20	(\$39,812.00)
	0390		AND COATING NG BEARINGS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.	10	\$3,981.20	\$39,812.00
	0540		AL CONCRETE	Material			-622	\$196.50	(\$122,223.00
	0540		AL CONCRETE ING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	622	\$196.50	\$122,223.00
	0590	FULL D	EPTH REPAIR	Material			-301	\$100.50	(\$30,250.50
	0590	FULL C	DEPTH REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.	301	\$100.50	\$30,250.50
Total	· · ·								(\$12,633.60



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4S3383B	FAS- S303(032)	7 Bridge rehabilitations	Various	JACKSON		WB, on I-35 SB to I-670 EB, o SB, and on Route B over Rout	on I-35 SB over I-670, on Front St to the 7
Totals by Jo	siedmun dd						
J4S3383B		tom Boy			This Estimate	Previous	To Date
	Posted I				\$29,313.10	\$2,858,074.10	\$2,887,387.20
	Posted I	em Adjustments	s Gross Iten	n Pay			
	Posted I Gross Ite	em Adjustments G		n Pay	\$29,313.10 (\$12,633.60) <b>\$16,679.50</b>	\$2,858,074.10 \$13,062.38 <b>\$2,871,136.48</b>	\$2,887,387.20 \$428.78 <b>\$2,887,815.98</b>
	Posted I Gross Ite	em Adjustments G		1 Pay	\$29,313.10 (\$12,633.60) <b>\$16,679.50</b> \$0.00	\$2,858,074.10 \$13,062.38 <b>\$2,871,136.48</b> \$0.00	\$2,887,387.20 \$428.78 <b>\$2,887,815.98</b> \$0.00
	Posted I Gross Ite Incentive Disincen	em Adjustments G		1 Pay	\$29,313.10 (\$12,633.60) <b>\$16,679.50</b>	\$2,858,074.10 \$13,062.38 <b>\$2,871,136.48</b>	\$2,887,387.20 \$428.78 <b>\$2,887,815.98</b>



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 5050001, Project Item Line Number 0320, Material Set 505000196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on Contractor to submit CRE20 Concrete test results.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 5050001, Project Item Line Number 0320, Material Set 505000196, Material 0505CCLOSL - Bridge Deck Concrete, Low Slump, Acceptance Action Generic 0505CCLOSL is insufficient.	Waiting on Contractor to submit Sand Gradation results.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 5050001, Project Item Line Number 0320, Material Set 505000196, Material 1005GECMLSBD - Bridge Wearing Surface Grade E LS/DO, Acceptance Action Generic 1005GECMLSBD is insufficient.	Waiting on Materials to submit Grade E tests.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 5050001, Project Item Line Number 0540, Material Set 505000196, Material 0505CCLOSL - Bridge Deck Concrete, Low Slump, Acceptance Action Generic 0505CCLOSL is insufficient.	Waiting on Contractor to submit CRE20 Concrete test results, and Materials to submit Grade E test results.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 7040104, Project Item Line Number 0360, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on Contractor to submit Grade E sample results.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 7040104, Project Item Line Number 0360, Material Set 704010496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Waiting on Contractor to submit Sand Gradation results.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 7040106, Project Item Line Number 0590, Material Set 704010696, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on Contractor to submit CRE20 Concrete test results, Sand test results, and Grade E results.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 7123100, Project Item Line Number 0390, Material Set 712310096, Material 1045PTIZ - High Solids Inorganic Zinc Silicat Paint, Acceptance Action Generic 1045PTIZ is insufficient.	Waiting on Contractor to submit PAL forms	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 7123100, Project Item Line Number 0390, Material Set 712310096, Material 1045PTGREPMA - Gray Epoxy-Mastic Primer, Acceptance Action Generic 1045PTGREPMA is insufficient.	Waiting on Contractor to submit PAL forms	kennec2	Overridden
Estimate Exception Type: Item Overrun: Contract 230217-C06, Contract Project J4S3383B, Project Item Line Number 0130, Contract Line Item Number 0130, Item 6175010A, Minor Item.	Item will appear on Change Order.	kennec2	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230217-C06, Contract Project J4S3383B, Project Item Line Number 0070, Contract Line Item Number 0070, Item 6161025, Minor Item.	Item will appear on Change Order.	kennec2	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230217-C06, Contract Project J4S3383B, Project Item Line Number 0080, Contract Line Item Number 0080, Item 6161030, Minor Item.	Item will appear on Change Order.	kennec2	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230217-C06, Contract Project J4S3383B, Project Item Line Number 0600, Contract Line Item Number 0600, Item 7101000, Minor Item.	Item will appear on Change Order.	kennec2	Acknowledged



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

date and can differ from the posted amount at the time the Estimate was Generated.

MAXNAMAXNAMAXNAMAXNAMAXNAMAXNAMAXNAMAXNA <td< th=""><th>Contract Nm.CONTRACT</th><th>Project No.</th><th>Category</th><th>Line No.</th><th>Item Code</th><th>Description</th><th>Bid Quantity</th><th>Net Change Order</th><th>Total Current Quantity</th><th>Unit</th><th>Total Posted Approved Qty</th><th>Unit Price</th><th>Total Value POSTED To Date (See report generated date)</th></td<>	Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
mm <td>30217-C06</td> <td>J4S3383B</td> <td>0001</td> <td>0010</td> <td>2022010</td> <td>REMOVAL OF IMPROVEMENTS</td> <td>1.00</td> <td>0.00</td> <td>1.00</td> <td>LS</td> <td>0.49</td> <td>\$8,019.30</td> <td>\$3,929.4</td>	30217-C06	J4S3383B	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.49	\$8,019.30	\$3,929.4
mm 			0001	0020	2153000	SHAPING SLOPES, CLASS III	15.00	0.00	15.00	100F	7.10	\$1,080.60	\$7,672.2
mm 			0001	0030	6122009	IMPACT ATTENUATOR 45 MPH (SAND BARREL ARRAY)	1.00	0.00	1.00	EA	1.00	\$3,014.40	\$3,014.4
000100020101001000010000101001000010100100001			0001	0040	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	1.00	-1.00	0.00	EA	0.00	\$3,696.90	\$0.0
001104700470204702047020470304700470047004700			0001	0050	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	1.00	\$1,876.90	\$1,876.9
No. 1000 <td></td> <td></td> <td>0001</td> <td>0060</td> <td>6161005</td> <td>CONSTRUCTION SIGNS</td> <td>2,142.00</td> <td>0.00</td> <td>2,142.00</td> <td>SQFT</td> <td>1,178.93</td> <td>\$6.80</td> <td>\$8,016.7</td>			0001	0060	6161005	CONSTRUCTION SIGNS	2,142.00	0.00	2,142.00	SQFT	1,178.93	\$6.80	\$8,016.7
Note 10000100 </td <td></td> <td></td> <td>0001</td> <td>0070</td> <td>6161025</td> <td>CHANNELIZER (TRIM LINE)</td> <td>151.00</td> <td>0.00</td> <td>151.00</td> <td>EA</td> <td>259.00</td> <td>\$29.60</td> <td>\$7,666.4</td>			0001	0070	6161025	CHANNELIZER (TRIM LINE)	151.00	0.00	151.00	EA	259.00	\$29.60	\$7,666.4
Norm ControlNorm ControlSymbolSymbol Control <td></td> <td></td> <td>0001</td> <td>0080</td> <td>6161030</td> <td>TYPE III MOVEABLE BARRICADE</td> <td>35.00</td> <td>0.00</td> <td>35.00</td> <td>EA</td> <td>38.00</td> <td>\$227.50</td> <td>\$8,645.0</td>			0001	0080	6161030	TYPE III MOVEABLE BARRICADE	35.00	0.00	35.00	EA	38.00	\$227.50	\$8,645.0
Interproc.<			0001	0090	6161040	FLASHING ARROW PANEL	10.00	0.00	10.00	EA	2.00	\$2,047.50	\$4,095.0
Image         Image <th< td=""><td></td><td></td><td>0001</td><td>0100</td><td>6161098A</td><td>INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR</td><td>16.00</td><td>0.00</td><td>16.00</td><td>EA</td><td>12.00</td><td>\$2,957.50</td><td>\$35,490.0</td></th<>			0001	0100	6161098A	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	16.00	0.00	16.00	EA	12.00	\$2,957.50	\$35,490.0
International probability of extrantic probabili			0001	0110	6173600D		658.00	0.00	658.00	LF	658.00	\$50.60	\$33,294.8
0200         0130         01730144         RELOCATING TEMPORARY TRAFFIC BARRIER         06800         0.000         0.000         0.00         0.00         0.00         0.00         0.00         0.0000         0.0000         0			0001	0120	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR	470.00	-470.00	0.00	LF	0.00	\$77.80	\$0.0
Internal ControlOneOneControl </td <td></td> <td></td> <td>0001</td> <td>0130</td> <td>6175010A</td> <td></td> <td>658.00</td> <td>0.00</td> <td>658.00</td> <td>LF</td> <td>1,645.00</td> <td>\$12.80</td> <td>\$21,056.0</td>			0001	0130	6175010A		658.00	0.00	658.00	LF	1,645.00	\$12.80	\$21,056.0
contcity<citycitycitycitycitycityc			0001	0140	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	470.00	-470.00	0.00	LF	0.00	\$41.20	\$0.0
International         Other         PREFORMED THERMOPLASTIC PAVEMENT MARKINS, 24 IM.         094.0         31.00         573.00         LF         0.00         353.00           0001         0170         6050800         RM-HTTE-HIGH BUILD WATERBORNE PAVEMENT MARKINS, 24 IM.         3.08.00         -1.397.00         1.181.00         LF         378.00         5.43.00           0001         0180         6050803         RM-HTTPH LEBADS         2.340.00         2.350.00         2.014.00         LF         378.00         5.43.00           0001         0180         6050803         RM-HTTPH LEBADS         EADSO         313.00         313.00         315.00         LF         0.00         5.43.00           0001         0200         6050800         RM-HTTPH PEADSO         LEBADSO         1.500.00         LF         0.00         5.43.00           0001         0200         6050900         RM-HTTPH PEADSO         LEBADSO         1.500.00         LF         0.00         1.500.00         LF         0.00         0.00           0001         0202         605090         AMARKINA PANAT, TMEP PEADSO         LEBADSO         2.0000         LEBADSO         2.0000         LEBADSO         2.0000         LEBADSO         2.0000         LEBADSO         2.0000				0150	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$293,800.00	\$0.00
International         Internaternat         International         Internat			0001	0151	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$279,680.00	\$279,680.00
1000107062090281.M YITE HOM BUILD WATERBORNE PAVEMENT RANKT, TYPEL LERAS3.008.01.307.001.611.00LF3.79.008.4.3010010180620902M. WILLOW HOM BUILD WATERBORNE PAVEMENT MARKING PANT, TYPEL LERAS63.00313.003.00.00LF0.008.00.08.00.00 <t< td=""><td></td><td></td><td>0001</td><td>0160</td><td>6200015</td><td>PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.</td><td>604.00</td><td>-31.00</td><td>573.00</td><td>LF</td><td>0.00</td><td>\$28.40</td><td>\$0.00</td></t<>			0001	0160	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	604.00	-31.00	573.00	LF	0.00	\$28.40	\$0.00
0001         0180         0269003         KIN YELLOW HIGH BULL DWATERBORNE PAVEMENT         2.3400         32.800         2.01.400         LF         33.600         54.30           0001         0190         6206006         1.211.WHTE HUR BULD WATERBORNE PAVEMENT         663.00         -31.300         35.00         LF         0.00         53.00         LF         0.00         14.00         LF         14.00         L				0170	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	3,008.00	-1,397.00	1,611.00	LF	379.00	\$4.30	\$1,629.7
00100190625950612 MINITE NICH BULD WATERBORNE PAVEMENT663.00-31.3035.001.E0.0099.0000102006206000AN WHITE STANDARD WATERBORNE PAVEMENT MARKING1.500.000.001.500.001.E997.05.33.0000102106206000AN NELLOW STANDARD WATERBORNE PAVEMENT140.000.0012.864.001.E140.001.E140.001.E140.001.E140.001.E140.001.E140.001.E1.5			0001	0180	6205903A		2,340.00	-326.00	2,014.00	LF	356.00	\$4.30	\$1,530.8
NAME         NAME <th< td=""><td></td><td></td><td>0001</td><td>0100</td><td>62050064</td><td></td><td>663.00</td><td>313.00</td><td>350.00</td><td>15</td><td>0.00</td><td>\$9.10</td><td>\$0.0</td></th<>			0001	0100	62050064		663.00	313.00	350.00	15	0.00	\$9.10	\$0.0
Normal         Print         Print <t< td=""><td></td><td></td><td></td><td></td><td></td><td>MARKING PAINT, TYPE L BEADS</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>						MARKING PAINT, TYPE L BEADS							
India			0001	0200	6206000C		1,500.00	0.00	1,500.00	LF	967.00	\$3.30	\$3,191.1
Interview         Interview <t< td=""><td></td><td></td><td>0001</td><td>0210</td><td>6206001C</td><td></td><td>140.00</td><td>0.00</td><td>140.00</td><td>LF</td><td>140.00</td><td>\$3.30</td><td>\$462.0</td></t<>			0001	0210	6206001C		140.00	0.00	140.00	LF	140.00	\$3.30	\$462.0
Note         Optimized         Opt			0001	0220	6207001	PAVEMENT MARKING REMOVAL	12,864.00	0.00	12,864.00	LF	0.00	\$0.50	\$0.0
00100250060106MGS BRIDGE APPROACH TRANSITION SECTION8.000.000.800FA6.00\$4,151.9000100260606304TYPE A CRASHWORTHY END TERMINAL (MASH)8.000.000.000.000.005.00 <td></td> <td></td> <td>0001</td> <td>0230</td> <td>6208076</td> <td>4 IN TEMPORARY PAVEMENT MARKING PAINT</td> <td>5,869.00</td> <td>-209.00</td> <td>5,660.00</td> <td>LF</td> <td>3,396.00</td> <td>\$1.60</td> <td>\$5,433.6</td>			0001	0230	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	5,869.00	-209.00	5,660.00	LF	3,396.00	\$1.60	\$5,433.6
Initial         Initial <t< td=""><td></td><td></td><td>0010</td><td>0240</td><td>6061060</td><td>MGS GUARDRAIL</td><td>763.00</td><td>0.00</td><td>763.00</td><td>LF</td><td>187.50</td><td>\$29.60</td><td>\$5,550.0</td></t<>			0010	0240	6061060	MGS GUARDRAIL	763.00	0.00	763.00	LF	187.50	\$29.60	\$5,550.0
00100260668014TYPE A CRASHWORTHY END TERMINAL (MASH)8.000.008.00EA6.00\$3,696.9007002702161502REMOVAL OF CONCRETE WEARING SURFACE17,290.00.0017,290.0SOFT17,280.00\$61.0300700200216500REMOVAL OF CATHODIC PROTECTION SYSTEM1.000.001.000.051.01\$5,190.5007070310216903MISC. Remova and Replace Barrier Curb1.010.001.020.01LF1.150.0\$1,559.9007070300205001OPTIONAL CONCRETE WEARING SURFACE1.921.000.001.921.00SQVD900.00\$1,66.00070703037031040DIAMOND GRINDING1.921.000.001.921.00SQVD900.00\$1,68.00070703037031040DIAMOND GRINDING1.921.001.921.00SQVD900.00\$1,539.4007070304704102SUBSTUCTURE REPAIR (UNFORMED)4.0001.0001.921.00SQVD9.000\$5,534.0007070305704104HALF-SOLE REPAIR300.003.77.006.77.60SQ10.00\$5,539.40070703077040102SUBSTUCTURE REPAIR (UNFORMED)1.800.003.76.00SQVD6.77.60\$6,76.00070703077040104FULDEPTH REPAIR300.003.76.005.77.005.75.00\$6,76.00\$1,65.0007070307710100REINFORCING STEEL (EPCXY COATED)1.800.000.00 <td< td=""><td></td><td></td><td>0010</td><td>0250</td><td>6061069</td><td></td><td>8.00</td><td>0.00</td><td>8.00</td><td>EA</td><td>6.00</td><td>\$4,151.90</td><td>\$24,911.4</td></td<>			0010	0250	6061069		8.00	0.00	8.00	EA	6.00	\$4,151.90	\$24,911.4
0070         0290         2164500         REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT         88.00         0.00         88.00         LF         88.00         \$1,063.30           0070         0300         2165500         REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT         1.00         0.00         1.00         LF         88.00         \$1,063.30           0070         0300         2165500         REMOVAL OF CATHODIC PROTECTION SYSTEM         1.00         0.00         1.00         LF         1.00         \$5,190.50           0070         0310         2169903         MISC.Remove and Replace Barrier Curb         15.00         0.00         1.921.00         SQVD         960.50         \$168.50           0070         0330         703104         DIAMOND GRINDING         1.921.00         1.921.00         1.921.00         SQVD         0.000         \$53.94.00           0070         0340         703424         CLASS B-2 CONCRETE         1.921.00         1.921.00         1.921.00         SQVD         0.000         \$53.94.00           0070         0340         704102         SUBSTRUCTURE REPAIR (UNFORMED)         40.00         1.00         6.77.60         \$GVF         6.77.60         \$S0F1         6.77.60         \$S0F1         6.77.60         \$S0F1			0010	0260	6063014		8.00	0.00	8.00	EA	6.00	\$3,696.90	\$22,181.4
OUT         OUT <td></td> <td></td> <td>0070</td> <td>0270</td> <td>2161502</td> <td>REMOVAL OF CONCRETE WEARING SURFACE</td> <td>17,290.00</td> <td>0.00</td> <td>17,290.00</td> <td>SQFT</td> <td>17,290.00</td> <td>\$6.10</td> <td>\$105,469.0</td>			0070	0270	2161502	REMOVAL OF CONCRETE WEARING SURFACE	17,290.00	0.00	17,290.00	SQFT	17,290.00	\$6.10	\$105,469.0
00700300216500REMOVAL OF CATHODIC PROTECTION SYSTEM1.000.001.00LS1.00S5.190.50007003102169903MISC.Remove and Replace Barrier Curb15.000.001.5000.15LF15.00\$1.559.9000700320505001OPTIONAL CONCRETE WEARING SURFACE1.921.000.001.921.00SQVD960.50\$166.50007003307031004DIAMOND GRINDING1.921.001.921.001.921.00SQVD0.000\$7.4000700340704102SLBSTRUCTURE REPAIR (UNFORMED)40.001.0041.00SQFT41.00\$5.934.00007003507040102SUBSTRUCTURE REPAIR (UNFORMED)40.003.700.003.700.00SQFT6.770.00\$5.394.00007003607040102FUL DEPTH REPAIR3.000.003.770.00SQFT6.770.00\$5.94.00007003607040102FUL DEPTH REPAIR3.000.003.770.00SQFT6.770.00\$5.94.00007003707040102FUL DEPTH REPAIR3.000.003.770.00SQFT6.770.00\$10.00007003807101000REINFORCING STEEL (EPOXY COATED)1.800.000.001.800.00LB1.455.20\$6.5000700390712001STRIP SEAL EXPANSION JOINT SYSTEM88.000.0088.00LF88.00\$3.812.00007004100204040STRIP SEAL EXPANSION JOINT SYSTEM88.003.4000.00<			0070	0290	2164500		88.00	0.00	88.00	LF	88.00	\$1,063.30	\$93,570.40
0000         0320         505001         OPTIONAL CONCRETE WEARING SURFACE         1,921.00         0.00         1,921.00         SQYD         960.00         \$168.60           0070         0330         7031004         DIAMOND GRINDING         1,921.00         1,921.00         SQYD         0.00         \$\$168.60           0070         0340         7031044         CLASS B-2 CONCRETE         7.00         0.00         1,921.00         SQYD         0.00         \$\$5,394.00           0070         0350         7040102         SUBSTRUCTURE REPAIR (UNFORMED)         40.00         1.00         41.00         SQFT         41.00         \$\$318.20           0070         0360         7040102         SUBSTRUCTURE REPAIR (UNFORMED)         40.00         3.00.00         \$7.760         \$\$QFT         6.776.00         \$\$GE20           0070         0360         7040104         HALF-SOLE REPAIR         3.000.0         3.776.00         \$\$QFT         6.776.00         \$\$GE30           0070         0370         7040106         FULL DEPTH REPAIR         350.00         3.00.00         \$\$1,80.00         \$\$GF1         5.00         \$\$106.50           0070         0380         710100         REINFORCING STEEL (EPOXY COATED)         1,800.0         1.00.0			0070	0300	2165500		1.00	0.00	1.00	LS	1.00	\$5,190.50	\$5,190.5
No.         No. <td></td> <td></td> <td>0070</td> <td>0310</td> <td>2169903</td> <td>MISC.Remove and Replace Barrier Curb</td> <td>15.00</td> <td>0.00</td> <td>15.00</td> <td>LF</td> <td>15.00</td> <td>\$1,559.90</td> <td>\$23,398.5</td>			0070	0310	2169903	MISC.Remove and Replace Barrier Curb	15.00	0.00	15.00	LF	15.00	\$1,559.90	\$23,398.5
Normal         Normal<			0070	0320	5050001	OPTIONAL CONCRETE WEARING SURFACE	1,921.00	0.00	1,921.00	SQYD	960.50	\$168.50	\$161,844.2
No.         No. <td></td> <td></td> <td>0070</td> <td>0330</td> <td>7031004</td> <td>DIAMOND GRINDING</td> <td>1,921.00</td> <td>0.00</td> <td>1,921.00</td> <td>SQYD</td> <td>0.00</td> <td>\$7.40</td> <td>\$0.0</td>			0070	0330	7031004	DIAMOND GRINDING	1,921.00	0.00	1,921.00	SQYD	0.00	\$7.40	\$0.0
Norm         Odd         Total of the solution of the			0070	0340	7034214	CLASS B-2 CONCRETE	7.00	0.00	7.00	CUYD	7.00	\$5,394.00	\$37,758.0
Normal         Normal<			0070	0350	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	40.00	1.00	41.00	SQFT	41.00	\$318.20	\$13,046.2
0070         0380         7101000         REINFORCING STEEL (EPOXY COATED)         1,800.0         0.00         1,800.0         LB         1,455.0         \$\$6.0           0070         0390         7123100         CLEANING AND COATING EXISTING BEARINGS         10.00         0.00         10.00         EA         10.00         \$\$3,981.20           0070         0400         7172010         STRIP SEAL EXPANSION JOINT SYSTEM         88.00         0.00         88.00         LF         88.00         \$\$81.20           0071         0410         202403         REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)         34.00         54.00         \$\$0.0			0070	0360	7040104	HALF-SOLE REPAIR	3,000.00	3,776.00	6,776.00	SQFT	6,776.00	\$66.20	\$448,571.2
0070         0390         7123100         CLEANING AND COATING EXISTING BEARINGS         10.00         0.00         10.00         EA         10.00         \$3,981.20           0070         0400         7172001         STRIP SEAL EXPANSION JOINT SYSTEM         88.00         0.00         88.00         LF         88.00         \$818.20           0071         0410         2024043         REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)         34.00         -34.00         0.00         SQFT         0.00         \$312.80			0070	0370	7040106	FULL DEPTH REPAIR	350.00	-345.00	5.00	SQFT	5.00	\$100.50	\$502.5
0070         0400         7172001         STRIP SEAL EXPANSION JOINT SYSTEM         88.00         0.00         88.00         LF         88.00         \$81.20           0071         0410         2024043         REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)         34.00         -34.00         SQFT         0.00         \$312.80			0070	0380	7101000	REINFORCING STEEL (EPOXY COATED)	1,800.00	0.00	1,800.00	LB	1,455.20	\$6.50	\$9,458.8
0071         0410         2024043         REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)         34.00         -34.00         0.00         SQFT         0.00         \$\$312.80			0070	0390	7123100	CLEANING AND COATING EXISTING BEARINGS	10.00	0.00	10.00	EA	10.00	\$3,981.20	\$39,812.0
			0070	0400	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	88.00	0.00	88.00	LF	88.00	\$818.20	\$72,001.6
0071         0420         2161500         REMOVAL OF SEAL COAT OR POLYMER WEARING SURFACE         5,358.00         0.00         5,358.00         SQFT         5,358.00         \$2.30			0071	0410	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	34.00	-34.00	0.00	SQFT	0.00	\$312.80	\$0.0
			0071	0420	2161500	REMOVAL OF SEAL COAT OR POLYMER WEARING SURFACE	5,358.00	0.00	5,358.00	SQFT	5,358.00	\$2.30	\$12,323.4
0071         0430         2164500         REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT         54.00         0.00         54.00         LF         54.00         \$1,063.30				0430	2164500		54.00	0.00	54.00	LF	54.00	\$1,063.30	\$57,418.2



Revision 3/23/2023

# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Page 6 of 22

#### Total Paid / All Items / All Estimates (Including this Estimate)

d date and can differ from the posted amount at the time the Estimate was Generated. N

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
217-C06	J4S3383B	0071	0440	2169903	MISC.Remove and Replace Barrier Curb	8.00	0.00	8.00	LF	8.00	\$1,559.90	\$12,479
		0071	0450	6233000	EPOXY POLYMER WEARING SURFACE	585.00	0.00	585.00	SQYD	585.00	\$85.30	\$49,900
		0071	0460	7034214	CLASS B-2 CONCRETE	6.40	0.00	6.40	CUYD	6.40	\$5,394.00	\$34,521
		0071	0470	7040104	HALF-SOLE REPAIR	300.00	38.00	338.00	SQFT	338.00	\$64.00	\$21,632
		0071	0480	7040106	FULL DEPTH REPAIR	850.00	-833.00	17.00	SQFT	17.00	\$97.00	\$1,649
		0071	0490	7101000	REINFORCING STEEL (EPOXY COATED)	980.00	-199.00	781.00	LB	781.00	\$6.50	\$5,076
		0071	0500	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	54.00	0.00	54.00	LF	54.00	\$818.20	\$44,182
		0072	0510	2161502	REMOVAL OF CONCRETE WEARING SURFACE	5,690.00	0.00	5,690.00	SQFT	5,690.00	\$7.20	\$40,968
		0072	0520	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE		0.00	52.00	LF	52.00	\$1,063.30	\$55,297
		0072	0530	2169903	MISC.Remove and Replace Barrier Curb	8.00	0.00	8.00	LF	8.00	\$1,559.90	\$12,479
		0072	0540	5050001	OPTIONAL CONCRETE WEARING SURFACE	622.00	0.00	622.00	SQYD	622.00	\$196.50	\$122,22
		0072	0550	7031004	DIAMOND GRINDING	622.00	0.00	622.00	SQYD	28.70	\$7.40	\$21
		0072	0560	7034214	CLASS B-2 CONCRETE	7.00	0.00	7.00	CUYD	7.00	\$5,394.00	\$37,75
		0072	0570	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	50.00	0.00	50.00	SQFT	30.80	\$557.20	\$17,16
		0072	0580	7040104	HALF-SOLE REPAIR	300.00	1,772.00	2,072.00	SQFT	2,072.00	\$66.20	\$137,16
		0072	0590	7040106	FULL DEPTH REPAIR	850.00	-549.00	301.00	SQFT	301.00	\$100.50	\$30,25
		0072	0600	7101000	REINFORCING STEEL (EPOXY COATED)	510.00	0.00	510.00	LB	752.00	\$6.50	\$4,88
		0072	0610	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	52.00	0.00	52.00	LF	52.00	\$818.20	\$42,54
		0073	0620	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	33.00	-33.00	0.00	SQFT	0.00	\$312.80	ş
		0073	0630	2169903	MISC.Remove and Replace Barrier Curb	34.00	-29.00	5.00	LF	5.00	\$20.00	\$10
		0073	0640	7034214	CLASS B-2 CONCRETE	3.00	0.00	3.00	CUYD	3.00	\$5,394.00	\$16,1
		0073	0650	7101000	REINFORCING STEEL (EPOXY COATED)	290.00	95.00	385.00	LB	290.00	\$6.50	\$1,88
		0073	0660	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	34.00	0.00	34.00	LF	34.00	\$818.20	\$27,8
		0074	0670	2161500	REMOVAL OF SEAL COAT OR POLYMER WEARING SURFACE	13,792.00	0.00	13,792.00	SQFT	12,857.00	\$1.70	\$21,8
		0074	0680	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	81.00	0.00	81.00	LF	81.00	\$796.30	\$64,50
		0074	0690	2169901	MISC.Removal of Loose Concrete from Prestressed Panels	1.00	0.00	1.00	LS	1.00	\$13,649.90	\$13,6
		0074	0700	2169903	MISC.Remove and Replace Barrier Curb	13.00	0.00	13.00	LF	13.00	\$3,412.50	\$44,36
		0074	0710	6233000	EPOXY POLYMER WEARING SURFACE	1,757.00	0.00	1,757.00	SQYD	1,428.50	\$85.30	\$121,8
		0074	0720	7034214	CLASS B-2 CONCRETE	8.80	0.00	8.80	CUYD	8.80	\$7,962.50	\$70,0
		0074	0730	7101000	REINFORCING STEEL (EPOXY COATED)	780.00	0.00	780.00	LB	780.00	\$9.40	\$7,3
		0074	0740	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$41,848.40	\$41,8
		0074	0750	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	81.00	0.00	81.00	LF	81.00	\$1,025.00	\$83,0
		0075	0760	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	59.00	0.00	59.00	LF	59.00	\$99.50	\$5,8
		0075	0770	7172054	OPEN CELL FOAM JOINT SEAL	59.00	0.00	59.00	LF	59.00	\$148.50	\$8,7
		0076	0780	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	71.00	0.00	71.00	LF	71.00	\$99.50	\$7,0
		0076	0790	7172002	STRIP SEAL	71.00	0.00	71.00	LF	71.00	\$202.90	\$14,4
		0073	5001	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	0.00	34.00	34.00	LF	34.00	\$1,065.30	\$36,2
		0001	5002	6189901	CONCRETE	0.00	1.00	1.00	LS	1.00	\$14,120.00	\$14,1
		0072	5003	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	0.00	18.16	18.16	CY	18.16	\$800.00	\$14,5
			5004	4039905	MISC.ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125B MIX)		126.70	126.70	SQYD	126.70	\$31.30	\$3,9
		0071	5004	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	·	126.70	126.70	SQYD	126.70	\$110.10	\$13,9
					SURFACING (3 IN. THICK OR LESS)							
	0071 5006 6189902 MISC ADDITIONAL MOBILIZATION FOR MILLING AND ASPHALT	0.00	1.00	1.00	EA	1.00	\$5,897.88	\$5,8				
		0072	5007	6049901		0.00	1.00	1.00	LS	1.00	\$3,362.25	\$3,3
		0073	5008	7040104	HALF-SOLE REPAIR	0.00	9.00	9.00	SQFT	9.00	\$66.20	\$59
		0073	5009	7039901	MISC.Backwall Repair	0.00	1.00	1.00	LS	1.00	\$14,085.09	\$14,08



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230217-C06 Ove	230217-C06 Overall - Total Value Posted to Date as of Report Generated Date										\$2,887,387.18	



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4S3383B DWR DWR Quantity Units Date Date Doted From Offset/ Station/ Distance Log Mile To Offset/ Station/ Log Mile Description Location Comments Line Number Item Code EA Arrow panel used in connection with signing for double lane drops to install closed signs on the overhead trusses. 0090 6161040 FLASHING ARROW PANEL 4/12/24 4/15/24 1.00 LF Bridge A0805 Barrier Relocation to temporary configuration. Contractor agreed to allowing 25% reduction in cost due to temporary reconfiguration. 0130 6175010A RELOCATING TEMPORARY TRAFFIC BARRIER 3/15/24 3/18/24 493.50 .188 .316 LF A0805 Relocation of barrier wall form winter configuration into deck pour configuration. 4/3/24 4/11/24 493.50 .188 .316 0760 2165000 REMOVAL OF EXISTING EXPANSION JOINT SEAL 4/12/24 4/15/24 59.00 LF A5164 joints .012 .188 0770 7172054 OPEN CELL FOAM JOINT SEAL 4/12/24 4/15/24 59.00 LF A5164 joints .012 .188

The information below this line are details for Construction Signs (if applicable). No Data Available



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
			. )	Туре			_,		
J4S3383B	0030	IMPACT ATTENUATOR 45 MPH (SAND	Material		3	Aug 2, 2023	SYSTEM	\$3,014.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		BARREL ARRAY)			3	Aug 2, 2023	SYSTEM	(\$3,014.40)	
					4	Aug 16, 2023	SYSTEM	\$3,014.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Aug 16, 2023	SYSTEM	(\$3,014.40)	
					5	Sep 5, 2023	SYSTEM	\$3,014.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$3,014.40)	
				- Total		2020		\$0.00	
			Material - Tot					\$0.00	
	0030 -	Total						\$0.00	
	0060	CONSTRUCTION	Material		1	Jun 30,	SYSTEM	\$1,251.20	This adjustment offsets the original system-generated Material Payment
	0000	SIGNS	Matorial			2023			Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Jun 30, 2023	SYSTEM	(\$1,251.20)	
					2	Jul 17, 2023	SYSTEM	\$2,988.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$2,988.60)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0060 -	Total						\$0.00	
	0070	CHANNELIZER (TRIM LINE)	Material		2	Jul 17, 2023	SYSTEM	\$296.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$296.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
			Overrun	Overrun	4	Aug 16, 2023	SYSTEM	(\$562.40)	
					10	Nov 16, 2023	SYSTEM	(\$2,634.40)	
				Overrun - T	otal			(\$3,196.80)	
			Overrun - Tot	tal				(\$3,196.80)	
	0070 -	Total						(\$3,196.80)	
	0080	TYPE III MOVEABLE BARRICADE	Material		1	Jun 30, 2023	SYSTEM	\$3,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Jun 30, 2023	SYSTEM	(\$3,640.00)	
					2	Jul 17, 2023	SYSTEM	\$4,095.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$4,095.00)	
				- Total				\$0.00	
			Material - Tot					\$0.00	
			Overrun	Overrun	10	Nov 16, 2023	SYSTEM	(\$682.50)	
				Overrun - T	otal			(\$682.50)	
			Overrun - Tot	tal				(\$682.50)	
	0080 -	Total						(\$682.50)	
	0100	CMS W/O	Material		1	Jun 30,	SYSTEM	\$11,830.00	This adjustment offsets the original system-generated Material Payment
		COMMUNICATION				2023			Estimate Item Adjustment (0003) due to user kennec2 overridding Payment



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J4S3383B	0100	INTERFACE, CONT F/	Material						Estimate Exception 3 on the current Payment Estimate.
		17			1	Jun 30, 2023	SYSTEM	(\$11,830.00)	
					2	Jul 17, 2023	SYSTEM	\$11,830.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$11,830.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0100 -	Total						\$0.00	
	0110	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material		3	Aug 2, 2023	SYSTEM	\$33,294.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Aug 2, 2023	SYSTEM	(\$33,294.80)	
					4	Aug 16, 2023	SYSTEM	\$33,294.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Aug 16, 2023	SYSTEM	(\$33,294.80)	
					5	Sep 5, 2023	SYSTEM	\$33,294.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$33,294.80)	
					6	Sep 18, 2023	SYSTEM	\$33,294.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Sep 15, 2023	SYSTEM	(\$33,294.80)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0110 -	Total						\$0.00	
	0130	RELOCATING TEMPORARY	Overrun	Overrun	15	Apr 15, 2024	SYSTEM	(\$12,633.60)	
		TRAFFIC BARRIER		Overrun - To				(\$12,633.60)	
			Overrun - To	tal				(\$12,633.60)	
	0130 -	Total						(\$12,633.60)	
	0170	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	Material		7	Oct 2, 2023	SYSTEM	\$1,629.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		FAINT			7	Oct 2, 2023	SYSTEM	(\$1,629.70)	
					14	Feb 16, 2024	SYSTEM	\$1,629.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					14	Feb 16, 2024	SYSTEM	(\$1,629.70)	
								\$0.00	
				- Total					
			Material - Tot					\$0.00 \$0.00	
	0170 -	Total	Material - To						
	<b>0170 -</b> 0180	6 IN. YELLOW HIGH BUILD WATERBORNE	Material - Tot Material		7	Oct 2, 2023	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		6 IN. YELLOW HIGH BUILD			7 7		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0008) due to user kennec2 overridding Payment
		6 IN. YELLOW HIGH BUILD WATERBORNE				2023 Oct 2,		\$0.00 \$0.00 \$1,530.80	Estimate Item Adjustment (0008) due to user kennec2 overridding Payment
		6 IN. YELLOW HIGH BUILD WATERBORNE			7	2023 Oct 2, 2023 Feb 16,	SYSTEM	\$0.00 \$0.00 \$1,530.80 (\$1,530.80)	Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment
		6 IN. YELLOW HIGH BUILD WATERBORNE			7 14	2023 Oct 2, 2023 Feb 16, 2024 Feb 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$1,530.80 (\$1,530.80) \$1,530.80	Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment



Apr 18, 2024

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3383B	0180 -	Total						\$0.00	
	0200	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		6	Sep 18, 2023	SYSTEM	\$3,191.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		WARKING			6	Sep 15, 2023	SYSTEM	(\$3,191.10)	
					7	Oct 2, 2023	SYSTEM	\$3,191.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Oct 2, 2023	SYSTEM	(\$3,191.10)	
					8	Oct 16, 2023	SYSTEM	\$3,191.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Oct 16, 2023	SYSTEM	(\$3,191.10)	
					9	Nov 2, 2023	SYSTEM	\$3,191.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Nov 2, 2023	SYSTEM	(\$3,191.10)	
					10	Nov 16, 2023	SYSTEM	\$3,191.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Nov 16, 2023	SYSTEM	(\$3,191.10)	
					14	Feb 16, 2024	SYSTEM	\$3,191.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					14	Feb 16, 2024	SYSTEM	(\$3,191.10)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0200 -	Total						\$0.00	
	0210	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		6	Sep 18, 2023	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		WARKING			6	Sep 15, 2023	SYSTEM	(\$462.00)	
					7	Oct 2, 2023	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					7	Oct 2, 2023	SYSTEM	(\$462.00)	
					8	Oct 16, 2023	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					8	Oct 16, 2023	SYSTEM	(\$462.00)	
					9	Nov 2, 2023	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Nov 2, 2023	SYSTEM	(\$462.00)	
					10	Nov 16, 2023	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			10	10	Nov 16, 2023	SYSTEM	(\$462.00)		
					14	Feb 16, 2024	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					14	Feb 16, 2024	SYSTEM	(\$462.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0210 -	Total						\$0.00	



		<b>D</b>		0.1			<b>a</b>		
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3383B	0240	MGS GUARDRAIL	Construction Stockpile		5	Sep 5, 2023	SYSTEM	(\$752.39)	Payment Estimate Item Adjustment generated Stockpile Transaction
					10	Nov 16, 2023	SYSTEM	(\$2,069.06)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$2,821.45)	
			Construction	Stockpile - 1	Fotal			(\$2,821.45)	
			Construction Stockpile		2	Jul 17, 2023	SYSTEM	\$11,481.43	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$11,481.43	
			Construction	Stockpile S	TMI - Tota			\$11,481.43	
			Material		5	Sep 5, 2023	SYSTEM	\$1,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$1,480.00)	
					6	Sep 18, 2023	SYSTEM	\$1,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Sep 15, 2023	SYSTEM	(\$1,480.00)	
					7	Oct 2, 2023	SYSTEM	\$1,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Oct 2, 2023	SYSTEM	(\$1,480.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0240 -	Total						\$8,659.98	
	0250	MGS BRIDGE APP. TRANS SEC	Construction Stockpile		5	Sep 5, 2023	SYSTEM	(\$9,865.40)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(REG/NO CURB)			10	Nov 16, 2023	SYSTEM	(\$4,932.70)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$14,798.10)	
			Construction	ction Stockpile - Total				(\$14,798.10)	
			Construction Stockpile STMI		2	Jul 17, 2023	SYSTEM	\$19,730.80 \$19,730.80	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total					
			Construction	Stockpile S	「MI - Tota			\$19,730.80	
	0250 -	Total						\$4,932.70	
	0260	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		5	Sep 5, 2023	SYSTEM	(\$9,844.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)			10	Nov 16, 2023	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$14,766.00)	
			Construction	Stockpile - 1				(\$14,766.00)	
			Construction Stockpile STMI		2	Jul 17, 2023	SYSTEM	\$19,688.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$19,688.00	
			Construction	Stockpile S	MI - Tota			\$19,688.00	
	0260 -	Total						\$4,922.00	
	0320	OPTIONAL CONCRETE WEARING	Material		8	Oct 16, 2023	SYSTEM	\$161,844.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		SURFACE			8	Oct 16, 2023	SYSTEM	(\$161,844.25)	
					9	Nov 2, 2023	SYSTEM	\$161,844.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Nov 2, 2023	SYSTEM	(\$161,844.25)	
					10	Nov 16, 2023	SYSTEM	\$161,844.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.



_					_	-	-		_
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3383B	0320	OPTIONAL CONCRETE	Material		10	Nov 16, 2023	SYSTEM	(\$161,844.25)	
	WEARING SURFACE			11	Dec 4, 2023	SYSTEM	\$161,844.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					11	Dec 4, 2023	SYSTEM	(\$161,844.25)	
					12	Dec 18, 2023	SYSTEM	\$161,844.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Dec 18, 2023	SYSTEM	(\$161,844.25)	
					13	Jan 16, 2024	SYSTEM	\$161,844.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Jan 16, 2024	SYSTEM	(\$161,844.25)	
					14	Feb 16, 2024	SYSTEM	\$161,844.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Feb 16, 2024	SYSTEM	(\$161,844.25)	
					15	Apr 16, 2024	SYSTEM	\$161,844.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Apr 15, 2024	SYSTEM	(\$161,844.25)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0320 -	0 - Total 0 SUBSTRUCTURE REPAIR (UNFORMED)						\$0.00	
	0350				12	Dec 18, 2023	SYSTEM	\$13,046.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					12	Dec 18, 2023	SYSTEM	(\$13,046.20)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
			Overrun	Overrun	12	Dec 18, 2023	SYSTEM	\$318.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					12	Dec 18, 2023	SYSTEM	(\$318.20)	
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0350 -	Total						\$0.00	
	0360	HALF-SOLE REPAIR	Material		4	Aug 16, 2023	SYSTEM	\$61,433.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Aug 16, 2023	SYSTEM	(\$61,433.60)	
					5	Sep 5, 2023	SYSTEM	\$156,827.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$156,827.80)	
				6	Sep 18, 2023	SYSTEM	\$232,295.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					6	Sep 15, 2023	SYSTEM	(\$232,295.80)	
					7	Oct 2, 2023	SYSTEM	\$250,831.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					7	Oct 2, 2023	SYSTEM	(\$250,831.80)	
					8	Oct 16, 2023	SYSTEM	\$253,215.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J4S3383B	0360	HALF-SOLE REPAIR	Material						Estimate Exception 9 on the current Payment Estimate.													
					8	Oct 16, 2023	SYSTEM	(\$253,215.00)														
					9	Nov 2, 2023	SYSTEM	\$253,215.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.													
					9	Nov 2, 2023	SYSTEM	(\$253,215.00)														
					10	Nov 16, 2023	SYSTEM	\$364,563.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.													
					10	Nov 16, 2023	SYSTEM	(\$364,563.40)														
					11	Dec 4, 2023	SYSTEM	\$437,317.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kennec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.													
					11	Dec 4, 2023	SYSTEM	(\$437,317.20)														
					12	Dec 18, 2023	SYSTEM	\$448,571.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.													
					12	Dec 18, 2023	SYSTEM	(\$448,571.20)														
					13	Jan 16, 2024	SYSTEM	\$448,571.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.													
					13	Jan 16, 2024	SYSTEM	(\$448,571.20)														
					14	Feb 16, 2024	SYSTEM	\$448,571.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.													
												14	Feb 16, 2024	SYSTEM	(\$448,571.20)							
					15	Apr 16, 2024	SYSTEM	\$448,571.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.													
					15	Apr 15, 2024	SYSTEM	(\$448,571.20)														
				- Total	1			\$0.00														
			Material - Tot	tal				\$0.00														
			Overrun	Overrun	6	Sep 15, 2023	SYSTEM	(\$33,695.80)														
					7	Oct 2, 2023	SYSTEM	\$18,536.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.													
					7	Oct 2, 2023	SYSTEM	(\$18,536.00)														
					8	Oct 16, 2023	SYSTEM	\$33,695.80	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',66.20000 - 66.20000, 'is applied (if non-zero).													
																		10	Nov 16, 2023	SYSTEM	\$66,663.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
																		10	Nov 16, 2023	SYSTEM	(\$66,663.40)	
																11	Dec 4, 2023	SYSTEM	(\$66,663.40)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
					11	Dec 4, 2023	SYSTEM	\$44,618.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kennec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.													
					11	Dec 4, 2023	SYSTEM	\$28,135.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kennec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.													
					11	Dec 4, 2023	SYSTEM	\$66,663.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kennec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.													
					11	Dec 4, 2023	SYSTEM	(\$72,753.80)														



t Li	ne Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	Description	Туре	Adjustment Type	Number	Date	By	Amount	i velitidirea
3B 03	60 HALF-SOLE REPAIR	Overrun	Overrun		Dec 18, 2023	SYSTEM	(\$139,417.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				12	Dec 18, 2023	SYSTEM	\$11,254.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				12	Dec 18, 2023	SYSTEM	\$139,417.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				12	Dec 18, 2023	SYSTEM	(\$11,254.00)	
			Overrun - T	otal			\$0.00	
		Overrun - To	tal				\$0.00	
03	60 - Total						\$0.00	
03	90 CLEANING AND COATING EXISTING BEARINGS	Material		14	Feb 16, 2024	SYSTEM	\$39,812.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				14	Feb 16, 2024	SYSTEM	(\$39,812.00)	
				15	Apr 16, 2024	SYSTEM	\$39,812.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				15	Apr 15, 2024	SYSTEM	(\$39,812.00)	
			- Total				\$0.00	
		Material - To	tal				\$0.00	
03	90 - Total			_			\$0.00	
04	00 STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		8	Oct 16, 2023	SYSTEM	(\$16,280.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				11	Dec 4, 2023 Dec 18,	SYSTEM SYSTEM	(\$8,140.00)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
					2023		x · · · · ·	·
			- Total				(\$32,560.00)	
		Construction	Stockpile - 1				(\$32,560.00)	
		Construction Stockpile STMI	- Total	3	Aug 2, 2023	SYSTEM	\$32,560.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		Construction		TML - Total			\$32,560.00	
04	00 - Total	Construction					\$0.00	
04		Material		10	Nov 16, 2023	SYSTEM	\$49,900.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				10	Nov 16, 2023	SYSTEM	(\$49,900.50)	
				11	Dec 4, 2023	SYSTEM	\$49,900.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				11	Dec 4, 2023	SYSTEM	(\$49,900.50)	
				12	Dec 18, 2023	SYSTEM	\$49,900.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				12	Dec 18, 2023	SYSTEM	(\$49,900.50)	
				13	Jan 16, 2024	SYSTEM	\$49,900.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				13	Jan 16, 2024	SYSTEM	(\$49,900.50)	
			- Total				\$0.00	
		Material - Tot	tal				\$0.00	
04	50 - Total						\$0.00	
04	70 HALF-SOLE REPAIR	Overrun	Overrun	8	Oct 16, 2023	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3383B	0470	HALF-SOLE REPAIR	Overrun	Overrun					Estimate Exception 14 on the current Payment Estimate.
					8	Oct 16, 2023	SYSTEM	(\$1,600.00)	
					9	Nov 2, 2023	SYSTEM	(\$1,600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					9	Nov 2, 2023	SYSTEM	\$832.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					9	Nov 2, 2023	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					9	Nov 2, 2023	SYSTEM	(\$832.00)	
					10	Nov 16, 2023	SYSTEM	(\$2,432.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					10	Nov 16, 2023	SYSTEM	\$2,432.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kennec2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					11	Dec 4, 2023	SYSTEM	(\$2,432.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					11	Dec 4, 2023	SYSTEM	\$2,432.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kennec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					12	Dec 18, 2023	SYSTEM	(\$2,432.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
	0470 - Total 0500 STRIP SEAL EXPANSION JOINT				12	Dec 18, 2023	SYSTEM	\$2,432.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			Overrun - T	otal			\$0.00		
			Overrun - To	tal				\$0.00	
							\$0.00		
		EXPANSION JOINT			8	Oct 16, 2023	SYSTEM	(\$9,990.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		SYSTEM			9	Nov 2, 2023	SYSTEM	(\$9,990.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$19,980.00)	
			Construction	n Stockpile - Total				(\$19,980.00)	
			Construction Stockpile STMI		3	Aug 2, 2023	SYSTEM	\$19,980.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			0.1111	- Total				\$19,980.00	
			Construction	Stockpile S	MI - Total			\$19,980.00	
		Total						\$0.00	
	0540	OPTIONAL CONCRETE WEARING SURFACE	Material		7	Oct 2, 2023	SYSTEM	\$122,223.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Oct 2, 2023	SYSTEM	(\$122,223.00)	
					8	Oct 16, 2023	SYSTEM	\$122,223.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Oct 16, 2023	SYSTEM	(\$122,223.00)	
					9	Nov 2, 2023	SYSTEM	\$122,223.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Nov 2, 2023	SYSTEM	(\$122,223.00)	
					10	Nov 16, 2023	SYSTEM	\$122,223.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					10	Nov 16, 2023	SYSTEM	(\$122,223.00)	
						Deck	OVOTEM	\$122,223.00	This adjustment offsets the original system-generated Material Payment
					11	Dec 4, 2023	SYSTEM	φ122,223.00	Estimate Item Adjustment (0024) due to user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																															
J4S3383B	0540	OPTIONAL	Material			2023																																		
		CONCRETE WEARING SURFACE			12	Dec 18, 2023	SYSTEM	\$122,223.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.																															
					12	Dec 18, 2023	SYSTEM	(\$122,223.00)																																
					13	Jan 16, 2024	SYSTEM	\$122,223.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.																															
					13	Jan 16, 2024	SYSTEM	(\$122,223.00)																																
					14	Feb 16, 2024	SYSTEM	\$122,223.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.																															
					14	Feb 16, 2024	SYSTEM	(\$122,223.00)																																
					15	Apr 16, 2024	SYSTEM	\$122,223.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.																															
					15	Apr 15, 2024	SYSTEM	(\$122,223.00)																																
				- Total				\$0.00																																
			Material - Tot	tal				\$0.00																																
	0540 -	Total						\$0.00																																
	0570	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		7	Oct 2, 2023	SYSTEM	\$17,161.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.																															
						7	Oct 2, 2023	SYSTEM	(\$17,161.76)																															
					8	Oct 16, 2023	SYSTEM	\$17,161.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.																															
					8	Oct 16, 2023	SYSTEM	(\$17,161.76)																																
						9	Nov 2, 2023	SYSTEM	\$17,161.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.																														
																					9	Nov 2, 2023	SYSTEM	(\$17,161.76)																
							10	Nov 16, 2023	SYSTEM	\$17,161.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kennec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.																													
																																							10	Nov 16, 2023
					11	Dec 4, 2023	SYSTEM	\$17,161.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.																															
					11	Dec 4, 2023	SYSTEM	(\$17,161.76)																																
					12	Dec 18, 2023	SYSTEM	\$17,161.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.																															
					12	Dec 18, 2023	SYSTEM	(\$17,161.76)																																
				- Total				\$0.00																																
			Material - Tot	tal				\$0.00																																
	0570 -	Total						\$0.00																																
	0580	HALF-SOLE REPAIR	Material		4	Aug 16, 2023	SYSTEM	\$106,913.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.																															
				4	4	4	Aug 16, 2023	SYSTEM	(\$106,913.00)																															
			5	5			5	Sep 5, 2023	SYSTEM	\$137,166.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.																													
					5	Sep 5, 2023	SYSTEM	(\$137,166.40)																																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J4S3383B	0580	HALF-SOLE REPAIR	Material		6	Sep 18, 2023	SYSTEM	\$137,166.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
				6	Sep 15, 2023	SYSTEM	(\$137,166.40)											
					7	Oct 2, 2023	SYSTEM	\$137,166.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.									
				7	Oct 2, 2023	SYSTEM	(\$137,166.40)											
					8	Oct 16, 2023	SYSTEM	\$137,166.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
					8	Oct 16, 2023	SYSTEM	(\$137,166.40)										
					9	Nov 2, 2023	SYSTEM	\$137,166.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
					9	Nov 2, 2023	SYSTEM	(\$137,166.40)										
					10	Nov 16, 2023	SYSTEM	\$137,166.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kennec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.									
					10	Nov 16, 2023	SYSTEM	(\$137,166.40)										
				- Total				\$0.00										
			Material - Tot	al				\$0.00										
			Overrun	Overrun	3	Aug 2, 2023	SYSTEM	\$27,142.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.									
					3	Aug 2, 2023	SYSTEM	\$10,261.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.									
					3	Aug 2, 2023	SYSTEM	(\$37,403.00)										
					4	Aug 16, 2023	SYSTEM	(\$37,403.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).									
					4	Aug 16, 2023	SYSTEM	\$27,671.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
								4	Aug 16, 2023	SYSTEM	\$21,978.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.						
					4	Aug 16, 2023	SYSTEM	\$37,403.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
					4	Aug 16, 2023	SYSTEM	(\$49,650.00)										
				Overrun - T	otal			\$0.00										
			Overrun - Tot	al				\$0.00										
	<b>0580</b> - 0590	FULL DEPTH	Material		4	Aug 16,	SYSTEM	\$0.00 \$27,135.00	This adjustment offsets the original system-generated Material Payment									
		REPAIR				2023			Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.									
													4		Aug 16, 2023	SYSTEM	(\$27,135.00)	
					5	Sep 5, 2023	SYSTEM	\$30,250.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
				5	Sep 5, 2023	SYSTEM	(\$30,250.50)											
					6	Sep 18, 2023	SYSTEM	\$30,250.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.									
					6	Sep 15, 2023	SYSTEM	(\$30,250.50)										
					7	Oct 2, 2023	SYSTEM	\$30,250.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J4S3383B	0590	FULL DEPTH	Material						Estimate Exception 17 on the current Payment Estimate.							
	REPAIR			7	Oct 2, 2023	SYSTEM	(\$30,250.50)									
					8	Oct 16, 2023	SYSTEM	\$30,250.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.							
					8	Oct 16, 2023	SYSTEM	(\$30,250.50)								
						9	Nov 2, 2023	SYSTEM	\$30,250.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.						
									9	Nov 2, 2023	SYSTEM	(\$30,250.50)				
					10	Nov 16, 2023	SYSTEM	\$30,250.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kennec2 overridding Payment Estimate Exception 15 on the current Payment Estimate.							
					10	Nov 16, 2023	SYSTEM	(\$30,250.50)								
					11	Dec 4, 2023	SYSTEM	\$30,250.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kennec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.							
												11	Dec 4, 2023	SYSTEM	(\$30,250.50)	
										12	Dec 18, 2023	SYSTEM	\$30,250.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.		
												12	Dec 18, 2023	SYSTEM	(\$30,250.50)	
							13	Jan 16, 2024	SYSTEM	\$30,250.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
					13	Jan 16, 2024	SYSTEM	(\$30,250.50)								
						14	Feb 16, 2024	SYSTEM	\$30,250.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.						
												14	Feb 16, 2024	SYSTEM	(\$30,250.50)	
					15	Apr 16, 2024	SYSTEM	\$30,250.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.							
					15	Apr 15, 2024	SYSTEM	(\$30,250.50)								
				- Total				\$0.00								
			Material - Tot	al				\$0.00								
	0590 - 0600	Total REINFORCING STEEL (EPOXY COATED)	Material		6	Sep 18, 2023	SYSTEM	<b>\$0.00</b> \$2,905.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.							
					6	Sep 15, 2023	SYSTEM	(\$2,905.50)								
				- Total				\$0.00								
			Material - Tot	al				\$0.00								
			Overrun	Overrun	11	Dec 4, 2023	SYSTEM	\$1,573.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.							
					11	Dec 4, 2023	SYSTEM	(\$1,573.00)								
					12	Dec 18, 2023	SYSTEM	(\$1,573.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).							
					12	Dec 18, 2023	SYSTEM	\$1,573.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kennec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.							
					13	Jan 16, 2024	SYSTEM	(\$1,573.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).							
				Overrun - T	otal			(\$1,573.00)								
			Overrun - To	tal				(\$1,573.00)								



Apr 18, 2024

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks			
J4S3383B	0600 -	Total		Туре				(\$1,573.00)				
04000000	0610	STRIP SEAL	Construction		6	Sep 15,	SYSTEM	(\$19,240.00)	Payment Estimate Item Adjustment generated Stockpile Transaction			
		EXPANSION JOINT SYSTEM	Stockpile			2023		· · · ·	, , , , ,			
			0	- Total	P-4-1			(\$19,240.00)				
			Construction Construction	Stockpile -	3	Aug 2,	SYSTEM	(\$19,240.00) \$19,240.00	Payment Estimate Item Adjustment generated Stockpile Transaction			
			Stockpile		0	2023	OTOTEM	¢10,210100				
				- Total				\$19,240.00				
			Construction	Stockpile S				\$19,240.00				
			Material		6	Sep 18, 2023	SYSTEM	\$42,546.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
					6	Sep 15, 2023	SYSTEM	(\$42,546.40)				
				- Total				\$0.00				
			Material - Tot	tal				\$0.00				
	0610 -	Total						\$0.00				
	0660	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		11	Dec 4, 2023	SYSTEM	(\$12,580.00)	Payment Estimate Item Adjustment generated Stockpile Transaction			
		0101EW		- Total				(\$12,580.00)				
			Construction	Stockpile - 1		A	000751	(\$12,580.00)				
			Construction Stockpile STMI	Tetal	3	Aug 2, 2023	SYSTEM	\$12,580.00	Payment Estimate Item Adjustment generated Stockpile Transaction			
			Construction	- Total	TMI Total			\$12,580.00 \$12,580.00				
	0660 -	· Total	Construction					\$0.00				
	0710	EPOXY POLYMER WEARING SURFACE	Material		4	Aug 16, 2023	SYSTEM	\$121,851.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					4	Aug 16, 2023	SYSTEM	(\$121,851.05)				
					5	Sep 5, 2023	SYSTEM	\$121,851.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
								5	Sep 5, 2023	SYSTEM	(\$121,851.05)	
					6	Sep 18, 2023	SYSTEM	\$121,851.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					6	Sep 15, 2023	SYSTEM	(\$121,851.05)				
					7	Oct 2, 2023	SYSTEM	\$121,851.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.			
					7	Oct 2, 2023	SYSTEM	(\$121,851.05)				
					8	Oct 16, 2023	SYSTEM	\$121,851.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					8	Oct 16, 2023	SYSTEM	(\$121,851.05)				
					9	Nov 2, 2023	SYSTEM	\$121,851.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment			
					9	Nov 2, 2023	SYSTEM	(\$121,851.05)	Estimate Exception 7 on the current Payment Estimate.			
					10	Nov 16, 2023	SYSTEM	\$121,851.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kennec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					10	Nov 16, 2023	SYSTEM	(\$121,851.05)				
				- Total				\$0.00				
			Material - Tot	tal				\$0.00				
	0710 -	Total						\$0.00				



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
4S3383B	0730	REINFORCING	Material	Туре	3	Aug 2,	SYSTEM	\$7,332.00	This adjustment offsets the original system-generated Material Payment
		STEEL (EPOXY COATED)			0	2023	OVOTEM	(\$7,222,00)	Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Aug 2, 2023	SYSTEM	(\$7,332.00)	
					4	Aug 16, 2023	SYSTEM	\$7,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Aug 16, 2023	SYSTEM	(\$7,332.00)	
					5	Sep 5, 2023	SYSTEM	\$7,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$7,332.00)	
					6	Sep 18, 2023	SYSTEM	\$7,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kennec2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					6	Sep 15, 2023	SYSTEM	(\$7,332.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0730 -	Total						\$0.00	
	0740	COATING - CONCRETE BENTS	Material		5	Sep 5, 2023	SYSTEM	\$41,848.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
		AND			5	Sep 5, 2023	SYSTEM	(\$41,848.40)	
					6	Sep 18, 2023	SYSTEM	\$41,848.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kennec2 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					6	Sep 15, 2023	SYSTEM	(\$41,848.40)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0740 -	Total						\$0.00	
	0750	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		4	Aug 16, 2023	SYSTEM	(\$29,970.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		0101Lill		- Total				(\$29,970.00)	
			Construction	Stockpile - 1				(\$29,970.00)	
			Construction Stockpile STMI		3	Aug 2, 2023	SYSTEM	\$29,970.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$29,970.00	
			Construction	Stockpile S	MI - Total			\$29,970.00	
	0750 -							\$0.00	
	0790	STRIP SEAL	Construction Stockpile		10	Nov 16, 2023	SYSTEM	(\$3,124.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$3,124.00)	
			Construction	Stockpile - 1				(\$3,124.00)	
			Construction Stockpile STMI		3	Aug 2, 2023	SYSTEM	\$3,124.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$3,124.00	
			Construction	Stockpile S	MI - Total			\$3,124.00	
	0790 -	Total						\$0.00	
S3383B ·								\$428.78	
verall - To	otal							\$428.78	



There are no contract adjustments to display for this contract.