

#### **Missouri Department of Transportation Contractor's Pay Estimate Summary**

Pay Estimate Created Date: October 16, 2023

Progress Estimate Number 8		Contract ID Prime Contractor	230217-C06 Comanche Constru	ction, Inc.			Original Contract Amou O23 Net Change Order Amou Current Contract Amou	unt \$197,072.10
Approval Date								
October 16, 2023			Generated and	Approved	(and should be co	nsidered Draft	) at the Project Office Level by	kennec2
October 16, 2023			Reviewed and Appr	oved (and	should be conside	ered Draft) at th	ne Resident Engineer Level by	sandis1
October 17, 2023				Reviewed	I and Approved at	the Central Off	ice Controllers Office Level by	ramses1
Original Completion Date		Current Co	mpletion Date	Actu	al Completion Da	te	% of Current Contract Amou	unt Complete
December	1, 2023	Decemb	per 1, 2023				64.61%	

Contract Informational Dates										
Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract								
March 8, 2023	March 8, 2023									
February 17, 2023	February 17, 2023									
May 1, 2023	May 1, 2023									
June 28, 2023	June 28, 2023									
	Original Completion Date  March 8, 2023  February 17, 2023  May 1, 2023	February 17, 2023 February 17, 2023 May 1, 2023								

Contract Total Pay For Estimate No. 8												
		This Estimate	Previous	To Date								
230217-C06												
	Total Posted Items Pay	\$344,787.40	\$1,733,841.00	\$2,078,628.40								
	Gross Item Adjustments	\$7,425.80	\$64,424.24	\$71,850.04								
	Incentive	\$0.00	\$0.00	\$0.00								
	Disincentive	\$0.00	\$0.00	\$0.00								
	Liquidated Damage	\$0.00	\$0.00	\$0.00								
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00								
			\$1,798,265.24	\$2,150,478.44								
<b>Contract Total Pa</b>	yable This Estimate:	\$352,213.20										

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
J4S3383B	0290	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	LF	\$1,063.300	22	\$23,392.60		
	0300	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	LS	\$5,190.500	0.5	\$2,595.25		
	0310	2169903	MISC.Remove and Replace Barrier Curb	LF	\$1,559.900	7.5	\$11,699.25		
	0320	5050001	OPTIONAL CONCRETE WEARING SURFACE	SQYD	\$168.500	960.5	\$161,844.25		
	0340	7034214	CLASS B-2 CONCRETE	CUYD	\$5,394.000	2	\$10,788.00		
	0360	7040104	HALF-SOLE REPAIR	SQFT	\$66.200	36	\$2,383.20		
	0380	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$6.500	630	\$4,095.00		
	0400	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	LF	\$818.200	44	\$36,000.80		
	0430	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	LF	\$1,063.300	27	\$28,709.10		
	0460	7034214	CLASS B-2 CONCRETE	CUYD	\$5,394.000	3.2	\$17,260.80		
	0470	7040104	HALF-SOLE REPAIR	SQFT	\$64.000	325	\$20,800.00		
	0480	7040106	FULL DEPTH REPAIR	SQFT	\$97.000	17	\$1,649.00		
	0490	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$6.500	227.5	\$1,478.75		
	0500	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	LF	\$818.200	27	\$22,091.40		
Project J4S3383B - Total									
Overall - Tota	al						\$344,787,40		

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Page 1 of 17 Revision 3/23/2023



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 16, 2023

Progress Estimate Number 8 Contract ID 230217-C06 Pay Period Start October 1, 2023 Original Contract Amount \$3,019,940.20 Pay Period End October 15, 2023 Net Change Order Amount Current Contract Amount \$3,217,012.30

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3383B	0200	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-967	\$3.30	(\$3,191.10)
	0200	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	967	\$3.30	\$3,191.10
	0210	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-140	\$3.30	(\$462.00)
	0210	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.	140	\$3.30	\$462.00
	0320	OPTIONAL CONCRETE WEARING SURFACE	Material			-960.5	\$168.50	(\$161,844.25)
	0320	OPTIONAL CONCRETE WEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	960.5	\$168.50	\$161,844.25
	0360	HALF-SOLE REPAIR	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',66.20000 - 66.20000, 'is applied (if non-zero).	509	\$66.20	\$33,695.80
	0360	HALF-SOLE REPAIR	Material			-3,825	\$66.20	(\$253,215.00)
	0360	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.	3,825	\$66.20	\$253,215.00
	0400	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$16,280.00)
	0470	HALF-SOLE REPAIR	Overrun			-25	\$64.00	(\$1,600.00)
	0470	HALF-SOLE REPAIR	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.	25	\$64.00	\$1,600.00
	0500	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$9,990.00)
	0540	OPTIONAL CONCRETE WEARING SURFACE	Material			-622	\$196.50	(\$122,223.00)
	0540	OPTIONAL CONCRETE WEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	622	\$196.50	\$122,223.00
	0570	SUPERSTRUCTURE REPAIR (UNFORMED)	Material			-30.8	\$557.20	(\$17,161.76)
	0570	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.	30.8	\$557.20	\$17,161.76

Revision 3/23/2023 Page 2 of 17



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 16, 2023

Progress Estimate Number	Contract ID	230217-C06	Pay Period Start	October 1, 2023	Original Contract Amount	\$3,019,940.20
8	<b>Prime Contractor</b>	Comanche Construction, Inc.	Pay Period End	October 15, 2023	<b>Net Change Order Amount</b>	\$197,072.10
ů .					Current Contract Amount	\$3,217,012.30

						Ψ0,2 ,0 .2.00		
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3383B	0580	HALF-SOLE REPAIR	Material			-2,072	\$66.20	(\$137,166.40)
	0580	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	2,072	\$66.20	\$137,166.40
	0590	FULL DEPTH REPAIR	Material			-301	\$100.50	(\$30,250.50)
	0590	FULL DEPTH REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.	301	\$100.50	\$30,250.50
	0710	EPOXY POLYMER WEARING SURFACE				-1,428.5	\$85.30	(\$121,851.05)
0710		EPOXY POLYMER WEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.	1,428.5	\$85.30	\$121,851.05
Total								\$7,425.80

Revision 3/23/2023 Page 3 of 17



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information										
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work						
J4S3383B		7 Bridge rehabilitations	Various	JACKSON	on I-35 NB to I-670 WB, on I-35 SB to I-670 EB, on I-35 SB over I-670, on Front St to I-29/I-35 SB, on I-670 EB to I-70 WB, on I-670 EB to US 71 SB, and on Route B over Route 7						

Totals by Job	o Numbers		SB, and on route B over rou	
J4S3383B		This Estimate	Previous	To Date
	Posted Item Pay	\$344,787.40	\$1,733,841.00	\$2,078,628.40
	Gross Item Adjustments	\$7,425.80	\$64,424.24	\$71,850.04
	Gross Item Pay	\$352,213.20	\$1,798,265.24	\$2,150,478.44
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	φυ.υυ	φυ.υυ	\$0.00

Revision 3/23/2023 Page 4 of 17



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 5050001, Project Item Line Number 0320, Material Set 505000196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with Materials and Contractor to clear exception.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 5050001, Project Item Line Number 0320, Material Set 505000196, Material 0505CCLOSL - Bridge Deck Concrete, Low Slump, Acceptance Action Generic 0505CCLOSL is insufficient.	Working with Materials and Contractor to clear exception.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 5050001, Project Item Line Number 0320, Material Set 505000196, Material 1005GECMLSBD - Bridge Wearing Surface Grade E LS/DO, Acceptance Action Generic 1005GECMLSBD is insufficient.	Working with Materials and Contractor to clear exception.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 5050001, Project Item Line Number 0540, Material Set 505000196, Material 0505CCLOSL - Bridge Deck Concrete, Low Slump, Acceptance Action Generic 0505CCLOSL is insufficient.	Working with Materials and Contractor to clear exception.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 6206000C, Project Item Line Number 0200, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with Contractor to clear exception.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 6206001C, Project Item Line Number 0210, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with Contractor to clear exception.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 6233000, Project Item Line Number 0710, Material Set 623300096, Material 1039AGPC - Aggregate for Epoxy Polymer Conc Overlay, Acceptance Action Generic 1039AGPC is insufficient.	Working with Materials and Contractor to clear exception.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 7040103, Project Item Line Number 0570, Material Set 704010396, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	Working with Materials and Contractor to clear exception.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 7040104, Project Item Line Number 0360, Material Set 704010496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Working with Materials and Contractor to clear exception.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 7040104, Project Item Line Number 0360, Material Set 704010496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Working with Materials and Contractor to clear exception.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 7040104, Project Item Line Number 0360, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with Materials and Contractor to clear exception.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 7040104, Project Item Line Number 0580, Material Set 704010496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Working with Materials and Contractor to clear exception.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3383B, Item 7040106, Project Item Line Number 0590, Material Set 704010696, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Working with Materials and Contractor to clear exception.	kennec2	Overridden
Estimate Exception Type: Item Overrun: Contract 230217-C06, Contract Project J4S3383B, Project Item Line Number 0470, Contract Line Item Number 0470, Item 7040104, Minor Item.	Item overridden for prompt payment of work to be paid on Change order.	kennec2	Overridden
Estimate Exception Type: Item Overrun: Contract 230217-C06, Contract Project J4S3383B, Project Item Line Number 0070, Contract Line Item Number 0070, Item 6161025, Minor Item.	To be paid on Traffic control change order.	kennec2	Acknowledged

Revision 3/23/2023 Page 5 of 17



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230217-C06	J4S3383B	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.27	\$8,019.30	\$2,165.21
		0001	0020	2153000	SHAPING SLOPES, CLASS III	15.00	0.00	15.00	100F	4.00	\$1,080.60	\$4,322.40
		0001	0030	6122009	IMPACT ATTENUATOR 45 MPH (SAND BARREL ARRAY)	1.00	0.00	1.00	EA	1.00	\$3,014.40	\$3,014.40
		0001	0040	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	1.00	0.00	1.00	EA	0.00	\$3,696.90	\$0.00
		0001	0050	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	2.00 0.00	0.00 2.00	EA	0.00	\$1,876.90	\$0.00
		0001	0060	6161005	CONSTRUCTION SIGNS	2,142.00	0.00	2,142.00	SQFT	912.00	\$6.80	\$6,201.60
		0001	0070	6161025	5 CHANNELIZER (TRIM LINE)	151.00	0.00	151.00	EA	170.00	\$29.60	\$5,032.00
		0001	0080	6161030	TYPE III MOVEABLE BARRICADE	35.00	0.00	35.00	EA	21.00	\$227.50	\$4,777.50
		0001	0090	6161040	FLASHING ARROW PANEL	10.00	0.00	10.00	EA	1.00	\$2,047.50	\$2,047.50
		0001	0100	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	16.00	0.00	16.00	EA	7.00	\$2,957.50	\$20,702.50
		0001	0110	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	658.00	0.00	658.00	LF	658.00	\$50.60	\$33,294.80
	0001	0120	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	470.00	0.00	470.00	LF	0.00	\$77.80	\$0.00	
		0001	0130	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	658.00	0.00	658.00	LF	0.00	\$12.80	\$0.00
		0001	0140	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	470.00	0.00	470.00	LF	0.00	\$41.20	\$0.00
		0001	0150	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$293,800.00	\$0.00
		0001	0151	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$279,680.00	\$279,680.00
		0001	0160	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	604.00	0.00	604.00	LF	0.00	\$28.40	\$0.00
		0001	0170	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	3,008.00	0.00	3,008.00	LF	379.00	\$4.30	\$1,629.70
		0001	0180	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,340.00	0.00	2,340.00	LF	356.00	\$4.30	\$1,530.80
		0001	0190	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	663.00	0.00	663.00	LF	0.00	\$9.10	\$0.00
		0001	0200	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,500.00	0.00	1,500.00	LF	967.00	\$3.30	\$3,191.10
		0001	0210	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	140.00	0.00	140.00	LF	140.00	\$3.30	\$462.00
		0001	0220	6207001	PAVEMENT MARKING REMOVAL	12,864.00	0.00	12,864.00	LF	0.00	\$0.50	\$0.00
		0001	0230	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	5,869.00	0.00	5,869.00	LF	1,654.00	\$1.60	\$2,646.40
		0010	0240	6061060	MGS GUARDRAIL	763.00	0.00	763.00	LF	50.00	\$29.60	\$1,480.00
		0010	0250	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	8.00	0.00	8.00	EA	4.00	\$4,151.90	\$16,607.60
		0010	0260	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8.00	0.00	8.00	EA	4.00	\$3,696.90	\$14,787.60
		0070	0270	2161502	REMOVAL OF CONCRETE WEARING SURFACE	17,290.00	0.00	17,290.00	SQFT	8,645.00	\$6.10	\$52,734.50
		0070	0290	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	88.00	0.00	88.00	LF	44.00	\$1,063.30	\$46,785.20
		0070	0300	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.50	\$5,190.50	\$2,595.25
		0070	0310	2169903	MISC.Remove and Replace Barrier Curb	15.00	0.00	15.00	LF	7.50	\$1,559.90	\$11,699.25
		0070	0320	5050001	OPTIONAL CONCRETE WEARING SURFACE	1,921.00	0.00	1,921.00	SQYD	960.50	\$168.50	\$161,844.25
		0070	0330	7031004	DIAMOND GRINDING	1,921.00	0.00	1,921.00	SQYD	0.00	\$7.40	\$0.00
		0070	0340	7034214	CLASS B-2 CONCRETE	7.00	0.00	7.00	CUYD	4.00	\$5,394.00	\$21,576.00
		0070	0350	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	40.00	0.00	40.00	SQFT	0.00	\$318.20	\$0.00
		0070	0360	7040104	HALF-SOLE REPAIR	3,000.00	1,500.00	4,500.00	SQFT	3,825.00	\$66.20	\$253,215.00
		0070	0370	7040106	FULL DEPTH REPAIR	350.00	0.00	350.00	SQFT	5.00	\$100.50	\$502.50
		0070	0380	7101000	REINFORCING STEEL (EPOXY COATED)	1,800.00	0.00	1,800.00	LB	630.00	\$6.50	\$4,095.00
		0070	0390	7123100	CLEANING AND COATING EXISTING BEARINGS	10.00	0.00	10.00	EA	0.00	\$3,981.20	\$0.00
		0070	0400	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	88.00	0.00	88.00	LF	44.00	\$818.20	\$36,000.80
		0071	0410	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	34.00	0.00	34.00	SQFT	0.00	\$312.80	\$0.00
		0071	0420	2161500	REMOVAL OF SEAL COAT OR POLYMER WEARING SURFACE	5,358.00	0.00	5,358.00	SQFT	4,539.00	\$2.30	\$10,439.70
		0071	0430	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	54.00	0.00	54.00	LF	27.00	\$1,063.30	\$28,709.10

Page 6 of 17 Revision 3/23/2023



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230217-C06	J4S3383B	0071	0440	2169903	MISC.Remove and Replace Barrier Curb	8.00	0.00	8.00	LF	0.00	\$1,559.90	\$0.00
		0071	0450	6233000	EPOXY POLYMER WEARING SURFACE	585.00	0.00	585.00	SQYD	0.00	\$85.30	\$0.00
		0071	0460	7034214	CLASS B-2 CONCRETE	6.40	0.00	6.40	CUYD	3.20	\$5,394.00	\$17,260.80
		0071	0470	7040104	HALF-SOLE REPAIR	300.00	0.00	300.00	SQFT	325.00	\$64.00	\$20,800.00
		0071	0480	7040106	FULL DEPTH REPAIR		0.00	850.00	SQFT	17.00	\$97.00	\$1,649.00
		0071	0490	7101000	REINFORCING STEEL (EPOXY COATED)	980.00	0.00	980.00	LB	227.50	\$6.50	\$1,478.75
		0071	0500	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	54.00	0.00	54.00	LF	27.00	\$818.20	\$22,091.40
		0072	0510	2161502	REMOVAL OF CONCRETE WEARING SURFACE	5,690.00	0.00	5,690.00	SQFT	5,690.00	\$7.20	\$40,968.00
		0072	0520	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	52.00	0.00	52.00	LF	52.00	\$1,063.30	\$55,291.60
		0072	0530	2169903	MISC.Remove and Replace Barrier Curb	8.00	0.00	8.00	LF	8.00	\$1,559.90	\$12,479.20
		0072	0540	5050001	OPTIONAL CONCRETE WEARING SURFACE	622.00	0.00	622.00	SQYD	622.00	\$196.50	\$122,223.00
		0072	0550	7031004	DIAMOND GRINDING	622.00	0.00	622.00	SQYD	28.70	\$7.40	\$212.38
		0072	0560	7034214	CLASS B-2 CONCRETE	7.00	0.00	7.00	CUYD	7.00	\$5,394.00	\$37,758.00
		0072	0570	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	50.00	0.00	50.00	SQFT	30.80	\$557.20	\$17,161.76
		0072	0580	7040104	HALF-SOLE REPAIR	300.00	1,772.00	2,072.00	SQFT	2,072.00	\$66.20	\$137,166.40
		0072	0590	7040106	FULL DEPTH REPAIR	850.00	-549.00	301.00	SQFT	301.00	\$100.50	\$30,250.50
		0072	0600	7101000	REINFORCING STEEL (EPOXY COATED)	510.00	0.00	510.00	LB	447.00	\$6.50	\$2,905.50
		0072	0610	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	52.00	0.00	52.00	LF	52.00	\$818.20	\$42,546.40
		0073	0620	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	33.00	0.00	33.00	SQFT	0.00	\$312.80	\$0.00
		0073	0630	2169903	MISC.Remove and Replace Barrier Curb	34.00	-29.00	5.00	LF	0.00	\$20.00	\$0.00
		0073	0640	7034214	CLASS B-2 CONCRETE	3.00	0.00	3.00	CUYD	0.00	\$5,394.00	\$0.00
		0073	0650	7101000	REINFORCING STEEL (EPOXY COATED)	290.00	0.00	290.00	LB	0.00	\$6.50	\$0.00
		0073	0660 717200	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	34.00	0.00	34.00	LF	0.00	\$818.20	\$0.00
		0074	0670	2161500	REMOVAL OF SEAL COAT OR POLYMER WEARING SURFACE	13,792.00	0.00	13,792.00	SQFT	12,857.00	\$1.70	\$21,856.90
		0074	0680	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	81.00	0.00	81.00	LF	81.00	\$796.30	\$64,500.30
		0074	0690	2169901	MISC.Removal of Loose Concrete from Prestressed Panels	1.00	0.00	1.00	LS	1.00	\$13,649.90	\$13,649.90
		0074	0700	2169903	MISC.Remove and Replace Barrier Curb	13.00	0.00	13.00	LF	13.00	\$3,412.50	\$44,362.50
		0074	0710	6233000	EPOXY POLYMER WEARING SURFACE	1,757.00	0.00	1,757.00	SQYD	1,428.50	\$85.30	\$121,851.05
		0074	0720	7034214	CLASS B-2 CONCRETE	8.80	0.00	8.80	CUYD	8.80	\$7,962.50	\$70,070.00
		0074	0730	7101000	REINFORCING STEEL (EPOXY COATED)	780.00	0.00	780.00	LB	780.00	\$9.40	\$7,332.00
		0074	0740	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$41,848.40	\$41,848.40
		0074	0750	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	81.00	0.00	81.00	LF	81.00	\$1,025.00	\$83,025.00
		0075	0760	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	59.00	0.00	59.00	LF	0.00	\$99.50	\$0.00
		0075	0770	7172054	OPEN CELL FOAM JOINT SEAL	59.00	0.00	59.00	LF	0.00	\$148.50	\$0.00
		0076	0780	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	71.00	0.00	71.00	LF	0.00	\$99.50	\$0.00
		0076	0790	7172002	STRIP SEAL	71.00	0.00	71.00	LF	0.00	\$202.90	\$0.00
		0073	5001	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	0.00	34.00	34.00	LF	0.00	\$1,065.30	\$0.00
		0001	5002	6189901		0.00	1.00	1.00	LS	1.00	\$14,120.00	\$14,120.00
	Project J45	S3383B - To	otal Value	Posted to I	Date as of Report Generated Date							\$2,078,628.40
230217-C06 Ove	rall - Total \	/alue Poste	ed to Date	as of Repo	rt Generated Date							\$2,078,628.40

Page 7 of 17 Revision 3/23/2023



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: J4S3383B

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0290	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	10/3/23	10/3/23	22.00	LF	N end of A0805	+		+		
0300	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	10/3/23	10/3/23	0.50	LS	1/2 of deck on A0805.	.188		.316		
0310	2169903	MISC. REMOVALS	10/9/23	10/16/23	7.50	LF	W side of A0805	.188		.316		
0320	5050001	OPTIONAL CONCRETE WEARING SURFACE	10/13/23	10/16/23	960.50	SQYD	Bridge deck of A0805.	.188		.316		
0340	7034214	CLASS B-2 CONCRETE	10/3/23	10/3/23	2.00	CUYD	N Joint on A0805.	+		+		
0360	7040104	HALF-SOLE REPAIR	10/9/23	10/16/23	36.00	SQFT	A0805 deck.	.188		.316		
0380	7101000	REINFORCING STEEL (EPOXY COATED)	10/3/23	10/3/23	630.00	LB	Steel for driving lane of bridge and barrier wall.	.188		.316		
0400	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	10/3/23	10/3/23	44.00	LF	1/2 of N and S joints on A0805.	+		+		
0430	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	10/11/23	10/16/23	27.00	LF	South Joint on A1111	.189		.245		
0460	7034214	CLASS B-2 CONCRETE	10/11/23	10/16/23	3.20	CUYD	South Joint on A1111	.189		.245		
0470	7040104	HALF-SOLE REPAIR	10/3/23	10/3/23	190.00	SQFT	Deck of A0805.	.189		.245		
			10/11/23	10/16/23	135.00	SQFT	B and C zones A1111	.189		.245		
0480	7040106	FULL DEPTH REPAIR	10/3/23	10/3/23	17.00	SQFT	Deck of A0805.	.189		.245		
0490	7101000	REINFORCING STEEL (EPOXY COATED)	10/11/23	10/16/23	227.50	LB	South Joint A1111	.189		.245		7 No. 5 E20 bars fit into the space required. Unable to fit 8th due to lack of space to place bar from existing steel reinforcement in end of bridge.
0500	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	10/11/23	10/16/23	27.00	LF	A1111 South Joint	.189		.245		

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023 Page 8 of 17



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3383B	0030	IMPACT ATTENUATOR 45 MPH (SAND	Material	,,	3	Aug 2, 2023	SYSTEM	\$3,014.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		BARREL ARRAY)			3	Aug 2, 2023	SYSTEM	(\$3,014.40)	
					4	Aug 16, 2023	SYSTEM	\$3,014.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Aug 16, 2023	SYSTEM	(\$3,014.40)	. ,
					5	Sep 5, 2023	SYSTEM	\$3,014.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$3,014.40)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0030 -	Total						\$0.00	
	0060	CONSTRUCTION SIGNS	Material		1	Jun 30, 2023	SYSTEM	\$1,251.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Jun 30, 2023	SYSTEM	(\$1,251.20)	
					2	Jul 17, 2023	SYSTEM	\$2,988.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$2,988.60)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0060 -	Total						\$0.00	
	0070	CHANNELIZER (TRIM LINE)	Material		2	Jul 17, 2023	SYSTEM	\$296.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$296.00)	
				- Total					
			Material - Tot	al				\$0.00	
			Overrun	Overrun	4	Aug 16, 2023	SYSTEM	(\$562.40)	
				Overrun - Total				(\$562.40)	
			Overrun - To	al				(\$562.40)	
	0070 -	Type III MOVEABLE BARRICADE	Material		1	Jun 30, 2023	SYSTEM	(\$562.40) \$3,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Jun 30, 2023	SYSTEM	(\$3,640.00)	
					2	Jul 17, 2023	SYSTEM	\$4,095.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$4,095.00)	
				- Total				\$0.00	
			Material - Tot					\$0.00	
	0080 -	Total						\$0.00	
	0100	CMS W/O COMMUNICATION INTERFACE, CONT	Material		1	Jun 30, 2023	SYSTEM	\$11,830.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		F/			1	Jun 30, 2023	SYSTEM	(\$11,830.00)	
					2	Jul 17, 2023	SYSTEM	\$11,830.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4S3383B	0100	CMS W/O COMMUNICATION	Material	Туро	2	Jul 17, 2023	SYSTEM	(\$11,830.00)		
		INTERFACE, CONT F/		- Total				\$0.00		
		17	Material - Tot					\$0.00		
	0100 -	Total						\$0.00		
	0110	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material		3	Aug 2, 2023	SYSTEM	\$33,294.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					3	Aug 2, 2023	SYSTEM	(\$33,294.80)		
					4	Aug 16, 2023	SYSTEM	\$33,294.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					4	Aug 16, 2023	SYSTEM	(\$33,294.80)		
					5	Sep 5, 2023	SYSTEM	\$33,294.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					5	Sep 5, 2023	SYSTEM	(\$33,294.80)		
					6	Sep 18, 2023	SYSTEM	\$33,294.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
						6	Sep 15, 2023	SYSTEM	(\$33,294.80)	
				- Total				\$0.00		
			Material - Tot	al				\$0.00		
	0110 -	Total						\$0.00		
	0170	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	Material		7	Oct 2, 2023	SYSTEM	\$1,629.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					7	Oct 2, 2023	SYSTEM	(\$1,629.70)		
				- Total				\$0.00		
			Material - Tot	al				\$0.00		
	0170 -	Total						\$0.00		
	0180	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material		7	Oct 2, 2023	SYSTEM	\$1,530.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					7	Oct 2, 2023	SYSTEM	(\$1,530.80)		
				- Total						
			Material - Tot	al				\$0.00		
	0180 -							\$0.00		
	0200	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		6	Sep 18, 2023	SYSTEM	\$3,191.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					6	Sep 15, 2023	SYSTEM	(\$3,191.10)		
					7	Oct 2, 2023	SYSTEM	\$3,191.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					7	Oct 2, 2023	SYSTEM	(\$3,191.10)		
					8	Oct 16, 2023	SYSTEM	\$3,191.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					8	Oct 16, 2023	SYSTEM	(\$3,191.10)		
				- Total				\$0.00		
			Material - Tot	al				\$0.00		
	0200 -	Total						\$0.00		
	0210	4 IN. YELLOW WATERBORNE	Material		6	Sep 18, 2023	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3383B	0210	PAVEMENT	Material						Estimate Exception 5 on the current Payment Estimate.
		MARKING			6	Sep 15, 2023	SYSTEM	(\$462.00)	
					7	Oct 2, 2023	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					7	Oct 2, 2023	SYSTEM	(\$462.00)	
					8	Oct 16, 2023	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					8	Oct 16, 2023	SYSTEM	(\$462.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0210 -	Total						\$0.00	
	0240	MGS GUARDRAIL	Construction Stockpile		5	Sep 5, 2023	SYSTEM	(\$752.39)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$752.39)	
			Construction	Stockpile - 1	otal			(\$752.39)	
			Construction Stockpile		2	Jul 17, 2023	SYSTEM	\$11,481.43	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$11,481.43	
			Construction	Stockpile S1	MI - Total			\$11,481.43	
			Material		5	Sep 5, 2023	SYSTEM	\$1,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$1,480.00)	
					6	Sep 18, 2023	SYSTEM	\$1,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Sep 15, 2023	SYSTEM	(\$1,480.00)	
					7	Oct 2, 2023	SYSTEM	\$1,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Oct 2, 2023	SYSTEM	(\$1,480.00)	·
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0240 -	Total						\$10,729.04	
	0250	MGS BRIDGE APP. TRANS SEC	Construction Stockpile		5	Sep 5, 2023	SYSTEM	(\$9,865.40)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(REG/NO CURB)		- Total				(\$9,865.40)	
			Construction	Stockpile - 1	otal			(\$9,865.40)	
			Construction Stockpile		2	Jul 17, 2023	SYSTEM	\$19,730.80	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$19,730.80	
			Construction	Stockpile S1	MI - Total			\$19,730.80	
	0250 -	Total						\$9,865.40	
	0260	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		5	Sep 5, 2023	SYSTEM	(\$9,844.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)		- Total				(\$9,844.00)	
			Construction	Stockpile - 1	otal			(\$9,844.00)	
			Construction Stockpile STMI		2	Jul 17, 2023	SYSTEM	\$19,688.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			JIWII	- Total				\$19,688.00	
			Construction	Stockpile S1	MI - Total			\$19,688.00	
	0260 -	Total						\$9,844.00	
	0320	OPTIONAL	Material		8	Oct 16,	SYSTEM	\$161,844.25	This adjustment offsets the original system-generated Material Payment



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3383B	0320	CONCRETE WEARING SURFACE	Material			2023			Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		SURFACE			8	Oct 16, 2023	SYSTEM	(\$161,844.25)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0320 -	- Total						\$0.00	
	0360	HALF-SOLE REPAIR	Material		4	Aug 16, 2023	SYSTEM	\$61,433.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Aug 16, 2023	SYSTEM	(\$61,433.60)	
					5	Sep 5, 2023	SYSTEM	\$156,827.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$156,827.80)	
					6	Sep 18, 2023	SYSTEM	\$232,295.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					6	Sep 15, 2023	SYSTEM	(\$232,295.80)	
					7	Oct 2, 2023	SYSTEM	\$250,831.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					7	Oct 2, 2023	SYSTEM	(\$250,831.80)	
					8	Oct 16, 2023	SYSTEM	\$253,215.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					8	Oct 16, 2023	SYSTEM	(\$253,215.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
					6	Sep 15,	OVICEELI		
			Overrun	Overrun		2023	SYSTEM	(\$33,695.80)	
			Overrun	Overrun	7		SYSTEM	(\$33,695.80) \$18,536.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
			Overrun	Overrun		2023 Oct 2,			Estimate Item Adjustment (0001) due to user kennec2 overridding Payment
			Overrun	Overrun	7	2023 Oct 2, 2023 Oct 2,	SYSTEM	\$18,536.00	Estimate Item Adjustment (0001) due to user kennec2 overridding Payment
			Overrun	Overrun - T	7 7 8	2023 Oct 2, 2023 Oct 2, 2023 Oct 16,	SYSTEM	\$18,536.00 (\$18,536.00)	Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',66.20000 - 66.20000, 'is
			Overrun - To	Overrun - T	7 7 8	2023 Oct 2, 2023 Oct 2, 2023 Oct 16,	SYSTEM	\$18,536.00 (\$18,536.00) \$33,695.80	Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',66.20000 - 66.20000, 'is
	0360 -	- Total		Overrun - T	7 7 8	2023 Oct 2, 2023 Oct 2, 2023 Oct 16,	SYSTEM	\$18,536.00 (\$18,536.00) \$33,695.80	Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',66.20000 - 66.20000, 'is
	0360 - 0400	STRIP SEAL EXPANSION JOINT		Overrun - T	7 7 8	2023 Oct 2, 2023 Oct 2, 2023 Oct 16,	SYSTEM	\$18,536.00 (\$18,536.00) \$33,695.80 \$0.00	Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',66.20000 - 66.20000, 'is applied (if non-zero).
		STRIP SEAL	Overrun - To	Overrun - T tal - Total	7 7 8 8 ootal 8	2023 Oct 2, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16,	SYSTEM SYSTEM SYSTEM	\$18,536.00 (\$18,536.00) \$33,695.80 \$0.00 \$0.00 (\$16,280.00) (\$16,280.00)	Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',66.20000 - 66.20000, 'is applied (if non-zero).
		STRIP SEAL EXPANSION JOINT	Overrun - To	Overrun - T tal	7 7 8 otal	2023 Oct 2, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16,	SYSTEM SYSTEM SYSTEM	\$18,536.00 (\$18,536.00) \$33,695.80 \$0.00 \$0.00 (\$16,280.00)	Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',66.20000 - 66.20000, 'is applied (if non-zero).  Payment Estimate Item Adjustment generated Stockpile Transaction
		STRIP SEAL EXPANSION JOINT	Overrun - To	Overrun - T tal - Total 1 Stockpile - 1	7 7 8 8 ootal 8	2023 Oct 2, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16,	SYSTEM SYSTEM SYSTEM	\$18,536.00 (\$18,536.00) \$33,695.80 \$0.00 \$0.00 (\$16,280.00) (\$16,280.00) (\$16,280.00) \$32,560.00	Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',66.20000 - 66.20000, 'is applied (if non-zero).
		STRIP SEAL EXPANSION JOINT	Overrun - To	Overrun - T tal - Total - Stockpile - 1	7  8  otal  8  Fotal  3	2023 Oct 2, 2023 Oct 12, 2023 Oct 16, 2023  Oct 16, 2023  Aug 2, 2023	SYSTEM SYSTEM SYSTEM SYSTEM	\$18,536.00 (\$18,536.00) \$33,695.80 \$0.00 \$0.00 (\$16,280.00) (\$16,280.00) \$32,560.00	Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',66.20000 - 66.20000, 'is applied (if non-zero).  Payment Estimate Item Adjustment generated Stockpile Transaction
	0400	STRIP SEAL EXPANSION JOINT SYSTEM	Overrun - To	Overrun - T tal - Total 1 Stockpile - 1	7  8  otal  8  Fotal  3	2023 Oct 2, 2023 Oct 12, 2023 Oct 16, 2023  Oct 16, 2023  Aug 2, 2023	SYSTEM SYSTEM SYSTEM SYSTEM	\$18,536.00 (\$18,536.00) \$33,695.80 \$0.00 \$0.00 (\$16,280.00) (\$16,280.00) (\$16,280.00) \$32,560.00 \$32,560.00	Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',66.20000 - 66.20000, 'is applied (if non-zero).  Payment Estimate Item Adjustment generated Stockpile Transaction
	0400	STRIP SEAL EXPANSION JOINT	Overrun - To	Overrun - T tal - Total - Stockpile - 1	7 7 8 otal 8 Fotal 3	2023 Oct 2, 2023 Oct 12, 2023 Oct 16, 2023  Oct 16, 2023  Aug 2, 2023	SYSTEM SYSTEM SYSTEM SYSTEM	\$18,536.00 (\$18,536.00) \$33,695.80 \$0.00 \$0.00 (\$16,280.00) (\$16,280.00) \$32,560.00	Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',66.20000 - 66.20000, 'is applied (if non-zero).  Payment Estimate Item Adjustment generated Stockpile Transaction
	0400	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile Construction Stockpile STMI Construction	Overrun - T tal - Total 1 Stockpile - T - Total	7 7 8 otal 8 Fotal 3	2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Oct 16, 2023 Oct 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM	\$18,536.00 (\$18,536.00) \$33,695.80 \$0.00 \$0.00 \$0.00 (\$16,280.00) (\$16,280.00) \$32,560.00 \$32,560.00 \$16,280.00	Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',66.20000 - 66.20000, 'is applied (if non-zero).  Payment Estimate Item Adjustment generated Stockpile Transaction  Payment Estimate Item Adjustment generated Stockpile Transaction  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment
	0400	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile Construction Stockpile STMI Construction	Overrun - T tal - Total 1 Stockpile - T - Total	7 7 8 otal 8 Fotal 3 TMI - Total 8	2023 Oct 2, 2023 Oct 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$18,536.00 (\$18,536.00) \$33,695.80 \$0.00 \$0.00 \$16,280.00) (\$16,280.00) \$32,560.00 \$32,560.00 \$16,280.00 \$16,280.00	Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',66.20000 - 66.20000, 'is applied (if non-zero).  Payment Estimate Item Adjustment generated Stockpile Transaction  Payment Estimate Item Adjustment generated Stockpile Transaction  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment
	0400	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile Construction Stockpile STMI Construction	Overrun - T tal  - Total  - Stockpile - 1  - Total  Overrun  Overrun	7 7 8 otal 8 Fotal 3 TMI - Total 8	2023 Oct 2, 2023 Oct 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$18,536.00 (\$18,536.00) \$33,695.80 \$0.00 \$0.00 \$16,280.00) (\$16,280.00) \$32,560.00 \$32,560.00 \$16,280.00 \$16,280.00 \$16,280.00	Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',66.20000 - 66.20000, 'is applied (if non-zero).  Payment Estimate Item Adjustment generated Stockpile Transaction  Payment Estimate Item Adjustment generated Stockpile Transaction  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3383B	0500	STRIP SEAL EXPANSION JOINT	Construction Stockpile		8	Oct 16, 2023	SYSTEM	(\$9,990.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		SYSTEM		- Total				(\$9,990.00)	
			Construction	Stockpile - 1	Γotal			(\$9,990.00)	
			Construction Stockpile STMI		3	Aug 2, 2023	SYSTEM	\$19,980.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$19,980.00	
			Construction	Stockpile S1	TMI - Total			\$19,980.00	
	0500 -	Total						\$9,990.00	
	0540	OPTIONAL CONCRETE WEARING SURFACE	Material		7	Oct 2, 2023	SYSTEM	\$122,223.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		SON ACE			7	Oct 2, 2023	SYSTEM	(\$122,223.00)	
					8	Oct 16, 2023	SYSTEM	\$122,223.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Oct 16, 2023	SYSTEM	(\$122,223.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0540 -	· Total						\$0.00	
		SUPERSTRUCTURE REPAIR (UNFORMED)	Material		7	Oct 2, 2023	SYSTEM	\$17,161.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					7	Oct 2, 2023	SYSTEM	(\$17,161.76)	
							8	Oct 16, 2023	SYSTEM
					8	Oct 16, 2023	SYSTEM	(\$17,161.76)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0570 -	· Total						\$0.00	
	0580	HALF-SOLE REPAIR	AIR Material		4	Aug 16, 2023	SYSTEM	\$106,913.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Aug 16, 2023	SYSTEM	(\$106,913.00)	
					5	Sep 5, 2023	SYSTEM	\$137,166.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$137,166.40)	
					6	Sep 18, 2023	SYSTEM	\$137,166.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Sep 15, 2023	SYSTEM	(\$137,166.40)	
					7	Oct 2, 2023	SYSTEM	\$137,166.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					7	Oct 2, 2023	SYSTEM	(\$137,166.40)	
					8	Oct 16, 2023	SYSTEM	\$137,166.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					8	Oct 16, 2023	SYSTEM	(\$137,166.40)	
				- Total				\$0.00	
			Material - Tot					\$0.00	
			Overrun	Overrun	3	Aug 2, 2023	SYSTEM	\$27,142.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
S3383B	0580	HALF-SOLE REPAIR	Overrun	Overrun	3	Aug 2, 2023	SYSTEM	\$10,261.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.								
					3	Aug 2, 2023	SYSTEM	(\$37,403.00)									
					4	Aug 16, 2023	SYSTEM	(\$37,403.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
							4	Aug 16, 2023	SYSTEM	\$27,671.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.						
					4	Aug 16, 2023	SYSTEM	\$21,978.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.								
					4	Aug 16, 2023	SYSTEM	\$37,403.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.								
					4	Aug 16, 2023	SYSTEM	(\$49,650.00)	Estimate Exception 11 on the current Payment Estimate.								
						2023											
				Overrun - T	otal			\$0.00									
			Overrun - To	tal				\$0.00									
		- Total						\$0.00									
	0590	FULL DEPTH REPAIR	Material		4	Aug 16, 2023	SYSTEM	\$27,135.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.								
													4	Aug 16, 2023	SYSTEM	(\$27,135.00)	
					5	Sep 5, 2023	SYSTEM	\$30,250.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.								
					5	Sep 5, 2023	SYSTEM	(\$30,250.50)									
					6	Sep 18, 2023	SYSTEM	\$30,250.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.								
					6	Sep 15, 2023	SYSTEM	(\$30,250.50)									
					7	Oct 2, 2023	SYSTEM	\$30,250.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 17 on the current Payment Estimate.								
					7	Oct 2, 2023	SYSTEM	(\$30,250.50)									
					8	Oct 16, 2023	SYSTEM	\$30,250.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.								
					8	Oct 16, 2023	SYSTEM	(\$30,250.50)									
				- Total				\$0.00									
			Material - Tot	tal				\$0.00									
	0590 -	- Total						\$0.00									
	0600	REINFORCING STEEL (EPOXY COATED)	Material		6	Sep 18, 2023	SYSTEM	\$2,905.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.								
		,			6	Sep 15, 2023	SYSTEM	(\$2,905.50)	-								
				- Total				\$0.00									
			Material - Tot	tal				\$0.00									
	0600 -	- Total						\$0.00									
	0610	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		6	Sep 15, 2023	SYSTEM	(\$19,240.00)	Payment Estimate Item Adjustment generated Stockpile Transaction								
		STSTEM		- Total				(\$19,240.00)									
			Construction	Stockpile -	Total			(\$19,240.00)									
			Construction Stockpile		3	Aug 2, 2023	SYSTEM	\$19,240.00	Payment Estimate Item Adjustment generated Stockpile Transaction								
			STMI	- Total				\$19,240.00									
			Construction	Stockpile S	TMI - Total			\$19,240.00									



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks			
rioject	Line	Description	Туре	Adjustment Type		Date	By	Amount	Rolland			
J4S3383B	0610	STRIP SEAL EXPANSION JOINT SYSTEM	Material		6	Sep 18, 2023	SYSTEM	\$42,546.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
					6	Sep 15, 2023	SYSTEM	(\$42,546.40)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	0610 -	Total						\$0.00				
	0660	STRIP SEAL EXPANSION JOINT	Construction Stockpile		3	Aug 2, 2023	SYSTEM	\$12,580.00	Payment Estimate Item Adjustment generated Stockpile Transaction			
		SYSTEM	STMI	- Total				\$12,580.00				
			Construction	Stockpile S	TMI - Total			\$12,580.00				
	0660 -	Total										
	0710	EPOXY POLYMER WEARING SURFACE	Material		4	Aug 16, 2023	SYSTEM	\$121,851.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					4	Aug 16, 2023	SYSTEM	(\$121,851.05)				
					5	Sep 5, 2023	SYSTEM	\$121,851.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
					5	Sep 5, 2023	SYSTEM	(\$121,851.05)				
					6	Sep 18, 2023	SYSTEM	\$121,851.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					6	Sep 15, 2023	SYSTEM	(\$121,851.05)				
					7	Oct 2, 2023	SYSTEM	\$121,851.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.			
					7	Oct 2, 2023	SYSTEM	(\$121,851.05)				
						8	Oct 16, 2023	SYSTEM	\$121,851.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
					8	Oct 16, 2023	SYSTEM	(\$121,851.05)				
				- Total								
			Material - To	laterial - Total								
	0710 -	Total						\$0.00				
	0730	REINFORCING STEEL (EPOXY COATED)	STEEL (EPOXY	Material		3	Aug 2, 2023	SYSTEM	\$7,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					3	Aug 2, 2023	SYSTEM	(\$7,332.00)				
								4	Aug 16, 2023	SYSTEM	\$7,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Aug 16, 2023	SYSTEM	(\$7,332.00)				
					5	Sep 5, 2023	SYSTEM	\$7,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.			
					5	Sep 5, 2023	SYSTEM	(\$7,332.00)				
					6	Sep 18, 2023	SYSTEM	\$7,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kennec2 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
					6	Sep 15, 2023	SYSTEM	(\$7,332.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	0730 -	Total						\$0.00				
	0740	PROTECTIVE	Material		5	Sep 5,	SYSTEM	\$41,848.40	This adjustment offsets the original system-generated Material Payment			





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3383B	0740	COATING - CONCRETE BENTS AND	Material			2023			Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$41,848.40)	
					6	Sep 18, 2023	SYSTEM	\$41,848.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kennec2 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					6	Sep 15, 2023	SYSTEM	(\$41,848.40)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0740 -	Total						\$0.00	
	0750	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		4	Aug 16, 2023	SYSTEM	(\$29,970.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$29,970.00)	
			Construction	Stockpile -	Γotal			(\$29,970.00)	
			Construction Stockpile		3	Aug 2, 2023	SYSTEM	\$29,970.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$29,970.00	
			Construction	Stockpile S	kpile STMI - Total				
	0750 -	Total						\$0.00	
	0790	STRIP SEAL	Construction Stockpile STMI		3	Aug 2, 2023	SYSTEM	\$3,124.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			SIIVII	- Total				\$3,124.00	
			Construction	Stockpile S	ГМI - Total			\$3,124.00	
	0790 -	Total						\$3,124.00	
J4S3383B	- Total							\$71,850.04	
Overall - T	otal							\$71,850.04	

## MoDOT

## Contract Adjustments for Contract - 230217-C06

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 17 of 17