

Pay Estimate Created Date: November 3, 2023

| Progress Estimate<br>Number | Contract ID         | 230217-F02                     | Pay Period<br>Start | October 16, 2023    | Original Contract Amount                              | \$13,077,700.00                  |
|-----------------------------|---------------------|--------------------------------|---------------------|---------------------|---|----------------------------------|
| 10                          | Prime<br>Contractor | Pace Construction Company, LLC | Pay Period End      | November 1,<br>2023 | Net Change Order<br>Amount<br>Current Contract Amount | (\$26,843.31)<br>\$13,050,856.69 |

| Approval Date    |  | By User |
|------------------|--|---------|
| November 3, 2023 | Generated and Approved (and should be considered Draft) at the Project Office Level by   | wilesd  |
| November 3, 2023 | Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by | amburs1 |
| November 6, 2023 | Reviewed and Approved at the Central Office Controllers Office Level by                  | ramses1 |

| Original Completion Date | Current Completion Date | Actual Completion Date | % of Current Contract Amount Complete |
|--------------------------|-------------------------|------------------------|---------------------------------------|
| July 31, 2024            | July 31, 2024           |                        | 17.73%                                |

|                        | Contract Informational Date | tes                            | Milestones                       |
|------------------------|-----------------------------|--------------------------------|----------------------------------|
| Date Description       | Original Completion Date    | <b>Current Completion Date</b> | No Milestones Exist for Contract |
| Acceptance Date        |                             |                                |                                  |
| Awarded Date           | March 8, 2023               | March 8, 2023                  |                                  |
| Letting Date           | February 17, 2023           | February 17, 2023              |                                  |
| Notice to Proceed Date | April 10, 2023              | April 10, 2023                 |                                  |
| Open to Traffic Date   |                             |                                |                                  |
| Work Began Date        | July 5, 2023                | July 5, 2023                   |                                  |

| Contract Total Pa | ay For Estimate No. 10     |               |                |                |
|-------------------|----------------------------|---------------|----------------|----------------|
|                   |                            | This Estimate | Previous       | To Date        |
| 230217-F02        |                            |               |                |                |
|                   | Total Posted Items Pay     | \$512,242.00  | \$1,801,247.41 | \$2,313,489.41 |
|                   | Gross Item Adjustments     | \$0.00        | \$936,934.63   | \$936,934.63   |
|                   | Incentive                  | \$0.00        | \$0.00         | \$0.00         |
|                   | Disincentive               | \$0.00        | \$0.00         | \$0.00         |
|                   | Liquidated Damage          | \$0.00        | \$0.00         | \$0.00         |
|                   | Other Contract Adjustments | \$0.00        | \$0.00         | \$0.00         |
|                   | •                          |               | \$2,738,182.04 | \$3,250,424.04 |
| Contract Total Pa | avable This Estimate:      | \$512.242.00  |                |                |

## Items Paid This Estimate Period

| Project<br>Number | Line<br>Number | Item<br>Code | Item Description   | Unit | Unit Price  | Current<br>Installed Qty | Current<br>Installed<br>Amount |
|-------------------|----------------|--------------|--|------|-------------|--------------------------|--------------------------------|
| J6I3568           | 0030           | 2063500      | CULVERT CLEANOUT   | EA   | \$6,750.000 | 0.25                     | \$1,687.50                     |
|                   | 0350           | 6131010      | FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR                        | SQYD | \$480.000   | 141.3                    | \$67,824.00                    |
|                   | 0380           | 6131014      | FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)                       | LF   | \$9.750     | 446                      | \$4,348.50                     |
|                   | 0390           | 6131015      | DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR               | EA   | \$29.000    | 48                       | \$1,392.00                     |
|                   | 0400           | 6131018      | TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) | EA   | \$15.000    | 106                      | \$1,590.00                     |
|                   | 0430           | 6149902      | MISC.GRATED INLET REPAIR/REPLACEMENT   | EA   | \$4,000.000 | 2                        | \$8,000.00                     |
|                   | 0470           | 6173000      | CONCRETE TRAFFIC BARRIER, TYPE C   | LF   | \$100.000   | 4,274                    | \$427,400.00                   |

 Project J6l3568 - Total
 \$512,242.00

 Overall - Total
 \$512,242.00

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

| Line Item         | Adjust      | ments This Estimate  |                    |                                  |          |                        |                                       |                      |
|-------------------|-------------|----------------------|--------------------|----------------------------------|----------|------------------------|---------------------------------------|----------------------|
| Project<br>Number | Line<br>No. | Item Description     | Adjustment<br>Type | Other Item<br>Adjustment<br>Type | Comments | Adjustment<br>Quantity | Line Item<br>Adjustment<br>Unit Price | Adjustment<br>amount |
| J6I3568           | 0050        | TYPE 5 AGGREGATE FOR | Material           |                                  |          | -99.8                  | \$22.00                               | (\$2,195.60)         |

Revision 3/23/2023 Page 1 of 19



Pay Estimate Created Date: November 3, 2023

Progress Estimate Number 10 Contract ID 230217-F02 Pay Period Start October 16, 2023 Original Contract Amount \$13,077,700.00
Prime Contractor Place Construction Company, LLC Pay Period End November 1, 2023 Period End November 1, 2023 Pay Period End Current Contract Amount \$13,050,856.69

| Project<br>Number | Line<br>No. | Item Description  | Adjustment<br>Type | Other Item<br>Adjustment<br>Type | Comments   | Adjustment<br>Quantity | Line Item<br>Adjustment<br>Unit Price | Adjustment<br>amount |
|-------------------|-------------|---|--------------------|----------------------------------|--|------------------------|---------------------------------------|----------------------|
| J6I3568           |             | BASE (4 IN. THICK)  |                    |                                  |  |                        |                                       |                      |
|                   | 0050        | TYPE 5 AGGREGATE FOR<br>BASE (4 IN. THICK)  | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0011) due to user wilesd<br>overridding Payment Estimate Exception 1 on<br>the current Payment Estimate. | 99.8                   | \$22.00                               | \$2,195.60           |
|                   | 0060        | TYPE 5 AGGREGATE FOR<br>BASE (6 IN. THICK)  | Material           |                                  |  | -96                    | \$23.00                               | (\$2,208.00)         |
|                   | 0060        | TYPE 5 AGGREGATE FOR<br>BASE (6 IN. THICK)  | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0012) due to user wilesd<br>overridding Payment Estimate Exception 2 on<br>the current Payment Estimate. | 96                     | \$23.00                               | \$2,208.00           |
|                   | 0170        | CONCRETE PAVEMENT (7<br>IN. NON-REINFORCED, 15<br>FT. JOINTS)                             | Material           |                                  |  | -95.5                  | \$128.00                              | (\$12,224.00)        |
|                   | 0170        | CONCRETE PAVEMENT (7<br>IN. NON-REINFORCED, 15<br>FT. JOINTS)                             | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0013) due to user wilesd<br>overridding Payment Estimate Exception 3 on<br>the current Payment Estimate. | 95.5                   | \$128.00                              | \$12,224.00          |
|                   | 0220        | CONCRETE CURB RAMP  | Material           |                                  |  | -6                     | \$1,854.00                            | (\$11,124.00)        |
|                   | 0220        | CONCRETE CURB RAMP  | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0014) due to user wilesd<br>overridding Payment Estimate Exception 5 on<br>the current Payment Estimate. | 6                      | \$1,854.00                            | \$11,124.00          |
|                   | 0240        | 6 IN. CONCRETE MEDIAN<br>STRIP  | Material           |                                  |  | -126.4                 | \$158.00                              | (\$19,971.20)        |
|                   | 0240        | 6 IN. CONCRETE MEDIAN<br>STRIP  | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0015) due to user wilesd<br>overridding Payment Estimate Exception 7 on<br>the current Payment Estimate. | 126.4                  | \$158.00                              | \$19,971.20          |
|                   | 0250        | CONCRETE SIDEWALK, 4<br>IN.   | Material           |                                  |  | -99.8                  | \$100.00                              | (\$9,980.00)         |
|                   | 0250        | CONCRETE SIDEWALK, 4<br>IN.   | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0016) due to user wilesd<br>overridding Payment Estimate Exception 8 on<br>the current Payment Estimate. | 99.8                   | \$100.00                              | \$9,980.00           |
|                   | 0350        | FURNISHING AND PLACING<br>CONCRETE MATERIAL FOR<br>FULL DEPTH PAVEMENT<br>REPAIR          | Material           |                                  |  | -141.3                 | \$480.00                              | (\$67,824.00)        |
|                   | 0350        | FURNISHING AND PLACING<br>CONCRETE MATERIAL FOR<br>FULL DEPTH PAVEMENT<br>REPAIR          | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0001) due to user wilesd<br>overridding Payment Estimate Exception 9 on<br>the current Payment Estimate. | 141.3                  | \$480.00                              | \$67,824.00          |
|                   | 0390        | DOWEL BAR (DRILLING,<br>FURNISHING AND<br>INSTALLATION) FOR FULL<br>DEPTH PAVEMENT REPAIR | Material           |                                  |  | -48                    | \$29.00                               | (\$1,392.00)         |
|                   | 0390        | DOWEL BAR (DRILLING,<br>FURNISHING AND<br>INSTALLATION) FOR FULL<br>DEPTH PAVEMENT REPAIR | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0002) due to user wilesd<br>overridding Payment Estimate Exception 10                                    | 48                     | \$29.00                               | \$1,392.00           |

Revision 3/23/2023 Page 2 of 19



Pay Estimate Created Date: November 3, 2023

Progress Estimate Number 10 Contract ID 230217-F02 Pay Period Start October 16, 2023 Original Contract Amount \$13,077,700.00 Start October 16, 2023 Original Contract Amount \$13,077,700.00 Pay Period End November 1, 2023 Original Contract Amount \$13,077,700.00 Pay Period End November 1, 2023 Original Contract Amount \$13,077,700.00 October 16, 2023 Octo

| et Line<br>er No. |  | Adjustment<br>Type | Other Item<br>Adjustment<br>Type | Comments  | Adjustment<br>Quantity | Line Item<br>Adjustment<br>Unit Price | Adjustment amount |
|-------------------|--|--------------------|----------------------------------|---|------------------------|---------------------------------------|-------------------|
| 8                 |  |                    |                                  | on the current Payment Estimate.  |                        |                                       |                   |
| 0400              | TIE BAR (DRILLING,<br>FURNISHING AND<br>INSTALLATION) FOR FULL<br>DEPTH PAVEMENT REPAIR<br>(TYPE L JOINTS) | Material           |                                  |   | -106                   | \$15.00                               | (\$1,590.00       |
| 0400              | TIE BAR (DRILLING,<br>FURNISHING AND<br>INSTALLATION) FOR FULL<br>DEPTH PAVEMENT REPAIR<br>(TYPE L JOINTS) | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0003) due to user wilesd<br>overridding Payment Estimate Exception 12<br>on the current Payment Estimate. | 106                    | \$15.00                               | \$1,590.00        |
| 0470              | CONCRETE TRAFFIC<br>BARRIER, TYPE C  | Material           |                                  |   | -7,196                 | \$100.00                              | (\$719,600.00     |
| 0470              | CONCRETE TRAFFIC<br>BARRIER, TYPE C  | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0004) due to user wilesd<br>overridding Payment Estimate Exception 14<br>on the current Payment Estimate. | 7,196                  | \$100.00                              | \$719,600.00      |
| 0990              | CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER   | Material           |                                  |   | -1                     | \$23,468.00                           | (\$23,468.00      |
| 0990              | CONTROLLER ASSEMBLY<br>HOUSING, NEMA TS2<br>CONTROLLER   | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0005) due to user wilesd<br>overridding Payment Estimate Exception 17<br>on the current Payment Estimate. | 1                      | \$23,468.00                           | \$23,468.00       |
| 1020              | CONDUIT, 2 IN., TRENCH<br>WITH TRACER WIRE   | Material           |                                  |   | -27                    | \$14.00                               | (\$378.00         |
| 1020              | CONDUIT, 2 IN., TRENCH<br>WITH TRACER WIRE   | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0006) due to user wilesd<br>overridding Payment Estimate Exception 18<br>on the current Payment Estimate. | 27                     | \$14.00                               | \$378.00          |
| 1030              | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE  | Material           |                                  |   | -493                   | \$38.00                               | (\$18,734.00      |
| 1030              | CONDUIT, 3 IN., PUSHED<br>WITH TRACER WIRE   | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0007) due to user wilesd<br>overridding Payment Estimate Exception 19<br>on the current Payment Estimate. | 493                    | \$38.00                               | \$18,734.00       |
| 1080              | PULL BOX, PREFORMED CLASS 1  | Material           |                                  |   | -1                     | \$1,546.00                            | (\$1,546.00       |
| 1080              | PULL BOX, PREFORMED<br>CLASS 1   | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0008) due to user wilesd<br>overridding Payment Estimate Exception 20<br>on the current Payment Estimate. | 1                      | \$1,546.00                            | \$1,546.00        |
| 1090              | PULL BOX, PREFORMED<br>CLASS 2   | Material           |                                  |   | -1                     | \$2,080.00                            | (\$2,080.00       |
| 1090              | PULL BOX, PREFORMED<br>CLASS 2   | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0009) due to user wilesd<br>overridding Payment Estimate Exception 21<br>on the current Payment Estimate. | 1                      | \$2,080.00                            | \$2,080.00        |
| 1100              | PULL BOX, PREFORMED CLASS 3  | Material           |                                  |   | -1                     | \$2,800.00                            | (\$2,800.00)      |
| 1100              | PULL BOX, PREFORMED  | Material           |                                  | This adjustment offsets the original system-  | 1                      | \$2,800.00                            | \$2,800.00        |

Revision 3/23/2023 Page 3 of 19



Pay Estimate Created Date: November 3, 2023

| Progress Estimate<br>Number |             | Contract ID      | 230217-F            | )2                 |                                  | ay Period<br>tart | October 16, 2023                  | Original Contra   | ct Amount                                 | \$13,077,700.00                       |                                  |
|-----------------------------|-------------|------------------|---------------------|--------------------|----------------------------------|-------------------|-----------------------------------|---|---|---------------------------------------|----------------------------------|
|                             | 1           | 0                | Prime<br>Contractor | Pace Cons<br>LLC   | struction Com                    |                   | ay Period End                     |   | Net Change Or<br>Amount<br>Current Contra | (                                     | (\$26,843.31)<br>\$13,050,856.69 |
| Project<br>Number           | Line<br>No. | Item Description |                     | Adjustment<br>Type | Other Item<br>Adjustment<br>Type |                   | Comments                          |   | Adjustment<br>Quantity                    | Line Item<br>Adjustment<br>Unit Price | Adjustment amount                |
| J6I3568                     |             |                  | CLASS 3             |                    |                                  | Ad                | djustment (001)<br>ing Payment Es | yment Estimate Ite<br>0) due to user wile<br>stimate Exception<br>nt Payment Estima | sd<br>22                                  |                                       |                                  |
| Total                       |             |                  |                     |                    |                                  |                   |                                   |   |   |                                       | \$0.00                           |

Revision 3/23/2023 Page 4 of 19



|                   |                            |   |       |             |                           | Contract Project Information   |                                |
|-------------------|----------------------------|---|-------|-------------|---------------------------|--------------------------------|--------------------------------|
| Project<br>Number | Federal<br>Proj.<br>Number | Project<br>Description  | Route | County      |                           |                                | Location of Work               |
| J6l3568           | I<br>44-4(209)             | Coldmill,<br>resurface,<br>signal, and<br>ADA<br>improvements | I-44  | ST<br>LOUIS | from Franklin County line | to Williams Road               |                                |
| Totals by .       | Job Numbe                  | rs  |       |             |                           |                                |                                |
| J6I3568           |                            |   |       |             | This Estimate             | Previous                       | To Date                        |
|                   |                            | d Item Pay<br>Item Adjustmer                                  | nts   |             | \$512,242.00<br>\$0.00    | \$1,801,247.41<br>\$936,934.63 | \$2,313,489.41<br>\$936,934.63 |
|                   |                            | ·   |       | tem Pay     | \$512,242.00              | \$2,738,182.04                 | \$3,250,424.04                 |
|                   | Incent                     | ive   |       |             | \$0.00                    | \$0.00                         | \$0.00                         |
|                   | Disino                     | entive  |       |             | \$0.00                    | \$0.00                         | \$0.00                         |
|                   |                            | ated Damages  |       |             | \$0.00                    | \$0.00                         | \$0.00                         |
|                   | Other                      | Other Contract Adjustments                                    |       |             | \$0.00                    | \$0.00                         | \$0.00                         |

Revision 3/23/2023 Page 5 of 19



## **Exceptions (Discrepancies) This Estimate Period**

| Exceptions (Discrepancies) This Estimate Period   |   |               |            |
|---|---|---------------|------------|
| Exceptions / Discrepencies  | Explanation   | Entered<br>By | Status     |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 3040504, Project Item Line Number 0050, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.                       | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 3040506, Project Item Line Number 0060, Material Set 304050696, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.                       | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 5021307, Project Item Line Number 0170, Material Set 502130796, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action 0501CCPAQCQA 7 in. is insufficient.        | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 5021307, Project Item Line Number 0170, Material Set 502130796, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient. | No Remark was entered by Engineer   | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 6081010, Project Item Line Number 0220, Material Set 608101096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.    | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 6081010, Project Item Line Number 0220, Material Set 608101096, Material 1067TRDO - Truncated Domes for ADA, Acceptance Action Generic 1067TRDO is insufficient.                               | No Remark was entered by Engineer   | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 6083006, Project Item Line Number 0240, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.    | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 6086004, Project Item Line Number 0250, Material Set 608600496, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.    | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 6131010, Project Item Line Number 0350, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.                           | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 6131015, Project Item Line Number 0390, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.            | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 6131015, Project Item Line Number 0390, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.                    | No Remark was entered by Engineer   | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 6131018, Project Item Line Number 0400, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient. | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 6131018, Project Item Line Number 0400, Material Set 613101896, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.                    | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 6173000, Project Item Line Number 0470, Material Set 617300096, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.            | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 6173000, Project Item Line Number 0470, Material Set 617300096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.                         | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 6173000, Project Item Line Number 0470, Material Set 617300096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.                  | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 9024283, Project Item Line Number 0990, Material Set 902428396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.                              | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 9025200, Project Item Line Number 1020, Material Set 902520096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.                               | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 9027300, Project Item Line Number 1030, Material Set 902730096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.                               | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 9028810, Project Item Line Number 1080, Material Set 902881096, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.                   | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 9028811, Project Item Line Number 1090, Material Set 902881196, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.                   | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l3568, Item 9028812, Project Item Line Number 1100, Material Set 902881296, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.                   | This discrepancy is being reviewed by TranSystems and Modot. Required reporting will be done to eliminate it. | wilesd        | Overridden |

Revision 3/23/2023 Page 6 of 19



### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

### Total Paid / All Items / All Estimates (Including this Estimate)

| Contract<br>Im.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | Description  | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit | Total<br>Posted<br>Approved<br>Qty | Unit Price   | Total Value POSTED<br>To Date (See report<br>generated date) |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|--------------|--|
| 30217-F02               | J6I3568        | 0001     | 0010        | 2022010      | REMOVAL OF IMPROVEMENTS  | 1.00            | 0.00                   | 1.00                         | LS   | 0.60                               | \$745,741.90 | \$450,428.1  |
|                         |                | 0001     | 0020        | 2063000      | CLASS 3 EXCAVATION   | 248.00          | 0.00                   | 248.00                       | CUYD | 120.00                             | \$60.00      | \$7,200.0  |
|                         |                | 0001     | 0030        | 2063500      | CULVERT CLEANOUT   | 1.00            | 0.00                   | 1.00                         | EA   | 1.00                               | \$6,750.00   | \$6,750.0  |
|                         |                | 0001     | 0040        | 2159910      | MISC.SHAPING SLOPES CLASS III-MODIFIED MATERIAL REQUIREMENT                                    | 38.00           | 0.00                   | 38.00                        | 100F | 0.00                               | \$1,000.00   | \$0.0  |
|                         |                | 0001     | 0050        | 3040504      | TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)  | 99.80           | 0.00                   | 99.80                        | SQYD | 99.80                              | \$22.00      | \$2,195.6  |
|                         |                | 0001     | 0060        | 3040506      | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  | 96.00           | 0.00                   | 96.00                        | SQYD | 96.00                              | \$23.00      | \$2,208.0  |
|                         |                | 0001     | 0070        | 4010150      | TYPE A2 SHOULDER   | 13.30           | 0.00                   | 13.30                        | SQYD | 0.00                               | \$274.00     | \$0.0  |
|                         |                | 0001     | 0080        | 4011209      | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  | 9,776.20        | 0.00                   | 9,776.20                     | TONS | 0.00                               | \$81.00      | \$0.0  |
|                         |                | 0001     | 0090        | 4030009      | ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP095BSM MIX)   | 19,475.40       | 0.00                   | 19,475.40                    | TONS | 0.00                               | \$132.00     | \$0.0  |
|                         |                | 0001     | 0100        | 4030109      | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)   | 7,965.00        | 0.00                   | 7,965.00                     | TONS | 0.00                               | \$105.00     | \$0.0  |
|                         |                | 0001     | 0110        | 4030217      | ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP190B MIX)   | 12,118.90       | 0.00                   | 12,118.90                    | TONS | 0.00                               | \$91.00      | \$0.0  |
|                         |                | 0001     | 0120        | 4031056      | ASPHALT PERFORMANCE TESTING  | 1.00            | 0.00                   | 1.00                         | LS   | 0.00                               | \$2,500.00   | \$0.0  |
|                         |                | 0001     | 0130        | 4031058      | INTELLIGENT COMPACTION   | 1.00            | 0.00                   | 1.00                         | LS   | 0.00                               | \$65,250.00  | \$0.0  |
|                         |                | 0001     | 0140        | 4031059      | PAVER-MOUNTED THERMAL PROFILES   | 1.00            | 0.00                   | 1.00                         | LS   | 0.00                               | \$25,500.00  | \$0.0  |
|                         |                | 0001     | 0150        | 4059903      | MISC.VOID REDUCING ASPHALT MEMBRANE, HALF WIDTH  | 59,783.00       | 0.00                   | 59,783.00                    | LF   | 0.00                               | \$2.55       | \$0.0  |
|                         |                | 0001     | 0160        | 4071007      | TACK COAT - LOW OR NON-TRACKING  | 35,977.00       | 0.00                   | 35,977.00                    | GAL  | 0.00                               | \$3.30       | \$0.0  |
|                         |                | 0001     | 0170        | 5021307      | CONCRETE PAVEMENT (7 IN. NON-REINFORCED, 15 FT. JOINTS)  | 95.50           | 0.00                   | 95.50                        | SQYD | 95.50                              | \$128.00     | \$12,224.0   |
|                         |                | 0001     | 0180        | 6042010      | ADJUSTING MANHOLE  | 2.00            | 0.00                   | 2.00                         | EA   | 0.00                               | \$4,000.00   | \$0.0  |
|                         |                | 0001     | 0190        | 6044011      | PIPE COLLAR, TYPE A  | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$4,750.00   | \$0.0  |
|                         |                | 0001     | 0200        | 6049902      | MISC.INLET TOP REPLACEMENT   | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$1,600.00   | \$0.0  |
|                         |                | 0001     | 0210        | 6079903      | MISC.CHAIN-LINK FENCE (72 IN.) WITH ANTI-GLARE SLATS   | 10,288.00       | -10,288.00             | 0.00                         | LF   | 0.00                               | \$48.00      | \$0.0  |
|                         |                | 0001     | 0220        | 6081010      | CONCRETE CURB RAMP   | 7.00            | 0.00                   | 7.00                         | SQYD | 6.00                               | \$1,854.00   | \$11,124.0   |
|                         |                | 0001     | 0230        | 6081012      | TRUNCATED DOMES  | 110.00          | 0.00                   | 110.00                       | SQFT | 60.00                              | \$50.00      | \$3,000.0  |
|                         |                | 0001     | 0240        | 6083006      | 6 IN. CONCRETE MEDIAN STRIP  | 171.00          | 0.00                   | 171.00                       | SQYD | 126.40                             | \$158.00     | \$19,971.2   |
|                         |                | 0001     | 0250        | 6086004      | CONCRETE SIDEWALK, 4 IN.   | 99.80           | 0.00                   | 99.80                        | SQYD | 99.80                              | \$100.00     | \$9,980.   |
|                         |                | 0001     | 0260        | 6089902      | MISC.ISLAND TUBULAR MARKERS  | 36.00           | 0.00                   | 36.00                        | EA   | 0.00                               | \$80.00      | \$0.0  |
|                         |                | 0001     | 0270        | 6091010      | CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S  | 96.00           | 0.00                   | 96.00                        | LF   | 83.00                              | \$70.00      | \$5,810.0  |
|                         |                | 0001     | 0280        | 6091011      | CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S   | 59.00           | 0.00                   | 59.00                        | LF   | 0.00                               | \$67.00      | \$0.0  |
|                         |                | 0001     | 0290        | 6092021      | INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A   | 25.00           | 0.00                   | 25.00                        | LF   | 25.00                              | \$35.00      | \$875.0  |
|                         |                | 0001     | 0300        | 6097000      | ROCK LINING  | 2.00            | 0.00                   | 2.00                         | CUYD | 0.00                               | \$1,000.00   | \$0.0  |
|                         |                | 0001     | 0310        | 6122017      | IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)   | 3.00            | 0.00                   | 3.00                         | EA   | 2.00                               | \$5,000.00   | \$10,000.0   |
|                         |                | 0001     | 0320        | 6122020      | REPLACEMENT SAND BARREL  | 19.00           | 0.00                   | 19.00                        | EA   | 0.00                               | \$500.00     | \$0.0  |
|                         |                | 0001     | 0330        | 6122030      | IMPACT ATTENUATOR (RELOCATION)   | 3.00            | 0.00                   | 3.00                         | EA   | 2.00                               | \$1,000.00   | \$2,000.0  |
|                         |                | 0001     | 0340        | 6123000A     | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  | 2.00            | 0.00                   | 2.00                         | EA   | 0.00                               | \$7,500.00   | \$0.0  |
|                         |                | 0001     | 0350        | 6131010      | FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR                        | 389.00          | 0.00                   | 389.00                       | SQYD | 141.30                             | \$480.00     | \$67,824.0   |
|                         |                | 0001     | 0360        | 6131012      | SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)  | 389.00          | 0.00                   | 389.00                       | SQYD | 0.00                               | \$6.50       | \$0.0  |
|                         |                | 0001     | 0370        | 6131013      | TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)                                 | 389.00          | 0.00                   | 389.00                       | SQYD | 0.00                               | \$10.00      | \$0.0  |
|                         |                | 0001     | 0380        | 6131014      | FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)                       | 1,390.00        | 0.00                   | 1,390.00                     | LF   | 446.00                             | \$9.75       | \$4,348.5  |
|                         |                | 0001     | 0390        | 6131015      | DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR               | 323.00          | 0.00                   | 323.00                       | EA   | 48.00                              | \$29.00      | \$1,392.0  |
|                         |                | 0001     | 0400        | 6131018      | TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) | 240.00          | 0.00                   | 240.00                       | EA   | 106.00                             | \$15.00      | \$1,590.0  |
|                         |                | 0001     | 0410        | 6133018      | FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR           | 11.50           | 0.00                   | 11.50                        | TONS | 0.00                               | \$70.00      | \$0.0  |
|                         |                | 0001     | 0420        | 6133019      | REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR  | 62.30           | 0.00                   | 62.30                        | SQYD | 0.00                               | \$105.00     | \$0.0  |
|                         |                | 0001     | 0430        | 6149902      | MISC.GRATED INLET REPAIR/REPLACEMENT   | 2.00            | 0.00                   | 2.00                         | EA   | 2.00                               | \$4,000.00   | \$8,000.0  |
|                         |                | 0001     | 0440        | 6169901      | MISC.TEMPORARY TRAFFIC CONTROL   | 1.00            | 0.00                   | 1.00                         | LS   | 0.50                               | \$24,720.00  | \$12,360.0   |
|                         |                | 0001     | 0450        | 6169902      | MISC.BOLLARDS  | 8.00            | 0.00                   | 8.00                         | EA   | 0.00                               | \$1,800.00   | \$0.0  |

Revision 3/23/2023 Page 7 of 19



### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

## Total Paid / All Items / All Estimates (Including this Estimate)

| Contract<br>Nm.CONTRACT | Project<br>No. | Category | Line<br>No.  | Item<br>Code       | Description   | Bid<br>Quantity | Net<br>Change | Total<br>Current | Unit     | Total<br>Posted | Unit Price           | Total Value POSTED To Date (See report |
|-------------------------|----------------|----------|--------------|--------------------|---|-----------------|---------------|------------------|----------|-----------------|----------------------|--|
| MIII.COMTRACT           | 140.           |          | NO.          | Code               |   | Quantity        | Order         | Quantity         |          | Approved<br>Qty |                      | generated date)                        |
| 230217-F02              | J6I3568        | 0001     | 0460         | 6169902            | MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)    | 3.00            | 0.00          | 3.00             | EA       | 2.00            | \$3,200.00           | \$6,400.0                              |
|                         |                | 0001     | 0470         | 6173000            | CONCRETE TRAFFIC BARRIER, TYPE C  | 7,196.00        | 0.00          | 7,196.00         | LF       | 7,196.00        | \$100.00             | \$719,600.0                            |
|                         |                | 0001     | 0480         | 6173600D           | TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED                          | 14,200.00       | 0.00          | 14,200.00        | LF       | 14,200.00       | \$41.27              | \$586,034.0                            |
|                         |                | 0001     | 0490         | 6181000            | MOBILIZATION  | 1.00            | 0.00          | 1.00             | LS       | 0.25            | \$1,115,000.00       | \$278,750.0                            |
|                         |                | 0001     | 0500         | 6200015            | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE                              | 530.00          | 0.00          | 530.00           | LF       | 0.00            | \$23.00              | \$0.0                                  |
|                         |                | 0001     | 0510         | 6200021            | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW                          | 98.00           | 0.00          | 98.00            | EA       | 0.00            | \$270.00             | \$0.0                                  |
|                         |                | 0001     | 0520         | 6200024            | PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW                            | 6.00            | 0.00          | 6.00             | EA       | 0.00            | \$250.00             | \$0.0                                  |
|                         |                | 0001     | 0530         | 6200027            | PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT                     | 7.00            | 0.00          | 7.00             | EA       | 0.00            | \$500.00             | \$0.0                                  |
|                         |                | 0001     | 0540         | 6200042            | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES         | 12.00           | 0.00          | 12.00            | EA       | 0.00            | \$75.00              | \$0.0                                  |
|                         |                | 0001     | 0550         | 6205901A           | 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT<br>MARKING PAINT, TYPE L BEADS          | 73,826.00       | 0.00          | 73,826.00        | LF       | 0.00            | \$0.19               | \$0.0                                  |
|                         |                | 0001     | 0560         | 6205902A           | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING<br>PAINT, TYPE L BEADS           | 132,312.00      | 0.00          | 132,312.00       | LF       | 0.00            | \$0.25               | \$0.0                                  |
|                         |                | 0001     | 0570         | 6205903A           | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT   | 83,208.00       | 0.00          | 83,208.00        | LF       | 0.00            | \$0.25               | \$0.0                                  |
|                         |                | 0001     | 0580         | 6205906A           | MARKING PAINT, TYPE L BEADS  12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT            | 4,966.00        | 0.00          | 4,966.00         | LF       | 0.00            | \$1.00               | \$0.0                                  |
|                         |                | 0001     | 0590         | 6206000C           |   | 50,302.00       | 0.00          | 50,302.00        | LF       | 0.00            | \$0.18               | \$0.0                                  |
|                         |                | 0001     | 0600         | 6208076            | PAINT, TYPE P BEADS  4 IN TEMPORARY PAVEMENT MARKING PAINT                          | 27,500.00       | 0.00          | 27,500.00        | LF       | 7,148.00        | \$1.50               | \$10,722.0                             |
|                         |                | 0001     | 0610         | 6209902            | MISC.CURB REFLECTORS  | 112.00          | 0.00          | 112.00           | EA       | 0.00            | \$25.00              | \$0.0                                  |
|                         |                | 0001     | 0620         | 6209902            | MISC.INLAID PAVEMENT MARKER INSTALLATION  | 1,984.00        | 0.00          | 1,984.00         | EA       | 0.00            | \$45.00              | \$0.0                                  |
|                         |                | 0001     | 0630         | 6221001            | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)      | 294,332.00      | 0.00          | 294,332.00       | SQYD     | 0.00            | \$3.00               | \$0.0                                  |
|                         |                | 0001     | 0640         | 6221003            | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK) | 65,437.00       | 0.00          | 65,437.00        | SQYD     | 0.00            | \$6.25               | \$0.0                                  |
|                         |                | 0001     | 0650         | 6221011            | COLDMILLING CONCRETE PAVEMENT FOR REMOVAL OF SURFACE                                | 1,471.00        | 0.00          | 1,471.00         | SQYD     | 0.00            | \$4.50               | \$0.0                                  |
|                         |                | 0001     | 0660         | 6224010            | MODIFIED COLDMILLING (DEPTH TRANSITIONS)  | 1,143.00        | 0.00          | 1,143.00         | SQYD     | 0.00            | \$7.00               | \$0.0                                  |
|                         |                | 0001     | 0670         | 6261000A           | BITUMINOUS SHOULDER RUMBLE STRIP  | 506.60          | 0.00          | 506.60           | STA      | 0.00            | \$31.00              | \$0.0                                  |
|                         |                | 0001     | 0680         | 6261001            | BITUMINOUS CENTERLINE RUMBLE STRIP  | 192.60          | 0.00          | 192.60           | STA      | 0.00            | \$31.00              | \$0.0                                  |
|                         |                | 0001     | 0690         | 6262000A           | PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP                                      | 192.60          | 0.00          | 192.60           | STA      | 0.00            | \$35.00              | \$0.0                                  |
|                         |                | 0001     | 0700         | 6262001            | PORTLAND CEMENT CONCRETE CENTERLINE RUMBLE STRIP                                    | 208.60          | 0.00          | 208.60           | STA      | 0.00            | \$35.00              | \$0.0                                  |
|                         |                | 0001     | 0710         | 6274000            | CONTRACTOR FURNISHED SURVEYING AND STAKING  | 1.00            | 0.00          | 1.00             | LS       | 0.00            | \$7,500.00           | \$0.0                                  |
|                         |                | 0001     | 0720         | 7039902            | MISC.MEDIAN BARRIER HEIGHT TRANSISTION  | 1.00            | 0.00          | 1.00             | EA       | 0.00            | \$7,000.00           | \$0.0                                  |
|                         |                | 0001     | 0730<br>0740 | 7261015<br>7261024 | 15 IN. PIPE GROUP A 24 IN. PIPE GROUP A   | 45.00<br>45.00  | 0.00          | 45.00<br>45.00   | LF<br>LF | 45.00           | \$135.00<br>\$285.00 | \$0.0<br>\$12,825.0                    |
|                         |                | 0001     | 0750         | 7311053            | PRECAST CONCRETE DROP INLET 5 FT X 3 FT   | 11.00           | 0.00          | 11.00            | FT       | 11.00           |                      | \$9,372.0                              |
|                         |                | 0001     | 0760         | 7319902            | MISC.MSD HEAVY DUTY 8 IN. INLET STONE   | 1.00            | 0.00          | 1.00             | EA       | 1.00            | \$1,500.00           | \$1,500.0                              |
|                         |                | 0001     | 0770         | 7320615A           | 15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END                                     | 1.00            | 0.00          | 1.00             | EA       | 0.00            | \$2,025.00           | \$0.0                                  |
|                         |                | 0001     | 0780         | 7350001            | SECTION PIPE LINER FOR EXISTING CULVERT   | 70.00           | 0.00          | 70.00            | LF       | 0.00            | \$545.00             | \$0.0                                  |
|                         |                | 0001     | 0790         | 8031000A           | TURF TYPE TALL FESCUE SODDING   | 400.00          | 0.00          | 400.00           | SQYD     | 0.00            | \$18.00              | \$0.0                                  |
|                         |                | 0001     | 0800         | 8061005            | ROCK DITCH CHECK  | 100.00          | 0.00          | 100.00           | LF       | 0.00            | \$20.00              | \$0.0                                  |
|                         |                | 0001     | 0810         | 8061016            | SEDIMENT REMOVAL  | 12.00           | 0.00          | 12.00            | CUYD     | 0.00            | \$60.00              | \$0.0                                  |
|                         |                | 0001     | 0820         | 8061019            | SILT FENCE  | 570.00          | 0.00          | 570.00           | LF       | 0.00            | \$5.00               | \$0.0                                  |
|                         |                | 0010     | 0830         | 6061060            | MGS GUARDRAIL   | 11,938.00       | 0.00          | 11,938.00        | LF       | 0.00            | \$27.00              | \$0.0                                  |
|                         |                | 0010     | 0840         | 6061061            | MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING                                      | 24,675.00       | 0.00          | 24,675.00        | LF       | 0.00            | \$30.50              | \$0.0                                  |
|                         |                | 0010     | 0850         | 6061069            | MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)                            | 19.00           | 0.00          | 19.00            | EA       | 0.00            | \$3,600.00           | \$0.0                                  |
|                         |                | 0010     | 0860         | 6061074            | MGS HEIGHT AND BLOCK TRANSITION   | 1.00            | 0.00          | 1.00             | EA       | 0.00            | \$800.00             | \$0.0                                  |
|                         |                | 0010     | 0870         | 6061080            | MGS END ANCHOR  | 37.00           | 0.00          | 37.00            | EA       | 0.00            | \$1,400.00           | \$0.0                                  |
|                         |                | 0010     | 0880         | 6063014            | TYPE A CRASHWORTHY END TERMINAL (MASH)  | 47.00           | 0.00          | 47.00            | EA       | 0.00            | \$3,000.00           | \$0.0                                  |

Revision 3/23/2023 Page 8 of 19



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Project Category Line Item Description Big Operation Contract Project Category Line Item Description Descr

| Contract<br>Nm.CONTRACT | Project<br>No. | Category  | Line<br>No. | Item<br>Code  | Description  | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit | Total<br>Posted<br>Approved<br>Qty | Unit Price  | Total Value POSTED<br>To Date (See report<br>generated date) |
|-------------------------|----------------|-----------|-------------|---------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 230217-F02              | J6I3568        | 0030      | 0890        | 9020213       | SIGNAL HEAD, TYPE 3S   | 3.00            | 0.00                   | 3.00                         | EA   | 0.00                               | \$891.00    | \$0.00   |
|                         |                | 0030      | 0900        | 9020214       | SIGNAL HEAD, TYPE 4S   | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$1,015.00  | \$0.00   |
|                         |                | 0030      | 0910        | 9020513       | SIGNAL HEAD, TYPE 3B   | 4.00            | 0.00                   | 4.00                         | EA   | 0.00                               | \$1,116.00  | \$0.00   |
|                         |                | 0030      | 0920        | 9020514       | SIGNAL HEAD, TYPE 4B   | 4.00            | 0.00                   | 4.00                         | EA   | 0.00                               | \$1,240.00  | \$0.00   |
|                         |                | 0030      | 0930        | 9020811       | SIGNAL HEAD, TYPE 1S, PEDESTRIAN   | 8.00            | 0.00                   | 8.00                         | EA   | 0.00                               | \$650.00    | \$0.00   |
|                         |                | 0030      | 0940        | 9020833       | SH-FLAT SHEET - SIGNAL SIGN  | 56.00           | 0.00                   | 56.00                        | SQFT | 0.00                               | \$38.00     | \$0.00   |
|                         |                | 0030      | 0950        | 9020834       | SIGNAL SIGN, MOUNTING HARDWARE   | 17.00           | 0.00                   | 17.00                        | EA   | 0.00                               | \$78.00     | \$0.00   |
|                         |                | 0030      | 0960        | 9023225       | POST, TYPE C, 25 FT. ARM OR 7.6 M ARM  | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$8,045.00  | \$0.00   |
|                         |                | 0030      | 0970        | 9023235       | POST, TYPE C, 35 FT. ARM OR 10.7 M ARM   | 2.00            | 0.00                   | 2.00                         | EA   | 0.00                               | \$9,600.00  | \$0.00   |
|                         |                | 0030      | 0980        | 9023255       | POST, TYPE C, 55 FT. ARM   | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$12,777.00 | \$0.00   |
|                         |                | 0030      | 0990        | 9024283       | CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER                                     | 1.00            | 0.00                   | 1.00                         | EA   | 1.00                               | \$23,468.00 | \$23,468.00  |
|                         |                | 0030      | 1000        | 9024975       | VIDEO DETECTION SYSTEM   | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$13,785.00 | \$0.00   |
|                         |                | 0030      | 1010        | 9025020       | CONDUIT, 1 IN., LOOP DETECTOR WITH TRACER WIRE                                       | 41.00           | 0.00                   | 41.00                        | LF   | 0.00                               | \$12.00     | \$0.00   |
|                         |                | 0030      | 1020        | 9025200       | CONDUIT, 2 IN., TRENCH WITH TRACER WIRE  | 27.00           | 0.00                   | 27.00                        | LF   | 27.00                              | \$14.00     | \$378.00   |
|                         |                | 0030      | 1030        | 9027300       | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE  | 518.00          | 0.00                   | 518.00                       | LF   | 493.00                             | \$38.00     | \$18,734.00  |
|                         |                | 0030      | 1040        | 9028308       | CABLE, 16 AWG 2 CONDUCTOR  | 1,230.00        | 0.00                   | 1,230.00                     | LF   | 0.00                               | \$1.50      | \$0.00   |
|                         |                | 0030      | 1050        | 9028310       | CABLE, 16 AWG 5 CONDUCTOR  | 1,240.00        | 0.00                   | 1,240.00                     | LF   | 0.00                               | \$1.50      | \$0.00   |
|                         |                | 0030      | 1060        | 9028311       | CABLE, 16 AWG 7 CONDUCTOR  | 2,400.00        | 0.00                   | 2,400.00                     | LF   | 0.00                               | \$2.00      | \$0.00   |
|                         |                | 0030      | 1070        | 9028500       | CABLE, LOOP DETECTOR, IN DUCT  | 2,040.00        | 0.00                   | 2,040.00                     | LF   | 0.00                               | \$7.00      | \$0.00   |
|                         |                | 0030      | 1080        | 9028810       | PULL BOX, PREFORMED CLASS 1  | 2.00            | 0.00                   | 2.00                         | EA   | 1.00                               | \$1,546.00  | \$1,546.00   |
|                         |                | 0030      | 1090        | 9028811       | PULL BOX, PREFORMED CLASS 2  | 1.00            | 0.00                   | 1.00                         | EA   | 1.00                               | \$2,080.00  | \$2,080.00   |
|                         |                | 0030      | 1100        | 9028812       | PULL BOX, PREFORMED CLASS 3  | 1.00            | 0.00                   | 1.00                         | EA   | 1.00                               | \$2,800.00  | \$2,800.00   |
|                         |                | 0030      | 1110        | 9029100       | BASE, CONCRETE   | 16.20           | 0.00                   | 16.20                        | CUYD | 0.00                               | \$2,347.00  | \$0.00   |
|                         |                | 0030      | 1120        | 9029902       | MISC.AUDIBLE PEDESTRIAN PUSHBUTTON   | 8.00            | 0.00                   | 8.00                         | EA   | 0.00                               | \$866.00    | \$0.00   |
|                         |                | 0030      | 1130        | 9029902       | MISC.COMBINATION PAD MOUNTED 120V/240V POWER SUPPLY AND LIGHTING CONTROLLER WITH UPS | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$19,000.00 | \$0.00   |
|                         |                | 0030      | 1140        | 9029902       | MISC.REMOTE PUSH BUTTON STANCHION  | 2.00            | 0.00                   | 2.00                         | EA   | 0.00                               | \$800.00    | \$0.00   |
|                         |                | 0040      | 1150        | 9031270A      | 2 IN. PSST POST - 12 GA.   | 20.00           | 36.00                  | 56.00                        | LF   | 0.00                               | \$30.00     | \$0.00   |
|                         |                | 0040      | 1160        | 9031271A      | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.   | 6.00            | 3.00                   | 9.00                         | EA   | 0.00                               | \$200.00    | \$0.00   |
|                         |                | 0050      | 1170        | 9108343       | CABLE, 14 AWG, 2 CONDUCTOR SPEAKER WIRE, SHIELDED                                    | 640.00          | 0.00                   | 640.00                       | LF   | 0.00                               | \$1.50      | \$0.00   |
|                         |                | 0050      | 1180        | 9109902       | MISC.FUSION SPLICE   | 4.00            | 0.00                   | 4.00                         | EA   | 0.00                               | \$140.00    | \$0.00   |
|                         |                | 0050      | 1190        | 9109902       | MISC.INSTALL COMMUNICATION EQUIPMENT   | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$600.00    | \$0.00   |
|                         |                | 0050      | 1200        | 9109902       | MISC.INSTALL MODOT FURNISHED IP-ADDRESSABLE POWER STRIP                              | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$180.00    | \$0.00   |
|                         |                | 0050      | 1210        | 9109902       | MISC.SM FIBER OPTIC JUMPER   | 4.00            | 0.00                   | 4.00                         | EA   | 0.00                               | \$18.00     | \$0.00   |
|                         |                | 0050      | 1220        | 9109902       | MISC.SM FIBER OPTIC PIGTAIL  | 4.00            | 0.00                   | 4.00                         | EA   | 0.00                               | \$18.00     | \$0.00   |
|                         |                | 0050      | 1230        | 9109902       | MISC.WALL-MOUNT FIBER INTERCONNECT CENTER  | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$700.00    | \$0.00   |
|                         |                | 0050      | 1240        | 9109903       | MISC.MODOT ITS ASSET RELOCATION  | 1,831.00        | 0.00                   | 1,831.00                     | LF   | 0.00                               | \$1.00      | \$0.00   |
|                         |                | 0010      | 5001        | 6069901       | MISC.Relocate existing Type C CET  | 0.00            | 1.00                   | 1.00                         | LS   | 0.00                               | \$3,575.25  | \$0.00   |
|                         |                | 0001      | 5002        | 6079903       | MISC.CHAIN LINK FENCE 72" 9 GAUGE WITH ANTI-GLARE SLATS                              | 0.00            | 10,288.00              | 10,288.00                    | LF   | 0.00                               | \$44.88     | \$0.00   |
|                         |                |           |             |               | Pate as of Report Generated Date   |                 |                        |                              |      |                                    |             | \$2,313,489.41   |
| 230217-F02 Ove          | rall - Tota    | Value Pos | ted to Da   | ite as of Rep | ort Generated Date   |                 |                        |                              |      |                                    |             | \$2,313,489.41   |

Revision 3/23/2023 Page 9 of 19



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6I3568

| Line<br>Number | Item<br>Code | Description                              | DWR<br>Date | DWR<br>Approval<br>Date | Quantity<br>Posted | Units | Location   | From<br>Station/<br>Log Mile | Offset/<br>Distance | To<br>Station/<br>Log<br>Mile | Offset/<br>Distance | Comments  |
|----------------|--------------|--|-------------|-------------------------|--------------------|-------|--|------------------------------|---------------------|-------------------------------|---------------------|---|
| 0030           | 2063500      | CULVERT CLEANOUT                         | 10/31/23    | 11/3/23                 | 0.25               | EA    | Structure 1-2 to Ex Inlet 5th St. 36"x60" Elliptical Opening   |                              |                     |                               |                     |   |
| 0350           | 6131010      | FURN & PLACE CONC MATL FOR FULL DEPTH    | 10/31/23    | 11/3/23                 | 9.30               | SQYD  | Lane 1 wb I-44   | 397+17                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 16.00              | SQYD  | Lane 2 wb I-44   | 340+49                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 16.00              | SQYD  | Lane 2 wb I-44   | 359+93                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 16.00              | SQYD  | Lane 3 wb I-44   | 392+77                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 20.00              | SQYD  | Lane 3 wb I-44   | 364+77                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 64.00              | SQYD  | Lane 2 wb I-44   | 379+84                       |                     |                               |                     |   |
| 0380           | 6131014      | FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR  | 10/31/23    | 11/3/23                 | 50.00              | LF    | Lane 1 wb I-44   | 397+17                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 60.00              | LF    | Lane 2 wb I-44   | 340+49                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 60.00              | LF    | Lane 2 wb I-44   | 359+93                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 60.00              | LF    | Lane 3 wb I-44   | 392+77                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 84.00              | LF    | Lane 3 wb I-44   | 364+77                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 132.00             | LF    | Lane 2 wb I-44   | 379+84                       |                     |                               |                     |   |
| 0390           | 6131015      | DOWEL BAR (DRILLING, FURNISHING AND INST | 10/31/23    | 11/3/23                 | 8.00               | EA    | Lane 1 wb I-44   | 397+18                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 8.00               | EA    | Lane 2 wb I-44   | 340+49                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 8.00               | EA    | Lane 2 wb I-44   | 359+93                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 8.00               | EA    | Lane 2 wb I-44   | 379+84                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 8.00               | EA    | Lane 3 wb I-44   | 364+77                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 8.00               | EA    | Lane 3 wb I-44   | 392+77                       |                     |                               |                     |   |
| 0400           | 6131018      | TIE BAR (DRILL, FURN & INSTAL) (TYPE L   | 10/31/23    | 11/3/23                 | 10.00              | EA    | Lane 1 wb I-44   | 397+17                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 12.00              | EA    | Lane 2 wb I-44   | 340+49                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 12.00              | EA    | Lane 2 wb I-44   | 359+93                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 12.00              | EA    | Lane 3 wb I-44   | 392+77                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 28.00              | EA    | Lane 3 wb I-44   | 364+77                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 32.00              | EA    | Lane 2 wb I-44   | 379+84                       |                     |                               |                     |   |
| 0430           | 6149902      | MISC. DRAINAGE FITTINGS                  | 10/31/23    | 11/3/23                 | 1.00               |       | I-44 Inlet Lt Side of Median   | 341+72                       |                     |                               |                     |   |
|                |              |  |             | 11/3/23                 | 1.00               |       | I-44 Inlet Rt Side of Median   | 340+66                       |                     |                               |                     |   |
| 0470           | 6173000      | CONCRETE TRAFFIC BARRIER, TYPE C         | 10/31/23    | 11/3/23                 | 4,274.00           | LF    | Completes Wall Qtys 313+89.12 to 340+97 (Trans) 341+80 to 353+08 (Trans) 355+39 to 371+28 (Trans) 373+56 to 382+85 (Trans) 386+86 to 394+33. | 313+89.12<br>median          | 394+33<br>median    |                               |                     | Includes 60ft of Transitions from Type C to Type A per plans. |

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023 Page 10 of 19



| Project | Line   | Description                             | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number                  | Created<br>Date   | Created<br>By   | Amount   | Remarks  |
|---------|--------|---|--------------------|-----------------------------|---------------------------------|---|---|--|--|
| J6I3568 | 0050   | TYPE 5<br>AGGREGATE<br>FOR BASE         | Material           |                             | 5                               | Aug 16,<br>2023   | SYSTEM  | \$2,195.60   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kirchm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.   |
|         |        |   |                    |                             | 5                               | Aug 16,<br>2023   | SYSTEM  | (\$2,195.60)   |  |
|         |        |   |                    |                             | 6                               | Sep 5,<br>2023  | SYSTEM  | \$2,195.60   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  |
|         |        |   |                    |                             | 6                               | Sep 5,<br>2023  | SYSTEM  | (\$2,195.60)   |  |
|         |        |   |                    |                             | 7                               | Sep 18,<br>2023   | SYSTEM  | \$2,195.60   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  |
|         |        |   |                    |                             | 7                               | Sep 18,<br>2023   | SYSTEM  | (\$2,195.60)   |  |
|         |        |   |                    |                             | 8                               | Oct 3,<br>2023  | SYSTEM  | \$2,195.60   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jimenj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.   |
|         |        |   |                    |                             | 8                               | Oct 3,<br>2023  | SYSTEM  | (\$2,195.60)   |  |
|         |        |   |                    |                             | 9                               | Oct 16,<br>2023   | SYSTEM  | \$2,195.60   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  |
|         |        |   |                    |                             | 9                               | Oct 16,<br>2023   | SYSTEM  | (\$2,195.60)   |  |
|         |        |   |                    |                             | 10                              | Nov 3,<br>2023  | SYSTEM  | \$2,195.60   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  |
|         |        |   |                    |                             | 10                              | Nov 3,<br>2023  | SYSTEM  | (\$2,195.60)   |  |
|         |        |   |                    | - Total                     |                                 |   |   | \$0.00   |  |
|         |        |   | Material - To      | tal                         |                                 |   |   | \$0.00   |  |
|         |        |   |                    |                             |                                 |   |   |  |  |
|         | 0050 - | · Total                                 |                    |                             |                                 |   |   | \$0.00   |  |
|         | 0050 - | TYPE 5<br>AGGREGATE<br>FOR BASE (6 IN.  | Material           |                             | 6                               | Sep 5,<br>2023  | SYSTEM  | \$2,208.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  |
|         |        | TYPE 5<br>AGGREGATE                     | Material           |                             | 6                               |   | SYSTEM SYSTEM   |  | Estimate Item Adjustment (0006) due to user wilesd overridding Payment   |
|         |        | TYPE 5<br>AGGREGATE<br>FOR BASE (6 IN.  | Material           |                             |                                 | 2023<br>Sep 5,  |   | \$2,208.00   | Estimate Item Adjustment (0006) due to user wilesd overridding Payment   |
|         |        | TYPE 5<br>AGGREGATE<br>FOR BASE (6 IN.  | Material           |                             | 6                               | 2023<br>Sep 5,<br>2023<br>Sep 18,   | SYSTEM  | \$2,208.00<br>(\$2,208.00)   | Estimate Item Adjustment (0006) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment  |
|         |        | TYPE 5<br>AGGREGATE<br>FOR BASE (6 IN.  | Material           |                             | 6                               | 2023<br>Sep 5,<br>2023<br>Sep 18,<br>2023   | SYSTEM SYSTEM   | \$2,208.00<br>(\$2,208.00)<br>\$2,208.00   | Estimate Item Adjustment (0006) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment  |
|         |        | TYPE 5<br>AGGREGATE<br>FOR BASE (6 IN.  | Material           |                             | 6<br>7<br>7                     | 2023<br>Sep 5,<br>2023<br>Sep 18,<br>2023<br>Sep 18,<br>2023<br>Oct 3,                  | SYSTEM SYSTEM   | \$2,208.00<br>(\$2,208.00)<br>\$2,208.00<br>(\$2,208.00)   | Estimate Item Adjustment (0006) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jimenj1 overridding Payment  |
|         |        | TYPE 5<br>AGGREGATE<br>FOR BASE (6 IN.  | Material           |                             | 6<br>7<br>7<br>8                | 2023<br>Sep 5,<br>2023<br>Sep 18,<br>2023<br>Sep 18,<br>2023<br>Oct 3,<br>2023          | SYSTEM SYSTEM SYSTEM SYSTEM                             | \$2,208.00<br>(\$2,208.00)<br>\$2,208.00<br>(\$2,208.00)<br>\$2,208.00   | Estimate Item Adjustment (0006) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jimenj1 overridding Payment  |
|         |        | TYPE 5<br>AGGREGATE<br>FOR BASE (6 IN.  | Material           |                             | 6 7 7 8 8 8                     | 2023 Sep 5, 2023 Sep 18, 2023 Sep 18, 2023 Oct 3, 2023 Oct 3, 2023 Oct 16,              | SYSTEM SYSTEM SYSTEM SYSTEM                             | \$2,208.00<br>(\$2,208.00)<br>\$2,208.00<br>(\$2,208.00)<br>\$2,208.00   | Estimate Item Adjustment (0006) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jimenj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment  |
|         |        | TYPE 5<br>AGGREGATE<br>FOR BASE (6 IN.  | Material           |                             | 6 7 7 8 8 8 9                   | 2023 Sep 5, 2023 Sep 18, 2023 Sep 18, 2023 Oct 3, 2023 Oct 16, 2023 Oct 16, 2023        | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM                      | \$2,208.00<br>(\$2,208.00)<br>\$2,208.00<br>(\$2,208.00)<br>\$2,208.00<br>(\$2,208.00)   | Estimate Item Adjustment (0006) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jimenj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment  |
|         |        | TYPE 5<br>AGGREGATE<br>FOR BASE (6 IN.  | Material           |                             | 6 7 7 8 8 8 9 9                 | 2023 Sep 5, 2023 Sep 18, 2023 Sep 18, 2023 Oct 3, 2023 Oct 16, 2023 Oct 16, 2023 Nov 3, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM               | \$2,208.00<br>(\$2,208.00)<br>\$2,208.00<br>(\$2,208.00)<br>\$2,208.00<br>(\$2,208.00)<br>\$2,208.00                           | Estimate Item Adjustment (0006) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jimenj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. |
|         |        | TYPE 5<br>AGGREGATE<br>FOR BASE (6 IN.  | Material           | - Total                     | 6<br>7<br>7<br>8<br>8<br>9<br>9 | 2023 Sep 5, 2023 Sep 18, 2023 Oct 3, 2023 Oct 16, 2023 Nov 3, 2023                      | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$2,208.00 (\$2,208.00) \$2,208.00 (\$2,208.00) \$2,208.00 (\$2,208.00) \$2,208.00 (\$2,208.00) \$2,208.00                     | Estimate Item Adjustment (0006) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jimenj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. |
|         |        | TYPE 5<br>AGGREGATE<br>FOR BASE (6 IN.  | Material - To      |                             | 6<br>7<br>7<br>8<br>8<br>9<br>9 | 2023 Sep 5, 2023 Sep 18, 2023 Oct 3, 2023 Oct 16, 2023 Nov 3, 2023                      | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$2,208.00  (\$2,208.00)  \$2,208.00  (\$2,208.00)  \$2,208.00  (\$2,208.00)  \$2,208.00  (\$2,208.00)  \$2,208.00             | Estimate Item Adjustment (0006) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jimenj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. |
|         | 0060   | TYPE 5<br>AGGREGATE<br>FOR BASE (6 IN.  |                    |                             | 6<br>7<br>7<br>8<br>8<br>9<br>9 | 2023 Sep 5, 2023 Sep 18, 2023 Oct 3, 2023 Oct 16, 2023 Nov 3, 2023                      | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$2,208.00  (\$2,208.00)  \$2,208.00  (\$2,208.00)  \$2,208.00  (\$2,208.00)  \$2,208.00  (\$2,208.00)  \$2,208.00  \$2,208.00 | Estimate Item Adjustment (0006) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jimenj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. |
|         | 0060   | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material - To      |                             | 6<br>7<br>7<br>8<br>8<br>9<br>9 | 2023 Sep 5, 2023 Sep 18, 2023 Oct 3, 2023 Oct 16, 2023 Nov 3, 2023                      | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$2,208.00  (\$2,208.00)  \$2,208.00  (\$2,208.00)  \$2,208.00  (\$2,208.00)  \$2,208.00  (\$2,208.00)  \$2,208.00  \$2,000.00 | Estimate Item Adjustment (0006) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jimenj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. |



| Project | Line   | Description             | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By   | Amount        | Remarks  |  |
|---------|--------|-------------------------|--------------------|-----------------------------|----------------|-----------------|-----------------|---------------|--|--|
| J6I3568 | 0170   | CONCRETE<br>PAVEMENT (7 | Material           |                             |                | 2023            |                 |               |  |  |
|         |        | IN. NON-<br>REINFORCED, |                    |                             | 7              | Sep 18,<br>2023 | SYSTEM          | \$12,224.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilesd overridding Payment Estimate Exception 3 on the current Payment Estimate.  |  |
|         |        |                         |                    |                             | 7              | Sep 18,<br>2023 | SYSTEM          | (\$12,224.00) |  |  |
|         |        |                         |                    |                             | 8              | Oct 3,<br>2023  | SYSTEM          | \$12,224.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user jimenj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |  |
|         |        |                         |                    |                             | 8              | Oct 3,<br>2023  | SYSTEM          | (\$12,224.00) |  |  |
|         |        |                         |                    |                             | 9              | Oct 16,<br>2023 | SYSTEM          | \$12,224.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilesd overridding Payment Estimate Exception 3 on the current Payment Estimate.  |  |
|         |        |                         |                    |                             | 9              | Oct 16,<br>2023 | SYSTEM          | (\$12,224.00) |  |  |
|         |        |                         |                    |                             | 10             | Nov 3,<br>2023  | SYSTEM          | \$12,224.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user wilesd overridding Payment Estimate Exception 3 on the current Payment Estimate.  |  |
|         |        |                         |                    |                             | 10             | Nov 3,<br>2023  | SYSTEM          | (\$12,224.00) |  |  |
|         |        |                         |                    | - Total                     |                |                 |                 | \$0.00        |  |  |
|         |        |                         | Material - Tot     | tal                         |                |                 |                 | \$0.00        |  |  |
|         | 0170 - | Total                   |                    |                             |                |                 |                 | \$0.00        |  |  |
|         | 0220   | CONCRETE<br>CURB RAMP   | Material           |                             | 4              | Aug 2,<br>2023  | SYSTEM          | \$7,416.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  |  |
|         |        |                         |                    |                             | 4              | Aug 2,<br>2023  | SYSTEM          | (\$7,416.00)  |  |  |
|         |        |                         |                    |                             | 5              | Aug 16,<br>2023 | SYSTEM          | \$7,416.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kirchm1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |  |
|         |        |                         |                    |                             | 5              | Aug 16,<br>2023 | SYSTEM          | (\$7,416.00)  |  |  |
|         |        |                         |                    |                             | 6              | Sep 5,<br>2023  | SYSTEM          | \$11,124.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilesd overridding Payment Estimate Exception 6 on the current Payment Estimate.  |  |
|         |        |                         |                    |                             | 6              | Sep 5,<br>2023  | SYSTEM          | (\$11,124.00) |  |  |
|         |        |                         |                    |                             | 7              | Sep 18,<br>2023 | SYSTEM          | \$11,124.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilesd overridding Payment Estimate Exception 6 on the current Payment Estimate.  |  |
|         |        |                         |                    |                             | 7              | Sep 18,<br>2023 | SYSTEM          | (\$11,124.00) |  |  |
|         |        |                         |                    |                             | 8              | Oct 3,<br>2023  | SYSTEM          | \$11,124.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user jimenj1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |  |
|         |        |                         |                    |                             | 8              | Oct 3,<br>2023  | SYSTEM          | (\$11,124.00) |  |  |
|         |        |                         |                    |                             | 9              | Oct 16,<br>2023 | SYSTEM          | \$11,124.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilesd overridding Payment Estimate Exception 6 on the current Payment Estimate.  |  |
|         |        |                         | Ę                  |                             |                | 9               | Oct 16,<br>2023 | SYSTEM        | (\$11,124.00)  |  |
|         |        |                         |                    |                             | 10             | Nov 3,<br>2023  | SYSTEM          | \$11,124.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user wilesd overridding Payment Estimate Exception 5 on the current Payment Estimate.  |  |
|         |        |                         |                    |                             | 10             | Nov 3,<br>2023  | SYSTEM          | (\$11,124.00) |  |  |
|         |        |                         |                    | - Total                     |                |                 |                 | \$0.00        |  |  |
|         |        |                         | Material - Tot     | tal                         |                |                 |                 | \$0.00        |  |  |
|         | 0220 - | Total                   |                    |                             |                |                 |                 | \$0.00        |  |  |
|         | 0230   | TRUNCATED DOMES         | Material           |                             | 4              | Aug 2,<br>2023  | SYSTEM          | \$3,000.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilesd overridding Payment Estimate Exception 3 on the current Payment Estimate.  |  |



| Project | Line   | Description                       | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks  |
|---------|--------|-----------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| J6I3568 | 0230   | TRUNCATED DOMES                   | Material           |                             | 4              | Aug 2,<br>2023  | SYSTEM        | (\$3,000.00)  |  |
|         |        |                                   |                    |                             | 5              | Aug 16,<br>2023 | SYSTEM        | \$3,000.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kirchm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
|         |        |                                   |                    |                             | 5              | Aug 16,<br>2023 | SYSTEM        | (\$3,000.00)  |  |
|         |        |                                   |                    |                             | 6              | Sep 5,<br>2023  | SYSTEM        | \$3,000.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wilesd overridding Payment Estimate Exception 8 on the current Payment Estimate.  |
|         |        |                                   |                    |                             | 6              | Sep 5,<br>2023  | SYSTEM        | (\$3,000.00)  |  |
|         |        |                                   |                    |                             | 7              | Sep 18,<br>2023 | SYSTEM        | \$3,000.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilesd overridding Payment Estimate Exception 8 on the current Payment Estimate.  |
|         |        |                                   |                    |                             | 7              | Sep 18,<br>2023 | SYSTEM        | (\$3,000.00)  |  |
|         |        |                                   |                    | - Total                     |                |                 |               | \$0.00        |  |
|         |        |                                   | Material - Tot     | tal                         |                |                 |               | \$0.00        |  |
|         | 0230 - | Total                             |                    |                             |                |                 |               | \$0.00        |  |
|         | 0240   | 6 IN.<br>CONCRETE<br>MEDIAN STRIP | Material           |                             | 4              | Aug 2,<br>2023  | SYSTEM        | \$19,971.20   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilesd overridding Payment Estimate Exception 4 on the current Payment Estimate.  |
|         |        |                                   |                    |                             | 4              | Aug 2,<br>2023  | SYSTEM        | (\$19,971.20) |  |
|         |        |                                   |                    |                             | 5              | Aug 16,<br>2023 | SYSTEM        | \$19,971.20   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kirchm1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
|         |        |                                   |                    |                             | 5              | Aug 16,<br>2023 | SYSTEM        | (\$19,971.20) |  |
|         |        |                                   |                    |                             | 6              | Sep 5,<br>2023  | SYSTEM        | \$19,971.20   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilesd overridding Payment Estimate Exception 9 on the current Payment Estimate.  |
|         |        |                                   |                    |                             | 6              | Sep 5,<br>2023  | SYSTEM        | (\$19,971.20) |  |
|         |        |                                   |                    |                             | 7              | Sep 18,<br>2023 | SYSTEM        | \$19,971.20   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesd overridding Payment Estimate Exception 9 on the current Payment Estimate.  |
|         |        |                                   |                    |                             | 7              | Sep 18,<br>2023 | SYSTEM        | (\$19,971.20) |  |
|         |        |                                   |                    |                             | 8              | Oct 3,<br>2023  | SYSTEM        | \$19,971.20   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user jimenj1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
|         |        |                                   |                    |                             | 8              | Oct 3,<br>2023  | SYSTEM        | (\$19,971.20) |  |
|         |        |                                   |                    |                             | 9              | Oct 16,<br>2023 | SYSTEM        | \$19,971.20   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilesd overridding Payment Estimate Exception 8 on the current Payment Estimate.  |
|         |        |                                   |                    |                             | 9              | Oct 16,<br>2023 | SYSTEM        | (\$19,971.20) |  |
|         |        |                                   |                    |                             | 10             | Nov 3,<br>2023  | SYSTEM        | \$19,971.20   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wilesd overridding Payment Estimate Exception 7 on the current Payment Estimate.  |
|         |        |                                   |                    |                             | 10             | Nov 3,<br>2023  | SYSTEM        | (\$19,971.20) |  |
|         |        |                                   |                    | - Total                     |                |                 |               | \$0.00        |  |
|         |        |                                   | Material - To      | tal                         |                |                 |               | \$0.00        |  |
|         | 0240 - |                                   |                    |                             |                |                 |               | \$0.00        |  |
|         | 0250   | CONCRETE<br>SIDEWALK, 4 IN.       | Material           |                             | 4              | Aug 2,<br>2023  | SYSTEM        | \$9,980.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesd overridding Payment Estimate Exception 5 on the current Payment Estimate.  |
|         |        |                                   |                    |                             | 4              | Aug 2,<br>2023  | SYSTEM        | (\$9,980.00)  |  |
|         |        |                                   |                    |                             | 5              | Aug 16,<br>2023 | SYSTEM        | \$9,980.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kirchm1 overridding Payment   |



| Project | Line   | Description  | Adjustment              | Other<br>Adjustment | Est.<br>Number                  | Created<br>Date   | Created  | Amount  | Remarks  |
|---------|--------|--|-------------------------|---------------------|---------------------------------|---|--|---|--|
|         |        |  | Туре                    | Type                | Number                          | Date  | Ву   |   |  |
| J6I3568 | 0250   | CONCRETE<br>SIDEWALK, 4 IN.  | Material                |                     |                                 |   |  |   | Estimate Exception 6 on the current Payment Estimate.  |
|         |        | ,  |                         |                     | 5                               | Aug 16,<br>2023   | SYSTEM   | (\$9,980.00)  |  |
|         |        |  |                         |                     | 6                               | Sep 5,<br>2023  | SYSTEM   | \$9,980.00  | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wilesd overridding Payment Estimate Exception 10 on the current Payment Estimate.   |
|         |        |  |                         |                     | 6                               | Sep 5,<br>2023  | SYSTEM   | (\$9,980.00)  |  |
|         |        |  |                         |                     | 7                               | Sep 18,<br>2023   | SYSTEM   | \$9,980.00  | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilesd overridding Payment Estimate Exception 10 on the current Payment Estimate.   |
|         |        |  |                         |                     | 7                               | Sep 18,<br>2023   | SYSTEM   | (\$9,980.00)  |  |
|         |        |  |                         |                     | 8                               | Oct 3,<br>2023  | SYSTEM   | \$9,980.00  | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user jimenj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.   |
|         |        |  |                         |                     | 8                               | Oct 3,<br>2023  | SYSTEM   | (\$9,980.00)  |  |
|         |        |  |                         |                     | 9                               | Oct 16,<br>2023   | SYSTEM   | \$9,980.00  | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesd overridding Payment Estimate Exception 9 on the current Payment Estimate.  |
|         |        |  |                         |                     | 9                               | Oct 16,<br>2023   | SYSTEM   | (\$9,980.00)  |  |
|         |        |  |                         |                     | 10                              | Nov 3,<br>2023  | SYSTEM   | \$9,980.00  | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user wilesd overridding Payment Estimate Exception 8 on the current Payment Estimate.  |
|         |        |  |                         |                     | 10                              | Nov 3,<br>2023  | SYSTEM   | (\$9,980.00)  |  |
|         |        |  |                         | - Total             |                                 |   |  | \$0.00  |  |
|         |        |  | Material - To           | tal                 |                                 |   |  | \$0.00  |  |
|         |        |  |                         |                     |                                 |   |  |   |  |
|         | 0250 - | · I otal   |                         |                     |                                 |   |  | \$0.00  |  |
|         | 0250 - | IMPACT<br>ATTENUATOR<br>65 MPH (SAND   | Material                |                     | 3                               | Jul 17,<br>2023   | SYSTEM   | <b>\$0.00</b><br>\$10,000.00  | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  |
|         |        | IMPACT<br>ATTENUATOR   | Material                |                     | 3                               |   | SYSTEM   |   | Estimate Item Adjustment (0001) due to user wilesd overridding Payment   |
|         |        | IMPACT<br>ATTENUATOR<br>65 MPH (SAND<br>BARREL   | Material                |                     |                                 | 2023<br>Jul 17,   |  | \$10,000.00   | Estimate Item Adjustment (0001) due to user wilesd overridding Payment   |
|         |        | IMPACT<br>ATTENUATOR<br>65 MPH (SAND<br>BARREL   | Material                |                     | 3                               | Jul 17,<br>2023<br>Aug 2,   | SYSTEM   | \$10,000.00<br>(\$10,000.00)  | Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment  |
|         |        | IMPACT<br>ATTENUATOR<br>65 MPH (SAND<br>BARREL   | Material                |                     | 3                               | Jul 17,<br>2023<br>Aug 2,<br>2023   | SYSTEM   | \$10,000.00<br>(\$10,000.00)<br>\$10,000.00   | Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment  |
|         |        | IMPACT<br>ATTENUATOR<br>65 MPH (SAND<br>BARREL   | Material                |                     | 3 4                             | 2023<br>Jul 17,<br>2023<br>Aug 2,<br>2023<br>Aug 2,<br>2023<br>Aug 16,                                      | SYSTEM SYSTEM                                    | \$10,000.00<br>(\$10,000.00)<br>\$10,000.00<br>(\$10,000.00)  | Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kirchm1 overridding Payment  |
|         |        | IMPACT<br>ATTENUATOR<br>65 MPH (SAND<br>BARREL   | Material                |                     | 3<br>4<br>4<br>5                | 2023<br>Jul 17,<br>2023<br>Aug 2,<br>2023<br>Aug 2,<br>2023<br>Aug 16,<br>2023                              | SYSTEM SYSTEM SYSTEM SYSTEM                      | \$10,000.00<br>(\$10,000.00)<br>\$10,000.00<br>(\$10,000.00)<br>\$10,000.00   | Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kirchm1 overridding Payment  |
|         |        | IMPACT<br>ATTENUATOR<br>65 MPH (SAND<br>BARREL   | Material                |                     | 3<br>4<br>4<br>5                | 2023<br>Jul 17,<br>2023<br>Aug 2,<br>2023<br>Aug 2,<br>2023<br>Aug 16,<br>2023<br>Aug 16,<br>2023<br>Sep 5, | SYSTEM SYSTEM SYSTEM SYSTEM                      | \$10,000.00<br>(\$10,000.00)<br>\$10,000.00<br>(\$10,000.00)<br>\$10,000.00   | Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kirchm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment  |
|         |        | IMPACT<br>ATTENUATOR<br>65 MPH (SAND<br>BARREL   | Material                | - Total             | 3 4 4 5 5 6 6                   | 2023 Jul 17, 2023 Aug 2, 2023 Aug 16, 2023 Aug 16, 2023 Sep 5, 2023 Sep 5,                                  | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM               | \$10,000.00<br>(\$10,000.00)<br>\$10,000.00<br>(\$10,000.00)<br>\$10,000.00<br>(\$10,000.00)  | Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kirchm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment  |
|         | 0310   | IMPACT<br>ATTENUATOR<br>65 MPH (SAND<br>BARREL<br>ARRAY)                                   | Material  Material - To |                     | 3 4 4 5 5 6 6                   | 2023 Jul 17, 2023 Aug 2, 2023 Aug 16, 2023 Aug 16, 2023 Sep 5, 2023 Sep 5,                                  | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM               | \$10,000.00<br>(\$10,000.00)<br>\$10,000.00<br>(\$10,000.00)<br>\$10,000.00<br>(\$10,000.00)<br>(\$10,000.00)                                 | Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kirchm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment  |
|         | 0310   | IMPACT<br>ATTENUATOR<br>65 MPH (SAND<br>BARREL   |                         |                     | 3 4 4 5 5 6 6                   | 2023 Jul 17, 2023 Aug 2, 2023 Aug 16, 2023 Aug 16, 2023 Sep 5, 2023 Sep 5,                                  | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM               | \$10,000.00<br>(\$10,000.00)<br>\$10,000.00<br>(\$10,000.00)<br>\$10,000.00<br>(\$10,000.00)<br>\$10,000.00                                   | Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kirchm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment  |
|         | 0310   | IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)  Total  FURN & PLACE CONC MATL FOR FULL       | Material - To           |                     | 3 4 4 5 5 6 6                   | 2023 Jul 17, 2023 Aug 2, 2023 Aug 16, 2023 Aug 16, 2023 Sep 5, 2023 Sep 5,                                  | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM               | \$10,000.00 (\$10,000.00) \$10,000.00 (\$10,000.00) \$10,000.00 (\$10,000.00) \$10,000.00 (\$10,000.00) \$0.00                                | Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kirchm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment  |
|         | 0310   | IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)  Total  FURN & PLACE CONC MATL                | Material - To           |                     | 3 4 4 5 5 6 6 6                 | 2023 Jul 17, 2023 Aug 2, 2023 Aug 16, 2023 Aug 16, 2023 Sep 5, 2023 Nov 3,                                  | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$10,000.00 (\$10,000.00) \$10,000.00 (\$10,000.00) \$10,000.00 (\$10,000.00) \$10,000.00 (\$10,000.00) \$0.00 \$0.00                         | Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kirchm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment |
|         | 0310   | IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)  Total  FURN & PLACE CONC MATL FOR FULL       | Material - To           |                     | 3<br>4<br>4<br>5<br>5<br>6<br>6 | 2023 Jul 17, 2023 Aug 2, 2023 Aug 16, 2023 Aug 16, 2023 Sep 5, 2023 Nov 3, 2023 Nov 3,                      | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$10,000.00 (\$10,000.00) \$10,000.00 (\$10,000.00) \$10,000.00 (\$10,000.00) \$10,000.00 \$0.00 \$0.00 \$0.00 \$67,824.00                    | Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kirchm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment |
|         | 0310   | IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)  Total  FURN & PLACE CONC MATL FOR FULL       | Material - To           | tal<br>- Total      | 3<br>4<br>4<br>5<br>5<br>6<br>6 | 2023 Jul 17, 2023 Aug 2, 2023 Aug 16, 2023 Aug 16, 2023 Sep 5, 2023 Nov 3, 2023 Nov 3,                      | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$10,000.00 (\$10,000.00) \$10,000.00) (\$10,000.00) (\$10,000.00) (\$10,000.00) (\$10,000.00) \$0.00 \$0.00 \$0.00 \$67,824.00)              | Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kirchm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment |
|         | 0310   | IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)  Total  FURN & PLACE CONC MATL FOR FULL DEPTH | Material - To           | tal<br>- Total      | 3<br>4<br>4<br>5<br>5<br>6<br>6 | 2023 Jul 17, 2023 Aug 2, 2023 Aug 16, 2023 Aug 16, 2023 Sep 5, 2023 Nov 3, 2023 Nov 3,                      | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$10,000.00  (\$10,000.00)  \$10,000.00)  (\$10,000.00)  \$10,000.00)  \$10,000.00  (\$10,000.00)  \$0.00  \$0.00  \$67,824.00  (\$67,824.00) | Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kirchm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment |



| Project | Line   | Description                                  | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number  | Created<br>Date | Created<br>By  | Amount         | Remarks  |              |   |   |                 |        |              |  |
|---------|--------|--|--------------------|-----------------------------|-----------------|-----------------|----------------|----------------|--|--------------|---|---|-----------------|--------|--------------|--|
| J6I3568 | 0390   | (DRILLING,<br>FURNISHING<br>AND INST         | Material           |                             |                 | 2023            |                |                | Estimate Item Adjustment (0002) due to user wilesd overridding Payment Estimate Exception 10 on the current Payment Estimate.  |              |   |   |                 |        |              |  |
|         |        | AND INST                                     |                    |                             | 10              | Nov 3,<br>2023  | SYSTEM         | (\$1,392.00)   |  |              |   |   |                 |        |              |  |
|         |        |  |                    | - Total                     |                 |                 |                | \$0.00         |  |              |   |   |                 |        |              |  |
|         |        |  | Material - To      | tal                         |                 |                 |                | \$0.00         |  |              |   |   |                 |        |              |  |
|         | 0390 - | Total  |                    |                             |                 |                 |                | \$0.00         |  |              |   |   |                 |        |              |  |
|         | 0400   | TIE BAR (DRILL,<br>FURN & INSTAL)<br>(TYPE L | Material           |                             | 10              | Nov 3,<br>2023  | SYSTEM         | \$1,590.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 12 on the current Payment Estimate. |              |   |   |                 |        |              |  |
|         |        |  |                    |                             | 10              | Nov 3,<br>2023  | SYSTEM         | (\$1,590.00)   |  |              |   |   |                 |        |              |  |
|         |        |  |                    | - Total                     |                 |                 |                | \$0.00         |  |              |   |   |                 |        |              |  |
|         |        |  | Material - To      | tal                         |                 |                 |                | \$0.00         |  |              |   |   |                 |        |              |  |
|         | 0400 - | Total  |                    |                             |                 |                 |                | \$0.00         |  |              |   |   |                 |        |              |  |
|         | 0460   | MISC. TRAFFIC<br>CONTROL<br>DEVICES          | Material           |                             | 2               | Jul 3,<br>2023  | SYSTEM         | \$6,400.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 1 on the current Payment Estimate.  |              |   |   |                 |        |              |  |
|         |        |  |                    |                             | 2               | Jul 3,<br>2023  | SYSTEM         | (\$6,400.00)   |  |              |   |   |                 |        |              |  |
|         |        |  |                    |                             | 3               | Jul 17,<br>2023 | SYSTEM         | \$6,400.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilesd overridding Payment Estimate Exception 2 on the current Payment Estimate.  |              |   |   |                 |        |              |  |
|         |        |  |                    |                             | 3               | Jul 17,<br>2023 | SYSTEM         | (\$6,400.00)   |  |              |   |   |                 |        |              |  |
|         |        |  |                    |                             | 4               | Aug 2,<br>2023  | SYSTEM         | \$6,400.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilesd overridding Payment Estimate Exception 7 on the current Payment Estimate.  |              |   |   |                 |        |              |  |
|         |        |  |                    |                             | 4               | Aug 2,<br>2023  | SYSTEM         | (\$6,400.00)   |  |              |   |   |                 |        |              |  |
|         |        |  |                    |                             | 5               | Aug 16,<br>2023 | SYSTEM         | \$6,400.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kirchm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |              |   |   |                 |        |              |  |
|         |        |  |                    |                             | 5               | Aug 16,<br>2023 | SYSTEM         | (\$6,400.00)   |  |              |   |   |                 |        |              |  |
|         |        |  |                    |                             | 6               | Sep 5,<br>2023  | SYSTEM         | \$6,400.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilesd overridding Payment Estimate Exception 12 on the current Payment Estimate. |              |   |   |                 |        |              |  |
|         |        |  |                    |                             | 6               | Sep 5,<br>2023  | SYSTEM         | (\$6,400.00)   |  |              |   |   |                 |        |              |  |
|         |        |  |                    | - Total                     |                 |                 |                | \$0.00         |  |              |   |   |                 |        |              |  |
|         |        |  | Material - To      | tal                         |                 |                 |                | \$0.00         |  |              |   |   |                 |        |              |  |
|         | 0460 - | Total  |                    |                             |                 |                 |                | \$0.00         |  |              |   |   |                 |        |              |  |
|         | 0470   | Total  CONCRETE TRAFFIC BARRIER, TYPE        | Material           |                             | 6               | Sep 5,<br>2023  | SYSTEM         | \$292,200.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 13 on the current Payment Estimate. |              |   |   |                 |        |              |  |
|         |        | С  |                    |                             | 6               | Sep 5,<br>2023  | SYSTEM         | (\$292,200.00) |  |              |   |   |                 |        |              |  |
|         |        |  |                    |                             |                 |                 |                |                |  |              |   | 7 | Sep 18,<br>2023 | SYSTEM | \$292,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilesd overridding Payment Estimate Exception 11 on the current Payment Estimate. |
|         |        |  |                    | 7                           | Sep 18,<br>2023 | SYSTEM          | (\$292,200.00) |                |  |              |   |   |                 |        |              |  |
|         |        |  |                    |                             |                 |                 | 8              | Oct 3,<br>2023 | SYSTEM   | \$292,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user jimenj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |   |                 |        |              |  |
|         |        |  |                    | S                           | 8               | Oct 3,<br>2023  | SYSTEM         | (\$292,200.00) |  |              |   |   |                 |        |              |  |
|         |        |  |                    |                             | 9               | Oct 16,<br>2023 | SYSTEM         | \$292,200.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilesd overridding Payment Estimate Exception 10 on the current Payment Estimate. |              |   |   |                 |        |              |  |
|         |        |  |                    |                             | 9               | Oct 16,<br>2023 | SYSTEM         | (\$292,200.00) |  |              |   |   |                 |        |              |  |



| ect | Line   | Description                                       | Adjustment<br>Type                | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount                       | Remarks  |
|-----|--------|---|-----------------------------------|-----------------------------|----------------|-----------------|---------------|------------------------------|--|
| 568 | 0470   | CONCRETE<br>TRAFFIC<br>BARRIER, TYPE<br>C         | Material                          |                             | 10             | Nov 3,<br>2023  | SYSTEM        | \$719,600.00                 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilesd overridding Payment Estimate Exception 14 on the current Payment Estimate. |
|     |        | 0   |                                   |                             | 10             | Nov 3,<br>2023  | SYSTEM        | (\$719,600.00)               |  |
|     |        |   |                                   | - Total                     |                |                 |               | \$0.00                       |  |
|     |        |   | Material - Tot                    | tal                         |                |                 |               | \$0.00                       |  |
|     | 0470 - | Total   |                                   |                             |                |                 |               | \$0.00                       |  |
|     | 0480   | TEMPORARY<br>TRAFFIC<br>BARRIER,<br>CONT. FURN/RE | Material                          |                             | 3              | Jul 17,<br>2023 | SYSTEM        | \$294,997.96                 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 3 on the current Payment Estimate.  |
|     |        | CONT. I OKN/KL                                    |                                   |                             | 3              | Jul 17,<br>2023 | SYSTEM        | (\$294,997.96)               |  |
|     |        |   |                                   |                             | 4              | Aug 2,<br>2023  | SYSTEM        | \$294,997.96                 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilesd overridding Payment Estimate Exception 8 on the current Payment Estimate.  |
|     |        |   |                                   |                             | 4              | Aug 2,<br>2023  | SYSTEM        | (\$294,997.96)               |  |
|     |        |   |                                   |                             | 5              | Aug 16,<br>2023 | SYSTEM        | \$294,997.96                 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kirchm1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
|     |        |   |                                   |                             | 5              | Aug 16,<br>2023 | SYSTEM        | (\$294,997.96)               |  |
|     |        |   |                                   |                             | 6              | Sep 5,<br>2023  | SYSTEM        | \$586,034.00                 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilesd overridding Payment Estimate Exception 17 on the current Payment Estimate. |
|     |        |   |                                   |                             | 6              | Sep 5,<br>2023  | SYSTEM        | (\$586,034.00)               |  |
|     |        |   |                                   | - Total                     |                |                 |               | \$0.00                       |  |
|     |        |   | Material - Tot                    | tal                         |                |                 |               | \$0.00                       |  |
|     | 0480 - | Total   |                                   |                             |                |                 |               | \$0.00                       |  |
|     | 0830   | MGS<br>GUARDRAIL                                  | Construction<br>Stockpile<br>STMI | Total                       | 1              | May 1,<br>2023  | SYSTEM        | \$178,226.88                 | Payment Estimate Item Adjustment generated Stockpile Transaction   |
|     |        |   | O a madema atia m                 | - Total                     | TABLE TO A S   |                 |               | \$178,226.88                 |  |
|     | 0830 - | Total   | Construction                      | Stockpile S1                | IVII - TOTA    |                 |               | \$178,226.88                 |  |
|     | 0840   | MGS   | Construction                      |                             | 1              | May 1,          | SYSTEM        | \$178,226.88<br>\$443,656.50 | Payment Estimate Item Adjustment generated Stockpile Transaction   |
|     | 0040   | GUARDRAIL, 8<br>FT. POSTS, 6                      | Stockpile<br>STMI                 | - Total                     | 1              | 2023            | SISILM        | \$443,656.50                 | r ayınını Esimate nem Aujusinen generateu Stocopile Harisaction  |
|     |        | FT 3 IN   | Construction                      |                             | IMI Total      |                 |               | \$443,656.50                 |  |
|     | 0840 - | Total   | Construction                      | Stockpile S1                | IVII - TOTAI   |                 |               | \$443,656.50                 |  |
| ľ   | 0850   | MGS BRIDGE  | Construction                      |                             | 1              | May 1.          | SYSTEM        | \$38,855.00                  | Payment Estimate Item Adjustment generated Stockpile Transaction   |
|     |        | APP. TRANS<br>SEC (REG/NO                         |                                   | - Total                     |                | 2023            |               | \$38.855.00                  |  |
|     |        | CURB)   | Construction                      |                             | MI - Total     |                 |               | \$38,855.00                  |  |
|     | 0850 - | Total   |                                   |                             |                |                 |               | \$38,855.00                  |  |
|     | 0860   | MGS HEIGHT<br>AND BLOCK                           | Construction<br>Stockpile         |                             | 1              | May 1,<br>2023  | SYSTEM        | \$393.50                     | Payment Estimate Item Adjustment generated Stockpile Transaction   |
|     |        | TRANSITION  | STMI                              | - Total                     |                |                 |               | \$393.50                     |  |
|     |        |   | Construction                      | Stockpile S1                | MI - Total     |                 |               | \$393.50                     |  |
|     | 0860 - | Total   |                                   |                             |                |                 |               | \$393.50                     |  |
|     | 0870   | MGS END<br>ANCHOR                                 | Construction<br>Stockpile<br>STMI |                             | 1              | May 1,<br>2023  | SYSTEM        | \$29,600.00                  | Payment Estimate Item Adjustment generated Stockpile Transaction   |
|     |        |   | J.1411                            | - Total                     |                |                 |               | \$29,600.00                  |  |
|     |        |   | Construction                      | Stockpile S1                | MI - Total     |                 |               | \$29,600.00                  |  |
|     | 0870 - | Total   |                                   |                             |                |                 |               | \$29,600.00                  |  |
|     | 0880   | TYPE A CRASHWORTHY END TERMINAL                   | Construction<br>Stockpile<br>STMI |                             | 1              | May 1,<br>2023  | SYSTEM        | \$88,125.00                  | Payment Estimate Item Adjustment generated Stockpile Transaction   |
|     |        | (MASH)  |                                   | - Total                     |                |                 |               | \$88,125.00                  |  |



| oject | Line                       | Description   | Adjustment<br>Type      | Other<br>Adjustment<br>Type | Est.<br>Number                | Created<br>Date   | Created<br>By                             | Amount   | Remarks  |
|-------|----------------------------|---|-------------------------|-----------------------------|-------------------------------|---|---|--|--|
| 3568  | 0880                       | TYPE A<br>CRASHWORTHY<br>END TERMINAL<br>(MASH)   | Construction            | n Stockpile Sī              | ГМI - Total                   |   |   | \$88,125.00  |  |
|       | 0880 -                     | Total   |                         |                             |                               |   |   | \$88,125.00  |  |
|       | 0990                       | CONTROLLER<br>ASSEMBLY<br>HOUSING,  | Material                |                             | 9                             | Oct 16,<br>2023   | SYSTEM                                    | \$23,468.00  | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wilesd overridding Payment Estimate Exception 14 on the current Payment Estimate.   |
|       |                            |   |                         |                             | 9                             | Oct 16,<br>2023   | SYSTEM                                    | (\$23,468.00)  |  |
|       |                            |   |                         |                             | 10                            | Nov 3,<br>2023  | SYSTEM                                    | \$23,468.00  | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilesd overridding Payment Estimate Exception 17 on the current Payment Estimate.   |
|       |                            |   |                         |                             | 10                            | Nov 3,<br>2023  | SYSTEM                                    | (\$23,468.00)  |  |
|       |                            |   |                         | - Total                     |                               |   |   | \$0.00   |  |
|       |                            |   | Material - To           | tal                         |                               |   |   | \$0.00   |  |
|       | 0990 -                     | Total   |                         |                             |                               |   |   | \$0.00   |  |
|       | 1020                       | CONDUIT, 2 IN.,<br>TRENCH WITH<br>TRACER WIRE   | Material                |                             | 9                             | Oct 16,<br>2023   | SYSTEM                                    | \$378.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilesd overridding Payment Estimate Exception 15 on the current Payment Estimate.   |
|       |                            |   |                         |                             | 9                             | Oct 16,<br>2023   | SYSTEM                                    | (\$378.00)   |  |
|       |                            |   |                         |                             | 10                            | Nov 3,<br>2023  | SYSTEM                                    | \$378.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilesd overridding Payment Estimate Exception 18 on the current Payment Estimate.   |
|       |                            |   |                         |                             | 10                            | Nov 3,<br>2023  | SYSTEM                                    | (\$378.00)   |  |
|       |                            |   |                         | - Total                     |                               |   |   | \$0.00   |  |
|       |                            |   | Material - To           | tal                         |                               |   |   | \$0.00   |  |
|       | 4020                       | Total   |                         |                             |                               |   |   |  |  |
|       | 1020 -                     | TOLAI   |                         |                             |                               |   |   | \$0.00   |  |
|       | 1030                       | CONDUIT, 3 IN.,<br>PUSHED WITH<br>TRACER WIRE   | Material                |                             | 9                             | Oct 16,<br>2023   | SYSTEM                                    | <b>\$0.00</b><br>\$18,734.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wilesd overridding Payment Estimate Exception 16 on the current Payment Estimate.   |
|       |                            | CONDUIT, 3 IN.,<br>PUSHED WITH  | Material                |                             | 9                             |   | SYSTEM                                    |  | Estimate Item Adjustment (0011) due to user wilesd overridding Payment   |
|       |                            | CONDUIT, 3 IN.,<br>PUSHED WITH  | Material                |                             |                               | 2023<br>Oct 16,   |   | \$18,734.00  | Estimate Item Adjustment (0011) due to user wilesd overridding Payment   |
|       |                            | CONDUIT, 3 IN.,<br>PUSHED WITH  | Material                |                             | 9                             | 2023<br>Oct 16,<br>2023<br>Nov 3,   | SYSTEM                                    | \$18,734.00<br>(\$18,734.00)<br>\$18,734.00<br>(\$18,734.00)   | Estimate Item Adjustment (0011) due to user wilesd overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesd overridding Payment   |
|       |                            | CONDUIT, 3 IN.,<br>PUSHED WITH  |                         | - Total                     | 9                             | 2023<br>Oct 16,<br>2023<br>Nov 3,<br>2023   | SYSTEM                                    | \$18,734.00<br>(\$18,734.00)<br>\$18,734.00<br>(\$18,734.00)<br>\$0.00   | Estimate Item Adjustment (0011) due to user wilesd overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesd overridding Payment   |
|       | 1030                       | CONDUIT, 3 IN.,<br>PUSHED WITH<br>TRACER WIRE   | Material  Material - To |                             | 9                             | 2023<br>Oct 16,<br>2023<br>Nov 3,<br>2023   | SYSTEM                                    | \$18,734.00<br>(\$18,734.00)<br>\$18,734.00<br>(\$18,734.00)<br>\$0.00   | Estimate Item Adjustment (0011) due to user wilesd overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesd overridding Payment   |
|       | 1030                       | CONDUIT, 3 IN.,<br>PUSHED WITH  |                         |                             | 9                             | 2023<br>Oct 16,<br>2023<br>Nov 3,<br>2023   | SYSTEM                                    | \$18,734.00<br>(\$18,734.00)<br>\$18,734.00<br>(\$18,734.00)<br>\$0.00   | Estimate Item Adjustment (0011) due to user wilesd overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesd overridding Payment   |
|       | 1030 -                     | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE  Total PULL BOX,  | Material - To           |                             | 9 10 10                       | 2023 Oct 16, 2023 Nov 3, 2023  Oct 16, 2023  Oct 16, 2023   | SYSTEM SYSTEM SYSTEM                      | \$18,734.00<br>(\$18,734.00)<br>\$18,734.00<br>(\$18,734.00)<br>\$0.00<br>\$0.00   | Estimate Item Adjustment (0011) due to user wilesd overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesd overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment  |
|       | 1030 -                     | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE  Total  PULL BOX, PREFORMED                                       | Material - To           |                             | 9 10 10                       | 2023 Oct 16, 2023 Nov 3, 2023 Nov 3, 2023 Oct 16, 2023  | SYSTEM SYSTEM SYSTEM                      | \$18,734.00<br>(\$18,734.00)<br>\$18,734.00<br>(\$18,734.00)<br>\$0.00<br>\$0.00<br>\$1,546.00   | Estimate Item Adjustment (0011) due to user wilesd overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesd overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilesd overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilesd overridding Payment Estimate Item Adjustment (0008) due to user wilesd overridding Payment  |
|       | 1030 -                     | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE  Total  PULL BOX, PREFORMED                                       | Material - To           |                             | 9 10 10 9 9                   | 2023 Oct 16, 2023 Nov 3, 2023  Oct 16, 2023  Oct 16, 2023  Oct 16, 2023  Nov 3, | SYSTEM SYSTEM SYSTEM SYSTEM               | \$18,734.00<br>(\$18,734.00)<br>\$18,734.00<br>(\$18,734.00)<br>\$0.00<br>\$0.00<br>\$1,546.00   | Estimate Item Adjustment (0011) due to user wilesd overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesd overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilesd overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate.   |
|       | 1030 -                     | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE  Total  PULL BOX, PREFORMED                                       | Material - To           |                             | 9 10 9 9 10                   | 2023 Oct 16, 2023 Nov 3, 2023  Oct 16, 2023  Oct 16, 2023  Nov 3, 2023  Nov 3, 2023   | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM        | \$18,734.00  (\$18,734.00)  \$18,734.00  (\$18,734.00)  \$0.00  \$0.00  \$1,546.00  (\$1,546.00)   | Estimate Item Adjustment (0011) due to user wilesd overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesd overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilesd overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilesd overridding Payment Estimate Item Adjustment (0008) due to user wilesd overridding Payment  |
|       | 1030 -                     | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE  Total  PULL BOX, PREFORMED                                       | Material - To           | tal<br>- Total              | 9 10 9 9 10                   | 2023 Oct 16, 2023 Nov 3, 2023  Oct 16, 2023  Oct 16, 2023  Nov 3, 2023  Nov 3, 2023   | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM        | \$18,734.00  (\$18,734.00)  \$18,734.00  (\$18,734.00)  \$0.00  \$0.00  \$1,546.00  (\$1,546.00)  (\$1,546.00)                                   | Estimate Item Adjustment (0011) due to user wilesd overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesd overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilesd overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilesd overridding Payment Estimate Item Adjustment (0008) due to user wilesd overridding Payment  |
|       | 1030 -                     | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE  Total  PULL BOX, PREFORMED  CLASS 1                              | Material - To           | tal<br>- Total              | 9 10 9 9 10                   | 2023 Oct 16, 2023 Nov 3, 2023  Oct 16, 2023  Oct 16, 2023  Nov 3, 2023  Nov 3, 2023   | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM        | \$18,734.00  (\$18,734.00)  \$18,734.00  (\$18,734.00)  \$0.00  \$0.00  \$1,546.00  (\$1,546.00)  (\$1,546.00)  \$1,546.00                       | Estimate Item Adjustment (0011) due to user wilesd overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesd overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilesd overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilesd overridding Payment Estimate Item Adjustment (0008) due to user wilesd overridding Payment  |
|       | 1030 -<br>1030 -<br>1080   | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE  Total  PULL BOX, PREFORMED  CLASS 1                              | Material - To           | tal<br>- Total              | 9 10 9 9 10                   | 2023 Oct 16, 2023 Nov 3, 2023  Oct 16, 2023  Oct 16, 2023  Nov 3, 2023  Nov 3, 2023   | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM        | \$18,734.00  (\$18,734.00)  \$18,734.00)  \$0.00  \$0.00  \$1,546.00  (\$1,546.00)  \$1,546.00  (\$1,546.00)                                     | Estimate Item Adjustment (0011) due to user wilesd overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesd overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilesd overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilesd overridding Payment Estimate Item Adjustment (0008) due to user wilesd overridding Payment  |
|       | 1030 -<br>1030 -<br>1080 - | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE   Total  PULL BOX, PREFORMED CLASS 1   Total  PULL BOX, PREFORMED | Material - To           | tal<br>- Total              | 9<br>10<br>10<br>9<br>9<br>10 | 2023 Oct 16, 2023 Nov 3, 2023  Oct 16, 2023                                     | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$18,734.00  (\$18,734.00)  \$18,734.00)  (\$18,734.00)  \$0.00  \$0.00  \$1,546.00)  (\$1,546.00)  (\$1,546.00)  \$0.00  \$0.00  \$0.00  \$0.00 | Estimate Item Adjustment (0011) due to user wilesd overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilesd overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilesd overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilesd overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate. |





| Project   | Line   | Description                       | Adjustment<br>Type                | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount       | Remarks  |
|-----------|--------|-----------------------------------|-----------------------------------|-----------------------------|----------------|-----------------|---------------|--------------|--|
| J6I3568   | 1090   | PULL BOX,<br>PREFORMED            | Material                          |                             |                | 2023            |               |              | Estimate Item Adjustment (0009) due to user wilesd overridding Payment Estimate Exception 21 on the current Payment Estimate.  |
|           |        | CLASS 2                           |                                   |                             | 10             | Nov 3,<br>2023  | SYSTEM        | (\$2,080.00) |  |
|           |        |                                   |                                   | - Total                     |                |                 |               | \$0.00       |  |
|           |        |                                   | Material - Tot                    | al                          |                |                 |               | \$0.00       |  |
|           | 1090 - | Total                             |                                   |                             |                |                 |               | \$0.00       |  |
|           | 1100   | PULL BOX,<br>PREFORMED<br>CLASS 3 | Material                          |                             | 9              | Oct 16,<br>2023 | SYSTEM        | \$2,800.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user wilesd overridding Payment Estimate Exception 19 on the current Payment Estimate. |
|           |        |                                   |                                   |                             | 9              | Oct 16,<br>2023 | SYSTEM        | (\$2,800.00) |  |
|           |        |                                   |                                   |                             | 10             | Nov 3,<br>2023  | SYSTEM        | \$2,800.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilesd overridding Payment Estimate Exception 22 on the current Payment Estimate. |
|           |        |                                   |                                   |                             | 10             | Nov 3,<br>2023  | SYSTEM        | (\$2,800.00) |  |
|           |        |                                   |                                   | - Total                     |                |                 |               | \$0.00       |  |
|           |        |                                   | Material - Tot                    | al                          |                |                 |               | \$0.00       |  |
|           | 1100 - | Total                             |                                   |                             |                |                 |               | \$0.00       |  |
|           | 5002   | MISC. FENCING                     | Construction<br>Stockpile<br>STMI |                             | 9              | Oct 16,<br>2023 | SYSTEM        | \$158,077.75 | Payment Estimate Item Adjustment generated Stockpile Transaction   |
|           |        |                                   | OTIVII                            | - Total                     |                |                 |               | \$158,077.75 |  |
|           |        |                                   | Construction                      | Stockpile S                 | ΓΜΙ - Total    |                 |               | \$158,077.75 |  |
|           | 5002 - | Total                             |                                   |                             |                |                 |               | \$158,077.75 |  |
| J6l3568 - | Total  |                                   |                                   |                             |                |                 |               | \$936,934.63 |  |
| Overall - | Total  |                                   |                                   |                             |                |                 |               | \$936,934.63 |  |

# MoDOT

# Contract Adjustments for Contract - 230217-F02

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 19 of 19