

Pay Estimate Created Date: March 18, 2024

Progress Estimate Number	Contract ID	230217-F07	Pay Period Start	March 2, 2024	Original Contract Amount	\$17,432,927.15
19	Prime Contractor	N.B. West Contracting Company	Pay Period End	March 15, 2024	Net Change Order Amount	\$351,435.95
15					Current Contract Amount	\$17,784,363.10

	By User		Approval Date
;	hillt5	Generated and Approved (and should be considered Draft) at the Project Office Level by	March 18, 2024
š	washas	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	March 18, 2024
	ramses1	Reviewed and Approved at the Central Office Controllers Office Level by	March 19, 2024

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
October 30, 2024	October 30, 2024		29.76%

	Contract Informational Dat	tes	Milestones
Date Description	Original Completion Date Current Completion D		No Milestones Exist for Contract
Acceptance Date			
Awarded Date	March 8, 2023	March 8, 2023	
Letting Date	February 17, 2023	February 17, 2023	
Notice to Proceed Date	April 10, 2023	April 10, 2023	
Open to Traffic Date			
Work Began Date			

Contract Total Page	y For Estimate No. 19			
		This Estimate	Previous	To Date
230217-F07				
	Total Posted Items Pay	\$378,608.18	\$4,914,643.92	\$5,293,252.10
	Gross Item Adjustments	(\$19,570.96)	\$1,219,938.97	\$1,200,368.01
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$6,134,582.89	\$6,493,620.11
Contract Total Pag	yable This Estimate:	\$359,037.22		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3281	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$1,414,087.550	0.05	\$70,704.38
	0040	2079909	MISC.LINEAR GRADING CLASS 2 - MODIFIED	STA	\$2,600.000	21	\$54,600.00
	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$10.500	790.8	\$8,303.40
	0130	5021310	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. JOINTS)	SQYD	\$140.000	113.8	\$15,932.00
	0160	6042010	ADJUSTING MANHOLE	EA	\$550.000	1	\$550.00
	0190	6081012	TRUNCATED DOMES	SQFT	\$35.000	80	\$2,800.00
	0200	6083006	6 IN. CONCRETE MEDIAN STRIP	SQYD	\$162.000	30.7	\$4,973.40
	0230	6085008	PAVED APPROACH, 8 IN.	SQYD	\$145.000	129.4	\$18,763.00
	0240	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$46.000	434.5	\$19,987.00
	0260	6089902	MISC.CONCRETE CURB RAMP	EA	\$5,600.000	3	\$16,800.00
	0290	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	LF	\$12.000	78	\$936.00
	0300	6092021	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	LF	\$12.000	21	\$252.00
	0710	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	FT	\$710.000	5	\$3,550.00
	0740	8031000A	TURF TYPE TALL FESCUE SODDING	SQYD	\$11.250	4,410	\$49,612.50
	0760	8049905A	MISC.AMENDED SOILS	SQYD	\$4.500	155	\$697.50
	0880	9016112	PULL BOX, PREFORMED CLASS 3	EA	\$2,700.000	2	\$5,400.00
	1220	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	LF	\$12.500	121	\$1,512.50
	1230	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	LF	\$20.000	192	\$3,840.00
	1240	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	LF	\$48.000	220	\$10,560.00

Revision 3/23/2023 Page 1 of 40



Pay Estimate Created Date: March 18, 2024

Progress Estimate Number	Contract ID 230217-F07	Pay Period Start March 2, 2024 Original Contract Amount \$17,432,927.15
19	Prime Contractor N.B. West Contracting	Company Pay Period End March 15, 2024 Net Change Order Amount \$351,435.95
19		Current Contract Amount \$17,784,363.10

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3281	1330	9028811	PULL BOX, PREFORMED CLASS 2	EA	\$2,350.000	1	\$2,350.00
	1340	9028812	PULL BOX, PREFORMED CLASS 3	EA	\$3,290.000	1	\$3,290.00
	1350	9029100	BASE, CONCRETE	CUYD	\$1,650.000	14.6	\$24,090.00
	1380	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE, PROGRAMMING AND ADJUSTMENT	LS	\$27,945.000	0.1	\$2,794.50
	1410	9029902	MISC.COMBINATION PAD MOUNTED 120V/240V POWER SUPPLY AND LIGHTING CONTROLLER WITH UPS	EA	\$19,580.000	0.5	\$9,790.00
	1430	9029902	MISC.NETWORK CONNECTED SIGNAL MONITOR	EA	\$1,230.000	2	\$2,460.00
	1440	9029902	MISC.OPTIONAL DETECTION SYSTEM	EA	\$24,000.000	0.5	\$12,000.00
	1610	9109902	MISC.ADJUST TO GRADE MODOT PULL BOX	EA	\$1,200.000	2	\$2,400.00
	5002	6089902	MISC.Misc Concrete Curb Ramp	EA	\$2,400.000	11	\$26,400.00
	5003	6089902	MISC.Misc. Cut -Through Curb Ramp	EA	\$500.000	6	\$3,000.00
	5004	6139905	MISC.Removal and Replacement of 10in Pavement	SQYD	\$260.000	1	\$260.00
Project Je	6S3281 - T	otal					\$378,608.18
Overall -	Total						\$378,608.18

Contract Adjustments This Estimate

		tments Exist on Contract						
ine item	Aujustii	ients This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3281	0070	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Material			-10.3	\$500.00	(\$5,150.00)
	0070	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.	10.3	\$500.00	\$5,150.00
	0210	SIDEWALK HAND-RAILING WITH BALUSTERS	Material			-10	\$235.00	(\$2,350.00)
	0210	SIDEWALK HAND-RAILING WITH BALUSTERS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.	10	\$235.00	\$2,350.00
	0740	TURF TYPE TALL FESCUE SODDING	Material			-4,410	\$11.25	(\$49,612.50)
	0740	TURF TYPE TALL FESCUE SODDING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.	4,410	\$11.25	\$49,612.50
	0760	MISC.	Material			-155	\$4.50	(\$697.50)
	0760	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 9 on the current Payment Estimate.	155	\$4.50	\$697.50
	0920	MISC.	Material			-2	\$3,620.00	(\$7,240.00)
	0920	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate.	2	\$3,620.00	\$7,240.00

Revision 3/23/2023 Page 2 of 40



Pay Estimate Created Date: March 18, 2024

Progress Estimate Number
19
Contract ID 230217-F07 Pay Period Start March 2, 2024 Original Contract Amount \$17,432,927.15
Prime Contractor N.B. West Contracting Company Pay Period End March 15, 2024 Net Change Order Amount \$351,435.95
Current Contract Amount \$17,784,363.10

4	Limit	Hama Day with the	A -11 t	Oth It	0	A -11 t	Lina It.	A alice to a contract
	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
281	0970	SIGNAL HEAD, TYPE 3B	Material			-16	\$1,120.00	(\$17,920.00
	0970	SIGNAL HEAD, TYPE 3B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 11 on the current Payment Estimate.	16	\$1,120.00	\$17,920.00
(0980	SIGNAL HEAD, TYPE 4B	Material			-6	\$1,250.00	(\$7,500.00
	0980	SIGNAL HEAD, TYPE 4B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 12 on the current Payment Estimate.	6	\$1,250.00	\$7,500.00
(0990	SH-FLAT SHEET - SIGNAL SIGN	Material			-186	\$41.00	(\$7,626.00
	0990	SH-FLAT SHEET - SIGNAL SIGN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 13 on the current Payment Estimate.	186	\$41.00	\$7,626.00
	1000	SIGNAL SIGN, MOUNTING HARDWARE	Material			-20.7	\$56.00	(\$1,159.20
	1000	SIGNAL SIGN, MOUNTING HARDWARE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 14 on the current Payment Estimate.	20.7	\$56.00	\$1,159.20
	1010	LUMINAIRE LED-A, 120 VOLT COMPATIBLE	Material			-4	\$425.00	(\$1,700.00
	1010	LUMINAIRE LED-A, 120 VOLT COMPATIBLE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 15 on the current Payment Estimate.	4	\$425.00	\$1,700.00
	1020	POST, SIGNAL 8 FT.	Material			-6	\$900.00	(\$5,400.00
	1020	POST, SIGNAL 8 FT.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.	6	\$900.00	\$5,400.00
	1050	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	Material			-2	\$10,700.00	(\$21,400.00
	1050	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate.	2	\$10,700.00	\$21,400.00
	1060	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	Material			-2	\$13,425.00	(\$26,850.00
	1060	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 21 on the current Payment Estimate.	2	\$13,425.00	\$26,850.00
	1120	POST, TYPE C, 25 FT. ARM OR 7.6 M ARM	Material			-2	\$7,260.00	(\$14,520.00
	1120	POST, TYPE C, 25 FT. ARM OR 7.6 M ARM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 23 on the current Payment Estimate.	2	\$7,260.00	\$14,520.00

Revision 3/23/2023 Page 3 of 40



Pay Estimate Created Date: March 18, 2024

Progress Estimate Number
19
Contract ID 230217-F07 Pay Period Start March 2, 2024 Original Contract Amount \$17,432,927.15
Prime Contractor N.B. West Contracting Company Pay Period End March 15, 2024 Net Change Order Amount \$351,435.95
Current Contract Amount \$17,784,363.10

Project lumber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
S3281	1160	POST, TYPE C, 45 FT. ARM OR 13.7 M ARM	Material			-2	\$12,100.00	(\$24,200.00
	1160	POST, TYPE C, 45 FT. ARM OR 13.7 M ARM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 25 on the current Payment Estimate.	2	\$12,100.00	\$24,200.00
	1210	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	Material			-1.5	\$20,580.00	(\$30,870.00
	1210	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 27 on the current Payment Estimate.	1.5	\$20,580.00	\$30,870.00
	1250	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material			-510	\$1.00	(\$510.00
	1250	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user hillt5 overridding Payment Estimate Exception 28 on the current Payment Estimate.	510	\$1.00	\$510.00
	1280	CABLE, 12 AWG 2 CONDUCTOR	Material			-640	\$1.20	(\$768.00
	1280	CABLE, 12 AWG 2 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user hillts overridding Payment Estimate Exception 29 on the current Payment Estimate.	640	\$1.20	\$768.00
	1290	CABLE, 16 AWG 2 CONDUCTOR	Material			-2,040	\$0.75	(\$1,530.00
	1290	CABLE, 16 AWG 2 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user hillts overridding Payment Estimate Exception 30 on the current Payment Estimate.	2,040	\$0.75	\$1,530.00
	1300	CABLE, 16 AWG 5 CONDUCTOR	Material			-2,060	\$1.55	(\$3,193.00
	1300	CABLE, 16 AWG 5 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user hillts overridding Payment Estimate Exception 31 on the current Payment Estimate.	2,060	\$1.55	\$3,193.00
	1310	CABLE, 16 AWG 7 CONDUCTOR	Material			-4,600	\$2.15	(\$9,890.00
	1310	CABLE, 16 AWG 7 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.	4,600	\$2.15	\$9,890.00
	1380	MISC.	Material			-0.1	\$27,945.00	(\$2,794.50
	1380	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate.	0.1	\$27,945.00	\$2,794.50
	1390	MISC.	Material			-12	\$870.00	(\$10,440.00
	1390	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	12	\$870.00	\$10,440.00



Pay Estimate Created Date: March 18, 2024

Progress Estimate Number
19
Contract ID 230217-F07 Pay Period Start March 2, 2024 Original Contract Amount \$17,432,927.15
Prime Contractor N.B. West Contracting Company Pay Period End March 15, 2024 Net Change Order Amount \$351,435.95
Current Contract Amount \$17,784,363.10

Project lumber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
S3281					Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 34 on the current Payment Estimate.			
	1400	MISC.	Material			-1	\$9,085.00	(\$9,085.00
	1400	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate.	1	\$9,085.00	\$9,085.00
	1410	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$7,239.26
	1410	MISC.	Material			-1.5	\$19,580.00	(\$29,370.00
	1410	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user hillts overridding Payment Estimate Exception 36 on the current Payment Estimate.	1.5	\$19,580.00	\$29,370.00
	1420	MISC.	Material			-13.48	\$610.00	(\$8,222.80
	1420	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user hillts overridding Payment Estimate Exception 37 on the current Payment Estimate.	13.48	\$610.00	\$8,222.80
	1430	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$2,177.24
	1430	MISC.	Material			-2	\$1,230.00	(\$2,460.00
	1430	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate.	2	\$1,230.00	\$2,460.00
	1440	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$10,154.46
	1440	MISC.	Material			-2	\$24,000.00	(\$48,000.0
	1440	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0031) due to user hillts overridding Payment Estimate Exception 39 on the current Payment Estimate.	2	\$24,000.00	\$48,000.00
	1460	MISC.	Material			-2	\$845.00	(\$1,690.00
	1460	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user hillt5 overridding Payment Estimate Exception 40 on the current Payment Estimate.	2	\$845.00	\$1,690.00
	1610	MISC.	Material			-15	\$1,200.00	(\$18,000.00
	1610	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user hillt5 overridding Payment Estimate Exception 41 on the current Payment Estimate.	15	\$1,200.00	\$18,000.00
	1640	MISC.	Material			-1	\$145.00	(\$145.00
	1640	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0034) due to user hillts overridding Payment Estimate Exception 42 on the current Payment Estimate.	1	\$145.00	\$145.00
		MISC.	Material			-1	\$600.00	(\$600.00

Revision 3/23/2023 Page 5 of 40



Pay Estimate Created Date: March 18, 2024

Progress Estimate Number
19
Contract ID 230217-F07 Pay Period Start March 2, 2024 Original Contract Amount \$17,432,927.15
Prime Contractor N.B. West Contracting Company Pay Period End March 15, 2024 Net Change Order Amount \$351,435.95
Current Contract Amount \$17,784,363.10

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3281	1670	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 43 on the current Payment Estimate.	1	\$600.00	\$600.00
	1680	MISC.	Material			-16	\$61.00	(\$976.00)
	1680	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0036) due to user hillt5 overridding Payment Estimate Exception 44 on the current Payment Estimate.	16	\$61.00	\$976.00
	1690	MISC.	Material			-2	\$22.00	(\$44.00)
	1690	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0037) due to user hillt5 overridding Payment Estimate Exception 45 on the current Payment Estimate.	2	\$22.00	\$44.00
	1700	MISC.	Material			-6	\$15.00	(\$90.00)
	1700	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0038) due to user hillt5 overridding Payment Estimate Exception 46 on the current Payment Estimate.	6	\$15.00	\$90.00
	1710	MISC.	Material			-1	\$565.00	(\$565.00)
	1710	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0039) due to user hillt5 overridding Payment Estimate Exception 47 on the current Payment Estimate.	1	\$565.00	\$565.00
	5003	MISC.	Material			-18	\$500.00	(\$9,000.00)
	5003	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.	18	\$500.00	\$9,000.00
	5004	MISC.	Material			-487.6	\$260.00	(\$126,776.00)
	5004	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0041) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate.	487.6	\$260.00	\$126,776.00
Fotal								(\$19,570.96)

Revision 3/23/2023 Page 6 of 40



					(Contract Project Information	on
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6S3281	FAF 61-2(17)	Resurface and ADA improvements	61	ST LOUIS	from north of Big Bend Bou	ulevard to Barracksview	
Totals by .	Job Numbe	ers					
J6S3281		ed Item Pay s Item Adjustme		Item Pay	This Estimate \$378,608.18 (\$19,570.96) \$359,037.22	Previous \$4,914,643.92 \$1,219,938.97 \$6,134,582.89	To Date \$5,293,252.10 \$1,200,368.01 \$6,493,620.11
	Liqui	itive centive dated Damages r Contract Adjus			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 3/23/2023 Page 7 of 40



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 4011209, Project Item Line Number 0070, Material Set 401120996, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	Visual report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 6084024, Project Item Line Number 0210, Material Set 6084024, Material 0712STSR - Railing for Steps or Handrail, Acceptance Action Generic 0712STSR is insufficient.	Materials report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 6089902, Project Item Line Number 5003, Material Set 608990296, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	PAL report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 6091010, Project Item Line Number 0270, Material Set 609101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	28 day breaks needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 6139905, Project Item Line Number 5004, Material Set 613990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	28 day breaks needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 6139905, Project Item Line Number 5004, Material Set 613990596, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	PAL report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 6139905, Project Item Line Number 5004, Material Set 613990596, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	PAL report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 8031000A, Project Item Line Number 0740, Material Set 8031000A96, Material 0803SO - Sod, Acceptance Action Generic 0803SO is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 8049905A, Project Item Line Number 0760, Material Set 8049905A, Material 0804TP - Topsoil, Acceptance Action Generic 0804TP is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9019902, Project Item Line Number 0920, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9020513, Project Item Line Number 0970, Material Set 902051396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9020514, Project Item Line Number 0980, Material Set 902051496, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9020833, Project Item Line Number 0990, Material Set 902083396, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9020834, Project Item Line Number 1000, Material Set 9020834, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9022651, Project Item Line Number 1010, Material Set 9022651, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9022708, Project Item Line Number 1020, Material Set 902270896, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092TSPS is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9022708, Project Item Line Number 1020, Material Set 902270896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9022708, Project Item Line Number 1020, Material Set 902270896, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9023135, Project Item Line Number 1050, Material Set 902313596, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9023135, Project Item Line Number 1050, Material Set 902313596, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9023140, Project Item Line Number 1060, Material Set 902314096, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9023140, Project Item Line Number 1060, Material Set 902314096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9023225, Project Item Line Number 1120, Material Set 902322596, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9023225, Project Item Line Number 1120, Material Set 902322596, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals,	Certification report needed	hillt5	Overridden

Revision 3/23/2023 Page 8 of 40



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 0902TSBTZCAB is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9023245, Project Item Line Number 1160, Material Set 902324596, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9023245, Project Item Line Number 1160, Material Set 902324596, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9024283, Project Item Line Number 1210, Material Set 902428396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9028100, Project Item Line Number 1250, Material Set 902810096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9028302, Project Item Line Number 1280, Material Set 902830296, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9028308, Project Item Line Number 1290, Material Set 902830896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9028310, Project Item Line Number 1300, Material Set 902831096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9028311, Project Item Line Number 1310, Material Set 902831196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9029901, Project Item Line Number 1380, Material Set 9029901, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9029902, Project Item Line Number 1390, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9029902, Project Item Line Number 1400, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9029902, Project Item Line Number 1410, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9029902, Project Item Line Number 1420, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9029902, Project Item Line Number 1430, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9029902, Project Item Line Number 1440, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9029902, Project Item Line Number 1460, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9109902, Project Item Line Number 1610, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9109902, Project Item Line Number 1640, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9109902, Project Item Line Number 1670, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9109902, Project Item Line Number 1680, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9109902, Project Item Line Number 1690, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9109902, Project Item Line Number 1700, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Certification report needed	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3281, Item 9109902, Project Item Line Number 1710, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Certification report needed	hillt5	Overridden

Revision 3/23/2023 Page 9 of 40



Total Paid / All Items / All Estimates (Including this Estimate)

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
0217-F07	J6S3281	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$1,414,087.55	\$777,748.15
		0001	0020	2063000	CLASS 3 EXCAVATION	454.00	0.00	454.00	CUYD	300.00	\$20.00	\$6,000.00
		0001	0030	2071000	LINEAR GRADING CLASS 1	26.70	0.00	26.70	STA	0.00	\$6,400.00	\$0.00
		0001	0040	2079909	MISC.LINEAR GRADING CLASS 2 - MODIFIED	312.20	0.00	312.20	STA	111.00	\$2,600.00	\$288,600.00
		0001	0050	3040183	TYPE 1 AGGREGATE FOR BASE (8 IN. THICK)	122.00	0.00	122.00	SQYD	33.80	\$15.00	\$507.00
		0001	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	30,201.00	0.00	30,201.00	SQYD	14,900.10	\$10.50	\$156,451.05
		0001	0070	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	26.30	0.00	26.30	TONS	10.30	\$500.00	\$5,150.00
		0001	0800	4030012	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP095CLP MIX)	28,353.20	0.00	28,353.20	TONS	0.00	\$127.00	\$0.00
		0001	0090	4031057	ASPHALT PERFORMANCE TESTING REPORTING	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
		0001	0100	4031058	INTELLIGENT COMPACTION	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
		0001	0110	4031059	PAVER-MOUNTED THERMAL PROFILES	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.0
		0001	0120	4071007	TACK COAT - LOW OR NON-TRACKING	30,608.00	0.00	30,608.00	GAL	0.00	\$3.00	\$0.0
		0001	0130	5021310	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. JOINTS)	1,488.60	0.00	1,488.60	SQYD	1,295.50	\$140.00	\$181,370.00
		0001	0140	6039902	WATER	10.00	0.00	10.00	EA	1.00	\$500.00	\$500.0
		0001	0150	6039902	WATER	45.00	0.00	45.00	EA	12.00	\$125.00	\$1,500.0
		0001	0160	6042010	ADJUSTING MANHOLE	57.00	0.00	57.00	EA	19.00	\$550.00	\$10,450.0
		0001	0170	6042020	ADJUSTING BASIN OR INLET	25.00	0.00	25.00	EA	2.00	\$2,500.00	\$5,000.0
		0001	0180	6044013	PIPE COLLAR, TYPE C	2.00	0.00	2.00	EA	0.00	\$1,200.00	\$0.0
		0001	0190	6081012	TRUNCATED DOMES	3,106.00	0.00	3,106.00	SQFT	555.00	\$35.00	\$19,425.0
		0001	0200	6083006	6 IN. CONCRETE MEDIAN STRIP	900.40	0.00	900.40	SQYD	72.20	\$162.00	\$11,696.4
		0001	0210	6084024	SIDEWALK HAND-RAILING WITH BALUSTERS	234.00	0.00	234.00	LF	10.00	\$235.00	\$2,350.0
		0001	0220	6085007	PAVED APPROACH, 7 IN.	343.60	0.00	343.60	SQYD	330.30	\$138.00	\$45,581.4
		0001	0230	6085008	PAVED APPROACH, 8 IN.	6,353.10	0.00	6,353.10	SQYD	3,568.30	\$145.00	\$517,403.5
		0001	0240	6086004	CONCRETE SIDEWALK, 4 IN.	16,937.70	0.00	16,937.70	SQYD	8,367.70	\$46.00	\$384,914.2
		0001	0250	6086007	CONCRETE SIDEWALK, 7 IN.	2,426.50	-2,426.50	0.00	SQYD	0.00	\$48.50	\$0.0
		0001	0260	6089902	MISC.CONCRETE CURB RAMP	121.00	-17.00	104.00	EA	35.00	\$5,600.00	\$196,000.0
		0001	0270	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	4,081.00	-2,035.00	2,046.00	LF	1,170.00	\$22.00	\$25,740.0
		0001	0280	6091052	CURB AND GUTTER TYPE B	548.00	0.00	548.00	LF	55.00	\$52.00	\$2,860.0
		0001	0290	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	1,531.00	-300.00	1,231.00	LF	1,231.00	\$12.00	\$14,772.0
		0001	0300	6092021	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	1,105.00	0.00	1,105.00	LF	1,048.00	\$12.00	\$12,576.0
		0001	0310	6097000	ROCK LINING	2.00	0.00	2.00	CUYD	0.00	\$300.00	\$0.0
		0001	0320	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	352.00	0.00	352.00	SQYD	0.00	\$400.00	\$0.0
		0001	0330	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	352.00	0.00	352.00	SQYD	0.00	\$5.00	\$0.0
		0001	0340	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)	352.00	0.00	352.00	SQYD	0.00	\$10.00	\$0.0
		0001	0350	6131014	(PAVEMENT REPAIR) FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	1,584.00	0.00	1,584.00	LF	0.00	\$9.00	\$0.0
		0001	0360	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	880.00	0.00	880.00	EA	0.00	\$9.00	\$0.0
		0001	0370	6141026	GRATE AND BEARING PLATE (3 FT. 1 IN. X 3 FT. 1 IN. OR 940 MM X 940 MM)	3.00	0.00	3.00	EA	1.00	\$3,400.00	\$3,400.0
		0001	0380	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X	6.00	0.00	6.00	EA	0.00	\$2,100.00	\$0.0
		0001	0390	6141121	G00MM) CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	6.00	0.00	6.00	EA	6.00	\$2,600.00	\$15,600.0
		0001	0400	6143010	MANHOLE FRAME AND COVER, TYPE 1-A	1.00	0.00	1.00	EA	1.00	\$900.00	\$900.0
		0001	0410	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$350,000.00	\$175,000.0
		0001	0420	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN, CONTRACTOR FURNISHED/RETAINED	6.00	0.00	6.00	EA	2.00	\$2,800.00	\$5,600.0
		0001	0430	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$1,761,471.57	\$1,321,103.6
		0001	0440	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	2.00	0.00	2.00	EA	0.00	\$600.00	\$0.0
		0001	0450	6191000	PAVEMENT EDGE TREATMENT	13,654.00	0.00	13,654.00	LF	0.00	\$0.01	\$0.0

Revision 3/23/2023 Page 10 of 40



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

io. i colou d	uaritities	anu vaiu	es are i	ased on R	eport Generated date and can differ from the posted am	ount at the	ime the E	stimate was	Genera	tea.		
Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTI To Date (See repo generated date)
0217-F07	J6S3281	0001	0460	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	322.00	0.00	322.00	LF	0.00	\$4.00	\$0
		0001	0470	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	11,860.00	0.00	11,860.00	LF	0.00	\$5.00	\$0
		0001	0480	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	2,671.00	0.00	2,671.00	LF	0.00	\$15.00	\$0
		0001	0490	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	393.00	0.00	393.00	EA	0.00	\$250.00	\$0
		0001	0500	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	17.00	0.00	17.00	EA	0.00	\$250.00	\$0
		0001	0510	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	6.00	0.00	6.00	EA	0.00	\$500.00	\$0
		0001	0520	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	2.00	0.00	2.00	EA	0.00	\$1,200.00	\$0
		0001	0530	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	8.00	0.00	8.00	EA	0.00	\$150.00	\$0
		0001	0540	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	540.00	0.00	540.00	EA	0.00	\$25.00	\$0
		0001	0550	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	80,718.00	0.00	80,718.00	LF	0.00	\$0.15	\$0
		0001	0560	6205902A		120,335.00	0.00	120,335.00	LF	0.00	\$0.21	\$0
		0001	0570	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT	515.00	0.00	515.00	LF	0.00	\$0.21	\$0
		0001	0580	6207001	MARKING PAINT, TYPE L BEADS PAVEMENT MARKING REMOVAL	1,786.00	0.00	1,786.00	LF	0.00	\$1.00	\$
		0001	0590	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	3.00	0.00	3.00	EA	0.00	\$50.00	\$
		0001	0600	6209902	MISC.18 IN. WHITE ISLAND TUBULAR MARKER	182.00	0.00	182.00	EA	0.00	\$100.00	\$
		0001	0610	6209902	MISC.18 IN. YELLOW ISLAND TUBULAR MARKER	81.00	0.00	81.00	EA	0.00	\$100.00	\$
		0001	0620	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	302,152.00	0.00	302,152.00	SQYD	0.00	\$3.50	\$
		0001	0630	6221011	COLDMILLING CONCRETE PAVEMENT FOR REMOVAL OF SURFACE	3,525.00	0.00	3,525.00	SQYD	0.00	\$8.00	\$
		0001	0640	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$43,685.00	\$21,8
		0001	0650	7209904	MISC.SMALL BLOCK RETAINING WALL	469.00	0.00	469.00	SQFT	0.00	\$80.00	
		0001	0660	7261012	12 IN. PIPE GROUP A	595.00	0.00	595.00	LF	441.00	\$142.00	\$62,6
		0001	0670	7261018	18 IN. PIPE GROUP A	122.00	0.00	122.00	LF	0.00	\$150.00	
		0001	0680	7261021	21 IN. PIPE GROUP A	20.00	0.00	20.00	LF	0.00	\$160.00	
		0001	0690	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	20.00	0.00	20.00	FT	0.00	\$660.00	
		0001	0700	7311033	PRECAST CONCRETE DROP INLET 3 FT X 3 FT	10.00	0.00	10.00	FT	6.00	\$880.00	\$5,2
		0001	0710	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	20.00	0.00	20.00	FT	20.00	\$710.00	\$14,2
		0001	0720	7319913	MISC.SINGLE STREET INLET	3.00	0.00	3.00	FT	3.00	\$1,120.00	\$3,3
		0001	0730	7320612A	12 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	3.00	0.00	3.00	EA	0.00	\$1,440.00	
		0001	0740	8031000A	TURF TYPE TALL FESCUE SODDING	20,794.00	0.00	20,794.00	SQYD	4,410.00	\$11.25	\$49,6
		0001	0750	8039905A	MISC.LANDSCAPE RESTORATION	42.00	0.00	42.00	SQYD	0.00	\$155.00	
		0001	0760	8049905A	MISC.AMENDED SOILS	4,612.00	0.00	4,612.00	SQYD	155.00	\$4.50	\$6
		0001	0770	8051000A	SEEDING - COOL SEASON GRASSES	0.18	0.00	0.18	ACRE	0.00	\$20,000.00	
		0001	0780	8061005	ROCK DITCH CHECK	30.00	0.00	30.00	LF	0.00	\$20.00	
		0001	0790	8061007A	CURB INLET CHECK	192.00	0.00	192.00	EA	0.00	\$25.00	
		0001	0800	8061016	SEDIMENT REMOVAL	284.00	0.00	284.00	CUYD	0.00	\$0.01	
		0001	0810	8061019	SILT FENCE	9,125.00	0.00	9,125.00	LF	0.00	\$3.00	
		0010	0820	6061060	MGS GUARDRAIL	38.00	0.00	38.00	LF	0.00	\$50.00	
		0010	0830	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	0.00	\$2,000.00	
		0020	0840	9011010	RELOCATED POLE	7.00	0.00	7.00	EA	0.00	\$1,500.00	
		0020	0850	9014004	CONDUIT, 4 IN. RIGID, PUSHED	132.00	0.00	132.00	LF	0.00	\$1.00	
		0020	0860	9015010	TRENCHING TYPE I	80.00	0.00	80.00	LF	0.00	\$10.00	
		0020	0870	9016110	PULL BOX, PREFORMED CLASS 1	6.00	0.00	6.00	EA	0.00	\$1,300.00	;
		0020	0880	9016112	PULL BOX, PREFORMED CLASS 3	6.00	0.00	6.00	EA	2.00	\$2,700.00	\$5,40
		0020	0890	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	600.00	0.00	600.00	LF	0.00	\$1.00	

Revision 3/23/2023 Page 11 of 40



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	teport Generated date and can differ from the posted amo Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230217-F07	J6S3281	0020	0900	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	310.00	0.00	310.00	LF	0.00	\$10.00	\$0.00
		0020	0910	9018230	NEUTRAL, 8 AWG POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	8.00	0.00	8.00	EA	0.00	\$1.00	\$0.00
		0020	0920	9019902	MISC.RELOCATE SECONDARY ELECTRIC SERVICE POLE	2.00	0.00	2.00	EA	2.00	\$3,620.00	\$7,240.00
		0030	0930	9020113	SIGNAL HEAD, TYPE 3T	3.00	0.00	3.00	EA	0.00	\$950.00	\$0.00
		0030	0940	9020115	SIGNAL HEAD, TYPE 5T	1.00	0.00	1.00	EA	0.00	\$1,170.00	\$0.00
		0030	0950	9020213	SIGNAL HEAD, TYPE 3S	13.00	0.00	13.00	EA	0.00	\$900.00	\$0.00
		0030	0960	9020214	SIGNAL HEAD, TYPE 4S	1.00	0.00	1.00	EA	0.00	\$1,050.00	\$0.00
		0030	0970	9020513	SIGNAL HEAD, TYPE 3B	85.00	0.00	85.00	EA	16.00	\$1,120.00	\$17,920.00
		0030	0980	9020514	SIGNAL HEAD, TYPE 4B	32.00	0.00	32.00	EA	6.00	\$1,250.00	\$7,500.00
		0030	0990	9020833	SH-FLAT SHEET - SIGNAL SIGN	911.00	0.00	911.00	SQFT	186.00	\$41.00	\$7,626.00
		0030	1000	9020834	SIGNAL SIGN, MOUNTING HARDWARE	107.00	0.00	107.00	EA	20.70	\$56.00	\$1,159.20
		0030	1010	9022651	LUMINAIRE LED-A, 120 VOLT COMPATIBLE	12.00	0.00	12.00	EA	4.00	\$425.00	\$1,700.00
		0030	1020	9022708	POST, SIGNAL 8 FT.	46.00	0.00	46.00	EA	6.00	\$900.00	\$5,400.00
		0030	1030	9022715	POST, SIGNAL 15 FT.	6.00	0.00	6.00	EA	0.00	\$1,400.00	\$0.00
		0030	1040	9023115	POST, TYPE CL, 15 FT. ARM OR 4.6 M ARM	1.00	0.00	1.00	EA	0.00	\$6,900.00	\$0.00
		0030	1050	9023135	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	3.00	0.00	3.00	EA	2.00	\$10,700.00	\$21,400.00
		0030	1060	9023140	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	3.00	0.00	3.00	EA	2.00	\$13,425.00	\$26,850.00
		0030	1070	9023145	POST, TYPE CL, 45 FT. ARM OR 13.7 M ARM	1.00	0.00	1.00	EA	0.00	\$14,730.00	\$0.00
		0030	1080	9023150	POST, TYPE CL, 50 FT. ARM OR 15.2 M ARM	1.00	0.00	1.00	EA	0.00	\$15,690.00	\$0.00
		0030	1090	9023155	POST, TYPE CL, 55 FT. ARM	1.00	0.00	1.00	EA	0.00	\$18,450.00	\$0.00
		0030	1100	9023215	POST, TYPE C, 15 FT. ARM OR 4.6 M ARM	1.00	0.00	1.00	EA	0.00	\$6,100.00	\$0.0
		0030	1110	9023220	POST, TYPE C, 20 FT. ARM OR 6.1 M ARM	3.00	0.00	3.00	EA	0.00	\$6,690.00	\$0.0
		0030	1120	9023225	POST, TYPE C, 25 FT. ARM OR 7.6 M ARM	4.00	0.00	4.00	EA	2.00	\$7,260.00	\$14,520.0
		0030	1130	9023230	POST, TYPE C, 30 FT. ARM OR 9.1 M ARM	5.00	0.00	5.00	EA	0.00	\$8,740.00	\$0.0
		0030	1140	9023235	POST, TYPE C, 35 FT. ARM OR 10.7 M ARM	5.00	0.00	5.00	EA	0.00	\$9,155.00	\$0.0
		0030	1150	9023240	POST, TYPE C, 40 FT. ARM OR 12.2 M ARM	5.00	0.00	5.00	EA	0.00	\$11,370.00	\$0.0
		0030	1160	9023245	POST, TYPE C, 45 FT. ARM OR 13.7 M ARM	5.00	0.00	5.00	EA	2.00	\$12,100.00	\$24,200.0
		0030	1170	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	1.00	0.00	1.00	EA	0.00	\$13,175.00	\$0.0
		0030	1180	9023255	POST, TYPE C, 55 FT. ARM	1.00	0.00	1.00	EA	0.00	\$16,630.00	\$0.0
		0030	1190	9023340	POST, TYPE B, LONGEST ARM 40 FT. OR 12.2 M	1.00	0.00	1.00	EA	0.00	\$16,540.00	\$0.0
		0030	1200	9023440	POST, TYPE BL. LONGEST ARM 40 FT. OR 12.2 M	2.00	0.00	2.00	EA	0.00	\$19,870.00	\$0.0
		0030	1210	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	12.00	0.00	12.00	EA	1.50	\$20.580.00	\$30,870.0
		0030	1220	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	851.00	0.00	851.00	LF	219.00	\$12.50	\$2,737.5
			1230	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	1,301.00	0.00	1,301.00	LF	430.00	\$20.00	\$8,600.0
		0030	1240	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	6,345.00	0.00	6,345.00	LF	1,549.00	\$48.00	\$74,352.0
		0030		9028100	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET			1,510.00	LF	510.00	\$1.00	\$510.0
		0030	1250	9028100	CABLE, 6 AWG 1 CONDUCTOR, POLE AND BRACKET	1,510.00 450.00	0.00	450.00	LF	0.00	\$1.00	\$0.0
		0030										
		0030	1270	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	3,000.00	0.00	3,000.00	LF	0.00	\$1.50	\$0.0
		0030	1280		CABLE, 12 AWG 2 CONDUCTOR	2,080.00	0.00	2,080.00	LF	640.00	\$1.20	\$768.0
		0030	1290	9028308	CABLE, 16 AWG 2 CONDUCTOR	23,340.00	0.00	23,340.00	LF	2,040.00	\$0.75	\$1,530.0
		0030	1300	9028310	CABLE, 16 AWG 5 CONDUCTOR	24,380.00	0.00	24,380.00	LF	2,060.00	\$1.55	\$3,193.0
		0030	1310	9028311	CABLE, 16 AWG 7 CONDUCTOR	27,630.00	0.00	27,630.00	LF	4,600.00	\$2.15	\$9,890.0
		0030	1320	9028810	PULL BOX, PREFORMED CLASS 1	7.00	0.00	7.00	EA	2.00	\$1,355.00	\$2,710.0
		0030	1330	9028811	PULL BOX, PREFORMED CLASS 2	24.00	0.00	24.00	EA	8.00	\$2,350.00	\$18,800.0
		0030	1340	9028812	PULL BOX, PREFORMED CLASS 3	29.00	0.00	29.00	EA	8.00	\$3,290.00	\$26,320.0
		0030	1350	9029100	BASE, CONCRETE	183.80	0.00	183.80	CUYD	58.44	\$1,650.00	\$96,426.00
		0030	1360	9029400	TEMPORARY TRAFFIC SIGNALS	1.00	0.00	1.00	LS	0.00	\$16,120.00	\$0.00

Revision 3/23/2023 Page 12 of 40



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Project Category Line Item Description Bid Net Total Unit Total Unit Total Unit Price Total Value POSTED

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230217-F07	J6S3281	0030	1370	9029901	MISC.POT HOLING UTILITY FACILITIES	1.00	0.00	1.00	LS	0.00	\$1.00	\$0.00
		0030	1380	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE, PROGRAMMING AND ADJUSTMENT	1.00	0.00	1.00	LS	0.10	\$27,945.00	\$2,794.50
		0030	1390	9029902	MISC.AUDIBLE PEDESTRIAN PUSHBUTTON AND SIGNING	129.00	0.00	129.00	EA	12.00	\$870.00	\$10,440.00
		0030	1400	9029902	MISC.COMBINATION PAD MOUNTED 120V/240V POWER SUPPLY AND LIGHTING CONTROLLER	2.00	0.00	2.00	EA	1.00	\$9,085.00	\$9,085.00
		0030	1410	9029902	MISC.COMBINATION PAD MOUNTED 120V/240V POWER SUPPLY AND LIGHTING CONTROLLER WITH UPS	12.00	0.00	12.00	EA	1.50	\$19,580.00	\$29,370.00
		0030	1420	9029902	MISC.COUNTDOWN PEDESTRIAN SIGNAL HEAD, TYPE 1S	137.00	0.00	137.00	EA	13.48	\$610.00	\$8,222.80
		0030	1430	9029902	MISC.NETWORK CONNECTED SIGNAL MONITOR	12.00	0.00	12.00	EA	2.00	\$1,230.00	\$2,460.00
		0030	1440	9029902	MISC.OPTIONAL DETECTION SYSTEM	22.00	0.00	22.00	EA	2.00	\$24,000.00	\$48,000.00
		0030	1450	9029902	MISC.PEDESTRIAN PUSH BUTTON EXTENSION	4.00	0.00	4.00	EA	0.00	\$308.00	\$0.00
		0030	1460	9029902	MISC.PEDESTRIAN PUSH BUTTON STANCHION, 4 FT.	40.00	0.00	40.00	EA	2.00	\$845.00	\$1,690.00
		0040	1470	9031010	CONCRETE FOOTINGS, EMBEDDED	5.00	0.00	5.00	CUYD	0.00	\$2,400.00	\$0.00
		0040	1480	9031210	STRUCTURAL STEEL POSTS	150.00	0.00	150.00	LB	0.00	\$12.00	\$0.00
		0040	1490	9031220	PIPE POSTS	2,416.00	0.00	2,416.00	LB	0.00	\$8.00	\$0.00
		0040	1500	9031250A	U-CHANNEL POST, 3 LB	20.00	0.00	20.00	LF	0.00	\$30.00	\$0.00
		0040	1510	9031270A	2 IN. PSST POST - 12 GA.	1,197.00	0.00	1,197.00	LF	0.00	\$26.00	\$0.00
		0040	1520	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	354.00	0.00	354.00	EA	0.00	\$250.00	\$0.00
		0040	1530	9031280	2.5 IN. PSST POST - 12 GA.	134.00	0.00	134.00	LF	0.00	\$28.00	\$0.00
		0040	1540	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	30.00	0.00	30.00	EA	0.00	\$350.00	\$0.00
		0040	1550	9035004A	SH-FLAT SHEET	524.00	0.00	524.00	SQFT	0.00	\$32.00	\$0.00
		0040	1560	9035069A	SHF-FLAT SHEET FLUORESCENT	207.00	0.00	207.00	SQFT	0.00	\$36.00	\$0.00
		0040	1570	9039902	MISC.REMOVE AND RELOCATE GROUND MOUNT SIGN	58.00	0.00	58.00	EA	0.00	\$400.00	\$0.00
		0040	1580	9039902	MISC.REMOVE AND RELOCATE GROUND MOUNT SIGN SPECIAL	4.00	0.00	4.00	EA	0.00	\$5,000.00	\$0.00
		0050	1590	9109901	MISC.ITS MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$2,000.00	\$0.00
		0050	1600	9109901	MISC.ST. LOUIS COUNTY ITS ASSET RELOCATIONS	1.00	0.00	1.00	LS	0.00	\$2,180.00	\$0.00
		0050	1610	9109902	MISC.ADJUST TO GRADE MODOT PULL BOX	62.00	0.00	62.00	EA	15.00	\$1,200.00	\$18,000.00
		0050	1620	9109902	MISC.CCTV CAMERA POWER CABLE	7.00	0.00	7.00	EA	0.00	\$2,060.00	\$0.00
		0050	1630	9109902	MISC.CCTV CAMERA RELOCATION	1.00	0.00	1.00	EA	0.00	\$7,875.00	\$0.00
		0050	1640	9109902	MISC.INSTALL MODOT FURNISHED IP-ADDRESSABLE POWER STRIP	12.00	0.00	12.00	EA	1.00	\$145.00	\$145.00
		0050	1650	9109902	MISC.ITS PULL BOX WITH CONCRETE PAD, PREFORMED CLASS 1	1.00	0.00	1.00	EA	0.00	\$1,920.00	\$0.00
		0050	1660	9109902	MISC.ITS PULL BOX WITH CONCRETE PAD, PREFORMED CLASS 5	1.00	0.00	1.00	EA	0.00	\$2,900.00	\$0.00
		0050	1670	9109902	MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT	11.00	0.00	11.00	EA	1.00	\$600.00	\$600.00
		0050	1680	9109902	MISC.SM F.O. FUSION SPLICE	318.00	0.00	318.00	EA	16.00	\$61.00	\$976.00
		0050	1690	9109902	MISC.SM F.O. JUMPER	64.00	0.00	64.00	EA	2.00	\$22.00	\$44.00
		0050	1700	9109902	MISC.SM F.O. PIGTAIL	68.00	0.00	68.00	EA	6.00	\$15.00	\$90.00
		0050	1710	9109902	MISC.WALL-MOUNTED INTERCONNECT CENTER	12.00	0.00	12.00	EA	1.00	\$565.00	\$565.00
		0050	1720	9109903	MISC.CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	1,110.00	0.00	1,110.00	LF	0.00	\$12.50	\$0.00
		0050	1730	9109903	MISC.CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	310.00	0.00	310.00	LF	0.00	\$12.50	\$0.00
		0050	1740	9109903	MISC.FIBER OPTIC CABLE, 24 STRAND SINGLE MODE	750.00	0.00	750.00	LF	0.00	\$2.35	\$0.00
		0050	1750	9109903	MISC.MODOT ITS ASSETS RELOCATION	500.00	0.00	500.00	LF	0.00	\$10.00	\$0.00
		0001	5001	6089901	MISC.Credit on Concrete Testing	0.00	1.00	1.00	LS	1.00	(\$46,600.80)	(\$46,600.80)
		0001	5002	6089902	MISC.Misc Concrete Curb Ramp	0.00	182.00	182.00	EA	114.00	\$2,400.00	\$273,600.00
		0001	5003	6089902	MISC.Misc. Cut -Through Curb Ramp	0.00	122.00	122.00	EA	18.00	\$500.00	\$9,000.00
		0001	5004	6139905	MISC.Removal and Replacement of 10in Pavement	0.00	488.20	488.20	SQYD	487.60	\$260.00	\$126,776.00
		0001	5005	2029905	MISC.8in Pavement Removal	0.00	288.00	288.00	SQYD	288.00	\$120.00	\$34,560.00
	Project J	6S3281 - To	tal Value	Posted to D	Date as of Report Generated Date							\$5,293,252.08
230217-F07 Over	rall - Total	Value Post	ed to Dat	te as of Repo	ort Generated Date							\$5,293,252.08

Revision 3/23/2023 Page 13 of 40



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6S3281

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/Log Mile	Offset/ Distance	To Station/Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	3/15/24	3/18/24	0.05	LS		1043+37 LT		1279+00		
0040	2079909	MISC. GRADING		3/8/24	15.00	STA		1281+00		1040+00		
	0010501	T-00 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1		3/18/24	6.00		Job Site					
0060	3040504	TYPE 5 AGGREGATE FOR BASE	3/4/24	3/8/24	121.60	SQYD	33.8 SQYD Concrete curb ramps: Sta. 1268+00 to 1268+14 RT, Sta. 1269+12 to 1269+36 RT, Sta. 1266+70 to 1266+82 RT, Sta. 1267+43 to 1267+58 RT 93.4 SQYD 4 inch sidewalk					
			3/6/24	3/11/24	109.00	SQYD	78.5 SQYD 5711 S Lindbergh Blvd, Sta. 1265+00 to 1266+18 RT 30.3 SQYD Revere Ln Sta. 1281+79 RT					
			3/7/24	3/8/24	59.60	SQYD	Revere Ln. Sta.	1281+79 RT				PCCP 23slhfrs0004
			3/11/24	3/18/24	80.90	SQYD	54.9SQYD 4" Sidewalk 20SQYD ADA Ramps 6SQYD Driveway Curb Ramps					
				3/18/24	92.70	SQYD	48.8sqyd in front of Phillips 66 1430 S Kirkwood Rd STA:1039+58.651040+47.30LT					
							6.7sqyd around power pole at Phillips 66 1430 S Kirkwood Rd STA:1040+55LT					
							17.8sqyd at entrance of Sunset Office Dr STA:1043+37.58RT					
							19.4sqyd on South entrance to Circle K 1435 S Kirkwood Rd STA:1042+64.38RT					
			3/12/24	3/18/24	58.20	SQYD	40sqyd for sidewalk South of entrance to Sunset Office Dr STA:1043+83.01-1044+43.01RT					
							5.7sqyd for 10" pavement at Sunset Office Dr STA:1043+37.58RT					
							12.5sqyd for South driveway to Circle K 1435 S Kirkwood Rd STA:1042+64.38RT					
				3/18/24	54.30	SQYD	23SQYD 8" Approach 41.3SQYD 4" Sidewalk 10SQYD ADA Curb Ramp 3SQYD Driveway Curb Ramp					
			3/13/24	3/18/24			35.2SQYD 8" Approach 35.9SQYD 10" Pavement Removal/Replace					
				3/18/24	25.90	SQYD	7 SQYD 4600 S Lindbergh (Chiropractic Center) 7 SQYD 5401 S Lindbergh Blvd 8 SQYD 4600 S Lindbergh (Chiropractic Center) 3 SQYD 5401 S Lindbergh Blvd					
				3/18/24			10SQYD 8" Approach 3SQYD Driveway Curb Ramp 21 SQYD Sta. 1047+19 RT, 10701 Watson Rd					
			3/13/24				8.3 SQYD 5718 S Lindbergh STA: 1268+37 LT 35.2 SQYD 10550 Baptist Church Rd, Sta. 1238+67 to 1239+12 RT including curb ramp					
0400	5004040	CONODETE DAVEMENT (40 IN NON DEINEODOED	0.00.004	3/18/24	42.20		Daywood Lo Oke 4004 (70 DT	1044+58.44RT		1045+19.69RT		DOOD COOL LIFTDOODS
0130	5021310	CONCRETE PAVEMENT (10 IN. NON-REINFORCED		3/11/24	30.70		Revere Ln Sta. 1281+79 RT	1281+79 RT				PCCP 23SLHFRS0004 PCCP 23slhfrs0004
				3/18/24			Sunset Office Dr.	1043+37.58RT				PCCP 23SLHFRS0004
				3/18/24	5.70	SQYD	Sunset Office Dr.	1043+37.58RT				PCCP 23SLHFRS0004
0160		ADJUSTING MANHOLE	3/6/24	3/8/24	1.00	EA	10550 Baptist Church Plaza North Entrance Driveway Curb Ramp	1237+95 RT				
0190	6081012	TRUNCATED DOMES		3/8/24	20.00		NE and SE Cut Throughs at Sunset Plaza Sta. 1264+37 to 1264+54 RT Sta. 1039+44 to 1039+49 LT					
0200	6083006	6 IN. CONCRETE MEDIAN STRIP	3/6/24	3/8/24	30.70	SQYD	Sunset Plaza SE and NE Islands	1057+63 LT		1058+42 LT		PCCP 23SLHFSR0004
0230	6085008	PAVED APPROACH, 8 IN.	3/11/24	3/18/24	19.40	SQYD	South Entrance to 1434 S Kirkwood Rd.	1042+64.38RT				PCCP 23SLHFRS0004
			3/12/24	3/18/24	12.50	SQYD		1042+64.38RT				
			0110101	3/18/24			Sta. 1045+60 RT					PCCP 23slhfrs0004
			3/13/24	3/18/24	35.20	SQYD	12.2 sqyd at 1045+59.47RT1525 S Kirkwood Rd North Entrance 23 sqyd at 1046+47.40RT 1525 S Kirkwood Rd South Entrance					17 gr 40, 3 gr 60 PCCP 23SLHFRS0004
				3/18/24			South entrance to 1525 S Kirkwood Rd.	1046+47 RT				PCCP 23SLHFRS0004
			3/15/24	3/18/24	29.30	SQYD	21 SQYD10701 Watson Rd STA:1047+19 RT 9.3 SQYD Extra work at 5718 S Lindbergh STA: 1268+37 LT					PCCP 23slhfrs0004
0240	6086004	CONCRETE SIDEWALK, 4 IN.	3/4/24	3/8/24	88.00	SQYD	45.4 SQYD 5721 S Lindbergh Blvd, Sta. 1268+14 to 1268+94 RT 42.6 SQYD 5721 S Lindbergh Blvd, Sta. 1266+82 to 1267+83					PCCP 23SLHFRS0004
			3/6/24	3/11/24	74.40	SQYD	5711 S Lindbergh Blvd, Sta. 1265+00 to 1266+18 RT					PCCP 23slhfrs0004
			3/11/24	3/18/24			21.2 SQYD Sta. 1264+54 to Sta. 1265+26 RT 33.7SQYD STA 12261+70-1262+20 RT					PCCP 23SLHFRS0004
				3/18/24	50.50	SQYD	48.8sqyd in front of Phillips 66 1430 S Kirkwood Rd STA:1039+58.651040+47.30LT					
			guero.	314010	40.00	801/2	6.7sqyd around power pole at Phillips 66 1430 S Kirkwood Rd STA:1040+55LT	1042-00 010-		4044 - 40 0 - 2		PCCP 23SLHFRS0004
			3/12/24	3/18/24			Between 1435 and 1503 S Lindbergh 5615 S Lindbergh	1043+83.01RT 1257+43 RT		1044+43.01RT 1258+10 RT		PCCP 23SLHFRS0004 PCCP 23SLHFRS0004
			3/13/24	3/18/24	11.00		8.6 SQYD 4600 S Lindbergh (Chiropractic Center)	0, .40 [1]		00:10111		PCCP 24slhfrs0005
			3/15/24	3/18/24			3.3 SQYD 5401 S Lindbergh Blvd 10550 Baptist Church Rd, Sta. to	1238+67 RT		1239+22 RT		PCCP 23slhfrs0004
0260	6000000	MISC CONCRETE	3/44/01	3/18/24			Between 1435 and 1503 S Kirkwood Rd.	1044+58.44RT		1045+19.69RT		PCCP 23SLHFRS0004
0260	อบช9902	MISC. CONCRETE		3/18/24	2.00	EA	Sta. 1264+37 to 1264+54 RT Sta. 1039+44 to 1039+49 LT					PCCP 23slhfrs0004
				3/18/24	1.00		SW Corner of Tesson Ferry and Lindbergh	1257+43				Added to job due to poor condition of existing ramp
0290	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)		3/8/24	29.00 49.00		Revere Ln Sta. 1043+83 to 1044+43 RT	1281+79 RT				PCCP 23SLHFRS0004 Poured 63' of 6" curb ran out of quantity after paying 1 49' still need to pay for 14' after change order.
			3/15/24	3/18/24	0.00	LF	Between 1435 and 1503 S Kirkwood Rd.	1044+58 RT		1045+20 RT		PCCP 23slhfrs0004 Poured 62' of curb to be paid after quantity change ordered on
0300	6092021	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	3/13/24	3/18/24	21.00	LF	4600 S Lindbergh	1172+48 LT		1172+69 LT		PCCP 23SLHFRS0004
		PRECAST CONCRETE DROP INLET 4 FT X 2 FT	3/12/24	3/18/24	5.00	FT		1265+37.45LT				Making up missed pay from 1/8/2024

Revision 3/23/2023 Page 14 of 40



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/Log Mile	Offset/ Distance	To Station/Log Mile	Offset/ Distance	Comments
												(GI 24)
0740	8031000A	TURF TYPE TALL FESCUE SODDING	3/15/24	3/18/24	4,410.00	SQYD	NB Lindbergh from Muller to Gravois					Sod to be monitored for proper rooting and growth Spec. 803.4
0760	8049905A	MISC. TOPSOIL	3/15/24	3/18/24	155.00	SQYD	Lindbergh					
0880	9016112	PULL BOX, PREFORMED CLASS 3	3/15/24	3/18/24	2.00	EA	Hackberry and Lindbergh Baptist Church and Lindbergh					Lighting pull box at existing PS location
1220	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	3/11/24	3/18/24	121.00	LF	Baptist Church and Lindbergh					
1230	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	3/11/24	3/18/24	192.00	LF	Baptist Church and Lindbergh					
1240	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	3/7/24	3/8/24	101.00	LF	Baptist Church					PB3 and PB4
			3/11/24	3/18/24	119.00	LF	Baptist Church and Lindbergh					
1330	9028811	PULL BOX, PREFORMED CLASS 2	3/4/24	3/8/24	1.00	EA	Baptist Church					PB 2
1340	9028812	PULL BOX, PREFORMED CLASS 3	3/4/24	3/8/24	1.00	EA	Baptist Church					
1350	9029100	BASE, CONCRETE	3/4/24	3/8/24	0.88	CUYD	Baptist Church					23SLHFRS0004
			3/7/24	3/8/24	3.27	CUYD	Baptist Church and Lindbergh					PCCP 23SLHFRS0004
			3/12/24	3/18/24	6.28	CUYD	Baptist Church and Lindbergh					Signal post 1 and 9
			3/13/24	3/18/24	4.17	CUYD	Baptist Church and Lindbergh					Signal base 4
1380	9029901	MISC.	3/13/24	3/18/24	0.10	LS	Lindbergh and Hackberry					
1410	9029902	MISC.	3/7/24	3/8/24	0.50	EA	Baptist Church and Lindbergh					
1430	9029902	MISC.	3/13/24	3/18/24	2.00	EA	Hackberry and Lindbergh Sappington and Lindbergh					
1440	9029902	MISC.	3/13/24	3/18/24	0.50	EA	Hackberry and Lindbergh					
1610	9109902	MISC. ITS	3/11/24	3/18/24	2.00	EA	Between Watson and Sunset Plaza	1054+88 RT		1057+27 RT		
5002	6089902	MISC. CONCRETE	3/4/24	3/8/24	4.00	EA	Sta. 1268+00 to 1268+14 RT Sta. 1269+12 to 1269+36 RT Sta. 1266+70 to 1266+82 RT Sta. 1267+43 to 1267+58 RT					Originally 7" Sidewalk PCCP 23SLHFRS0004
			3/11/24	3/18/24	2.00	EA	5655 S Lindbergh STA: 1260+98 RT					PCCP 23SLHFRS0004
			3/12/24	3/18/24	1.00	EA	North Side of 5615 S Lindbergh	1257+43 RT				Originally 7" Sidewalk PCCP 23SLHFRS0004
			3/13/24	3/18/24	2.00	EA	1 ramp 4600 S Lindbergh (Chiropractic Center) 1 ramp 5401 S Lindbergh Blvd					PCCP 24slhfrs0005
			3/14/24	3/18/24	1.00	EA	South end of North entrance to 5401 S Lindbergh	1238+40 RT				Originally 7" Sidewalk PCCP 23SLHFRS0004
			3/15/24	3/18/24	1.00	EA	1 ADA ramp Sta. 1239+22 RT, 10550 Baptist Church Rd					PCCP 24slhfrs0004
5003	6089902	MISC. CONCRETE	3/4/24	3/8/24	6.00	EA	NE and SE Islands at Sunset Plaza					PCCP 23SLHFRS0004
5004	6139905	MISC. PAVEMENT REPAIR	3/6/24	3/11/24	1.00	SQYD	5711 S Lindbergh	1265+00				Originally 7" Sidewalk PCCP 23SLHFRS0004
			3/13/24	3/18/24	0.00	SQYD	1525 S Kirkwood Rd North Entrance	1045+59 RT				35.9SQYD needs to be added on future change order Type 5 Paid for on this day
5005	2029905	MISC. REMOVALS	3/15/24	3/18/24	0.00	SQYD	5718 S Lindbergh STA: 1268+37 LT					13SQYD to be paid after change ordered updated quantity Extra work added to job due to drainage issue at newly installed approach.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 15 of 40



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3281	0060	TYPE 5 AGGREGATE FOR BASE	Material		4	Aug 2, 2023	SYSTEM	\$6,201.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Aug 2, 2023	SYSTEM	(\$6,201.30)	
					15	Jan 17, 2024	SYSTEM	\$1,364.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Jan 17, 2024	SYSTEM	(\$1,364.77)	
					16	Feb 2, 2024	SYSTEM	\$12,307.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					16	Feb 2, 2024	SYSTEM	(\$12,307.87)	
					17	Feb 16, 2024	SYSTEM	\$30,357.37	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$30,357.37)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0060 -	Total						\$0.00	
	0070	BIT. PAVEMENT MIXTURE PG64-22	Material		13	Dec 18, 2023	SYSTEM	\$5,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weingl1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		(BP-1)			13	Dec 18, 2023	SYSTEM	(\$5,150.00)	
					14	Jan 2, 2024	SYSTEM	\$5,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Jan 2, 2024	SYSTEM	(\$5,150.00)	
					15	Jan 17, 2024	SYSTEM	\$5,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					15	Jan 17, 2024	SYSTEM	(\$5,150.00)	
					16	Feb 2, 2024	SYSTEM	\$5,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					16	Feb 2, 2024	SYSTEM	(\$5,150.00)	
					17	Feb 16, 2024	SYSTEM	\$5,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$5,150.00)	
					18	Mar 1, 2024	SYSTEM	\$5,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					18	Mar 1, 2024	SYSTEM	(\$5,150.00)	
					19	Mar 18, 2024	SYSTEM	\$5,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$5,150.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0070 -	Total						\$0.00	
	0130	CONCRETE PAVEMENT (10 IN. NON- REINFORCED	Material		4	Aug 2, 2023	SYSTEM	\$14,406.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3281	0130	CONCRETE PAVEMENT	Material		4	Aug 2, 2023	SYSTEM	(\$14,406.00)	
		(10 IN. NON- REINFORCED			5	Aug 16, 2023	SYSTEM	\$18,774.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Aug 16, 2023	SYSTEM	(\$18,774.00)	
					6	Sep 5, 2023	SYSTEM	\$53,858.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Sep 5, 2023	SYSTEM	(\$53,858.00)	
					7	Sep 18, 2023	SYSTEM	\$53,858.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Sep 18, 2023	SYSTEM	(\$53,858.00)	
					8	Oct 2, 2023	SYSTEM	\$53,858.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Oct 2, 2023	SYSTEM	(\$53,858.00)	
					9	Oct 16, 2023	SYSTEM	\$58,548.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Oct 16, 2023	SYSTEM	(\$58,548.00)	
					14	Jan 2, 2024	SYSTEM	\$102,816.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Jan 2, 2024	SYSTEM	(\$102,816.00)	
				- Total				\$0.00	
				- IOlai					
			Material - To					\$0.00	
	0130 -	- Total	Material - To						
	0130 - 0140	- Total WATER - UTILITY ITEM	Material - To		10	Nov 2, 2023	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		WATER -			10		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0002) due to user hillt5 overridding Payment
		WATER -				2023 Nov 2,		\$0.00 \$0.00 \$500.00	Estimate Item Adjustment (0002) due to user hillt5 overridding Payment
		WATER -			10	2023 Nov 2, 2023 Nov 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 (\$500.00)	Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hillt5 overridding Payment
		WATER -			10	Nov 2, 2023 Nov 16, 2023 Nov 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 (\$500.00)	Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hillt5 overridding Payment
		WATER -			10 11 11	2023 Nov 2, 2023 Nov 16, 2023 Nov 16, 2023 Dec 4,	SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 (\$500.00) \$500.00	Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment
		WATER -			10 11 11 12	2023 Nov 2, 2023 Nov 16, 2023 Nov 16, 2023 Dec 4, 2023	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 (\$500.00) \$500.00 \$500.00	Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment
		WATER -			10 11 11 12	2023 Nov 2, 2023 Nov 16, 2023 Nov 16, 2023 Dec 4, 2023 Dec 4, 2023 Dec 18,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 (\$500.00) \$500.00 (\$500.00)	Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weingl1 overridding Payment Estimate Item Adjustment (0003) due to user weingl1 overridding Payment
		WATER -			10 11 11 12 12 13	2023 Nov 2, 2023 Nov 16, 2023 Nov 16, 2023 Dec 4, 2023 Dec 18, 2023 Dec 18, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 (\$500.00) \$500.00 (\$500.00) \$500.00	Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weingl1 overridding Payment Estimate Item Adjustment (0003) due to user weingl1 overridding Payment
		WATER -			10 11 11 12 12 13	2023 Nov 2, 2023 Nov 16, 2023 Nov 16, 2023 Dec 4, 2023 Dec 4, 2023 Dec 18, 2023 Jan 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 (\$500.00) \$500.00 (\$500.00) \$500.00 (\$500.00)	Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weingl1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.
		WATER -			10 11 11 12 12 13 13 14	2023 Nov 2, 2023 Nov 16, 2023 Nov 16, 2023 Dec 4, 2023 Dec 18, 2023 Dec 18, 2023 Jan 2, 2024 Jan 2, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 (\$500.00) \$500.00 (\$500.00) \$500.00 (\$500.00) \$500.00	Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weingl1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.
	0140	WATER - UTILITY ITEM		- Total	10 11 11 12 12 13 13 14	2023 Nov 2, 2023 Nov 16, 2023 Nov 16, 2023 Dec 4, 2023 Dec 18, 2023 Dec 18, 2023 Jan 2, 2024 Jan 2, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 (\$500.00) \$500.00 (\$500.00) \$500.00 (\$500.00) \$500.00 (\$500.00)	Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weingl1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.
	0140	WATER -	Material - To	- Total	10 11 11 12 12 13 13 14	2023 Nov 2, 2023 Nov 16, 2023 Nov 16, 2023 Dec 4, 2023 Dec 18, 2023 Dec 18, 2023 Jan 2, 2024 Jan 2, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$500.00 (\$500.00) \$500.00 (\$500.00) \$500.00 (\$500.00) \$500.00 (\$500.00)	Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weingl1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3281	0150	UTILITY ITEM	Material			2023			Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Aug 16, 2023	SYSTEM	(\$125.00)	
					6	Sep 5, 2023	SYSTEM	\$125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Sep 5, 2023	SYSTEM	(\$125.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0150 -	Total						\$0.00	
	0190	TRUNCATED DOMES	Material		5	Aug 16, 2023	SYSTEM	\$1,470.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Aug 16, 2023	SYSTEM	(\$1,470.00)	
					6	Sep 5, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Sep 5, 2023	SYSTEM	(\$3,500.00)	
					7	Sep 18, 2023	SYSTEM	\$4,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Sep 18, 2023	SYSTEM	(\$4,550.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0190 -	· Total						\$0.00	
	0210	SIDEWALK HAND- RAILING WITH BALUSTERS	Material		10	Nov 2, 2023	SYSTEM	\$2,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		BALOGTERO			10	Nov 2, 2023	SYSTEM	(\$2,350.00)	
					11	Nov 16, 2023	SYSTEM	\$2,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Nov 16, 2023	SYSTEM	(\$2,350.00)	
					12	Dec 4, 2023	SYSTEM	\$2,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Dec 4, 2023	SYSTEM	(\$2,350.00)	
					13	Dec 18, 2023	SYSTEM	\$2,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weingl1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	Dec 18, 2023	SYSTEM	(\$2,350.00)	
					14	Jan 2, 2024	SYSTEM	\$2,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					14	Jan 2, 2024	SYSTEM	(\$2,350.00)	
					15	Jan 17, 2024	SYSTEM	\$2,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					15	Jan 17, 2024	SYSTEM	(\$2,350.00)	
					16	Feb 2, 2024	SYSTEM	\$2,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					16	Feb 2,	SYSTEM	(\$2,350.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3281	0210	SIDEWALK	Material			2024			
		HAND- RAILING WITH BALUSTERS			17	Feb 16, 2024	SYSTEM	\$2,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$2,350.00)	
					18	Mar 1, 2024	SYSTEM	\$2,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					18	Mar 1, 2024	SYSTEM	(\$2,350.00)	
					19	Mar 18, 2024	SYSTEM	\$2,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$2,350.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0210 -	- Total						\$0.00	
	0220	PAVED APPROACH, 7 IN.	Material		4	Aug 2, 2023	SYSTEM	\$12,834.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Aug 2, 2023	SYSTEM	(\$12,834.00)	
					5	Aug 16, 2023	SYSTEM	\$23,156.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Aug 16, 2023	SYSTEM	(\$23,156.40)	
					6	Sep 5, 2023	SYSTEM	\$34,403.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					6	Sep 5, 2023	SYSTEM	(\$34,403.40)	
					7	Sep 18, 2023	SYSTEM	\$41,013.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Sep 18, 2023	SYSTEM	(\$41,013.60)	
					8	Oct 2, 2023	SYSTEM	\$41,013.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Oct 2, 2023	SYSTEM	(\$41,013.60)	
					9	Oct 16, 2023	SYSTEM	\$41,013.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Oct 16, 2023	SYSTEM	(\$41,013.60)	
					10	Nov 2, 2023	SYSTEM	\$41,013.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Nov 2, 2023	SYSTEM	(\$41,013.60)	
					11	Nov 16, 2023	SYSTEM	\$41,013.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Nov 16, 2023	SYSTEM	(\$41,013.60)	
					12	Dec 4, 2023	SYSTEM	\$41,013.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Dec 4, 2023	SYSTEM	(\$41,013.60)	
					13	Dec 18,	SYSTEM	\$41,013.60	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3281	0220	PAVED APPROACH, 7	Material			2023			Estimate Item Adjustment (0005) due to user weingl1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		IN.			13	Dec 18, 2023	SYSTEM	(\$41,013.60)	
					14	Jan 2, 2024	SYSTEM	\$45,581.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					14	Jan 2, 2024	SYSTEM	(\$45,581.40)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0220 -	· Total						\$0.00	
	0230	PAVED APPROACH, 8 IN.	Material		4	Aug 2, 2023	SYSTEM	\$26,245.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Aug 2, 2023	SYSTEM	(\$26,245.00)	
					5	Aug 16, 2023	SYSTEM	\$29,275.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Aug 16, 2023	SYSTEM	(\$29,275.50)	
					6	Sep 5, 2023	SYSTEM	\$33,524.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Sep 5, 2023	SYSTEM	(\$33,524.00)	
					11	Nov 16, 2023	SYSTEM	\$13,904.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11	Nov 16, 2023	SYSTEM	(\$13,904.20)	
					12	Dec 4, 2023	SYSTEM	\$83,083.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					12	Dec 4, 2023	SYSTEM	(\$83,083.70)	
					13	Dec 18, 2023	SYSTEM	\$167,343.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weingl1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					13	Dec 18, 2023	SYSTEM	(\$167,343.20)	
					14	Jan 2, 2024	SYSTEM	\$73,802.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					14	Jan 2, 2024	SYSTEM	(\$73,802.39)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0230 -	- Total						\$0.00	
	0240	CONCRETE SIDEWALK, 4 IN.	Material		5	Aug 16, 2023	SYSTEM	\$28,441.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Aug 16, 2023	SYSTEM	(\$28,441.80)	
					6	Sep 5, 2023	SYSTEM	\$51,133.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					6	Sep 5, 2023	SYSTEM	(\$51,133.60)	
					7	Sep 18, 2023	SYSTEM	\$61,101.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Sep 18,	SYSTEM	(\$61,101.80)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3281	0240	CONCRETE	Material			2023			
		SIDEWALK, 4 IN.			8	Oct 2, 2023	SYSTEM	\$78,071.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Oct 2, 2023	SYSTEM	(\$78,071.20)	
					9	Oct 16, 2023	SYSTEM	\$101,043.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Oct 16, 2023	SYSTEM	(\$101,043.60)	
					10	Nov 2, 2023	SYSTEM	\$91,784.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					10	Nov 2, 2023	SYSTEM	(\$91,784.26)	
					11	Nov 16, 2023	SYSTEM	\$126,758.06	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Nov 16, 2023	SYSTEM	(\$126,758.06)	
					12	Dec 4, 2023	SYSTEM	\$146,777.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					12	Dec 4, 2023	SYSTEM	(\$146,777.26)	
					13	Dec 18, 2023	SYSTEM	\$162,992.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weingl1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					13	Dec 18, 2023	SYSTEM	(\$162,992.26)	
					14	Jan 2, 2024	SYSTEM	\$141,156.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					14	Jan 2, 2024	SYSTEM	(\$141,156.52)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0240 -	Total						\$0.00	
	0270	CONCRETE CURB (6 IN. HEIGHT AND	Material		14	Jan 2, 2024	SYSTEM	\$12,188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		UNDER)			14	Jan 2, 2024	SYSTEM	(\$12,188.00)	
					15	Jan 17, 2024	SYSTEM	\$16,456.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					15	Jan 17, 2024	SYSTEM	(\$16,456.00)	
					16	Feb 2, 2024	SYSTEM	\$23,804.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					16	Feb 2, 2024	SYSTEM	(\$23,804.00)	
					17	Feb 16, 2024	SYSTEM	\$23,804.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$23,804.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0270 -	Total						\$0.00	
	0300	INTEGRAL CURB (OVER	Material		14	Jan 2, 2024	SYSTEM	\$11,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment



June 2000 Section Type Augustment Augustment Type Augustment Augustment Augustment Type Augustment Augustment Type Augustment Augustment Augustment Type Augustment A	oject	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Material Type Material Type Material Type Material Type Material Type T	oject	LIIIC	Description		Adjustment				Amount	romana
TYPE A	3281	0300	6 IN HEIGHT)	Material	Туре					Fetimate Exception 11 on the current Payment Estimate
Total S0.00 Material - Total S0.00	70201	0000		Material		14	Jan 2	SYSTEM	(\$11 400 00)	Estimate Exception 11 of the outront aymont Estimate.
Material - Total Support Suppo								0.0.2	(\$11,100.00)	
19					- Total				\$0.00	
Type				Material - Tot	tal					
TALL FESCUE 2024 Estimate Eman Adjustment (0005) due to user hillforwardiding Payment Estimate. 2024 202										
Total S0.00		0740	TALL FESCUE	Material		19		SYSTEM	\$49,612.50	Estimate Item Adjustment (0005) due to user hillt5 overridding Payment
Material - Total S0.00						19		SYSTEM	(\$49,612.50)	
19					- Total				\$0.00	
19				Material - Tot	tal				\$0.00	
TOPSOIL 2024 Estimate Item Adjustment (0006) due to user hills overridding Payment Estimate Estimate Estimate Estimate Exception 9 on the current Payment Estimate Estimate Exception 9 on the current Payment Estimate Estimate Exception 9 on the current Payment Estimate Estimate Exception 9 on the current Payment Estimate Estimate Exception 9 on the current Payment Estimate Item Adjustment (0006) due to user hills overridding Payment Estimate Item Adjustment (0007) due to user hills overridding Payment Estimate Exception 9 on the current Payment Estimate Estimate Exception 10 on the current Payment Esti		0740 -	Total						\$0.00	
		0760		Material		19		SYSTEM	\$697.50	Estimate Item Adjustment (0006) due to user hillt5 overridding Payment
						19		SYSTEM	(\$697.50)	
18					- Total				\$0.00	
18				Material - Tot	tal				\$0.00	
HIGHWAY LIGHTING		0760 -	· Total						\$0.00	
19		0920	HIGHWAY	Material		18		SYSTEM	\$7,240.00	Estimate Item Adjustment (0005) due to user hillt5 overridding Payment
2024 Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate. 19						18		SYSTEM	(\$7,240.00)	
2024 -Total \$0.00						19		SYSTEM	\$7,240.00	Estimate Item Adjustment (0007) due to user hillt5 overridding Payment
Material - Total \$0.00						19		SYSTEM	(\$7,240.00)	
SIGNAL HEAD, TYPE 3T					- Total				\$0.00	
SIGNAL HEAD, TYPE Stockpile STMI - Total S1,586.82 Payment Estimate Item Adjustment generated Stockpile Transaction S1,586.82				Material - Tot	tal				\$0.00	
HEAD, TYPE Stockpile STMI - Total \$1,586.82		0920 -	- Total						\$0.00	
Construction Stockpile STMI - Total \$1,586.82		0930	HEAD, TYPE	Stockpile		16		SYSTEM	\$1,586.82	Payment Estimate Item Adjustment generated Stockpile Transaction
9930 - Total \$1,586.82 0940 SIGNAL HEAD, TYPE Stockpile STMI 16 Feb 2, 2024 SYSTEM \$739.87 Payment Estimate Item Adjustment generated Stockpile Transaction - Total \$739.87 0940 - Total \$739.87 0950 SIGNAL Construction 16 Feb 2, SYSTEM \$6,341.40 Payment Estimate Item Adjustment generated Stockpile Transaction			31						\$1,586.82	
0940 SIGNAL HEAD, TYPE Stockpile STMI - Total S739.87 Payment Estimate Item Adjustment generated Stockpile Transaction S739.87 Payment Estimate Item Adjustment generated S739.87 Payment generated S7399.87 Payment generated S7399.87 Payment generated				Construction	Stockpile ST	MI - Total			· ·	
HEAD, TYPE Stockpile STMI -Total \$739.87									\$1,586.82	
-Total \$739.87		0940	HEAD, TYPE	Stockpile		16		SYSTEM	\$739.87	Payment Estimate Item Adjustment generated Stockpile Transaction
0940 - Total SIGNAL Construction 16 Feb 2, SYSTEM \$6,341.40 Payment Estimate Item Adjustment generated Stockpile Transaction			31	OTIVII	- Total				\$739.87	
0950 SIGNAL Construction 16 Feb 2, SYSTEM \$6,341.40 Payment Estimate Item Adjustment generated Stockpile Transaction				Construction	Stockpile S	MI - Total			\$739.87	
		0940 -	Total						\$739.87	
		0950	HEAD, TYPE	Stockpile		16		SYSTEM	\$6,341.40	Payment Estimate Item Adjustment generated Stockpile Transaction
3S STMI - Total \$6,341.40			38	STIVII	- Total				\$6,341.40	
Construction Stockpile STMI - Total \$6,341.40				Construction	Stockpile S	「MI - Total			\$6,341.40	
0950 - Total \$6,341.40		0950 -	Total						\$6,341.40	
O960 SIGNAL Construction HEAD, TYPE Stockpile STML STML STML STML STML STML STML STML		0960	HEAD, TYPE	Stockpile		16		SYSTEM	\$617.98	Payment Estimate Item Adjustment generated Stockpile Transaction
4S STMI - Total \$617.98			4S	SIMI	- Total				\$617.98	
Construction Stockpile STMI - Total \$617.98				Construction	Stockpile S	ΓΜΙ - Total			\$617.98	
0960 - Total \$617.98		0960 -	Total						\$617.98	
970 SIGNAL HEAD, TYPE 38 Construction 38 Signal Head, Type 38 Signal Hea		0970	HEAD, TYPE			16		SYSTEM	(\$5,520.96)	Payment Estimate Item Adjustment generated Stockpile Transaction



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3281	0970	SIGNAL HEAD, TYPE	Construction Stockpile		17	Feb 16, 2024	SYSTEM	(\$5,520.96)	Payment Estimate Item Adjustment generated Stockpile Transaction
		3B		- Total				(\$11,041.92)	
			Construction	Stockpile - 1	「otal			(\$11,041.92)	
			Construction Stockpile		16	Feb 2, 2024	SYSTEM	\$58,660.20	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$58,660.20	
			Construction	Stockpile S	ΓMI - Total			\$58,660.20	
			Material		16	Feb 2, 2024	SYSTEM	\$8,960.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					16	Feb 2, 2024	SYSTEM	(\$8,960.00)	
					17	Feb 16, 2024	SYSTEM	\$17,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$17,920.00)	
					18	Mar 1, 2024	SYSTEM	\$17,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					18	Mar 1, 2024	SYSTEM	(\$17,920.00)	
					19	Mar 18, 2024	SYSTEM	\$17,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$17,920.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0970 -	Total						\$47,618.28	
	0980	SIGNAL HEAD, TYPE	Construction Stockpile		16	Feb 2, 2024	SYSTEM	(\$1,624.20)	Payment Estimate Item Adjustment generated Stockpile Transaction
		4B			17	Feb 16, 2024	SYSTEM	(\$3,248.40)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$4,872.60)	
								(\$4,072.00)	
			Construction	Stockpile - 1	Total			(\$4,872.60)	
			Construction Stockpile	Stockpile - 1	Total 16	Feb 2, 2024	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	Stockpile - 1			SYSTEM	(\$4,872.60)	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction Stockpile	- Total	16	2024	SYSTEM	(\$4,872.60) \$25,987.20	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction Stockpile STMI	- Total	16	2024	SYSTEM	(\$4,872.60) \$25,987.20 \$25,987.20	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			Construction Stockpile STMI	- Total	16 「MI - Total	2024 Feb 2,		(\$4,872.60) \$25,987.20 \$25,987.20 \$25,987.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment
			Construction Stockpile STMI	- Total	16 TMI - Total	Feb 2, 2024	SYSTEM	(\$4,872.60) \$25,987.20 \$25,987.20 \$25,987.20 \$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment
			Construction Stockpile STMI	- Total	16 FMI - Total 16	Feb 2, 2024 Feb 2, 2024 Feb 16,	SYSTEM	(\$4,872.60) \$25,987.20 \$25,987.20 \$25,987.20 \$2,500.00 (\$2,500.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment
			Construction Stockpile STMI	- Total	16 TMI - Total 16 16 17	Feb 2, 2024 Feb 2, 2024 Feb 16, 2024 Feb 16,	SYSTEM SYSTEM	(\$4,872.60) \$25,987.20 \$25,987.20 \$25,987.20 \$2,500.00 (\$2,500.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment
			Construction Stockpile STMI	- Total	16 FMI - Total 16 16 17 17	Feb 2, 2024 Feb 16, 2024 Feb 16, 2024 Mar 1,	SYSTEM SYSTEM SYSTEM	(\$4,872.60) \$25,987.20 \$25,987.20 \$25,987.20 \$2,500.00 (\$2,500.00) \$7,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment
			Construction Stockpile STMI	- Total	16 16 16 17 17	Feb 2, 2024 Feb 16, 2024 Feb 16, 2024 Mar 1, 2024 Mar 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,872.60) \$25,987.20 \$25,987.20 \$25,987.20 \$2,500.00 (\$2,500.00) \$7,500.00 \$7,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment
			Construction Stockpile STMI	- Total	16 16 16 17 17 18	Feb 2, 2024 Feb 16, 2024 Feb 16, 2024 Mar 1, 2024 Mar 18, 4024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,872.60) \$25,987.20 \$25,987.20 \$25,987.20 \$2,500.00 (\$2,500.00) \$7,500.00 (\$7,500.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3281	0980	SIGNAL HEAD, TYPE 4B	Material - To	tal				\$0.00	
	0980 -	Total						\$21,114.60	
	0990	SH-FLAT SHEET -	Construction Stockpile		16	Feb 2, 2024	SYSTEM	(\$3,809.74)	Payment Estimate Item Adjustment generated Stockpile Transaction
		SIGNAL SIGN			17	Feb 16, 2024	SYSTEM	(\$3,809.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$7,619.49)	
			Construction	Stockpile - T	「otal			(\$7,619.49)	
			Construction Stockpile		1	May 16, 2023	SYSTEM	\$14,073.03	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMA	- Total				\$14,073.03	
			Construction	Stockpile S1	ΓMA - Tota	al		\$14,073.03	
			Material		16	Feb 2, 2024	SYSTEM	\$3,813.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					16	Feb 2, 2024	SYSTEM	(\$3,813.00)	
					17	Feb 16, 2024	SYSTEM	\$7,626.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$7,626.00)	
					18	Mar 1, 2024	SYSTEM	\$7,626.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					18	Mar 1, 2024	SYSTEM	(\$7,626.00)	
					19	Mar 18, 2024	SYSTEM	\$7,626.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$7,626.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0990 -	Total						\$6,453.54	
	1000	SIGNAL SIGN, MOUNTING HARDWARE	Material		16	Feb 2, 2024	SYSTEM	\$599.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					16	Feb 2, 2024	SYSTEM	(\$599.20)	
					17	Feb 16, 2024	SYSTEM	\$1,159.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$1,159.20)	
					18	Mar 1, 2024	SYSTEM	\$1,159.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					18	Mar 1, 2024	SYSTEM	(\$1,159.20)	
					19	Mar 18, 2024	SYSTEM	\$1,159.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$1,159.20)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1000 -	Total						\$0.00	
	1010	LUMINAIRE LED-A, 120 VOLT	Material		17	Feb 16, 2024	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 15 on the current Payment Estimate.



				1					
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3281	1010	COMPATIBLE	Material		17	Feb 16, 2024	SYSTEM	(\$1,700.00)	
					18	Mar 1, 2024	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					18	Mar 1, 2024	SYSTEM	(\$1,700.00)	
					19	Mar 18, 2024	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$1,700.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1010 -	· Total						\$0.00	
	1020	POST, SIGNAL 8 FT.	Material		16	Feb 2, 2024	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					16	Feb 2, 2024	SYSTEM	(\$2,700.00)	
					17	Feb 16, 2024	SYSTEM	\$5,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$5,400.00)	
					18	Mar 1, 2024	SYSTEM	\$5,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					18	Mar 1, 2024	SYSTEM	(\$5,400.00)	
					19	Mar 18, 2024	SYSTEM	\$5,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$5,400.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1020 -	- Total						\$0.00	
	1030	POST, SIGNAL 15 FT.	Construction Stockpile STMI		16	Feb 2, 2024	SYSTEM	\$7,021.44	Payment Estimate Item Adjustment generated Stockpile Transaction
			O TIVII	- Total				\$7,021.44	
			Construction	Stockpile S1	ГМI - Tota			\$7,021.44	
	1030 -	- Total						\$7,021.44	
	1040	POST, TYPE CL, 15 FT. ARM OR 4.6 M	Construction Stockpile STMI		9	Oct 16, 2023	SYSTEM	\$4,729.72	Payment Estimate Item Adjustment generated Stockpile Transaction
		ARM OR 4.6 M	OTIVII	- Total				\$4,729.72	
			Construction	Stockpile S1	ГМI - Tota			\$4,729.72	
	1040 -	- Total						\$4,729.72	
	1050	POST, TYPE CL, 35 FT. ARM OR 10.7	Construction Stockpile		17	Feb 16, 2024	SYSTEM	(\$15,659.03)	Payment Estimate Item Adjustment generated Stockpile Transaction
		M ARM		- Total				(\$15,659.03)	
			Construction	Stockpile - 1	Γotal			(\$15,659.03)	
			Construction Stockpile STMI		9	Oct 16, 2023	SYSTEM	\$23,488.54	Payment Estimate Item Adjustment generated Stockpile Transaction
			O I IVII	- Total				\$23,488.54	
			Construction	Stockpile S	ГМI - Tota			\$23,488.54	
			Material		17	Feb 16, 2024	SYSTEM	\$21,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$21,400.00)	



1000 POST_TYPE APRIL	roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
18	S3281	1050	CL, 35 FT. ARM OR 10.7	Material		18		SYSTEM	\$21,400.00	Estimate Item Adjustment (0012) due to user hillt5 overridding Payment
2024 Estimate Elem Adjustment (0016) due to user hills overending Payment Estimate Estimate Exception 19 on the current Payment Estimate.			M ARM			18		SYSTEM	(\$21,400.00)	
1000 POST, TYPE Solopile Transaction 17						19		SYSTEM	\$21,400.00	Estimate Item Adjustment (0014) due to user hillt5 overridding Payment
100						19		SYSTEM	(\$21,400.00)	
1060 POST, TYPE Construction 17 Feb 16, SYSTEM (\$20.544.92) Payment Estimate Item Adjustment generated Stockpile Transaction (\$20.544.92) Payment Estimate Item Adjustment generated Stockpile Transaction (\$20.544.92) Payment Estimate Item Adjustment generated Stockpile Transaction SYSTEM SY					- Total				\$0.00	
1000 POST, TYPE ARM OR 12.2 M ARM Construction Stockpile Total (20,544.92) Payment Estimate Item Adjustment generated Stockpile Transaction (20,544.92) Payment Estimate Item Adjustment generated Stockpile Transaction (20,544.92) Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Total Stoc				Material - Tot	al				\$0.00	
Cut Cut Construction Stockpile -Total (\$20,544.92) (1050 -	Total						\$7,829.51	
Construction Stockpile Total		1060	CL, 40 FT.			17		SYSTEM	(\$20,544.92)	Payment Estimate Item Adjustment generated Stockpile Transaction
					- Total				(\$20,544.92)	
Stockpile STMI				Construction	Stockpile - T	otal .			(\$20,544.92)	
Address Construction Stockpile STMI - Total Substitute Sub				Stockpile		9		SYSTEM	\$30,817.38	Payment Estimate Item Adjustment generated Stockpile Transaction
Material				STMI	- Total				\$30,817.38	
2024 Estimate Item Adjustment (0017) due to user hittlis overridding Payment Estimate Item Adjustment (0017) due to user hittlis overridding Payment Estimate Exception 21 on the current Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Estimate Exception 21 on the current Payment Estimate Item Adjustment (0017) due to user hittlis overridding Payment Estimate Estimate Estimate Estimate Estimate Estimate Estimate Item Adjustment (0015) due to user hittlis overridding Payment Estimate Estimate Item Adjustment (0015) due to user hittlis overridding Payment Estimate Item Adjustment (0015) due to user hittlis overridding Payment Estimate Item Adjustment (0015) due to user hittlis overridding Payment Estimate Item Adjustment (0015) due to user hittlis overridding Payment Estimate Item Adjustment (0015) due to user hittlis overridding Payment Estimate Item Adjustment (0015) due to user hittlis overridding Payment Estimate Item Adjustment (0015) due to user hittlis overridding Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Advisory (Sec. 850.00) 1060 - Total				Construction	Stockpile S1	MI - Total			\$30,817.38	
2024 18				Material		17		SYSTEM	\$26,850.00	Estimate Item Adjustment (0017) due to user hillt5 overridding Payment
2024						17		SYSTEM	(\$26,850.00)	
19						18		SYSTEM	\$26,850.00	Estimate Item Adjustment (0013) due to user hillt5 overridding Payment
2024 Estimate Item Adjustment (0015) due to user hill5 overridding Payment Estimate Exception 21 on the current Payment Estimate. Sind Estimate Exception 21 on the current Payment Estimate.						18		SYSTEM	(\$26,850.00)	
1060 - Total						19		SYSTEM	\$26,850.00	Estimate Item Adjustment (0015) due to user hillt5 overridding Payment
1060 - Total						19		SYSTEM	(\$26,850.00)	
1070 POST, TYPE CL, 45 FT. ARM OR 15. 2 M ARM 1080 POST, TYPE CL, 50 FT. ARM OR 15. 2 M ARM 1080 POST, TYPE CL, 50 FT. ARM OR 15. 2 M ARM 1080 POST, TYPE CL, 50 FT. ARM OR 15. 2 M ARM 1090 POST, TYPE CL, 55 FT. ARM OR 15. 2 M ARM 1090 POST, TYPE CL, 55 FT. ARM OR 15. 2 M ARM 1090 POST, TYPE CL, 55 FT. ARM OR 15. 2 M ARM 1090 POST, TYPE CL, 55 FT. ARM OR 15. 2 M ARM 1090 POST, TYPE CL, 55 FT. ARM OR 15. 2 M ARM 1090 POST, TYPE CL, 55 FT. ARM OR 15. 2 M ARM 1090 Total 1090 Total 1090 POST, TYPE C. Construction Stockpile STMI - Total 1090 POST, TYPE C. Construction Stockpile STMI - Total 1090 Total 1090 Total 1090 POST, TYPE C. Construction Stockpile STMI - Total 1090 POST, TYPE C. Construction Stockpile STMI - Total 1090 Total 1090 - Total 1090 Total 1090 POST, TYPE C. Construction Stockpile STMI - Total 1090 Total					- Total				\$0.00	
1070				Material - Tot	al				\$0.00	
Ccl. 45 FT, ARM OR 13.7 STMI -Total \$11,466.02		1060 -	Total						\$10,272.46	
Total \$11,466.02		1070	CL, 45 FT.	Stockpile		9		SYSTEM		
1070 - Total				J I IVII	- Total				\$11,466.02	
1080 POST, TYPE CL, 50 FT. ARM OR 15.2 M ARM Construction Stockpile STMI - Total \$12,091.42 Payment Estimate Item Adjustment generated Stockpile Transaction \$12,091.42 \$14,551.68 \$14,551				Construction	Stockpile S1	「MI - Total			\$11,466.02	
CL, 50 FT. ARM OR 15.2 STMI -Total \$12,091.42		1070 -	Total						\$11,466.02	
M ARM		1080	CL, 50 FT.	Stockpile		9		SYSTEM	\$12,091.42	Payment Estimate Item Adjustment generated Stockpile Transaction
1080 - Total \$12,091.42				SIMI	- Total				\$12,091.42	
1090 POST, TYPE CL, 55 FT. ARM CL, 55 FT. ARM CR 4.6 M AR				Construction	Stockpile S1	「MI - Total			\$12,091.42	
CL, 55 FT. Stockpile STMI 2023 \$14,551.68		1080 -	Total						\$12,091.42	
- Total \$14,551.68		1090	CL, 55 FT.	Stockpile		9		SYSTEM	\$14,551.68	Payment Estimate Item Adjustment generated Stockpile Transaction
1090 - Total \$14,551.68 1100 POST, TYPE C, 15 FT. ARM OR 4.6 M ARM OR			ARM	SIMI	- Total				\$14,551.68	
1100 POST, TYPE Construction Stockpile STMI 9 Oct 16, 2023 9 SYSTEM \$3,987.72 Payment Estimate Item Adjustment generated Stockpile Transaction \$3,987.72 \$3,987.72				Construction	Stockpile S1	ſMI - Total			\$14,551.68	
1100 POST, TYPE C, 15 FT. ARM OR 4.6 M ARM OR 4.6 M ARM OR 4.6 M ARM OR 4.6 M ARM OR 4.6 M ARM OR 4.6 M ARM OR 4.6 M ARM OR 4.6 M ARM OR 4.6 M ARM OR 4.6 M ARM OR 4.6 M ARM OR 4.6 M ARM OR 4.6 M ARM OR 4.6 M ARM OR 4.6 M ARM OR 4.6 M ARM OR 4.6 M ARM OR 4.6 M ARM		1090 -	Total						\$14,551.68	
- Total \$3,987.72			POST, TYPE C, 15 FT. ARM	Stockpile		9		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile STMI - Total \$3,987.72			OR 4.6 M ARM	SIMI	- Total				\$3,987.72	
				Construction	Stockpile S1	MI - Total			\$3,987.72	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3281	1100 -	· Total						\$3,987.72	
	1110	POST, TYPE C, 20 FT. ARM OR 6.1 M ARM	Construction Stockpile STMI		9	Oct 16, 2023	SYSTEM	\$13,530.90	Payment Estimate Item Adjustment generated Stockpile Transaction
		010.1 W/W	OTIVII	- Total				\$13,530.90	
			Construction	Stockpile S	TMI - Tota	1		\$13,530.90	
	1110 -	Total						\$13,530.90	
	1120	POST, TYPE C, 25 FT. ARM OR 7.6 M ARM	Construction Stockpile		16	Feb 2, 2024	SYSTEM	(\$10,038.20)	Payment Estimate Item Adjustment generated Stockpile Transaction
		OIC 7.0 W AIRW		- Total				(\$10,038.20)	
			Construction	Stockpile - 1	Γotal			(\$10,038.20)	
			Construction Stockpile STMI		9	Oct 16, 2023	SYSTEM	\$20,076.40	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$20,076.40	
			Construction	Stockpile S	TMI - Tota	l e		\$20,076.40	
			Material		16	Feb 2, 2024	SYSTEM	\$14,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hillt5 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					16	Feb 2, 2024	SYSTEM	(\$14,520.00)	
					17	Feb 16, 2024	SYSTEM	\$14,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$14,520.00)	
					18	Mar 1, 2024	SYSTEM	\$14,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					18	Mar 1, 2024	SYSTEM	(\$14,520.00)	
					19	Mar 18, 2024	SYSTEM	\$14,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$14,520.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1120 -	Total						\$10,038.20	
	1130	POST, TYPE C, 30 FT. ARM OR 9.1 M ARM	Construction Stockpile STMI		9	Oct 16, 2023	SYSTEM	\$31,694.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		CIT O. I WI AIRWI		- Total				\$31,694.00	
			Construction	Stockpile S	TMI - Tota	l		\$31,694.00	
	1130 -	Total						\$31,694.00	
	1140	POST, TYPE C, 35 FT. ARM OR 10.7 M	Construction Stockpile STMI		9	Oct 16, 2023	SYSTEM	\$33,448.30	Payment Estimate Item Adjustment generated Stockpile Transaction
		ARM		- Total				\$33,448.30	
			Construction	Stockpile S	TMI - Tota			\$33,448.30	
	1140 -	Total						\$33,448.30	
	1150	POST, TYPE C, 40 FT. ARM OR 12.2 M	Construction Stockpile STMI		9	Oct 16, 2023	SYSTEM	\$43,168.50	Payment Estimate Item Adjustment generated Stockpile Transaction
		ARM		- Total				\$43,168.50	
			Construction	Stockpile S	TMI - Tota			\$43,168.50	
	1150 -	· Total						\$43,168.50	
	1160	POST, TYPE C, 45 FT. ARM OR 13.7 M	Construction Stockpile		16	Feb 2, 2024	SYSTEM	(\$18,569.08)	Payment Estimate Item Adjustment generated Stockpile Transaction
		ARM		- Total				(\$18,569.08)	
			Construction	Stockpile - 1	Total			(\$18,569.08)	
			Construction Stockpile		9	Oct 16, 2023	SYSTEM	\$46,422.70	Payment Estimate Item Adjustment generated Stockpile Transaction



				1					
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
6S3281	1160	POST, TYPE	STMI	- Total				\$46,422.70	
		C, 45 FT. ARM OR 13.7 M	Construction	Stockpile S	MI - Total			\$46,422.70	
		ARM	Material		16	Feb 2, 2024	SYSTEM	\$24,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					16	Feb 2, 2024	SYSTEM	(\$24,200.00)	Estimate Exception to on the outlier aymone Estimate.
					17	Feb 16, 2024	SYSTEM	\$24,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hillt5 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$24,200.00)	
					18	Mar 1, 2024	SYSTEM	\$24,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					18	Mar 1, 2024	SYSTEM	(\$24,200.00)	
					19	Mar 18, 2024	SYSTEM	\$24,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$24,200.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1160 -	Total						\$27,853.62	
	1170	POST, TYPE C, 50 FT. ARM OR 15.2 M	Construction Stockpile STMI		9	Oct 16, 2023	SYSTEM	\$10,048.80	Payment Estimate Item Adjustment generated Stockpile Transaction
		ARM		- Total				\$10,048.80	
			Construction	Stockpile S	MI - Total			\$10,048.80	
	1170 -	Total						\$10,048.80	
	1180	POST, TYPE C, 55 FT. ARM	Construction Stockpile STMI		9	Oct 16, 2023	SYSTEM	\$13,133.40	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$13,133.40	
			Construction	Stockpile S	MI - Total			\$13,133.40	
	1180 -	Total						\$13,133.40	
	1190	POST, TYPE B, LONGEST ARM 40 FT.	Construction Stockpile STMI		9	Oct 16, 2023	SYSTEM	\$12,946.84	Payment Estimate Item Adjustment generated Stockpile Transaction
		OR 12.		- Total				\$12,946.84	
			Construction	Stockpile S1	MI - Total			\$12,946.84	
	1190 -	Total						\$12,946.84	
	1200	POST, TYPE BL, LONGEST ARM 40 FT.	Construction Stockpile STMI		9	Oct 16, 2023	SYSTEM	\$31,238.20	Payment Estimate Item Adjustment generated Stockpile Transaction
		OR 12.		- Total				\$31,238.20	
			Construction	Stockpile S	MI - Total			\$31,238.20	
	1200 -	Total						\$31,238.20	
	1210	CONTROLLER ASSEMBLY HOUSING,	Construction Stockpile		16	Feb 2, 2024	SYSTEM	(\$12,114.11)	Payment Estimate Item Adjustment generated Stockpile Transaction
		nooniid,			17	Feb 16, 2024	SYSTEM	(\$12,114.10)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$24,228.21)	
			Construction	Stockpile - 1	otal			(\$24,228.21)	
			Construction Stockpile		10	Nov 2, 2023	SYSTEM	\$43,488.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI		12	Dec 4, 2023	SYSTEM	\$150,337.68	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$193,825.68	
			Construction	Stockpile S	MI - Total			\$193,825.68	
			Material		16	Feb 2,	SYSTEM	\$15,435.00	This adjustment offsets the original system-generated Material Payment
									· · · · · · · · · · · · · · · · · · ·



_									
et	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
			,,	Туре					
31	1210	CONTROLLER ASSEMBLY HOUSING,	Material			2024			Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate.
		HOOSING,			16	Feb 2, 2024	SYSTEM	(\$15,435.00)	
					17	Feb 16, 2024	SYSTEM	\$30,870.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hillt5 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$30,870.00)	
					18	Mar 1, 2024	SYSTEM	\$30,870.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					18	Mar 1, 2024	SYSTEM	(\$30,870.00)	
					19	Mar 18, 2024	SYSTEM	\$30,870.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$30,870.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1210 -	Total						\$169,597.47	
	1220	CONDUIT, 2 IN., TRENCH WITH	Material		14	Jan 2, 2024	SYSTEM	\$325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.
		TRACER WIRE			14	Jan 2, 2024	SYSTEM	(\$325.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1220 -	Total						\$0.00	
	1230	CONDUIT, 3 IN., TRENCH WITH	Material		13	Dec 18, 2023	SYSTEM	\$1,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user weingl1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
		TRACER WIRE			13	Dec 18, 2023	SYSTEM	(\$1,540.00)	
					14	Jan 2, 2024	SYSTEM	\$3,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate.
									Estimate Exception 17 on the current Fayment Estimate.
					14	Jan 2, 2024	SYSTEM	(\$3,460.00)	Estimate Exception 17 on the current Payment Estimate.
				- Total	14		SYSTEM	(\$3,460.00) \$0.00	Estimate Exception 17 on the current Payment Estimate.
			Material - To		14		SYSTEM	, , , , ,	Estimate Exception 17 on the current Payment Estimate.
	1230 -	· Total	Material - To		14		SYSTEM	\$0.00	Estimate Exception 17 on the current Payment Estimate.
	1230 -	CONDUIT, 3 IN., PUSHED WITH			13		SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weing/1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
		CONDUIT, 3 IN., PUSHED				2024 Dec 18,		\$0.00 \$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weingl1 overridding Payment
		CONDUIT, 3 IN., PUSHED WITH TRACER			13	Dec 18, 2023	SYSTEM	\$0.00 \$0.00 \$0.00 \$3,168.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weingl1 overridding Payment
		CONDUIT, 3 IN., PUSHED WITH TRACER			13	Dec 18, 2023 Dec 18, 2023 Jan 2,	SYSTEM	\$0.00 \$0.00 \$0.00 \$3,168.00 (\$3,168.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weingl 1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillts overridding Payment
		CONDUIT, 3 IN., PUSHED WITH TRACER			13 13 14	Dec 18, 2023 Dec 18, 2023 Jan 2, 2024 Jan 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$3,168.00 (\$3,168.00) \$10,128.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weingl1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment
		CONDUIT, 3 IN., PUSHED WITH TRACER		tal - Total	13 13 14	Dec 18, 2023 Dec 18, 2023 Jan 2, 2024 Jan 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$3,168.00 (\$3,168.00) \$10,128.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weingl 1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment
	1240	CONDUIT, 3 IN., PUSHED WITH TRACER	Material	tal - Total	13 13 14	Dec 18, 2023 Dec 18, 2023 Jan 2, 2024 Jan 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$3,168.00 (\$3,168.00) \$10,128.00 (\$10,128.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weingl 1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment
	1240	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE Total CABLE, 10 AWG 1 CONDUCTOR,	Material	tal - Total	13 13 14	Dec 18, 2023 Dec 18, 2023 Jan 2, 2024 Jan 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$3,168.00 (\$3,168.00) \$10,128.00 (\$10,128.00) \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weingl 1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillts overridding Payment
	1240 -	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE Total CABLE, 10 AWG 1	Material Material - To	tal - Total	13 13 14	Dec 18, 2023 Dec 18, 2023 Jan 2, 2024 Feb 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$3,168.00 (\$3,168.00) \$10,128.00 (\$10,128.00) \$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weingl1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment



Dunings	1:	Description	A -1:	Other	F-4	0	0	A	Develop
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3281	1250	CABLE, 10 AWG 1	Material			2024			Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 27 on the current Payment Estimate.
		CONDUCTOR, POLE AND BRAC			18	Mar 1, 2024	SYSTEM	(\$510.00)	
					19	Mar 18, 2024	SYSTEM	\$510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hillt5 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$510.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1250 -	- Total						\$0.00	
	1280	CABLE, 12 AWG 2 CONDUCTOR	Material		17	Feb 16, 2024	SYSTEM	\$768.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hillt5 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$768.00)	
					18	Mar 1, 2024	SYSTEM	\$768.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					18	Mar 1, 2024	SYSTEM	(\$768.00)	
					19	Mar 18, 2024	SYSTEM	\$768.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$768.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1280 -	- Total						\$0.00	
	1290	CABLE, 16 AWG 2 CONDUCTOR	Material		16	Feb 2, 2024	SYSTEM	\$442.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					16	Feb 2, 2024	SYSTEM	(\$442.50)	
					17	Feb 16, 2024	SYSTEM	\$1,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$1,530.00)	
					18	Mar 1, 2024	SYSTEM	\$1,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hillt5 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					18	Mar 1, 2024	SYSTEM	(\$1,530.00)	
					19	Mar 18, 2024	SYSTEM	\$1,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$1,530.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1290 -	- Total						\$0.00	
	1300	CABLE, 16 AWG 5 CONDUCTOR	Material		16	Feb 2, 2024	SYSTEM	\$914.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hillt5 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					16	Feb 2, 2024	SYSTEM	(\$914.50)	
					17	Feb 16, 2024	SYSTEM	\$3,193.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$3,193.00)	



ct Line								
	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
81 1300	CABLE, 16 AWG 5 CONDUCTOR	Material		18	Mar 1, 2024	SYSTEM	\$3,193.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				18	Mar 1, 2024	SYSTEM	(\$3,193.00)	
				19	Mar 18, 2024	SYSTEM	\$3,193.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				19	Mar 18, 2024	SYSTEM	(\$3,193.00)	
			- Total				\$0.00	
		Material - To	tal				\$0.00	
1300	- Total						\$0.00	
1310	CABLE, 16 AWG 7 CONDUCTOR	Material		16	Feb 2, 2024	SYSTEM	\$4,171.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				16	Feb 2, 2024	SYSTEM	(\$4,171.00)	
				17	Feb 16, 2024	SYSTEM	\$9,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				17	Feb 16, 2024	SYSTEM	(\$9,890.00)	
				18	Mar 1, 2024	SYSTEM	\$9,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				18	Mar 1, 2024	SYSTEM	(\$9,890.00)	
				19	Mar 18, 2024	SYSTEM	\$9,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				19	Mar 18, 2024	SYSTEM	(\$9,890.00)	
			- Total				\$0.00	
		Material - To	tal				\$0.00	
		material 10						
1310	- Total	material 10					\$0.00	
1310 1330	- Total PULL BOX, PREFORMED CLASS 2	Material		13	Dec 18, 2023	SYSTEM	\$0.00 \$7,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weingl1 overridding Payme Estimate Exception 14 on the current Payment Estimate.
	PULL BOX, PREFORMED			13		SYSTEM		Estimate Item Adjustment (0010) due to user weingl1 overridding Payme
	PULL BOX, PREFORMED				2023 Dec 18,		\$7,050.00	Estimate Item Adjustment (0010) due to user weingl1 overridding Payme
	PULL BOX, PREFORMED			13	2023 Dec 18, 2023 Jan 2,	SYSTEM	\$7,050.00 (\$7,050.00)	Estimate Item Adjustment (0010) due to user weingl1 overridding Payme Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment
	PULL BOX, PREFORMED		- Total	13	2023 Dec 18, 2023 Jan 2, 2024 Jan 2,	SYSTEM	\$7,050.00 (\$7,050.00) \$9,400.00	Estimate Item Adjustment (0010) due to user weingl1 overridding Payme Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment
	PULL BOX, PREFORMED		- Total	13	2023 Dec 18, 2023 Jan 2, 2024 Jan 2,	SYSTEM	\$7,050.00 (\$7,050.00) \$9,400.00 (\$9,400.00)	Estimate Item Adjustment (0010) due to user weingl1 overridding Payme Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment
1330	PULL BOX, PREFORMED	Material	- Total	13	2023 Dec 18, 2023 Jan 2, 2024 Jan 2,	SYSTEM	\$7,050.00 (\$7,050.00) \$9,400.00 (\$9,400.00)	Estimate Item Adjustment (0010) due to user weingl1 overridding Payme Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment
1330	PULL BOX, PREFORMED CLASS 2	Material	- Total	13	2023 Dec 18, 2023 Jan 2, 2024 Jan 2,	SYSTEM	\$7,050.00 (\$7,050.00) \$9,400.00 (\$9,400.00) \$0.00	Estimate Item Adjustment (0010) due to user weingl1 overridding Payme Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
1330	PULL BOX, PREFORMED CLASS 2 - Total PULL BOX, PREFORMED	Material Material - To	- Total	13	2023 Dec 18, 2023 Jan 2, 2024 Jan 2, 2024 Dec 18,	SYSTEM SYSTEM SYSTEM	\$7,050.00 (\$7,050.00) \$9,400.00 (\$9,400.00) \$0.00 \$0.00	Estimate Item Adjustment (0010) due to user weingl1 overridding Payme Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weingl1 overridding Payment Estimate Item Adjustment (0011) due to user weingl1 overridding Payment
1330	PULL BOX, PREFORMED CLASS 2 - Total PULL BOX, PREFORMED	Material Material - To	- Total	13 14 14	Dec 18, 2023 Jan 2, 2024 Jan 2, 2024 Dec 18, 2023 Dec 18, 2023	SYSTEM SYSTEM SYSTEM	\$7,050.00 (\$7,050.00) \$9,400.00 (\$9,400.00) \$0.00 \$0.00 \$3,290.00	Estimate Item Adjustment (0010) due to user weingl1 overridding Payme Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weingl1 overridding Payment Estimate Item Adjustment (0011) due to user weingl1 overridding Payment
1330	PULL BOX, PREFORMED CLASS 2 - Total PULL BOX, PREFORMED	Material Material - To	- Total	13 14 14 13	Dec 18, 2024 Jan 2, 2024 Jan 2, 2024 Dec 18, 2023 Dec 18, 2023 Jan 2, 2024	SYSTEM SYSTEM SYSTEM SYSTEM	\$7,050.00 (\$7,050.00) \$9,400.00 (\$9,400.00) \$0.00 \$0.00 \$3,290.00	Estimate Item Adjustment (0010) due to user weingl1 overridding Payme Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weingl1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment
1330	PULL BOX, PREFORMED CLASS 2 - Total PULL BOX, PREFORMED	Material Material - To	- Total	13 14 14 13 13	Dec 18, 2024 Jan 2, 2024 Dec 18, 2023 Dec 18, 2023 Dec 18, 2023 Jan 2, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,050.00 (\$7,050.00) \$9,400.00 (\$9,400.00) \$0.00 \$0.00 \$3,290.00 (\$3,290.00)	Estimate Item Adjustment (0010) due to user weingl1 overridding Payme Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weingl1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment
1330	PULL BOX, PREFORMED CLASS 2 - Total PULL BOX, PREFORMED	Material Material - To	- Total tal	13 14 14 13 13	Dec 18, 2024 Jan 2, 2024 Dec 18, 2023 Dec 18, 2023 Dec 18, 2023 Jan 2, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,050.00 (\$7,050.00) \$9,400.00 (\$9,400.00) \$0.00 \$0.00 \$3,290.00 (\$3,290.00) (\$3,290.00)	Estimate Item Adjustment (0010) due to user weingl1 overridding Paymer Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weingl1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J6S3281	1380	MISC.	Material		19	Mar 18, 2024	SYSTEM	\$2,794.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate.												
					19	Mar 18, 2024	SYSTEM	(\$2,794.50)													
				- Total				\$0.00													
			Material - Tot	tal				\$0.00													
	1380 -	Total						\$0.00													
	1390	MISC.	Construction Stockpile		16	Feb 2, 2024	SYSTEM	(\$3,145.02)	Payment Estimate Item Adjustment generated Stockpile Transaction												
					17	Feb 16, 2024	SYSTEM	(\$4,168.98)	Payment Estimate Item Adjustment generated Stockpile Transaction												
				- Total				(\$7,314.00)													
				Stockpile - T	otal			(\$7,314.00)													
		Construction Stockpile STMI		13	Dec 18, 2023	SYSTEM	\$78,625.50	Payment Estimate Item Adjustment generated Stockpile Transaction													
				- Total				\$78,625.50													
			Construction Material	Stockpile S1	MI - Total			\$78,625.50													
			Material		16	Feb 2, 2024	SYSTEM	\$4,489.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.												
											16	Feb 2, 2024	SYSTEM	(\$4,489.20)							
					17	Feb 16, 2024	SYSTEM	\$10,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate.												
					17	Feb 16, 2024	SYSTEM	(\$10,440.00)													
					18	Mar 1, 2024	SYSTEM	\$10,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.												
						18	Mar 1, 2024	SYSTEM	(\$10,440.00)												
					19	Mar 18, 2024	SYSTEM	\$10,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 34 on the current Payment Estimate.												
								19	Mar 18, 2024	SYSTEM	(\$10,440.00)										
				- Total				\$0.00													
			Material - Tot	tal				\$0.00													
	1390 -	Total						\$71,311.50													
	1400	MISC.	Construction Stockpile		16	Feb 2, 2024	SYSTEM	(\$5,232.75)	Payment Estimate Item Adjustment generated Stockpile Transaction												
				- Total				(\$5,232.75)													
			Construction	Stockpile - T	otal			(\$5,232.75)													
			Construction Stockpile	Construction		16	Feb 2, 2024	SYSTEM	\$11,773.68	Payment Estimate Item Adjustment generated Stockpile Transaction											
			2	- Total				\$11,773.68													
			Construction	Stockpile S1	MI - Total			\$11,773.68													
			Material		13	Dec 18, 2023	SYSTEM	\$1,817.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user weingl1 overridding Payment Estimate Exception 16 on the current Payment Estimate.												
													13	Dec 18, 2023	SYSTEM	(\$1,817.00)					
					14	Jan 2, 2024	SYSTEM	\$1,817.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 21 on the current Payment Estimate.												
																		14	Jan 2, 2024	SYSTEM	(\$1,817.00)
					15	Jan 17, 2024	SYSTEM	\$1,817.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment												



Property										
Marcal 1400 Marcal 150 Mar	Project	Line	Description						Amount	Remarks
15				1,700		rambor	Date			
10	6S3281	1400	MISC.	Material						Estimate Exception 7 on the current Payment Estimate.
2024 SysTem (50,00 at 5 user) hill Coverniding Payment Estimate Exception 2 on the outered Payment Estimate Estimate Exception 2 on the outered Payment Estimate Estimate Exception 3 on the outered Payment Estimate Estimate Item Adjustment (0027) data to act while Coverniding Payment Estimate Estimate Item Adjustment (0027) data to act while Coverniding Payment Estimate Estimate Item Adjustment (0027) data to act while Coverniding Payment Estimate Estimate Item Adjustment (0027) data to act while Coverniding Payment Estimate Estimate Item Adjustment (0027) data to act while Coverniding Payment Estimate Estimate Item Adjustment (0027) data to act while Coverniding Payment Estimate Item Adjustment (0027) data to act while Coverniding Payment Estimate Item Adjustment (0027) data to act while Coverniding Payment Estimate Item Adjustment (0027) data to act while Coverniding Payment Estimate Item Adjustment (0027) data to act while Coverniding Payment Estimate Item Adjustment (0027) data to act while Coverniding Payment Estimate Item Adjustment (0027) data to act while Coverniding Payment Estimate Item Adjustment Estimate Item						15		SYSTEM	(\$1,817.00)	
17 Fab 18						16		SYSTEM	\$9,085.00	Estimate Item Adjustment (0034) due to user hillt5 overridding Payment
Page						16		SYSTEM	(\$9,085.00)	
2024 18						17		SYSTEM	\$9,085.00	Estimate Item Adjustment (0030) due to user hillt5 overridding Payment
2024						17		SYSTEM	(\$9,085.00)	
100						18		SYSTEM	\$9,085.00	Estimate Item Adjustment (0023) due to user hillt5 overridding Payment
2024						18		SYSTEM	(\$9,085.00)	
2024 \$0.00						19		SYSTEM	\$9,085.00	Estimate Item Adjustment (0026) due to user hillt5 overridding Payment
Material - Total						19		SYSTEM	(\$9,085.00)	
1400 - Total					- Total				\$0.00	
MISC Construction 18				Material - To	tal				\$0.00	
Stockpile 2024		1400 -	Total						\$6,540.93	
-Total -Total		1410	MISC.			18		SYSTEM	(\$14,478.51)	Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile - Total						19		SYSTEM	(\$7,239.26)	Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Slockpile STM -Total S115,886.00 Payment Estimate Item Adjustment generated Stockpile Transaction S10ckpile STM -Total S115,886.00 S115					- Total				(\$21,717.77)	
Stockpile Total				Construction	1 Stockpile - 1	Γotal			(\$21,717.77)	
Construction Stockpile STMI - Total				Stockpile		16		SYSTEM	\$115,886.00	Payment Estimate Item Adjustment generated Stockpile Transaction
Material				SIMI	- Total				\$115,886.00	
2024 Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 34 on the current Payment Estimate.				Construction	1 Stockpile S	TMI - Tota			\$115,886.00	
19				Material		18		SYSTEM	\$19,580.00	Estimate Item Adjustment (0002) due to user hillt5 overridding Payment
2024 Estimate Item Adjustment (0002) due to user hillto overridding Payment Estimate Exception 36 on the current Payment Estimate. 19						18		SYSTEM	(\$19,580.00)	
Total Total So.00 Material - Total Syd,168.23 1420 MISC. Construction Stockpile 16 Feb 2, 2024 17 Feb 16, 2024 SYSTEM (\$2,085.36) Payment Estimate Item Adjustment generated Stockpile Transaction Total Construction Stockpile - Total Construction Stockpile - Total Construction Stockpile SYSTEM (\$5,129.68) Construction Stockpile - Total Construction Stockpile - Total SYSTEM (\$5,129.68) Construction Stockpile - Total Construction Stockpile - Total SSZ,133.98 Construction Stockpile STMI - Total SSZ,133.98 Material Material 16 Feb 2, SYSTEM \$3,342.80 This adjustment offsets the original system-generated Material Payment						19		SYSTEM	\$29,370.00	Estimate Item Adjustment (0002) due to user hillt5 overridding Payment
Material - Total 1410 - Total 1420 MISC. Construction Stockpile - Total Construction Stockpile - Total Construction Stockpile - Total Construction Stockpile - Total Construction Stockpile - Total Construction Stockpile - Total Construction Stockpile - Total Construction Stockpile - Total Construction Stockpile - Total Construction Stockpile - Total Construction Stockpile - Total Construction Stockpile - Total Construction Stockpile - Total Construction Stockpile - Total S52,133.98 Construction Stockpile STMI - Total S52,133.98 Construction Stockpile STMI - Total S52,133.98 Construction Stockpile STMI - Total S52,133.98 This adjustment offsets the original system-generated Material Payment						19		SYSTEM	(\$29,370.00)	
1410 - Total MISC. Construction Stockpile If Feb 2, 2024										
MISC. Construction Stockpile 16				Material - To	tal					
Stockpile 2024 (\$3,044.32) Payment Estimate Item Adjustment generated Stockpile Transaction - Total (\$5,129.68) Construction Stockpile - Total (\$5,129.68) Construction Stockpile - Total (\$5,129.68) Construction Stockpile STMI - Total \$52,133.98 Construction Stockpile STMI - Total \$52,133.98 Material 16 Feb 2, SYSTEM \$3,342.80 This adjustment offsets the original system-generated Material Payment									\$94,168.23	
- Total (\$5,129.68) Construction Stockpile - Total (\$5,129.68)		1420	MISC.			16		SYSTEM	(\$2,085.36)	Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile - Total Construction Stockpile STMI 9 Oct 16, SYSTEM \$52,133.98 Payment Estimate Item Adjustment generated Stockpile Transaction \$52,133.98 Payment Estimate Item Adjustment generated Stockpile Transaction \$52,133.98 Payment Estimate Item Adjustment generated Stockpile Transaction \$52,133.98 Construction Stockpile STMI - Total \$52,133.98 Material 16 Feb 2, SYSTEM \$3,342.80 This adjustment offsets the original system-generated Material Payment						17		SYSTEM	, , ,	Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile STMI 9 Oct 16, 2023 SYSTEM \$52,133.98 Payment Estimate Item Adjustment generated Stockpile Transaction \$552,133.98 Construction Stockpile STMI - Total \$52,133.98 Material 16 Feb 2, SYSTEM \$3,342.80 This adjustment offsets the original system-generated Material Payment										
Stockpile STMI - Total S52,133.98 Construction Stockpile STMI - Total \$52,133.98 Material 16 Feb 2, SYSTEM \$3,342.80 This adjustment offsets the original system-generated Material Payment				Construction	1 Stockpile - 1				(\$5,129.68)	
-Total \$52,133.98 Construction Stockpile STMI - Total \$52,133.98 Material 16 Feb 2, SYSTEM \$3,342.80 This adjustment offsets the original system-generated Material Payment				Stockpile		9		SYSTEM	\$52,133.98	Payment Estimate Item Adjustment generated Stockpile Transaction
Material 16 Feb 2, SYSTEM \$3,342.80 This adjustment offsets the original system-generated Material Payment				O I IVII	- Total				\$52,133.98	
				Construction	1 Stockpile S	TMI - Tota			\$52,133.98	
				Material		16	Feb 2.	SYSTEM	\$3,342,80	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
			1,750	Туре	rambor	Buto	Dy		
J6S3281	1420	MISC.	Material						Estimate Exception 24 on the current Payment Estimate.
					16	Feb 2, 2024	SYSTEM	(\$3,342.80)	
					17	Feb 16, 2024	SYSTEM	\$8,222.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$8,222.80)	
					18	Mar 1, 2024	SYSTEM	\$8,222.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					18	Mar 1, 2024	SYSTEM	(\$8,222.80)	
					19	Mar 18, 2024	SYSTEM	\$8,222.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hillt5 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$8,222.80)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1420 -	- Total						\$47,004.30	
	1430	MISC.	Construction Stockpile		19	Mar 18, 2024	SYSTEM	(\$2,177.24)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$2,177.24)	
				n Stockpile - 1	Total			(\$2,177.24)	
			Construction Stockpile STMI		12	Dec 4, 2023	SYSTEM	\$13,063.44	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$13,063.44	
			Construction	Stockpile S	MI - Total			\$13,063.44	
			Material		19	Mar 18, 2024	SYSTEM	\$2,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$2,460.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1430 -	- Total						\$10,886.20	
	1440	MISC.	Construction Stockpile		17	Feb 16, 2024	SYSTEM	(\$20,308.93)	Payment Estimate Item Adjustment generated Stockpile Transaction
					18	Mar 1, 2024	SYSTEM	(\$10,154.47)	Payment Estimate Item Adjustment generated Stockpile Transaction
					19	Mar 18, 2024	SYSTEM	(\$10,154.46)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$40,617.86)	
				n Stockpile - 1				(\$40,617.86)	
			Construction Stockpile STMI		13	Dec 18, 2023	SYSTEM	\$446,796.46	Payment Estimate Item Adjustment generated Stockpile Transaction
			O T WIII	- Total				\$446,796.46	
			Construction	n Stockpile S	MI - Total			\$446,796.46	
			Material		17	Feb 16, 2024	SYSTEM	\$24,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user hillt5 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$24,000.00)	
					18	Mar 1, 2024	SYSTEM	\$36,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					18	Mar 1, 2024	SYSTEM	(\$36,000.00)	



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks														
i iojoot	LING	Bosonption	Туре	Adjustment Type	Number	Date	Ву	Amount	romano														
J6S3281	1440	MISC.	Material	1 900					Estimate Exception 39 on the current Payment Estimate.														
					19	Mar 18, 2024	SYSTEM	(\$48,000.00)															
				- Total				\$0.00															
			Material - Tot	al				\$0.00															
	1440 -	Total						\$406,178.60															
	1450	MISC.	Construction Stockpile STMI		13	Dec 18, 2023	SYSTEM	\$546.96	Payment Estimate Item Adjustment generated Stockpile Transaction														
			STIVII	- Total				\$546.96															
			Construction	Stockpile S	ГМI - Tota	<u> </u>		\$546.96															
	1450 -	Total						\$546.96															
	1460	MISC.	Material		17	Feb 16, 2024	SYSTEM	\$1,690.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 37 on the current Payment Estimate.														
					17	Feb 16, 2024	SYSTEM	(\$1,690.00)															
					18	Mar 1, 2024	SYSTEM	\$1,690.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hillt5 overridding Payment Estimate Exception 37 on the current Payment Estimate.														
					18	Mar 1, 2024	SYSTEM	(\$1,690.00)															
							19	Mar 18, 2024	SYSTEM	\$1,690.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hillt5 overridding Payment Estimate Exception 40 on the current Payment Estimate.												
					19	Mar 18, 2024	SYSTEM	(\$1,690.00)															
				- Total				\$0.00															
			Material - Tot	al				\$0.00															
	1460 -	Total						\$0.00															
	1480	STRUCTURAL STEEL POSTS			2	Jun 16, 2023	SYSTEM	\$705.00	Payment Estimate Item Adjustment generated Stockpile Transaction														
				- Total				\$705.00															
	4400	Tatal	Construction	Stockpile S	MI - Tota			\$705.00															
		Total	Otmustis		0	lum 40	OVOTEM	\$705.00	Description to the Adjustment reported Ottoballia Transportion														
	1490	PIPE POSTS	Construction Stockpile STMI	Total	2	Jun 16, 2023	SYSTEM	\$9,905.60	Payment Estimate Item Adjustment generated Stockpile Transaction														
			0	- Total	FRU Takal			\$9,905.60															
	1490	Total	Construction	Stockpile S	rwii - Tota			\$9,905.60 \$9,905.60															
	1610	MISC. ITS	Material		7	Sep 18, 2023	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 9 on the current Payment Estimate.														
					7	Sep 18, 2023	SYSTEM	(\$1,200.00)	Example 10 of the outfort Engineer Estimate.														
														8	8	8			8	Oct 2, 2023	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					8	Oct 2, 2023		(\$1,200.00)															
					9 9 10	9	Oct 16, 2023	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hillt5 overridding Payment Estimate Exception 9 on the current Payment Estimate.													
						9	Oct 16, 2023	SYSTEM	(\$1,200.00)														
						10	Nov 2, 2023	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate.													
						Nov 2, 2023	SYSTEM	(\$1,200.00)															
					11	Nov 16, 2023	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment														



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks													
				Туре			-,															
J6S3281	1610	MISC. ITS	Material						Estimate Exception 9 on the current Payment Estimate.													
					11	Nov 16, 2023	SYSTEM	(\$2,400.00)														
					12	Dec 4, 2023	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 11 on the current Payment Estimate.													
					12	Dec 4, 2023	SYSTEM	(\$3,600.00)														
					13	Dec 18, 2023	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user weingl1 overridding Payment Estimate Exception 17 on the current Payment Estimate.													
					13	Dec 18, 2023	SYSTEM	(\$6,000.00)														
					14	Jan 2, 2024	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.													
					14	Jan 2, 2024	SYSTEM	(\$6,000.00)														
					15	Jan 17, 2024	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.													
					15	Jan 17, 2024	SYSTEM	(\$8,400.00)														
					16	Feb 2, 2024	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user hillt5 overridding Payment Estimate Exception 25 on the current Payment Estimate.													
					16	Feb 2, 2024	SYSTEM	(\$9,600.00)														
					17	Feb 16, 2024	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate.													
					17	Feb 16, 2024	SYSTEM	(\$9,600.00)														
					18	Mar 1, 2024	SYSTEM	\$15,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate.													
					18	Mar 1, 2024	SYSTEM	(\$15,600.00)														
					19	Mar 18, 2024	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user hillt5 overridding Payment Estimate Exception 41 on the current Payment Estimate.													
					19	Mar 18, 2024	SYSTEM	(\$18,000.00)														
				- Total				\$0.00														
			Material - To	tal				\$0.00														
	1610 -	· Total						\$0.00														
	1640	MISC. ITS	Material		18	Mar 1, 2024	SYSTEM	\$145.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 39 on the current Payment Estimate.													
					18	Mar 1, 2024	SYSTEM	(\$145.00)														
																	19	19	Mar 18, 2024	SYSTEM	\$145.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user hillt5 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$145.00)														
				- Total				\$0.00														
			Material - To	tal				\$0.00														
	1640 -	Total						\$0.00														
	1670	MISC. ITS	Material		18	Mar 1, 2024	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 40 on the current Payment Estimate.													
					18	Mar 1, 2024	SYSTEM	(\$600.00)														



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks							
	20	2 esc.,pas.,	Туре	Adjustment Type	Number	Date	Ву	, unount	, c.maile							
J6S3281	1670	MISC. ITS	Material		19	Mar 18, 2024	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 43 on the current Payment Estimate.							
					19	Mar 18, 2024	SYSTEM	(\$600.00)								
				- Total				\$0.00								
			Material - Tot	tal				\$0.00								
	1670 -	· Total						\$0.00								
	1680	MISC. ITS	Material		18	Mar 1, 2024	SYSTEM	\$976.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user hillt5 overridding Payment Estimate Exception 41 on the current Payment Estimate.							
					18	Mar 1, 2024	SYSTEM	(\$976.00)								
					19	Mar 18, 2024	SYSTEM	\$976.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user hillt5 overridding Payment Estimate Exception 44 on the current Payment Estimate.							
					19	Mar 18, 2024	SYSTEM	(\$976.00)								
				- Total				\$0.00								
			Material - Tot	tal				\$0.00								
	1680 -	· Total						\$0.00								
	1690	MISC. ITS	Material		18	Mar 1, 2024	SYSTEM	\$44.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hillt5 overridding Payment Estimate Exception 42 on the current Payment Estimate.							
					18	Mar 1, 2024	SYSTEM	(\$44.00)								
												19	Mar 18, 2024	SYSTEM	\$44.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hillt5 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$44.00)								
				- Total				\$0.00								
			Material - Tot	tal				\$0.00								
	1690 -	· Total						\$0.00								
	1700	MISC. ITS	Material		18	Mar 1, 2024	SYSTEM	\$90.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user hillt5 overridding Payment Estimate Exception 43 on the current Payment Estimate.							
					18	Mar 1, 2024	SYSTEM	(\$90.00)								
					19	Mar 18, 2024	SYSTEM	\$90.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user hillt5 overridding Payment Estimate Exception 46 on the current Payment Estimate.							
					19	Mar 18, 2024	SYSTEM	(\$90.00)								
				- Total				\$0.00								
			Material - Tot	tal				\$0.00								
	1700 -	- Total						\$0.00								
	1710	MISC. ITS	Material		18	Mar 1, 2024	SYSTEM	\$565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user hillt5 overridding Payment Estimate Exception 44 on the current Payment Estimate.							
					18	Mar 1, 2024	SYSTEM	(\$565.00)								
					19	Mar 18, 2024	SYSTEM	\$565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user hillt5 overridding Payment Estimate Exception 47 on the current Payment Estimate.							
					19	Mar 18, 2024	SYSTEM	(\$565.00)								
				- Total				\$0.00								
			Material - Tot	tal				\$0.00								
	17 <u>10</u> -	- Total						\$0.00								
	5002	MISC.	Material		8	Oct 2,	SYSTEM	\$36,000.00	This adjustment offsets the original system-generated Material Payment							
						,		, ,	,,,							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3281	5002	CONCRETE	Material			2023			Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Oct 2, 2023	SYSTEM	(\$36,000.00)	
					9	Oct 16, 2023	SYSTEM	\$45,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Oct 16, 2023	SYSTEM	(\$45,600.00)	
					11	Nov 16, 2023	SYSTEM	\$98,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					11	Nov 16, 2023	SYSTEM	(\$98,400.00)	
					12	Dec 4, 2023	SYSTEM	\$112,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					12	Dec 4, 2023	SYSTEM	(\$112,800.00)	
					13	Dec 18, 2023	SYSTEM	\$132,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user weingl1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					13	Dec 18, 2023	SYSTEM	(\$132,000.00)	
					14	Jan 2, 2024	SYSTEM	\$148,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					14	Jan 2, 2024	SYSTEM	(\$148,800.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	5002	5002 - Total						00.00	
	5002 -							\$0.00	
	5002 -	MISC.	Material		18	Mar 1, 2024	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		MISC.	Material		18		SYSTEM SYSTEM		Estimate Item Adjustment (0035) due to user hillt5 overridding Payment
		MISC.	Material			2024 Mar 1,		\$6,000.00	Estimate Item Adjustment (0035) due to user hillt5 overridding Payment
		MISC.	Material		18	2024 Mar 1, 2024 Mar 18,	SYSTEM	\$6,000.00 (\$6,000.00)	Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment
		MISC.		- Total	18	2024 Mar 1, 2024 Mar 18, 2024 Mar 18,	SYSTEM	\$6,000.00 (\$6,000.00) \$9,000.00	Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment
	5003	MISC. CONCRETE	Material Material - To		18	2024 Mar 1, 2024 Mar 18, 2024 Mar 18,	SYSTEM	\$6,000.00 (\$6,000.00) \$9,000.00 (\$9,000.00) \$0.00	Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		MISC. CONCRETE			18	2024 Mar 1, 2024 Mar 18, 2024 Mar 18,	SYSTEM	\$6,000.00 (\$6,000.00) \$9,000.00 (\$9,000.00)	Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	5003	MISC. CONCRETE			18	2024 Mar 1, 2024 Mar 18, 2024 Mar 18,	SYSTEM	\$6,000.00 (\$6,000.00) \$9,000.00 (\$9,000.00) \$0.00	Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	5003 -	MISC. CONCRETE Total MISC. PAVEMENT	Material - To		18 19	2024 Mar 1, 2024 Mar 18, 2024 Mar 18, 2024	SYSTEM SYSTEM SYSTEM	\$6,000.00 (\$6,000.00) \$9,000.00 (\$9,000.00) \$0.00 \$0.00	Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment
	5003 -	MISC. CONCRETE Total MISC. PAVEMENT	Material - To		18 19 19	2024 Mar 1, 2024 Mar 18, 2024 Mar 18, 2024 Nov 16, 2023	SYSTEM SYSTEM SYSTEM	\$6,000.00 (\$6,000.00) \$9,000.00 (\$9,000.00) \$0.00 \$0.00 \$22,880.00	Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment
	5003 -	MISC. CONCRETE Total MISC. PAVEMENT	Material - To		18 19 19	2024 Mar 1, 2024 Mar 18, 2024 Mar 18, 2024 Nov 16, 2023 Dec 4,	SYSTEM SYSTEM SYSTEM SYSTEM	\$6,000.00 (\$6,000.00) \$9,000.00 (\$9,000.00) \$0.00 \$0.00 \$22,880.00	Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment
	5003 -	MISC. CONCRETE Total MISC. PAVEMENT	Material - To		18 19 19 11 11 11	2024 Mar 1, 2024 Mar 18, 2024 Mar 18, 2024 Nov 16, 2023 Nov 16, 2023 Dec 4, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$6,000.00 (\$6,000.00) \$9,000.00 (\$9,000.00) \$0.00 \$0.00 \$22,880.00 (\$22,880.00)	Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment
	5003 -	MISC. CONCRETE Total MISC. PAVEMENT	Material - To		18 19 19 11 11 11 12	2024 Mar 1, 2024 Mar 18, 2024 Mar 18, 2024 Nov 16, 2023 Dec 4, 2023 Dec 4, 2023 Dec 18, 18, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$6,000.00 (\$6,000.00) \$9,000.00 (\$9,000.00) \$0.00 \$0.00 \$22,880.00 (\$22,880.00) \$40,430.00	Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate.
	5003 -	MISC. CONCRETE Total MISC. PAVEMENT	Material - To		18 19 19 11 11 12 12 13	2024 Mar 1, 2024 Mar 18, 2024 Mar 18, 2024 Nov 16, 2023 Dec 4, 2023 Dec 4, 2023 Dec 18, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$6,000.00 (\$6,000.00) \$9,000.00 (\$9,000.00) \$0.00 \$0.00 \$22,880.00 (\$22,880.00) \$40,430.00 (\$40,430.00)	Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate.





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3281	5004	MISC.	Material			2024			
		PAVEMENT REPAIR			15	Jan 17, 2024	SYSTEM	\$49,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					15	Jan 17, 2024	SYSTEM	(\$49,400.00)	
					16	Feb 2, 2024	SYSTEM	\$49,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					16	Feb 2, 2024	SYSTEM	(\$49,400.00)	
					17	Feb 16, 2024	SYSTEM	\$81,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					17	Feb 16, 2024	SYSTEM	(\$81,380.00)	
					18	Mar 1, 2024	SYSTEM	\$126,516.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					18	Mar 1, 2024	SYSTEM	(\$126,516.00)	
					19	Mar 18, 2024	SYSTEM	\$126,776.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					19	Mar 18, 2024	SYSTEM	(\$126,776.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	5004 -	Total						\$0.00	
J6S3281	- Total							\$1,200,368.01	
Overall -	Total							\$1,200,368.01	

MoDOT

Contract Adjustments for Contract - 230217-F07

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 40 of 40