

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 2, 2024

Progress Estimate 15	Number	Contract ID Prime Contrac	230317-H03 tor Apex Paving		/ Period Start / Period End	June 16, 2 June 30, 2	2024 N	Priginal Contract Amount let Change Order Amount current Contract Amount	\$8,566,286.74 \$37,281.00 \$8,603,567.74
Approval Date									By User
July 2, 2024			Generated and	Approved	(and should be	at the Project Office Level by	collie1		
July 2, 2024		F	Reviewed and Appro	oved (and	should be cons	sidered Draft	t) at the	Resident Engineer Level by	stottt1
July 3, 2024		e Controllers Office Level by	ramses1						
Original Completion	Current Cor	npletion Date	al Completion Date %			% of Current Contract Amount Complete			
October 1, 202	October 1, 2024 Octob							77.44%	
	Contract I	nformational Dat	es		Mi	lestones			
Date Description	Original C	Completion Date	Current Complet	ion Date	No Milestone	s Exist for C	Contract		
Acceptance Date									
Awarded Date	·		April 5, 2023						
Letting Date	March 17,	2023	March 17, 2023						
Notice to Proceed Date	May 8, 202	23	May 8, 2023						
Open to Traffic Date	, -,								

Contract Total Pay	For Estimate No. 15			
		This Estimate	Previous	To Date
230317-H03				
	Total Posted Items Pay	\$1,192,489.29	\$5,470,076.43	\$6,662,565.72
	Gross Item Adjustments	(\$32,065.95)	(\$75,317.18)	(\$107,383.13)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$5,394,759.25	\$6,555,182.59
Contract Total Pay	able This Estimate:	\$1,160,423.34		

April 17, 2024

Items Paid This Estimate Period

Work Began Date

April 17, 2024

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
J9S3326	0050	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$92.980	10,999.26	\$1,022,711.19		
	0060	4071005	TACK COAT	GAL	\$1.000	10,211	\$10,211.00		
	0250	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$5.450	2,541.8	\$13,852.81		
	0260	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	SQYD	\$7.860	730.9	\$5,744.87		
	0350	7034600	CURB BLOCKOUT	LF	\$143.000	244	\$34,892.00		
Project J98	3326 - Tot	tal					\$1,087,411.87		
J9S3403	0460	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$88.960	1,115.46	\$99,231.32		
	0470	4071005	TACK COAT	GAL	\$1.000	968	\$968.00		
	0570	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$7.610	160	\$1,217.60		
	0580	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	SQYD	\$9.830	372.38	\$3,660.50		
Project J9S3403 - Total									
Overall - Total									

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

	ine Item Adjustments Exist on Contract ine Item Adjustments This Estimate											
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount				
J9S3326	0050	BITUMINOUS PAVEMENT MIXTURE PG64-22	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL		(\$1.79)	(\$1,274.52)				

Revision 3/23/2023 Page 1 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 2, 2024

Progress Estimate Number
15

Contract ID 230317-H03 Pay Period Start June 16, 2024 Original Contract Amount S8,566,286.74
Prime Contractor Apex Paving Co. Pay Period End June 30, 2024 Original Contract Amount Current Contract Amount S8,566,286.74

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3326		(SURFACE LEVELING)						
	0050	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	2,185.26	(\$1.79)	(\$3,910.48)
	0050	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,978.7	(\$1.79)	(\$3,540.84)
	0050	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	2,514.47	(\$1.79)	(\$4,499.59)
	0050	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,757.36	(\$1.79)	(\$3,144.76)
	0050	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,851.24	(\$1.79)	(\$3,312.76)
	0050	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	Asphalt Cement Price Adjustment	10999.3 tons of SL24-8			(\$9,074.39)
	0290	MGS GUARDRAIL	Material			-850	\$32.61	(\$27,718.50)
	0290	MGS GUARDRAIL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user stottt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	850	\$32.61	\$27,718.50
	0350	CURB BLOCKOUT	Material			-244	\$143.00	(\$34,892.00)
	0350	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user stottt1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	244	\$143.00	\$34,892.00
	0360	CURB BLOCKOUT	Material			-274	\$130.00	(\$35,620.00)
	0360	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user stottt1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	274	\$130.00	\$35,620.00
	0370	CURB BLOCKOUT	Material			-265	\$133.00	(\$35,245.00)
	0370	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user stottt1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	265	\$133.00	\$35,245.00
	0380	CURB BLOCKOUT	Material			-315	\$115.00	(\$36,225.00)
	0380	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user stottt1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	315	\$115.00	\$36,225.00
	0390	CURB BLOCKOUT	Material			-280	\$127.00	(\$35,560.00)
	0390	CURB BLOCKOUT			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user stottt1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	280	\$127.00	\$35,560.00
J9S3403	0460	BITUMINOUS PAVEMENT MIXTURE PG64-22	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,115.46	(\$1.79)	(\$1,996.09)

Revision 3/23/2023 Page 2 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 2, 2024

Progress Estimate Number	Contract ID Prime Contractor	230317-H03		, -	Original Contract Amount Net Change Order Amount	\$8,566,286.74 \$37.281.00
15	Trime Contractor	Apex I avilig Co.	r ay r eriou Eriu	Julie 30, 2024	Current Contract Amount	\$8,603,567.74

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3403		(SURFACE LEVELING)						
	0460	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	-4.5	\$87.17	(\$392.27)
	0460	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	Asphalt Cement Price Adjustment	1115.46 tons of SL24-8			(\$920.25)
J9S3528	0680	TYPE A2 SHOULDER	Material			-707.5	\$94.00	(\$66,505.00)
	0680	TYPE A2 SHOULDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	707.5	\$94.00	\$66,505.00
	0720	CONCRETE PAVEMENT (9 IN. NON-REINF)	Material			-1,893.96	\$109.00	(\$206,441.64)
	0720	CONCRETE PAVEMENT (9 IN. NON-REINF)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1,893.96	\$109.00	\$206,441.64
	0790	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-30	\$14.00	(\$420.00)
	0790	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user stottt1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	30	\$14.00	\$420.00
	0800	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material			-120	\$18.00	(\$2,160.00)
	0800	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	120	\$18.00	\$2,160.00
	0940	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-28,259	\$0.14	(\$3,956.26)
	0940	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user stottt1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	28,259	\$0.14	\$3,956.26
	0950	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-17,307	\$0.20	(\$3,461.40)
	0950	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user stottt1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	17,307	\$0.20	\$3,461.40
JSE0084	1020	MISC.	Material			-4,037.4	\$54.77	(\$221,128.40)
	1020	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	4,037.4	\$54.77	\$221,128.40

Revision 3/23/2023 Page 3 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 2, 2024

Progi	15		Contract ID 230317-H03 Prime Contractor Apex Paving Co		. Pay Period End June 30, 2024 Net			l Contract Ar ange Order A Contract An	mount \$	\$8,566,286.74 \$37,281.00 \$8,603,567.74	
Project Number	Line No.	Item Descrip	tion	Adjustmer Type	Other Item Adjustment Type	Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
JSE0084						Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
Total											(\$32,065.95)

Revision 3/23/2023 Page 4 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Information					
Project Number	Federal Proj. Number	Project Description	Route	County		,	Location of Work				
J9S3326	FAS S703(28)	Resurface and bridge rehabilitation	162	NEW MADRID	from Route 25 near Cl	larkton to Route 61 near Po	rtageville				
J9S3403	FAS S703(19)	Resurface	J	DUNKLIN	from Bus. 25 in Malder	om Bus. 25 in Malden to Route 53					
J9S3528	FAS S704(27)	Resurface	84	PEMISCOT	from Route 412 to I-55	5					
JSE0084	FAS- S704(076)	Resurface	С	PEMISCOT	from Route 412 to Rou	from Route 412 to Route 164					
Γotals by .	Job Number	s									
J9S3326		Item Pay Item Adjustmer		tem Pay	This Estimate \$1,087,411.87 (\$28,757.34) \$1,058,654.53	Previous \$875,847.34 \$0.00 \$875,847.34	To Date \$1,963,259.21 (\$28,757.34) \$1,934,501.87				
	Incentive Disincentive Liquidated Damages Other Contract Adjustments				\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
J9S3403		Item Pay Item Adjustmer		tem Pay	This Estimate \$105,077.42 (\$3,308.61) \$101,768.81	Previous \$1,292,931.85 (\$36,385.01) \$1,256,546.84	To Date \$1,398,009.27 (\$39,693.62) \$1,358,315.65				
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
J9S3528		Item Pay Item Adjustmer		tem Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$1,316,028.39 (\$23,862.30) \$1,292,166.09	To Date \$1,316,028.39 (\$23,862.30) \$1,292,166.09				
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
JSE0084		Item Pay Item Adjustmer		tem Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$1,985,268.85 (\$15,069.87) \$1,970,198.98	To Date \$1,985,268.85 (\$15,069.87) \$1,970,198.98				
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				

Revision 3/23/2023 Page 5 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JSE0084, Item 3049910, Project Item Line Number 1020, Material Set 304991096, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSE0084, Item 3049910, Project Item Line Number 1020, Material Set 304991096, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Materials sample needs to be completed.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 4010150, Project Item Line Number 0680, Material Set 401015096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 4010150, Project Item Line Number 0680, Material Set 401015096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Materials sample needs to be completed.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 5021109, Project Item Line Number 0720, Material Set 502110996, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 5021109, Project Item Line Number 0720, Material Set 502110996, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Materials sample needs to be completed.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 5021109, Project Item Line Number 0720, Material Set 502110996, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 5021109, Project Item Line Number 0720, Material Set 502110996, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Materials sample needs to be completed.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 5021109, Project Item Line Number 0720, Material Set 502110996, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 5021109, Project Item Line Number 0720, Material Set 502110996, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Materials sample needs to be completed.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 5021109, Project Item Line Number 0720, Material Set 502110996, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 5021109, Project Item Line Number 0720, Material Set 502110996, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Materials sample needs to be completed.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3326, Item 6061060, Project Item Line Number 0290, Material Set 606106096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3326, Item 6061060, Project Item Line Number 0290, Material Set 606106096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	Materials sample needs to be completed.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131015, Project Item Line Number 0790, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131015, Project Item Line Number 0790, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Materials sample needs to be completed.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131017, Project Item Line Number 0800, Material Set 613101796, Material 1057JMDBEC6.11 - Dowel Bar Epoxy Ctd Gr60 1 1/4 @, Acceptance Action Generic ReinforcingMisc is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131017, Project Item Line Number 0800, Material Set 613101796, Material 1057JMDBEC6.11 - Dowel Bar Epoxy Ctd Gr60 1 1/4 @, Acceptance Action Generic ReinforcingMisc is insufficient.	Materials sample needs to be completed.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131018, Project Item Line Number 0810, Material Set 613101896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131018, Project Item Line Number 0810, Material Set 613101896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Materials sample needs to be completed.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131018, Project Item Line Number 0810, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131018, Project Item Line Number 0810, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Materials sample needs to be completed.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6206000C, Project Item Line Number 0940, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6206000C, Project Item Line Number 0940, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne	Materials sample needs to be completed.	collie1	Overridden

Revision 3/23/2023 Page 6 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
White, Acceptance Action Generic 1048PMTRWBWH is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6206001C, Project Item Line Number 0950, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6206001C, Project Item Line Number 0950, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Materials sample needs to be completed.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3326, Item 7034600, Project Item Line Number 0350, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3326, Item 7034600, Project Item Line Number 0350, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Materials sample needs to be completed.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3326, Item 7034600, Project Item Line Number 0360, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3326, Item 7034600, Project Item Line Number 0360, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Materials sample needs to be completed.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3326, Item 7034600, Project Item Line Number 0370, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3326, Item 7034600, Project Item Line Number 0370, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Materials sample needs to be completed.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3326, Item 7034600, Project Item Line Number 0380, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3326, Item 7034600, Project Item Line Number 0390, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	materials inspection to be entered	collie1	Overridden
Estimate Exception Type: Item Overrun: Contract 230317-H03, Contract Project J9S3528, Project Item Line Number 0710, Contract Line Item Number 0710, Item 4071005, Minor Item.	change order is needed	collie1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230317-H03, Contract Project J9S3528, Project Item Line Number 0730, Contract Line Item Number 0730, Item 6089902, Minor Item.	change order	stottt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230317-H03, Contract Project J9S3403, Project Item Line Number 0460, Contract Line Item Number 0460, Item 4020520, Minor Item.	change order	stottt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230317-H03, Contract Project J9S3528, Project Item Line Number 0650, Contract Line Item Number 0650, Item 3040506, Minor Item.	change order	stottt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230317-H03, Contract Project J9S3528, Project Item Line Number 0970, Contract Line Item Number 0970, Item 6221001, Minor Item.	change order	stottt1	Acknowledged

Revision 3/23/2023 Page 7 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

osted Qua	antities	and value	es are b	ased on R	eport Generated date and can differ from the posted amo	unt at the t	ime the i	stimate wa	s Gener	ated.		
ract I	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
103 J	983326	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.90	\$27,328.20	\$24,595.38
		0001	0020	2153000	SHAPING SLOPES, CLASS III	25.00	0.00	25.00	100F	20.80	\$1,429.44	\$29,732.35
		0001	0030	3049910	MISC.PERMANENT AGGREGATE EDGE TREATEMENT	2,853.50	0.00	2,853.50	TONS	0.00	\$50.77	\$0.00
		0001	0040	3105002	GRAVEL (A) OR CRUSHED STONE (B)	110.00	0.00	110.00	TONS	0.00	\$50.79	\$0.00
		0001	0050	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	15,873.90	0.00	15,873.90	TONS	10,999.26	\$92.98	\$1,022,711.19
		0001	0060	4071005	LEVELING) TACK COAT	19,559.00	0.00	19,559.00	GAL	10,211.00	\$1.00	\$10,211.00
		0001	0070	4091048	EMULSIFIED ASPHALT, SEAL COAT	210.00	0.00	210.00	GAL	0.00	\$14.28	\$0.00
		0001	0080	4094011	SEAL COAT AGGREGATE, GRADE B1	564.00	0.00	564.00	SQYD	0.00	\$7.00	\$0.00
		0001	0090	6083003	3 IN. CONCRETE MEDIAN STRIP	86.00	0.00	86.00	SQYD	86.00	\$110.00	\$9,460.00
		0001	0100	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	4.00	0.00	4.00	EA	4.00	\$4,800.00	\$19,200.00
		0001	0110	6122030	IMPACT ATTENUATOR (RELOCATION)	16.00	0.00	16.00	EA	16.00	\$2,000.00	\$32,000.00
		0001	0120	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00		EA	0.00		\$0.00
		0001	0130	6161005	CONSTRUCTION SIGNS	1,633.00	0.00	1,633.00	SQFT	1,138.00	\$6.00	\$6,828.00
		0001	0140	6161025	CHANNELIZER (TRIM LINE)	120.00	0.00	120.00	EA	120.00	\$24.00	\$2,880.00
		0001	0150	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	2.00	0.00	2.00	EA	0.00	\$4,500.00	\$0.00
		0001	0160	6181000	RETAINED MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$243,470.98	\$121,735.49
		0001	0170	6200013	COLD APPLIED TAPE PAVEMENT MARKING, 24 IN. WHITE	44.00	14.00 0.00		LF	0.00	\$25.00	\$0.00
		0001	0180	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R	2.00	0.00	2.00	EA	0.00	\$1,500.00	\$0.00
		0001	0190	6205301B	CROSSING MARKER TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	11,600.00	0.00	11,600.00	LF	6,534.00	\$1.50	\$9,801.00
		0001	0200	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	10,000.00	0.00	10,000.00	LF	8,023.00	\$1.50	\$12,034.50
		0001	0210	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	120.00	0.00	120.00	LF	96.00	\$9.00	\$864.00
		0001	0220	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	199,134.00	0.00	199,134.00	LF	0.00	\$0.13	\$0.00
		0001 0230	0230	6206001C	PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	50,880.00	0.00	50,880.00	LF	2,475.00	\$0.13	\$321.75
		0001	0240	6207001	PAVEMENT MARKING REMOVAL	29,540.00	0.00	29,540.00	LF	12,541.00	\$0.50	\$6,270.50
		0001	0250	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	8,590.00	0.00	8,590.00	SQYD	2,541.80	\$5.45	\$13,852.81
		0001	0260	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	8,957.00	0.00	8,957.00	SQYD	730.90	\$7.86	\$5,744.87
		0001	0270	7250424	24 IN. PIPE GROUP C	27.00	0.00	27.00	LF	0.00	\$125.00	\$0.00
		0001	0280	7250436	36 IN. PIPE GROUP C	48.00	0.00	48.00	LF	0.00	\$160.00	\$0.00
		0010	0290	6061060	MGS GUARDRAIL	1,100.00	0.00	1,100.00	LF	850.00	\$32.61	\$27,718.50
		0010	0300	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	33.00	0.00	33.00	EA	27.00	\$4,039.56	\$109,068.12
		0010	0310	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	1.00	\$1,456.42	\$1,456.42
		0010	0320	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	31.00	0.00	31.00	EA	26.00	\$3,659.09	\$95,136.34
		0010	0330	6063020	TYPE C CRASHWORTHY END TERMINAL (MASH)	7.00	0.00	7.00	EA	7.00	\$32,013.57	\$224,094.99
		0030	0340	9029400	TEMPORARY TRAFFIC SIGNALS	4.00	0.00	4.00	LS	4.00	\$0.00	\$0.00
		0070	0350	7034600	CURB BLOCKOUT	244.00	0.00	244.00	LF	244.00	\$143.00	\$34,892.00
		0071	0360	7034600	CURB BLOCKOUT	274.00	0.00	274.00	LF	274.00	\$130.00	\$35,620.00
		0072	0370	7034600	CURB BLOCKOUT	265.00	0.00	265.00	LF	265.00	\$133.00	\$35,245.00
		0073	0380	7034600	CURB BLOCKOUT	315.00	0.00	315.00	LF	315.00	\$115.00	\$36,225.00
		0074	0390	7034600	CURB BLOCKOUT	280.00	0.00	280.00	LF	280.00	\$127.00	\$35,560.00
P	roject J9	S3326 - To	otal Value	Posted to D	ate as of Report Generated Date							\$1,963,259.22
J	983403	0001	0400	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$5,056.58	\$0.00
		0001	0410	2129903	MISC.SHOULDER GRADING	108,504.00	0.00	108,504.00	LF	0.00	\$0.97	\$0.00
		0001	0420	2153000	SHAPING SLOPES, CLASS III	3.00	0.00	3.00	100F	0.00	\$1,252.05	\$0.00

Page 8 of 29 Revision 3/23/2023



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

3403 0001 0001 0001 0001 0001 0001 0001	0440 0450 0460 0470 0480 0490 0500 0510 0520 0530 0540 0550 0560 0570 0580 0690 0610 0620 0630	6206108A 6221001 6224010 6261000A 6061060 6061069 6063014	GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT EMULSIFIED ASPHALT, SEAL COAT SEAL COAT AGGREGATE, GRADE B1 TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) MODIFIED COLDMILLING (DEPTH TRANSITIONS) BITUMINOUS SHOULDER RUMBLE STRIP MGS GUARDRAIL MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) TYPE A CRASHWORTHY END TERMINAL (MASH)	22.00 5,305.00 12,264.80 14,889.00 255.00 671.00 2.00 1,765.00 100.00 120,422.00 920.00 4,783.00 4,783.00 1,147.30 150.00 4.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	22.00 5,305.00 12,264.80 14,889.00 255.00 671.00 2.00 1,765.00 100.00 1.00 28,692.00 920.00 1,053.00 4,783.00 1,147.30	TONS TONS GAL GAL SQYD EA SQFT EA LS LF LF SQYD SQYD SQYD	Qty 0.00 2,887.12 12,269.30 14,037.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	\$52.58 \$94.63 \$88.96 \$1.00 \$12.99 \$7.00 \$0.00 \$6.00 \$124,218.63 \$0.13 \$0.14 \$1.00 \$7.61 \$9.83 \$17.50	\$0.0 \$273,208.1 \$1,091,476.9 \$14,037.0 \$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$
0001 0001 0001 0001 0001 0001 0001 000	0460 0470 0480 0490 0500 0510 0520 0530 0540 0550 0560 0570 0580 0590 0600 0610 0620	4020520 4071005 4091048 4094011 6123000A 6161005 6161025 6181000 6206001C 6206001C 62261001 6224010 6224010 6261000A 6061060 6061069 6063014	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT EMULSIFIED ASPHALT, SEAL COAT SEAL COAT AGGREGATE, GRADE B1 TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS B IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) MODIFIED COLDMILLING (DEPTH TRANSITIONS) BITUMINOUS SHOULDER RUMBLE STRIP MGS GUARDRAIL MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	12,264.80 14,889.00 255.00 671.00 2.00 1,765.00 100.00 120,422.00 28,692.00 1,053.00 4,783.00 1,147.30 150.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	12,264.80 14,889.00 255.00 671.00 2.00 1,765.00 100.00 120,422.00 28,692.00 920.00 1,053.00 4,783.00 1,147.30	TONS GAL GAL SQYD EA SQFT EA LS LF LF SQYD SQYD	12,269.30 14,037.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 1,714.34	\$88.96 \$1.00 \$12.99 \$7.00 \$0.00 \$6.00 \$124,218.63 \$0.13 \$0.14 \$1.00 \$7.61	\$1,091,476.9 \$14,037.0 \$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$
0001 0001 0001 0001 0001 0001 0001 000	0470 0480 0490 0500 0510 0520 0530 0540 0550 0560 0570 0580 0690 0610 0620	4071005 4091048 4094011 6123000A 6161005 6161025 6181000 6206000C 6206001C 6206108A 6221001 6224010 6261000A 6061060 6061069 6063014	LEVELING) TACK COAT EMULSIFIED ASPHALT, SEAL COAT SEAL COAT AGGREGATE, GRADE B1 TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) MODIFIED COLDMILLING (DEPTH TRANSITIONS) BITUMINOUS SHOULDER RUMBLE STRIP MGS GUARDRAIL MGS BRIDGE APPROACH TRANSITION SECTION (REGULARINO CURB)	14,889.00 255.00 671.00 2.00 1,765.00 100.00 120,422.00 920.00 1,053.00 4,783.00 1,147.30 150.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	14,889.00 255.00 671.00 2.00 1,765.00 100.00 1.00 120,422.00 920.00 1,053.00 4,783.00 1,147.30	GAL GAL SQYD EA SQFT EA LS LF LF SQYD SQYD	14,037.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 1,714.34	\$1.00 \$12.99 \$7.00 \$0.00 \$6.00 \$22.00 \$124,218.63 \$0.13 \$0.14 \$1.00 \$7.61	\$14,037.0 \$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$
0001 0001 0001 0001 0001 0001 0001 000	0480 0490 0500 0510 0520 0530 0540 0550 0560 0570 0580 0590 0610 0620	4091048 4094011 6123000A 6161005 6161025 6181000 6206000C 6206001C 6206108A 6221001 6224010 6261000A 6061060 6061069 6063014	EMULSIFIED ASPHALT, SEAL COAT SEAL COAT AGGREGATE, GRADE B1 TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) MODIFIED COLDMILLING (DEPTH TRANSITIONS) BITUMINOUS SHOULDER RUMBLE STRIP MGS GUARDRAIL MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	255.00 671.00 2.00 1,765.00 100.00 120,422.00 28,692.00 920.00 1,053.00 4,783.00 1,147.30	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	255.00 671.00 2.00 1,765.00 100.00 1.00 120,422.00 28,692.00 920.00 1,053.00 4,783.00	GAL SQYD EA SQFT EA LS LF LF SQYD SQYD	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	\$12.99 \$7.00 \$0.00 \$6.00 \$124,218.63 \$0.13 \$0.14 \$1.00 \$7.61	\$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$16.851.9
0001 0001 0001 0001 0001 0001 0001 000	0490 0500 0510 0520 0530 0540 0550 0560 0570 0580 0590 0600 0610 0620	4094011 6123000A 6161005 6161025 6181000 6206000C 6206001C 6206108A 6221001 6224010 6261000A 6061060 6063014	SEAL COAT AGGREGATE, GRADE B1 TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) MODIFIED COLDMILLING (DEPTH TRANSITIONS) BITUMINOUS SHOULDER RUMBLE STRIP MGS GUARDRAIL MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	671.00 2.00 1,765.00 100.00 120,422.00 28,692.00 920.00 1,053.00 4,783.00 1,147.30	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	671.00 2.00 1,765.00 100.00 1.00 120,422.00 28,692.00 920.00 1,053.00 4,783.00	SQYD EA SQFT EA LS LF LF SQYD SQYD	0.00 0.00 0.00 0.00 0.00 0.00 0.00 320.00	\$7.00 \$0.00 \$6.00 \$22.00 \$124,218.63 \$0.13 \$0.14 \$1.00 \$7.61	\$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$2.435.2
0001 0001 0001 0001 0001 0001 0001 000	0500 0510 0520 0530 0540 0550 0560 0570 0580 0590 0600 0610 0620	6123000A 6161005 6161025 6181000 6206000C 6206001C 6206108A 6221001 6224010 6261000A 6061060 6061069 6063014	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) MODIFIED COLDMILLING (DEPTH TRANSITIONS) BITUMINOUS SHOULDER RUMBLE STRIP MGS GUARDRAIL MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	2.00 1,765.00 100.00 1.00 120,422.00 28,692.00 920.00 1,053.00 4,783.00 1,147.30 150.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2.00 1,765.00 100.00 1.00 120,422.00 28,692.00 920.00 1,053.00 4,783.00 1,147.30	EA SQFT EA LS LF LF SQYD SQYD	0.00 0.00 0.00 0.00 0.00 0.00 0.00 320.00	\$0.00 \$6.00 \$22.00 \$124,218.63 \$0.13 \$0.14 \$1.00 \$7.61	\$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$16,851.9
0001 0001 0001 0001 0001 0001 0001 000	0510 0520 0530 0540 0550 0560 0570 0580 0590 0600 0610 0620	6161005 6161025 6181000 6206000C 6206001C 6206108A 6221001 6224010 6261000A 6061060 6061069 6063014	CONSTRUCTION SIGNS CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) MODIFIED COLDMILLING (DEPTH TRANSITIONS) BITUMINOUS SHOULDER RUMBLE STRIP MGS GUARDRAIL MGS BRIDGE APPROACH TRANSITION SECTION (REGULARINO CURB)	1,765.00 100.00 1.00 120,422.00 28,692.00 920.00 1,053.00 4,783.00 1,147.30 150.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00	1,765.00 100.00 1.00 120,422.00 28,692.00 920.00 1,053.00 4,783.00 1,147.30	SQFT EA LS LF LF SQYD SQYD	0.00 0.00 0.00 0.00 0.00 0.00 320.00	\$6.00 \$22.00 \$124,218.63 \$0.13 \$0.14 \$1.00 \$7.61	\$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$16,851.0
0001 0001 0001 0001 0001 0001 0001 000	0520 0530 0540 0550 0560 0570 0580 0590 0600 0610 0620	6161025 6181000 6206000C 6206001C 6206108A 6221001 6224010 6261000A 6061060 6061069 6063014	CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) MODIFIED COLDMILLING (DEPTH TRANSITIONS) BITUMINOUS SHOULDER RUMBLE STRIP MGS GUARDRAIL MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	100.00 1.00 120,422.00 28,692.00 920.00 1,053.00 4,783.00 1,147.30	0.00 0.00 0.00 0.00 0.00 0.00 0.00	100.00 1.00 120,422.00 28,692.00 920.00 1,053.00 4,783.00	EA LS LF LF SQYD SQYD	0.00 0.00 0.00 0.00 0.00 320.00	\$22.00 \$124,218.63 \$0.13 \$0.14 \$1.00 \$7.61 \$9.83	\$0.0 \$0.0 \$0.0 \$0.0 \$2,435.1
0001 0001 0001 0001 0001 0001 0001 0010 0010 0010 ect J9\$3403 - T	0530 0540 0550 0560 0570 0580 0590 0600 0610	6181000 6206000C 6206001C 6206108A 6221001 6224010 6261000A 6061060 6061069 6063014	MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) MODIFIED COLDMILLING (DEPTH TRANSITIONS) BITUMINOUS SHOULDER RUMBLE STRIP MGS GUARDRAIL MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	1.00 120,422.00 28,692.00 920.00 1,053.00 4,783.00 1,147.30	0.00 0.00 0.00 0.00 0.00 0.00	1.00 120,422.00 28,692.00 920.00 1,053.00 4,783.00 1,147.30	LS LF LF SQYD SQYD	0.00 0.00 0.00 0.00 320.00	\$124,218.63 \$0.13 \$0.14 \$1.00 \$7.61 \$9.83	\$0.0 \$0.0 \$0.0 \$0.0 \$2,435.1
0001 0001 0001 0001 0001 0001 0010 0010 0010 ect J9\$3403 - T	0540 0550 0560 0570 0580 0590 0600 0610 0620	6206000C 6206001C 6206108A 6221001 6224010 6261000A 6061060 6061069 6063014	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) MODIFIED COLDMILLING (DEPTH TRANSITIONS) BITUMINOUS SHOULDER RUMBLE STRIP MGS GUARDRAIL MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	120,422.00 28,692.00 920.00 1,053.00 4,783.00 1,147.30	0.00 0.00 0.00 0.00 0.00	120,422.00 28,692.00 920.00 1,053.00 4,783.00 1,147.30	LF LF SQYD	0.00 0.00 0.00 320.00 1,714.34	\$0.13 \$0.14 \$1.00 \$7.61 \$9.83	\$0.0 \$0.0 \$0.1 \$2,435.1
0001 0001 0001 0001 0001 0010 0010 001	0550 0560 0570 0580 0590 0600 0610 0620	6206001C 6206108A 6221001 6224010 6261000A 6061060 6061069 6063014	PAINT, TYPE P BEADS 4 IN, YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 8 IN, WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) MODIFIED COLDMILLING (DEPTH TRANSITIONS) BITUMINOUS SHOULDER RUMBLE STRIP MGS GUARDRAIL MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	28,692.00 920.00 1,053.00 4,783.00 1,147.30	0.00 0.00 0.00 0.00	28,692.00 920.00 1,053.00 4,783.00 1,147.30	LF LF SQYD SQYD	0.00 0.00 320.00 1,714.34	\$0.14 \$1.00 \$7.61 \$9.83	\$0.0 \$0.0 \$2,435.1
0001 0001 0001 0001 0010 0010 0010 ect J9\$3403 - T	0560 0570 0580 0590 0600 0610 0620	6206108A 6221001 6224010 6261000A 6061060 6061069 6063014	MARKING PAINT, TYPE P BEADS 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) MODIFIED COLDMILLING (DEPTH TRANSITIONS) BITUMINOUS SHOULDER RUMBLE STRIP MGS GUARDRAIL MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	920.00 1,053.00 4,783.00 1,147.30	0.00 0.00 0.00	920.00 1,053.00 4,783.00 1,147.30	LF SQYD SQYD	0.00 320.00 1,714.34	\$1.00 \$7.61 \$9.83	\$0.6 \$2,435.2 \$16,851.9
0001 0001 0001 0010 0010 0010 ect J9\$3403 - T	0570 0580 0590 0600 0610 0620	6221001 6224010 6261000A 6061060 6061069 6063014	PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) MODIFIED COLDMILLING (DEPTH TRANSITIONS) BITUMINOUS SHOULDER RUMBLE STRIP MGS GUARDRAIL MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	1,053.00 4,783.00 1,147.30 150.00	0.00	1,053.00 4,783.00 1,147.30	SQYD	320.00 1,714.34	\$7.61 \$9.83	\$2,435 \$16,851.
0001 0001 0010 0010 0010 ect J9S3403 - T	0580 0590 0600 0610 0620	6224010 6261000A 6061060 6061069 6063014	SURFACING (3 IN. THICK OR LESS) MODIFIED COLDMILLING (DEPTH TRANSITIONS) BITUMINOUS SHOULDER RUMBLE STRIP MGS GUARDRAIL MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4,783.00 1,147.30 150.00	0.00	4,783.00 1,147.30	SQYD	1,714.34	\$9.83	\$16,851.9
0001 0010 0010 0010 ect J9S3403 - T	0590 0600 0610 0620	6261000A 6061060 6061069 6063014	BITUMINOUS SHOULDER RUMBLE STRIP MGS GUARDRAIL MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	1,147.30 150.00	0.00	1,147.30				
0010 0010 0010 ect J9S3403 - T	0600 0610 0620 otal Value	6061060 6061069 6063014	MGS GUARDRAIL MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	150.00			STA	0.00	\$17.50	\$0.0
0010 0010 ect J9S3403 - T	0610 0620 otal Value	6061069 6063014	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)		0.00					
0010 ect J9S3403 - T	0620	6063014	(REGULAR/NO CURB)	4.00		150.00	LF	0.00	\$40.47	\$0.0
ect J9S3403 - T	otal Value		TYPE A CRASHWORTHY END TERMINAL (MASH)		0.00	4.00	EA	0.00	\$4,146.39	\$0.0
		Posted to D		4.00	0.00	4.00	EA	0.00	\$3,430.71	\$0.0
3528 0004	UESU		ate as of Report Generated Date							\$1,398,009.
3320 0001		2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$12,000.00	\$12,000.0
0001	0640	2129903	MISC.SHOULDER GRADING	6,723.00	0.00	6,723.00	LF	625.00	\$3.90	\$2,437.
0001	0650	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,750.00	0.00	1,750.00	SQYD	2,057.20	\$11.00	\$22,629.
0001	0660	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	380.50	0.00	380.50	TONS	380.50	\$69.32	\$26,376.
0001	0670	3105002	GRAVEL (A) OR CRUSHED STONE (B)	13.00	0.00	13.00	TONS	0.00	\$69.34	\$0.
0001	0680	4010150	TYPE A2 SHOULDER	556.00	151.50	707.50	SQYD	707.50	\$94.00	\$66,505.
0001	0690	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	5,603.70	0.00	5,603.70	TONS	5,573.69	\$110.45	\$615,614.
0001	0700	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	673.00	0.00	673.00	TONS	468.62	\$122.26	\$57,293.
0001	0710	4071005	TACK COAT	4,293.00	0.00	4,293.00	GAL	5,324.00	\$2.55	\$13,576.
0001	0720	5021109	CONCRETE PAVEMENT (9 IN. NON-REINF)	1,750.00	160.00	1,910.00	SQYD	1,893.96	\$109.00	\$206,441.
0001	0730	6089902	MISC.ADA CURB RAMP	8.00	4.00	12.00	EA	16.00	\$1,400.00	\$22,400.
0001	0740	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$0.00	\$0.
0001	0750	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	250.00	0.00	250.00	SQYD	250.00	\$331.58	\$82,895.
0001	0760	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	250.00	0.00	250.00	SQYD	250.00	\$15.00	\$3,750.
0001	0770	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	250.00	0.00	250.00	SQYD	250.00	\$14.00	\$3,500.
0001	0780	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	461.00	0.00	461.00	LF	461.00	\$12.00	\$5,532.
0001	0790	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION)	30.00	0.00	30.00	EA	30.00	\$14.00	\$420.
0001	0800	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH	120.00	0.00	120.00	EA	120.00	\$18.00	\$2,160.
0001	0810	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR	60.00	0.00	60.00	EA	60.00	\$15.00	\$900.
0001	0820	6161005	CONSTRUCTION SIGNS	1,368.00	0.00	1,368.00	SQFT	591.00	\$6.50	\$3,841.
0004	0830	6161025	CHANNELIZER (TRIM LINE)	150.00	0.00	150.00	EA	150.00	\$24.00	\$3,600.
0001	0840	6161030	TYPE III MOVEABLE BARRICADE	7.00	0.00	7.00	EA	7.00	\$145.00	\$1,015.0
0001		6161098A	CHANCEARI E MESSACE SIGNI WITHOUT COMMUNICATION	3.00	0.00	3.00	EA	3.00	\$3,000.00	\$9,000.0
	0001 0001 0001 0001 0001 0001 0001 000	0001 0710 0001 0720 0001 0730 0001 0740 0001 0750 0001 0760 0001 0770 0001 0780 0001 0790 0001 0800 0001 0810 0001 0820 0001 0830	0001 0710 4071005 0001 0720 5021109 0001 0730 6089902 0001 0740 6123000A 0001 0750 6131010 0001 0760 6131012 0001 0770 6131013 0001 0780 6131014 0001 0790 6131015 0001 0800 6131017 0001 0810 6131018 0001 0820 6161005 0001 0830 6161025 0001 0840 6161030	0001 0710 4071005 TACK COAT 0001 0720 5021109 CONCRETE PAVEMENT (9 IN. NON-REINF) 0001 0730 6089902 MISC.ADA CURB RAMP 0001 0740 6123000A TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) 0001 0750 6131010 FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR 0001 0760 6131012 SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) 0001 0770 6131013 TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) 0001 0780 6131014 FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) 0001 0790 6131015 DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR 0001 0800 6131017 DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) 0001 0810 6131018 TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) 0001 0820 6161005 CONSTRUCTION SIGNS 0001 0830 6161025 CHANNELIZER (TRIM LINE)	0001 0710 4071005 TACK COAT 4,293.00 0001 0720 5021109 CONCRETE PAVEMENT (9 IN. NON-REINF) 1,750.00 0001 0730 6089902 MISC.ADA CURB RAMP 8.00 0001 0740 6123000A TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) 2.00 0001 0750 6131010 FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR 250.00 0001 0760 6131012 SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) 250.00 0001 0770 6131013 TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) 250.00 0001 0780 6131014 FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) 461.00 0001 0790 6131015 DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FOR FULL DEPTH PAVEMENT REPAIR 30.00 0001 0800 6131017 DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR 120.00 0001 0810 6131018 TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) 60.00	0001 0710 4071005 TACK COAT 4,293.00 0.00 0001 0720 5021109 CONCRETE PAVEMENT (9 IN. NON-REINF) 1,750.00 160.00 0001 0730 6089902 MISC.ADA CURB RAMP 8.00 4.00 0001 0740 6123000A TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) 2.00 0.00 0001 0750 6131010 FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR 250.00 0.00 0001 0760 6131012 SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) 250.00 0.00 0001 0770 6131013 TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) 250.00 0.00 0001 0780 6131014 FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INSTALLATION) 461.00 0.00 0001 0790 6131015 DOWEL BAR (FURNISHING AND INSTALLATION) 30.00 0.00 0001 0800 6131017 DOWEL BAR (FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR 120.00 0.00 0001 0810 6131018 <td>0001 0710 4071005 TACK COAT 4,293.00 0.00 4,293.00 0001 0720 5021109 CONCRETE PAVEMENT (9 IN. NON-REINF) 1,750.00 160.00 1,910.00 0001 0730 6089902 MISC.ADA CURB RAMP 8.00 4.00 12.00 0001 0740 6123000A TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) 2.00 0.00 2.00 0001 0750 6131010 FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR 250.00 0.00 250.00 0001 0760 6131012 SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) 250.00 0.00 250.00 0001 0770 6131013 TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) 250.00 0.00 250.00 0001 0780 6131014 FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER 461.00 0.00 461.00 0001 0790 6131015 DOWEL BAR (FURNISHING AND INSTALLATION) 30.00 0.00 30.00 0001 0800 6131018 TIE BAR (D</td> <td>0001 0710 4071005 TACK COAT 4,293.00 0.00 4,293.00 GAL 0001 0720 5021109 CONCRETE PAVEMENT (9 IN. NON-REINF) 1,750.00 160.00 1,910.00 SQYD 0001 0730 6089902 MISC.ADA CURB RAMP 8.00 4.00 12.00 EA 0001 0740 6123000A TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) 2.00 0.00 2.00 EA 0001 0750 6131010 FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL 250.00 0.00 250.00 SQYD 0001 0760 6131012 SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) 250.00 0.00 250.00 SQYD 0001 0770 6131013 TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) 250.00 0.00 250.00 SQYD 0001 0780 6131014 FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER 461.00 0.00 461.00 LF 0001 0790 6131015 DOWEL BAR (PURINISHING AND INSTALLATION) 30.00</td> <td>0001 0710 4071005 TACK COAT 4,293.00 0.00 4,293.00 GAL 5,324.00 0001 0720 5021109 CONCRETE PAVEMENT (9 IN. NON-REINF) 1,750.00 160.00 1,910.00 SQYD 1,893.96 0001 0730 6089902 MISC.ADA CURB RAMP 8.00 4.00 12.00 EA 16.00 0001 0740 6123000A TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) 2.00 0.00 2.00 EA 0.00 0001 0750 6131010 FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL 250.00 0.00 250.00 SQYD 250.00 0001 0760 6131012 SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) 250.00 0.00 250.00 SQYD 250.00 0001 0770 6131013 TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) 250.00 0.00 250.00 SQYD 250.00 0001 0780 6131013 FURL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER 461.00 0.00 461.00 LF</td> <td> 0001 0710 4071005 TACK COAT 4,293.00 0.00 4,293.00 GAL 5,324.00 \$2.55 </td>	0001 0710 4071005 TACK COAT 4,293.00 0.00 4,293.00 0001 0720 5021109 CONCRETE PAVEMENT (9 IN. NON-REINF) 1,750.00 160.00 1,910.00 0001 0730 6089902 MISC.ADA CURB RAMP 8.00 4.00 12.00 0001 0740 6123000A TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) 2.00 0.00 2.00 0001 0750 6131010 FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR 250.00 0.00 250.00 0001 0760 6131012 SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) 250.00 0.00 250.00 0001 0770 6131013 TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) 250.00 0.00 250.00 0001 0780 6131014 FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER 461.00 0.00 461.00 0001 0790 6131015 DOWEL BAR (FURNISHING AND INSTALLATION) 30.00 0.00 30.00 0001 0800 6131018 TIE BAR (D	0001 0710 4071005 TACK COAT 4,293.00 0.00 4,293.00 GAL 0001 0720 5021109 CONCRETE PAVEMENT (9 IN. NON-REINF) 1,750.00 160.00 1,910.00 SQYD 0001 0730 6089902 MISC.ADA CURB RAMP 8.00 4.00 12.00 EA 0001 0740 6123000A TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) 2.00 0.00 2.00 EA 0001 0750 6131010 FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL 250.00 0.00 250.00 SQYD 0001 0760 6131012 SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) 250.00 0.00 250.00 SQYD 0001 0770 6131013 TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) 250.00 0.00 250.00 SQYD 0001 0780 6131014 FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER 461.00 0.00 461.00 LF 0001 0790 6131015 DOWEL BAR (PURINISHING AND INSTALLATION) 30.00	0001 0710 4071005 TACK COAT 4,293.00 0.00 4,293.00 GAL 5,324.00 0001 0720 5021109 CONCRETE PAVEMENT (9 IN. NON-REINF) 1,750.00 160.00 1,910.00 SQYD 1,893.96 0001 0730 6089902 MISC.ADA CURB RAMP 8.00 4.00 12.00 EA 16.00 0001 0740 6123000A TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) 2.00 0.00 2.00 EA 0.00 0001 0750 6131010 FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL 250.00 0.00 250.00 SQYD 250.00 0001 0760 6131012 SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) 250.00 0.00 250.00 SQYD 250.00 0001 0770 6131013 TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) 250.00 0.00 250.00 SQYD 250.00 0001 0780 6131013 FURL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER 461.00 0.00 461.00 LF	0001 0710 4071005 TACK COAT 4,293.00 0.00 4,293.00 GAL 5,324.00 \$2.55

Revision 3/23/2023 Page 9 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category		Item Code	Port Generated date and can differ from the posted amo	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230317-H03	J9S3528	0001	0860	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$55,870.24	\$55,870.24
		0001	0870	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	50.00	0.00	50.00	LF	50.00	\$6.00	\$300.00
		0001	0880	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	232.00	0.00	232.00	LF	232.00	\$25.00	\$5,800.00
		0001	0890	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	100.00	0.00	100.00	LF	100.00	\$25.00	\$2,500.00
		0001	0900	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	19.00	0.00	19.00	EA	19.00	\$275.00	\$5,225.00
		0001	0910	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
		0001	0920	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	874.00	0.00	874.00	LF	0.00	\$1.50	\$0.00
		0001	0930	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	4,476.00	0.00	4,476.00	LF	0.00	\$1.50	\$0.00
		0001	0940	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	28,259.00	0.00	28,259.00	LF	28,259.00	\$0.14	\$3,956.2
		0001	0950	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	17,307.00	0.00	17,307.00	LF	17,307.00	\$0.20	\$3,461.4
		0001	0960	6207001	PAVEMENT MARKING REMOVAL	5,350.00	0.00	5,350.00	LF	5,350.00	\$1.00	\$5,350.0
		0001	0970	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	6,130.00	0.00	6,130.00	SQYD	7,058.32	\$7.37	\$52,019.8
		0001	0980	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	7,541.00	0.00	7,541.00	SQYD	3,434.81	\$4.85	\$16,658.8
		0001	0990	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	61.00	0.00	61.00	STA	0.00	\$36.03	\$0.0
	Project JS	S3528 - To	otal Value	Posted to D	ate as of Report Generated Date							\$1,316,028.3
	JSE0084	0001	1000	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$8,323.57	\$0.0
		0001	1010	2159910	MISC.SHAPING SLOPES CLASS III - MODIFIED	4.00	0.00	4.00	100F	4.00	\$1,348.46	\$5,393.8
		0001	1020	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	4,037.40	0.00	4,037.40	TONS	4,037.40	\$54.77	\$221,128.4
		0001	1030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	90.00	0.00	90.00	TONS	90.00	\$54.78	\$4,930.2
		0001	1040	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	17,336.40	0.00	17,336.40	TONS	16,059.99	\$96.54	\$1,550,431.4
		0001	1050	4071007	TACK COAT - NON-TRACKING	18,331.00	0.00	18,331.00	GAL	10,408.00	\$1.00	\$10,408.0
		0001	1060	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$0.00	\$0.0
		0001	1070	6161005	CONSTRUCTION SIGNS	1,189.00	0.00	1,189.00	SQFT	906.00	\$6.50	\$5,889.0
		0001	1080	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	0.00	\$45.00	\$0.0
		0001	1090	6161010	RELOCATED SIGNS	476.00	0.00	476.00	SQFT	0.00	\$6.50	\$0.0
		0001	1100	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	0.00	\$24.00	\$0.0
		0001	1110	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$145.00	\$1,450.0
		0001	1120	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.0
		0001	1130	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$63,827.62	\$63,827.6
		0001	1140	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	106,816.00	0.00	106,816.00	LF	106,816.00	\$0.13	\$13,886.0
		0001	1150	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	15,092.00	0.00	15,092.00	LF	15,092.00	\$0.18	\$2,716.5
		0001	1160	6206108A	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	8,045.00	0.00	8,045.00	LF	8,045.00	\$0.50	\$4,022.5
		0001	1170	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,348.00	0.00	1,348.00	SQYD	481.67	\$10.84	\$5,221.3
		0001	1180	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	0.00	856.00	SQYD	856.00	\$41.26	\$35,318.5	
		0001	1190	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	5,430.00	0.00	5,430.00	SQYD	2,425.87	\$8.07	\$19,576.7
		0010	1200	6061060	MGS GUARDRAIL	175.00	0.00	175.00	LF	175.00	\$33.69	\$5,895.7
		0010	1210	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$4,146.39	\$16,585.5
		0010	1220	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	1.00	\$1,794.45	\$1,794.45
		0010	1230	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3.00	0.00	3.00	EA	3.00	\$3,597.61	\$10,792.8
	Project JS	SE0084 - To	otal Value	e Posted to D	Date as of Report Generated Date							\$1,985,268.8
30317-H03 Ove	rall - Total	Value Post	ted to Da	te as of Repo	ort Generated Date							\$6,662,565.7

Revision 3/23/2023 Page 10 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9S3326

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0050	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	6/18/24	7/2/24	712.23	TONS	EBL and 17.054 to 15.913 WBL	17.054		16.582		
			6/20/24	7/2/24	2,185.26	TONS		15.913		10.962		
			6/21/24	7/2/24	1,978.70	TONS	EBL	16.582		12.574		
			6/24/24	7/2/24	2,514.47	TONS	WBL	10.962		5.200		
			6/25/24	7/2/24	1,757.36	TONS	EBL	12.574		8.791		
			6/27/24	7/2/24	1,851.24	TONS	WBL			3.622		
0060	4071005	TACK COAT	6/18/24	7/2/24	678.00	GAL	EBL 17.054 to 15.913 WBL	17.054		16.582		
			6/20/24	7/2/24	2,130.00	GAL	WBL	15.913		10.962		
			6/21/24	7/2/24	1,839.00	GAL	EBL	16.582		12.574		
			6/24/24	7/2/24	2,420.00	GAL	WBL	10.962		5.200		
			6/25/24	7/2/24	1,597.00	GAL	EBL	12.574		8.791		
			6/27/24	7/2/24	1,547.00	GAL	WBL	5.200		3.622		
0250	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	6/18/24	7/2/24	2,541.80	SQYD	End Job	16.969		17.054		
0260	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	6/18/24	7/2/24	5.10	SQYD	Robin Lane RT	16.005				
				7/2/24	8.90	SQYD	Portageville School District RT	16.445				
				7/2/24	9.80	SQYD	Hailey St RT	16.564				
				7/2/24	13.30	SQYD	First Assembly of God LT	16.304				
				7/2/24	16.30	SQYD	Park Ave RT	16.069				
				7/2/24	16.70	SQYD	Parking Lot Entrance LT	16.824				
				7/2/24	18.00	SQYD	Dogwood Apts LT	16.438				
				7/2/24	22.00	SQYD	Co Rd 345 LT	16.851				
				7/2/24	25.00	SQYD	Portageville Nursing & Rehab LT	16.550				
				7/2/24	26.00	SQYD	Cottonwood Point Apts LT	16.397				
				7/2/24	27.70	SQYD	King Ave RT	16.403				
				7/2/24	35.70	SQYD	Magnolia Manor Apts LT	16.378				
				7/2/24	35.80	SQYD	Circle Dr for Apartment x's 2	16.581				
				7/2/24	41.30	SQYD	Farm Shop Ent LT	16.617				
				7/2/24	53.30	SQYD	Bill Hayes Ford LT	16.328				
				7/2/24	55.20	SQYD	Farm Credit of SEMO RT	16.374				
				7/2/24	68.00	SQYD	Bill Hayes Ford	16.355				
				7/2/24	125.00	SQYD	Rte F South RT	16.259				
				7/2/24	127.80	SQYD	Rte F North LT	16.259				
0350	7034600	CURB BLOCKOUT	6/18/24	6/30/24	122.00	LF		0		0		Bridge #A3269 North Barrier Wall Curb Blockout
				6/30/24	122.00	LF		0		0		Bridge #A3269 South Barrier Wall Curb Blockout

Project: J9S3403

Line lumber	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0460	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	6/17/24	7/2/24	1,115.46	TONS	EBL and 10.288 to 10.503 on WBL	10.583		11.503		
0470	4071005	TACK COAT	6/17/24	7/2/24	968.00	GAL	EBL and 10.288 to 10.503 WBL	10.583		11.503		
0570	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	6/17/24	7/2/24	160.00	SQYD	Rte 25/End Project	11.492		11.503		
0580	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	6/17/24	7/2/24	2.20	SQYD	Private Ent LT	11.279				
				7/2/24	2.80	SQYD	Alley RT	11.327				
				7/2/24	3.60	SQYD	Private Ent LT	11.362				
				7/2/24	3.80	SQYD	Private Ent LT	11.401				
				7/2/24	4.40	SQYD	Private Ent LT	11.375				
				7/2/24	4.40	SQYD	Private Entrance LT	11.369				
				7/2/24	5.10	SQYD	Alley way RT					
				7/2/24	5.10	SQYD	Private Entrance LT	10.882				
				7/2/24	6.00	SQYD	Private Entrance LT	10.961				
				7/2/24	6.40	SQYD	Private Entrance LT	6.4	10.920			
				7/2/24	7.30	SQYD	Private Entrance RT	11.105				
				7/2/24	9.30	SQYD	Stokes Blvd North RT	11.371				
				7/2/24	10.40	SQYD	Subdivision Entrance LT	11.00				
				7/2/24	11.10	SQYD	Stokes Blvd RT	11.363				
				7/2/24	12.80	SQYD	Oak Street RT	11.141				
				7/2/24	16.10	SQYD	Smith St LT	11.433				
				7/2/24	16.10	SQYD	Washington Ave RT		11.289			
				7/2/24	16.70	SQYD	Elm Street RT	11.212				
				7/2/24	25.78	SQYD	Stevenson St LT					
				7/2/24			Palo Verde RT	11.061				
				7/2/24			Strokelan Dr LT	11.251				
				7/2/24	133.30	SQYD	Rte 25/End Project	11.492		11.503		

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 11 of 29



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J9S3326	0050	BITUMINOUS PAVEMENT MIXTURE	Other Item Adjustment	ACAD	15	Jul 2, 2024	stottt1	(\$9,074.39)	10999.3 tons of SL24-8							
		PG64-22 (SUR		ACAD - Tota	al			(\$9,074.39)								
			Other Item /	Adjustment -	Total			(\$9,074.39)								
			Price FUEL		15	Jul 2, 2024	SYSTEM	(\$19,682.95)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL							
				- Total				(\$19,682.95)								
			Price FUEL	- Total				(\$19,682.95)								
	0050 -	Total						(\$28,757.34)								
	0090	3 IN. CONCRETE MEDIAN STRIP	Material		12	May 16, 2024	SYSTEM	\$9,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user olivem2 overridding Payment Estimate Exception 8 on the current Payment Estimate.							
					12	May 16, 2024	SYSTEM	(\$9,460.00)								
				- Total				\$0.00								
			Material - To	otal				\$0.00								
	0090 -	Total						\$0.00								
	0190	TEMPORARY REMOVABLE MARKING TAPE 4	Material		11	May 2, 2024	SYSTEM	\$2,851.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stottt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.							
		IN.,			11 May 2, S 2024		SYSTEM	(\$2,851.50)								
				- Total				\$0.00								
			Material - To					\$0.00								
	0190 -	Total						\$0.00								
	0200		Material		11	May 2, 2024	SYSTEM	\$6,030.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stottt1 overridding Payment Estimate Exception 12 on the current Payment Estimate.							
					11	May 2, 2024	SYSTEM	(\$6,030.00)								
				- Total				\$0.00								
			Material - Total					\$0.00								
	0200 -	Total						\$0.00								
	0210	REMOVABLE MARKING TAPE,	Material	Material		May 2, 2024	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stottt1 overridding Payment Estimate Exception 13 on the current Payment Estimate.							
		24 IN.			11	May 2, 2024	SYSTEM	(\$360.00)								
				- Total				\$0.00								
			Material - To	otal				\$0.00								
	0210 -	Total						\$0.00								
	0290		- Total MGS GUARDRAIL							Material		12	May 16, 2024	SYSTEM	\$4,076.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user olivem2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					12	May 16, 2024	SYSTEM	(\$4,076.25)								
					13	Jun 3, 2024	SYSTEM	\$17,527.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stottt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.							
					13	Jun 3, 2024	SYSTEM	(\$17,527.88)								
					14	Jun 18, 2024	SYSTEM	\$27,718.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user collie1 overridding Payment Estimate Exception 7 on the current Payment Estimate.							
					14	Jun 18, 2024	SYSTEM	(\$27,718.50)								
					15	Jul 2, 2024	SYSTEM	\$27,718.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stottt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.							
					15	Jul 2, 2024	SYSTEM	(\$27,718.50)								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J9S3326	0290	MGS GUARDRAIL	Material	- Total				\$0.00						
			Material - To	otal				\$0.00						
	0290 -							\$0.00						
	0350	CURB BLOCKOUT	Material		15	Jul 2, 2024	SYSTEM	\$34,892.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user stottt1 overridding Payment Estimate Exception 14 on the current Payment Estimate.					
					15	Jul 2, 2024	SYSTEM	(\$34,892.00)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0350 -	Total						\$0.00						
	0360	CURB BLOCKOUT	Material		11	May 2, 2024	SYSTEM	\$17,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stottt 1 overridding Payment Estimate Exception 16 on the current Payment Estimate.					
					11	May 2, 2024	SYSTEM	(\$17,810.00)						
					12	May 16, 2024	SYSTEM	\$35,620.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user olivem2 overridding Payment Estimate Exception 15 on the current Payment Estimate.					
					12	May 16, 2024	SYSTEM	(\$35,620.00)						
					13	Jun 3, 2024	SYSTEM	\$35,620.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stottt1 overridding Payment Estimate Exception 14 on the current Payment Estimate.					
					13	Jun 3, 2024	SYSTEM	(\$35,620.00)						
					14	Jun 18, 2024	SYSTEM	\$35,620.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user collie1 overridding Payment Estimate Exception 14 on the current Payment Estimate.					
										14	Jun 18, 2024	SYSTEM	(\$35,620.00)	
													15	Jul 2, 2024
					15	Jul 2, 2024	SYSTEM	(\$35,620.00)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0360 -	Total						\$0.00						
	0370	CURB BLOCKOUT	Material	Material	Material	Material		11	May 2, 2024	SYSTEM	\$17,689.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stottt1 overridding Payment Estimate Exception 19 on the current Payment Estimate.		
					11	May 2, 2024	SYSTEM	(\$17,689.00)						
					12	May 16, 2024	SYSTEM	\$35,245.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user olivem2 overridding Payment Estimate Exception 18 on the current Payment Estimate.					
					12	May 16, 2024	SYSTEM	(\$35,245.00)						
						1	13	Jun 3, 2024	SYSTEM	\$35,245.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stottt1 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
				15	13	Jun 3, 2024	SYSTEM	(\$35,245.00)						
						14	Jun 18, 2024	SYSTEM	\$35,245.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user collie1 overridding Payment Estimate Exception 15 on the current Payment Estimate.				
					14	Jun 18, 2024	SYSTEM	(\$35,245.00)						
				15	Jul 2, 2024	SYSTEM	\$35,245.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user stottt 1 overridding Payment Estimate Exception 16 on the current Payment Estimate.						
					15	Jul 2, 2024	SYSTEM	(\$35,245.00)						
						2024								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3326	0370	CURB BLOCKOUT	Material	- Total				\$0.00	
			Material - To	otal				\$0.00	
	0370 -	Total						\$0.00	
	0380	CURB BLOCKOUT	Material		13	Jun 3, 2024	SYSTEM	\$18,112.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stottt1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					13	Jun 3, 2024	SYSTEM	(\$18,112.50)	
					14	Jun 18, 2024	SYSTEM	\$36,225.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user collie1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					14	Jun 18, 2024	SYSTEM	(\$36,225.00)	
					15	Jul 2, 2024	SYSTEM	\$36,225.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user stottt1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					15	Jul 2, 2024	SYSTEM	(\$36,225.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0380 -	Total						\$0.00	
	0390	CURB BLOCKOUT	Material		13	Jun 3, 2024	SYSTEM	\$17,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stottt1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					13	Jun 3, 2024	SYSTEM	(\$17,780.00)	
					14	Jun 18, 2024	SYSTEM	\$35,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user collie1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					14	Jun 18, 2024	SYSTEM	(\$35,560.00)	
					15	Jul 2, 2024	SYSTEM	\$35,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user stottt1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					15	Jul 2, 2024	SYSTEM	(\$35,560.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0390 -	Total						\$0.00	
J9S3326 -	Total							(\$28,757.34)	
J9S3403	0450	BITUMINOUS PAVEMENT	Other Item Adjustment	ACAD	14	Jun 18, 2024	stottt1	(\$2,057.07)	Asphalt Index for 2887.12 tons BB24-3
		MIXTURE PG64-22 (BAS		ACAD - Tot	al			(\$2,057.07)	
			Other Item	Adjustment -	Total			(\$2,057.07)	
			Price FUEL		14	Jun 18, 2024	SYSTEM	(\$5,166.44)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				(\$5,166.44)	
			Price FUEL	- Total				(\$5,166.44)	
	0450 -	Total						(\$7,223.51)	
	0460	BITUMINOUS PAVEMENT MIXTURE	Other Item Adjustment	ACAD	14	Jun 18, 2024	stottt1	(\$9,201.92)	Asphalt Index for 11153.84 tons SL24-8
		PG64-22 (SUR			15	Jul 2, 2024	stottt1	(\$920.25)	1115.46 tons of SL24-8
				ACAD - Tot	al			(\$10,122.17)	
			Other Item	Adjustment -	Total			(\$10,122.17)	
			Overrun	Overrun	15	Jul 2, 2024	SYSTEM	(\$392.27)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				Overrun - T	otal			(\$392.27)	
			Overrun - T	otal				(\$392.27)	
			Price FUEL		14	Jun 18, 2024	SYSTEM	(\$19,959.58)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J9S3403	0460	BITUMINOUS PAVEMENT MIXTURE	Price FUEL		15	Jul 2, 2024	SYSTEM	(\$1,996.09)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
		PG64-22 (SUR		- Total				(\$21,955.67)														
			Price FUEL	- Total				(\$21,955.67)														
	0460 -	Total						(\$32,470.11)														
J9S3403 -	Total							(\$39,693.62)														
J9S3528	0650	TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		4	Aug 16, 2023	SYSTEM	\$19,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
		THICK)			4	Aug 16, 2023	SYSTEM	(\$19,250.00)														
					5	Sep 5, 2023	SYSTEM	\$22,629.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					5	Sep 5, 2023	SYSTEM	(\$22,629.20)														
					6	Sep 18, 2023	SYSTEM	\$22,629.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					6	Sep 18, 2023	SYSTEM	(\$22,629.20)														
					7	Dec 4, 2023	SYSTEM	\$22,629.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					7	Dec 4, 2023	SYSTEM	(\$22,629.20)														
																		8	Jan 2, 2024	SYSTEM	\$22,629.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
																		8	Jan 2, 2024	SYSTEM	(\$22,629.20)	
														9	Mar 4, 2024	SYSTEM	\$22,629.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
										9	Mar 4, 2024	SYSTEM	(\$22,629.20)									
					10	Apr 2, 2024	SYSTEM	\$22,629.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					10	Apr 2, 2024	SYSTEM	(\$22,629.20)														
				- Total				\$0.00														
			Material - To	otal				\$0.00														
			Material - T	Overrun	5	Sep 5, 2023	SYSTEM	(\$3,394.04)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
				Overrun - T	otal			(\$3,394.04)														
			Overrun - T	otal				(\$3,394.04)														
			Price FUEL		4	Aug 16, 2023	SYSTEM	\$84.52	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
					5	Sep 5, 2023	SYSTEM	\$14.84	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
				- Total				\$99.36														
			Price FUEL	- Total				\$99.36														
	0650 -	Total						(\$3,294.68)														
	0660		MISC. N AGGREGATE	Material		4	Aug 16, 2023	SYSTEM	\$26,376.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 5 on the current Payment Estimate.												
					4	Aug 16, 2023	SYSTEM	(\$26,376.26)														
					5	Sep 5, 2023	SYSTEM	\$26,376.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user collie1 overridding Payment Estimate Exception 5 on the current Payment Estimate.													
					5	Sep 5,	SYSTEM	(\$26,376.26)														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3528	0660	MISC.	Material			2023			
		AGGREGATE FOR BASE			6	Sep 18, 2023	SYSTEM	\$26,376.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stottt1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Sep 18, 2023	SYSTEM	(\$26,376.26)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0660 -							\$0.00	
	0680	TYPE A2 SHOULDER	Material		6	Sep 18, 2023	SYSTEM	\$52,264.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Sep 18, 2023	SYSTEM	(\$52,264.00)	
					7	Dec 4, 2023	SYSTEM	\$66,505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$66,505.00)	
					8	Jan 2, 2024	SYSTEM	\$66,505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Jan 2, 2024	SYSTEM	(\$66,505.00)	
					9	Mar 4, 2024	SYSTEM	\$66,505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Mar 4, 2024	SYSTEM	(\$66,505.00)	
					10	Apr 2, 2024	SYSTEM	\$66,505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Apr 2, 2024	SYSTEM	(\$66,505.00)	
					11	May 2, 2024	SYSTEM	\$66,505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	May 2, 2024	SYSTEM	(\$66,505.00)	
					12	May 17, 2024	SYSTEM	\$66,505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	May 16, 2024	SYSTEM	(\$66,505.00)	
					13	Jun 3, 2024	SYSTEM	\$66,505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Jun 3, 2024	SYSTEM	(\$66,505.00)	
					14	Jun 18, 2024	SYSTEM	\$66,505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user collie1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Jun 18, 2024	SYSTEM	(\$66,505.00)	
					15	Jul 2, 2024	SYSTEM	\$66,505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					15	Jul 2, 2024	SYSTEM	(\$66,505.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	FUEL	7	Dec 4, 2023	collie1	(\$1.48)	Items were paid during the incorrect pay period. This amount was removed to correct the Fuel Adjustment.
					7	Dec 4, 2023	collie1	\$15.59	This is the Fuel Index calculated for when work was actually completed.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3528	0680	TYPE A2 SHOULDER	Other Item Adjustment	FUEL - Tota	ı			\$14.11	
			Other Item	Adjustment -	Total			\$14.11	
			Price FUEL		6	Sep 18, 2023	SYSTEM	\$2.51	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Dec 4, 2023	SYSTEM	\$1.48	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$3.99	
			Price FUEL	- Total				\$3.99	
	0680 -	Total						\$18.10	
	0690	BIT. PAVEMENT MIXTURE	Price FUEL		1	Jun 30, 2023	SYSTEM	(\$4,619.45)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		PG64-22 (BP-1)			3	Aug 2, 2023	SYSTEM	(\$722.39)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				(\$5,341.84)	
			Price FUEL	- Total				(\$5,341.84)	
	0690 -	Total						(\$5,341.84)	
	0700	PAVEMENT	Price FUEL		1	Jun 30, 2023	SYSTEM	(\$435.63)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		MIXTURE PG64-22 (BAS		- Total				(\$435.63)	
			Price FUEL	- Total				(\$435.63)	
	0700 -	Total						(\$435.63)	
	0710	TACK COAT	Material		1	Jun 30, 2023	SYSTEM	\$12,342.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Jun 30, 2023	SYSTEM	(\$12,342.00)	·
					2	Jul 17, 2023	SYSTEM	\$12,342.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$12,342.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	1	Jun 30, 2023	SYSTEM	(\$1,394.85)	
					3	Aug 2, 2023	SYSTEM	(\$1,234.20)	
				Overrun - T	otal			(\$2,629.05)	
			Overrun - T	otal				(\$2,629.05)	
	0710 -	Total						(\$2,629.05)	
	0720	CONCRETE PAVEMENT (9 IN. NON-REINF)	Material		5	Sep 5, 2023	SYSTEM	\$189,001.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$189,001.64)	
					6	Sep 18, 2023	SYSTEM	\$189,001.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stottt1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Sep 18, 2023	SYSTEM	(\$189,001.64)	
					7	Dec 4, 2023	SYSTEM	\$206,441.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$206,441.64)	
				2024 Estimate Item Adjustment (0005) of	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user collie1 overridding Payment Estimate Exception 6 on the current Payment Estimate.				
					8	Jan 2, 2024	SYSTEM	(\$206,441.64)	



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
528	0720	CONCRETE PAVEMENT (9 IN. NON-REINF)	Material		9	Mar 4, 2024	SYSTEM	\$206,441.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stottt1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Mar 4, 2024	SYSTEM	(\$206,441.64)	
					10	Apr 2, 2024	SYSTEM	\$206,441.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user collie1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					10	Apr 2, 2024	SYSTEM	(\$206,441.64)	
					11	May 2, 2024	SYSTEM	\$206,441.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	May 2, 2024	SYSTEM	(\$206,441.64)	
					12	May 17, 2024	SYSTEM	\$206,441.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	May 16, 2024	SYSTEM	(\$206,441.64)	
					13	Jun 3, 2024	SYSTEM	\$206,441.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	Jun 3, 2024	SYSTEM	(\$206,441.64)	
					14	Jun 18, 2024	SYSTEM	\$206,441.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Jun 18, 2024	SYSTEM	(\$206,441.64)	
					15	Jul 2, 2024	SYSTEM	\$206,441.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					15	Jul 2, 2024	SYSTEM	(\$206,441.64)	
				- Total				\$0.00	
			Material - To					\$0.00	
			Other Item Adjustment	FUEL	7	Dec 4, 2023	collie1	(\$98.21)	Items were paid during the incorrect pay period. This amount was removed to correct the Fuel Adjustment.
					7	Dec 4, 2023	collie1	\$22.18	This is the Fuel Index calculated for when work was actually completed.
			OII II	FUEL - Tota				(\$76.03)	
			Other Item /	Adjustment -	Total 5	Sep 5,	SYSTEM	(\$76.03) \$240.34	Peferance Itam Price Adjustment Index Adjustment Type applied is ELIEL
			FUEL		7	2023 Dec 4,	SYSTEM	\$98.21	Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total	,	2023	STOTEM	\$338.55	Reference nem Price Adjustment muex Adjustment Type applied is 1 OLL
			Price FUEL					\$338.55	
	0720 -	Total						\$262.52	
		MISC. CONCRETE	Overrun	Overrun	6	Sep 18, 2023	SYSTEM	(\$5,600.00)	
				Overrun - T	otal			(\$5,600.00)	
			Overrun - T	otal				(\$5,600.00)	
	0730 -	Total						(\$5,600.00)	
	0750	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		5	Sep 5, 2023	SYSTEM	\$82,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user collie1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$82,895.00)	
					6	Sep 18, 2023	SYSTEM	\$82,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stottt1 overridding Payment Estimate Exception 16 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J9S3528	0750	FURN & PLACE CONC MATL FOR	Material		6	Sep 18, 2023	SYSTEM	(\$82,895.00)										
		FULL DEPTH			7	Dec 4, 2023	SYSTEM	\$82,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 10 on the current Payment Estimate.									
					7	Dec 4, 2023	SYSTEM	(\$82,895.00)										
				- Total				\$0.00										
			Material - To	otal				\$0.00										
	0750 -	· Total						\$0.00										
	0770	AGGREGATE FOR BASE (4 IN.	Material		5	Sep 5, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user collie1 overridding Payment Estimate Exception 18 on the current Payment Estimate.									
		TH			5	Sep 5, 2023	SYSTEM	(\$3,500.00)										
					6	Sep 18, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stottt1 overridding Payment Estimate Exception 19 on the current Payment Estimate.									
					6	Sep 18, 2023	SYSTEM	(\$3,500.00)										
					7	Dec 4, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user collie1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
					7	Dec 4, 2023	SYSTEM	(\$3,500.00)										
					8	Jan 2, 2024	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 10 on the current Payment Estimate.									
														8	Jan 2, 2024	SYSTEM	(\$3,500.00)	
					9	Mar 4, 2024	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stottt1 overridding Payment Estimate Exception 10 on the current Payment Estimate.									
											9	Mar 4, 2024	SYSTEM	(\$3,500.00)				
															10	Apr 2, 2024	SYSTEM	\$3,500.00
					10	Apr 2, 2024	SYSTEM	(\$3,500.00)										
				- Total				\$0.00										
			Material - To	otal				\$0.00										
	0770 -	· Total						\$0.00										
	0790	DOWEL BAR (DRILLING, FURNISHING AND	Material		5	Sep 5, 2023	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user collie1 overridding Payment Estimate Exception 19 on the current Payment Estimate.									
		INST			5	Sep 5, 2023	SYSTEM	(\$420.00)										
		INOT			6	Sep 18, 2023	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stottt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.									
					6	Sep 18, 2023	SYSTEM	(\$420.00)										
				-			7						7	Dec 4, 2023	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
				2024 Estimate Item Adjustment (0007) due to user stott														
					8		SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
					8	Jan 2, 2024	SYSTEM	(\$420.00)										
					9	Mar 4, 2024	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									

MoDOT

Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J9S3528	0790	DOWEL BAR (DRILLING,	Material		9	Mar 4, 2024	SYSTEM	(\$420.00)		
		FURNISHING AND INST			10	Apr 2, 2024	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user collie1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
					10	Apr 2, 2024	SYSTEM	(\$420.00)		
					11	May 2, 2024	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					11	May 2, 2024	SYSTEM	(\$420.00)		
					12	May 17, 2024	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stott11 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					12	May 16, 2024	SYSTEM	(\$420.00)		
					13	Jun 3, 2024	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					13	Jun 3, 2024	SYSTEM	(\$420.00)		
					14	Jun 18, 2024	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user collie1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
						14	Jun 18, 2024	SYSTEM	(\$420.00)	
						15	Jul 2, 2024	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stottt1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					15	Jul 2, 2024	SYSTEM	(\$420.00)		
				- Total				\$0.00		
			Material - T	a fal				60.00		
	0700	Total	Material - 1	otai				\$0.00		
		- Total		otai	E	Can F	CVCTEM	\$0.00	This adjustment offsets the ariginal system generated Material Degrees	
	0790 - 0800	DOWEL BAR (FURNISH AND INSTALL WITH BASK	Material	otai	5	Sep 5, 2023	SYSTEM	\$0.00 \$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user collie1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	
		DOWEL BAR (FURNISH AND INSTALL WITH		otal	5		SYSTEM	\$0.00	Estimate Item Adjustment (0021) due to user collie1 overridding Payment	
		DOWEL BAR (FURNISH AND INSTALL WITH		otai		2023 Sep 5,		\$0.00 \$2,160.00	Estimate Item Adjustment (0021) due to user collie1 overridding Payment	
		DOWEL BAR (FURNISH AND INSTALL WITH		otai	5	2023 Sep 5, 2023 Sep 18,	SYSTEM	\$0.00 \$2,160.00 (\$2,160.00)	Estimate Item Adjustment (0021) due to user collie1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stottt1 overridding Payment	
		DOWEL BAR (FURNISH AND INSTALL WITH		otai	5	2023 Sep 5, 2023 Sep 18, 2023	SYSTEM SYSTEM	\$0.00 \$2,160.00 (\$2,160.00) \$2,160.00	Estimate Item Adjustment (0021) due to user collie1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stottt1 overridding Payment	
		DOWEL BAR (FURNISH AND INSTALL WITH		otai	5 6	2023 Sep 5, 2023 Sep 18, 2023 Sep 18, 2023 Dec 4,	SYSTEM SYSTEM SYSTEM	\$0.00 \$2,160.00 (\$2,160.00) \$2,160.00 (\$2,160.00)	Estimate Item Adjustment (0021) due to user collie1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stottt1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user collie1 overridding Payment	
		DOWEL BAR (FURNISH AND INSTALL WITH		otai —	5 6 6 7	2023 Sep 5, 2023 Sep 18, 2023 Sep 18, 2023 Dec 4, 2023 Dec 4,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$2,160.00 (\$2,160.00) \$2,160.00 (\$2,160.00) \$2,160.00	Estimate Item Adjustment (0021) due to user collie1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stott1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user collie1 overridding Payment	
		DOWEL BAR (FURNISH AND INSTALL WITH		otal —	5 6 6 7	2023 Sep 5, 2023 Sep 18, 2023 Sep 18, 2023 Dec 4, 2023 Dec 4, 2023 Jan 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$2,160.00 (\$2,160.00) \$2,160.00 (\$2,160.00) (\$2,160.00)	Estimate Item Adjustment (0021) due to user collie1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stottt1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user collie1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment	
		DOWEL BAR (FURNISH AND INSTALL WITH		otal (5 6 7 7 8	2023 Sep 5, 2023 Sep 18, 2023 Sep 18, 2023 Dec 4, 2023 Dec 4, 2023 Jan 2, 2024 Jan 2, 2n 2	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$2,160.00 (\$2,160.00) \$2,160.00 (\$2,160.00) \$2,160.00 (\$2,160.00)	Estimate Item Adjustment (0021) due to user collie1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stottt1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user collie1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment	
		DOWEL BAR (FURNISH AND INSTALL WITH		otal (5 6 7 7 8	2023 Sep 5, 2023 Sep 18, 2023 Sep 18, 2023 Dec 4, 2023 Dec 4, 2023 Jan 2, 2024 Mar 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$2,160.00 (\$2,160.00) \$2,160.00 (\$2,160.00) \$2,160.00 (\$2,160.00)	Estimate Item Adjustment (0021) due to user collie1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stottt1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user collie1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.	
		DOWEL BAR (FURNISH AND INSTALL WITH		OCA1	5 6 7 7 8 8 9	2023 Sep 5, 2023 Sep 18, 2023 Sep 18, 2023 Dec 4, 2023 Dec 4, 2023 Jan 2, 2024 Mar 4, 2024 Mar 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$2,160.00 (\$2,160.00) \$2,160.00 (\$2,160.00) \$2,160.00 (\$2,160.00) \$2,160.00 (\$2,160.00)	Estimate Item Adjustment (0021) due to user collie1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stottt1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user collie1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
		DOWEL BAR (FURNISH AND INSTALL WITH		otal (5 6 7 7 8 8 9	2023 Sep 5, 2023 Sep 18, 2023 Sep 18, 2023 Dec 4, 2023 Dec 4, 2023 Jan 2, 2024 Mar 4, 2024 Mar 4, 2024 Apr 2,	SYSTEM	\$0.00 \$2,160.00 (\$2,160.00) \$2,160.00 (\$2,160.00) \$2,160.00 (\$2,160.00) \$2,160.00 (\$2,160.00)	Estimate Item Adjustment (0021) due to user collie1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stottt1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user collie1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stott1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.	

MoDOT

Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3528	0800	DOWEL BAR (FURNISH AND	Material			2024			Estimate Item Adjustment (0005) due to user stottt1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	INSTALL WITH BASK			11	May 2, 2024	SYSTEM	(\$2,160.00)		
					12	May 17, 2024	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stottt1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					12	May 16, 2024	SYSTEM	(\$2,160.00)	
					13	Jun 3, 2024	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stottt1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					13	Jun 3, 2024	SYSTEM	(\$2,160.00)	
					14	Jun 18, 2024	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					14	Jun 18, 2024	SYSTEM	(\$2,160.00)	
					15	Jul 2, 2024	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					15	Jul 2, 2024	SYSTEM	(\$2,160.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0800 -	· Total						\$0.00	
	FURN & INSTAL	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	.)		5	Sep 5, 2023	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user collie1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$900.00)	
					6	Sep 18, 2023	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stottt1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					6	Sep 18, 2023	SYSTEM	(\$900.00)	
					7	Dec 4, 2023	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user collie1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$900.00)	
					8	Jan 2, 2024	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					8	Jan 2, 2024	SYSTEM	(\$900.00)	
					9	Mar 4, 2024	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stottt1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					9	Mar 4, 2024	SYSTEM	(\$900.00)	
					10	Apr 2, 2024	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					10	Apr 2, 2024	SYSTEM	(\$900.00)	
					11	May 2, 2024	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stottt1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					11	May 2, 2024	SYSTEM	(\$900.00)	
					12	May 17, 2024	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stottt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					12	May 16,	SYSTEM	(\$900.00)	



					_				
roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
S3528	0810	TIE BAR (DRILL,	Material			2024			
		FURN & INSTAL) (TYPE L			13	Jun 3, 2024	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stottt1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					13	Jun 3, 2024	SYSTEM	(\$900.00)	
					14	Jun 18, 2024	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					14	Jun 18, 2024	SYSTEM	(\$900.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0810 -	Total						\$0.00	
	0820	CONSTRUCTION SIGNS	Material		1	Jun 30, 2023	SYSTEM	\$3,841.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user collie1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Jun 30, 2023	SYSTEM	(\$3,841.50)	
					2	Jul 17, 2023	SYSTEM	\$3,841.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$3,841.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0820 -	Total						\$0.00	
	0830	CHANNELIZER (TRIM LINE)	Material		1	Jun 30, 2023	SYSTEM	\$1,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Jun 30, 2023	SYSTEM	(\$1,560.00)	
					2	Jul 17, 2023	SYSTEM	\$1,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stottt1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$1,560.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0830 -	Total						\$0.00	
	0850	CMS W/O COMMUNICATION INTERFACE,	Material		1	Jun 30, 2023	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		CONT F/			1	Jun 30, 2023	SYSTEM	(\$9,000.00)	
					2	Jul 17, 2023	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stottt1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$9,000.00)	
				- Total				\$0.00	
			Material - T					\$0.00 \$0.00	
	0850 -	Total	Material - To						
	0850 - 0880	Total PREF THERMO PVMT MARK, 24 IN WHIT			9	Mar 4, 2024	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stottt1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
		PREF THERMO PVMT MARK, 24			9		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0010) due to user stottt1 overridding Payment
		PREF THERMO PVMT MARK, 24				2024 Mar 4,		\$0.00 \$0.00 \$5,800.00	Estimate Item Adjustment (0010) due to user stottt1 overridding Payment



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Froject	Line	Description	Type	Adjustment Type	Number	Date	By	Amount	Remains
J9S3528	0880	PREF THERMO	Material	- Total				\$0.00	
		PVMT MARK, 24 IN WHIT	Material - To	l otal				\$0.00	
	0880 -							\$0.00	
	0890	PREF THERMO	Material		9	Mar 4,	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment
	0030	PVMT MARK, 24 IN YELLOW	Waterial		5	2024	OTOTEM	Ψ2,000.00	Estimate Item Adjustment (0011) due to user stottt overridding Payment Estimate Exception 16 on the current Payment Estimate.
					9	Mar 4, 2024	SYSTEM	(\$2,500.00)	
					10	Apr 2, 2024	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					10	Apr 2, 2024	SYSTEM	(\$2,500.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0890 -	Total						\$0.00	
	0900	PREF THERMO PVMT MARK, LT/RT ARROW	Material		9	Mar 4, 2024	SYSTEM	\$5,225.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stottt1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					9 Mar 4, SYSTEM (\$5,225.00)				
					10	Apr 2, 2024	SYSTEM	\$5,225.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user collie1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					10	Apr 2, 2024	SYSTEM	(\$5,225.00)	
				- Total		2024		\$0.00	
			Material - To					\$0.00	
	0900 -	Total						\$0.00	
	0910	PREF THERMO PVMT MARK, R/R XING	Material		9	Mar 4, 2024	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stottt1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					9	Mar 4, 2024	SYSTEM	(\$3,000.00)	
					10	Apr 2, 2024	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user collie1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					10	Apr 2, 2024	SYSTEM	(\$3,000.00)	
				- Total		2024		\$0.00	
			Material - T	otal				\$0.00	
	0910 -	Total						\$0.00	
	0940	4 IN. WHITE WATERBORNE PAVEMENT	Material		9	Mar 4, 2024	SYSTEM	\$3,956.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stottt1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
		MARKING			9	Mar 4, 2024	SYSTEM	(\$3,956.26)	
					10	Apr 2, 2024	SYSTEM	\$3,956.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user collie1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					10	Apr 2, 2024	SYSTEM	(\$3,956.26)	
					11	May 2, 2024	SYSTEM	\$3,956.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					11	May 2, 2024	SYSTEM	(\$3,956.26)	
					12	May 17, 2024	SYSTEM	\$3,956.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					12	May 16, 2024	SYSTEM	(\$3,956.26)	
					13	Jun 3,	SYSTEM	\$3,956.26	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3528	0940	4 IN. WHITE WATERBORNE PAVEMENT	Material			2024			Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
		MARKING			13	Jun 3, 2024	SYSTEM	(\$3,956.26)	
					14	Jun 18, 2024	SYSTEM	\$3,956.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user collie1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					14	Jun 18, 2024	SYSTEM	(\$3,956.26)	
					15	Jul 2, 2024	SYSTEM	\$3,956.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stottt1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					15	Jul 2, 2024	SYSTEM	(\$3,956.26)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0940 -	Total						\$0.00	
	0950	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		9	Mar 4, 2024	SYSTEM	\$3,461.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stottt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
		WARKING			9	Mar 4, 2024	SYSTEM	(\$3,461.40)	
					10	Apr 2, 2024	SYSTEM	\$3,461.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user collie1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					10	Apr 2, 2024	SYSTEM	(\$3,461.40)	
					11	May 2, 2024	SYSTEM	\$3,461.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stottt1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					11	May 2, 2024	SYSTEM	(\$3,461.40)	
					12	May 17, 2024	SYSTEM	\$3,461.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stottt1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					12	May 16, 2024	SYSTEM	(\$3,461.40)	
					13	Jun 3, 2024	SYSTEM	\$3,461.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stottt1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					13	Jun 3, 2024	SYSTEM	(\$3,461.40)	
					14	Jun 18, 2024	SYSTEM	\$3,461.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					14	Jun 18, 2024	SYSTEM	(\$3,461.40)	
					15	Jul 2, 2024	SYSTEM	\$3,461.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stottt1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					15	Jul 2, 2024	SYSTEM	(\$3,461.40)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0950 -	Total						\$0.00	
	0970	COLDMILLING BIT. PAVT FOR REM OF SURF.	Overrun	Overrun	1	Jun 30, 2023	SYSTEM	(\$6,841.72)	
		NEW OF SURF.		Overrun - T	otal			(\$6,841.72)	
			Overrun - T	otal				(\$6,841.72)	
	0970 -	Total						(\$6,841.72)	
J9S3528 -	Total							(\$23,862.30)	
JSE0084	1020	MISC. AGGREGATE FOR BASE	Material		4	Aug 16, 2023	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate.



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
0084	1020	MISC. AGGREGATE	Material		4	Aug 16, 2023	SYSTEM	(\$221,128.40)							
		FOR BASE			5	Sep 5, 2023	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
					5	Sep 5, 2023	SYSTEM	(\$221,128.40)							
					6	Sep 18, 2023	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
					6	Sep 18, 2023	SYSTEM	(\$221,128.40)							
					7	Dec 4, 2023	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					7	Dec 4, 2023	SYSTEM	(\$221,128.40)							
					8	Jan 2, 2024	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					8	Jan 2, 2024	SYSTEM	(\$221,128.40)							
					9	Mar 4, 2024	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
											9	Mar 4, 2024	SYSTEM	(\$221,128.40)	
										10	Apr 2, 2024	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
						10	Apr 2, 2024	SYSTEM	(\$221,128.40)						
						11	May 2, 2024	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
							11	May 2, 2024	SYSTEM	(\$221,128.40)					
					12	May 17, 2024	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					12	May 16, 2024	SYSTEM	(\$221,128.40)							
					13	Jun 3, 2024	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					13	Jun 3, 2024	SYSTEM	(\$221,128.40)							
					14	Jun 18, 2024	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					14	Jun 18, 2024	SYSTEM	(\$221,128.40)							
					15	Jul 2, 2024	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					15	Jul 2, 2024	SYSTEM	(\$221,128.40)							
				- Total				\$0.00							
			Material - To	otal				\$0.00							
	1020 -	Total						\$0.00							
	1030	GRAVEL (A) OR CRUSHED STONE (B)	Material		4	Aug 16, 2023	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 7 on the current Payment Estimate.						
					4	Aug 16, 2023	SYSTEM	(\$4,930.20)							
					5	Sep 5,	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSE0084	1030	GRAVEL (A) OR CRUSHED STONE	Material			2023			Estimate Item Adjustment (0010) due to user collie1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
		(B)			5	Sep 5, 2023	SYSTEM	(\$4,930.20)	
					6	Sep 18, 2023	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					6	Sep 18, 2023	SYSTEM	(\$4,930.20)	
					7	Dec 4, 2023	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$4,930.20)	
				8	Jan 2, 2024	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					8	Jan 2, 2024	SYSTEM	(\$4,930.20)	
					9	Mar 4, 2024	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				9	Mar 4, 2024	SYSTEM	(\$4,930.20)		
					10	Apr 2, 2024	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					10	Apr 2, 2024	SYSTEM	(\$4,930.20)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1030 -	· Total						\$0.00	
	1040	BITUMINOUS PAVEMENT	ENT FUEL JRE		2	Jul 17, 2023	SYSTEM	(\$1,945.62)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		MIXTURE PG64-22 (SUR			3	Aug 2, 2023	SYSTEM	(\$17,249.28)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				(\$19,194.90)	
			Price FUEL	- Total				(\$19,194.90)	
	1040 -	· Total						(\$19,194.90)	
	1050	TACK COAT - NON-TRACKING	Material		2	Jul 17, 2023	SYSTEM	\$1,646.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$1,646.00)	
					3	Aug 2, 2023	SYSTEM	\$10,408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Aug 2, 2023	SYSTEM	(\$10,408.00)	
					4	Aug 16, 2023	SYSTEM	\$10,408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Aug 16, 2023	SYSTEM	(\$10,408.00)	
					5	Sep 5, 2023	SYSTEM	\$10,408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$10,408.00)	
					6	Sep 18, 2023	SYSTEM	\$10,408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stottt1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					6	Sep 18, 2023	SYSTEM	(\$10,408.00)	
				- Total				\$0.00	



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
10,000	20	2000.ipuo.i	Туре	Adjustment Type	Number	Date	Ву	7 1110 1111	, contains
SE0084	1050	TACK COAT - NON-TRACKING	Material - To	otal				\$0.00	
	1050 -	1050 - Total							
	1070	CONSTRUCTION SIGNS	Material		2	Jul 17, 2023	SYSTEM	\$5,889.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$5,889.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1070 -	· Total						\$0.00	
	1110	TYPE III MOVEABLE BARRICADE	Material		2	Jul 17, 2023	SYSTEM	\$870.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$870.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1110 -	· Total						\$0.00	
	1120	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material		2	Jul 17, 2023	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stottt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
		CONTE			2	Jul 17, 2023	SYSTEM	(\$6,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1120 -	· Total						\$0.00	
	1140	4 IN. WHITE WATERBORNE PAVEMENT	Other Item Adjustment	REFL	4	Aug 16, 2023	collie1	\$2,777.22	20% deduct for retroreflectivity
		MARKING		REFL - Tota	ıl			\$2,777.22	
			Other Item	Adjustment -	Total			\$2,777.22	
	1140 -	Total							
	1150	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		4	Aug 16, 2023	SYSTEM	\$2,716.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user collie1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		WARRING				Aug 16, 2023	SYSTEM	(\$2,716.56)	
				5	5	Sep 5, 2023	SYSTEM	\$2,716.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user collie1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$2,716.56)	
					6	Sep 18, 2023	SYSTEM	\$2,716.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stottt1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
						Sep 18, 2023	SYSTEM	(\$2,716.56)	
								\$0.00	
				- Total				Ψ0.00	
			Material - T					\$0.00	
			Material - To Other Item Adjustment		4	Aug 16, 2023	collie1		20% deduct for retroreflectivity
			Other Item	otal		Aug 16, 2023	collie1	\$0.00	20% deduct for retroreflectivity
			Other Item Adjustment	otal REFL	ıl	Aug 16, 2023	collie1	\$0.00 \$543.31	20% deduct for retroreflectivity
	1150 -	· Total	Other Item Adjustment	otal REFL REFL - Tota	ıl	Aug 16, 2023	collie1	\$0.00 \$543.31 \$543.31	20% deduct for retroreflectivity
	1150 - 1160	8 IN. WHITE WATERBORNE PAVEMENT	Other Item Adjustment	otal REFL REFL - Tota	ıl	Aug 16, 2023 Aug 16, 2023	collie1	\$0.00 \$543.31 \$543.31 \$543.31	20% deduct for retroreflectivity This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		8 IN. WHITE WATERBORNE	Other Item Adjustment	otal REFL REFL - Tota	l Total	2023 Aug 16,		\$0.00 \$543.31 \$543.31 \$543.31	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user collie1 overridding Payment





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSE0084	1160	8 IN. WHITE	Material						Estimate Exception 27 on the current Payment Estimate.
		WATERBORNE PAVEMENT MARKING			5	Sep 5, 2023	SYSTEM	(\$4,022.50)	
					6	Sep 18, 2023	SYSTEM	\$4,022.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					6	Sep 18, 2023	SYSTEM	(\$4,022.50)	
					7	Dec 4, 2023	SYSTEM	\$4,022.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user collie1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$4,022.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	REFL	4	Aug 16, 2023	collie1	\$804.50	20% deduct for retroreflectivity
				REFL - Tota	ıl			\$804.50	
			Other Item /	Adjustment -	Total			\$804.50	
	1160 -	Total						\$804.50	
JSE0084 -	- Total							(\$15,069.87)	
Overall -	Total							(\$107,383.13)	

MoDOT

Contract Adjustments for Contract - 230317-H03

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 29 of 29