

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 2, 2024

Progress Estimate 8	Number	Contract ID Prime Contracto	230317-H03 or Apex Paving Co		Period Start Period End	December 2 January 1, 2	024	Original Contract Amount Net Change Order Amount Current Contract Amount	\$8,566,286.74 \$37,281.00 \$8,603,567.74
Approval Date									By User
January 3, 2024			Generated and A	Approved	(and should	be considered	d Draft) a	at the Project Office Level by	stottt1
January 3, 2024		R	eviewed and Appro	ved (and	should be co	onsidered Dra	ft) at the	Resident Engineer Level by	stottt1
January 3, 2024			ı	Reviewed	and Approv	ed at the Cen	tral Offic	e Controllers Office Level by	ramses1
Original Completion	n Date	Current Con	npletion Date	Actu	ıal Completi	on Date	9	6 of Current Contract Amoun	nt Complete
October 1, 202	4	Octobe	r 1, 2024					38.03%	
	Contract	Informational Dat	es			Milestones			
Date Description	Original (	Completion Date	Current Completi	on Date	No Milesto	nes Exist for	Contract		
Acceptance Date									
Awarded Date	April 5, 20	)23	April 5, 2023						
Letting Date	March 17	, 2023	March 17, 2023						
Notice to Proceed Date	May 8, 20	23	May 8, 2023						

Contract Total Pa	y For Estimate No. 8			
		This Estimate	Previous	To Date
230317-H03				
	Total Posted Items Pay	\$56,024.99	\$3,215,679.59	\$3,271,704.58
	Gross Item Adjustments	\$0.00	(\$38,932.17)	(\$38,932.17)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	,		\$3,176,747.42	\$3,232,772.41
Contract Total Pag	yable This Estimate:	\$56,024.99		

#### Items Paid This Estimate Period

Open to Traffic Date

Work Began Date

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9S3528	0840	6161030	TYPE III MOVEABLE BARRICADE	EA	\$145.000	7	\$1,015.00
	0860	6181000	MOBILIZATION	LS	\$55,870.240	0.25	\$13,967.56
Project J9S3	528 - Total						\$14,982.56
JSE0084	1010	2159910	MISC.SHAPING SLOPES CLASS III - MODIFIED	100F	\$1,348.460	4	\$5,393.84
	1110	6161030	TYPE III MOVEABLE BARRICADE	EA	\$145.000	4	\$580.00
	1200	6061060	MGS GUARDRAIL	LF	\$33.690	175	\$5,895.75
	1210	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$4,146.390	4	\$16,585.56
	1220	6061080	MGS END ANCHOR	EA	\$1,794.450	1	\$1,794.45
	1230	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$3,597.610	3	\$10,792.83
Project JSE0	0084 - Total						\$41,042.43
Overall - Tot	al						\$56,024.99

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item /	Adjustr	nents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3528	0650	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-2,057.2	\$11.00	(\$22,629.20)
	0650	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	2,057.2	\$11.00	\$22,629.20

Revision 3/23/2023 Page 1 of 18



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 2, 2024

Progr	ess Es	timate Number Contract II Prime Con		317-H03 x Paving Co.	Pay Period End January 1, 2024 Net C	nal Contract A hange Order nt Contract A	Amount \$	\$8,566,286.74 \$37,281.00 \$8,603,567.74	
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
J9S3528					Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
	0680	TYPE A2 SHOULDER	Material			-707.5	\$94.00	(\$66,505.00)	
	0680	TYPE A2 SHOULDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	707.5	\$94.00	\$66,505.00	
	0720	CONCRETE PAVEMENT ( 9 IN. NON-REINF)	Material			-1,893.96	\$109.00	(\$206,441.64)	
	0720	CONCRETE PAVEMENT ( 9 IN. NON-REINF)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user collie1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	1,893.96	\$109.00	\$206,441.64	
	0770	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material			-250	\$14.00	(\$3,500.00)	
	0770	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	250	\$14.00	\$3,500.00	
	0790	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-30	\$14.00	(\$420.00)	
	0790	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	30	\$14.00	\$420.00	
	0800	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material			-120	\$18.00	(\$2,160.00)	
	0800	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	120	\$18.00	\$2,160.00	
	0810	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material			-60	\$15.00	(\$900.00)	
	0810	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	60	\$15.00	\$900.00	
JSE0084	1020	MISC.	Material			-4,037.4	\$54.77	(\$221,128.40)	
	1020	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	4,037.4	\$54.77	\$221,128.40	
	1030	GRAVEL (A) OR CRUSHED STONE (B)	Material			-90	\$54.78	(\$4,930.20)	

Revision 3/23/2023 Page 2 of 18



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 2, 2024

Progr	ess Es	timate Number 8	Contract II Prime Con		317-H03 ex Paving Co.	•	December 2, 2023 January 1, 2024	Net Ch	al Contract Anange Order	\$8,566,286.74 \$37,281.00 \$8,603,567.74	
Project Number	Line No.	Item Descri	ption	Adjustment Type	Other Item Adjustment Type	С	Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JSE0084	1030	GRAVEL (A) OR	CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate.			90	\$54.78	\$4,930.20
Total											\$0.00

Revision 3/23/2023 Page 3 of 18



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	n	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work	
J9S3326	FAS S703(28)	Resurface and bridge rehabilitation	162	NEW MADRID	from Route 25 near Cl	arkton to Route 61 near P	ortageville	
J9S3403	FAS S703(19)	Resurface	J	DUNKLIN	from Bus. 25 in Malde	n to Route 53		
J9S3528	FAS S704(27)	Resurface	84	PEMISCOT	from Route 412 to I-55	5		
JSE0084	FAS- S704(076)	Resurface	С	PEMISCOT	from Route 412 to Rou	ute 164		
Γotals by J	Job Number	s						
J9S3326		Item Pay Item Adjustme		tem Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$0.00 \$0.00 \$0.00	To Date \$0.00 \$0.00 \$0.00	
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	
J9S3403		Item Pay Item Adjustme		tem Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$0.00 \$0.00 \$0.00	To Date \$0.00 \$0.00 \$0.00	
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	
J9S3528		Item Pay Item Adjustme	nts Gross I	tem Pay	This Estimate \$14,982.56 \$0.00 \$14,982.56	Previous \$1,271,453.17 (\$23,862.30) \$1,247,590.87	To Date \$1,286,435.73 (\$23,862.30) \$1,262,573.43	
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	
JSE0084		Item Pay Item Adjustme		tem Pay	This Estimate \$41,042.43 \$0.00 \$41,042.43	Previous \$1,944,226.42 (\$15,069.87) \$1,929,156.55	To Date \$1,985,268.85 (\$15,069.87) \$1,970,198.98	
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	

Revision 3/23/2023 Page 4 of 18



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 3040506, Project Item Line Number 0650, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSE0084, Item 3049910, Project Item Line Number 1020, Material Set 304991096, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Explanation  Testing information is not complete.  Testing information is not complete.	Entered By collie1	Status
Number 0650, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSE0084, Item 3049910, Project Item Line Number 1020, Material Set 304991096, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.			Overridden
Number 1020, Material Set 304991096, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Testing information is not complete.	collie1	
			Overridden
Estimate Exception Type: Insufficient Materials: Project JSE0084, Item 3049910, Project Item Line Number 1020, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Testing information is not complete.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSE0084, Item 3105002, Project Item Line Number 1030, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Testing information is not complete.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 4010150, Project Item Line Number 0680, Material Set 401015096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Testing information is not complete.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 5021109, Project Item Line Number 0720, Material Set 502110996, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Testing information is not complete.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 5021109, Project Item Line Number 0720, Material Set 502110996, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Testing information is not complete.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 5021109, Project Item Line Number 0720, Material Set 502110996, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Testing information is not complete.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 5021109, Project Item Line Number 0720, Material Set 502110996, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Testing information is not complete.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131013, Project Item Line Number 0770, Material Set 613101396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Testing information is not complete.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131015, Project Item Line Number 0790, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Testing information is not complete.	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131017, Project Item Line Number 0800, Material Set 613101796, Material 1057JMDBEC6.11 - Dowel Bar Epoxy Ctd Gr60 1 1/4 @, Acceptance Action Generic ReinforcingMisc is insufficient.	Testing information is not complete.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131018, Project Item Line Number 0810, Material Set 613101896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Testing information is not complete.	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131018, Project Item Line Number 0810, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Testing information is not complete.	collie1	Overridden
Estimate Exception Type: Item Overrun: Contract 230317-H03, Contract Project J9S3528, Project Item Line Number 0650, Contract Line Item Number 0650, Item 3040506, Minor Item.	Awaiting change order.	collie1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230317-H03, Contract Project J9S3528, Project Item Line Number 0710, Contract Line Item Number 0710, Item 4071005, Minor Item.	Awaiting change order.	collie1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230317-H03, Contract Project J9S3528, Project Item Line Number 0730, Contract Line Item Number 0730, Item 6089902, Minor Item.	Awaiting change order.	collie1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230317-H03, Contract Project J9S3528, Project Item Line Number 0970, Contract Line Item Number 0970, Item 6221001, Minor Item.	Awaiting change order.	collie1	Acknowledged

Revision 3/23/2023 Page 5 of 18



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					eport Generated date and can differ from the posted amo							T
tract NTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
H03 J	J9S3326	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$27,328.20	\$0.00
		0001	0020	2153000	SHAPING SLOPES, CLASS III	25.00	0.00	25.00	100F	0.00	\$1,429.44	\$0.00
		0001	0030	3049910	MISC.PERMANENT AGGREGATE EDGE TREATEMENT	2,853.50	0.00	2,853.50	TONS	0.00	\$50.77	\$0.00
		0001	0040	3105002	GRAVEL (A) OR CRUSHED STONE (B)	110.00	0.00	110.00	TONS	0.00	\$50.79	\$0.00
		0001	0050	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	15,873.90	0.00	15,873.90	TONS	0.00	\$92.98	\$0.00
		0001	0060	4071005	LEVELING) TACK COAT	19,559.00	0.00	19,559.00	GAL	0.00	\$1.00	\$0.00
		0001	0070	4091048	EMULSIFIED ASPHALT, SEAL COAT	210.00	0.00	210.00	GAL	0.00	\$14.28	\$0.00
		0001	0080	4094011	SEAL COAT AGGREGATE, GRADE B1	564.00	0.00	564.00	SQYD	0.00	\$7.00	\$0.00
		0001	0090	6083003	3 IN. CONCRETE MEDIAN STRIP	86.00	0.00	86.00	SQYD	0.00	\$110.00	\$0.00
		0001	0100	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	4.00	0.00	4.00	EA	0.00	\$4,800.00	\$0.00
		0001	0110	6122030	IMPACT ATTENUATOR (RELOCATION)	16.00	0.00	16.00	EA	0.00	\$2,000.00	\$0.00
		0001	0120	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	0.00	\$0.00	\$0.00
		0001	0130	6161005	CONSTRUCTION SIGNS	1,633.00	0.00	1,633.00	SQFT	0.00	\$6.00	\$0.00
		0001	0140	6161025	CHANNELIZER (TRIM LINE)	120.00	0.00	120.00	EA	0.00	\$24.00	\$0.00
		0001	0150	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	2.00	0.00	2.00	EA	0.00	\$4,500.00	\$0.00
		0001	0160	6181000	RETAINED  MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$243,470.98	\$0.00
		0001	0170	6200013	COLD APPLIED TAPE PAVEMENT MARKING, 24 IN. WHITE	44.00	0.00	44.00	LF	0.00	\$25.00	\$0.00
		0001	0180	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	2.00	0.00	2.00	EA	0.00	\$1,500.00	\$0.00
		0001	0190	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	11,600.00	0.00	11,600.00	LF	0.00	\$1.50	\$0.00
		0001	0200	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	10,000.00	0.00	10,000.00	LF	0.00	\$1.50	\$0.00
		0001	0210	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	120.00	0.00	120.00	LF	0.00	\$9.00	\$0.00
		0001	0220	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	199,134.00	0.00	199,134.00	LF	0.00	\$0.13	\$0.00
		0001	0230	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	50,880.00	0.00	50,880.00	LF	0.00	\$0.13	\$0.00
		0001	0240	6207001	PAVEMENT MARKING REMOVAL	29,540.00	0.00	29,540.00	LF	0.00	\$0.50	\$0.00
		0001	0250	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	8,590.00	0.00	8,590.00	SQYD	0.00	\$5.45	\$0.00
		0001	0260	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	8,957.00	0.00	8,957.00	SQYD	0.00	\$7.86	\$0.00
		0001	0270	7250424	24 IN. PIPE GROUP C	27.00	0.00	27.00	LF	0.00	\$125.00	\$0.00
		0001	0280	7250436	36 IN. PIPE GROUP C	48.00	0.00	48.00	LF	0.00	\$160.00	\$0.00
		0010	0290	6061060	MGS GUARDRAIL	1,100.00	0.00	1,100.00	LF	0.00	\$32.61	\$0.00
		0010	0300	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	33.00	0.00	33.00	EA	0.00	\$4,039.56	\$0.00
		0010	0310	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	0.00	\$1,456.42	\$0.00
		0010	0320	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	31.00	0.00	31.00	EA	0.00	\$3,659.09	\$0.00
		0010	0330	6063020	TYPE C CRASHWORTHY END TERMINAL (MASH)	7.00	0.00	7.00	EA	0.00	\$32,013.57	\$0.00
		0030	0340	9029400	TEMPORARY TRAFFIC SIGNALS	4.00	0.00	4.00	LS	0.00	\$0.00	\$0.00
		0070	0350	7034600	CURB BLOCKOUT	244.00	0.00	244.00	LF	0.00	\$143.00	\$0.00
		0071	0360	7034600	CURB BLOCKOUT	274.00	0.00	274.00	LF	0.00	\$130.00	\$0.00
		0072	0370	7034600	CURB BLOCKOUT	265.00	0.00	265.00	LF	0.00	\$133.00	\$0.00
		0073	0380	7034600	CURB BLOCKOUT	315.00	0.00	315.00	LF	0.00	\$115.00	\$0.00
		0074	0390	7034600	CURB BLOCKOUT	280.00	0.00	280.00	LF	0.00	\$127.00	\$0.00
F	Project J9	S3326 - To	otal Value	Posted to D	ate as of Report Generated Date							\$0.00
J	19S3403	0001	0400	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$5,056.58	\$0.00
		0001	0410	2129903	MISC.SHOULDER GRADING	108,504.00	0.00	108,504.00	LF	0.00	\$0.97	\$0.00
		0001	0420	2153000	SHAPING SLOPES, CLASS III	3.00	0.00	3.00	100F	0.00	\$1,252.05	\$0.00

Page 6 of 18 Revision 3/23/2023



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT					eport Generated date and can differ from the posted amo	unit at the t	iiiic tiic t	_Sumate wa	o Como	aicu.		
	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230317-H03	J9S3403	0001	0440	3105002	GRAVEL (A) OR CRUSHED STONE (B)	22.00	0.00	22.00	TONS	0.00	\$52.58	\$0.00
		0001	0450	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	5,305.00	0.00	5,305.00	TONS	0.00	\$94.63	\$0.00
		0001	0460	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	12,264.80	0.00	12,264.80	TONS	0.00	\$88.96	\$0.00
		0001	0470	4071005	TACK COAT	14,889.00	0.00	14,889.00	GAL	0.00	\$1.00	\$0.00
		0001	0480	4091048	EMULSIFIED ASPHALT, SEAL COAT	255.00	0.00	255.00	GAL	0.00	\$12.99	\$0.00
		0001	0490	4094011	SEAL COAT AGGREGATE, GRADE B1	671.00	0.00	671.00	SQYD	0.00	\$7.00	\$0.00
		0001	0500	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$0.00	\$0.00
		0001	0510	6161005	CONSTRUCTION SIGNS	1,765.00	0.00	1,765.00	SQFT	0.00	\$6.00	\$0.00
		0001	0520	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	0.00	\$22.00	\$0.00
		0001	0530	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$124,218.63	\$0.00
		0001	0540	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	120,422.00	0.00	120,422.00	LF	0.00	\$0.13	\$0.00
		0001	0550	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT. TYPE P BEADS	28,692.00	0.00	28,692.00	LF	0.00	\$0.14	\$0.00
		0001	0560	6206108A	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	920.00	0.00	920.00	LF	0.00	\$1.00	\$0.00
		0001	0570	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,053.00	0.00	1,053.00	SQYD	0.00	\$7.61	\$0.00
		0001	0580	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	4,783.00	0.00	4,783.00	SQYD	0.00	\$9.83	\$0.00
		0001	0590	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,147.30	0.00	1,147.30	STA	0.00	\$17.50	\$0.00
		0010	0600	6061060	MGS GUARDRAIL	150.00	0.00	150.00	LF	0.00	\$40.47	\$0.00
		0010	0610	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	0.00	\$4,146.39	\$0.00
		0010	0620	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$3,430.71	\$0.00
	Project J	9S3403 - To	tal Value	Posted to D	ate as of Report Generated Date							\$0.00
	J9S3528	0001	0630	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$12,000.00	\$12,000.00
			0000	2022010		1.00						*,
		0001	0640	2129903	MISC.SHOULDER GRADING	6,723.00	0.00	6,723.00	LF	625.00	\$3.90	
					MISC.SHOULDER GRADING  TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)						\$3.90 \$11.00	\$2,437.50
		0001	0640	2129903		6,723.00	0.00	6,723.00	LF	625.00		\$2,437.50 \$22,629.20
		0001	0640 0650	2129903 3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	6,723.00 1,750.00	0.00	6,723.00 1,750.00	LF SQYD	625.00 2,057.20	\$11.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00
		0001 0001 0001	0640 0650 0660	2129903 3040506 3049910	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) MISC.PERMANENT AGGREGATE EDGE TREATMENT	6,723.00 1,750.00 380.50	0.00	6,723.00 1,750.00 380.50	LF SQYD TONS	625.00 2,057.20 380.50	\$11.00 \$69.32	\$2,437.50 \$22,629.20 \$26,376.26
		0001 0001 0001 0001	0640 0650 0660 0670	2129903 3040506 3049910 3105002	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)	6,723.00 1,750.00 380.50 13.00	0.00 0.00 0.00 0.00	6,723.00 1,750.00 380.50 13.00	LF SQYD TONS TONS	625.00 2,057.20 380.50 0.00	\$11.00 \$69.32 \$69.34	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00
		0001 0001 0001 0001 0001	0640 0650 0660 0670 0680	2129903 3040506 3049910 3105002 4010150	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER	6,723.00 1,750.00 380.50 13.00 556.00	0.00 0.00 0.00 0.00 151.50	6,723.00 1,750.00 380.50 13.00 707.50	LF SQYD TONS TONS SQYD	625.00 2,057.20 380.50 0.00 707.50	\$11.00 \$69.32 \$69.34 \$94.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06
		0001 0001 0001 0001 0001	0640 0650 0660 0670 0680	2129903 3040506 3049910 3105002 4010150 4011209	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70	0.00 0.00 0.00 0.00 151.50	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70	LF SQYD TONS TONS SQYD	625.00 2,057.20 380.50 0.00 707.50 5,573.69	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48
		0001 0001 0001 0001 0001 0001	0640 0650 0660 0670 0680 0690	2129903 3040506 3049910 3105002 4010150 4011209 4013000	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00	0.00 0.00 0.00 0.00 151.50 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00	LF SQYD TONS TONS SQYD TONS TONS	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48
		0001 0001 0001 0001 0001 0001 0001	0640 0650 0660 0670 0680 0690 0700	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC. PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00	LF SQYD TONS TONS SQYD TONS TONS GAL	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0670 0680 0690 0700 0710	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT (9 IN. NON-REINF)	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 0.0	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00	LF SQYD TONS TONS SQYD TONS TONS GAL SQYD	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0670 0680 0690 0710 0720	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT (9 IN. NON-REINF)  MISC.ADA CURB RAMP	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00	LF SQYD TONS TONS SQYD TONS TONS GAL SQYD EA	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0670 0680 0690 0700 0710 0720 0730	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT ( 9 IN. NON-REINF)  MISC.ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 8.00	0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 12.00	LF SQYD TONS TONS SQYD TONS TONS GAL SQYD EA	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00 \$0.00
		0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	0640 0650 0660 0670 0680 0690 0710 0720 0730 0740	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A 6131010	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT (9 IN. NON-REINF)  MISC.ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 8.00 2.00 250.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 2.00 250.00	LF SQYD TONS TONS SQYD TONS TONS GAL SQYD EA SQYD	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00 0.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00 \$331.58	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00 \$0.00 \$82,895.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0670 0680 0690 0710 0720 0730 0740 0750	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A 6131010	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT (9 IN. NON-REINF)  MISC.ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL  DEPTH PAVEMENT REPAIR  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)  TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 8.00 2.00 250.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00 0.00 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 2.00 250.00	LF SQYD TONS TONS SQYD TONS TONS GAL SQYD EA SQYD	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00 0.00 250.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00 \$331.58	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00 \$0.00 \$82,895.00 \$3,750.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0660 0660 0670 0680 0700 0710 0720 0730 0750 0760	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A 6131010 6131012 6131013	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC. PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT ( 9 IN. NON-REINF)  MISC. ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL  DEPTH PAVEMENT REPAIR  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)  TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)  (PAVEMENT REPAIR)  FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 2.00 250.00 250.00	0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00 0.00 0.00 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 2.00 250.00 250.00	LF SQYD TONS TONS SQYD TONS GAL SQYD EA SQYD SQYD SQYD	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00 0.00 250.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00 \$331.58 \$15.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00 \$0.00 \$82,895.00 \$3,750.00 \$5,532.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0670 0680 0690 0710 0720 0730 0740 0750 0770 0770	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A 6131010 6131012 6131013	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT (9 IN. NON-REINF)  MISC.ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL  DEPTH PAVEMENT REPAIR  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)  TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)  (PAVEMENT REPAIR)  FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER  AND INTERNAL SAW CUTS)  DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION)	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 8.00 250.00 250.00 461.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00 0.00 0.00 0.00 0.00 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 2.00 250.00 250.00 461.00	LF SQYD TONS TONS SQYD TONS TONS GAL SQYD EA SQYD SQYD SQYD LF	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00 0.00 250.00 250.00 461.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00 \$331.58 \$15.00 \$14.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00 \$0.00 \$82,895.00 \$3,750.00 \$5,532.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0660 0670 0680 0700 0710 0720 0730 0740 0750 0770 0780	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A 6131010 6131012 6131013 6131014 6131015	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC. PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT ( 9 IN. NON-REINF)  MISC. ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR)  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)  TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)  (PAVEMENT REPAIR)  FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)  DOWEL BAR (FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR  DOWEL BAR (FURNISHING AND INSTALLATION WITH	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 250.00 250.00 250.00 461.00 30.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00 0.00 0.00 0.00 0.00 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 250.00 250.00 250.00 461.00	LF SQYD TONS TONS SQYD TONS GAL SQYD EA SQYD SQYD SQYD SQYD LF EA	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00 0.00 250.00 250.00 250.00 461.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00 \$331.58 \$15.00 \$14.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00 \$3,750.00 \$3,750.00 \$5,532.00 \$420.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0660 0670 0680 0700 0710 0720 0730 0760 0770 0780 0790	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A 6131010 6131013 6131014 6131015 6131017	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT (9 IN. NON-REINF)  MISC.ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)  TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)  (PAVEMENT REPAIR)  FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)  DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR  TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 8.00 250.00 250.00 461.00 30.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 160.00 0.00 0.00 0.00 0.00 0	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 250.00 250.00 250.00 461.00 30.00	LF SQYD TONS TONS SQYD TONS TONS GAL SQYD EA SQYD SQYD SQYD LF EA EA	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00 250.00 250.00 461.00 30.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00 \$331.58 \$15.00 \$14.00 \$14.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00 \$3,750.00 \$3,750.00 \$5,532.00 \$420.00 \$2,160.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0660 0670 0680 0700 0710 0720 0730 0740 0750 0770 0780 0790 0800	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A 6131010 6131013 6131014 6131015 6131017 6131018	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT (9 IN. NON-REINF)  MISC.ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)  TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)  (PAVEMENT REPAIR)  FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)  DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR  TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR  TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR  TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 2.00 250.00 250.00 461.00 30.00 120.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00 0.00 0.00 0.00 0.00 0.00 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 250.00 250.00 250.00 461.00 30.00 120.00	LF SQYD TONS TONS SQYD TONS GAL SQYD EA SQYD SQYD LF EA EA EA	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00 250.00 250.00 461.00 30.00 120.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00 \$331.58 \$15.00 \$14.00 \$14.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00 \$3,750.00 \$3,750.00 \$420.00 \$420.00 \$3,841.50
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0660 0670 0680 0700 0710 0720 0730 0760 0770 0780 0800 0810	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A 6131010 6131013 6131014 6131015 6131017 6131018	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC. PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT ( 9 IN. NON-REINF)  MISC. ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)  TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)  (PAVEMENT REPAIR)  FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)  DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR  DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR  TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)  CONSTRUCTION SIGNS	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 250.00 250.00 250.00 461.00 30.00 1,368.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00 0.00 0.00 0.00 0.00 0.00 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 250.00 250.00 250.00 461.00 30.00 120.00 60.00 1,368.00	LF SQYD TONS TONS SQYD TONS TONS GAL SQYD EA SQYD SQYD LF EA EA EA SQFT	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00 250.00 250.00 461.00 30.00 120.00 60.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00 \$331.58 \$15.00 \$14.00 \$14.00 \$18.00 \$15.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00

Page 7 of 18 Revision 3/23/2023



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category		Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230317-H03	J9S3528	0001	0860	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$55,870.24	\$55,870.24
		0001	0870	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	50.00	0.00	50.00	LF	0.00	\$6.00	\$0.00
		0001	0880	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	232.00	0.00	232.00	LF	0.00	\$25.00	\$0.00
		0001	0890	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	100.00	0.00	100.00	LF	0.00	\$25.00	\$0.00
		0001	0900	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	19.00	0.00	19.00	EA	0.00	\$275.00	\$0.00
		0001	0910	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	2.00	0.00	2.00	EA	0.00	\$1,500.00	\$0.00
		0001	0920	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	874.00	0.00	874.00	LF	0.00	\$1.50	\$0.00
		0001	0930	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	4,476.00	0.00	4,476.00	LF	0.00	\$1.50	\$0.00
		0001	0940	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	28,259.00	0.00	28,259.00	LF	0.00	\$0.14	\$0.0
		0001	0950	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	17,307.00	0.00	17,307.00	LF	0.00	\$0.20	\$0.0
		0001	0960	6207001	PAVEMENT MARKING REMOVAL	5,350.00	0.00	5,350.00	LF	0.00	\$1.00	\$0.0
		0001	0970	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	6,130.00	0.00	6,130.00	SQYD	7,058.32	\$7.37	\$52,019.8
		0001	0980	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	7,541.00	0.00	7,541.00	SQYD	3,434.81	\$4.85	\$16,658.8
		0001	0990	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	61.00	0.00	61.00	STA	0.00	\$36.03	\$0.0
	Project J	9S3528 - To	otal Value	Posted to D	ate as of Report Generated Date							\$1,286,435.73
	JSE0084	0001	1000	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$8,323.57	\$0.00
		0001	1010	2159910	MISC.SHAPING SLOPES CLASS III - MODIFIED	4.00	0.00	4.00	100F	4.00	\$1,348.46	\$5,393.8
		0001	1020	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	4,037.40	0.00	4,037.40	TONS	4,037.40	\$54.77	\$221,128.4
		0001	1030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	90.00	0.00	90.00	TONS	90.00	\$54.78	\$4,930.2
		0001	1040	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	17,336.40	0.00	17,336.40	TONS	16,059.99	\$96.54	\$1,550,431.4
		0001	1050	4071007	TACK COAT - LOW OR NON-TRACKING	18,331.00	0.00	18,331.00	GAL	10,408.00	\$1.00	\$10,408.0
		0001	1060	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$0.00	\$0.0
		0001	1070	6161005	CONSTRUCTION SIGNS	1,189.00	0.00	1,189.00	SQFT	906.00	\$6.50	\$5,889.0
		0001	1080	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	0.00	\$45.00	\$0.0
		0001	1090	6161010	RELOCATED SIGNS	476.00	0.00	476.00	SQFT	0.00	\$6.50	\$0.0
		0001	1100	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	0.00	\$24.00	\$0.0
		0001	1110	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$145.00	\$1,450.0
		0001	1120	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.0
		0001	1130	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$63,827.62	\$63,827.6
		0001	1140	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	106,816.00	0.00	106,816.00	LF	106,816.00	\$0.13	\$13,886.0
		0001	1150	6206001C		15,092.00	0.00	15,092.00	LF	15,092.00	\$0.18	\$2,716.5
		0001	1160	6206108A	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	8,045.00	0.00	8,045.00	LF	8,045.00	\$0.50	\$4,022.5
		0001	1170	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,348.00	0.00	1,348.00	SQYD	481.67	\$10.84	\$5,221.3
		0001	1180	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	856.00	0.00	856.00	SQYD	856.00	\$41.26	\$35,318.5
		0001	1190	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	5,430.00	0.00	5,430.00	SQYD	2,425.87	\$8.07	\$19,576.7
		0010	1200	6061060	MGS GUARDRAIL	175.00	0.00	175.00	LF	175.00	\$33.69	\$5,895.7
		0010	1210	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$4,146.39	\$16,585.5
		0010	1220	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	1.00	\$1,794.45	\$1,794.4
		0010	1230	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3.00	0.00	3.00	EA	3.00	\$3,597.61	\$10,792.8
	Project JS	SE0084 - <u>To</u>	otal Val <u>u</u> e	e Posted to D	Date as of Report Generated Date							\$1,985,268.8
20247 1102 000					ort Generated Date							\$3,271,704.58

Page 8 of 18 Revision 3/23/2023



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

#### Project: J9S3528

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location		Offset/ Distance		Offset/ Distance	Comments
0840	6161030	TYPE III MOVEABLE BARRICADE	12/27/23	1/2/24	7.00	EA	Route 84	0		0		Route 84
0860	6181000	MOBILIZATION	12/28/23	1/2/24	0.25	LS	Route 412	0		0		Remainder of mobilizati

#### Project: JSE0084

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
1010	2159910	MISC. SHAPING SLOPES	12/28/23	1/2/24	4.00	100F	Bridge A4412 on Route C	0		0		Bridge A4412 on Route C for guardrail installation
1110	6161030	TYPE III MOVEABLE BARRICADE	12/27/23	1/2/24	4.00	EA	Route C	0		0		Route C
1200	6061060	MGS GUARDRAIL	12/28/23	1/2/24	175.00	LF	Bridge A4412 on Route C	0		0		Bridge A4412 on Route C
1210	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	12/28/23	1/2/24	4.00	EA	Bridge A4412 on Route C	0		0		Bridge A4412 on Route C
1220	6061080	MGS END ANCHOR	12/28/23	1/2/24	1.00	EA	Bridge A4412 on Route C	0		0		Bridge A4412 on Route C
1230	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	12/28/23	1/2/24	3.00	EA	Bridge A4412 on Route C	0		0		Bridge A4412 on Route C

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 9 of 18



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
528	0650	TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		4	Aug 16, 2023	SYSTEM	\$19,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
		THICK)			4	Aug 16, 2023	SYSTEM	(\$19,250.00)							
					5	Sep 5, 2023	SYSTEM	\$22,629.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					5	Sep 5, 2023	SYSTEM	(\$22,629.20)							
					6	Sep 18, 2023	SYSTEM	\$22,629.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
											6	Sep 18, 2023	SYSTEM	(\$22,629.20)	
						7	Dec 4, 2023	SYSTEM	\$22,629.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					7	Dec 4, 2023	SYSTEM	(\$22,629.20)							
					8	Jan 2, 2024	SYSTEM	\$22,629.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					8	Jan 2, 2024	SYSTEM	(\$22,629.20)							
				- Total				\$0.00							
			Material - T					\$0.00							
			Overrun	Overrun	5	Sep 5, 2023	SYSTEM	(\$3,394.04)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL						
				Overrun - T	otal			(\$3,394.04)							
			Overrun - T	otal				(\$3,394.04)							
			Price FUEL		4	Aug 16, 2023	SYSTEM	\$84.52	Reference Item Price Adjustment Index Adjustment Type applied is FUEL						
					5	Sep 5, 2023	SYSTEM	\$14.84	Reference Item Price Adjustment Index Adjustment Type applied is FUEL						
				- Total				\$99.36							
			Price FUEL	- Total				\$99.36							
	0650 -							(\$3,294.68)							
	0660	MISC. AGGREGATE FOR BASE	Material		4	Aug 16, 2023	SYSTEM	\$26,376.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 5 on the current Payment Estimate.						
					4	Aug 16, 2023	SYSTEM	(\$26,376.26)							
					5	Sep 5, 2023	SYSTEM	\$26,376.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user collie1 overridding Payment Estimate Exception 5 on the current Payment Estimate.						
					5	Sep 5, 2023	SYSTEM	(\$26,376.26)							
					6	Sep 18, 2023	SYSTEM	\$26,376.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stottt1 overridding Payment Estimate Exception 5 on the current Payment Estimate.						
					6	Sep 18, 2023	SYSTEM	(\$26,376.26)							
				- Total				\$0.00							
			Material - To	otal				\$0.00							
J	0660 -							\$0.00							
	0680	TYPE A2 SHOULDER	Material		6	Sep 18, 2023	SYSTEM	\$52,264.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
					6	Sep 18, 2023	SYSTEM	(\$52,264.00)							
					7	Dec 4, 2023	SYSTEM	\$66,505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Exception 5 on the current Payment Estimate.						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
9S3528	0680	TYPE A2 SHOULDER	Material		7	Dec 4, 2023	SYSTEM	(\$66,505.00)	
					8	Jan 2, 2024	SYSTEM	\$66,505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Jan 2, 2024	SYSTEM	(\$66,505.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	FUEL	7	Dec 4, 2023	collie1	(\$1.48)	Items were paid during the incorrect pay period. This amount was removed to correct the Fuel Adjustment.
					7	Dec 4, 2023	collie1	\$15.59	This is the Fuel Index calculated for when work was actually completed.
				FUEL - Tota	ıl			\$14.11	
			Other Item A	Adjustment -	Total			\$14.11	
			Price FUEL		6	Sep 18, 2023	SYSTEM	\$2.51	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Dec 4, 2023	SYSTEM	\$1.48	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$3.99	
			Price FUEL	- Total				\$3.99	
	0680 -	Total						\$18.10	
	0690	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	E FUEL		1	Jun 30, 2023	SYSTEM	(\$4,619.45)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					3	Aug 2, 2023	SYSTEM	(\$722.39)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				(\$5,341.84)	
			Price FUEL	- Total				(\$5,341.84)	
	0690 -	Total						(\$5,341.84)	
	0700	BITUMINOUS PAVEMENT MIXTURE	Price FUEL		1	Jun 30, 2023	SYSTEM	(\$435.63)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		PG64-22 (BAS		- Total				(\$435.63)	
	0700	Total	Price FUEL	- Total				(\$435.63)	
	0700 - 0710	TACK COAT	Material		1	Jun 30, 2023	SYSTEM	(\$435.63) \$12,342.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment
					1	Jun 30,	SYSTEM	(\$12,342.00)	Estimate Exception 1 on the current Payment Estimate.
						2023			
					2	Jul 17, 2023	SYSTEM	\$12,342.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$12,342.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	1	Jun 30, 2023	SYSTEM	(\$1,394.85)	
					3	Aug 2, 2023	SYSTEM	(\$1,234.20)	
				Overrun - T	otal			(\$2,629.05)	
			Overrun - To	otal				(\$2,629.05)	
	0710 -	Total						(\$2,629.05)	
	0720	CONCRETE PAVEMENT ( 9 IN. NON-REINF)	Material		5	Sep 5, 2023	SYSTEM	\$189,001.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		,			5	Sep 5, 2023	SYSTEM	(\$189,001.64)	
					6	Sep 18, 2023	SYSTEM	\$189,001.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stottt1 overridding Payment Estimate Exception 10 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J9S3528	0720	CONCRETE PAVEMENT ( 9 IN.	Material		6	Sep 18, 2023	SYSTEM	(\$189,001.64)															
		NON-REINF)			7	Dec 4, 2023	SYSTEM	\$206,441.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 6 on the current Payment Estimate.														
					7	Dec 4, 2023	SYSTEM	(\$206,441.64)															
					8	Jan 2, 2024	SYSTEM	\$206,441.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user collie1 overridding Payment Estimate Exception 6 on the current Payment Estimate.														
					8	Jan 2, 2024	SYSTEM	(\$206,441.64)															
				- Total				\$0.00															
			Material - To	otal				\$0.00															
			Other Item Adjustment	FUEL	7	Dec 4, 2023	collie1	(\$98.21)	Items were paid during the incorrect pay period. This amount was removed to correct the Fuel Adjustment.														
					7	Dec 4, 2023	collie1	\$22.18	This is the Fuel Index calculated for when work was actually completed.														
				FUEL - Tota	ıl			(\$76.03)															
			Other Item A	Adjustment -	Total			(\$76.03)															
			Price FUEL		5	Sep 5, 2023	SYSTEM	\$240.34	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
					7	Dec 4, 2023	SYSTEM	\$98.21	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
				- Total				\$338.55															
			Price FUEL	- Total				\$338.55															
	0720 -							\$262.52															
	0730	MISC. CONCRETE	Overrun	Overrun		Sep 18, 2023	SYSTEM	(\$5,600.00)															
			O	Overrun - T	otal			(\$5,600.00)															
	0730 -	Total	Overrun - To	otai				(\$5,600.00)															
	0750	FURN & PLACE CONC MATL FOR FULL DEPTH	8		5	Sep 5, 2023	SYSTEM	\$82,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user collie1 overridding Payment Estimate Exception 15 on the current Payment Estimate.														
					5	Sep 5, 2023	SYSTEM	(\$82,895.00)															
					6	Sep 18, 2023	SYSTEM	\$82,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stottt1 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
					6	Sep 18, 2023	SYSTEM	(\$82,895.00)															
																				7	Dec 4, 2023	SYSTEM	\$82,895.00
					7	Dec 4, 2023	SYSTEM	(\$82,895.00)															
				- Total				\$0.00															
			Material - To	otal				\$0.00															
	0750 -	Total						\$0.00															
	0770	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. TH	Material		5	Sep 5, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user collie1 overridding Payment Estimate Exception 18 on the current Payment Estimate.														
		IH			5	Sep 5, 2023	SYSTEM	(\$3,500.00)															
					6	Sep 18, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stottt1 overridding Payment Estimate Exception 19 on the current Payment Estimate.														
					6	Sep 18, 2023	SYSTEM	(\$3,500.00)															
					7	Dec 4, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user collie1 overridding Payment Estimate Exception 11 on the current Payment Estimate.														



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																			
3528	0770	TYPE 1 OR 5 AGGREGATE	Material		7	Dec 4, 2023	SYSTEM	(\$3,500.00)																				
		FOR BASE (4 IN. TH			8	Jan 2, 2024	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																			
					8	Jan 2, 2024	SYSTEM	(\$3,500.00)																				
				- Total				\$0.00																				
			Material - To	otal				\$0.00																				
	0770 -	· Total						\$0.00																				
	0790	DOWEL BAR (DRILLING, FURNISHING AND INST	Material		5	Sep 5, 2023	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user collie1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																			
					5	Sep 5, 2023	SYSTEM	(\$420.00)																				
					6	Sep 18, 2023	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stottt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																			
					6	Sep 18, 2023	SYSTEM	(\$420.00)																				
					7	Dec 4, 2023	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment Estimate Exception 12 on the current Payment Estimate.																			
															7	Dec 4, 2023	SYSTEM	(\$420.00)										
					8	Jan 3, 2024	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.																			
					8	Jan 2, 2024	SYSTEM	(\$420.00)																				
				- Total				\$0.00																				
			Material - To	otal				\$0.00																				
	0790 -	· Total						\$0.00																				
	0800	DOWEL BAR (FURNISH AND INSTALL WITH BASK	Material		5	Sep 5, 2023	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user collie1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																			
		DASK		6	5	Sep 5, 2023	SYSTEM	(\$2,160.00)																				
					6	Sep 18, 2023	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stottt1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																			
					6	Sep 18, 2023	SYSTEM	(\$2,160.00)																				
														7	Dec 4, 2023	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user collie1 overridding Payment Estimate Exception 14 on the current Payment Estimate.										
																							7	7	Dec 4, 2023	SYSTEM	(\$2,160.00)	
																										01/0==1/		
					8	Jan 2, 2024	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 12 on the current Payment Estimate.																			
					8		SYSTEM	(\$2,160.00)	Estimate Item Adjustment (0008) due to user collie1 overridding Payment																			
				- Total		2024 Jan 2,			Estimate Item Adjustment (0008) due to user collie1 overridding Payment																			
			Material - T			2024 Jan 2,		(\$2,160.00)	Estimate Item Adjustment (0008) due to user collie1 overridding Payment																			
	0800 -	· Total	Material - To			2024 Jan 2,		(\$2,160.00)	Estimate Item Adjustment (0008) due to user collie1 overridding Payment																			
	0800 - 0810	Total  TIE BAR (DRILL, FURN & INSTAL) (TYPE L	Material - To			2024 Jan 2,		(\$2,160.00) \$0.00 \$0.00	Estimate Item Adjustment (0008) due to user collie1 overridding Payment																			
		TIE BAR (DRILL, FURN & INSTAL)			8	Jan 2, 2024  Sep 5,	SYSTEM	(\$2,160.00) \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user collie1 overridding Payment																			



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks	
1000000	00:0	TIE DAG (SS)		Туре		0 10	0)/0==-	(0-2-2		
J9S3528	0810	TIE BAR (DRILL, FURN & INSTAL)	Material		6	Sep 18, 2023	SYSTEM	(\$900.00)		
		(TYPE L			7	Dec 4, 2023	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user collie1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
					7	Dec 4, 2023	SYSTEM	(\$900.00)		
					8	Jan 2, 2024	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
					8	Jan 2, 2024	SYSTEM	(\$900.00)		
				- Total		2024		\$0.00		
			Material - To					\$0.00		
	0810 -	Total	Material - 10	otai				\$0.00		
							OVOTEN		Title of the second of the sec	
	0820	CONSTRUCTION SIGNS	Material		1	Jun 30, 2023	SYSTEM	\$3,841.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user collie1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					1	Jun 30, 2023	SYSTEM	(\$3,841.50)		
					2	Jul 17, 2023	SYSTEM	\$3,841.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					2	Jul 17, 2023	SYSTEM	(\$3,841.50)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0820 -	Total						\$0.00		
	0830	CHANNELIZER (TRIM LINE)	Material	Material		1	Jun 30, 2023	SYSTEM	\$1,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Jun 30, 2023	SYSTEM	(\$1,560.00)		
					2	Jul 17, 2023	SYSTEM	\$1,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stottt1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					2	Jul 17, 2023	SYSTEM	(\$1,560.00)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0830 -	Total						\$0.00		
	0850	CMS W/O COMMUNICATION INTERFACE,	Material		1	Jun 30, 2023	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
		CONT F/			1	Jun 30, 2023	SYSTEM	(\$9,000.00)		
					2	Jul 17, 2023	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stottt1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					2	Jul 17, 2023	SYSTEM	(\$9,000.00)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0850 -	Total						\$0.00		
	0970	COLDMILLING BIT. PAVT FOR	Overrun	Overrun	1	Jun 30, 2023	SYSTEM	(\$6,841.72)		
		REM OF SURF.		Overrun - T	otal			(\$6,841.72)		
			Overrun - T	otal				(\$6,841.72)		
	0970 -	Total						(\$6,841.72)		
J9S3528 -	- Total							(\$23,862.30)		
JSE0084	1020	MISC. AGGREGATE	Material		4	Aug 16, 2023	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment	



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks	
				Type			,			
JSE0084	1020	FOR BASE	Material		4	A 40	OVOTEM	(0004 400 40)	Estimate Exception 3 on the current Payment Estimate.	
					4	Aug 16, 2023	SYSTEM	(\$221,128.40)		
					5	Sep 5, 2023	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					5	Sep 5, 2023	SYSTEM	(\$221,128.40)		
					6	Sep 18, 2023	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					6	Sep 18, 2023	SYSTEM	(\$221,128.40)		
					7	Dec 4, 2023	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					7	Dec 4, 2023	SYSTEM	(\$221,128.40)		
					8	Jan 2, 2024	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					8	Jan 2, 2024	SYSTEM	(\$221,128.40)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
		· Total						\$0.00		
	1030	GRAVEL (A) OR CRUSHED STONE (B)	Material		4	Aug 16, 2023	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					4	Aug 16, 2023	SYSTEM	(\$4,930.20)		
					5	Sep 5, 2023	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user collie1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
							5	Sep 5, 2023	SYSTEM	(\$4,930.20)
					6	Sep 18, 2023	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					6	Sep 18, 2023	SYSTEM	(\$4,930.20)		
					7	Dec 4, 2023	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					7	Dec 4, 2023	SYSTEM	(\$4,930.20)		
					8	Jan 2, 2024	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					8	Jan 2, 2024	SYSTEM	(\$4,930.20)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
		· Total					a).(a)==:	\$0.00		
	1040	BITUMINOUS PAVEMENT MIXTURE	Price FUEL		2	Jul 17, 2023	SYSTEM	(\$1,945.62)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
		PG64-22 (SUR			3	Aug 2, 2023	SYSTEM	(\$17,249.28)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
				- Total				(\$19,194.90)		
			Price FUEL	- Total				(\$19,194.90)		
		· Total						(\$19,194.90)		
	1050	TACK COAT - LOW OR NON- TRACKING	Material		2	Jul 17, 2023	SYSTEM	\$1,646.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
84	1050	TACK COAT - LOW OR NON-	Material		2	Jul 17, 2023	SYSTEM	(\$1,646.00)	
		TRACKING			3	Aug 2, 2023	SYSTEM	\$10,408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Aug 2, 2023	SYSTEM	(\$10,408.00)	
					4	Aug 16, 2023	SYSTEM	\$10,408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Paymen Estimate Exception 8 on the current Payment Estimate.
					4	Aug 16, 2023	SYSTEM	(\$10,408.00)	
					5	Sep 5, 2023	SYSTEM	\$10,408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Paymen Estimate Exception 8 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$10,408.00)	
					6	Sep 18, 2023	SYSTEM	\$10,408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stottt1 overridding Paymen Estimate Exception 9 on the current Payment Estimate.
					6	Sep 18, 2023	SYSTEM	(\$10,408.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1050 -	Total						\$0.00	
	1070	CONSTRUCTION SIGNS	Material		2	Jul 17, 2023	SYSTEM	\$5,889.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$5,889.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1070 -	Total						\$0.00	
	1110	TYPE III MOVEABLE BARRICADE	Material		2	Jul 17, 2023	SYSTEM	\$870.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$870.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1110 -	Total						\$0.00	
	1120	CMS W/O COMMUNICATION INTERFACE,	Material		2	Jul 17, 2023	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stottt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
		CONT F/			2	Jul 17, 2023	SYSTEM	(\$6,000.00)	
				- Total				\$0.00	
								\$0.00	
			Material - To	otal					
	1120 -	· Total	Material - To	otal				\$0.00	
	<b>1120</b> - 1140	4 IN. WHITE WATERBORNE		REFL	4	Aug 16, 2023	collie1	\$2,777.22	20% deduct for retroreflectivity
		4 IN. WHITE	Other Item			Aug 16, 2023	collie1		20% deduct for retroreflectivity
		4 IN. WHITE WATERBORNE PAVEMENT	Other Item Adjustment	REFL	ıl	Aug 16, 2023	collie1	\$2,777.22	20% deduct for retroreflectivity
		4 IN. WHITE WATERBORNE PAVEMENT MARKING	Other Item Adjustment	REFL - Tota	ıl	Aug 16, 2023	collie1	\$2,777.22 \$2,777.22	20% deduct for retroreflectivity
	1140	4 IN. WHITE WATERBORNE PAVEMENT MARKING  Total  4 IN. YELLOW WATERBORNE PAVEMENT	Other Item Adjustment	REFL - Tota	ıl	Aug 16, 2023  Aug 16, 2023	collie1	\$2,777.22 \$2,777.22 \$2,777.22	This adjustment offsets the original system-generated Material Payment
	1140	4 IN. WHITE WATERBORNE PAVEMENT MARKING  Total 4 IN. YELLOW WATERBORNE	Other Item Adjustment Other Item	REFL - Tota	ıl Total	2023 Aug 16,		\$2,777.22 \$2,777.22 \$2,777.22 \$2,777.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user collie1 overridding Paymen





roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
E0084	1150	4 IN. YELLOW WATERBORNE	Material		5	Sep 5, 2023	SYSTEM	(\$2,716.56)																
		PAVEMENT MARKING			6	Sep 18, 2023	SYSTEM	\$2,716.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stottt1 overridding Payment Estimate Exception 27 on the current Payment Estimate.															
					6	Sep 18, 2023	SYSTEM	(\$2,716.56)																
				- Total				\$0.00																
			Material - To	otal				\$0.00																
			Other Item Adjustment	REFL	4	Aug 16, 2023	collie1	\$543.31	20% deduct for retroreflectivity															
				REFL - Tota	ıl			\$543.31																
			Other Item	Adjustment -	Total			\$543.31																
	1150 -	Total						\$543.31																
	1160	8 IN. WHITE WATERBORNE PAVEMENT MARKING	Material	Material		4	Aug 16, 2023	SYSTEM	\$4,022.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 10 on the current Payment Estimate.														
						4	Aug 16, 2023	SYSTEM	(\$4,022.50)															
					5	Sep 5, 2023	SYSTEM	\$4,022.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user collie1 overridding Payment Estimate Exception 27 on the current Payment Estimate.															
					5	Sep 5, 2023	SYSTEM	(\$4,022.50)																
					6	Sep 18, 2023	SYSTEM	\$4,022.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 28 on the current Payment Estimate.															
					6	Sep 18, 2023	SYSTEM	(\$4,022.50)																
																						7	Dec 4, 2023	SYSTEM
					7	Dec 4, 2023	SYSTEM	(\$4,022.50)																
				- Total				\$0.00																
			Material - To	otal				\$0.00																
			Other Item Adjustment	REFL	4	Aug 16, 2023	collie1	\$804.50	20% deduct for retroreflectivity															
				REFL - Tota	ıl			\$804.50																
			Other Item	Adjustment -	Total			\$804.50																
	1160 -	Total						\$804.50																
E0084 -	Total							(\$15,069.87)																
erall - 1	Γotal							(\$38,932.17)																

# MoDOT

### Contract Adjustments for Contract - 230317-H03

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 18 of 18