

Pay Estimate Created Date: March 4, 2024

Progress Estimate Number 9		Contract ID Prime Contractor	230317-H03 Apex Paving Co.		Period Start Period End	January 2, March 1, 20	024 <b>N</b>	Priginal Contract Amount let Change Order Amount current Contract Amount	\$8,566,286.74 \$37,281.00 \$8,603,567.74		
Approval Date									By User		
March 4, 2024		(	Generated and App	proved (	and should b	e considered	l Draft) a	t the Project Office Level by	stottt1		
March 4, 2024		Revi	ewed and Approve	d (and s	should be cor	nsidered Draf	ft) at the	Resident Engineer Level by	stottt1		
March 5, 2024			Re	viewed	and Approve	d at the Cent	ral Office	Controllers Office Level by	ramses1		
Original Comp	letion Date	Current Comple	etion Date	Actua	Actual Completion Date % of Current Cont			of Current Contract Amou	ract Amount Complete		
October 1	October 1, 2024 October 1, 2024							38.31%			
	Contract	Informational Dates			IV	lilestones					
Date Description	on Original	Completion Date Cu	irrant Camplatian	Data	No Mileston	es Exist for (	Contract				

	Contract Informational Dates									
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract							
Acceptance Date										
Awarded Date	April 5, 2023	April 5, 2023								
Letting Date	March 17, 2023	March 17, 2023								
Notice to Proceed Date	May 8, 2023	May 8, 2023								
Open to Traffic Date										
Work Began Date										

Contract Total Pay For Estimate No. 9											
		This Estimate	Previous	To Date							
230317-H03											
	Total Posted Items Pay	\$24,242.66	\$3,271,704.58	\$3,295,947.24							
	Gross Item Adjustments	\$0.00	(\$38,932.17)	(\$38,932.17)							
	Incentive	\$0.00	\$0.00	\$0.00							
	Disincentive	\$0.00	\$0.00	\$0.00							
	Liquidated Damage	\$0.00	\$0.00	\$0.00							
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00							
	•		\$3,232,772.41	\$3,257,015.07							
<b>Contract Total Pa</b>	ayable This Estimate:	\$24,242.66									

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9S3528	0870	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	LF	\$6.000	50	\$300.00
	0880	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$25.000	232	\$5,800.00
	0890	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	LF	\$25.000	100	\$2,500.00
	0900	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	EA	\$275.000	19	\$5,225.00
	0910	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	EA	\$1,500.000	2	\$3,000.00
	0940	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.140	28,259	\$3,956.26
	0950	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.200	17,307	\$3,461.40
Project J95	3528 - Tota	al					\$24,242.66
Overall - To	ntal						\$24 242 66

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item /	ne Item Adjustments This Estimate												
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount					
J9S3528	0650	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-2,057.2	\$11.00	(\$22,629.20)					

Revision 3/23/2023 Page 1 of 21



Pay Estimate Created Date: March 4, 2024

. regions =etimate reasons	230317-H03 Pay Period Start Apex Paving Co. Pay Period End	March 1, 2024	Original Contract Amount Net Change Order Amount Current Contract Amount	\$8,566,286.74 \$37,281.00 \$8,603,567.74
----------------------------	--	---------------	--	---

	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
28	0650	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	2,057.2	\$11.00	\$22,629.20
	0680	TYPE A2 SHOULDER	Material			-707.5	\$94.00	(\$66,505.00
	0680	TYPE A2 SHOULDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	707.5	\$94.00	\$66,505.00
(	0720	CONCRETE PAVEMENT ( 9 IN. NON-REINF)	Material			-1,893.96	\$109.00	(\$206,441.64)
	0720	CONCRETE PAVEMENT ( 9 IN. NON-REINF)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user stottt1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	1,893.96	\$109.00	\$206,441.64
	0770	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material			-250	\$14.00	(\$3,500.00)
	0770	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user stottt1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	250	\$14.00	\$3,500.00
(	0790	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-30	\$14.00	(\$420.00)
(	0790	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	30	\$14.00	\$420.00
	0800	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material			-120	\$18.00	(\$2,160.00)
(	0800	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user stottt1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	120	\$18.00	\$2,160.00
	0810	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material			-60	\$15.00	(\$900.00)
(	0810	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user stottt1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	60	\$15.00	\$900.00
	0880	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-232	\$25.00	(\$5,800.00)
	0880	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user stottt1	232	\$25.00	\$5,800.00

Revision 3/23/2023 Page 2 of 21



Pay Estimate Created Date: March 4, 2024

Progress Estimate Number	Contract ID Prime Contractor	230317-H03 Apex Paving Co.		Original Contract Amount Net Change Order Amount	\$8,566,286.74 \$37,281.00
3				Current Contract Amount	\$8,603,567.74

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3528		IN. WHITE			overridding Payment Estimate Exception 15 on the current Payment Estimate.			
	0890	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material			-100	\$25.00	(\$2,500.00)
	0890	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user stottt1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	100	\$25.00	\$2,500.00
	0900	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-19	\$275.00	(\$5,225.00)
	0900	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user stottt1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	19	\$275.00	\$5,225.00
	0910	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	Material			-2	\$1,500.00	(\$3,000.00)
	0910	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user stottt1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	2	\$1,500.00	\$3,000.00
	0940	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-28,259	\$0.14	(\$3,956.26)
	0940	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user stottt1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	28,259	\$0.14	\$3,956.26
	0950	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-17,307	\$0.20	(\$3,461.40)
	0950	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user stottt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	17,307	\$0.20	\$3,461.40
JSE0084	1020	MISC.	Material			-4,037.4	\$54.77	(\$221,128.40)
	1020	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	4,037.4	\$54.77	\$221,128.40
	1030	GRAVEL (A) OR CRUSHED STONE (B)	Material			-90	\$54.78	(\$4,930.20)
	1030	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	90	\$54.78	\$4,930.20

Revision 3/23/2023 Page 3 of 21



Pay Estimate Created Date: March 4, 2024

Progress Estimate Number 9		Contract ID 230317-H03 Prime Contractor Apex Paving Co.		Pay Period End March 1, 2024 Net C		Net Ch	Change Order Amount		\$8,566,286.74 \$37,281.00 \$8,603,567.74		
Project Number	Line No.	Item Descrip	otion	Adjustmer Type	Other Item Adjustment Type	Co	mments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
Total											\$0.00

Revision 3/23/2023 Page 4 of 21



					(	Contract Project Information	on					
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work					
J9S3326	FAS S703(28)	Resurface and bridge rehabilitation	162	NEW MADRID	from Route 25 near C	from Route 25 near Clarkton to Route 61 near Portageville						
J9S3403	FAS S703(19)	Resurface	J	DUNKLIN	from Bus. 25 in Malde	en to Route 53						
J9S3528	FAS S704(27)	Resurface	84	PEMISCOT	from Route 412 to I-5							
JSE0084	FAS- S704(076)	Resurface	С	PEMISCOT	from Route 412 to Ro	n Route 412 to Route 164						
Totals by J	Job Numbers	8										
J9S3326	Incentive Disince Liquida		Gross I	tem Pay	This Estimate \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	Previous \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	To Date \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00					
J9S3403		Item Pay tem Adjustme		tem Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$0.00 \$0.00 \$0.00	To Date \$0.00 \$0.00 <b>\$0.00</b>					
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					
J9S3528		Item Pay tem Adjustme		tem Pay	This Estimate \$24,242.66 \$0.00 \$24,242.66	Previous \$1,286,435.73 (\$23,862.30) \$1,262,573.43	To Date \$1,310,678.39 (\$23,862.30) \$1,286,816.09					
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					
JSE0084		Item Pay tem Adjustme		tem Pay	This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$1,985,268.85 (\$15,069.87) \$1,970,198.98	To Date \$1,985,268.85 (\$15,069.87) \$1,970,198.98					
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					

Revision 3/23/2023 Page 5 of 21



### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 3040506, Project Item Line Number 0650, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSE0084, Item 3049910, Project Item Line Number 1020, Material Set 304991096, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSE0084, Item 3049910, Project Item Line Number 1020, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSE0084, Item 3105002, Project Item Line Number 1030, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 4010150, Project Item Line Number 0680, Material Set 401015096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 5021109, Project Item Line Number 0720, Material Set 502110996, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 5021109, Project Item Line Number 0720, Material Set 502110996, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 5021109, Project Item Line Number 0720, Material Set 502110996, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 5021109, Project Item Line Number 0720, Material Set 502110996, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131013, Project Item Line Number 0770, Material Set 613101396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131015, Project Item Line Number 0790, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131017, Project Item Line Number 0800, Material Set 613101796, Material 1057JMDBEC6.11 - Dowel Bar Epoxy Ctd Gr60 1 1/4 @, Acceptance Action Generic ReinforcingMisc is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131018, Project Item Line Number 0810, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6131018, Project Item Line Number 0810, Material Set 613101896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6200015, Project Item Line Number 0880, Material Set 620001596, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6200018, Project Item Line Number 0890, Material Set 620001896, Material 1048PMPFYL - Preformed Thermoplastic Marking Tape YL, Acceptance Action Generic 1048PMPFYL is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6200021, Project Item Line Number 0900, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6200033, Project Item Line Number 0910, Material Set 620003396, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6206000C, Project Item Line Number 0940, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3528, Item 6206001C, Project Item Line Number 0950, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	insufficient tests entered	stottt1	Overridden
Estimate Exception Type: Item Overrun: Contract 230317-H03, Contract Project J9S3528, Project Item Line Number 0650, Contract Line Item Number 0650, Item 3040506, Minor Item.	change order to be written	stottt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230317-H03, Contract Project J9S3528, Project Item Line Number 0710, Contract Line Item Number 0710, Item 4071005, Minor Item.	change order to be written	stottt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230317-H03, Contract Project J9S3528, Project Item Line Number 0730, Contract Line Item Number 0730, Item 6089902, Minor Item.	change order to be written	stottt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230317-H03, Contract Project J9S3528, Project Item Line Number 0970, Contract Line Item Number 0970, Item 6221001, Minor Item.	change order to be written	stottt1	Acknowledged

Revision 3/23/2023 Page 6 of 21



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					eport Generated date and can differ from the posted amo							T
tract NTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
H03 J	J9S3326	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$27,328.20	\$0.00
		0001	0020	2153000	SHAPING SLOPES, CLASS III	25.00	0.00	25.00	100F	0.00	\$1,429.44	\$0.00
		0001	0030	3049910	MISC.PERMANENT AGGREGATE EDGE TREATEMENT	2,853.50	0.00	2,853.50	TONS	0.00	\$50.77	\$0.00
		0001	0040	3105002	GRAVEL (A) OR CRUSHED STONE (B)	110.00	0.00	110.00	TONS	0.00	\$50.79	\$0.00
		0001	0050	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	15,873.90	0.00	15,873.90	TONS	0.00	\$92.98	\$0.00
		0001	0060	4071005	LEVELING) TACK COAT	19,559.00	0.00	19,559.00	GAL	0.00	\$1.00	\$0.00
		0001	0070	4091048	EMULSIFIED ASPHALT, SEAL COAT	210.00	0.00	210.00	GAL	0.00	\$14.28	\$0.00
		0001	0080	4094011	SEAL COAT AGGREGATE, GRADE B1	564.00	0.00	564.00	SQYD	0.00	\$7.00	\$0.00
		0001	0090	6083003	3 IN. CONCRETE MEDIAN STRIP	86.00	0.00	86.00	SQYD	0.00	\$110.00	\$0.00
		0001	0100	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	4.00	0.00	4.00	EA	0.00	\$4,800.00	\$0.00
		0001	0110	6122030	IMPACT ATTENUATOR (RELOCATION)	16.00	0.00	16.00	EA	0.00	\$2,000.00	\$0.00
		0001	0120	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	0.00	\$0.00	\$0.00
		0001	0130	6161005	CONSTRUCTION SIGNS	1,633.00	0.00	1,633.00	SQFT	0.00	\$6.00	\$0.00
		0001	0140	6161025	CHANNELIZER (TRIM LINE)	120.00	0.00	120.00	EA	0.00	\$24.00	\$0.00
		0001	0150	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	2.00	0.00	2.00	EA	0.00	\$4,500.00	\$0.00
		0001	0160	6181000	RETAINED  MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$243,470.98	\$0.00
		0001	0170	6200013	COLD APPLIED TAPE PAVEMENT MARKING, 24 IN. WHITE	44.00	0.00	44.00	LF	0.00	\$25.00	\$0.00
		0001	0180	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	2.00	0.00	2.00	EA	0.00	\$1,500.00	\$0.00
		0001	0190	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	11,600.00	0.00	11,600.00	LF	0.00	\$1.50	\$0.00
		0001	0200	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	10,000.00	0.00	10,000.00	LF	0.00	\$1.50	\$0.00
		0001	0210	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	120.00	0.00	120.00	LF	0.00	\$9.00	\$0.00
		0001	0220	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	199,134.00	0.00	199,134.00	LF	0.00	\$0.13	\$0.00
		0001	0230	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	50,880.00	0.00	50,880.00	LF	0.00	\$0.13	\$0.00
		0001	0240	6207001	PAVEMENT MARKING REMOVAL	29,540.00	0.00	29,540.00	LF	0.00	\$0.50	\$0.00
		0001	0250	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	8,590.00	0.00	8,590.00	SQYD	0.00	\$5.45	\$0.00
		0001	0260	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	8,957.00	0.00	8,957.00	SQYD	0.00	\$7.86	\$0.00
		0001	0270	7250424	24 IN. PIPE GROUP C	27.00	0.00	27.00	LF	0.00	\$125.00	\$0.00
		0001	0280	7250436	36 IN. PIPE GROUP C	48.00	0.00	48.00	LF	0.00	\$160.00	\$0.00
		0010	0290	6061060	MGS GUARDRAIL	1,100.00	0.00	1,100.00	LF	0.00	\$32.61	\$0.00
		0010	0300	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	33.00	0.00	33.00	EA	0.00	\$4,039.56	\$0.00
		0010	0310	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	0.00	\$1,456.42	\$0.00
		0010	0320	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	31.00	0.00	31.00	EA	0.00	\$3,659.09	\$0.00
		0010	0330	6063020	TYPE C CRASHWORTHY END TERMINAL (MASH)	7.00	0.00	7.00	EA	0.00	\$32,013.57	\$0.00
		0030	0340	9029400	TEMPORARY TRAFFIC SIGNALS	4.00	0.00	4.00	LS	0.00	\$0.00	\$0.00
		0070	0350	7034600	CURB BLOCKOUT	244.00	0.00	244.00	LF	0.00	\$143.00	\$0.00
		0071	0360	7034600	CURB BLOCKOUT	274.00	0.00	274.00	LF	0.00	\$130.00	\$0.00
		0072	0370	7034600	CURB BLOCKOUT	265.00	0.00	265.00	LF	0.00	\$133.00	\$0.00
		0073	0380	7034600	CURB BLOCKOUT	315.00	0.00	315.00	LF	0.00	\$115.00	\$0.00
		0074	0390	7034600	CURB BLOCKOUT	280.00	0.00	280.00	LF	0.00	\$127.00	\$0.00
F	Project J9	S3326 - To	otal Value	Posted to D	ate as of Report Generated Date							\$0.00
J	19S3403	0001	0400	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$5,056.58	\$0.00
		0001	0410	2129903	MISC.SHOULDER GRADING	108,504.00	0.00	108,504.00	LF	0.00	\$0.97	\$0.00
		0001	0420	2153000	SHAPING SLOPES, CLASS III	3.00	0.00	3.00	100F	0.00	\$1,252.05	\$0.00

Page 7 of 21 Revision 3/23/2023



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT					eport Generated date and can differ from the posted amo	unit at the t	iiiic tiic t	_Sumate wa	o Como	aicu.		
	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230317-H03	J9S3403	0001	0440	3105002	GRAVEL (A) OR CRUSHED STONE (B)	22.00	0.00	22.00	TONS	0.00	\$52.58	\$0.00
		0001	0450	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	5,305.00	0.00	5,305.00	TONS	0.00	\$94.63	\$0.00
		0001	0460	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	12,264.80	0.00	12,264.80	TONS	0.00	\$88.96	\$0.00
		0001	0470	4071005	TACK COAT	14,889.00	0.00	14,889.00	GAL	0.00	\$1.00	\$0.00
		0001	0480	4091048	EMULSIFIED ASPHALT, SEAL COAT	255.00	0.00	255.00	GAL	0.00	\$12.99	\$0.00
		0001	0490	4094011	SEAL COAT AGGREGATE, GRADE B1	671.00	0.00	671.00	SQYD	0.00	\$7.00	\$0.00
		0001	0500	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$0.00	\$0.00
		0001	0510	6161005	CONSTRUCTION SIGNS	1,765.00	0.00	1,765.00	SQFT	0.00	\$6.00	\$0.00
		0001	0520	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	0.00	\$22.00	\$0.00
		0001	0530	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$124,218.63	\$0.00
		0001	0540	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	120,422.00	0.00	120,422.00	LF	0.00	\$0.13	\$0.00
		0001	0550	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT. TYPE P BEADS	28,692.00	0.00	28,692.00	LF	0.00	\$0.14	\$0.00
		0001	0560	6206108A	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	920.00	0.00	920.00	LF	0.00	\$1.00	\$0.00
		0001	0570	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,053.00	0.00	1,053.00	SQYD	0.00	\$7.61	\$0.00
		0001	0580	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	4,783.00	0.00	4,783.00	SQYD	0.00	\$9.83	\$0.00
		0001	0590	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,147.30	0.00	1,147.30	STA	0.00	\$17.50	\$0.00
		0010	0600	6061060	MGS GUARDRAIL	150.00	0.00	150.00	LF	0.00	\$40.47	\$0.00
		0010	0610	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	0.00	\$4,146.39	\$0.00
		0010	0620	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$3,430.71	\$0.00
	Project J	9S3403 - To	tal Value	Posted to D	ate as of Report Generated Date							\$0.00
	J9S3528	0001	0630	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$12,000.00	\$12,000.00
			0000	2022010		1.00						*,
		0001	0640	2129903	MISC.SHOULDER GRADING	6,723.00	0.00	6,723.00	LF	625.00	\$3.90	
					MISC.SHOULDER GRADING  TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)						\$3.90 \$11.00	\$2,437.50
		0001	0640	2129903		6,723.00	0.00	6,723.00	LF	625.00		\$2,437.50 \$22,629.20
		0001	0640 0650	2129903 3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	6,723.00 1,750.00	0.00	6,723.00 1,750.00	LF SQYD	625.00 2,057.20	\$11.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00
		0001 0001 0001	0640 0650 0660	2129903 3040506 3049910	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) MISC.PERMANENT AGGREGATE EDGE TREATMENT	6,723.00 1,750.00 380.50	0.00	6,723.00 1,750.00 380.50	LF SQYD TONS	625.00 2,057.20 380.50	\$11.00 \$69.32	\$2,437.50 \$22,629.20 \$26,376.26
		0001 0001 0001 0001	0640 0650 0660 0670	2129903 3040506 3049910 3105002	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)	6,723.00 1,750.00 380.50 13.00	0.00 0.00 0.00 0.00	6,723.00 1,750.00 380.50 13.00	LF SQYD TONS TONS	625.00 2,057.20 380.50 0.00	\$11.00 \$69.32 \$69.34	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00
		0001 0001 0001 0001 0001	0640 0650 0660 0670 0680	2129903 3040506 3049910 3105002 4010150	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER	6,723.00 1,750.00 380.50 13.00 556.00	0.00 0.00 0.00 0.00 151.50	6,723.00 1,750.00 380.50 13.00 707.50	LF SQYD TONS TONS SQYD	625.00 2,057.20 380.50 0.00 707.50	\$11.00 \$69.32 \$69.34 \$94.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06
		0001 0001 0001 0001 0001	0640 0650 0660 0670 0680	2129903 3040506 3049910 3105002 4010150 4011209	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70	0.00 0.00 0.00 0.00 151.50	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70	LF SQYD TONS TONS SQYD	625.00 2,057.20 380.50 0.00 707.50 5,573.69	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48
		0001 0001 0001 0001 0001 0001	0640 0650 0660 0670 0680 0690	2129903 3040506 3049910 3105002 4010150 4011209 4013000	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00	0.00 0.00 0.00 0.00 151.50 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00	LF SQYD TONS TONS SQYD TONS TONS	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48
		0001 0001 0001 0001 0001 0001 0001	0640 0650 0660 0670 0680 0690 0700	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC. PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00	LF SQYD TONS TONS SQYD TONS TONS GAL	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0670 0680 0690 0700 0710	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT (9 IN. NON-REINF)	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 0.0	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00	LF SQYD TONS TONS SQYD TONS TONS GAL SQYD	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0670 0680 0690 0710 0720	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT (9 IN. NON-REINF)  MISC.ADA CURB RAMP	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00	LF SQYD TONS TONS SQYD TONS TONS GAL SQYD EA	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0670 0680 0690 0700 0710 0720 0730	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT ( 9 IN. NON-REINF)  MISC.ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 8.00	0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 12.00	LF SQYD TONS TONS SQYD TONS TONS GAL SQYD EA	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00 \$0.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0670 0680 0690 0710 0720 0730 0740	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A 6131010	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT (9 IN. NON-REINF)  MISC.ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 8.00 2.00 250.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 2.00 250.00	LF SQYD TONS TONS SQYD TONS TONS GAL SQYD EA SQYD	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00 0.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00 \$331.58	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00 \$0.00 \$82,895.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0670 0680 0690 0710 0720 0730 0740 0750	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A 6131010	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT (9 IN. NON-REINF)  MISC.ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL  DEPTH PAVEMENT REPAIR  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)  TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 8.00 2.00 250.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00 0.00 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 2.00 250.00	LF SQYD TONS TONS SQYD TONS TONS GAL SQYD EA SQYD	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00 0.00 250.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00 \$331.58	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00 \$0.00 \$82,895.00 \$3,750.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0660 0660 0670 0680 0700 0710 0720 0730 0740 0750	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A 6131010 6131012 6131013	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC. PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT ( 9 IN. NON-REINF)  MISC. ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL  DEPTH PAVEMENT REPAIR)  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)  TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)  (PAVEMENT REPAIR)  FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 2.00 250.00 250.00	0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00 0.00 0.00 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 2.00 250.00 250.00	LF SQYD TONS TONS SQYD TONS GAL SQYD EA SQYD SQYD SQYD	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00 0.00 250.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00 \$331.58 \$15.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00 \$0.00 \$82,895.00 \$3,750.00 \$5,532.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0670 0680 0690 0710 0720 0730 0740 0750 0770 0770	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A 6131010 6131012 6131013 6131014	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT (9 IN. NON-REINF)  MISC.ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL  DEPTH PAVEMENT REPAIR  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)  TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)  (PAVEMENT REPAIR)  FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER  AND INTERNAL SAW CUTS)  DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION)	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 8.00 250.00 250.00 461.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00 0.00 0.00 0.00 0.00 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 2.00 250.00 250.00 461.00	LF SQYD TONS TONS SQYD TONS TONS GAL SQYD EA SQYD SQYD SQYD LF	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00 0.00 250.00 250.00 461.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00 \$331.58 \$15.00 \$14.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00 \$0.00 \$82,895.00 \$3,750.00 \$5,532.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0660 0670 0680 0700 0710 0720 0730 0740 0750 0770 0780	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A 6131010 6131012 6131013 6131014 6131015	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC. PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT ( 9 IN. NON-REINF)  MISC. ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR)  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)  TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)  (PAVEMENT REPAIR)  FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)  DOWEL BAR (FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR  DOWEL BAR (FURNISHING AND INSTALLATION WITH	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 250.00 250.00 250.00 461.00 30.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00 0.00 0.00 0.00 0.00 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 250.00 250.00 250.00 461.00	LF SQYD TONS TONS SQYD TONS GAL SQYD EA SQYD SQYD SQYD SQYD LF EA	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00 0.00 250.00 250.00 250.00 461.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00 \$331.58 \$15.00 \$14.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00 \$3,750.00 \$3,750.00 \$5,532.00 \$420.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0660 0670 0680 0700 0710 0720 0730 0760 0770 0780 0790	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A 6131010 6131013 6131014 6131015 6131017	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT (9 IN. NON-REINF)  MISC.ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)  TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)  (PAVEMENT REPAIR)  FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)  DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR  TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 8.00 250.00 250.00 461.00 30.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 160.00 0.00 0.00 0.00 0.00 0	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 250.00 250.00 250.00 461.00 30.00	LF SQYD TONS TONS SQYD TONS TONS GAL SQYD EA SQYD SQYD SQYD LF EA EA	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00 250.00 250.00 461.00 30.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00 \$331.58 \$15.00 \$14.00 \$14.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00 \$3,750.00 \$3,750.00 \$5,532.00 \$420.00 \$2,160.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0660 0670 0680 0700 0710 0720 0730 0740 0750 0770 0780 0790 0800	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A 6131010 6131013 6131014 6131015 6131017 6131018	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC.PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT (9 IN. NON-REINF)  MISC.ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)  TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)  (PAVEMENT REPAIR)  FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)  DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR  TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR  TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR  TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 2.00 250.00 250.00 461.00 30.00 120.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00 0.00 0.00 0.00 0.00 0.00 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 250.00 250.00 250.00 461.00 30.00 120.00	LF SQYD TONS TONS SQYD TONS GAL SQYD EA SQYD SQYD SQYD LF EA EA	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00 250.00 250.00 461.00 30.00 120.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00 \$331.58 \$15.00 \$14.00 \$14.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00 \$66,505.00 \$615,614.06 \$57,293.48 \$13,576.20 \$206,441.64 \$22,400.00 \$3,750.00 \$3,750.00 \$5,532.00 \$420.00 \$2,160.00 \$900.00
		0001 0001 0001 0001 0001 0001 0001 000	0640 0650 0660 0660 0670 0680 0700 0710 0720 0730 0760 0770 0780 0800 0810	2129903 3040506 3049910 3105002 4010150 4011209 4013000 4071005 5021109 6089902 6123000A 6131010 6131013 6131014 6131015 6131017 6131018	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  MISC. PERMANENT AGGREGATE EDGE TREATMENT  GRAVEL (A) OR CRUSHED STONE (B)  TYPE A2 SHOULDER  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  TACK COAT  CONCRETE PAVEMENT ( 9 IN. NON-REINF)  MISC. ADA CURB RAMP  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)  TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)  (PAVEMENT REPAIR)  FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)  DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR  DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR  TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)  CONSTRUCTION SIGNS	6,723.00 1,750.00 380.50 13.00 556.00 5,603.70 673.00 4,293.00 1,750.00 250.00 250.00 250.00 461.00 30.00 1,368.00	0.00 0.00 0.00 0.00 151.50 0.00 0.00 160.00 4.00 0.00 0.00 0.00 0.00 0.00 0.00	6,723.00 1,750.00 380.50 13.00 707.50 5,603.70 673.00 4,293.00 1,910.00 250.00 250.00 250.00 461.00 30.00 120.00 60.00 1,368.00	LF SQYD TONS TONS SQYD TONS TONS GAL SQYD EA SQYD EA SQYD SQYD LF EA EA EA SQFT	625.00 2,057.20 380.50 0.00 707.50 5,573.69 468.62 5,324.00 1,893.96 16.00 250.00 250.00 461.00 30.00 120.00 60.00	\$11.00 \$69.32 \$69.34 \$94.00 \$110.45 \$122.26 \$2.55 \$109.00 \$1,400.00 \$331.58 \$15.00 \$14.00 \$14.00 \$18.00 \$15.00	\$2,437.50 \$22,629.20 \$26,376.26 \$0.00

Revision 3/23/2023 Page 8 of 21



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230317-H03	J9S3528	0001	0860	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$55,870.24	\$55,870.24
		0001	0870	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	50.00	0.00	50.00	LF	50.00	\$6.00	\$300.00
		0001	0880	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	232.00	0.00	232.00	LF	232.00	\$25.00	\$5,800.00
		0001	0890	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	100.00	0.00	100.00	LF	100.00	\$25.00	\$2,500.00
		0001	0900	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	19.00	0.00	19.00	EA	19.00	\$275.00	\$5,225.00
		0001	0910	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
		0001	0920	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	874.00	0.00	874.00	LF	0.00	\$1.50	\$0.00
		0001	0930	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	4,476.00	0.00	4,476.00	LF	0.00	\$1.50	\$0.00
		0001	0940	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	28,259.00	0.00	28,259.00	LF	28,259.00	\$0.14	\$3,956.26
		0001	0950	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	17,307.00	0.00	17,307.00	LF	17,307.00	\$0.20	\$3,461.40
		0001	0960	6207001	PAVEMENT MARKING REMOVAL	5,350.00	0.00	5,350.00	LF	0.00	\$1.00	\$0.00
		0001	0970	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	6,130.00	0.00	6,130.00	SQYD	7,058.32	\$7.37	\$52,019.82
		0001	0980	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	7,541.00	0.00	7,541.00	SQYD	3,434.81	\$4.85	\$16,658.83
		0001	0990	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	61.00	0.00	61.00	STA	0.00	\$36.03	\$0.00
	Project J	S3528 - To	tal Value	Posted to D	ate as of Report Generated Date							\$1,310,678.39
	JSE0084	0001	1000	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$8,323.57	\$0.00
		0001	1010	2159910	MISC.SHAPING SLOPES CLASS III - MODIFIED	4.00	0.00	4.00	100F	4.00	\$1,348.46	\$5,393.84
		0001	1020	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	4,037.40	0.00	4,037.40	TONS	4,037.40	\$54.77	\$221,128.40
		0001	1030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	90.00	0.00	90.00	TONS	90.00	\$54.78	\$4,930.20
		0001	1040	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	17,336.40	0.00	17,336.40	TONS	16,059.99	\$96.54	\$1,550,431.43
		0001	1050	4071007	TACK COAT - LOW OR NON-TRACKING	18,331.00	0.00	18,331.00	GAL	10,408.00	\$1.00	\$10,408.00
		0001	1060	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$0.00	\$0.00
		0001	1070	6161005	CONSTRUCTION SIGNS	1,189.00	0.00	1,189.00	SQFT	906.00	\$6.50	\$5,889.00
		0001	1080	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	0.00	\$45.00	\$0.00
		0001	1090	6161010	RELOCATED SIGNS	476.00	0.00	476.00	SQFT	0.00	\$6.50	\$0.00
		0001	1100	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	0.00	\$24.00	\$0.00
		0001	1110	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$145.00	\$1,450.00
		0001	1120	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
		0001	1130	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$63,827.62	\$63,827.62
		0001	1140	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	106,816.00	0.00	106,816.00	LF	106,816.00	\$0.13	\$13,886.08
		0001	1150	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	15,092.00	0.00	15,092.00	LF	15,092.00	\$0.18	\$2,716.56
		0001	1160	6206108A	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	8,045.00	0.00	8,045.00	LF	8,045.00	\$0.50	\$4,022.50
		0001	1170	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,348.00	0.00	1,348.00	SQYD	481.67	\$10.84	\$5,221.30
		0001	1180	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	856.00	0.00	856.00	SQYD	856.00	\$41.26	\$35,318.56
		0001	1190	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	5,430.00	0.00	5,430.00	SQYD	2,425.87	\$8.07	\$19,576.77
		0010	1200	6061060	MGS GUARDRAIL	175.00	0.00	175.00	LF	175.00	\$33.69	\$5,895.75
		0010	1210	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$4,146.39	\$16,585.56
		0010	1220	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	1.00	\$1,794.45	\$1,794.45
		0010	1230	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3.00	0.00	3.00	EA	3.00	\$3,597.61	\$10,792.83
	Project J	SE0084 - To	otal Value	e Posted to D	late as of Report Generated Date							\$1,985,268.86
230317-H03 Ove	rall - Total	Value Post	ed to Da	te as of Repo	ort Generated Date							\$3,295,947.24

Page 9 of 21 Revision 3/23/2023



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9S3528

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0870	6200003	PREF THERMO PAVEMENT MARKING, 4 IN WHITE	2/28/24	3/4/24	50.00	LF	Route 84	0		0		
0880	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	2/28/24	3/4/24	232.00	LF	Route 84	0	0			
0890	6200018	PREF THERMO PVMT MARK, 24 IN YELLOW	2/28/24	3/4/24	100.00	LF	Route 84	0		0		
0900	6200021	PREF THERMO PVMT MARK, LT/RT ARROW	2/28/24	3/4/24	19.00	EA	Route 84	0		0		
0910	6200033	PREF THERMO PVMT MARK, R/R XING	2/28/24	3/4/24	2.00	EA	Route 84	0		0		
0940	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	2/28/24	3/4/24	28,259.00	LF	Route 84	0		0		
0950	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	2/28/24	3/4/24	17,307.00	LF	Route 84	0		0		

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 10 of 21



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3528	0650	TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		4	Aug 16, 2023	SYSTEM	\$19,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		THICK)			4	Aug 16, 2023	SYSTEM	(\$19,250.00)	
					5	Sep 5, 2023	SYSTEM	\$22,629.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$22,629.20)	
					6	Sep 18, 2023	SYSTEM	\$22,629.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Sep 18, 2023	SYSTEM	(\$22,629.20)	
					7	Dec 4, 2023	SYSTEM	\$22,629.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$22,629.20)	
					8	Jan 2, 2024	SYSTEM	\$22,629.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jan 2, 2024	SYSTEM	(\$22,629.20)	
					9	Mar 4, 2024	SYSTEM	\$22,629.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Mar 4, 2024	SYSTEM	(\$22,629.20)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	5	Sep 5, 2023	SYSTEM	(\$3,394.04)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				Overrun - T	otal			(\$3,394.04)	
			Overrun - T	otal				(\$3,394.04)	
			Price FUEL		4	Aug 16, 2023	SYSTEM	\$84.52	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Sep 5, 2023	SYSTEM	\$14.84	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$99.36	
			Price FUEL	- Total				\$99.36	
	0650 -							(\$3,294.68)	
	0660	MISC. AGGREGATE FOR BASE	Material			Aug 16, 2023	SYSTEM	\$26,376.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Aug 16, 2023	SYSTEM	(\$26,376.26)	
					5	Sep 5, 2023	SYSTEM	\$26,376.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user collie1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$26,376.26)	
					6	Sep 18, 2023	SYSTEM	\$26,376.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stottt1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Sep 18, 2023	SYSTEM	(\$26,376.26)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0660 -							\$0.00	
	0680	TYPE A2 SHOULDER	Material		6	Sep 18, 2023	SYSTEM	\$52,264.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 8 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3528	0680	TYPE A2 SHOULDER	Material		6	Sep 18, 2023	SYSTEM	(\$52,264.00)	
					7	Dec 4, 2023	SYSTEM	\$66,505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$66,505.00)	
					8	Jan 2, 2024	SYSTEM	\$66,505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Jan 2, 2024	SYSTEM	(\$66,505.00)	
					9	Mar 4, 2024	SYSTEM	\$66,505.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Mar 4, 2024	SYSTEM	(\$66,505.00)	
				- Total				\$0.00	
			Material - To					\$0.00	
			Other Item Adjustment	FUEL	7	Dec 4, 2023	collie1	(\$1.48)	Items were paid during the incorrect pay period. This amount was removed to correct the Fuel Adjustment.
					7	Dec 4, 2023	collie1	\$15.59	This is the Fuel Index calculated for when work was actually completed.
				FUEL - Tota	ı			\$14.11	
			Other Item A	Adjustment -	Total			\$14.11	
			Price FUEL		6	Sep 18, 2023	SYSTEM	\$2.51	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Dec 4, 2023	SYSTEM	\$1.48	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$3.99	
			Price FUEL	- Total				\$3.99	
	0680 -	Total						\$18.10	
	0690	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Price FUEL		1	Jun 30, 2023	SYSTEM	(\$4,619.45)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		1 304 22 (31 1)			3	Aug 2, 2023	SYSTEM	(\$722.39)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				(\$5,341.84)	
			Price FUEL	- Total				(\$5,341.84)	
	0690 -							(\$5,341.84)	
	0700	BITUMINOUS PAVEMENT MIXTURE	Price FUEL		1	Jun 30, 2023	SYSTEM	(\$435.63)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		PG64-22 (BAS	D.i. Etter	- Total				(\$435.63)	
	0700	Tabel	Price FUEL	- Iotal				(\$435.63)	
	0700 -		Material		4	lum 00	CVCTEA	(\$435.63)	This adjustment effects the existed queter and Al-A-3-1 Day
	0710	TACK COAT	Material		1	Jun 30, 2023	SYSTEM	\$12,342.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Jun 30, 2023	SYSTEM	(\$12,342.00)	
					2	Jul 17, 2023	SYSTEM	\$12,342.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
							01/0==1/	(\$12.242.00)	
					2	Jul 17, 2023	SYSTEM	(\$12,342.00)	
				- Total	2		SYSTEM	\$0.00	
			Material - To		2		SYSTEM		
			Material - To				SYSTEM	\$0.00	
				otal		2023 Jun 30,		\$0.00 \$0.00	



	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
	J9S3528	0710	TACK COAT	Overrun - T	otal				(\$2,629.05)	
PAYERSHY   DR   NON-REINY		0710 -	Total						(\$2,629.05)	
		0720	PAVEMENT (9 IN.	Material		5		SYSTEM	\$189,001.64	Estimate Item Adjustment (0008) due to user collie1 overridding Payment
2023   Spy 18, SYSTEM   (\$109,001.64)   Spy 18, SYSTEM   (\$109,001.64)   Spy 18, SYSTEM   (\$109,001.64)   Spy 18, SYSTEM   (\$109,001.64)   Spy 18, SYSTEM   S						5		SYSTEM	(\$189,001.64)	
2023   97   20						6		SYSTEM	\$189,001.64	Estimate Item Adjustment (0010) due to user stottt1 overridding Payment
2023   SYSTEM   (\$206,411.64)						6		SYSTEM	(\$189,001.64)	
2023   SYSTEM   \$206,441.64   This adjustment offsets the original system-generated Material Payment Estimate Estimate Item Adjustment (0005) due to user collisit overridding Payment Estimate Item Adjustment (0005) due to user collisit overridding Payment Estimate Exception 6 on the current Payment Estimate Estimate Exception 6 on the current Payment Estimate Payment Estimate Payment Estimate Item Adjustment (1965) due to user solution overridding Payment Estimate Estimate Exception 6 on the current Payment Estimate Payment Estimate Payment P						7		SYSTEM	\$206,441.64	Estimate Item Adjustment (0008) due to user collie1 overridding Payment
2024   Estimate Item Appliatment (005) due to user collect overridding Payment Estimate Exception 6 on the current Payment Estimate.						7		SYSTEM	(\$206,441.64)	
						8		SYSTEM	\$206,441.64	Estimate Item Adjustment (0005) due to user collie1 overridding Payment
Bestimate Item Adjustment (1000) due to user stotts overridding Payment Estimate. Estimate Exception 6 on the current Payment Estimate.   Section 7 on the current Payment Estimate.   Section 6 on the current Payment Estimate.   Section 7 on the current Payment Estimate.   Section 8 on the current Payment Estimate Exception 15 on the current Payment Estimate.   Section 8 on the						8		SYSTEM	(\$206,441.64)	
Public   Total   So 00     So 00						9		SYSTEM	\$206,441.64	Estimate Item Adjustment (0005) due to user stottt1 overridding Payment
Material - Total  Other Item Adjustment  FUEL   7   Dec 4, 2023   Collie1   (\$98.21)   Items were paid during the incorrect pay period. This amount was removed to correct the Fuel Adjustment.  FUEL - Total						9		SYSTEM	(\$206,441.64)	
Other Item Adjustment				Material - 1					\$0.00	
Adjustment   2023   correct the Fuel Adjustment.   7   Dec 4, 2023   correct the Fuel Adjustment.   7   Dec 4, 2023   correct the Fuel Adjustment.   2024   collie1   \$22.18   This is the Fuel Index calculated for when work was actually completed.   2023   (\$76.03)				Material - To	otal				\$0.00	
Pitel					FUEL	7		collie1	(\$98.21)	
Other Item Adjustment - Total Price FUEL  5 Sep 5, SYSTEM \$240.34 Reference Item Price Adjustment Index Adjustment Type applied is FUEL  7 Dec 4, 2023  7 Dec 4, 2023  Reference Item Price Adjustment Index Adjustment Type applied is FUEL  - Total  5339.55  0720 - Total  0730 MISC. CONCRETE  Overrun Overrun 6 Sep 18, 2023  Overrun - Total  0730 - Total						7		collie1	\$22.18	This is the Fuel Index calculated for when work was actually completed.
Price FUEL   5   Sep 5, 2023   SYSTEM   \$240.34   Reference Item Price Adjustment Index Adjustment Type applied is FUEL					FUEL - Tota	ıl			(\$76.03)	
FUEL   2023   7   Dec 4,   SYSTEM   \$98.21   Reference Item Price Adjustment Index Adjustment Type applied is FUEL				Other Item A	Adjustment -	Total			(\$76.03)	
Price FUEL - Total   \$338.55						5		SYSTEM	\$240.34	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
Price FUEL - Total   \$338.55						7		SYSTEM	\$98.21	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
10730   MISC. CONCRETE   Overrun   Overrun   6   Sep 18, 2023   SYSTEM   (\$5,600.00)					- Total				\$338.55	
Overrun   Over				Price FUEL	- Total				\$338.55	
2023     2023     2023     2023     2023     2024   2025			* **						\$262.52	
10730 - Total   (\$5,600.00)		0730	MISC. CONCRETE	Overrun	Overrun	6		SYSTEM	(\$5,600.00)	
Sep 18, 2023   SYSTEM   Sep 5.00   SySTEM   Sep 5.00   This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate.					Overrun - T	otal			(\$5,600.00)	
FURN & PLACE CONC MATL FOR FULL DEPTH  5 Sep 5, 2023 SYSTEM \$82,895.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate.  5 Sep 5, 2023 SYSTEM (\$82,895.00)  6 Sep 18, 2023 SYSTEM \$82,895.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stott1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  6 Sep 18, 2023 SYSTEM (\$82,895.00)  7 Dec 4, 2023 SYSTEM \$82,895.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate.  7 Dec 4, 2023 SYSTEM (\$82,895.00)  8 SYSTEM SYSTEM SYSTEM SYSTEM Estimate Exception 10 on the current Payment Estimate Exception 10 on the current Payment Estimate.				Overrun - T	otal				(\$5,600.00)	
CONC MATL FOR FULL DEPTH  2023 Estimate Item Adjustment (0018) due to user collie1 overridding Payment Estimate.  5 Sep 5, 2023 SYSTEM (\$82,895.00)  6 Sep 18, 2023 SYSTEM \$82,895.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stott1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  6 Sep 18, 2023 SYSTEM (\$82,895.00)  7 Dec 4, 2023 SYSTEM \$82,895.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  7 Dec 4, 2023 SYSTEM (\$82,895.00)		0730 -							(\$5,600.00)	
6 Sep 18, 2023 SYSTEM \$82,895.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stottt1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  6 Sep 18, 2023 SYSTEM (\$82,895.00)  7 Dec 4, 2023 SYSTEM \$82,895.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  7 Dec 4, 2023 SYSTEM (\$82,895.00)		0750	CONC MATL FOR	Material		5		SYSTEM	\$82,895.00	Estimate Item Adjustment (0018) due to user collie1 overridding Payment
Estimate Item Adjustment (0012) due to user stottt1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  Sep 18, 2023  Dec 4, 2023  System (\$82,895.00)  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  Dec 4, 2023  System (\$82,895.00)						5		SYSTEM	(\$82,895.00)	
7 Dec 4, 2023 SYSTEM \$82,895.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  7 Dec 4, 2023 SYSTEM (\$82,895.00)						6		SYSTEM	\$82,895.00	Estimate Item Adjustment (0012) due to user stottt1 overridding Payment
2023 Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  7 Dec 4, 2023 (\$82,895.00)						6		SYSTEM	(\$82,895.00)	
2023						7		SYSTEM	\$82,895.00	Estimate Item Adjustment (0009) due to user collie1 overridding Payment
- Total \$0.00						7		SYSTEM	(\$82,895.00)	
					- Total				\$0.00	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3528	0750	FURN & PLACE CONC MATL FOR FULL DEPTH	Material - To	otal				\$0.00	
	0750 -	· Total						\$0.00	
	0770	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. TH	Material		5	Sep 5, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user collie1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
		In			5	Sep 5, 2023	SYSTEM	(\$3,500.00)	
					6	Sep 18, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stottt1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					6	Sep 18, 2023	SYSTEM	(\$3,500.00)	
					7	Dec 4, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user collie1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$3,500.00)	
					8	Jan 2, 2024	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Jan 2, 2024	SYSTEM	(\$3,500.00)	
					9	Mar 4, 2024	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stottt1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					9	Mar 4, 2024	SYSTEM	(\$3,500.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0770 -	· Total						\$0.00	
	0790	DOWEL BAR							
		(DRILLING, FURNISHING AND	Material		5	Sep 5, 2023	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user collie1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
			матела		5		SYSTEM	\$420.00 (\$420.00)	Estimate Item Adjustment (0020) due to user collie1 overridding Payment
		FURNISHING AND	Material			2023 Sep 5,			Estimate Item Adjustment (0020) due to user collie1 overridding Payment
		FURNISHING AND	Material		5	2023 Sep 5, 2023 Sep 18,	SYSTEM	(\$420.00)	Estimate Item Adjustment (0020) due to user collie1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stottt1 overridding Payment
		FURNISHING AND	Material		5	2023 Sep 5, 2023 Sep 18, 2023	SYSTEM SYSTEM	(\$420.00) \$420.00	Estimate Item Adjustment (0020) due to user collie1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stottt1 overridding Payment
		FURNISHING AND	Material		5 6	2023 Sep 5, 2023 Sep 18, 2023 Sep 18, 2023 Dec 4,	SYSTEM SYSTEM SYSTEM	(\$420.00) \$420.00 (\$420.00)	Estimate Item Adjustment (0020) due to user collie1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stottt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment
		FURNISHING AND	Material		5 6 6 7	2023 Sep 5, 2023 Sep 18, 2023 Sep 18, 2023 Dec 4, 2023 Dec 4,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$420.00) \$420.00 (\$420.00) \$420.00	Estimate Item Adjustment (0020) due to user collie1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stottt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment
		FURNISHING AND	Material		5 6 6 7	2023 Sep 5, 2023 Sep 18, 2023 Sep 18, 2023 Dec 4, 2023 Dec 4, 2023 Jan 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$420.00) \$420.00 (\$420.00) \$420.00	Estimate Item Adjustment (0020) due to user collie1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stottt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment
		FURNISHING AND	Material		5 6 7 7 8	2023 Sep 5, 2023 Sep 18, 2023 Sep 18, 2023 Dec 4, 2023 Dec 4, 2023 Jan 3, 2024 Jan 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$420.00) \$420.00 (\$420.00) \$420.00 (\$420.00)	Estimate Item Adjustment (0020) due to user collie1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stottt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment
		FURNISHING AND	Material		5 6 7 7 8	2023 Sep 5, 2023 Sep 18, 2023 Sep 18, 2023 Dec 4, 2023 Dec 4, 2023 Jan 3, 2024 Mar 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$420.00) \$420.00 (\$420.00) \$420.00 (\$420.00) \$420.00	Estimate Item Adjustment (0020) due to user collie1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stottt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.
		FURNISHING AND	Material	- Total	5 6 7 7 8 8	2023 Sep 5, 2023 Sep 18, 2023 Dec 4, 2023 Dec 4, 2023 Jan 3, 2024 Mar 4, 2024 Mar 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$420.00) \$420.00 (\$420.00) \$420.00 (\$420.00) \$420.00 \$420.00	Estimate Item Adjustment (0020) due to user collie1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stottt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.
		FURNISHING AND	Material - To		5 6 7 7 8 8	2023 Sep 5, 2023 Sep 18, 2023 Dec 4, 2023 Dec 4, 2023 Jan 3, 2024 Mar 4, 2024 Mar 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$420.00) \$420.00 (\$420.00) \$420.00 (\$420.00) \$420.00 (\$420.00)	Estimate Item Adjustment (0020) due to user collie1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stottt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.
	0790 -	FURNISHING AND INST			5 6 7 7 8 8	2023 Sep 5, 2023 Sep 18, 2023 Dec 4, 2023 Dec 4, 2023 Jan 3, 2024 Mar 4, 2024 Mar 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$420.00) \$420.00 (\$420.00) \$420.00 (\$420.00) \$420.00 (\$420.00) \$420.00	Estimate Item Adjustment (0020) due to user collie1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stottt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.
	<b>0790 -</b> 0800	FURNISHING AND INST	Material - To		5 6 7 7 8 8	2023 Sep 5, 2023 Sep 18, 2023 Dec 4, 2023 Dec 4, 2023 Jan 3, 2024 Mar 4, 2024 Mar 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$420.00) \$420.00 (\$420.00) \$420.00 (\$420.00) \$420.00 (\$420.00) \$420.00 \$420.00	Estimate Item Adjustment (0020) due to user collie1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stottt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.



ct	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	Lino	2 dod.,pub.,	Туре	Adjustment Type	Number	Date	Ву	7 1110 1111	. Contains
28	0800	DOWEL BAR (FURNISH AND INSTALL WITH BASK	Material		6	Sep 18, 2023	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stottt1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
		DAGR			6	Sep 18, 2023	SYSTEM	(\$2,160.00)	
					7	Dec 4, 2023	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user collie1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$2,160.00)	
					8	Jan 2, 2024	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					8	Jan 2, 2024	SYSTEM	(\$2,160.00)	
					9	Mar 4, 2024	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stottt1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					9	Mar 4, 2024	SYSTEM	(\$2,160.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0800 -	Total						\$0.00	
	0810	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	Material		5	Sep 5, 2023	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user collie1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$900.00)	
					6	Sep 18, 2023	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stottt1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					6	Sep 18, 2023	SYSTEM	(\$900.00)	
					7	Dec 4, 2023	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user collie1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$900.00)	
					8	Jan 2, 2024	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					8	Jan 2, 2024	SYSTEM	(\$900.00)	
					9	Mar 4, 2024	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stottt1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					9	Mar 4, 2024	SYSTEM	(\$900.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0810 -							\$0.00	
	0820	CONSTRUCTION SIGNS	Material		1	Jun 30, 2023	SYSTEM	\$3,841.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user collie1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Jun 30, 2023	SYSTEM	(\$3,841.50)	
					2	Jul 17, 2023	SYSTEM	\$3,841.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$3,841.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0820 -	Total						\$0.00	



t L	ine	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
28 08	830	CHANNELIZER (TRIM LINE)	Material		1	Jun 30, 2023	SYSTEM	\$1,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Jun 30, 2023	SYSTEM	(\$1,560.00)	
					2	Jul 17, 2023	SYSTEM	\$1,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stottt1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$1,560.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
08	830 -	Total						\$0.00	
08	850	CMS W/O COMMUNICATION INTERFACE,	Material		1	Jun 30, 2023	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user collie1 overridding Paymen Estimate Exception 4 on the current Payment Estimate.
		CONT F/			1	Jun 30, 2023	SYSTEM	(\$9,000.00)	
					2	Jul 17, 2023	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stottt1 overridding Paymen Estimate Exception 8 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$9,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
08	850 -	Total						\$0.00	
08	880	PREF THERMO PVMT MARK, 24 IN WHIT	Material		9	Mar 4, 2024	SYSTEM	\$5,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stottt1 overridding Paymen Estimate Exception 15 on the current Payment Estimate.
					9	Mar 4, 2024	SYSTEM	(\$5,800.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
0	880 -	Total						\$0.00	
08	890	PREF THERMO PVMT MARK, 24 IN YELLOW	Material		9	Mar 4, 2024	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stottt1 overridding Paymen Estimate Exception 16 on the current Payment Estimate.
					9	Mar 4, 2024	SYSTEM	(\$2,500.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
0	890 -	Total						\$0.00	
09	900	PREF THERMO PVMT MARK, LT/RT ARROW	Material		9	Mar 4, 2024	SYSTEM	\$5,225.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stottt1 overridding Paymen Estimate Exception 17 on the current Payment Estimate.
					9	Mar 4, 2024	SYSTEM	(\$5,225.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
0	900 -	Total						\$0.00	
09	910	PREF THERMO PVMT MARK, R/R XING	Material		9	Mar 4, 2024	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stottt1 overridding Paymen Estimate Exception 18 on the current Payment Estimate.
					9	Mar 4, 2024	SYSTEM	(\$3,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
0	910 -	Total						\$0.00	
09	940	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		9	Mar 4, 2024	SYSTEM	\$3,956.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stottt1 overridding Payment Estimate Exception 19 on the current Payment Estimate.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J9S3528	0940	4 IN. WHITE WATERBORNE	Material		9	Mar 4, 2024	SYSTEM	(\$3,956.26)	
		PAVEMENT MARKING		- Total				\$0.00	
			Material - T	otal				\$0.00	
	0940 -	· Total						\$0.00	
	0950	4 IN. YELLOW WATERBORNE PAVEMENT	Material		9	Mar 4, 2024	SYSTEM	\$3,461.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stottt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
		MARKING			9	Mar 4, 2024	SYSTEM	(\$3,461.40)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0950 -	- Total						\$0.00	
	0970	COLDMILLING BIT. PAVT FOR REM OF SURF.	Overrun	Overrun	1	Jun 30, 2023	SYSTEM	(\$6,841.72)	
		REW OF SURF.		Overrun - T	otal			(\$6,841.72)	
			Overrun - T	otal				(\$6,841.72)	
	0970 -	· Total						(\$6,841.72)	
983528	Total							(\$23,862.30)	
JSE0084	1020	MISC. AGGREGATE FOR BASE	Material		4	Aug 16, 2023	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Aug 16, 2023	SYSTEM	(\$221,128.40)	
					5	Sep 5, 2023	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$221,128.40)	
					6	Sep 18, 2023	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Sep 18, 2023	SYSTEM	(\$221,128.40)	
					7	Dec 4, 2023	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$221,128.40)	
					8	Jan 2, 2024	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Jan 2, 2024	SYSTEM	(\$221,128.40)	
					9	Mar 4, 2024	SYSTEM	\$221,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Mar 4, 2024	SYSTEM	(\$221,128.40)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	1020 -	Total						\$0.00	
	1030	GRAVEL (A) OR CRUSHED STONE (B)	Material		4	Aug 16, 2023	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Aug 16, 2023	SYSTEM	(\$4,930.20)	
					5	Sep 5, 2023	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user collie1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$4,930.20)	
					6	Sep 18,	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSE0084	1030	GRAVEL (A) OR CRUSHED STONE	Material			2023			Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
		(B)			6	Sep 18, 2023	SYSTEM	(\$4,930.20)	
					7	Dec 4, 2023	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$4,930.20)	
					8	Jan 2, 2024	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Jan 2, 2024	SYSTEM	(\$4,930.20)	
					9	Mar 4, 2024	SYSTEM	\$4,930.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Mar 4, 2024	SYSTEM	(\$4,930.20)	
				- Total				\$0.00	
			Material - To					\$0.00	
	10 <u>30</u> -	· Total						\$0.00	
	1040	BITUMINOUS PAVEMENT	Price FUEL		2	Jul 17, 2023	SYSTEM	(\$1,945.62)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		MIXTURE PG64-22 (SUR			3	Aug 2, 2023	SYSTEM	(\$17,249.28)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				(\$19,194.90)	
			Price FUEL	- Total				(\$19,194.90)	
	1040 -	· Total						(\$19,194.90)	
	1050	TACK COAT - LOW OR NON- TRACKING	Material		2	Jul 17, 2023	SYSTEM	\$1,646.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$1,646.00)	
					3	Aug 2, 2023	SYSTEM	\$10,408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Aug 2, 2023	SYSTEM	(\$10,408.00)	
					4	Aug 16, 2023	SYSTEM	\$10,408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Aug 16, 2023	SYSTEM	(\$10,408.00)	
					5	Sep 5, 2023	SYSTEM	\$10,408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user collie1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$10,408.00)	
					6	Sep 18, 2023	SYSTEM	\$10,408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stottt1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					6	Sep 18, 2023	SYSTEM	(\$10,408.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1050 -	Total						\$0.00	
	1070	CONSTRUCTION SIGNS	Material		2	Jul 17, 2023	SYSTEM	\$5,889.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$5,889.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSE0084	1070 -	· Total						\$0.00	
	1110	TYPE III MOVEABLE BARRICADE	Material		2	Jul 17, 2023	SYSTEM	\$870.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stottt 1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$870.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1110	) - Total						\$0.00	
	1120	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material		2	Jul 17, 2023	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stottt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					2	Jul 17, 2023	SYSTEM	(\$6,000.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1120	· Total						\$0.00	
	1140	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Other Item Adjustment	REFL	4	Aug 16, 2023	collie1	\$2,777.22	20% deduct for retroreflectivity
				REFL - Tota	ıl			\$2,777.22	
			Other Item	Other Item Adjustment - Total				\$2,777.22	
	1140 -	· Total						\$2,777.22	
	1150	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		4	Aug 16, 2023	SYSTEM	\$2,716.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user collie1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					4	Aug 16, 2023	SYSTEM	(\$2,716.56)	
					5	Sep 5, 2023	SYSTEM	\$2,716.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user collie1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$2,716.56)	
					6	Sep 18, 2023	SYSTEM	\$2,716.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stottt1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					6	Sep 18, 2023	SYSTEM	(\$2,716.56)	
				- Total				\$0.00	
			Material - Total					\$0.00	
			Other Item Adjustment	REFL	4	Aug 16, 2023	collie1	\$543.31	20% deduct for retroreflectivity
				REFL - Total				\$543.31	
			Other Item	Other Item Adjustment - Total				\$543.31	
	1150	150 - Total							
	1160	8 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		4	Aug 16, 2023	SYSTEM	\$4,022.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	Aug 16, 2023	SYSTEM	(\$4,022.50)	
					5	Sep 5, 2023	SYSTEM	\$4,022.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user collie1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$4,022.50)	
					6	Sep 18, 2023	SYSTEM	\$4,022.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					6	Sep 18, 2023	SYSTEM	(\$4,022.50)	
					7	Dec 4, 2023	SYSTEM	\$4,022.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user collie1 overridding Payment Estimate Exception 19 on the current Payment Estimate.

Mar 11, 2024



## Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSE0084 11	1160	8 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		7	Dec 4, 2023	SYSTEM	(\$4,022.50)	
				- Total				\$0.00	
			Material - Total					\$0.00	
			Other Item Adjustment	REFL	4	Aug 16, 2023	collie1	\$804.50	20% deduct for retroreflectivity
				REFL - Total				\$804.50	
			Other Item Adjustment - Total					\$804.50	
	1160 -	Total						\$804.50	
JSE0084 - Total									
Overall -	Total						(\$38,932.17)		

## MoDOT

### Contract Adjustments for Contract - 230317-H03

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 21 of 21