

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 15, 2024

Progress Estir 5	mate Number	Contract ID Prime Contractor	230421-F05 Reinhold Electric, Inc.	Pay Period Start April 2, 20 Pay Period End April 15, 2		Original Contract Amount Net Change Order Amount Current Contract Amount	\$527,314.00 \$0.00 \$527,314.00	
Approval Date							By User	
April 16, 2024		G	Senerated and Approved	d (and should be con	sidered Draft) at	t the Project Office Level by	norton1	
April 17, 2024		Revie	ewed and Approved (and	d should be considered	ed Draft) at the l	Resident Engineer Level by	HELLET	
April 18, 2024			Reviewe	d and Approved at th	e Central Office	Controllers Office Level by	ramses1	
Original Comp	oletion Date	Current Completion Date Actual Completion Date % of Current Cont				of Current Contract Amount	Complete	
December 3	er 30, 2024 December 30, 2024 22.51%							

	Milestones		
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	May 3, 2023	May 3, 2023	
Letting Date	April 21, 2023	April 21, 2023	
Notice to Proceed Date	June 1, 2023	June 1, 2023	
Open to Traffic Date			
Work Began Date			

Contract Total Pay For Estimate No. 5				
	This Estimate	Previous	To Date	
230421-F05				
Total Posted Items Pay	\$0.00	\$118,721.00	\$118,721.00	
Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
		\$118,721.00	\$118,721.00	
Contract Total Payable This Estimate:	\$0.00			

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments Exist on Contract ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JSL0089	0070	LUMINAIRE, LED-A	Material			-72	\$518.00	(\$37,296.00)
	0070	LUMINAIRE, LED-A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	72	\$518.00	\$37,296.00
	0080	LUMINAIRE, LED-B	Material			-90	\$555.00	(\$49,950.00)
	0080	LUMINAIRE, LED-B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	90	\$555.00	\$49,950.00
	0100	MISC.	Material			-8	\$615.00	(\$4,920.00)
	0100	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user norton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	8	\$615.00	\$4,920.00
	0110	MISC.	Material			-33	\$625.00	(\$20,625.00)
	0110	MISC.	Material		This adjustment offsets the original system-	33	\$625.00	\$20,625.00

Revision 3/23/2023 Page 1 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 15, 2024

Progr		timate Number 5	Contract II Prime Con		421-F05 nhold Electric	, Inc. Pay Period End April 15, 2024 Net C	nal Contract hange Order ent Contract	r Amount	\$527,314.00 \$0.00 \$527,314.00
Project Number	Line No.	Item Descri	ption	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JSL0089						generated Material Payment Estimate Item Adjustment (0004) due to user norton1 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
	0130		MISC.	Material			-2	\$715.00	(\$1,430.00)
	0130		MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	2	\$715.00	\$1,430.00
	0170		MISC.	Material			-18	\$250.00	(\$4,500.00)
	0170		MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	18	\$250.00	\$4,500.00
Total									\$0.00

Revision 3/23/2023 Page 2 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Informatio	n	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work	
JSL0089	FAS- S503 (068)	Lighting improvements	Various	FRANKLIN	at various locations in	Franklin and Jefferson cou	unties	
otals by J	Job Numbe	ers						
JSL0089		d Harris Barri			This Estimate	Previous	To Date	

Totals by Job	Numbers			
JSL0089		This Estimate	Previous	To Date
	Posted Item Pay	\$0.00	\$118,721.00	\$118,721.00
	Gross Item Adjustments Gross Item Pay	\$0.00 \$0.00	\$0.00 \$118,721.00	\$0.00 \$118,721.00
			· · · ·	· ,
	Incentive Disincentive	\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00

Revision 3/23/2023 Page 3 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JSL0089, Item 9011311, Project Item Line Number 0070, Material Set 9011311, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on Material Certifications from the contractor to resolve this issue.	norton1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0089, Item 9011312, Project Item Line Number 0080, Material Set 9011312, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on Material Certifications from the contractor to resolve this issue.	norton1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0089, Item 9019902, Project Item Line Number 0100, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on Material Certifications from the contractor to resolve this issue.	norton1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0089, Item 9019902, Project Item Line Number 0110, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on Material Certifications from the contractor to resolve this issue.	norton1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0089, Item 9019902, Project Item Line Number 0130, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on Material Certifications from the contractor to resolve this issue.	norton1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0089, Item 9019902, Project Item Line Number 0170, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on Material Certifications from the contractor to resolve this issue.	norton1	Overridden

Revision 3/23/2023 Page 4 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230421-F05	JSL0089	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$1.00	\$0.00
		0001	0020	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	0.00	\$1,200.00	\$0.00
		0001	0030	6169901	MISC.LUMP SUM TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.00	\$4,500.00	\$0.00
		0001	0040	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$17,200.00	\$0.00
		0020	0050	9011030	LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT	1.00	0.00	1.00	EA	0.00	\$3,750.00	\$0.00
		0020	0060	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	6.00	0.00	6.00	EA	0.00	\$4,928.00	\$0.00
		0020	0070	9011311	LUMINAIRE, LED-A	185.00	0.00	185.00	EA	72.00	\$518.00	\$37,296.00
		0020	0080	9011312	LUMINAIRE, LED-B	178.00	0.00	178.00	EA	90.00	\$555.00	\$49,950.00
		0020	0090	9011313	LUMINAIRE, LED-C	63.00	0.00	63.00	EA	0.00	\$585.00	\$0.00
		0020	0100	9019902	MISC.150W TENON MOUNT LED LUMINAIRE	34.00	0.00	34.00	EA	8.00	\$615.00	\$4,920.00
		0020	0110	9019902	MISC.250W TENON MOUNT LED LUMINAIRE	135.00	0.00	135.00	EA	33.00	\$625.00	\$20,625.00
		0020	0120	9019902	MISC.30 FT LIGHTING POLE BASE	2.00	0.00	2.00	EA	0.00	\$2,420.00	\$0.00
		0020	0130	9019902	MISC.400W TENON MOUNT LED LUMINAIRE	53.00	0.00	53.00	EA	2.00	\$715.00	\$1,430.00
		0020	0140	9019902	MISC.45 FT LIGHTING POLE BASE	24.00	0.00	24.00	EA	0.00	\$2,545.00	\$0.00
		0020	0150	9019902	MISC.ADJUST LIGHTING FOUNDATIONS	2.00	0.00	2.00	EA	0.00	\$3,560.00	\$0.00
		0020	0160	9019902	MISC.LIGHTING BASE DOOR REPAIR	34.00	0.00	34.00	EA	0.00	\$250.00	\$0.00
		0020	0170	9019902	MISC.LIGHTING POLE BASE DOOR	50.00	0.00	50.00	EA	18.00	\$250.00	\$4,500.00
	Project JS	SL0089 - To	otal Value	Posted to E	Date as of Report Generated Date							\$118,721.00
230421-F05 Ove	rall - Total	Value Post	ed to Dat	te as of Repo	ort Generated Date							\$118,721.00

Revision 3/23/2023 Page 5 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Page 6 of 10 Revision 3/23/2023



Line Item Adjustments by Estimate

Contract ID: 230421-F05

ect Lin	ne Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
089 007	70 LUMINAIRE, LED-A	Material		2	Mar 4, 2024	SYSTEM	\$24,864.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
				2	Mar 4, 2024	SYSTEM	(\$24,864.00)								
				3	Mar 15, 2024	SYSTEM	\$29,008.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
				3	Mar 15, 2024	SYSTEM	(\$29,008.00)								
				4	Apr 2, 2024	SYSTEM	\$37,296.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
				4	Apr 2, 2024	SYSTEM	(\$37,296.00)								
				5	Apr 15, 2024	SYSTEM	\$37,296.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
				5	Apr 15, 2024	SYSTEM	(\$37,296.00)								
			- Total				\$0.00								
		Material - To					\$0.00								
00-	70 - Total														
							\$0.00								
800	30 LUMINAIRE, LED-B	Material		1	Feb 16, 2024	SYSTEM	\$16,095.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
				1	Feb 16, 2024	SYSTEM	(\$16,095.00)								
					2	Mar 4, 2024	SYSTEM	\$32,745.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
										2	Mar 4, 2024	SYSTEM	(\$32,745.00)		
				3	Mar 15, 2024	SYSTEM	(\$44,400.00)								
				4	Apr 2, 2024	SYSTEM	\$49,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.							
				4	Apr 2, 2024	SYSTEM	(\$49,950.00)								
				5	Apr 15, 2024	SYSTEM	\$49,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.							
				5	Apr 15, 2024	SYSTEM	(\$49,950.00)								
			- Total				\$0.00								
		Material - To	otal				\$0.00								
008	30 - Total						\$0.00								
				3	Mar 15,	SYSTEM	\$2,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user norton1 overridding Payment							
010	00 MISC. HIGHWAY LIGHTING	Material			2024			Estimate Exception 3 on the current Payment Estimate.							
	HIGHWAY			3	2024 Mar 15, 2024	SYSTEM	(\$2,460.00)								
	HIGHWAY				Mar 15,	SYSTEM SYSTEM	(\$2,460.00) \$4,920.00	Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment							
	HIGHWAY			3	Mar 15, 2024 Apr 2,		, , ,	Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user norton1 overridding Payment							



Line Item Adjustments by Estimate

Contract ID: 230421-F05

Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks					
,		·	Туре	Adjustment Type	Number	Date	Ву							
JSL0089	0100	MISC. HIGHWAY	Material			2024			Estimate Item Adjustment (0003) due to user norton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
		LIGHTING			5	Apr 15, 2024	SYSTEM	(\$4,920.00)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0100 -	Total						\$0.00						
	0110	MISC. HIGHWAY LIGHTING	Material		2	Mar 4, 2024	SYSTEM	\$4,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user norton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					2	Mar 4, 2024	SYSTEM	(\$4,375.00)						
						3	Mar 15, 2024	SYSTEM	\$6,875.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user norton1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
					3	Mar 15, 2024	SYSTEM	(\$6,875.00)						
					4	Apr 2, 2024	SYSTEM	\$20,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user norton1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					4	Apr 2, 2024	SYSTEM	(\$20,625.00)						
					5	Apr 15, 2024	SYSTEM	\$20,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user norton1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					5	Apr 15, 2024	SYSTEM	(\$20,625.00)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0110 -	Total						\$0.00						
	0130	MISC. HIGHWAY LIGHTING	Material		4	Apr 2, 2024	SYSTEM	\$1,430.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
										4	Apr 2, 2024	SYSTEM	(\$1,430.00)	
									5	Apr 15, 2024	SYSTEM	\$1,430.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					5	Apr 15, 2024	SYSTEM	(\$1,430.00)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0130 -	Total						\$0.00						
	0170	MISC. HIGHWAY LIGHTING	Material		1	Feb 16, 2024	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					1	Feb 16, 2024	SYSTEM	(\$750.00)						
					2	Mar 4, 2024	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user norton1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					2	Mar 4, 2024	SYSTEM	(\$3,250.00)						
			3	3	Mar 15, 2024	SYSTEM	\$3,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.						
					3	Mar 15, 2024	SYSTEM	(\$3,750.00)						
					4	Apr 2, 2024	SYSTEM	\$4,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate.					

Apr 19, 2024



Line Item Adjustments by Estimate

Contract ID: 230421-F05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSL0089	0170	MISC. HIGHWAY	Material		4	Apr 2, 2024	SYSTEM	(\$4,500.00)	
		LIGHTING			5	Apr 15, 2024	SYSTEM	\$4,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
						Apr 15, 2024	SYSTEM	(\$4,500.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0170 - Total							\$0.00	
JSL0089	JSL0089 - Total							\$0.00	
Overall -	Overall - Total								

MoDOT

Contract Adjustments for Contract - 230421-F05

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 10 of 10