

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 16, 2024

Progress Estimate Number			Pay Period Start January 2, 2024	•	' '
14	Prime Contractor N.E	.B. West Contracting Company	Pay Period End January 15, 2024	4 Net Change Order Amount \$	60.00
14				Current Contract Amount \$	28,247,068.30

By User		Approval Date
jamesc4	Generated and Approved (and should be considered Draft) at the Project Office Level by	January 16, 2024
REDHAC	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	January 16, 2024
ramses1	Reviewed and Approved at the Central Office Controllers Office Level by	January 17, 2024

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2024	November 1, 2024		30.39%

	Contract Informational Dat	tes	Milestones
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	May 3, 2023	May 3, 2023	
Letting Date	April 21, 2023	April 21, 2023	
Notice to Proceed Date	June 5, 2023	June 5, 2023	
Open to Traffic Date			
Work Began Date	June 27, 2023	June 27, 2023	

Contract Total Pay For Estimate No. 14			
	This Estimate	Previous	To Date
230421-F06			
Total Posted Items Pay	\$5,935.90	\$8,578,845.04	\$8,584,780.94
Gross Item Adjustments	\$0.00	\$551,450.85	\$551,450.85
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
		\$9,130,295.89	\$9,136,231.79
Contract Total Payable This Estimate:	\$5,935.90		

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6P3288	0180	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED $\!\!/$ RETAINED	LF	\$32.000	50	\$1,600.00
	0190	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	LF	\$10.000	50	\$500.00
	0230	6207001	PAVEMENT MARKING REMOVAL	LF	\$0.600	5,789	\$3,473.40
Project J6P32	288 - Total						\$5,573.40
J6S3283B	4130	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	LF	\$0.250	1,450	\$362.50
Project J6S32	283B - Total						\$362.50
Overall - Tota	ıl						\$5,935.90

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6P3288	0050	CONCRETE APPROACH PAVEMENT	Material			-1,371	\$181.00	(\$248,151.00)
	0050	CONCRETE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user jamesc4 overridding Payment Estimate Exception 9 on the current Payment Estimate.	1,371	\$181.00	\$248,151.00
	0800	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material			-1,100	\$4.00	(\$4,400.00)
	0800	FIELD APPLICATION OF	Material		This adjustment offsets the original system-	1,100	\$4.00	\$4,400.00

Revision 3/23/2023 Page 1 of 27



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 16, 2024

Progress Estimate Number
14

Contract ID 230421-F06 Pay Period Start January 2, 2024 Original Contract Amount \$28,247,068.30
Prime Contractor N.B. West Contracting Company Pay Period End January 15, 2024 Net Change Order Amount \$0.00
Current Contract Amount \$28,247,068.30

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
Number		INORGANIC ZINC PRIMER			generated Material Payment Estimate Item Adjustment (0001) due to user jamesc4 overridding Payment Estimate Exception 16 on the current Payment Estimate.			
	1040	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material			-1,100	\$4.00	(\$4,400.00
	1040	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 17 on the current Payment Estimate.	1,100	\$4.00	\$4,400.00
	1570	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material			-1,100	\$4.00	(\$4,400.00
	1570	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user jamesc4 overridding Payment Estimate Exception 18 on the current Payment Estimate.	1,100	\$4.00	\$4,400.00
	2220	OPEN CELL FOAM JOINT SEAL	Material			-98	\$52.00	(\$5,096.00)
	2220	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user jamesc4 overridding Payment Estimate Exception 20 on the current Payment Estimate.	98	\$52.00	\$5,096.00
	2440	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material			-1,400	\$4.00	(\$5,600.00)
	2440	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Exception 19 on the current Payment Estimate.	1,400	\$4.00	\$5,600.00
	2630	BRIDGE APPROACH SLAB (MAJOR)	Material			-89	\$492.00	(\$43,788.00)
	2630	BRIDGE APPROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user jamesc4 overridding Payment Estimate Exception 3 on the current Payment Estimate.	89	\$492.00	\$43,788.00
	3000	OPEN CELL FOAM JOINT SEAL	Material			-39.5	\$52.00	(\$2,054.00)
	3000	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment Estimate Exception 21 on the current Payment Estimate.	39.5	\$52.00	\$2,054.00
6S3283B	4130	4 IN TEMPORARY PAVEMENT MARKING PAINT	Material			-132,462.5	\$0.25	(\$33,115.62)
	4130	4 IN TEMPORARY PAVEMENT MARKING PAINT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 15 on the current Payment Estimate.	132,462.5	\$0.25	\$33,115.62
Total								\$0.00

Revision 3/23/2023 Page 2 of 27



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information		
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work	
J6P3288	FAF-21-2(87)	17 Bridge rehabilitations	21	JEFFERSON	at various loca	tions in Jefferson County		
J6S3283B	FAF-21-2(91)	Coldmill and resurface	21, Old 21	JEFFERSON	on Route 21 fro	om Meramec River to Schenk	Road and on Old Route 21 from Rou	ite 21 to Konert Roa
otals by J	ob Numbers							
J6P3288				TI	nis Estimate	Previous	To Date	
		Posted Item Pay Gross Item Adjustments Gross Item Pay			5,573.40 0.00 5, <b>573.40</b>	\$4,478,659.31 \$257,792.80 <b>\$4,736,452.11</b>	\$4,484,232.71 \$257,792.80 <b>\$4,742,025.51</b>	
	Incentive			\$(	0.00	\$0.00	\$0.00	
	Disincentive	e			0.00	\$0.00	\$0.00	
	Liquidated				0.00	\$0.00		
		ract Adjustmen	ts	\$0	0.00	\$0.00	\$0.00	
J6S3283B				т.	nis Estimate	Previous	To Date	1
JUUJZUJD	Posted Iten	n Pav			11s Estimate 362.50	\$4,100,185.73	\$4,100,548.23	
		Adjustments			0.00	\$293.658.05	\$293.658.05	
	Gross Rem		ss Item F		862.50	\$4,393,843.78	\$4,394,206.28	
	Incentive			\$0	0.00	\$0.00	\$0.00	
	Disincentive	е			0.00	\$0.00	\$0.00	
	Liquidated	Damages		\$0	0.00	\$0.00	\$0.00	

Revision 3/23/2023 Page 3 of 27



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 2169903, Project Item Line Number 2620, Material Set 2169903, Material 0704CMRP - Rapid Set Concrete Patching Material, Acceptance Action Generic 0704CMRP is insufficient.	Working with contractor to resolve	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3283B, Item 4030003, Project Item Line Number 3890, Material Set 403000396, Material 0403SP095C - Superpave 9.5 mm, Des C, Acceptance Action Generic AspHigh is insufficient.	Working with contractor to resolve	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 5031010A, Project Item Line Number 2630, Material Set 5031010A96, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Working with contractor to resolve	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 5031010A, Project Item Line Number 2630, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Working with contractor to resolve	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 5031010A, Project Item Line Number 2630, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Working with contractor to resolve	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 5031010A, Project Item Line Number 2630, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with contractor to resolve	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 5031010A, Project Item Line Number 2630, Material Set 5031010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Working with contractor to resolve	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 5031010A, Project Item Line Number 2630, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	Working with contractor to resolve	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 5041000, Project Item Line Number 0050, Material Set 504100096, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Working with contractor to resolve	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 5041000, Project Item Line Number 0050, Material Set 504100096, Material 0501CCPAQCQA - Concrete, Payment contractor mix or QCQA, Acceptance Action 0501CCPAQCQA Payement is insufficient.	Working with contractor to resolve	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 5041000, Project Item Line Number 0050, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Working with contractor to resolve	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 5041000, Project Item Line Number 0050, Material Set 504100096, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with contractor to resolve	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 5052000, Project Item Line Number 3770, Material Set 505200096, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Working with SL materials to resolve	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 6092011, Project Item Line Number 0070, Material Set 609201196, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Working with contractor to resolve	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3283B, Item 6208076, Project Item Line Number 4130, Material Set 6208076, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Sample record forthcoming	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 7125210, Project Item Line Number 0800, Material Set 712521096, Material 1045PTIZ - High Solids Inorganic Zinc Silicat Paint, Acceptance Action Generic 1045PTIZ is insufficient.	Change order forthcoming	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 7125210, Project Item Line Number 1040, Material Set 712521096, Material 1045PTIZ - High Solids Inorganic Zinc Silicat Paint, Acceptance Action Generic 1045PTIZ is insufficient.	Change order forthcoming	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 7125210, Project Item Line Number 1570, Material Set 712521096, Material 1045PTIZ - High Solids Inorganic Zinc Silicat Paint, Acceptance Action Generic 1045PTIZ is insufficient.	Change order forthcoming	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 7125210, Project Item Line Number 2440, Material Set 712521096, Material 1045PTIZ - High Solids Inorganic Zinc Silicat Paint, Acceptance Action Generic 1045PTIZ is insufficient.	Change order forthcoming	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 7172054, Project Item Line Number 2220, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	Working with contractor to resolve	jamesc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 7172054, Project Item Line Number 3000, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	Working with contractor to resolve	jamesc4	Overridden
Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 1230, Contract Line Item Number 1230, Item 5050004, Minor Item.	Change order forthcoming	jamesc4	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2250, Contract Line Item Number 2250, Item 5050004, Minor Item.	Change order forthcoming	jamesc4	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2660, Contract Line Item Number 2660, Item 7040101, Minor Item.	Change order forthcoming	jamesc4	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3020, Contract Line Item Number 3020, Item 5050004, Minor Item.	Change order forthcoming	jamesc4	Acknowledged

Revision 3/23/2023 Page 4 of 27



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3760, Contract Line Item Number 3760, Item 5050004, Minor Item.	Change order forthcoming	jamesc4	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Line Number 3950, Contract Line Item Number 3950, Item 6131010, Minor Item.	Change order forthcoming	jamesc4	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Line Number 3980, Contract Line Item Number 3980, Item 6131014, Minor Item.	Change order forthcoming	jamesc4	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Line Number 4010, Contract Line Item Number 4010, Item 6133019, Minor Item.	Change order forthcoming	jamesc4	Acknowledged

Revision 3/23/2023 Page 5 of 27



### Total Paid / All Items / All Estimates (Including this Estimate)

Contract .CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POST To Date (See rep generated date
421-F06	J6P3288	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.40	\$295,000.00	\$118,00
		0001	0015	2079909	MISC.MODIFIED LINEAR GRADING	259.80	0.00	259.80	STA	0.00	\$1,189.50	\$
		0001	0020	2159910	MISC.SHAPING SLOPES, CLASS III (MODIFIED)	194.00	0.00	194.00	100F	48.00	\$750.00	\$36,00
		0001	0025	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	29,076.00	0.00	29,076.00	SQYD	0.00	\$19.45	\$
		0001	0030	4010150	TYPE A2 SHOULDER	29,075.90	0.00	29,075.90	SQYD	0.00	\$25.00	\$
		0001	0040	4136000	PCCP JOINT/CRACK SEALING	13,050.00	0.00	13,050.00	LF	0.00	\$3.00	\$
		0001	0050	5041000	CONCRETE APPROACH PAVEMENT	2,742.60	0.00	2,742.60	SQYD	1,371.00	\$181.00	\$248,15
		0001	0060	6091041	CONCRETE GUTTER TYPE A	280.00	0.00	280.00	LF	0.00	\$145.00	
		0001	0070	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	250.00	0.00	250.00	LF	62.50	\$62.00	\$3,8
		0001	0080	6113020	FURNISHING TYPE 2 ROCK BLANKET	53.00	0.00	53.00	CUYD	0.00	\$45.00	
		0001	0090	6113040	PLACING TYPE 2 ROCK BLANKET	53.00	0.00	53.00	CUYD	0.00	\$301.00	
		0001	0100	6116010A	SLOPE PROTECTION	37.00	0.00	37.00	SQYD	0.00	\$829.00	
		0001	0110	6122010	IMPACT ATTENUATOR 50 MPH (SAND BARREL ARRAY)	8.00	0.00	8.00	EA	0.00	\$1,500.00	
		0001	0120	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	13.00	0.00	13.00	EA	6.00	\$1,500.00	\$9,0
		0001	0130	6122020	REPLACEMENT SAND BARREL	21.00	0.00	21.00	EA	0.00	\$250.00	
		0001	0140	6122030	IMPACT ATTENUATOR (RELOCATION)	21.00	0.00	21.00	EA	6.00	\$1,000.00	\$6,0
		0001	0150	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	4.00	0.00	4.00	EA	0.00	\$5,000.00	
		0001	0155	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$10,000.00	\$20,0
		0001	0160	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$120,000.00	\$60,
		0001	0170	6169902	MISC.NTICP COMPLIANT CHANGEABLE MESSAGE SIGN	4.00	0.00	4.00	EA	3.00	\$2,500.00	\$7,
		0001	0180	6173600D	(CONTRACTOR FURNISHED AND RETAINED) TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	12,175.00	0.00	12,175.00	LF	5,337.50	\$32.00	\$170,
		0001	0190	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	12,175.00	0.00	12,175.00	LF	5,337.50	\$10.00	\$53,
		0001	0200	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$1,550,000.00	\$1,162,
		0001	0210	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	57,350.00	0.00	57,350.00	LF	3,094.00	\$2.00	\$6,
		0001	0220	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	57,350.00	0.00	57,350.00	LF	2,751.00	\$2.00	\$5,
		0001	0230	6207001	PAVEMENT MARKING REMOVAL	129,037.00	0.00	129,037.00	LF	8,838.00	\$0.60	\$5,
		0001	0240	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	129,037.00	0.00	129,037.00	LF	32,661.00	\$1.00	\$32,
		0001	0250	6214600A	FLOWABLE BACKFILL	45.00	0.00	45.00	CUYD	15.00	\$824.00	\$12,
		0001	0260	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	605.00	0.00	605.00	SQYD	0.00	\$35.00	
		0001	0270	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$5,000.00	
		0010	0280	6061060	MGS GUARDRAIL	14,550.00	0.00	14,550.00	LF	3,425.00	\$25.00	\$85,
		0010	0290	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	47.00	0.00	47.00	EA	8.00	\$3,600.00	\$28,
		0010	0300	6061074	MGS HEIGHT AND BLOCK TRANSITION	1.00	0.00	1.00	EA	0.00	\$650.00	
		0010	0310	6061080	MGS END ANCHOR	13.00	0.00	13.00	EA	2.00	\$1,400.00	\$2,
		0010	0320	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	34.00	0.00	34.00	EA	6.00	\$3,000.00	\$18,
		0040	0330	9031270A	2 IN. PSST POST - 12 GA.	418.00	0.00	418.00	LF	0.00	\$20.00	
		0040	0340	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	114.00	0.00	114.00	EA	0.00	\$150.00	
		0040	0350	9035069A	SHF-FLAT SHEET FLUORESCENT	140.00	0.00	140.00	SQFT	0.00	\$28.00	
		0050	0360	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	0.00	\$16,000.00	
		0050	0370	2161501	REMOVAL OF ASPHALT WEARING SURFACE	12,569.00	0.00	12,569.00	SQFT	12,569.00	\$1.75	\$21,
		0050	0380	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$52,000.00	
		0050	0390	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	123.00	0.00	123.00	LF	0.00	\$631.00	
			0400	2169903	CONCRETE  MISC.Remove and Replace Barrier Curb	16.00	0.00	16.00	LF	0.00	\$1,001.00	
		0050										
		0050	0410	5031010A	BRIDGE APPROACH SLAB (MAJOR)	178.00	0.00	178.00	SQYD	0.00	\$492.00	
		0050	0420	7031004	DIAMOND GRINDING	1,382.00	0.00	1,382.00	SQYD	0.00	\$9.75	
		0050	0430	7034214	CLASS B-2 CONCRETE	33.00	0.00	33.00	CUYD	0.00	\$2,700.00	

Revision 3/23/2023 Page 6 of 27



### Total Paid / All Items / All Estimates (Including this Estimate)

No.		Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See report generated date)
J6P3288	0050	0440	7040101	SUBSTRUCTURE REPAIR (FORMED)	20.00	0.00	20.00	SQFT	0.00	\$169.00	\$0.0
	0050	0450	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	31.00	0.00	31.00	SQFT	0.00	\$173.25	\$0.0
	0050	0460	7040113	CLEANING AND EPOXY COATING	200.00	0.00	200.00	SQFT	0.00	\$30.00	\$0.0
	0050	0470	7061070	MECHANICAL BAR SPLICE	64.00	0.00	64.00	EA	0.00	\$12.80	\$0.0
	0050	0480	7101000	REINFORCING STEEL (EPOXY COATED)	3,670.00	0.00	3,670.00	LB	0.00	\$2.35	\$0.0
	0050	0490	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$17,500.00	\$0.0
	0050	0500	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1,100.00	0.00	1,100.00	SQFT	0.00	\$70.00	\$0.0
	0050	0510	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,100.00	0.00	1,100.00	SQFT	0.00	\$4.00	\$0.0
	0050	0520	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$3.00	\$0.0
	0050	0530	7125370A	FINISH FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$2.00	\$0.0
	0050	0540	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	61.00	0.00	61.00	LF	0.00	\$488.00	\$0.0
	0050	0550	7172054	OPEN CELL FOAM JOINT SEAL	61.00	0.00	61.00	LF	0.00	\$52.00	\$0.0
	0051	0560	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,382.00	0.00	1,382.00	SQYD	667.30	\$60.00	\$40,038.0
	0051	0570	2161503	REMOVAL OF EXISTING DECK REPAIR	50.00	0.00	50.00	SQFT	0.00	\$31.00	\$0.0
	0051	0580	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	8.00	0.00	8.00	CY	4.29	\$700.00	\$3,003.0
	0051	0590	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,382.00	0.00	1,382.00	SQYD	1,382.00	\$118.00	\$163,076.0
	0051	0600	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$139.00	\$0.0
	0053	0650	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	0.00	\$16,000.00	\$0.0
	0053	0660	2161501	REMOVAL OF ASPHALT WEARING SURFACE	10,868.00	0.00	10,868.00	SQFT	0.00	\$2.00	\$0.
	0053	0670	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$47,000.00	\$0.
	0053	0680	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	112.00	0.00	112.00	LF	0.00	\$631.00	\$0.
	0053	0690	2169903		15.00	0.00	15.00	LE	0.00	\$1.001.00	\$0.
											\$0.
											\$0.
											\$0.
											\$0.
											\$0.
											\$0.
											\$0
											\$0.
	0053	0780	7110200	(EPOXY)	1.00	0.00	1.00	LS	0.00	\$17,500.00	\$0.
	0053	0790	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1,100.00	0.00	1,100.00	SQFT	1,100.00	\$70.00	\$77,000.
	0053	0800	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,100.00	0.00	1,100.00	SQFT	1,100.00	\$4.00	\$4,400.
	0053	0810	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$3.00	\$0
	0053	0820	7125370A	FINISH FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$2.00	\$0
	0053	0830	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	56.00	0.00	56.00	LF	0.00	\$488.00	\$0
	0053	0840	7172054	OPEN CELL FOAM JOINT SEAL	56.00	0.00	56.00	LF	0.00	\$52.00	\$0
	0054	0850	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,194.00	0.00	1,194.00	SQYD	0.00	\$60.00	\$0
	0054	0860	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	5.00	0.00	5.00	CY	0.00	\$700.00	\$0
	0054	0870	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,194.00	0.00	1,194.00	SQYD	0.00	\$118.00	\$0
	0054	0880	7040106	FULL DEPTH REPAIR	25.00	0.00	25.00	SQFT	0.00	\$139.00	\$0
	0056	0930	2161000	SCARIFICATION OF BRIDGE DECK	1,160.00	0.00	1,160.00	SQYD	0.00	\$13.00	\$0
	0056	0940	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	72.00	0.00	72.00	LF	0.00	\$631.00	\$0
	0056	0950	2169903	CONCRETE  MISC.Remove and Replace Barrier Curb	12.00	0.00	12.00	LF	0.00	\$1,001.00	\$0.
	0056	0960	7031004	DIAMOND GRINDING	1,160.00	0.00	1,160.00	SQYD	0.00	\$9.75	\$0.
	J6P3288	0050 0050 0050 0050 0050 0050 0050 005	0050         0450           0050         0460           0050         0470           0050         0480           0050         0490           0050         0500           0050         0510           0050         0520           0050         0530           0050         0540           0050         0550           0051         0560           0051         0580           0051         0580           0053         0660           0053         0660           0053         0660           0053         0670           0053         0670           0053         0700           0053         0700           0053         0710           0053         0720           0053         0750           0053         0750           0053         0760           0053         0760           0053         0760           0053         0760           0053         0760           0053         0790           0053         0790           0053 <td>0050         0450         7040102           0050         0460         7040113           0050         0470         7061070           0050         0480         7101000           0050         0490         7110200           0050         0500         7125201           0050         0550         7125306A           0050         0530         7125370A           0050         0540         7172001           0050         0550         7172054           0051         0560         2161001           0051         0560         2161503           0051         0580         5050004           0051         0580         5052000           0051         0580         5052000           0053         0660         2161501           0053         0660         2164501           0053         0660         2164500           0053         0660         2164500           0053         0660         2164500           0053         0690         2169903           0053         0700         5031010A           0053         0700         7034214</td> <td>0050         0450         7040102         SUBSTRUCTURE REPAIR (UNFORMED)           0050         0460         7040113         CLEANING AND EPOXY COATING           0050         0470         7051070         MECHANICAL BAR SPLICE           0050         0480         7101000         REINFORCING STEEL (EPOXY COATED)           0050         0490         7110200         PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)           0050         0590         7125200         SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL           0050         05910         7125210         FIELD APPLICATION OF INORGANIC ZINC PRIMER           0050         0590         7125370A         FINISH FIELD COAT (SYSTEM G)           0050         0530         7125370A         FINISH FIELD COAT (SYSTEM G)           0050         0550         7172001         STRIP SEAL EXPANSION JOINT SYSTEM           0051         0550         7172004         PEND CELL FOAM JOINT SEAL           0051         0550         7172004         PEND CELL FOAM JOINT SEAL           0051         0560         2161001         TOTAL SURFACE HYDRO DEMOLITION           0051         0560         2161001         TOTAL SURFACE HYDRO DEMOLITION           0051         0560         5050000         LATEX MODIFIED</td> <td>0050         0450         7040102         SUBSTRUCTURE REPAIR (UNFORMED)         31.00           0050         0460         7040113         CLEANING AND EPOXY COATING         200.00           0050         0470         7061070         MECHANICAL BAR SPLICE         46.00           0050         0480         7101000         REINFORCING STELL (EPOXY COATED)         3,670.00           0050         0490         7110200         REPOXETIVE COATING - CONCRETE BENTS AND PIERS         1.00           0050         0500         7125201         PIELD APPLICATION OF INORGANIC ZINO PRIMER         1.100.00           0050         0510         7125201         PIELD APPLICATION OF INORGANIC ZINO PRIMER         1.100.00           0050         0520         7125305A         INTERMEDIATE FIELD COAT (SYSTEM G)         1.100.00           0050         0520         7125305A         INTERMEDIATE FIELD COAT (SYSTEM G)         1.100.00           0051         0550         7172001         STRIP SEAL EXPANSION JOINT SYSTEM         61.00           0051         0560         7172001         STRIP SEAL EXPANSION JOINT SYSTEM         61.00           0051         0560         2161503         REMOVAL OF EXISTING EXPANSION JOINT SYSTEM         61.00           0051         0560</td> <td>  JAMES   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982  </td> <td>  JERS   1955   0.440   70.49191   SUBSTRUCTURE REPAIR (PORMED)   20.00   0.00   20.00   20.00   20.00   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.</td> <td>  1987-2088   0.0500</td> <td>  March   Marc</td> <td>                                     </td>	0050         0450         7040102           0050         0460         7040113           0050         0470         7061070           0050         0480         7101000           0050         0490         7110200           0050         0500         7125201           0050         0550         7125306A           0050         0530         7125370A           0050         0540         7172001           0050         0550         7172054           0051         0560         2161001           0051         0560         2161503           0051         0580         5050004           0051         0580         5052000           0051         0580         5052000           0053         0660         2161501           0053         0660         2164501           0053         0660         2164500           0053         0660         2164500           0053         0660         2164500           0053         0690         2169903           0053         0700         5031010A           0053         0700         7034214	0050         0450         7040102         SUBSTRUCTURE REPAIR (UNFORMED)           0050         0460         7040113         CLEANING AND EPOXY COATING           0050         0470         7051070         MECHANICAL BAR SPLICE           0050         0480         7101000         REINFORCING STEEL (EPOXY COATED)           0050         0490         7110200         PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)           0050         0590         7125200         SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL           0050         05910         7125210         FIELD APPLICATION OF INORGANIC ZINC PRIMER           0050         0590         7125370A         FINISH FIELD COAT (SYSTEM G)           0050         0530         7125370A         FINISH FIELD COAT (SYSTEM G)           0050         0550         7172001         STRIP SEAL EXPANSION JOINT SYSTEM           0051         0550         7172004         PEND CELL FOAM JOINT SEAL           0051         0550         7172004         PEND CELL FOAM JOINT SEAL           0051         0560         2161001         TOTAL SURFACE HYDRO DEMOLITION           0051         0560         2161001         TOTAL SURFACE HYDRO DEMOLITION           0051         0560         5050000         LATEX MODIFIED	0050         0450         7040102         SUBSTRUCTURE REPAIR (UNFORMED)         31.00           0050         0460         7040113         CLEANING AND EPOXY COATING         200.00           0050         0470         7061070         MECHANICAL BAR SPLICE         46.00           0050         0480         7101000         REINFORCING STELL (EPOXY COATED)         3,670.00           0050         0490         7110200         REPOXETIVE COATING - CONCRETE BENTS AND PIERS         1.00           0050         0500         7125201         PIELD APPLICATION OF INORGANIC ZINO PRIMER         1.100.00           0050         0510         7125201         PIELD APPLICATION OF INORGANIC ZINO PRIMER         1.100.00           0050         0520         7125305A         INTERMEDIATE FIELD COAT (SYSTEM G)         1.100.00           0050         0520         7125305A         INTERMEDIATE FIELD COAT (SYSTEM G)         1.100.00           0051         0550         7172001         STRIP SEAL EXPANSION JOINT SYSTEM         61.00           0051         0560         7172001         STRIP SEAL EXPANSION JOINT SYSTEM         61.00           0051         0560         2161503         REMOVAL OF EXISTING EXPANSION JOINT SYSTEM         61.00           0051         0560	JAMES   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982   1982	JERS   1955   0.440   70.49191   SUBSTRUCTURE REPAIR (PORMED)   20.00   0.00   20.00   20.00   20.00   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.50   0.	1987-2088   0.0500	March   Marc	

Revision 3/23/2023 Page 7 of 27



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract LCONTRACT	Project No.	Category	Line No.	Item Code	port Generated date and can differ from the posted amo Description	Bid Quantity	Net Change	Total Current	Unit	Total Posted	Unit Price	Total Value POST To Date (See rep
	No.		110.	5006		Squartity	Order	Quantity		Approved Qty		generated date
)421-F06	J6P3288	0056	0970	7034214	CLASS B-2 CONCRETE	6.80	0.00	6.80	CUYD	0.00	\$4,025.00	\$
		0056	0980	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	59.00	0.00	59.00	SQFT	0.00	\$173.25	\$
		0056	0990	7040110	EPOXY PRESSURE INJECTING	104.00	0.00	104.00	LF	0.00	\$52.50	\$
		0056	1000	7040113	CLEANING AND EPOXY COATING	100.00	0.00	100.00	SQFT	0.00	\$30.00	\$
		0056	1010	7101000	REINFORCING STEEL (EPOXY COATED)	710.00	0.00	710.00	LB	0.00	\$2.35	\$
		0056	1020	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$7,000.00	\$
		0056	1030	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEFI	1,100.00	0.00	1,100.00	SQFT	1,100.00	\$70.00	\$77,00
		0056	1040	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,100.00	0.00	1,100.00	SQFT	1,100.00	\$4.00	\$4,40
		0056	1050	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$3.00	
		0056	1060	7125370A	FINISH FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$2.00	
		0056	1070	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	67.00	0.00	67.00	LF	0.00	\$488.00	
		0057	1080	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,160.00	0.00	1,160.00	SQYD	0.00	\$60.00	
		0057	1090	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	0.00	4.00	CY	0.00	\$700.00	
		0057	1100	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,160.00	0.00	1,160.00	SQYD	0.00	\$118.00	
		0057	1110	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$139.00	
		0059	1160	2161501	REMOVAL OF ASPHALT WEARING SURFACE	14,109.00	0.00	14,109.00	SQFT	14,109.00	\$1.75	\$24,6
		0059	1170	7031004	DIAMOND GRINDING	1,568.00	0.00	1,568.00	SQYD	0.00	\$9.75	
		0059	1180	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	12.00	0.00	12.00	SQFT	0.00	\$173.25	
		0059	1190	7040110	EPOXY PRESSURE INJECTING	30.00	0.00	30.00	LF	0.00	\$52.50	
		0059	1200	7049903	MISC.Barrier Curb Repair	51.00	0.00	51.00	LF	38.90	\$349.00	\$13,5
		0059	1210	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$10,500.00	****
		0060	1220	2161001	(EPOXY) TOTAL SURFACE HYDRO DEMOLITION	1,568.00	0.00	1,568.00	SQYD	1,568.00	\$60.00	\$94,
		0060	1230	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	0.00	3.00	CY	43.93	\$700.00	\$30,
		0060	1240	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,568.00	0.00	1,568.00	SQYD	1,568.00	\$118.00	\$185,
		0062	1280	2161501	REMOVAL OF ASPHALT WEARING SURFACE	13,604.00	0.00	13,604.00	SQFT	0.00	\$1.75	ψ100,
		0062	1290	7031004	DIAMOND GRINDING	1,512.00	0.00	1,512.00	SQYD	0.00	\$9.75	
		0062	1300	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	12.00	0.00	12.00	SQFT	0.00	\$173.25	
			1310	7040102	EPOXY PRESSURE INJECTING	35.00	0.00	35.00	LF	0.00	\$52.50	
		0062										
		0062	1320	7049903	MISC.Barrier Curb Repair	10.00	0.00	10.00	LF	0.00	\$349.00	
		0062	1330	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,500.00	
		0063	1340	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,512.00	0.00	1,512.00	SQYD	0.00	\$60.00	
		0063	1350	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	0.00	3.00	CY	0.00	\$700.00	
		0063	1360	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,512.00	0.00	1,512.00	SQYD	0.00	\$118.00	
		0065	1400	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	0.00	\$16,000.00	
		0065	1410	2161501	REMOVAL OF ASPHALT WEARING SURFACE	9,986.00	0.00	9,986.00	SQFT	0.00	\$2.00	
		0065	1420	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$64,000.00	
		0065	1430	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	123.00	0.00	123.00	LF	0.00	\$631.00	
		0065	1440	2169903	MISC.Remove and Replace Barrier Curb	19.00	0.00	19.00	LF	0.00	\$1,001.00	
		0065	1450	5031010A	BRIDGE APPROACH SLAB (MAJOR)	177.00	0.00	177.00	SQYD	0.00	\$492.00	
		0065	1460	7031004	DIAMOND GRINDING	1,088.00	0.00	1,088.00	SQYD	0.00	\$9.75	
		0065	1470	7034214	CLASS B-2 CONCRETE	50.10	0.00	50.10	CUYD	0.00	\$1,752.00	
		0065	1480	7040101	SUBSTRUCTURE REPAIR (FORMED)	65.00	0.00	65.00	SQFT	0.00	\$169.00	
		0065	1490	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	90.00	0.00	90.00	SQFT	0.00	\$173.25	
		0065	1500	7040107	SLAB EDGE REPAIR (BRIDGES)	5.00	0.00	5.00	LF	0.00	\$410.00	
		0065	1510	7040110	EPOXY PRESSURE INJECTING	24.00	0.00	24.00	LF	0.00	\$52.50	

Revision 3/23/2023 Page 8 of 27



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					port Generated date and can differ from the posted amo							
Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
0421-F06	J6P3288	0065	1530	7061070	MECHANICAL BAR SPLICE	37.00	0.00	37.00	EA	0.00	\$12.80	\$0.
		0065	1540	7101000	REINFORCING STEEL (EPOXY COATED)	4,580.00	0.00	4,580.00	LB	0.00	\$2.35	\$0.
		0065	1550	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$14,000.00	\$0.
		0065	1560	7125200	(EPOXY) SURFACE PREPARATION FOR RECOATING STRUCTURAL	1,100.00	0.00	1,100.00	SQFT	1,100.00	\$70.00	\$77,000
		0065	1570	7125210	STEEL FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,100.00	0.00	1,100.00	SQFT	1,100.00	\$4.00	\$4,400
		0065	1580	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$3.00	\$1,100
		0065	1590	7125370A	FINISH FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$2.00	\$0
		0065	1600	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	61.00	0.00	61.00	LF	0.00	\$488.00	\$1
		0065	1610	7172054	OPEN CELL FOAM JOINT SEAL	61.00	0.00	61.00	LF	0.00	\$52.00	\$
		0066	1620	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,088.00	0.00	1,088.00	SQYD	0.00	\$60.00	\$
		0066	1630	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	0.00	100.00	SQFT	0.00	\$31.00	\$
		0066	1640	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	7.00	0.00	7.00	CY	0.00	\$700.00	\$
		0066	1650	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,088.00	0.00	1.088.00	SQYD	0.00	\$118.00	\$
		0066	1660	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$139.00	\$
		0068	1710	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	0.50	\$16,000.00	\$8,00
		0068	1720	2161501	REMOVAL OF ASPHALT WEARING SURFACE	10,771.00	0.00	10,771.00	SQFT	10,771.00	\$2.00	\$21,54
		0068	1730	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$75,000.00	\$
		0068	1740	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	145.00	0.00	145.00	LF	0.00	\$631.00	\$
					CONCRETE				LF			\$
		0068	1750	2169903	MISC.Remove and Replace Barrier Curb	63.00	0.00	63.00		0.00	\$1,001.00	
		0068	1760	5031010A	BRIDGE APPROACH SLAB (MAJOR)	177.00	0.00	177.00	SQYD	0.00	\$492.00	
		0068	1770	7031004	DIAMOND GRINDING	1,183.00	0.00	1,183.00	SQYD	0.00	\$9.75	
		0068	1780	7034214	CLASS B-2 CONCRETE	57.90	0.00	57.90	CUYD	0.00	\$1,752.00	
		0068	1790	7040101	SUBSTRUCTURE REPAIR (FORMED)	19.00	0.00	19.00	SQFT	0.00	\$169.00	
		0068	1800	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	5.00	0.00	5.00	SQFT	0.00	\$173.25	
		0068	1810	7040107	SLAB EDGE REPAIR (BRIDGES)	20.00	0.00	20.00	LF	0.00	\$410.00	
		0068	1820	7040110	EPOXY PRESSURE INJECTING	70.00	0.00	70.00	LF	0.00	\$52.50	
		0068	1830	7040113	CLEANING AND EPOXY COATING	100.00	0.00	100.00	SQFT	0.00	\$30.00	
		0068	1840	7061070	MECHANICAL BAR SPLICE	37.00	0.00	37.00	EA	0.00	\$12.80	
		0068	1850	7101000	REINFORCING STEEL (EPOXY COATED)	4,410.00	0.00	4,410.00	LB	0.00	\$2.35	
		0068	1860	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$14,000.00	
		0068	1870	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1,200.00	0.00	1,200.00	SQFT	0.00	\$70.00	
		0068	1880	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,200.00	0.00	1,200.00	SQFT	0.00	\$4.00	
		0068	1890	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,200.00	0.00	1,200.00	SQFT	0.00	\$3.00	
		0068	1900	7125370A	FINISH FIELD COAT (SYSTEM G)	1,200.00	0.00	1,200.00	SQFT	0.00	\$2.00	
		0068	1910	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	71.00	0.00	71.00	LF	0.00	\$488.00	
		0068	1920	7172054	OPEN CELL FOAM JOINT SEAL	74.00	0.00	74.00	LF	0.00	\$52.00	
		0069	1930	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,183.00	0.00	1,183.00	SQYD	1,183.00	\$60.00	\$70,9
		0069	1940	2161503	REMOVAL OF EXISTING DECK REPAIR	50.00	0.00	50.00	SQFT	0.00	\$31.00	
		0069	1950	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	6.00	0.00	6.00	CY	0.00	\$700.00	
		0069	1960	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,183.00	0.00	1,183.00	SQYD	1,183.00	\$118.00	\$139,5
		0069	1970	7040106	FULL DEPTH REPAIR	25.00	0.00	25.00	SQFT	0.00	\$139.00	
		0071	2020	2161501	REMOVAL OF ASPHALT WEARING SURFACE	13,440.00	0.00	13,440.00	SQFT	0.00	\$1.75	
		0071	2030	2169903	MISC.Remove and Replace Barrier Curb	20.00	0.00	20.00	LF	0.00	\$1,001.00	
		0071	2040	7031004	DIAMOND GRINDING	1,493.00	0.00	1,493.00	SQYD	0.00	\$9.75	
		0071	2050	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	8.00	0.00	8.00	SQFT	0.00	\$173.25	
		0071	2060	7040107	SLAB EDGE REPAIR (BRIDGES)	20.00	0.00	20.00	LF	0.00	\$410.00	

Revision 3/23/2023 Page 9 of 27



### Total Paid / All Items / All Estimates (Including this Estimate)

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTO Date (See rep
421-F06	J6P3288	0071	2070	7040110	EPOXY PRESSURE INJECTING	20.00	0.00	20.00	LF	0.00	\$52.50	\$
		0071	2080	7049903	MISC.Barrier Curb Repair	4.00	0.00	4.00	LF	0.00	\$349.00	\$
		0071	2090	7129902	MISC.Cored Slab Drains	1.00	0.00	1.00	EA	0.00	\$1,984.00	\$
		0071	2100	7172054	OPEN CELL FOAM JOINT SEAL	93.00	0.00	93.00	LF	0.00	\$52.00	\$
		0072	2110	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,493.00	0.00	1,493.00	SQYD	0.00	\$60.00	\$
		0072	2120	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	0.00	3.00	CY	0.00	\$700.00	
		0072	2130	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,493.00	0.00	1,493.00	SQYD	0.00	\$118.00	
		0074	2170	2161501	REMOVAL OF ASPHALT WEARING SURFACE	14,179.00	0.00	14,179.00	SQFT	14,178.00	\$1.75	\$24,8
		0074	2180	7031004	DIAMOND GRINDING	1,575.00	0.00	1,575.00	SQYD	0.00	\$9.75	
		0074	2190	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	9.00	0.00	9.00	SQFT	0.00	\$173.25	
		0074	2200	7040110	EPOXY PRESSURE INJECTING	28.00	0.00	28.00	LF	0.00	\$52.50	
		0074	2210	7049903	MISC.Barrier Curb Repair	4.00	0.00	4.00	LF	0.00	\$349.00	
		0074	2220	7172054	OPEN CELL FOAM JOINT SEAL	98.00	0.00	98.00	LF	98.00	\$52.00	\$5,0
		0075	2230	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,575.00	0.00	1,575.00	SQYD	1,575.00	\$60.00	\$94,
		0075	2240	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	0.00	100.00	SQFT	0.00	\$31.00	
		0075	2250	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	0.00	3.00	CY	16.81	\$700.00	\$11,
		0075	2260	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,575.00	0.00	1,575.00	SQYD	1,575.00	\$118.00	\$185,
		0075	2270	7040106	FULL DEPTH REPAIR	25.00	0.00	25.00	SQFT	0.00	\$139.00	
		0077	2320	2161501	REMOVAL OF ASPHALT WEARING SURFACE	13,271.00	0.00	13,271.00	SQFT	0.00	\$1.80	
		0077	2330	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	86.00	0.00	86.00	LF	0.00	\$631.00	
		0077	2340	2169903	CONCRETE  MISC.Remove and Replace Barrier Curb	15.00	0.00	15.00	LF	0.00	\$1,001.00	
		0077	2350	7031004	DIAMOND GRINDING	1,457.00	0.00	1,457.00	SQYD	0.00	\$9.75	
		0077	2360	7034214	CLASS B-2 CONCRETE	7.20	0.00	7.20	CUYD	0.00	\$4,025.00	
			2370	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	45.00	0.00	45.00	SQFT	0.00	\$173.25	
		0077	2380	7040102	EPOXY PRESSURE INJECTING	121.00	0.00	121.00	LF	0.00	\$52.50	
		0077	2390	7040113	CLEANING AND EPOXY COATING	505.00	0.00	505.00	SQFT	0.00	\$30.00	
		0077	2400	7040113	MECHANICAL BAR SPLICE	10.00	0.00	10.00	EA	0.00	\$12.80	
		0077	2410	7101000		680.00	0.00	680.00	LB	0.00	\$2.35	
		0077			REINFORCING STEEL (EPOXY COATED)							
		0077	2420	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	
		0077	2430	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1,400.00	0.00	1,400.00	SQFT	1,400.00	\$70.00	\$98,
		0077	2440	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,400.00	0.00	1,400.00	SQFT	1,400.00	\$4.00	\$5,
		0077	2450	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,400.00	0.00	1,400.00	SQFT	0.00	\$3.00	
		0077	2460	7125370A	FINISH FIELD COAT (SYSTEM G)	1,400.00	0.00	1,400.00	SQFT	0.00	\$2.00	
		0077	2470	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	86.00	0.00	86.00	LF	0.00	\$488.00	
		0078	2480	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,457.00	0.00	1,457.00	SQYD	0.00	\$60.00	
		0078	2490	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	11.00	0.00	11.00	CY	0.00	\$700.00	
		0078	2500	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,457.00	0.00	1,457.00	SQYD	0.00	\$118.00	
		0078	2510	7040106	FULL DEPTH REPAIR	100.00	0.00	100.00	SQFT	0.00	\$139.00	
		0800	2560	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	23.00	0.00	23.00	SQFT	11.50	\$350.00	\$4,
		0800	2570	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	0.50	\$16,000.00	\$8,
		0800	2580	2161501	REMOVAL OF ASPHALT WEARING SURFACE	8,506.00	0.00	8,506.00	SQFT	8,506.00	\$2.25	\$19,
		0800	2590	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.50	\$50,000.00	\$25,
		0800	2600	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	137.00	0.00	137.00	LF	68.50	\$631.00	\$43,
		0080	2610	2169903	CONCRETE  MISC.REMOVAL OF EXISTING BRIDGE RAIL	480.00	0.00	480.00	LF	480.00	\$21.00	\$10,
		0080	2620	2169903	MISC.Remove and Replace Barrier Curb	17.00	0.00	17.00	LF	8.50	\$1,001.00	\$8,
		0000			2	17.50	5.00	17.00	Li	0.00	↓.,001.00	Ψ0,

Revision 3/23/2023 Page 10 of 27



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					port Generated date and can differ from the posted amou							
Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See repor generated date)
30421-F06	J6P3288	0800	2640	7031004	DIAMOND GRINDING	911.00	0.00	911.00	SQYD	0.00	\$9.75	\$0.0
		0800	2650	7034214	CLASS B-2 CONCRETE	61.80	0.00	61.80	CUYD	36.00	\$1,650.00	\$59,400.0
		0800	2660	7040101	SUBSTRUCTURE REPAIR (FORMED)	10.00	0.00	10.00	SQFT	16.05	\$169.00	\$2,712.4
		0800	2670	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	20.00	0.00	20.00	SQFT	0.00	\$173.25	\$0.
		0800	2680	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	29.00	0.00	29.00	SQFT	0.00	\$180.00	\$0.0
		0800	2690	7040110	EPOXY PRESSURE INJECTING	11.00	0.00	11.00	LF	0.00	\$52.50	\$0.
		0800	2700	7040164	FIBER REINFORCED POLYMER WRAP	83.00	0.00	83.00	SF	0.00	\$178.00	\$0.
		0800	2710	7049904	MISC.CLEANING AND PROTECTIVE COATING (EPOXY)	988.00	0.00	988.00	SQFT	0.00	\$15.00	\$0.
		0800	2720	7061070	MECHANICAL BAR SPLICE	30.00	0.00	30.00	EA	0.00	\$12.80	\$0
		0800	2730	7101000	REINFORCING STEEL (EPOXY COATED)	5,850.00	0.00	5,850.00	LB	771.00	\$2.35	\$1,811
		0800	2740	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$14,000.00	\$0.
		0080	2750	7151001	(EPOXY) VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$6,000.00	\$0.
		0081	2760	2161001	TOTAL SURFACE HYDRO DEMOLITION	911.00	0.00	911.00	SQYD	573.00	\$60.00	\$34,380.
		0081	2770	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	6.00	0.00	6.00	CY	2.36	\$700.00	\$1.648.
		0081	2780	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	911.00	0.00	911.00	SQYD	573.00	\$118.00	\$67,614.
		0081	2790	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$139.00	\$0.
		0083	2840	2161501	REMOVAL OF ASPHALT WEARING SURFACE	7,672.00	0.00	7,672.00	SQFT	0.00	\$2.30	\$0
		0083	2850	7031004	DIAMOND GRINDING	852.00	0.00	852.00	SQYD	0.00	\$9.75	\$0
			2860	7040110	EPOXY PRESSURE INJECTING	16.00	0.00	16.00	LF	0.00	\$52.50	\$0
		0083										
		0083	2870	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$7,000.00	\$0
		0083	2880	7172054	OPEN CELL FOAM JOINT SEAL	80.00	0.00	80.00	LF	0.00	\$52.00	\$0
		0084	2890	2161001	TOTAL SURFACE HYDRO DEMOLITION	852.00	0.00	852.00	SQYD	0.00	\$60.00	\$0
		0084	2900	2161503	REMOVAL OF EXISTING DECK REPAIR	125.00	0.00	125.00	SQFT	0.00	\$31.00	\$0
		0084	2910	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	2.00	0.00	2.00	CY	0.00	\$700.00	\$0
		0084	2920	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	852.00	0.00	852.00	SQYD	0.00	\$118.00	\$0
		0086	2960	2161501	REMOVAL OF ASPHALT WEARING SURFACE	7,650.00	0.00	7,650.00	SQFT	7,650.00	\$2.30	\$17,595
		0086	2970	7031004	DIAMOND GRINDING	850.00	0.00	850.00	SQYD	0.00	\$9.75	\$0
		0086	2980	7040113	CLEANING AND EPOXY COATING	4.00	0.00	4.00	SQFT	0.00	\$30.00	\$0
		0086	2990	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$7,000.00	\$0
		0086	3000	7172054	OPEN CELL FOAM JOINT SEAL	79.00	0.00	79.00	LF	39.50	\$52.00	\$2,054
		0087	3010	2161001	TOTAL SURFACE HYDRO DEMOLITION	850.00	0.00	850.00	SQYD	519.70	\$60.00	\$31,182
		0087	3020	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	2.00	0.00	2.00	CY	11.74	\$700.00	\$8,218
		0087	3030	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	850.00	0.00	850.00	SQYD	413.00	\$118.00	\$48,734
		0089	3070	2161501	REMOVAL OF ASPHALT WEARING SURFACE	15,134.00	0.00	15,134.00	SQFT	0.00	\$1.75	\$0
		0089	3080	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$12,000.00	\$0
		0089	3090	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	112.00	0.00	112.00	LF	0.00	\$631.00	\$0
		0089	3100	2169902	CONCRETE MISC.REMOVAL OF EXISTING BEARINGS AND ANCHOR BOLTS	12.00	0.00	12.00	EA	0.00	\$3,300.00	\$0
		0089	3110	2169903	MISC.Remove and Replace Barrier Curb	14.00	0.00	14.00	LF	0.00	\$1,001.00	\$1
		0089	3120	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	198.00	0.00	198.00	SQYD	0.00	\$340.00	\$
			3130	7031004	DIAMOND GRINDING	1,652.00	0.00	1,652.00	SQYD	0.00	\$9.75	\$(
		0089	3140	7031004	CLASS B-2 CONCRETE		0.00		CUYD	0.00		
		0089	3140	7034214	SUBSTRUCTURE REPAIR (UNFORMED)	13.70	0.00	13.70 30.00	SQFT	0.00	\$4,250.00 \$173.25	\$0
		0089			, ,							
		0089	3160	7040110	EPOXY PRESSURE INJECTING	54.00	0.00	54.00	LF	0.00	\$52.50	\$
		0089	3170	7061070	MECHANICAL BAR SPLICE	16.00	0.00	16.00	EA	0.00	\$12.80	\$1
		0089	3180	7101000	REINFORCING STEEL (EPOXY COATED)	1,620.00	0.00	1,620.00	LB	0.00	\$2.35	\$0
		0089	3190	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$17,500.00	\$1

Revision 3/23/2023 Page 11 of 27



### Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230421-F06	J6P3288	0089	3200	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1,300.00	0.00	1,300.00	SQFT	0.00	\$70.00	\$0.0
		0089	3210	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,300.00	0.00	1,300.00	SQFT	0.00	\$4.00	\$0.0
		0089	3220	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,300.00	0.00	1,300.00	SQFT	0.00	\$3.00	\$0.0
		0089	3230	7125370A	FINISH FIELD COAT (SYSTEM G)	1,300.00	0.00	1,300.00	SQFT	0.00	\$2.00	\$0.0
		0089	3240	7163000	TYPE N PTFE BEARING	12.00	0.00	12.00	EA	0.00	\$3,150.00	\$0.0
		0089	3250	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	112.00	0.00	112.00	LF	0.00	\$488.00	\$0.0
		0090	3260	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,652.00	0.00	1,652.00	SQYD	0.00	\$60.00	\$0.0
		0090	3270	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	0.00	3.00	CY	0.00	\$700.00	\$0.0
		0090	3280	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,652.00	0.00	1,652.00	SQYD	0.00	\$118.00	\$0.0
		0092	3320	2161000	SCARIFICATION OF BRIDGE DECK	1,277.00	0.00	1,277.00	SQYD	0.00	\$12.00	\$0.0
		0092	3330	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	75.00	0.00	75.00	LF	0.00	\$631.00	\$0.0
		0092	3340	2169903	MISC.Remove and Replace Barrier Curb	12.00	0.00	12.00	LF	0.00	\$1,001.00	\$0.0
		0092	3350	7031004	DIAMOND GRINDING	1,277.00	0.00	1,277.00	SQYD	0.00	\$9.75	\$0.0
		0092	3360	7034214	CLASS B-2 CONCRETE	6.30	0.00	6.30	CUYD	0.00	\$3,950.00	\$0.0
		0092	3370	7040101	SUBSTRUCTURE REPAIR (FORMED)	20.00	0.00	20.00	SQFT	0.00	\$169.00	\$0.0
		0092	3380	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	76.00	0.00	76.00	SQFT	0.00	\$173.25	\$0.0
		0092	3390	7040110	EPOXY PRESSURE INJECTING	115.00	0.00	115.00	LF	0.00	\$52.50	\$0.0
		0092	3400	7040113	CLEANING AND EPOXY COATING	175.00	0.00	175.00	SQFT	0.00	\$30.00	\$0.0
		0092	3410	7061070	MECHANICAL BAR SPLICE	10.00	0.00	10.00	EA	0.00	\$12.80	\$0.
		0092	3420	7101000	REINFORCING STEEL (EPOXY COATED)	600.00	0.00	600.00	LB	0.00	\$2.35	\$0.
		0092	3430	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$7,000.00	\$0.
		0092	3440	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1,300.00	0.00	1,300.00	SQFT	0.00	\$70.00	\$0.
		0092	3450	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,300.00	0.00	1,300.00	SQFT	0.00	\$4.00	\$0.
		0092	3460	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,300.00	0.00	1,300.00	SQFT	0.00	\$3.00	\$0.
		0092	3470	7125370A	FINISH FIELD COAT (SYSTEM G)	1,300.00	0.00	1,300.00	SQFT	0.00	\$2.00	\$0.
		0092	3480	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	75.00	0.00	75.00	LF	0.00	\$488.00	\$0.
		0093	3490	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,277.00	0.00	1,277.00	SQYD	0.00	\$60.00	\$0.
		0093	3500	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	6.00	0.00	6.00	CY	0.00	\$700.00	\$0.
		0093	3510	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,277.00	0.00	1,277.00	SQYD	0.00	\$118.00	\$0.
		0093	3520	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$139.00	\$0.
		0095	3570	2161501	REMOVAL OF ASPHALT WEARING SURFACE	16,029.00	0.00	16,029.00	SQFT	0.00	\$8.50	\$0.
		0095	3580	7031004	DIAMOND GRINDING	1,781.00	0.00	1,781.00	SQYD	0.00	\$9.75	\$0.
		0095	3590	7040110	EPOXY PRESSURE INJECTING	50.00	0.00	50.00	LF	0.00	\$52.50	\$0.
		0095	3600	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$10,500.00	\$0.
		0096	3610	2161001	(EPOXY) TOTAL SURFACE HYDRO DEMOLITION	1,781.00	0.00	1,781.00	SQYD	0.00	\$60.00	\$0.
		0096	3620	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	5.00	0.00	5.00	CY	0.00	\$700.00	\$0.
		0096	3630	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,781.00	0.00	1,781.00	SQYD	0.00	\$118.00	\$0.
		0096	3640	7040106	FULL DEPTH REPAIR	25.00	0.00	25.00	SQFT	0.00	\$139.00	\$0.
		0098	3690	2161501	REMOVAL OF ASPHALT WEARING SURFACE	16,335.00	0.00	16,335.00	SQFT	16,335.00	\$8.50	\$138,847.
		0098	3700	7031004	DIAMOND GRINDING	1,815.00	0.00	1,815.00	SQYD	0.00	\$9.75	\$0.
		0098	3710	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	4.00	0.00	4.00	SQFT	0.00	\$173.25	\$0.
		0098	3720	7040110	EPOXY PRESSURE INJECTING	6.00	0.00	6.00	LF	0.00	\$52.50	\$0.
		0098	3730	7049903	MISC.Barrier Curb Repair	4.00	0.00	4.00	LF	0.00	\$349.00	\$0.
		0098	3740	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$10,500.00	\$0.
					(EPOXY)							
		0099	3750	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,815.00	0.00	1,815.00	SQYD	1,815.00	\$60.00	\$108,900

Revision 3/23/2023 Page 12 of 27



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

		ea.	General	sumate was	ne me E	ant at the th	port Generated date and can differ from the posted amou	babba bir rib	o are be	na value	uaniilies a	oto. i ootou Q
Total Value POSTE To Date (See repo generated date)	Unit Price	Total Posted Approved Qty	Unit	Total Current Quantity	Net Change Order	Bid Quantity	Description	ltem Code	Line No.	Category	Project No.	Contract Nm.CONTRACT
\$6,587.	\$700.00	9.41	CY	4.00	0.00	4.00	SUPPLEMENTARY WEARING SURFACE MATERIAL	5050004	3760	0099	J6P3288	80421-F06
\$214,170.	\$118.00	1,815.00	SQYD	1,815.00	0.00	1,815.00	LATEX MODIFIED CONCRETE WEARING SURFACE	5052000	3770	0099		
\$4,484,232.							te as of Report Generated Date	e Posted to Da	al Value I	P3288 - Tot	Project J6F	
\$4,725.	\$4,725.00	1.00	LS	1.00	0.00	1.00	MISC.CLEAR VEGETATION AND DEBRIS	2019901	3810	0001	J6S3283B	
\$0.	\$120,000.00	0.00	LS	1.00	0.00	1.00	REMOVAL OF IMPROVEMENTS	2022010	3820	0001		
\$1,917.	\$106.50	18.00	CUYD	18.00	0.00	18.00	CLASS 3 EXCAVATION	2063000	3830	0001		
\$1,194.	\$597.00	2.00	STA	2.00	0.00	2.00	LINEAR GRADING CLASS 1	2071000	3840	0001		
\$0.	\$233.00	0.00	STA	1,969.00	0.00	1,969.00	MISC.SHOULDERING	2129909	3850	0001		
\$0.	\$750.00	0.00	100F	282.00	0.00	282.00	MISC.SHAPING SLOPES, CLASS III (MODIFIED)	2159910	3860	0001		
\$0.	\$23.25	0.00	SQYD	1,404.00	0.00	1,404.00	GRAVEL (A)	3101003	3870	0001		
\$322,310.	\$70.00	4,604.44	TONS	28,138.40	0.00	28,138.40	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	4011209	3880	0001		
\$1,111,339.	\$85.00	13,074.58	TONS	34,041.50	0.00	34,041.50	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095C MIX)	4030003	3890	0001		
\$0.	\$86.00	0.00	TONS	34,041.50	0.00	34,041.50	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095CLP MIX)	4030011	3900	0001		
\$17,709.	\$2.85	6,214.00	GAL	45,432.00	0.00	45,432.00	TACK COAT	4071005	3910	0001		
\$83,470.	\$2.85	29,288.00	GAL	64,990.00	0.00	64,990.00	MISC.MODIFIED BONDED ASPHALTIC CONCRETE PAVEMENT	4139912	3920	0001		
\$0.	\$82.75	0.00	SQYD	953.00	0.00	953.00	6 IN. CONCRETE MEDIAN STRIP	6083006	3930	0001		
\$0.	\$2,500.00	0.00	EA	6.00	0.00	6.00	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	6123000A	3940	0001		
\$1,109,567.	\$193.50	5,734.20	SQYD	4,956.00	0.00	4,956.00	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL	6131010	3950	0001		
\$0.	\$5.00	0.00	SQYD	496.00	0.00	496.00	DEPTH PAVEMENT REPAIR SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	6131012	3960	0001		
\$0.	\$5.00	0.00	SQYD	496.00	0.00	496.00	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)	6131013	3970	0001		
							(PAVEMENT REPAIR)					
\$205,965.	\$9.00	22,885.00	LF	21,800.00	0.00	21,800.00	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	6131014	3980	0001		
\$151,848.	\$13.40	11,332.00	EA	12,048.00	0.00	12,048.00	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	6131015	3990	0001		
\$137,561.	\$215.00	639.82	TONS	660.00	0.00	660.00	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR	6133018	4000	0001		
\$161,610.	\$30.00	5,387.00	SQYD	4,000.00	0.00	4,000.00	CLASS B PARTIAL DEPTH PAVEMENT REPAIR REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	6133019	4010	0001		
\$25,000.	\$50,000.00	0.50	LS	1.00	0.00	1.00	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	6169901	4020	0001		
\$7,500.	\$2,500.00	3.00	EA	4.00	0.00	4.00	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN	6169902	4030	0001		
		0.75	10	1.00	0.00	4.00	(CONTRACTOR FURNISHED AND RETAINED)	0404000	1010			
\$487,500.	\$650,000.00	0.75	LS	1.00	0.00	1.00	MOBILIZATION	6181000	4040	0001		
\$0.	\$20.00	0.00	LF	183.00	0.00	183.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	6200015	4050	0001		
\$0.	\$300.00	0.00	EA	24.00	0.00	24.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	6200021	4060	0001		
\$0.	\$25.00	0.00	EA	39.00	0.00	39.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	6200042	4070	0001		
\$0.	\$0.26	0.00	LF	167,465.00	0.00	167,465.00	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	6205902A	4080	0001		
\$0.	\$0.25	0.00	LF	132,587.00	0.00	132,587.00	PAINT, TYPE L BEADS 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT	6205903A	4090	0001		
							MARKING PAINT, TYPE L BEADS			0001		
\$0.	\$0.85	0.00	LF	8,381.00	0.00	8,381.00	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	6205906A	4100	0001		
\$0.	\$0.20	0.00	LF	3,372.00	0.00	3,372.00	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6206000C	4110	0001		
\$0.	\$0.20	0.00	LF	3,372.00	0.00	3,372.00	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	6206001C	4120	0001		
\$33,115.	\$0.25	132,462.50	LF	254,025.00	0.00	254,025.00	MARKING PAINT, TYPE P BEADS 4 IN TEMPORARY PAVEMENT MARKING PAINT	6208076	4130	0001		
\$227,325.	\$1.40	162,375.00	SQYD	339,811.00	0.00	339,811.00	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	6221001	4140	0001		
							SURFACING (3 IN. THICK OR LESS)					
\$0.	\$0.10	0.00	SQYD	53,703.00	0.00	53,703.00	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	6224010	4150	0001		
\$0.	\$24.75	0.00	STA	2,484.00	0.00	2,484.00	BITUMINOUS SHOULDER RUMBLE STRIP	6261000A	4160	0001		
\$0.	\$2,500.00	0.00	LS	1.00	0.00	1.00	CONTRACTOR FURNISHED SURVEYING AND STAKING	6274000	4170	0001		
\$9,880	\$123.50	80.00	LF	80.00	0.00	80.00	12 IN. PIPE GROUP A	7261012	4180	0001		
\$1,008.	\$504.00	2.00	EA	2.00	0.00	2.00	12 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	7320612A	4190	0001		
\$0.	\$25.00	0.00	LF	23,388.00	0.00	23,388.00	MGS GUARDRAIL	6061060	4200	0010		
\$0.	\$3,600.00	0.00	EA	2.00	0.00	2.00	MGS BRIDGE APPROACH TRANSITION SECTION	6061069	4210	0010		

Revision 3/23/2023 Page 13 of 27



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230421-F06	J6S3283B				(REGULAR/NO CURB)							
		0010	4220	6061074	MGS HEIGHT AND BLOCK TRANSITION	1.00	0.00	1.00	EA	0.00	\$650.00	\$0.00
		0010	4230	6061080	MGS END ANCHOR	41.00	0.00	41.00	EA	0.00	\$1,400.00	\$0.00
		0010	4240	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	42.00	0.00	42.00	EA	0.00	\$3,000.00	\$0.00
		0010	4250	6063021	TYPE D CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$31,000.00	\$0.00
		0040	4260	9031010	CONCRETE FOOTINGS, EMBEDDED	19.00	0.00	19.00	CUYD	0.00	\$1,800.00	\$0.00
		0040	4270	9031210	STRUCTURAL STEEL POSTS	9,650.00	0.00	9,650.00	LB	0.00	\$5.50	\$0.00
		0040	4280	9031220	PIPE POSTS	1,810.00	0.00	1,810.00	LB	0.00	\$7.50	\$0.00
		0040	4290	9031270A	2 IN. PSST POST - 12 GA.	135.00	0.00	135.00	LF	0.00	\$20.00	\$0.00
		0040	4300	9031273A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 7 GA.	15.00	0.00	15.00	EA	0.00	\$250.00	\$0.00
		0040	4310	9035004A	SH-FLAT SHEET	1,310.00	0.00	1,310.00	SQFT	0.00	\$26.00	\$0.00
		0040	4320	9035011A	ST-STRUCTURAL	1,968.00	0.00	1,968.00	SQFT	0.00	\$29.00	\$0.00
	0050 4330 9109903 MISC.MODOT ITS ASSETS RELOCATION							1,000.00	LF	0.00	\$18.00	\$0.00
	Project J65	3283B - To	tal Value	Posted to D	late as of Report Generated Date							\$4,100,548.22
230421-F06 Ove	rall - Total V	alue Poste	d to Date	as of Report	t Generated Date							\$8,584,780.92

Revision 3/23/2023 Page 14 of 27



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: J6P3288

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0180	6173600D	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	1/2/24	1/8/24	50.00	LF	bridges 3/4/5 sb 21					
0190	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	1/2/24	1/8/24	50.00	LF	bridges 3/4/5 sb rt 21					
0230	6207001	PAVEMENT MARKING REMOVAL	1/12/24	1/12/24	5,789.00	LF	SB route 21 bridges 1 & 2 5560 FT SB 3,4,5 - 229 FT					

#### Project: J6S3283B

Line Number	Item Code	Description			Quantity Posted		Location	Offset/ Distance	Offset/ Distance	Comments
4130	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	1/12/24	1/12/24	1,450.00	LF	sb route 21 partial depth asphalt repairs			

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 15 of 27



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3288	0050	CONCRETE APPROACH	Material		12	Dec 18, 2023	SYSTEM	(\$248,151.00)	
		PAVEMENT			13	Jan 2, 2024	SYSTEM	\$248,151.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user jamesc4 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					13	Jan 2, 2024	SYSTEM	(\$248,151.00)	
					14	Jan 16, 2024	SYSTEM	\$248,151.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jamesc4 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					14	Jan 16, 2024	SYSTEM	(\$248,151.00)	
				- Total				(\$248,151.00)	
			Material - Tota					(\$248,151.00)	
			MaterialCredit		13	Jan 2, 2024	SYSTEM	\$248,151.00	
				- Total				\$248,151.00	
			MaterialCredit	- Total				\$248,151.00	
	0050 -	· Total						\$0.00	
	0070	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		9	Nov 1, 2023	SYSTEM	\$1,984.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user jamesc4 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Nov 1, 2023	SYSTEM	(\$1,984.00)	
					10	Nov 16, 2023	SYSTEM	\$3,069.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user jamesc4 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					10	Nov 16, 2023	SYSTEM	(\$3,069.00)	
					11	Dec 4, 2023	SYSTEM	(\$3,875.00)	
					12	Dec 18, 2023	SYSTEM	(\$3,875.00)	
				- Total				(\$7,750.00)	
			Material - Tota	ı				(\$7,750.00)	
			MaterialCredit		12	Dec 18, 2023	SYSTEM	\$3,875.00	
					13	Jan 2, 2024	SYSTEM	\$3,875.00	
				- Total				\$7,750.00	
			MaterialCredit					\$7,750.00 \$7,750.00	
	0070 -	·Total	MaterialCredit						
	<b>0070 -</b> 0155	TRUCK OR TRAILER MOUNTED ATTEN			11	Dec 4, 2023	SYSTEM	\$7,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		TRUCK OR TRAILER			11		SYSTEM	\$7,750.00 \$0.00	Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment
		TRUCK OR TRAILER MOUNTED ATTEN				2023 Dec 4,		\$7,750.00 \$0.00 \$20,000.00	Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment
		TRUCK OR TRAILER MOUNTED ATTEN		- Total		2023 Dec 4,		\$7,750.00 \$0.00 \$20,000.00 (\$20,000.00)	Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment
		TRUCK OR TRAILER MOUNTED ATTEN (TMA)	Material	- Total		2023 Dec 4,		\$7,750.00 \$0.00 \$20,000.00 (\$20,000.00)	Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment
	0155	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	Material	- Total		2023 Dec 4,		\$7,750.00 \$0.00 \$20,000.00 (\$20,000.00) \$0.00	Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment
	0155	TRUCK OR TRAILER MOUNTED ATTEN (TMA)  Total 4 IN TEMPORARY PAVEMENT	Material  Material - Tota	- Total	11	2023  Dec 4, 2023  Aug 2,	SYSTEM	\$7,750.00 \$0.00 \$20,000.00 (\$20,000.00) \$0.00 \$0.00	Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment
	0155	TRUCK OR TRAILER MOUNTED ATTEN (TMA)  Total 4 IN TEMPORARY PAVEMENT	Material  Material - Tota	- Total	3	2023  Dec 4, 2023  Aug 2, 2023  Aug 2,	SYSTEM	\$7,750.00 \$0.00 \$20,000.00 (\$20,000.00) \$0.00 \$0.00 \$5,129.00	Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment
	0155	TRUCK OR TRAILER MOUNTED ATTEN (TMA)  Total 4 IN TEMPORARY PAVEMENT	Material  Material - Tota	- Total	3	2023  Dec 4, 2023  Aug 2, 2023  Aug 2,	SYSTEM	\$7,750.00 \$0.00 \$20,000.00 (\$20,000.00) \$0.00 \$0.00 \$5,129.00	Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment
	0155	TRUCK OR TRAILER MOUNTED ATTEN (TMA)  Total  4 IN TEMPORARY PAVEMENT MARKING PAINT	Material - Tota	- Total	3	2023  Dec 4, 2023  Aug 2, 2023  Aug 2,	SYSTEM	\$7,750.00 \$0.00 \$20,000.00 (\$20,000.00) \$0.00 \$0.00 \$5,129.00 (\$5,129.00)	Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment
	0155 - 0155 - 0240	TRUCK OR TRAILER MOUNTED ATTEN (TMA)  Total  4 IN TEMPORARY PAVEMENT MARKING PAINT	Material - Tota	- Total	3	2023  Dec 4, 2023  Aug 2, 2023  Aug 2,	SYSTEM	\$7,750.00 \$0.00 \$20,000.00 (\$20,000.00) \$0.00 \$0.00 \$5,129.00 (\$5,129.00) \$0.00	Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment
	0155 - 0240	TRUCK OR TRAILER MOUNTED ATTEN (TMA)  Total  4 IN TEMPORARY PAVEMENT MARKING PAINT	Material - Tota  Material - Tota  Material - Tota  Construction	- Total	3 3	2023 Dec 4, 2023 Aug 2, 2023 Aug 2, 2023 Nov 1,	SYSTEM SYSTEM SYSTEM	\$7,750.00 \$0.00 \$20,000.00 (\$20,000.00) \$0.00 \$0.00 \$5,129.00 (\$5,129.00) \$0.00 \$0.00	Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 4 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3288	0280	MGS GUARDRAIL	Construction Stockpile	- Total				(\$51,066.75)	
			Construction	Stockpile - To	otal			(\$51,066.75)	
			Construction Stockpile STMI		5	Sep 5, 2023	SYSTEM	\$216,940.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$216,940.50	
			Construction	Stockpile STI	MI - Total			\$216,940.50	
	0280 -	Total						\$165,873.75	
	0290	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile		9	Nov 1, 2023	SYSTEM	(\$4,100.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(NES/NO OSNE)			11	Dec 4, 2023	SYSTEM	(\$6,150.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					12	Dec 18, 2023	SYSTEM	(\$6,150.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$16,400.00)	
			Construction	Stockpile - To				(\$16,400.00)	
			Construction Stockpile STMI		5	Sep 5, 2023	SYSTEM	\$96,350.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$96,350.00	
	0000	Total	Construction	Stockpile STI	vii - Total			\$96,350.00	
	0290 -		Construction		_	Ca= 5	CVCTC14	\$79,950.00	Doumant Estimate Item Adjustment recented Statistics Transaction
	0300	MGS HEIGHT AND BLOCK TRANSITION	Construction Stockpile STMI	- Total	5	Sep 5, 2023	SYSTEM	\$394.50 \$394.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction		MI Total			\$394.50	
	0300 -	Total	Construction	Otockpile 011	vii - Totai			\$394.50	
	0310		Construction Stockpile		11	Dec 4, 2023	SYSTEM	(\$820.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			,		12	Dec 18, 2023	SYSTEM	(\$820.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$1,640.00)	
			Construction	Stockpile - To	otal			(\$1,640.00)	
			Construction Stockpile STMI		5	Sep 5, 2023	SYSTEM	\$10,660.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$10,660.00	
			Construction	Stockpile STI	MI - Total			\$10,660.00	
	0310 -	Total						\$9,020.00	
	0320	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		9	Nov 1, 2023	SYSTEM	(\$3,750.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)			11	Dec 4, 2023	SYSTEM	,	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total	12	Dec 18, 2023	SYSTEM	(\$3,750.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction		otal			(\$11,250.00)	
			Construction Construction	отоскрпе - 10	5	Sep 5,	SYSTEM	(\$11,250.00) \$63,750.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Stockpile STMI	- Total	3	2023	STSTEM	\$63,750.00	rayment Estimate tem Aujustinent generated Stockpile Transaction
			Construction		VII - <u>Total</u>			\$63,750.00	
	03 <u>20</u> -	Total						\$52,500.00	
	0580	WEARING	Material		9	Nov 1, 2023	SYSTEM	\$1,204.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		SURFACE MATERIAL			9	Nov 1, 2023	SYSTEM	(\$1,204.00)	Laurian Laception i on the current Fayment Estillate.
					10	Nov 16, 2023	SYSTEM	\$1,204.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Nov 16, 2023	SYSTEM	(\$1,204.00)	
			- Total				\$0.00		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6P3288	0580	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material - Tota					\$0.00		
	0580 -	- Total						\$0.00		
	0590	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		9	Nov 1, 2023	SYSTEM	\$92,512.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					9	Nov 1, 2023	SYSTEM	(\$92,512.00)		
					10	Nov 16, 2023	SYSTEM	\$92,512.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					10	Nov 16, 2023	SYSTEM	(\$92,512.00)		
				- Total				\$0.00		
			Material - Tota	<u> </u>				\$0.00		
		- Total						\$0.00		
	0800	FIELD APPLICATION OF INORGANIC ZINC	Material		12	Dec 18, 2023	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
					12	Dec 18, 2023	SYSTEM	(\$4,400.00)		
					13	Jan 2, 2024	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user jamesc4 overridding Payment Estimate Exception 18 on the current Payment Estimate.	
						13	Jan 2, 2024	SYSTEM	(\$4,400.00)	
					14	Jan 16, 2024	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user jamesc4 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
					14	Jan 16, 2024	SYSTEM	(\$4,400.00)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
		- Total						\$0.00 \$0.00		
	0800 - 1040	- Total FIELD APPLICATION OF INORGANIC ZINC	Material - Tota		12	Dec 18, 2023	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 18 on the current Payment Estimate.	
		FIELD APPLICATION OF			12		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment	
		FIELD APPLICATION OF				2023 Dec 18,		\$0.00 \$0.00 \$4,400.00	Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment	
		FIELD APPLICATION OF			12	2023  Dec 18, 2023  Jan 2,	SYSTEM	\$0.00 \$0.00 \$4,400.00 (\$4,400.00)	Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 18 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment	
		FIELD APPLICATION OF			12	2023  Dec 18, 2023  Jan 2, 2024  Jan 2,	SYSTEM	\$0.00 \$0.00 \$4,400.00 (\$4,400.00) \$4,400.00	Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 18 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment	
		FIELD APPLICATION OF			12 13	2023  Dec 18, 2023  Jan 2, 2024  Jan 2, 2024  Jan 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$4,400.00 (\$4,400.00) \$4,400.00	Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 18 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment	
		FIELD APPLICATION OF			12 13 13	2023 Dec 18, 2023 Jan 2, 2024 Jan 2, 2024 Jan 16, 2024 Jan 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,400.00 (\$4,400.00) \$4,400.00 (\$4,400.00)	Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 18 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment	
	1040	FIELD APPLICATION OF INORGANIC ZINC		- Total	12 13 13	2023 Dec 18, 2023 Jan 2, 2024 Jan 2, 2024 Jan 16, 2024 Jan 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,400.00 (\$4,400.00) \$4,400.00 (\$4,400.00) (\$4,400.00) \$0.00	Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 18 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment	
	1040	FIELD APPLICATION OF	Material	- Total	12 13 13	2023 Dec 18, 2023 Jan 2, 2024 Jan 2, 2024 Jan 16, 2024 Jan 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,400.00 (\$4,400.00) \$4,400.00 (\$4,400.00) (\$4,400.00)	Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 18 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment	
	1040	FIELD APPLICATION OF INORGANIC ZINC	Material	- Total	12 13 13	2023 Dec 18, 2023 Jan 2, 2024 Jan 2, 2024 Jan 16, 2024 Jan 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,400.00 (\$4,400.00) \$4,400.00 (\$4,400.00) (\$4,400.00) \$0.00	Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 18 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment	
	1040	FIELD APPLICATION OF INORGANIC ZINC	Material - Tota	- Total	12 13 13 14 14	2023 Dec 18, 2023 Jan 2, 2024 Jan 16, 2024 Jan 16, 2024 Sep 5,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,400.00 (\$4,400.00) \$4,400.00 (\$4,400.00) \$4,400.00 \$0.00 \$0.00	Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 18 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment	
	1040	FIELD APPLICATION OF INORGANIC ZINC	Material - Tota	- Total	12 13 13 14 14	2023 Dec 18, 2023 Jan 2, 2024 Jan 16, 2024 Jan 16, 2024 Sep 5, 2023 Sep 5,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,400.00 (\$4,400.00) \$4,400.00 (\$4,400.00) \$4,400.00 \$0.00 \$0.00 \$9,562.60	Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 18 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment	
	1040	FIELD APPLICATION OF INORGANIC ZINC	Material - Tota	- Total	12 13 13 14 14 5	2023 Dec 18, 2023 Jan 2, 2024 Jan 16, 2024 Jan 16, 2024 Sep 5, 2023 Sep 5, 2023 Sep 19,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,400.00 (\$4,400.00) \$4,400.00 (\$4,400.00) \$4,400.00 \$0.00 \$0.00 \$9,562.60	Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 18 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment	
	1040	FIELD APPLICATION OF INORGANIC ZINC	Material - Tota	- Total	12 13 13 14 14 5 5	2023 Dec 18, 2023 Jan 2, 2024 Jan 2, 2024 Jan 16, 2024 Jan 16, 2024 Sep 5, 2023 Sep 5, 2023 Sep 19, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,400.00 (\$4,400.00) \$4,400.00 (\$4,400.00) \$0.00 \$0.00 \$9,562.60 (\$9,562.60)	Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 18 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
I6P3288	1200	MISC.	Material			2023			Estimate Item Adjustment (0005) due to user jamesc4 overridding Paymen Estimate Exception 4 on the current Payment Estimate.
					8	Oct 16, 2023	SYSTEM	(\$9,562.60)	
					9	Nov 1, 2023	SYSTEM	\$9,562.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user jamesc4 overridding Paymen Estimate Exception 9 on the current Payment Estimate.
					9	Nov 1, 2023	SYSTEM	(\$9,562.60)	
				- Total				(\$9,562.60)	
			Material - Tota					(\$9,562.60)	
			MaterialCredit		8	Oct 16, 2023	SYSTEM	\$9,562.60	
				- Total				\$9,562.60	
			MaterialCredit	- Total				\$9,562.60	
	1200 -	Total						\$0.00	
	1230	SUPPLEMENTARY WEARING SURFACE	Overrun	Overrun		Oct 16, 2023	SYSTEM	(\$11,851.00)	
		MATERIAL			10	Nov 16, 2023	SYSTEM	(\$16,800.00)	
				Overrun - T	otal			(\$28,651.00)	
			Overrun - Tota					(\$28,651.00)	
	1230 -	· Total						(\$28,651.00)	
	1240	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		10	Nov 16, 2023	SYSTEM	\$185,024.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user jamesc4 overridding Paymen Estimate Exception 8 on the current Payment Estimate.
					10	Nov 16, 2023	SYSTEM	(\$185,024.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	1240 -	Total						\$0.00	
	1570	FIELD APPLICATION OF INORGANIC ZINC	Material		13	Jan 2, 2024	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					13	Jan 2, 2024	SYSTEM	(\$4,400.00)	
					14	Jan 16, 2024	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user jamesc4 overridding Paymer Estimate Exception 18 on the current Payment Estimate.
					14	Jan 16, 2024	SYSTEM	(\$4,400.00)	Estimate Exception to off the current rayment Estimate.
				- Total				\$0.00	
			Material - Tota					\$0.00	
	15 <u>70</u> -	· Total						\$0.00	
	1960	LATEX MODIFIED CONCRETE WEARING	Material		8	Oct 16, 2023	SYSTEM	\$78,741.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user jamesc4 overridding Paymei Estimate Exception 1 on the current Payment Estimate.
		SURFACE			8	Oct 16, 2023	SYSTEM	(\$78,741.40)	Zaopaon i on ao outon'i ajmon Esumato.
					9	Nov 1, 2023	SYSTEM	\$78,741.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user jamesc4 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Nov 1, 2023	SYSTEM	(\$78,741.40)	
					10	Nov 16, 2023	SYSTEM	\$78,741.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user jamesc4 overridding Paymer Estimate Exception 9 on the current Payment Estimate.
					10	Nov 16, 2023	SYSTEM	(\$78,741.40)	,
				- Total				\$0.00	
			Material - Tota					\$0.00	
								60.00	
	1960 -	Total						\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3288	2220	OPEN CELL FOAM	Material	.,					Estimate Exception 22 on the current Payment Estimate.
		JOINT SEAL			13	Jan 2,	SYSTEM	(\$5,096.00)	
					14	2024 Jan 16, 2024	SYSTEM	\$5,096.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user jamesc4 overridding Payment
					14	Jan 16, 2024	SYSTEM	(\$5,096.00)	Estimate Exception 20 on the current Payment Estimate.
				- Total		2024		\$0.00	
			Material - Tota					\$0.00	
	2220 -	- Total						\$0.00	
	2250	SUPPLEMENTARY WEARING SURFACE			9	Nov 1, 2023	SYSTEM	\$8,183.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		MATERIAL			9	Nov 1, 2023	SYSTEM	(\$8,183.00)	
					10	Nov 16, 2023	SYSTEM	\$8,183.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Nov 16, 2023	SYSTEM	(\$8,183.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
			Overrun	Overrun		Nov 1, 2023	SYSTEM	(\$6,083.00)	
				Overrun - T	12	Dec 18, 2023	SYSTEM	(\$3,584.00)	
			Overrun - Tota		Otal			(\$9,667.00)	
	2250 -	- Total	Overruit - Tota	11				(\$9,667.00)	
	2260	LATEX MODIFIED CONCRETE WEARING SURFACE	CONCRETE WEARING		9	Nov 1, 2023	SYSTEM	\$105,574.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Nov 1, 2023	SYSTEM	(\$105,574.60)	
					10	Nov 16, 2023	SYSTEM	\$105,574.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user jamesc4 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					10	Nov 16, 2023	SYSTEM	(\$105,574.60)	
					- Total			\$0.00	
			Material - Total					\$0.00	
		- Total				_	a	\$0.00	
	2440	FIELD APPLICATION OF INORGANIC ZINC	Material		11	Dec 4, 2023	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user jamesc4 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					11	Dec 4, 2023	SYSTEM	(\$5,600.00)	
					12	Dec 18, 2023	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					12	Dec 18, 2023	SYSTEM	(\$5,600.00)	
						Jan 2, 2024	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					13	Jan 2, 2024	SYSTEM	(\$5,600.00)	
					14	Jan 16, 2024	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					14	Jan 16, 2024	SYSTEM	(\$5,600.00)	
				- Total				\$0.00	
			Material - Tota	l e				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3288	2440 -	- Total						\$0.00	
	2620	MISC. REMOVALS	Material		12	Dec 18, 2023	SYSTEM	\$8,508.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Dec 18, 2023	SYSTEM	(\$8,508.50)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	2620 -	- Total						\$0.00	
	2630	BRIDGE APPROACH SLAB	Material		11	Dec 4, 2023	SYSTEM	(\$43,788.00)	
		(MAJOR ROAD)			12	Dec 18, 2023	SYSTEM	(\$43,788.00)	
					13	Jan 2, 2024	SYSTEM	\$43,788.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc4 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	Jan 2, 2024	SYSTEM	(\$43,788.00)	
					14	Jan 16, 2024	SYSTEM	\$43,788.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user jamesc4 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Jan 16, 2024	SYSTEM	(\$43,788.00)	Estimate Exception of the editorial dynamic Estimate.
				- Total		LULT		(\$87,576.00)	
			Material - Tota	Material - Total				(\$87,576.00)	
			MaterialCredit		12	Dec 18, 2023	SYSTEM	\$43,788.00	
					13	Jan 2,	SYSTEM	\$43,788.00	
				- Total		2024		\$87,576.00	
			MaterialCredit					\$87,576.00	
	2630	- Total	Wateriarorean	- Total				\$0.00	
	2650		Material		10	Nov 16,	SYSTEM	\$59,400.00	This adjustment offsets the original system-generated Material Payment
	2030	CLASS B-2 CONCRETE				2023			Estimate Item Adjustment (0017) due to user jamesc4 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					10	Nov 16, 2023	SYSTEM	(\$59,400.00)	
					11				
						Dec 4, 2023	SYSTEM	\$59,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					11		SYSTEM	\$59,400.00 (\$59,400.00)	Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
						2023 Dec 4,			Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
					11	Dec 4, 2023  Dec 18,	SYSTEM	(\$59,400.00)	Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
				- Total	11 12	Dec 4, 2023  Dec 18, 2023  Dec 18,	SYSTEM SYSTEM	(\$59,400.00) \$59,400.00	Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
			Material - Tota		11 12	Dec 4, 2023  Dec 18, 2023  Dec 18,	SYSTEM SYSTEM	(\$59,400.00) \$59,400.00 (\$59,400.00)	Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
	2650 -	- Total	Material - Tota		11 12	Dec 4, 2023  Dec 18, 2023  Dec 18,	SYSTEM SYSTEM	(\$59,400.00) \$59,400.00 (\$59,400.00)	Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
	2650 - 2660	SUBSTRUCTURE REPAIR	Material - Tota		11 12 12	Dec 4, 2023  Dec 18, 2023  Dec 18,	SYSTEM SYSTEM	(\$59,400.00) \$59,400.00 (\$59,400.00) \$0.00	Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
		SUBSTRUCTURE		ı	11 12 12 9	2023 Dec 4, 2023 Dec 18, 2023 Dec 18, 2023	SYSTEM SYSTEM SYSTEM	(\$59,400.00) \$59,400.00 (\$59,400.00) \$0.00 \$0.00	Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
		SUBSTRUCTURE REPAIR		Overrun Overrun - To	11 12 12 9	2023 Dec 4, 2023 Dec 18, 2023 Dec 18, 2023	SYSTEM SYSTEM SYSTEM	(\$59,400.00) \$59,400.00 (\$59,400.00) \$0.00 \$0.00 (\$1,022.45)	Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
	2660	SUBSTRUCTURE REPAIR	Overrun	Overrun Overrun - To	11 12 12 9	2023 Dec 4, 2023 Dec 18, 2023 Dec 18, 2023	SYSTEM SYSTEM SYSTEM	(\$59,400.00) \$59,400.00 (\$59,400.00) \$0.00 \$0.00 (\$1,022.45)	Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
	2660 -	SUBSTRUCTURE REPAIR (FORMED)  Total  SUPPLEMENTARY WEARING SURFACE	Overrun	Overrun Overrun - To	11 12 12 9	2023 Dec 4, 2023 Dec 18, 2023 Dec 18, 2023	SYSTEM SYSTEM SYSTEM	(\$59,400.00) \$59,400.00 (\$59,400.00) \$0.00 \$0.00 \$1,022.45 (\$1,022.45) (\$1,022.45)	Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
	2660 -	SUBSTRUCTURE REPAIR (FORMED)  Total  SUPPLEMENTARY WEARING	Overrun - Tota	Overrun Overrun - To	11 12 12 12 9 9 obtail	2023  Dec 4, 2023  Dec 18, 2023  Dec 18, 2023  Nov 1, 2023	SYSTEM SYSTEM SYSTEM SYSTEM	(\$59,400.00) \$59,400.00 (\$59,400.00) \$0.00 \$0.00 (\$1,022.45) (\$1,022.45) (\$1,022.45)	Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user jamesc4 overridding Payment
	2660 -	SUBSTRUCTURE REPAIR (FORMED)  Total  SUPPLEMENTARY WEARING SURFACE	Overrun - Tota	Overrun Overrun - To	11 12 12 12 9 9 ottal	2023 Dec 4, 2023 Dec 18, 2023 Dec 18, 2023  Nov 1, 2023  Sep 5, 2023 Sep 5,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$59,400.00) \$59,400.00 (\$59,400.00) \$0.00 \$0.00 (\$1,022.45) (\$1,022.45) (\$1,022.45) \$1,648.50	Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user jamesc4 overridding Payment Estimate Item Adjustment (0007) due to user jamesc4 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6P3288	2770	SUPPLEMENTARY	Material	Турс		2023				
		WEARING SURFACE MATERIAL			7	Oct 2, 2023	SYSTEM	(\$1,648.50)		
					10	Nov 16, 2023	SYSTEM	\$1,648.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user jamesc4 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					10	Nov 16, 2023	SYSTEM	(\$1,648.50)	·	
				- Total				(\$1,648.50)		
			Material - Tota	ı				(\$1,648.50)		
			MaterialCredit		8	Oct 16, 2023	SYSTEM	\$1,648.50		
				- Total				\$1,648.50		
			MaterialCredit	- Total				\$1,648.50		
	2770	- Total						\$0.00		
	2780	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		5	Sep 5, 2023	SYSTEM	\$67,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
		SURFACE			5	Sep 5, 2023	SYSTEM	(\$67,614.00)		
					6	Sep 19, 2023	SYSTEM	\$67,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user jamesc4 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					6	Sep 19, 2023	SYSTEM	(\$67,614.00)		
					7	Oct 2, 2023	SYSTEM	(\$67,614.00)		
					10	Nov 16, 2023	SYSTEM	\$67,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user jamesc4 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
					10	Nov 16, 2023	SYSTEM	(\$67,614.00)		
				- Total				(\$67,614.00)		
			Material - Tota	ı				(\$67,614.00)		
			MaterialCredit		8	Oct 16, 2023	SYSTEM	\$67,614.00		
				- Total				\$67,614.00		
			MaterialCredit - Total					\$67,614.00		
	2780	- Total						\$0.00		
	3000	OPEN CELL FOAM JOINT SEAL	Material		13	Jan 2, 2024	SYSTEM	\$2,054.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment Estimate Exception 23 on the current Payment Estimate.	
						13				·
					13	Jan 2, 2024	SYSTEM	(\$2,054.00)	·	
					14		SYSTEM	(\$2,054.00) \$2,054.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment Estimate Exception 21 on the current Payment Estimate.	
						2024 Jan 16,		\$2,054.00 (\$2,054.00)	Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment	
				- Total	14	2024 Jan 16, 2024 Jan 16,	SYSTEM	\$2,054.00 (\$2,054.00) \$0.00	Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment	
			Material - Tota		14	2024 Jan 16, 2024 Jan 16,	SYSTEM	\$2,054.00 (\$2,054.00) \$0.00	Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment	
		- Total			14	Jan 16, 2024 Jan 16, 2024	SYSTEM	\$2,054.00 (\$2,054.00) \$0.00 \$0.00	Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment Estimate Exception 21 on the current Payment Estimate.	
	<b>3000 3020</b>	SUPPLEMENTARY WEARING SURFACE	Material - Tota		14	2024 Jan 16, 2024 Jan 16,	SYSTEM	\$2,054.00 (\$2,054.00) \$0.00	Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment	
		SUPPLEMENTARY WEARING			14	2024 Jan 16, 2024 Jan 16, 2024 Sep 5,	SYSTEM	\$2,054.00 (\$2,054.00) \$0.00 \$0.00	Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment Estimate Exception 21 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc4 overridding Payment	
		SUPPLEMENTARY WEARING SURFACE			14	2024 Jan 16, 2024 Jan 16, 2024 Sep 5, 2023	SYSTEM SYSTEM SYSTEM	\$2,054.00 (\$2,054.00) \$0.00 \$0.00 \$0.00 \$2,205.00	Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment Estimate Exception 21 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc4 overridding Payment	
		SUPPLEMENTARY WEARING SURFACE			14 14 5 5 5	2024  Jan 16, 2024  Jan 16, 2024  Sep 5, 2023  Sep 5, 2023  Sep 19,	SYSTEM SYSTEM SYSTEM	\$2,054.00 (\$2,054.00) \$0.00 \$0.00 \$2,205.00	Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment Estimate Exception 21 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user jamesc4 overridding Payment Estimate Item Adjustment (0005) due to user jamesc4 overridding Payment	



MATERIAL   Material   Total	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
Total	J6P3288	3020	WEARING SURFACE	Material		10		SYSTEM	\$8,218.00	Estimate Item Adjustment (0003) due to user jamesc4 overridding Payment	
Material   1041   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   1021   102			MATERIAL	AL.		10		SYSTEM	(\$8,218.00)		
Moderal Code   8					- Total				(\$2,205.00)		
Total				Material - Tota					(\$2,205.00)		
Material Credit - Total				MaterialCredit		8		SYSTEM	\$2,205.00		
Overrun					- Total				\$2,205.00		
100   Nov 16   SYSTEM   (\$6,518.00)				MaterialCredit	- Total				\$2,205.00		
2023				Overrun	Overrun	5		SYSTEM	(\$805.00)		
						10		SYSTEM	(\$6,013.00)		
1000   LATEX MODIFIED   Material   Supplementary   Supplemen					Overrun - T	otal			(\$6,818.00)		
Automotive				Overrun - Total					(\$6,818.00)		
CONCRETE   VEARING SURFACE     2023		3020 -	· Total						(\$6,818.00)		
Sep 1, SySTEM   \$48,734.00		3030	LATEX MODIFIED CONCRETE	Material		5		SYSTEM	\$48,734.00	Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment	
Supplement   Supplement   Supplement   Supplement   Statistate   Sta			SURFACE			5	Sep 5, 2023	SYSTEM	(\$48,734.00)		
2023   SYSTEM   (\$48,734.00)						6		SYSTEM	\$48,734.00	Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment	
2023   10						6		SYSTEM	(\$48,734.00)		
10							7		SYSTEM	(\$48,734.00)	
Total   (\$45,734.00)						10	Nov 16,	SYSTEM	\$48,734.00	Estimate Item Adjustment (0020) due to user jamesc4 overridding Payment	
Material - Total   (\$48,734.00)						10		SYSTEM	(\$48,734.00)		
Material Credit					- Total				(\$48,734.00)		
Supplemental   Supp				Material - Tota					(\$48,734.00)		
Material Credit - Total   \$48,734.00				MaterialCredit		8		SYSTEM	\$48,734.00		
Supplementary   Wearing Supplementary   Wearing Supplementary   Wearing Supplement   Supplementary   Supplem						- Total			\$48,734.00		
SUPPLEMENTARY   WEARING SURFACE   MATERIAL     6				MaterialCredit	rialCredit - Total				\$48,734.00		
SurFACE   Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment Estimate Exception 3 on the current Payment Estimate.		3030 -	· Total						\$0.00		
6   Sep 19, 2023   SYSTEM   (\$4,200.00)     7		3760	WEARING SURFACE	Material		6		SYSTEM	\$4,200.00	Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment	
2023			IVIATERIAL			6		SYSTEM	(\$4,200.00)		
2023   Estimate Item Adjustment (0005) due to user jamesc4 overridding Payment Estimate Exception 6 on the current Payment Estimate.   10   Nov 16, 2023   SYSTEM (\$6,587.00)						7		SYSTEM	(\$4,200.00)		
2023   (\$4,200.00)						10		SYSTEM	\$6,587.00	Estimate Item Adjustment (0005) due to user jamesc4 overridding Payment	
Material - Total         (\$4,200.00)           MaterialCredit         8         Oct 16, 2023         \$4,200.00           - Total         \$4,200.00           MaterialCredit - Total         \$4,200.00           Overrun         Overrun         6         Sep 19, 2023         \$YSTEM         (\$1,400.00)           10         Nov 16, SYSTEM         (\$2,387.00)						10		SYSTEM	(\$6,587.00)		
MaterialCredit					- Total				(\$4,200.00)		
2023				Material - Tota					(\$4,200.00)		
MaterialCredit - Total         \$4,200.00           Overrun         Overrun         6         Sep 19, 2023         SYSTEM (\$1,400.00)           10         Nov 16, SYSTEM (\$2,387.00)				MaterialCredit		8		SYSTEM	\$4,200.00		
Overrun Overrun 6 Sep 19, 2023 (\$1,400.00)  10 Nov 16, SYSTEM (\$2,387.00)					- Total				\$4,200.00		
2023 10 Nov 16, SYSTEM (\$2,387.00)				MaterialCredit	- Total				\$4,200.00		
				Overrun	Overrun	6		SYSTEM	(\$1,400.00)		
2023						10	Nov 16, 2023	SYSTEM	(\$2,387.00)		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J6P3288	3760	SUPPLEMENTARY WEARING	Overrun	Overrun - T	otal			(\$3,787.00)			
		SURFACE MATERIAL	Overrun - Tota	ıl				(\$3,787.00)			
	3760 -	- Total						(\$3,787.00)			
	3770	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		6	Sep 19, 2023	SYSTEM	\$142,579.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
					6	Sep 19, 2023	SYSTEM	(\$142,579.40)			
					7	Oct 2, 2023	SYSTEM	(\$142,579.40)			
					8	Oct 16, 2023	SYSTEM	\$142,579.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					8	Oct 16, 2023	SYSTEM	(\$142,579.40)			
					9	Nov 1, 2023	SYSTEM	\$142,579.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user jamesc4 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
					9	Nov 1, 2023	SYSTEM	(\$142,579.40)			
					10	Nov 16, 2023	SYSTEM	\$142,579.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user jamesc4 overridding Payment Estimate Exception 13 on the current Payment Estimate.		
									10	Nov 16, 2023	SYSTEM
				- Total				(\$142,579.40)			
			Material - Tota					(\$142,579.40)			
			MaterialCredit		8	Oct 16, 2023	SYSTEM	\$142,579.40			
				- Total				\$142,579.40			
			MaterialCredit	- Total				\$142,579.40			
	3770 -	Total									
	3//0	- Total						\$0.00			
J6P3288 -		- 10tai						\$0.00 \$257,792.80			
J6P3288 - J6S3283B	Total	ASPH. CONC. MIXTURE PG 70-22 (SP095C)	Material		10	Nov 16, 2023	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user Jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
	Total	ASPH. CONC. MIXTURE PG	Material		10		SYSTEM	\$257,792.80	Estimate Item Adjustment (0021) due to user jamesc4 overridding Payment		
	Total	ASPH. CONC. MIXTURE PG	Material	- Total		2023 Nov 16,		\$257,792.80 \$1,049,092.95	Estimate Item Adjustment (0021) due to user jamesc4 overridding Payment		
	Total	ASPH. CONC. MIXTURE PG	Material  Material - Tota			2023 Nov 16,		\$257,792.80 \$1,049,092.95 (\$1,049,092.95)	Estimate Item Adjustment (0021) due to user jamesc4 overridding Payment		
	Total 3890	ASPH. CONC. MIXTURE PG				2023 Nov 16,		\$257,792.80 \$1,049,092.95 (\$1,049,092.95) \$0.00	Estimate Item Adjustment (0021) due to user jamesc4 overridding Payment		
	Total 3890	ASPH. CONC. MIXTURE PG 70-22 (SP095C)	Material - Tota			2023 Nov 16,		\$257,792.80 \$1,049,092.95 (\$1,049,092.95) \$0.00	Estimate Item Adjustment (0021) due to user jamesc4 overridding Payment		
	Total 3890 3890 -	ASPH. CONC. MIXTURE PG 70-22 (SP095C)  - Total  FURN & PLACE CONC MATL FOR	Material - Tota		10	2023 Nov 16, 2023 Jun 30,	SYSTEM	\$257,792.80 \$1,049,092.95 (\$1,049,092.95) \$0.00 \$0.00	Estimate Item Adjustment (0021) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment		
	Total 3890 3890 -	ASPH. CONC. MIXTURE PG 70-22 (SP095C)  - Total  FURN & PLACE CONC MATL FOR	Material - Tota		10	2023 Nov 16, 2023 Jun 30, 2023 Jun 30,	SYSTEM	\$257,792.80 \$1,049,092.95 (\$1,049,092.95) \$0.00 \$0.00 \$28,057.50	Estimate Item Adjustment (0021) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment		
	Total 3890 3890 -	ASPH. CONC. MIXTURE PG 70-22 (SP095C)  - Total  FURN & PLACE CONC MATL FOR	Material - Tota		10	2023 Nov 16, 2023 Jun 30, 2023 Jun 30, 2023 Jul 17,	SYSTEM SYSTEM	\$257,792.80 \$1,049,092.95 (\$1,049,092.95) \$0.00 \$0.00 \$28,057.50	Estimate Item Adjustment (0021) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment		
	Total 3890 3890 -	ASPH. CONC. MIXTURE PG 70-22 (SP095C)  - Total  FURN & PLACE CONC MATL FOR	Material - Tota		1 1 2	Jun 30, 2023  Jun 30, 2023  Jun 30, 2023  Jul 17, 2023  Jul 17,	SYSTEM SYSTEM SYSTEM	\$257,792.80 \$1,049,092.95 (\$1,049,092.95) \$0.00 \$0.00 \$28,057.50 (\$28,057.50) \$229,839.30	Estimate Item Adjustment (0021) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment		
	Total 3890 3890 -	ASPH. CONC. MIXTURE PG 70-22 (SP095C)  - Total  FURN & PLACE CONC MATL FOR	Material - Tota		10	2023 Nov 16, 2023 Jun 30, 2023 Jun 30, 2023 Jul 17, 2023 Jul 17, 2023 Aug 2,	SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM	\$257,792.80 \$1,049,092.95 (\$1,049,092.95) \$0.00 \$0.00 \$28,057.50 (\$28,057.50) \$229,839.30	Estimate Item Adjustment (0021) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.		
	Total 3890 3890 -	ASPH. CONC. MIXTURE PG 70-22 (SP095C)  - Total  FURN & PLACE CONC MATL FOR	Material - Tota		10 1 1 2 2 3	2023 Nov 16, 2023 Jun 30, 2023 Jul 17, 2023 Jul 17, 2023 Aug 2, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$257,792.80 \$1,049,092.95 (\$1,049,092.95) \$0.00 \$0.00 \$28,057.50 (\$28,057.50) \$229,839.30 (\$229,839.30) \$310,780.35	Estimate Item Adjustment (0021) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.		
	Total 3890 3890 -	ASPH. CONC. MIXTURE PG 70-22 (SP095C)  - Total  FURN & PLACE CONC MATL FOR	Material - Tota		10 1 2 2 3 3 3	2023  Nov 16, 2023  Jun 30, 2023  Jun 30, 2023  Jul 17, 2023  Aug 2, 2023  Aug 2, 2023  Sep 5,	SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM	\$257,792.80 \$1,049,092.95 (\$1,049,092.95) \$0.00 \$0.00 \$28,057.50 (\$28,057.50) \$229,839.30 (\$229,839.30) \$310,780.35	Estimate Item Adjustment (0021) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.		
	Total 3890 3890 -	ASPH. CONC. MIXTURE PG 70-22 (SP095C)  - Total  FURN & PLACE CONC MATL FOR	Material - Tota		10 1 1 2 2 3 3 5 5	2023 Nov 16, 2023 Jun 30, 2023 Jun 30, 2023 Jul 17, 2023 Aug 2, 2023 Aug 2, 2023 Sep 5, 2023 Sep 5,	SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM	\$257,792.80 \$1,049,092.95 (\$1,049,092.95) \$0.00 \$0.00 \$28,057.50 (\$28,057.50) \$229,839.30 (\$229,839.30) \$310,780.35 (\$310,780.35)	Estimate Item Adjustment (0021) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.		



J6S3283B   J6CONC MATL FOR FULL DEPTH	
FULL DEPTH    Naterial - Total   S0.00	
Overrun         Overrun         7         Oct 2, 2023         SYSTEM         (\$2,244.60)           8         Oct 16, 2023         SYSTEM         (\$52,109.55)           10         Nov 16, 2023         SYSTEM         (\$54,954.00)           11         Dec 4, 2023         SYSTEM         (\$41,273.55)           Overrun - Total         (\$150,581.70)           Overrun - Total         (\$150,581.70)           3950 - Total         (\$150,581.70)           3980 FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR         Overrun         10         Nov 16, 2023         SYSTEM         (\$4,356.00)           11         Dec 4, 2023         SYSTEM         (\$5,409.00)	
2023	
2023	
2023	
2023	
Overrun - Total   (\$150,581.70)	
3950 - Total   (\$150,581.70)     3980   FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR   10   Nov 16, 2023   SYSTEM (\$4,356.00)	
3980 FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR FOR FOR FOR FOR FOR FOR FOR FOR FOR	
PAVEMENT 2023	
2023	
Overrun - Total (\$9,765.00)	
Overrun - Total (\$9,765.00)	
3980 - Total (\$9,765.00) 3990 DOWEL BAR Material 1 Jun 30, SYSTEM \$3,886.00 This adjustment offsets the original system-generated Material	
(DRILLING, 2023 Estimate Item Adjustment (0001) due to user jamesc4 overrid Estimate Exception 2 on the current Payment Estimate.	Iding Payment
1 Jun 30, 2023 SYSTEM (\$3,886.00)	
2 Jul 17, 2023 \$27,202.00 This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0001) due to user jamesc4 overrid Estimate Exception 4 on the current Payment Estimate.	
2 Jul 17, 2023 SYSTEM (\$27,202.00)	
3 Aug 2, 2023 \$YSTEM \$36,984.00 This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0004) due to user jamesc4 overrid Estimate Exception 3 on the current Payment Estimate.	
3 Aug 2, 2023 SYSTEM (\$36,984.00)	
4 Aug 16, 2023 \$35,984.00 This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0001) due to user jamesc4 overrid Estimate Exception 1 on the current Payment Estimate.	
4 Aug 16, 2023 SYSTEM (\$36,984.00)	
5 Sep 5, 2023 SYSTEM \$2,036.80 This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0013) due to user jamesc4 overrid Estimate Exception 7 on the current Payment Estimate.	
5 Sep 5, 2023 (\$2,036.80)	
-Total \$0.00	
Material - Total \$0.00	
3990 - Total \$0.00	
4010 REMOVAL FOR Overrun Overrun 9 Nov 1, 2023 (\$41,610.00)  CLASS B PARTIAL DEPTH PAVT R	
Overrun - Total (\$41,610.00)	
Overrun - Total (\$41,610.00)	
4010 - Total (\$41,610.00)	
4130 4 IN TEMPORARY PAVEMENT MARKING PAINT MARKING PAINT MARKING PAINT MARKING PAINT MARKING PAINT STATE A SYSTEM S1,390.75 SYSTEM \$1,390.75 Estimate Item Adjustment (0016) due to user jamesc4 overrid Estimate Exception 11 on the current Payment Estimate.	
11 Dec 4, 2023 (\$1,390.75)	
13 Jan 2, 2024 \$32,753.12 This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0012) due to user jamesc4 overrid Estimate Exception 15 on the current Payment Estimate.	
13 Jan 2, 2024 (\$32,753.12)	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3283B	4130	4 IN TEMPORARY PAVEMENT MARKING PAINT	Material		14	Jan 16, 2024	SYSTEM	\$33,115.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					14	Jan 16, 2024	SYSTEM	(\$33,115.62)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
			Other Item Adjustment	REFL	13	Jan 2, 2024	jamesc4	(\$6,550.63)	Withholding 20% for reflectivity
				REFL - Tota	ı			(\$6,550.63)	
			Other Item Ad	justment - To	tal			(\$6,550.63)	
	4130 -	Total						(\$6,550.63)	
	4200	MGS GUARDRAIL	Construction Stockpile STMA		5	Sep 5, 2023	SYSTEM	\$34,665.75	Payment Estimate Item Adjustment generated Stockpile Transaction
			O T WIN		6	Sep 19, 2023	SYSTEM	\$226,323.13	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$260,988.88	
			Construction	Stockpile STN	/IA - Total			\$260,988.88	
			Construction Stockpile STMI		5	Sep 5, 2023	SYSTEM	\$78,030.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$78,030.00	
			Construction	Stockpile STI	/II - Total			\$78,030.00	
	4200 -							\$339,018.88	
	4210	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile STMI		5	Sep 5, 2023	SYSTEM	\$4,100.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		,		- Total				\$4,100.00	
		_	Construction	Stockpile STI	/II - Total			\$4,100.00	
	4210 -					-		\$4,100.00	
	4220	MGS HEIGHT AND BLOCK TRANSITION	BLOCK Stockpile		5 Sep 5, 2023 SYSTEM			\$394.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$394.50	
	1000		Construction	Stockpile STI	/II - Total			\$394.50	
	4220 -				_		2112	\$394.50	
	4230	MGS END ANCHOR	Construction Stockpile STMI		5	Sep 5, 2023	SYSTEM	\$33,620.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total	II. Total			\$33,620.00	
	4200	Total	Construction	Stockpile STA	ni - Total			\$33,620.00	
	4230 - 4240	TYPE A	Construction		5	Sep 5,	SYSTEM	\$33,620.00 \$78,750.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		CRASHWORTHY END TERMINAL	Stockpile	Total		2023			,
		(MASH)	Construction	- Total	/II - Total			\$78,750.00 \$78,750.00	
	4240 -	Total	Sonstruction :	Stockpile 311	m - TOtal			\$78,750.00	
	4250	TYPE D	Construction		3	Aug 2,	SYSTEM	\$46,282.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	4230	CRASHWORTHY END TERMINAL	Stockpile STMI	- Total	3	2023	STSTEM	\$46,282.00	rayment Estimate item rujustinent generateu Stockpile Hansaction
		(MASH)	Construction		/II - Total			\$46,282.00	
	4250 -	Total	Sonstruction :	Stockpile 311	m- Total			\$46,282.00	
J6S3283B								\$293,658.05	
Overall - To								\$551,450.85	
Overall - I	otai							ψυυ 1,400.00	

# MoDOT

## Contract Adjustments for Contract - 230421-F06

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 27 of 27