71.71%



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 17, 2024

June 28, 2024

Progress Estimate Number	Contract ID	230519-C04	Pay Period Start	January 2, 2024	Original Contract Amount	\$10,985,676.85
13	Prime Contractor	Radmacher Brothers Excavating Co.,Inc.	Pay Period End	2024	Net Change Order Amount Current Contract Amount	(\$171,710.46) \$10,813,966.39

Approval Date					By User						
January 17, 2024		Generated and Approved (and should be considered Draft) at the Project Office Level by									
January 17, 2024		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by									
January 18, 2024			Reviewed and Approved at the Cer	ntral Office Controllers Office Level by	ramses1						
Original Comp	letion Date	Current Completion Date	mpletion Date Actual Completion Date % of Current Contract Amou								

	Milestones		
Date Description	Original Completion Date	No Milestones Exist for Contract	
Acceptance Date			
Awarded Date	June 7, 2023	June 7, 2023	
Letting Date	May 19, 2023	May 19, 2023	
Notice to Proceed Date	July 10, 2023	July 10, 2023	
Open to Traffic Date			
Work Began Date	July 17, 2023	July 17, 2023	

June 28, 2024

Contract Total Pa	Contract Total Pay For Estimate No. 13												
		This Estimate	Previous	To Date									
230519-C04													
	Total Posted Items Pay	\$61,760.40	\$7,692,653.87	\$7,754,414.27									
	Gross Item Adjustments	(\$924.00)	\$51,307.06	\$50,383.06									
	Incentive	\$0.00	\$0.00	\$0.00									
	Disincentive	\$0.00	\$0.00	\$0.00									
	Liquidated Damage	\$0.00	\$0.00	\$0.00									
	Other Contract Adjustments	\$0.00	(\$155.26)	(\$155.26)									
			\$7,743,805.67	\$7,804,642.07									
<b>Contract Total Pa</b>	yable This Estimate:	\$60,836.40											

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4P3443	0100	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$14.000	83	\$1,162.00
	0140	5021334	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	SQYD	\$137.000	175	\$23,975.00
	0150	5041000	CONCRETE APPROACH PAVEMENT	SQYD	\$180.000	58.6	\$10,548.00
	0220	6113010	FURNISHING TYPE 1 ROCK BLANKET	CUYD	\$56.000	300	\$16,800.00
	0230	6113030	PLACING TYPE 1 ROCK BLANKET	CUYD	\$22.000	300	\$6,600.00
	0650	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	SQYD	\$3.800	450	\$1,710.00
	0840	8061004	SEDIMENT TRAP ROCK	CUYD	\$108.000	6.3	\$680.40
	0850	8061005	ROCK DITCH CHECK	LF	\$19.000	15	\$285.00
Project J4P3	443 - Total						\$61,760.40
Overall - Tot	al						\$61,760,40

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3443	0160	PIPE COLLAR, TYPE A	Material			-1	\$1,600.00	(\$1,600.00)
	0160	PIPE COLLAR, TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user raybol1	1	\$1,600.00	\$1,600.00

Revision 3/23/2023 Page 1 of 34



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 17, 2024

Progress Estimate Number	Contract ID	230519-C04	Pay Period Start	January 2, 2024	Original Contract Amount	\$10,985,676.85
13	Prime Contractor	Radmacher Brothers Excavating Co.,Inc.	Pay Period End		Not Change Order	(\$171,710.46) \$10,813,966.39

ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
443					overridding Payment Estimate Exception 6 on the current Payment Estimate.			
	0210	ROCK LINING	Material			-102	\$136.00	(\$13,872.00
	0210	ROCK LINING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	102	\$136.00	\$13,872.00
	0500	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-8	\$340.00	(\$2,720.00
	0500	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	8	\$340.00	\$2,720.00
	0680	REINFORCING STEEL (CULVERTS)	Material			-8,330	\$2.70	(\$22,491.00
	0680	REINFORCING STEEL (CULVERTS)			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	8,330	\$2.70	\$22,491.00
	0770	18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	Material			-1	\$1,900.00	(\$1,900.00
	0770	18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	1	\$1,900.00	\$1,900.00
	0950	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material			-15,226.2	\$98.00	(\$1,492,167.60
	0950	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	15,226.2	\$98.00	\$1,492,167.60
	1390	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-21	\$44.00	(\$924.00
	1780	BRIDGE APPROACH SLAB (MAJOR)	Material			-128	\$340.00	(\$43,520.00
	1780	BRIDGE APPROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	128	\$340.00	\$43,520.00
	1840	SLAB ON CONCRETE NU- GIRDER	Material			-664	\$460.00	(\$305,440.00
	1840	SLAB ON CONCRETE NU- GIRDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	664	\$460.00	\$305,440.00
	1880	REINFORCING STEEL (EPOXY COATED)	Material			-10,970	\$2.10	(\$23,037.00

Revision 3/23/2023 Page 2 of 34

-15,520

15,520

\$2.10

\$2.10

(\$32,592.00)

\$32,592.00

(\$924.00)



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 17, 2024

2070

2070

Total

REINFORCING STEEL (EPOXY COATED)

REINFORCING STEEL (EPOXY COATED)

Material

Material

	Progre	ss Estimate Number	Contract ID Prime Contractor	230519-C04 Radmacher Co.,Inc.	4 Brothers Exc	avating	Pay Period Start Pay Period E	January 2, 2024 nd January 15, 2024	Original Con Amount Net Change ( Amount Current Cont	Order	\$10,985,676.85 (\$171,710.46) <b>t</b> \$10,813,966.39
Project Number	Line No.	Item D	escription	Adjustment Type	Other Item Adjustment Type		Comment	ts	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3443	1880		ORCING STEEL POXY COATED)	Material		generate Adji	ed Material Payr ustment (0012) o ng Payment Esti	the original system- ment Estimate Item due to user raybol1 imate Exception 15 Payment Estimate.	,	\$2.10	\$23,037.00
	2020	SLAB ON (	CONCRETE NU- GIRDER	Material					-838	\$450.00	(\$377,100.00)
	2020 SLAB ON CONCRETE I GIRD		CONCRETE NU- GIRDER	Material		generati Adji	ed Material Payr ustment (0010) o ng Payment Esti	the original system- ment Estimate Item due to user raybol1 imate Exception 11 Payment Estimate.		\$450.00	\$377,100.00

This adjustment offsets the original systemgenerated Material Payment Estimate Item Adjustment (0011) due to user raybol1

overridding Payment Estimate Exception 16 on the current Payment Estimate.

Revision 3/23/2023 Page 3 of 34



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4P3443	FAF 7-1(46)	2 Bridge replacements and intersection improvements	7	CASS	on Rte. 7 (275th Street) ov	er I-49	
Totals by .	Job Numbe	ers					
J4P3443		ed Item Pay s Item Adjustme		Item Pay	This Estimate \$61,760.40 (\$924.00) \$60,836.40	<b>Previous</b> \$7,692,653.87 \$51,307.06 <b>\$7,743,960.93</b>	<b>To Date</b> \$7,754,414.27 \$50,383.06 <b>\$7,804,797.33</b>
	Incen Disin	tive centive			\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00
		dated Damages Contract Adjus			\$0.00 \$0.00	\$0.00 (\$155.26)	\$0.00 (\$155.26)

Revision 3/23/2023 Page 4 of 34



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered	Status
		Ву	
Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 3049905, Project Item Line Number 0940, Material Set 304990596, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Need QCQA materials report for the Type 5 Aggregate rock.	raybol1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 5021334, Project Item Line Number 0950, Material Set 502133496, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action 0501CCPAQCQA 10 1/2 in. is insufficient.	Need QC materials report for the concrete.	raybol1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 5021334, Project Item Line Number 0950, Material Set 502133496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Need QC materials report for the rock.	raybol1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 5021334, Project Item Line Jumber 0950, Material Set 502133496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Need QC materials report for the sand.	raybol1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 5031010A, Project Item Line lumber 1780, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Need QCQA materials report for the concrete.	raybol1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 6044011, Project Item Line Jumber 0160, Material Set 604401196, Material 0604CPCR - Collar for Pipe Connection, Acceptance Action Generic 0604CPCR is insufficient.	Need materials report for the pipe collar.	raybol1	Overridden
estimate Exception Type: Insufficient Materials: Project J4P3443, Item 6097000, Project Item Line stumber 0210, Material Set 609700096, Material 0611EPM - Embankment Protection Material, acceptance Action Generic 0611EPM is insufficient.	Need materials report for the rock lining.	raybol1	Overridden
estimate Exception Type: Insufficient Materials: Project J4P3443, Item 6200021, Project Item Line stumber 0500, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indicat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Need materials report for the preformed arrows.	raybol1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7034221, Project Item Line Number 1840, Material Set 703422196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Need QC and QCQA materials report for the rock.	raybol1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7034221, Project Item Line Number 1840, Material Set 703422196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Need QC materials report for the sand.	raybol1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7034221, Project Item Line Jumber 2020, Material Set 703422196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Need QC materials report for the concrete.	raybol1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7061030, Project Item Line Jumber 0680, Material Set 706103096, Material 1036RSDFPL42M29 - Reinforcing Steel No. 9/M29 Gr 00/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Need PAL materials report for the rebar.	raybol1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7061030, Project Item Line Number 0680, Material Set 706103096, Material 1036RSDFPL42M36 - Reinforcing Steel No. 11/M36 Gr 10/M420@, Acceptance Action Generic ReSteelBars is insufficient.	Need PAL materials report for the rebar.	raybol1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7061030, Project Item Line Jumber 0680, Material Set 706103096, Material 1036RSDFPL42M32 - Reinforcing Steel No. 10/M32 Gr 00/M420@, Acceptance Action Generic ReSteelBars is insufficient.	Need PAL materials report for the rebar.	raybol1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7101000, Project Item Line Jumber 1880, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Need PAL materials report for the anchor bolts.	raybol1	Overridden
estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7101000, Project Item Line lumber 2070, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch iolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Need PAL materials report for the anchor bolts.	raybol1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7320018A, Project Item Line Jumber 0770, Material Set 7320018A96, Material 1020ESAC - Flared End Section Aluminum coated teel, Acceptance Action Generic 1020ESAC is insufficient.	Need materials report for the 18" Flared End Section.	raybol1	Overridden
Estimate Exception Type: Item Overrun: Contract 230519-C04, Contract Project J4P3443, Project Item ine Number 1390, Contract Line Item Number 1390, Item 9027400, Minor Item.	No Remark was entered by Engineer	raybol1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230519-C04, Contract Project J4P3443, Project Item Line Number 0900, Contract Line Item Number 0900, Item 8064138, Minor Item.	No Remark was entered by Engineer	raybol1	Acknowledged

Revision 3/23/2023 Page 5 of 34



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted amo		time the E	estimate was	s Gener			
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230519-C04	J4P3443	0001	0010	2013000	CLEARING AND GRUBBING	2.00	0.00	2.00	ACRE	2.00	\$9,000.00	\$18,000.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	-1.00	0.00	LS	0.00	\$202,700.00	\$0.00
		0001	0021	2022010	REMOVAL OF IMPROVEMENTS	0.00	1.00	1.00	LS	0.90	\$200,750.00	\$180,675.00
		0001	0030	2031000	CLASS A EXCAVATION	14,656.00	0.00	14,656.00	CUYD	14,656.00	\$15.00	\$219,840.00
		0001	0040	2035500	EMBANKMENT IN PLACE	28,657.00	0.00	28,657.00	CUYD	28,657.00	\$19.00	\$544,483.00
		0001	0050	2036000	COMPACTING EMBANKMENT	12,365.00	0.00	12,365.00	CUYD	12,365.00	\$3.10	\$38,331.50
		0001	0060	2037075	COMPACTING IN CUT	92.90	0.00	92.90	STA	92.90	\$660.00	\$61,314.00
		0001	0070	2063000	CLASS 3 EXCAVATION	2,628.00	142.00	2,770.00	CUYD	1,839.00	\$14.00	\$25,746.00
		0001	0080	2063300	CLASS 4 EXCAVATION	17.00	0.00	17.00	CUYD	17.00	\$144.00	\$2,448.00
		0001	0090	2063500	CULVERT CLEANOUT	3.00	0.00	3.00	EA	0.00	\$1,600.00	\$0.00
		0001	0095	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	1.00	\$44,800.00	\$44,800.00
		0001	0100	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,854.00	-764.00	1,090.00	SQYD	406.00	\$14.00	\$5,684.00
		0001	0110	3049905	MISC.OPTIONAL BASE	3.027.00	0.00	3,027.00	SQYD	2,146.80	\$14.00	\$30,055.20
		0001	0120	4019905	MISC.OPTIONAL PAVEMENT	3,026.90	0.00	3,026.90	SQYD	2,635.70	\$105.00	\$276,748.50
		0001	0130	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT.	762.50	-762.50	0.00	SQYD	0.00	\$105.00	\$0.00
					JOINTS)							
		0001	0140	5021334	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	761.30	0.00	761.30	SQYD	404.10	\$137.00	\$55,361.70
		0001	0150	5041000	CONCRETE APPROACH PAVEMENT	275.20	0.00	275.20	SQYD	216.00	\$180.00	\$38,880.00
		0001	0160	6044011	PIPE COLLAR, TYPE A	1.00	0.00	1.00	EA	1.00	\$1,600.00	\$1,600.00
		0001	0170	6053030A	PIPE AGGREGATE PAVEMENT EDGE DRAIN	515.00	-515.00	0.00	LF	0.00	\$36.00	\$0.00
		0001	0180	6054020	OUTLET PIPES AND SPLASH PADS	2.00	-2.00	0.00	EA	0.00	\$1,400.00	\$0.00
		0001	0190	6081000	CONCRETE MEDIAN	2,298.80	0.00	2,298.80	SQYD	0.00	\$64.00	\$0.00
		0001	0200	6091011	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	1,780.00	0.00	1,780.00	LF	0.00	\$25.00	\$0.00
		0001	0210	6097000	ROCK LINING	127.00	0.00	127.00	CUYD	102.00	\$136.00	\$13,872.00
		0001 0	0220	6113010	FURNISHING TYPE 1 ROCK BLANKET	2,429.00	0.00	2,429.00	CUYD	2,421.00	\$56.00	\$135,576.00
		0001	0230	6113030	PLACING TYPE 1 ROCK BLANKET	2,429.00	0.00	2,429.00	CUYD	2,421.00	\$22.00	\$53,262.00
		0001	0240	6122008	IMPACT ATTENUATOR 40 MPH (SAND BARREL ARRAY)	1.00	0.00	1.00	EA	1.00	\$4,500.00	\$4,500.00
		0001	0250	6122010	IMPACT ATTENUATOR 50 MPH (SAND BARREL ARRAY)	1.00	0.00	1.00	EA	1.00	\$4,500.00	\$4,500.00
		0001	0260	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	5.00	0.00	5.00	EA	5.00	\$4,500.00	\$22,500.00
		0001	0270	6122030	IMPACT ATTENUATOR (RELOCATION)	3.00	0.00	3.00	EA	0.00	\$4,500.00	\$0.00
		0001	0280	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	6.00	0.00	6.00	EA	0.00	\$1,100.00	\$0.00
		0001	0290	6132018	FURNISHING AND PLACING CONCRETE MATERIAL FOR	202.70	0.00	202.70	CUYD	0.00	\$620.00	\$0.00
		0001	0300	6139905	CLASS A PARTIAL DEPTH PAVEMENT REPAIR  MISC.RAPID STRENGTH CONCRETE FOR PAVEMENT REPAIR	321.60	0.00	321.60	SQYD	0.00	\$170.00	\$0.00
		0001	0310	6143014	MANHOLE FRAME AND COVER, TYPE 4	1.00	0.00	1.00	EA	1.00	\$1,200.00	\$1,200.00
		0001	0320	6161005	CONSTRUCTION SIGNS	2,497.00	0.00	2,497.00	SQFT	2,186.10	\$6.30	\$13,772.43
		0001	0330	6161008	ADVANCED WARNING RAIL SYSTEM	20.00	0.00	20.00	EA	7.00	\$68.00	\$476.00
		0001	0340	6161025	CHANNELIZER (TRIM LINE)	141.00	263.00	404.00	EA	404.00	\$19.00	\$7,676.00
			0350	6161030	TYPE III MOVEABLE BARRICADE	25.00	0.00	25.00	EA	9.00	\$170.00	\$1,530.00
		0001			DIRECTIONAL INDICATOR BARRICADE	68.00	0.00	68.00		56.00	\$79.00	
		0001	0360	6161033					EA			\$4,424.00
		0001	0370	6161040	FLASHING ARROW PANEL	5.00	0.00	5.00	EA	3.00	\$3,400.00	\$10,200.00
		0001	0380	6161055	SEQUENTIAL FLASHING WARNING LIGHT	68.00	0.00	68.00	EA	56.00	\$68.00	\$3,808.00
		0001	0390	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	6.00	0.00	6.00	EA	4.00	\$5,800.00	\$23,200.00
		0001	0400	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	30.00	0.00	30.00	EA	10.00	\$1,500.00	\$15,000.00
		0001	0410	6173103	CONCRETE TRAFFIC BARRIER, TYPE D (MOMENT SLAB)	1,233.00	-515.00	718.00	LF	213.00	\$180.00	\$38,340.00
		0001	0420	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	4,723.00	866.00	5,589.00	LF	5,589.00	\$16.00	\$89,424.00
		0001	0430	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	9,130.00	0.00	9,130.00	LF	2,301.00	\$10.00	\$23,010.00
Revision 3/23/20	ກລວ											Page 6 of 34

Page 6 of 34 Revision 3/23/2023



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

	Project				eport Generated date and can differ from the posted ame Description	ount at the	Net	stimate was	Gener Unit	ated. Total	Unit Price	Total Value POSTED
Contract Nm.CONTRACT	No.	Category	Line No.	Item Code	Description	Quantity	Change Order	Current Quantity	Offic	Posted Approved Qty	Offit Price	To Date (See report generated date)
230519-C04	J4P3443	0001	0440	6181000	MOBILIZATION	1.00	0.00	1.00	LS		\$825,000.00	\$825,000.00
		0001	0450	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	1.00	0.00	1.00	EA	0.00	\$600.00	\$0.00
		0001	0460	6191000	PAVEMENT EDGE TREATMENT	790.00	480.00	1,270.00	LF	1,270.00	\$6.80	\$8,636.00
		0001	0470	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	831.00	0.00	831.00	LF	0.00	\$6.90	\$0.00
		0001	0480	6200012	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE	409.00	0.00	409.00	LF	0.00	\$12.00	\$0.00
		0001	0490	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	196.00	0.00	196.00	LF	0.00	\$21.00	\$0.00
		0001	0500	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	18.00	0.00	18.00	EA	8.00	\$340.00	\$2,720.00
		0001	0510	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	10.00	0.00	10.00	EA	0.00	\$290.00	\$0.00
		0001	0520	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	5.00	0.00	5.00	EA	0.00	\$680.00	\$0.00
		0001	0530	6200039	PREFORMED THERMOPLASTIC PAVEMENT MARKING, OFF RAMP WRONG WAY ARROW	6.00	0.00	6.00	EA	0.00	\$680.00	\$0.00
		0001	0540	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	39.00	0.00	39.00	EA	0.00	\$68.00	\$0.00
		0001	0550	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	228.00	0.00	228.00	LF	96.00	\$13.00	\$1,248.00
		0001	0560	6205440A	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	9.00	0.00	9.00	EA	1.00	\$160.00	\$160.00
		0001	0570	6205442	TEMPORARY NON-REMOVABLE MARKING TAPE STRAIGHT ARROW	3.00	4.00	7.00	EA	7.00	\$132.00	\$924.00
		0001	0580	6205443A	TEMPORARY NON-REMOVABLE MARKING TAPE COMBINATION STRAIGHT- LEFT/RIGHT ARROW	3.00	1.00	4.00	EA	4.00	\$260.00	\$1,040.00
		0001	0590	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	10,103.00	0.00	10,103.00	LF	0.00	\$0.25	\$0.00
		0001	0600	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	5,838.00	0.00	5,838.00	LF	0.00	\$0.25	\$0.00
		0001	0610	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,394.00	0.00	1,394.00	LF	0.00	\$0.50	\$0.00
		0001	0620	6207001	PAVEMENT MARKING REMOVAL	27,040.00	0.00	27,040.00	LF	4,815.00	\$0.60	\$2,889.00
		0001	0630	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	15.00	0.00	15.00	EA	4.00	\$100.00	\$400.00
		0001	0640	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	31,370.00	0.00	31,370.00	LF	26,684.00	\$0.15	\$4,002.60
		0001	0650	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	3,683.00	0.00	3,683.00	SQYD	3,647.00	\$3.80	\$13,858.60
		0001	0660	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.75	\$100,000.00	\$75,000.00
		0001	0670	7034041	CLASS B-1 CONCRETE (CULVERTS)	43.70	10.70	54.40	CUYD	54.40	\$1,800.00	\$97,920.00
		0001	0680	7061030	REINFORCING STEEL (CULVERTS)	6,370.00	1,960.00	8,330.00	LB	8,330.00	\$2.70	\$22,491.00
		0001	0690	7250318A	18 IN. PIPE GROUP B	76.00	0.00	76.00	LF	76.00	\$106.00	\$8,056.00
		0001	0700	7261018	18 IN. PIPE GROUP A	805.00	0.00	805.00	LF	112.00	\$89.00	\$9,968.00
		0001	0710	7261024	24 IN. PIPE GROUP A	220.00	0.00	220.00	LF	0.00	\$125.00	\$0.00
		0001	0720	7261036	36 IN. PIPE GROUP A	103.00	0.00	103.00	LF	103.00	\$190.00	\$19,570.00
		0001	0730	7261042	42 IN. PIPE GROUP A	383.00	94.00	477.00	LF	477.00	\$230.00	\$109,710.00
		0001	0735	7265442	JACKED 42 IN. CLASS V REINFORCED CONCRETE PIPE CULVERT (GASKET TYPE)	66.00	-66.00	0.00	LF	0.00	\$3,000.00	\$0.00
		0001	0740	7310048	PRECAST CONCRETE MANHOLE - 48 IN.	11.00	0.00	11.00	FT	11.00	\$460.00	\$5,060.00
		0001	0750	7311033	PRECAST CONCRETE DROP INLET 3 FT X 3 FT	8.00	0.00	8.00	FT	0.00	\$1,000.00	\$0.00
		0001	0760	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	1.00	0.00	1.00	FT	1.00	\$6,800.00	\$6,800.00
		0001	0770	7320018A	18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$1,900.00	\$1,900.00
		0001	0780	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	16.00	0.00	16.00	EA	0.00	\$1,900.00	\$0.00
		0001	0790	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$2,200.00	\$0.00
		0001	0800	7320636A	36 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600.00
		0001	0810	7320642A	42 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	4.00	0.00	4.00	EA	4.00	\$3,600.00	\$14,400.00
		0001	0820	8025006	MULCHING	10.40	0.00	10.40	ACRE	6.00	\$470.00	\$2,820.00
		0001	0830	8051000A	SEEDING - COOL SEASON GRASSES	10.40	0.00	10.40	ACRE	6.00	\$2,700.00	\$16,200.00
		0001	0840	8061004	SEDIMENT TRAP ROCK	56.20	0.00	56.20	CUYD	7.60	\$108.00	\$820.80

Page 7 of 34 Revision 3/23/2023



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted ame Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
230519-C04	J4P3443	0001	0850	8061005	ROCK DITCH CHECK	1,008.00	0.00	1,008.00	LF	Qty 613.00	\$19.00	\$11,647.00
		0001	0860	8061007A	CURB INLET CHECK	1.00	0.00	1.00	EA	0.00	\$132.00	\$0.00
		0001	0870	8061016	SEDIMENT REMOVAL	262.00	0.00	262.00	CUYD	50.00	\$27.00	\$1,350.00
		0001	0880	8061019	SILT FENCE	6,862.00	0.00	6,862.00	LF	220.00	\$1.30	\$286.00
		0001	0890	8064128	TYPE 1 TURF REINFORCEMENT MAT	1,227.00	0.00	1,227.00	SQYD	0.00	\$3.10	\$0.00
		0001	0900	8064138	TYPE 2D EROSION CONTROL BLANKET	6,262.00	0.00	6,262.00	SQYD	6,903.00	\$2.40	\$16,567.20
		0003	0940	3049905	MISC.ALTERNATE BASE	20,225.00	0.00	20,225.00	SQYD	17,937.80	\$12.00	\$215,253.60
		0003	0950	5021334	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT.	18,416.60	0.00	18,416.60	SQYD	15,226.20	\$98.00	\$1,492,167.60
		0003	0960	6262000A	JOINTS) PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP	12.70	0.00	12.70	STA	0.00	\$700.00	\$0.00
		0005	0980	5021340	TYPE A2 SHOULDER	1,808.20	0.00	1,808.20	SQYD	1,392.10	\$55.00	\$76,565.50
		0010	0990	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	2,114.00	538.00	2,652.00	LF	0.00	\$35.00	\$0.00
		0010	1000	6061069	MGS BRIDGE APPROACH TRANSITION SECTION	2.00	-2.00	0.00	EA	0.00	\$4,100.00	\$0.00
					(REGULAR/NO CURB)							
		0010	1010	6061074	MGS HEIGHT AND BLOCK TRANSITION	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0010	1020	6061080	MGS END ANCHOR	6.00	2.00	8.00	EA	0.00	\$1,400.00	\$0.00
		0010	1030	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	7.00	0.00	7.00	EA	0.00	\$3,400.00	\$0.00
		0010	1040	6064500	AGGREGATE BEDDING FOR 3 - STRAND GUARD CABLE	31.00	0.00	31.00	CUYD	0.00	\$125.00	\$0.00
		0010	1050	6069902	MISC.HTGC ANCHOR ASSEMBLY	1.00	0.00	1.00	EA	0.00	\$5,400.00	\$0.00
		0010	1060	6069903	MISC.HIGH TENSION GUARD CABLE	410.00	0.00	410.00	LF	0.00	\$39.00	\$0.00
		0010	1070	6240104A	SEPARATION GEOTEXTILE	274.00	0.00	274.00	SQYD	0.00	\$5.10	\$0.00
		0020	1080	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	16.00	0.00	16.00	EA	0.00	\$3,200.00	\$0.00
		0020	1090	9011115	BRACKET ARM, 15 FT. OR 4.6 M	16.00	0.00	16.00	EA	0.00	\$1,500.00	\$0.00
		0020	1100	9011312	LUMINAIRE, LED-B	16.00	0.00	16.00	EA	0.00	\$840.00	\$0.00
		0020	1110	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	4.00	0.00	4.00	EA	0.00	\$9,000.00	\$0.00
		0020	1120	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	460.00	0.00	460.00	LF	77.00	\$23.00	\$1,771.00
		0020	1130	9014004	CONDUIT, 4 IN. RIGID, PUSHED	527.00	0.00	527.00	LF	405.00	\$35.00	\$14,175.00
		0020	1140	9015010	TRENCHING TYPE I	5,804.00	0.00	5,804.00	LF	0.00	\$11.00	\$0.00
		0020	1150	9016110	PULL BOX, PREFORMED CLASS 1	5.00	0.00	5.00	EA	0.00	\$2,500.00	\$0.00
		0020	1160	9016112	PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	0.00	\$4,800.00	\$0.00
		0020	1170	9017002	CABLE, 2 AWG 1 CONDUCTOR	810.00	0.00	810.00	LF	0.00	\$5.30	\$0.00
		0020	1180	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	1,920.00	0.00	1,920.00	LF	0.00	\$2.40	\$0.00
		0020	1190	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	5,780.00	0.00	5,780.00	LF	0.00	\$4.80	\$0.00
		0020	1200	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	16.00	0.00	16.00	EA	0.00	\$3,200.00	\$0.00
		0020	1210	9018612	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	1.00	0.00	1.00	EA	0.00	\$8,100.00	\$0.00
		0030	1220	9020113	SIGNAL HEAD, TYPE 3T	5.00	0.00	5.00	EA	0.00	\$1,300.00	\$0.00
		0030	1230	9020213	SIGNAL HEAD, TYPE 3S	5.00	0.00	5.00	EA	0.00	\$1,300.00	\$0.00
		0030	1240	9020513	SIGNAL HEAD, TYPE 3B	8.00	0.00	8.00	EA	0.00	\$1,500.00	\$0.00
		0030	1250	9020833	SH-FLAT SHEET - SIGNAL SIGN	60.00	0.00	60.00	SQFT	0.00	\$66.00	\$0.00
		0030	1260	9020834	SIGNAL SIGN, MOUNTING HARDWARE	8.00	0.00	8.00	EA	0.00	\$380.00	\$0.00
		0030	1270	9022651	LUMINAIRE LED-A, 120 VOLT COMPATIBLE	3.00	0.00	3.00	EA	0.00	\$680.00	\$0.00
		0030	1280	9022715	POST, SIGNAL 15 FT.	4.00	0.00	4.00	EA	0.00	\$1,900.00	\$0.00
		0030	1290	9023115	POST, TYPE CL, 15 FT. ARM OR 4.6 M ARM	1.00	0.00	1.00	EA	0.00	\$9,700.00	\$0.00
		0030	1300	9023120	POST, TYPE CL, 20 FT. ARM OR 6.1 M ARM	1.00	0.00	1.00	EA	0.00	\$11,800.00	\$0.00
		0030	1310	9023130	POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	0.00	\$14,900.00	\$0.00
		0030	1320	9023135	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	1.00	0.00	1.00	EA	0.00	\$15,600.00	\$0.00
		0030	1330	9023215	POST, TYPE C, 15 FT. ARM OR 4.6 M ARM	1.00	0.00	1.00	EA	0.00	\$9,300.00	\$0.00

Revision 3/23/2023 Page 8 of 34



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted ame Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
230519-C04	J4P3443	0030	1340	9023230	POST, TYPE C, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	Qty 0.00	\$12,400.00	\$0.00
200010 001	011 0110	0030	1350	9024975	VIDEO DETECTION SYSTEM	1.00	0.00	1.00	EA	0.00	\$71,500.00	\$0.00
		0030	1360	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	789.00	0.00	789.00	LF	211.00	\$34.00	\$7,174.00
		0030	1370	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	137.00	0.00	137.00	LF	0.00	\$45.00	\$0.00
		0030	1380	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	115.00	0.00	115.00	LF	0.00	\$49.00	\$0.00
		0030	1390	9027400	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	193.00	0.00	193.00	LF	214.00	\$44.00	\$9,416.00
		0030	1400	9028100	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	180.00	0.00	180.00	LF	0.00	\$2.70	\$0.00
		0030	1410	9028202	CABLE, 2 AWG 1 CONDUCTOR, POWER	490.00	0.00	490.00	LF	0.00	\$5.40	\$0.00
		0030	1420	9028302	CABLE, 12 AWG 2 CONDUCTOR	1,260.00	0.00	1,260.00	LF	0.00	\$5.30	\$0.00
		0030	1430	9028311	CABLE, 16 AWG 7 CONDUCTOR	10,050.00	0.00	10,050.00	LF	0.00	\$3.30	\$0.00
		0030	1440	9028811	PULL BOX, PREFORMED CLASS 2	4.00	0.00	4.00	EA	0.00	\$3,400.00	\$0.00
		0030	1450	9028812	PULL BOX, PREFORMED CLASS 3	6.00	0.00	6.00	EA	0.00	\$4,900.00	\$0.00
		0030	1460	9029100	BASE, CONCRETE	21.40	0.00	21.40	CUYD	0.00	\$2.700.00	\$0.00
		0030	1470	9029401	TEMPORARY TRAFFIC SIGNALS AND LIGHTING	1.00	0.00	1.00	LS	1.00	\$236,000.00	\$236,000.00
		0040	1480	9031020	CONCRETE FOOTINGS, BOLT DOWN	7.30	0.00	7.30	CUYD	0.00	\$1,300.00	\$0.00
		0040	1490	9031210	STRUCTURAL STEEL POSTS	4.640.00	0.00	4,640.00	LB	0.00	\$5.30	\$0.00
		0040	1500	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL	8.00	0.00	8.00	EA	0.00	\$420.00	\$0.00
					TUBE)							
		0040	1510	9031270A	2 IN. PSST POST - 12 GA.	624.00	0.00	624.00	LF	0.00	\$21.00	\$0.00
		0040	1520	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	39.00	0.00	39.00	EA	0.00	\$84.00	\$0.00
		0040	1530	9031272A	2.25 IN. PSST POST INSERT (6 FT.) - 12 GA.	4.00	0.00	4.00	EA	0.00	\$137.00	\$0.00
		0040	1540	9031280	2.5 IN. PSST POST - 12 GA.	192.00	0.00	192.00	LF	0.00	\$24.00	\$0.00
		0040	1550	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	12.00	0.00	12.00	EA	0.00	\$105.00	\$0.00
		0040	1560	9035004A	SH-FLAT SHEET	365.00	0.00	365.00	SQFT	0.00	\$21.00	\$0.00
		0040	1570	9035011A	ST-STRUCTURAL	756.00	0.00	756.00	SQFT	0.00	\$32.00	\$0.00
		0040	1580	9035069A	SHF-FLAT SHEET FLUORESCENT	116.00	0.00	116.00	SQFT	0.00	\$24.00	\$0.00
		0040	1590	9039901	MISC.NB ON RAMP TRUSS #48	1.00	0.00	1.00	LS		\$136,800.00	\$0.00
		0040	1600	9039901	MISC.NEW TRUSS SIGNS ON EXISTING TRUSS #45	1.00	0.00	1.00	LS	0.00	\$13,200.00	\$0.00
		0040	1610	9039901	MISC.SB AT EXIT 158 TRUSS #41	1.00	0.00	1.00	LS		\$136,800.00	\$0.00
		0040	1620	9039901	MISC.SB OFF RAMP CANT. TRUSS #42	1.00	0.00	1.00	LS	0.00	\$89,500.00	\$0.00
		0040	1630	9039901	MISC.TUBULAR SUPPORT, TYPE S-1310, TRUSS #43	1.00	0.00	1.00	LS	0.00	\$52,600.00	\$0.00
		0050	1640	9105200	CONDUIT, 2 IN., RIGID, IN TRENCH	1,384.00	0.00	1,384.00	LF	1,155.00	\$20.00	\$23,100.00
		0050	1650	9107202	CONDUIT, 4 IN., RIGID, PUSHED	284.00	0.00	284.00	LF	284.00	\$51.00	\$14,484.00
		0050	1660	9108202	CABLE, 2 AWG, 1 CONDUCTOR, POWER	210.00	0.00	210.00	LF	0.00	\$5.30	\$0.00
		0050	1670	9108353	FIBER OPTIC CABLE, 12-STRAND, SINGLE MODE	1,880.00	0.00	1,880.00	LF	0.00	\$8.40	\$0.00
		0050	1680	9108811	PULL BOX, PREFORMED CLASS 2	1.00	0.00	1.00	EA	1.00	\$3,500.00	\$3,500.00
		0050	1690	9108816	PULL BOX, PREFORMED CLASS 5	8.00	0.00	8.00	EA	0.00	\$4,000.00	\$0.00
		0050	1700	9109901	MISC.FIBER OPTIC SPLICING, TESTING AND DOCUMENTATION	1.00	0.00	1.00	LS	0.00	\$13,100.00	\$0.00
		0050	1710	9109901	MISC.RELOCATE SCOUT CAMERA POLE	1.00	0.00	1.00	LS	1.00	\$27,900.00	\$27,900.00
		0050	1720	9109901	MISC.SALVAGING EXISTING ITS EQUIPMENT	1.00	0.00	1.00	LS	0.00	\$760.00	\$0.00
		0050	1730	9109902	MISC.FIBER MEDIA CONVERTER	2.00	0.00	2.00	EA	0.00	\$610.00	\$0.00
		0050	1740	9109902	MISC.SCOUT FIBER SPLICE VAULT	1.00	0.00	1.00	EA	1.00	\$7,200.00	\$7,200.00
		0070	1750	2061000	CLASS 1 EXCAVATION	123.00	22.00	145.00	CUYD	145.00	\$88.00	\$12,760.00
		0070	1760	2061003	CLASS 1 EXCAVATION IN ROCK	22.00	-22.00	0.00	CUYD	0.00	\$520.00	\$0.00
		0070	1770	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	0.00	\$108,800.00	\$0.00
		0070	1780	5031010A	BRIDGE APPROACH SLAB (MAJOR)	128.00	0.00	128.00	SQYD	128.00	\$340.00	\$43,520.00
		0070	1790	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	325.00	25.00	350.00	LF	350.00	\$120.00	\$42,000.00
Revision 3/23/20	000											Page 9 of 3

Page 9 of 34 Revision 3/23/2023



#### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Project Category Line | Item | Description | Bid | Net | Total | Unit | Total | Unit Price | Total Value POSTED

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230519-C04	J4P3443	0070	1800	7026000	PRE-BORE FOR PILING	215.00	0.00	215.00	LF	215.00	\$34.00	\$7,310.00
		0070	1810	7027000	PILE POINT REINFORCEMENT	10.00	0.00	10.00	EA	10.00	\$135.00	\$1,350.00
		0070	1820	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	89.80	0.00	89.80	CUYD	89.80	\$1,300.00	\$116,740.00
		0070	1830	7034219A	TYPE D BARRIER	487.00	0.00	487.00	LF	0.00	\$250.00	\$0.00
		0070	1840	7034221	SLAB ON CONCRETE NU-GIRDER	664.00	0.00	664.00	SQYD	664.00	\$460.00	\$305,440.00
		0070	1850	7034620	FORM LINERS	179.00	0.00	179.00	SQYD	179.00	\$79.00	\$14,141.00
		0070	1860	7039902	MISC.Cast Stone Sign	1.00	0.00	1.00	EA	0.00	\$8,900.00	\$0.00
		0070	1870	7056022	NU 43, PRESTRESSED CONCRETE NU-GIRDER	621.00	0.00	621.00	LF	621.00	\$510.00	\$316,710.00
		0070	1880	7101000	REINFORCING STEEL (EPOXY COATED)	10,970.00	0.00	10,970.00	LB	10,970.00	\$2.10	\$23,037.00
		0070	1890	7123610	SLAB DRAIN	2.00	0.00	2.00	EA	2.00	\$890.00	\$1,780.00
		0070	1900	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,900.00	\$3,800.00
		0070	1910	7161000	PLAIN NEOPRENE BEARING PAD	3.00	0.00	3.00	EA	3.00	\$370.00	\$1,110.00
		0070	1920	7161002	LAMINATED NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	6.00	\$420.00	\$2,520.00
		0070	1930	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	3.00	0.00	3.00	EA	3.00	\$630.00	\$1,890.00
		0071	1940	2061000	CLASS 1 EXCAVATION	158.00	33.00	191.00	CUYD	191.00	\$88.00	\$16,808.00
		0071	1950	2061003	CLASS 1 EXCAVATION IN ROCK	33.00	-33.00	0.00	CUYD	0.00	\$440.00	\$0.00
		0071	1960	5031010A	BRIDGE APPROACH SLAB (MAJOR)	168.00	0.00	168.00	SQYD	168.00	\$320.00	\$53,760.00
		0071	1970	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	402.00	74.00	476.00	LF	476.00	\$120.00	\$57,120.00
		0071	1980	7026000	PRE-BORE FOR PILING	312.00	0.00	312.00	LF	312.00	\$27.00	\$8,424.00
		0071	1990	7027000	PILE POINT REINFORCEMENT	12.00	0.00	12.00	EA	12.00	\$135.00	\$1,620.00
		0071	2000	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	123.60	0.00	123.60	CUYD	123.60	\$1,000.00	\$123,600.00
		0071	2010	7034219A	TYPE D BARRIER	479.00	0.00	479.00	LF	479.00	\$250.00	\$119,750.00
		0071	2020	7034221	SLAB ON CONCRETE NU-GIRDER	838.00	0.00	838.00	SQYD	838.00	\$450.00	\$377,100.00
		0071	2030	7034620	FORM LINERS	179.00	0.00	179.00	SQYD	179.00	\$79.00	\$14,141.00
		0071	2040	7039902	MISC.Cast Stone Sign	1.00	0.00	1.00	EA	1.00	\$8,900.00	\$8,900.00
		0071	2050	7056022	NU 43, PRESTRESSED CONCRETE NU-GIRDER	828.00	0.00	828.00	LF	828.00	\$510.00	\$422,280.00
		0071	2060	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	1.00	\$27,500.00	\$27,500.00
		0071	2070	7101000	REINFORCING STEEL (EPOXY COATED)	15,520.00	0.00	15,520.00	LB	15,520.00	\$2.10	\$32,592.00
		0071	2080	7123610	SLAB DRAIN	2.00	0.00	2.00	EA	2.00	\$890.00	\$1,780.00
		0071	2090	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,900.00	\$3,800.00
		0071	2100	7161000	PLAIN NEOPRENE BEARING PAD	4.00	0.00	4.00	EA	4.00	\$370.00	\$1,480.00
		0071	2110	7161002	LAMINATED NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$420.00	\$3,360.00
		0071	2120	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	4.00	0.00	4.00	EA	4.00	\$630.00	\$2,520.00
		0001	5001	7310072	PRECAST CONCRETE MANHOLE - 72 IN.	0.00	26.00	26.00	FT	26.00	\$500.77	\$13,020.02
		0001	5002	8061020	TEMPORARY PIPE	0.00	60.00	60.00	LF	60.00	\$120.00	\$7,200.00
		0001	5003	7269902	MISC.RIGID PIPE CULVERT DESIGN COSTS	0.00	1.00	1.00	EA	1.00	\$8,000.00	\$8,000.00
		0001	5004	1046002	VALUE ENGINEERING	0.00	73,085.99	73,085.99	EA	73,085.99	\$1.00	\$73,085.99
		0001	5005	6122020	REPLACEMENT SAND BARREL	0.00	3.00	3.00	EA	3.00	\$1,575.00	\$4,725.00
		0001	5006	8061020	TEMPORARY PIPE	0.00	80.00	80.00	LF	80.00	\$42.78	\$3,422.40
		0001	5007	1046002	VALUE ENGINEERING	0.00	48,329.63	48,329.63	EA	48,329.63	\$1.00	\$48,329.63
	Project J		otal Value	Posted to D	ate as of Report Generated Date							\$7,754,414.27
230519-C04 Ove	rall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$7,754,414.27

Revision 3/23/2023 Page 10 of 34

16.00

32.00

32.00

17.00

17.00

16.00



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4P3443

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0100	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1/3/24	1/4/24	83.00	SQYD	NB MO-7	15+63.91	LT/RT	16+38.00	LT/RT	
0140	5021334	CONCRETE PAVEMENT (10 1/2 IN. NON-REINF,	1/3/24	1/4/24	82.70	SQYD	NB MO-7	15+63.91	LT/RT	16+38.00	LT/RT	
				1/4/24	92.30	SQYD	Ramp 3A	0+72.00	LT/RT	1+59.67	LT/RT	
0150	5041000	CONCRETE APPROACH PAVEMENT	1/3/24	1/4/24	58.60	SQYD	NB MO-7 (Bridge A9287)	15+43.91		15+63.91		
0220	6113010	FURNISHING TYPE 1 ROCK BLANKET	1/4/24	1/11/24	300.00	CUYD	Ramp 4A	0+0.00	LT	1+47.62	LT	
0230	6113030	PLACING TYPE 1 ROCK BLANKET	1/4/24	1/11/24	300.00	CUYD	Ramp 4A	0+00	LT	1+47.62	LT	
0650	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1/4/24	1/11/24	450.00	SQYD	Ramp 4A	0+00	LT	1+47.62	LT	
0840	8061004	SEDIMENT TRAP ROCK	1/4/24	1/11/24	6.30	CUYD	Ramp 2A	1+20	LT			
0850	8061005	ROCK DITCH CHECK	1/4/24	1/11/24	15.00	LF	Ramp 4	4+75	RT			

0850	8061005	ROCK DITCH CHE	ECK	1/4/24 1/11/24	15.00 LF	Ramp 4			4+	75 RT			
he info	rmation be		e details for Construction S	igns (if applicabl	e).								
Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Inf	ormation	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J4P3443	0320	July 25, 2023	218	EO5-1 36x48 1	2.00 GORE EXIT		157.255		1.00	12.00			12.0
				R2-1 36x48 12 XX	.00 SPEED LIMIT		156.91	NB I-49	2.00	12.00			24.0
				GO20-5aP 36x24 (PLAQUE)	6.00 WORK ZONE		156.91	NB I-49	2.00	6.00			12.0
				WO20-6a 48x48 RIGHT/CENTER/LE	16.00 EFT LANE CLOSED		156.71	NB I-49	1.00	16.00			16.0
				CONST-5 96x48 PRESENCE			155.42	NB I-49	1.00	32.00			32.0
				WO20-5 48x48 RIGHT/CENTER/LE AHEAD	16.00 EFT LANE CLOSED		156.41	NB I-49	2.00	16.00			32.0
				WO20-1 48x48 ROAD/BRIDGE/RAI	16.00 MP WORK AHEAD		155.887	NB I-49	2.00	16.00			32.0
				CONST-8 48x36 ZONE NO PHONE	12.00 WORK ZONE		155.71	NB I-49	2.00	12.00			24.0
				CONST-7 72x36 WORK ZONE			155.611	NB I-49	1.00	18.00			18.
				WO4-1aL 48x48 (ARROW SYMBOL)			156.71	NB I-49	1.00	16.00			16.
		July 26, 2023	470	WO20-1 48x48	16.00		146.183	MO-7 N	2.00	16.00			32.
				ROAD/BRIDGE/RAI	12.00 WORK		145.847	MO-7 N	2.00	12.00			24.
				ZONE NO PHONE 2 CONST-7 72x36			145.745	MO-7 N	1.00	18.00			18.0
				WORK ZONE  CONST-5 96x48	32.00 POINT OF		145.647	MO-7 N	1.00	32.00			32.
				PRESENCE WO21-5 48x48	16.00 SHOULDER		1.463	EB 275th	1.00	16.00			16.
				WORK AHEAD CONST-5 96x48			1.409	EB 275th	1.00	32.00			32.
				PRESENCE			1.158	EB 275th	1.00	16.00			16.
				WO20-1 48x48 ROAD/BRIDGE/RAI									
				CONST-8 48x36 ZONE NO PHONE			0.946	EB 275th	1.00	12.00			12.
				CONST-7 72x36 WORK ZONE			0.831	EB 275th	1.00	18.00			18.
				WO20-1 48x48 ROAD/BRIDGE/RAI	MP WORK AHEAD		0.0	NB Brookhart	1.00	16.00			16.
				WO21-5 48x48 WORK AHEAD	16.00 SHOULDER		146.491	MO-7 N	1.00	16.00			16.
				WO20-5 48x48 RIGHT/CENTER/LE AHEAD	16.00 EFT LANE CLOSED			SB I-49	2.00	16.00			32.
				WO20-1 48x48 ROAD/BRIDGE/RAI	16.00 MP WORK AHEAD			SB I-49	2.00	16.00			32.
				R2-1 36x48 12 XX	.00 SPEED LIMIT			SB I-49	2.00	12.00			24.
				GO20-5aP 36x24 (PLAQUE)	6.00 WORK ZONE			SB I-49	2.00	6.00			12.
				WO20-6a 48x48 RIGHT/CENTER/LE	16.00 EFT LANE CLOSED			SB I-49	1.00	16.00			16.
				WO4-1aR 48x48 (ARROW SYMBOL)	16.00 MERGE			SB I-49	1.00	16.00			16.
				WO20-1 48x48 ROAD/BRIDGE/RAI	16.00		25.302	SB I-49	2.00	16.00			32.
				CONST-8 48x36 ZONE NO PHONE	12.00 WORK		25.197	SB I-49	2.00	12.00			24.
				CONST-7 72x36			25.093	SB I-49	1.00	18.00			18.0
				WORK ZONE  CONST-5 96x48	32.00 POINT OF		24.846	SB I-49	1.00	32.00			32.
		August 8, 2023	16	PRESENCE WO20-1 48x48	16.00		0.109	MO-2 RAMP TO SB I-49	1.00	16.00			16.
			32	ROAD/BRIDGE/RAI Variable ??x?? 1	.00 SPECIAL SIGN		156.279	NB I-49	32.00	1.00	RUMBLE STRIPS AHEAD		32.
			157	BY QUANTITY OF S R11-2 48x30 10	SQUARE FEET		146.474	MO-7 N	1.00	10.00			10.
				CLOSED  Variable ??x?? 1				MO-7 N	17.00	1.00	DETOUR N 49 ARROW		17.
				BY QUANTITY OF	SQUARE FEET								17.0

Revision 3/23/2023 Page 11 of 34

146.184 MO-7 N

146.045 MO-7 N

145.981 MO-7 N

146.518 MO-7 N

146.563 MO-7 N

1.00

2.00

32.00

17.00

17.00

16.00

16.00

1.00

1.00

1.00

RUMBLE STRIPS AHEAD

DETOUR N 49 ARROW 50B

DETOUR N 49 ARROW 50C

WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED

WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET

29.70

29.70

29.70

10.00

26.00

29.70

29.70

29.70

6.93

16.00

29.70

29.70

16.00

16.00

29.70

29.70

29.70

29.70



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

Line	DWR Date	Total Quantity Posted For DWR	Sign Information	Station	Log	Location	Number of	SF Each	Special Sign	SF Each Special	Total SF to
	August 8, 2023	Date 157	WO4-1aL 48x48 16.00 MERGE			MO-7 N	1.00	16.00		Sign	Post 16.00
	August 14, 2023	16	WO5-1 48x48 16.00	1+00		Ramp 1 to NB I-49	1.00	16.00			16.00
	September 14, 2023	148	WO20-1 48x48 16.00		1.894	SB Orchard Rd	1.00	16.00			16.0
			WO1-4L 48x48 16.00 REVERSE CURVE (SYMBOL LEFT ARROW)		146.326	MO-7 N	1.00	16.00			16.0
			WO4-1R 48x48 16.00 MERGE (SYMBOL FROM RIGHT)		146.477	MO-7 N	1.00	16.00			16.0
			WO3-3 48x48 16.00 SIGNAL AHEAD (SYMBOL)		146.521	MO-7 N	1.00	16.00			16.0
			WO5-1 48x48 16.00 ROAD/BRIDGE/RAMP NARROWS		26.142	SB I-49	1.00	16.00			16.0
			WO13-1 30x30 6.25 ADVISORY SPEED (PLAQUE)		26.142	SB I-49	1.00	6.25			6.2
			WO1-4R 48x48 16.00 REVERSE CURVE (SYMBOL RIGHT ARROW)		40.058	MO-7 S	1.00	16.00			16.0
			WO1-4L 48x48 16.00 REVERSE CURVE (SYMBOL LEFT ARROW)		40.212	MO-7 S	1.00	16.00			16.0
			R10-6 24x36 6.00 STOP HERE ON RED (45 DEGREE ARROW			MO-7 N, MO-7 S, Ramp 2	5.00	6.00			30.0
	September 21, 2023	58	WO1-4L 48x48 16.00 REVERSE CURVE (SYMBOL LEFT ARROW)			NB I-49	1.00	16.00			16.0
			R11-2 48x30 10.00 ROAD CLOSED	24+00		MO-7 N	1.00	10.00			10.0
			Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET				16.00	1.00	Added Lane		16.0
			WO1-4R 48x48 16.00 REVERSE CURVE (SYMBOL RIGHT ARROW)			NB I-49	1.00	16.00			16.0
	October 23, 2023	262	Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		2.439	EB 299th St	27.70	1.00	50Q, Detour 49		27.7
			Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		2.472	SB Outer Rd	29.70	1.00	50A, Detour N 49		29.7
			WO20-2 48x48 16.00 DETOUR AHEAD		1.556	SB Brookhart Dr	1.00	16.00			16.0
			BY QUANTITY OF SQUARE FEET						50Q, Detour 49		27.7
			AHEAD								16.0
			BY QUANTITY OF SQUARE FEET								27.7
			BY QUANTITY OF SQUARE FEET								29.7
			BY QUANTITY OF SQUARE FEET								29.7
			BY QUANTITY OF SQUARE FEET								29.7
	0.4.100.0000	000	BY QUANTITY OF SQUARE FEET								27.7
	October 26, 2023	208	BY QUANTITY OF SQUARE FEET								29.7
			BY QUANTITY OF SQUARE FEET								29.7
			BY QUANTITY OF SQUARE FEET								29.7
			BY QUANTITY OF SQUARE FEET								
			BY QUANTITY OF SQUARE FEET								29.7
			BY QUANTITY OF SQUARE FEET		1.568	SB Outer Rd	29.70	1.00	50E, Detour N 49		29.7
		Line   DWR Date	DWR Date   Total Quantity Posted For DWR Date	Number   Date   WOA-1st 48x8 18.00 MERGE (ARROW SYMBOL)	Direct	Discontinument	District	Number   March   Mar	Number   Court   Cou	DUNC DUNC DUNC DE	Divide   D

4.327

1.672

2.536

0.03

1.489

1.489

146.161 MO-7 N

156.808 NB I-49

156.864 NB I-49

156.961 NB I-49

157.535 NB I-49

158.153 NB I-49

158.183 NB I-49

NB Outer Rd

SB Outer Rd

Commercial St

Commercial St

EB 275th St

EB 275th St

146.53 MO-7 N ramp to NB 49

SB Brookhart Dr

NB I-49 ramp to MO-7

NB I-49 ramp to Commercial 29.70

29.70

29.70

29.70

1.00

29.70

1.00

1.00

29.70

29.70

1.00

16.00

29.70

29.70

29.70

29.70

1.00

1.00

1.00

10.00

1.00

1.00

6.93

16.00

1.00

1.00

16.00

1.00

1.00

1.00

1.00

1.00

50C, Detour N 49

50E, Detour N 49

50A, Detour N 49

M3-3 South (on 13 existing detour signs)

Yield Sign (changed to 2 Stop signs)

Ramp Closed

50P, Detour S 7

50J, Detour S 49

50P, Detour S 7

50A, Detour S 49

50K, Detour S 7

Ramp Closed Ahead

50K, Detour S 7

50A, Detour S 49

50K, Detour S 7

50F. Detour S 7

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET R11-2 48x30 10.00 ROAD CLOSED

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET

R1-2 48 TRI 6.93 YIELD

R1-1 48x48 13.25 STOP

WO20-2 48x48 16.00 DETOUR AHEAD

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET

WO20-2 48x48 16.00 DETOUR AHEAD

November 8, 2023 59

November 17, 2023

158.623 NB I-49 Revision 3/23/2023 Page 12 of 34



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

0.086 NB I-49 ramp to Commercial 29.70 St

50J, Detour S 49

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET

THE HITE	IIIIation be	IOW LINE IIIIC LIC	details for construction of	gris (ii upplicubic).								
Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J4P3443	0320	November 17, 2023	504	Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		158.623	NB I-49	29.70	1.00	50K, Detour S 7		29.70
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		26.208	SB I-49	29.70	1.00	50F, Detour S 49 (shown in plans, didn't need)		29.70
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		26.208	SB I-49	29.70	1.00	50K, Detour S 7		29.70

Revision 3/23/2023 Page 13 of 34



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4P3443	0040	EMBANKMENT IN PLACE	Material		2	Aug 2, 2023	SYSTEM	\$77,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					2	Aug 2, 2023	SYSTEM	(\$77,140.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0040 -	Total						\$0.00		
	0100	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		7	Oct 16, 2023	SYSTEM	\$1,918.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
		more			7	Oct 16, 2023	SYSTEM	(\$1,918.00)		
					8	Nov 2, 2023	SYSTEM	\$3,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					8	Nov 2, 2023	SYSTEM	(\$3,220.00)		
					9	Nov 16, 2023	SYSTEM	\$3,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					9	Nov 16, 2023	SYSTEM	(\$3,220.00)		
				- Total				\$0.00		
			Material - To					\$0.00		
	0100 -	Total						\$0.00		
	0110	MISC. AGGREGATE FOR BASE	Material		5	Sep 18, 2023	SYSTEM	\$5,808.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					5	Sep 18, 2023	SYSTEM	(\$5,808.60)		
					6	Oct 2, 2023	SYSTEM	\$5,808.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					6	Oct 2, 2023	SYSTEM	(\$5,808.60)		
					7	Oct 16, 2023	SYSTEM	\$17,988.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					7	Oct 16, 2023	SYSTEM	(\$17,988.60)		
					8	Nov 2, 2023	SYSTEM	\$17,988.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					8	Nov 2, 2023	SYSTEM	(\$17,988.60)	,	
						9	Nov 16, 2023	SYSTEM	\$30,055.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Nov 16, 2023	SYSTEM	(\$30,055.20)		
				- Total				\$0.00		
			Material - To					\$0.00		
	0110 -	Total						\$0.00		
	0140	CONCRETE PAVEMENT (10 1/2 IN. NON-REINF,	Material		8	Nov 2, 2023	SYSTEM	\$31,386.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					8	Nov 2, 2023	SYSTEM	(\$31,386.70)		
					9	Nov 16, 2023	SYSTEM	\$31,386.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					9	Nov 16, 2023	SYSTEM	(\$31,386.70)		
					10	Dec 4, 2023	SYSTEM	\$31,386.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment	
		CONCRETE PAVEMENT (10 1/2		tal	9	2023 Nov 2, 2023 Nov 16, 2023 Nov 16, 2023 Dec 4,	SYSTEM SYSTEM SYSTEM	\$0.00 \$31,386.70 (\$31,386.70) \$31,386.70	Estimate Item Adjustment (0004) due to user raybol1 overridding Paymen Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Paymen Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment	



DAP3443   O140	l Material Payment overridding Payment
10	overridding Payment
2023   Estimate Item Adjustment (0001) due to user raybol 1 of Estimate Exception 2 on the current Payment Estimate	overridding Payment
2023	
Material - Total \$0.00  0140 - Total \$0.00  0150 CONCRETE APPROACH Material 8 Nov 2, 2023 SYSTEM \$14,652.00 This adjustment offsets the original system-generated Estimate Item Adjustment (0005) due to user raybol 1 or 100 or 1	
0140 - Total     \$0.00       0150     CONCRETE APPROACH     Material     8     Nov 2, 2023     SYSTEM \$14,652.00     This adjustment offsets the original system-generated Estimate Item Adjustment (0005) due to user raybold of E	
0150 CONCRETE Material 8 Nov 2, SYSTEM \$14,652.00 This adjustment offsets the original system-generated Estimate Item Adjustment (0005) due to user raybol 1 or 100 control of the control	
APPROACH 2023 Estimate Item Adjustment (0005) due to user raybol1 of	
	overridding Payment
8 Nov 2, 2023 (\$14,652.00)	
9 Nov 16, 2023 \$28,332.00 This adjustment offsets the original system-generated Estimate Item Adjustment (0005) due to user raybol1 of Estimate Exception 12 on the current Payment Estimate.	overridding Payment
9 Nov 16, 2023 (\$28,332.00)	
- Total \$0.00	
Material - Total \$0.00	
0150 - Total \$0.00	
0160 PIPE COLLAR, TYPE A TYPE	2 overridding Payment
12 Jan 2, 2024 SYSTEM (\$1,600.00)	
13 Jan 17, 2024 \$1,600.00 This adjustment offsets the original system-generated Estimate Item Adjustment (0002) due to user raybol1 of Estimate Exception 6 on the current Payment Estimate	overridding Payment
13 Jan 17, 2024 (\$1,600.00)	
- Total \$0.00	
Material - Total \$0.00	
0160 - Total \$0.00	
0210 ROCK LINING Material 12 Jan 2, 2024 \$13,872.00 This adjustment offsets the original system-generated Estimate Item Adjustment (0003) due to user moses)2 Estimate Exception 7 on the current Payment Estimate	
2024 Estimate Item Adjustment (0003) due to user mosesj2	
Estimate Item Adjustment (0003) due to user mosesj2 Estimate Exception 7 on the current Payment Estimate  12 Jan 2, SYSTEM (\$13,872.00)	te.  I Material Payment overridding Payment
Estimate Item Adjustment (0003) due to user mosesj2 Estimate Exception 7 on the current Payment Estimate  12 Jan 2, 2024  13 Jan 17, 2024  SYSTEM \$13,872.00  This adjustment offsets the original system-generated Estimate Item Adjustment (0003) due to user raybol1 or	te.  I Material Payment overridding Payment
2024   Estimate Item Adjustment (0003) due to user moses)2	te.  I Material Payment overridding Payment
2024   Estimate Item Adjustment (0003) due to user moses)2	te.  I Material Payment overridding Payment
2024   Estimate Item Adjustment (0003) due to user moses)2	te.  I Material Payment overridding Payment
2024   Estimate Item Adjustment (0003) due to user moses)2	I Material Payment overridding Payment te.
2024   Estimate Item Adjustment (0003) due to user moses;2	I Material Payment overridding Payment te.
2024   Estimate Item Adjustment (0003) due to user moses;2	I Material Payment overridding Payment te.
2024   Estimate Item Adjustment (0003) due to user moses)2	I Material Payment overridding Payment te.
2024   Estimate Item Adjustment (0003) due to user moses)2	Ite.  I Material Payment overridding Payment ite.  I installed quantity on all 9.00000 - 19.00000, 'is
2024   Estimate Item Adjustment (0003) due to user moses)2	I Material Payment overridding Payment te.  r installed quantity on all 9.00000 - 19.00000, 'is



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3443	0390	CMS WITH COMMUNICATION	Material	- Total				\$0.00	
		INTERFACE, CONT F	Material - To	tal				\$0.00	
	0390 -							\$0.00	
	0420	TEMPORARY TRAFFIC BARRIER, CONT.	Material		2	Aug 2, 2023	SYSTEM	\$28,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		FURN/RE			2	Aug 2, 2023	SYSTEM	(\$28,800.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	3	Aug 16, 2023	SYSTEM	(\$3,584.00)	
					5	Sep 18, 2023	SYSTEM	(\$10,272.00)	
					9	Nov 16, 2023	SYSTEM	\$13,856.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',16.00000 - 16.00000, 'is applied (if non-zero).
				Overrun - To	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0420 -	Total						\$0.00	
	0460	PAVEMENT EDGE TREATMENT	Material		7	Oct 16, 2023	SYSTEM	\$5,576.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Oct 16, 2023	SYSTEM	(\$5,576.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	7	Oct 16, 2023	SYSTEM	(\$204.00)	
					8	Nov 2, 2023	SYSTEM	(\$3,060.00)	
					9	Nov 16, 2023	SYSTEM	\$3,264.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',6.80000 - 6.80000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0460 -	Total						\$0.00	
	0500	PREF THERMO PVMT MARK, LT/RT ARROW	Material		10	Dec 4, 2023	SYSTEM	\$2,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					10	Dec 4, 2023	SYSTEM	(\$2,720.00)	
					11	Dec 18, 2023	SYSTEM	\$2,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					11	Dec 18, 2023	SYSTEM	(\$2,720.00)	
					12	Jan 2, 2024	SYSTEM	\$2,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mosesj2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					12	Jan 2, 2024	SYSTEM	(\$2,720.00)	
					13	Jan 17, 2024	SYSTEM	\$2,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					13	Jan 17, 2024	SYSTEM	(\$2,720.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0500 -	Total						\$0.00	
	0550	TEMPORARY REMOVABLE MARKING TAPE,	Material		5	Sep 18, 2023	SYSTEM	\$624.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user raybol1 overridding Payment Estimate Exception 10 on the current Payment Estimate.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	2.110	2000.ipuo.i	Туре	Adjustment Type	Number	Date	Ву	,	. Constitution of the cons
J4P3443	0550	24 IN.	Material		5	Sep 18, 2023	SYSTEM	(\$624.00)	
					6	Oct 2, 2023	SYSTEM	\$936.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Oct 2, 2023	SYSTEM	(\$936.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0550 -	Total						\$0.00	
	0560	TEMPORARY NON-REMOVABLE TAPE LT/RT	Material		5	Sep 18, 2023	SYSTEM	\$160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user raybol1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
		ARROW			5	Sep 18, 2023	SYSTEM	(\$160.00)	
					6	Oct 2, 2023	SYSTEM	\$160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Oct 2, 2023	SYSTEM	(\$160.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0560 -	Total						\$0.00	
	0570	TEMPORARY NON-REMOVABLE MARKING TAPE	Material		5	Sep 18, 2023	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					5	Sep 18, 2023	SYSTEM	(\$924.00)	
					6	Oct 2, 2023	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user raybol1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Oct 2, 2023	SYSTEM	(\$924.00)	
				- Total				\$0.00	
			Material - Tot	aterial - Total				\$0.00	
			Overrun	Overrun Overrun		Sep 18, 2023	SYSTEM	(\$528.00)	
					9	Nov 16, 2023	SYSTEM	\$528.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',132.00000 - 132.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0570 -	Total						\$0.00	
	0580	TEMPORARY N/R MARK TAPE COMBO ST LT/RT	Material		5	Sep 18, 2023	SYSTEM	\$1,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					5	Sep 18, 2023	SYSTEM	(\$1,040.00)	
					6	Oct 2, 2023	SYSTEM	\$1,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					6	Oct 2, 2023	SYSTEM	(\$1,040.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
			Overrun	Overrun	5	Sep 18, 2023	SYSTEM	(\$260.00)	
					9	Nov 16, 2023	SYSTEM	\$260.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',260.00000 - 260.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0580 -	Total						\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3443	0650	PERMANENT EROSION CONTROL	Material		2	Aug 2, 2023	SYSTEM	\$266.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		GEOTEXTILE			2	Aug 2, 2023	SYSTEM	(\$266.00)	
					3	Aug 16, 2023	SYSTEM	\$4,335.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Aug 16, 2023	SYSTEM	(\$4,335.80)	
					4	Sep 5, 2023	SYSTEM	\$4,335.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Sep 5, 2023	SYSTEM	(\$4,335.80)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0650 -					0.10	OVOTELL	\$0.00	
	0670	CLASS B-1 CONCRETE (CULVERTS)	Material		6	Oct 2, 2023	SYSTEM	\$78,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user raybol1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					6	Oct 2, 2023	SYSTEM	(\$78,660.00)	
					7	Oct 16, 2023	SYSTEM	\$78,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					7	Oct 16, 2023	SYSTEM	(\$78,660.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0670 -	Total						\$0.00	
	0680	REINFORCING STEEL (CULVERTS)	Material		4	Sep 5, 2023	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					4	Sep 5, 2023	SYSTEM	(\$13,500.00)	
					5	Sep 18, 2023	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user raybol1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					5	Sep 18, 2023	SYSTEM	(\$13,500.00)	
					6	Oct 2, 2023	SYSTEM	\$17,199.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user raybol1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					6	Oct 2, 2023	SYSTEM	(\$17,199.00)	
					7	Oct 16, 2023	SYSTEM	\$17,199.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user raybol1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					7	Oct 16, 2023	SYSTEM	(\$17,199.00)	
					8	Nov 2, 2023	SYSTEM	\$17,199.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$17,199.00)	
					9	Nov 16, 2023	SYSTEM	\$17,199.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					9	Nov 16, 2023	SYSTEM	(\$17,199.00)	
					10	Dec 4, 2023	SYSTEM	\$17,199.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					10	Dec 4, 2023	SYSTEM	(\$17,199.00)	
					11	Dec 18,	SYSTEM	\$22,491.00	This adjustment offsets the original system-generated Material Payment



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
P3443	0680	REINFORCING STEEL	Material			2023			Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
		(CULVERTS)			11	Dec 18, 2023	SYSTEM	(\$22,491.00)	
					12	Jan 2, 2024	SYSTEM	\$22,491.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mosesj2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					12	Jan 2, 2024	SYSTEM	(\$22,491.00)	
					13	Jan 17, 2024	SYSTEM	\$22,491.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					13	Jan 17, 2024	SYSTEM	(\$22,491.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0680 -	Total						\$0.00	
	0760	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material		11	Dec 18, 2023	SYSTEM	\$6,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					11	Dec 18, 2023	SYSTEM	(\$6,800.00)	
					12	Jan 2, 2024	SYSTEM	\$6,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mosesj2 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					12	Jan 2, 2024	SYSTEM	(\$6,800.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0760 -	Total						\$0.00	
	0770	18 IN. GROUP B FLARED END SEC	Material		12	Jan 2, 2024	SYSTEM	\$1,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mosesj2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					12	Jan 2, 2024	SYSTEM	(\$1,900.00)	
					13	Jan 17, 2024	SYSTEM	\$1,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					13	Jan 17, 2024	SYSTEM	(\$1,900.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0770 -	Total						\$0.00	
	0820	MULCHING	Material		7	Oct 16, 2023	SYSTEM	\$235.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					7	Oct 16, 2023	SYSTEM	(\$235.00)	
				- Total				\$0.00	
			Material - Tot					\$0.00	
	0000	Total	material - 10	.cri					
	0820 -							\$0.00	
	0830	SEEDING - COOL SEASON GRASSES	Material		5	Sep 18, 2023	SYSTEM	\$7,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					5	Sep 18, 2023	SYSTEM	(\$7,290.00)	
					6	Oct 2, 2023	SYSTEM	\$7,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					6	Oct 2, 2023	SYSTEM	(\$7,290.00)	
					7	Oct 16, 2023	SYSTEM	\$8,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					7	Oct 16,	SYSTEM	(\$8,640.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
4P3443	0830	SEEDING - COOL SEASON GRASSES	Material		8	2023 Nov 2, 2023	SYSTEM	\$10,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment
					8	Nov 2,	SYSTEM	(\$10,260.00)	Estimate Exception 39 on the current Payment Estimate.
				- Total		2023		\$0.00	
			Material - Tot					\$0.00	
	0830 -	Total						\$0.00	
	0840	SEDIMENT TRAP ROCK	Material		6	Oct 2, 2023	SYSTEM	\$140.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					6	Oct 2, 2023	SYSTEM	(\$140.40)	
					7	Oct 16, 2023	SYSTEM	\$140.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					7	Oct 16, 2023	SYSTEM	(\$140.40)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0840 -	Total						\$0.00	
	0850	ROCK DITCH CHECK	Material		1	Jul 17, 2023	SYSTEM	\$1,653.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Jul 17, 2023	SYSTEM	(\$1,653.00)	
					2	Aug 2, 2023	SYSTEM	\$1,653.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Aug 2, 2023	SYSTEM	(\$1,653.00)	
					3	Aug 16, 2023	SYSTEM	\$3,287.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Aug 16, 2023	SYSTEM	(\$3,287.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0850 -	Total						\$0.00	
	0890	TYPE 1 TURF REINFORCEMENT MAT	Material		5	Sep 18, 2023	SYSTEM	\$2,731.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user raybol1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					5	Sep 18, 2023	SYSTEM	(\$2,731.10)	
					6	Oct 2, 2023	SYSTEM	\$2,731.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					6	Oct 2, 2023	SYSTEM	(\$2,731.10)	
					7	Oct 16, 2023	SYSTEM	\$2,731.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					7	Oct 16, 2023	SYSTEM	(\$2,731.10)	
					8	Nov 2, 2023	SYSTEM	\$2,731.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$2,731.10)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0890 -	Total						\$0.00	
	0900	TYPE 2D EROSION	Overrun	Overrun	10	Dec 4, 2023	SYSTEM	(\$1,538.40)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3443	0900	CONTROL BLANKET	Overrun	Overrun - T	otal			(\$1,538.40)	
		BLAINNE I	Overrun - To	tal				(\$1,538.40)	
	0900 -	Total						(\$1,538.40)	
	0940	MISC. AGGREGATE FOR BASE	Material		4	Sep 5, 2023	SYSTEM	\$52,567.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Sep 5, 2023	SYSTEM	(\$52,567.20)	
					5	Sep 18, 2023	SYSTEM	\$52,567.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Sep 18, 2023	SYSTEM	(\$52,567.20)	
					6	Oct 2, 2023	SYSTEM	\$113,109.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Oct 2, 2023	SYSTEM	(\$113,109.60)	
					7	Oct 16, 2023	SYSTEM	\$119,905.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Oct 16, 2023	SYSTEM	(\$119,905.20)	
					8	Nov 2, 2023	SYSTEM	\$156,393.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$156,393.60)	
					9	Nov 16, 2023	SYSTEM	\$178,377.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Nov 16, 2023	SYSTEM	(\$178,377.60)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0940 -	Total						\$0.00	
	0950	CONCRETE PAVEMENT (10 1/2 IN. NON-REINF,	Material		4	Sep 5, 2023	SYSTEM	\$340,040.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Sep 5, 2023	SYSTEM	(\$340,040.40)	
					5	Sep 18, 2023	SYSTEM	\$429,298.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Sep 18, 2023	SYSTEM	(\$429,298.80)	
					6	Oct 2, 2023	SYSTEM	\$649,147.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Oct 2, 2023	SYSTEM	(\$649,147.10)	
					7	Oct 16, 2023	SYSTEM	\$870,798.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Oct 16, 2023	SYSTEM	(\$870,798.60)	
					8	Nov 2, 2023	SYSTEM	\$926,296.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$926,296.00)	
					9	Nov 16, 2023	SYSTEM	\$1,362,307.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Nov 16, 2023	SYSTEM	(\$1,362,307.80)	
					10	Dec 4,	SYSTEM	\$1,362,307.80	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3443	0950	CONCRETE PAVEMENT (10 1/2	Material			2023			Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		IN. NON-REINF,			10	Dec 4, 2023	SYSTEM	(\$1,362,307.80)	
					11	Dec 18, 2023	SYSTEM	\$1,465,051.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11	Dec 18, 2023	SYSTEM	(\$1,465,051.00)	
					12	Jan 2, 2024	SYSTEM	\$1,492,167.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mosesj2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Jan 2, 2024	SYSTEM	(\$1,492,167.60)	
					13	Jan 17, 2024	SYSTEM	\$1,492,167.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Jan 17, 2024	SYSTEM	(\$1,492,167.60)	
				- Total				\$0.00	
			Material - To					\$0.00	
	0950 -	Total	material - 10						
								\$0.00	
	0980	TYPE A2 SHOULDER	Material		8	Nov 2, 2023	SYSTEM	\$29,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user raybol1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$29,700.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0980 -	Total						\$0.00	
	0990	MGS GUARDRAIL, 8 FT. POSTS, 6 FT. - 3 IN	Construction Stockpile STMI		8	Nov 2, 2023	SYSTEM	\$40,057.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		0 114	OTIVII	- Total				\$40,057.00	
			Construction	Stockpile S	MI - Tota			\$40,057.00	
	0990 -	Total						\$40,057.00	
	1120	CONDUIT, 2 IN. RIGID, IN TRENCH	Material		8	Nov 2, 2023	SYSTEM	\$1,771.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$1,771.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1120 -	Total						\$0.00	
	1130	CONDUIT, 4 IN. RIGID, PUSHED	Material		8	Nov 2, 2023	SYSTEM	\$1,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user raybol1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$1,680.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1130	Total						\$0.00	
	1360	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		8	Nov 2, 2023	SYSTEM	\$1,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user raybol1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$1,530.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1360	· Total						\$0.00	
			O. ( a mm : : :	0	10	lan C	CVCTCA		This adjustment offsets the existing level of the existing level o
	1390	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	Overrun	Overrun	12	Jan 2, 2024	SYSTEM	\$924.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user mosesj2 overridding Payment Estimate Exception 19 on the current Payment Estimate.



ect	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
443	1390	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	Overrun	Overrun	12	Jan 2, 2024	SYSTEM	(\$924.00)	
		TRACEIT WINE			13	Jan 17, 2024	SYSTEM	(\$924.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				Overrun - T	otal			(\$924.00)	
			Overrun - To	tal				(\$924.00)	
	1390 -	Total						(\$924.00)	
	1470	TEMPORARY TRAFFIC SIGNALS AND LIGHTING	Material		3	Aug 16, 2023	SYSTEM	\$236,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					3	Aug 16, 2023	SYSTEM	(\$236,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1470 -	Total						\$0.00	
ľ	1500	BREAKAWAY ASSEMBLY	Construction Stockpile		9	Nov 16, 2023	SYSTEM	\$2,106.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		(PERFORATED SQUARE STEEL	STMI	- Total				\$2,106.00	
		TUBE)	Construction	Stockpile S	ΓΜΙ - Total			\$2,106.00	
	1500 -	Total						\$2,106.00	
ľ	1510	2 IN. PSST POST - 12 GA.	Construction Stockpile		9	Nov 16, 2023	SYSTEM	\$6,034.08	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$6,034.08	
			Construction	Stockpile S	ΓΜΙ - Total			\$6,034.08	
	1510 -	Total						\$6,034.08	
	1520	DRIVEN POST ANCHOR FOR 2	Construction Stockpile		9	Nov 16, 2023	SYSTEM	\$1,195.74	Payment Estimate Item Adjustment generated Stockpile Transaction
		IN. PSST - 12 GA.	STMI	- Total				\$1,195.74	
			Construction	Stockpile S	ΓΜΙ - Total			\$1,195.74	
	1520 -	Total						\$1,195.74	
ľ	1530	2.25 IN. PSST POST INSERT (6	Construction Stockpile		9	Nov 16, 2023	SYSTEM	\$245.28	Payment Estimate Item Adjustment generated Stockpile Transaction
		F1.) - 12 GA.	STMI	- Total				\$245.28	
			Construction	Stockpile S	ΓMI - Tota			\$245.28	
	1530 -	Total						\$245.28	
	1540	2.5 IN. PSST POST - 12 GA.	Construction Stockpile		9	Nov 16, 2023	SYSTEM	\$2,184.96	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$2,184.96	
			Construction	Stockpile S	ГМI - Total			\$2,184.96	
	1540 -	Total						\$2,184.96	
	1550	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Stockpile		9	Nov 16, 2023	SYSTEM	\$1,022.40	Payment Estimate Item Adjustment generated Stockpile Transaction
		1 001 - 1 0A.	511111	- Total				\$1,022.40	
			Construction	Stockpile S	ΓΜΙ - Total			\$1,022.40	
	1550 -	Total						\$1,022.40	
	1640	CONDUIT, 2 IN., RIGID, IN TRENCH	Material		8	Nov 2, 2023	SYSTEM	\$21,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user raybol1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$21,080.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1640 -	Total						\$0.00	
	1680	PULL BOX, PREFORMED CLASS 2	Material		8	Nov 2, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user raybol1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$3,500.00)	. ,
				- Total				\$0.00	



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J4P3443	1680	PULL BOX, PREFORMED CLASS 2	Material - To	tal				\$0.00	
	1680 -	- Total						\$0.00	
	1710	MISC. ITS	Material		8	Nov 2, 2023	SYSTEM	\$27,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user raybol1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$27,900.00)	
					9	Nov 16, 2023	SYSTEM	\$27,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					9	Nov 16, 2023	SYSTEM	(\$27,900.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1710 -	- Total						\$0.00	
	1740	MISC. ITS	Material		8	Nov 2, 2023	SYSTEM	\$7,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user raybol1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$7,200.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1740 -	- Total						\$0.00	
	1750	CLASS 1 EXCAVATION	Overrun	Overrun	6	Oct 2, 2023	SYSTEM	(\$1,936.00)	
					9	Nov 16, 2023	SYSTEM	\$1,936.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',88.00000 - 88.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	1750 -	- Total						\$0.00	
	1780	BRIDGE APPROACH SLAB	Material		12	Jan 2,	SYSTEM	£42 E20 00	This adjustment offsets the original system-generated Material Payment
		(MAJOR ROAD)	material		12	2024	OTOTEM	\$43,520.00	Estimate Item Adjustment (0009) due to user mosesj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					12		SYSTEM	(\$43,520.00)	Estimate Item Adjustment (0009) due to user mosesj2 overridding Payment
						2024 Jan 2,			Estimate Item Adjustment (0009) due to user mosesj2 overridding Payment
					12	Jan 2, 2024 Jan 17,	SYSTEM	(\$43,520.00)	Estimate Item Adjustment (0009) due to user mosesj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment
				- Total	12	Jan 2, 2024 Jan 17, 2024 Jan 17,	SYSTEM	(\$43,520.00) \$43,520.00	Estimate Item Adjustment (0009) due to user mosesj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment
			Material - To		12	Jan 2, 2024 Jan 17, 2024 Jan 17,	SYSTEM	(\$43,520.00) \$43,520.00 (\$43,520.00)	Estimate Item Adjustment (0009) due to user mosesj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment
	1780 -				12	Jan 2, 2024 Jan 17, 2024 Jan 17,	SYSTEM	(\$43,520.00) \$43,520.00 (\$43,520.00)	Estimate Item Adjustment (0009) due to user mosesj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment
	1780 - 1790	- Total  GALVANIZED STRUCTURAL STEEL PILES (12			12	Jan 2, 2024 Jan 17, 2024 Jan 17,	SYSTEM	(\$43,520.00) \$43,520.00 (\$43,520.00) \$0.00	Estimate Item Adjustment (0009) due to user mosesj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment
		-Total  GALVANIZED STRUCTURAL	Material - To		12 13 13	2024 Jan 2, 2024 Jan 17, 2024 Jan 17, 2024	SYSTEM SYSTEM SYSTEM	(\$43,520.00) \$43,520.00 (\$43,520.00) \$0.00 \$0.00	Estimate Item Adjustment (0009) due to user mosesj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment
		- Total  GALVANIZED STRUCTURAL STEEL PILES (12	Material - To		12 13 13	2024  Jan 2, 2024  Jan 17, 2024  Jan 17, 2024  Sep 18, 2023  Sep 18,	SYSTEM SYSTEM SYSTEM	(\$43,520.00) \$43,520.00 (\$43,520.00) \$0.00 \$0.00 \$42,000.00	Estimate Item Adjustment (0009) due to user mosesj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment
		- Total  GALVANIZED STRUCTURAL STEEL PILES (12	Material - To		12 13 13 5	2024  Jan 2, 2024  Jan 17, 2024  Jan 17, 2024  Sep 18, 2023  Sep 18, 2023  Oct 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$43,520.00) \$43,520.00 (\$43,520.00) \$0.00 \$0.00 \$42,000.00	Estimate Item Adjustment (0009) due to user mosesj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user raybol1 overridding Payment Estimate Item Adjustment (0016) due to user raybol1 overridding Payment
		- Total  GALVANIZED STRUCTURAL STEEL PILES (12	Material - To		12 13 13 5 5 6	2024  Jan 2, 2024  Jan 17, 2024  Jan 17, 2024  Sep 18, 2023  Oct 2, 2023  Oct 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$43,520.00) \$43,520.00 (\$43,520.00) \$0.00 \$0.00 \$42,000.00 (\$42,000.00) \$42,000.00	Estimate Item Adjustment (0009) due to user mosesj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user raybol1 overridding Payment Estimate Item Adjustment (0016) due to user raybol1 overridding Payment
		- Total  GALVANIZED STRUCTURAL STEEL PILES (12	Material - To		12 13 13 5 5 6	2024  Jan 2, 2024  Jan 17, 2024  Jan 17, 2024  Sep 18, 2023  Oct 2, 2023  Oct 2, 2023  Oct 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$43,520.00) \$43,520.00 (\$43,520.00) \$0.00 \$0.00 \$42,000.00 (\$42,000.00)	Estimate Item Adjustment (0009) due to user mosesj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate.
		- Total  GALVANIZED STRUCTURAL STEEL PILES (12	Material - To		12 13 13 5 5 6 6 7	2024  Jan 2, 2024  Jan 17, 2024  Jan 17, 2024  Sep 18, 2023  Oct 2, 2023  Oct 2, 2023  Oct 16, 2023  Oct 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$43,520.00) \$43,520.00  (\$43,520.00) \$0.00 \$0.00 \$42,000.00  \$42,000.00  (\$42,000.00)  \$42,000.00	Estimate Item Adjustment (0009) due to user mosesj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4P3443	1790	GALVANIZED STRUCTURAL	Material			2023				
		STEEL PILES (12 IN		- Total				\$0.00		
			Material - To		_	0 40	OVOTEM	\$0.00		
			Overrun	Overrun	5	Sep 18, 2023	SYSTEM	(\$3,000.00)		
					9	Nov 16, 2023	SYSTEM	\$3,000.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',120.00000 - 120.00000, 'is applied (if non-zero).	
				Overrun - T	otal			\$0.00		
			Overrun - To	tal				\$0.00		
	1790 -	Total						\$0.00		
	1810	PILE POINT REINFORCEMENT	Material		6	Oct 2, 2023	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
					6	Oct 2, 2023	SYSTEM	(\$1,350.00)		
					7	Oct 16, 2023	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
					7	Oct 16, 2023	SYSTEM	(\$1,350.00)		
					8	Nov 2, 2023	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	
					8	Nov 2, 2023	SYSTEM	(\$1,350.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	1810 -	Total						\$0.00		
	1820		ETE		3	Aug 16, 2023	SYSTEM	\$39,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
						3	Aug 16, 2023	SYSTEM	(\$39,000.00)	
						4	Sep 5, 2023	SYSTEM	\$105,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					4	Sep 5, 2023	SYSTEM	(\$105,950.00)		
					5	Sep 18, 2023	SYSTEM	\$105,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
					5	Sep 18, 2023	SYSTEM	(\$105,950.00)		
					6	Oct 2, 2023	SYSTEM	\$116,740.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user raybol1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	
					6	Oct 2, 2023	SYSTEM	(\$116,740.00)		
					7	Oct 16, 2023	SYSTEM	\$116,740.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user raybol1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
					7	Oct 16, 2023	SYSTEM	(\$116,740.00)		
						8	Nov 2, 2023	SYSTEM	\$116,740.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user raybol1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$116,740.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	1820 -	Total						\$0.00		
	1840	SLAB ON CONCRETE NU- GIRDER	Material		10	Dec 4, 2023	SYSTEM	\$137,448.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3443	1840	SLAB ON CONCRETE NU-	Material		10	Dec 4, 2023	SYSTEM	(\$137,448.00)	
		GIRDER			11	Dec 18, 2023	SYSTEM	\$305,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					11	Dec 18, 2023	SYSTEM	(\$305,440.00)	
					12	Jan 2, 2024	SYSTEM	\$305,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mosesj2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					12	Jan 2, 2024	SYSTEM	(\$305,440.00)	
					13	Jan 17, 2024	SYSTEM	\$305,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					13	Jan 17, 2024	SYSTEM	(\$305,440.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1840 -	Total						\$0.00	
	1870	NU 43, PRESTRESSED CONC NU-GIRDER	Material		9	Nov 16, 2023	SYSTEM	\$316,710.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user raybol1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					9	Nov 16, 2023	SYSTEM	(\$316,710.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1870 -	Total						\$0.00	
	1880	REINFORCING STEEL (EPOXY COATED)	Material		4	Sep 5, 2023	SYSTEM	\$23,037.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					4	Sep 5, 2023	SYSTEM	(\$23,037.00)	
					5	Sep 18, 2023	SYSTEM	\$23,037.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user raybol1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					5	Sep 18, 2023	SYSTEM	(\$23,037.00)	
					6	Oct 2, 2023	SYSTEM	\$23,037.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user raybol1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					6	Oct 2, 2023	SYSTEM	(\$23,037.00)	
					7	Oct 16, 2023	SYSTEM	\$23,037.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user raybol1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					7	Oct 16, 2023	SYSTEM	(\$23,037.00)	
					8	Nov 2, 2023	SYSTEM	\$23,037.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user raybol1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$23,037.00)	
					9	Nov 16, 2023	SYSTEM	\$23,037.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user raybol1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					9	Nov 16, 2023	SYSTEM	(\$23,037.00)	
					10	Dec 4, 2023	SYSTEM	\$23,037.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					10	Dec 4, 2023	SYSTEM	(\$23,037.00)	
					11	Dec 18, 2023	SYSTEM	\$23,037.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					11	Dec 18,	SYSTEM	(\$23,037.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4P3443	1880	REINFORCING	Material			2023				
		STEEL (EPOXY COATED)			12	Jan 2, 2024	SYSTEM	\$23,037.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user mosesj2 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
					12	Jan 2, 2024	SYSTEM	(\$23,037.00)		
					13	Jan 17, 2024	SYSTEM	\$23,037.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user raybol1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
					13	Jan 17, 2024	SYSTEM	(\$23,037.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	1880 -	Total						\$0.00		
	1910	PLAIN NEOPRENE BEARING PAD	Material		6	Oct 2, 2023	SYSTEM	\$1,110.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user raybol1 overridding Payment Estimate Exception 38 on the current Payment Estimate.	
					6	Oct 2, 2023	SYSTEM	(\$1,110.00)		
				- Total				\$0.00		
			Material - To					\$0.00		
	19 <u>10</u> -	· Total						\$0.00		
	1920	LAMINATED NEOPRENE BEARING PAD	Material		6	Oct 2, 2023	SYSTEM	\$2,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user raybol1 overridding Payment Estimate Exception 40 on the current Payment Estimate.	
						6	Oct 2, 2023	SYSTEM	(\$2,520.00)	
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	1920 -	Total						\$0.00		
	1930	LAMINATED NEOPRENE BEARING PAD (TAPERED)	LAMINATED NEOPRENE BEARING PAD	Material		6	Oct 2, 2023	SYSTEM	\$1,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user raybol1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					6	Oct 2, 2023	SYSTEM	(\$1,890.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	1930 -	Total						\$0.00		
	1940	CLASS 1 EXCAVATION	Overrun	Overrun	6	Oct 2, 2023	SYSTEM	(\$2,904.00)		
					9	Nov 16, 2023	SYSTEM	\$2,904.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',88.00000 - 88.00000, 'is applied (if non-zero).	
				Overrun - T	otal			\$0.00		
			Overrun - To	tal				\$0.00		
	1940 -	Total						\$0.00		
	1960	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		7	Oct 16, 2023	SYSTEM	\$53,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					7	Oct 16, 2023	SYSTEM	(\$53,760.00)		
					8	Nov 2, 2023	SYSTEM	\$53,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user raybol1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					8	Nov 2, 2023	SYSTEM	(\$53,760.00)		
					9	Nov 16, 2023	SYSTEM	\$53,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					9	Nov 16, 2023	SYSTEM	(\$53,760.00)		
					10	Dec 4, 2023	SYSTEM	\$53,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	



MAPSHAS   1980	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
1	J4P3443	1960		Material		10		SYSTEM	(\$53,760.00)		
1970   1970			(MAJOR ROAD)			11		SYSTEM	\$53,760.00	Estimate Item Adjustment (0007) due to user raybol1 overridding Payment	
1900 - Total   1970   CALL VANIZED   Malerial   5						11		SYSTEM	(\$53,760.00)		
1500   Total   1500   Total   1500   This adjustment offices the original system-generated Material Payment Estimate   1500					- Total				\$0.00		
1970   GALVANIZED   STRUCTURAL   STRUCTURA				Material - To	tal				\$0.00		
STELL PILES   12		1960 -	Total						\$0.00		
Sep 18, SYSTEM   S\$7,000 to   STORE   S\$7,000 to   SYSTEM   S\$7,		1970	STRUCTURAL STEEL PILES (12	Material		5		SYSTEM	\$57,060.00	Estimate Item Adjustment (0009) due to user raybol1 overridding Payment	
Edimate Exception 15 on the current Payment Estimate			114			5		SYSTEM	(\$57,060.00)		
2023   7						6		SYSTEM	\$57,060.00	Estimate Item Adjustment (0019) due to user raybol1 overridding Payment	
2023   SYSTEM   (\$57,080.00)   Estimate later Adjustment (0017) due to user raybol to correction playment Estimate   System   S						6		SYSTEM	(\$57,060.00)		
8						7		SYSTEM	\$57,060.00	Estimate Item Adjustment (0017) due to user raybol1 overridding Payment	
2023   SYSTEM   SST,060.00   Estimate Exception 21 on the current Payment Estimate.						7		SYSTEM	(\$57,060.00)		
1970   Total   1970						8		SYSTEM	\$57,060.00	Estimate Item Adjustment (0025) due to user raybol1 overridding Payment	
Material - Total   So.00						8		SYSTEM	(\$57,060.00)		
Overrun   Overrun   5   Sep 18,   SYSTEM   (\$8,820.00)   Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',120,00000 - 120,00000, 'is applied (if non-zero).					- Total				\$0.00		
2023   9   Nov 16, SYSTEM   \$9,820.00   Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of 1,120,00000 - 120,00000, is applied (if non-zero).				Material - To	tal				\$0.00		
2023   September				Overrun	Overrun	5		SYSTEM	(\$8,820.00)		
1970 - Total   1990						9		SYSTEM	\$8,820.00	previous payment estimates. Price Adjustments of ',120.00000 - 120.00000, 'is	
1970 - Total   1990   PILE POINT REINFORCEMENT   Material   4   Sep 5, 2023   SYSTEM   \$810.00   This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate Exception 8 on the current Payment Estimate Exception 8 on the current Payment Estimate Estimate Item Adjustment (0019) due to user raybol1 overridding Payment Estimate Item Adjustment (0019) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate Exception 16 on the current Payment Estimate Estimate Exception 17 on the current Payment Estimate Estimate Exception 17 on the current Payment Estimate Estimate Exception 17 on the current Payment Estimate Estimate Estimate Exception 18 on the current Payment Estimate Estimate Estimate Exception 18 on the current Payment Estimate Estimate Estimate Exception 18 on the current Payment Estimate Estimate Estimate Exception 18 on the current Payment Estimate Exception 29 on the current Payment Estimate.					Overrun - T	otal			\$0.00		
PILE POINT REINFORCEMENT   Material Reinforcement ReInforcement ReInforcement REINFORCEMENT   Material Reinforcement ReInforce				Overrun - To	tal						
REINFORCEMENT   2023   Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 8 on the current Payment Estimate.											
5 Sep 18, SYSTEM \$810.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate.  5 Sep 18, SYSTEM (\$810.00)  6 Oct 2, SYSTEM \$810.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate.  6 Oct 2, SYSTEM (\$810.00)  7 Oct 16, SYSTEM \$810.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate.  7 Oct 16, SYSTEM \$810.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user raybol1 overridding Payment Estimate Item Adjustment (0018) due to user raybol1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  7 Oct 16, SYSTEM (\$810.00)  8 Nov 2, SYSTEM \$1,620.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user raybol1 overridding Payment Estimate Item Adjustment (0026) due to user raybol1 overridding Payment Estimate Exception 23 on the current Payment Estimate.		1990		Material			2023		,	Estimate Item Adjustment (0006) due to user raybol1 overridding Payment	
Estimate Item Adjustment (0019) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  5						4	0000	SYSTEM	(\$810.00)		
6 Oct 2, 2023 SYSTEM \$810.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  6 Oct 2, 2023 SYSTEM (\$810.00)  7 Oct 16, 2023 SYSTEM \$810.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user raybol1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  7 Oct 16, 2023 SYSTEM (\$810.00)  8 Nov 2, SYSTEM \$1,620.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user raybol1 overridding Payment Estimate Item Adjustment (0026) due to user raybol1 overridding Payment Estimate Item Adjustment (0026) due to user raybol1 overridding Payment Estimate Exception 23 on the current Payment Estimate.						5		SYSTEM	\$810.00	Estimate Item Adjustment (0019) due to user raybol1 overridding Payment	
Estimate Item Adjustment (0020) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  6 Oct 2, 2023  7 Oct 16, 2023  8 SYSTEM (\$810.00)  7 Oct 16, 2023  8 Nov 2, 2023  8 Nov 2, 2023  8 Nov 2, SYSTEM (\$1,620.00)  Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate.  7 Item (\$810.00)  This adjustment (0018) due to user raybol1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  8 Nov 2, SYSTEM (\$1,620.00)  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user raybol1 overridding Payment Estimate Exception 23 on the current Payment Estimate.						5		SYSTEM	(\$810.00)		
7 Oct 16, 2023  8810.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user raybol1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  7 Oct 16, 2023  8 Nov 2, 2023  8 Nov 2, 2023  8 Nov 2, 2023  SYSTEM \$1,620.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user raybol1 overridding Payment Estimate Exception 23 on the current Payment Estimate.  8 Nov 2, SYSTEM (\$1,620.00)						6		SYSTEM	\$810.00	Estimate Item Adjustment (0020) due to user raybol1 overridding Payment	
2023 Estimate Item Adjustment (0018) due to user raybol1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  7 Oct 16, 2023  8 Nov 2, 2023  SYSTEM \$1,620.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user raybol1 overridding Payment Estimate Exception 23 on the current Payment Estimate.  8 Nov 2, SYSTEM (\$1,620.00)						6		SYSTEM	(\$810.00)		
8 Nov 2, 2023  8 SYSTEM \$1,620.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user raybol1 overridding Payment Estimate Exception 23 on the current Payment Estimate.  8 Nov 2, SYSTEM (\$1,620.00)						7		SYSTEM	\$810.00	Estimate Item Adjustment (0018) due to user raybol1 overridding Payment	
2023 Estimate Item Adjustment (0026) due to user raybol1 overridding Payment Estimate Exception 23 on the current Payment Estimate.  8 Nov 2, SYSTEM (\$1,620.00)						7		SYSTEM	(\$810.00)		
							8		SYSTEM	\$1,620.00	Estimate Item Adjustment (0026) due to user raybol1 overridding Payment
						8		SYSTEM	(\$1,620.00)		
- Total \$0.00					- Total				\$0.00		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3443	1990	PILE POINT REINFORCEMENT	Material - Tot	tal				\$0.00	
	1990 -	Total						\$0.00	
	2000	CLASS B CONCRETE (SUBSTRUCTURE)	Material		3	Aug 16, 2023	SYSTEM	\$75,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Aug 16, 2023	SYSTEM	(\$75,000.00)	
					4	Sep 5, 2023	SYSTEM	\$123,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					4	Sep 5, 2023	SYSTEM	(\$123,600.00)	
					5	Sep 18, 2023	SYSTEM	\$123,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user raybol1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					5	Sep 18, 2023	SYSTEM	(\$123,600.00)	
					6	Oct 2, 2023	SYSTEM	\$123,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user raybol1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					6	Oct 2, 2023	SYSTEM	(\$123,600.00)	
					7	Oct 16, 2023	SYSTEM	\$123,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user raybol1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					7	Oct 16, 2023	SYSTEM	(\$123,600.00)	
					8	Nov 2, 2023	SYSTEM	\$123,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user raybol1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$123,600.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	2000 -	Total						\$0.00	
	2010	TYPE D BARRIER	Material		7	Oct 16, 2023	SYSTEM	\$119,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user raybol1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					7	Oct 16, 2023	SYSTEM	(\$119,750.00)	
					8	Nov 2, 2023	SYSTEM	\$119,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user raybol1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$119,750.00)	
					9	Nov 16, 2023	SYSTEM	\$119,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user raybol1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					9	Nov 16, 2023	SYSTEM	(\$119,750.00)	
					10	Dec 4, 2023	SYSTEM	\$119,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Dec 4, 2023	SYSTEM	(\$119,750.00)	
					11	Dec 18, 2023	SYSTEM	\$119,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					11	Dec 18, 2023	SYSTEM	(\$119,750.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	2010 -	Total						\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3443	2020	SLAB ON CONCRETE NU- GIRDER	Material		5	Sep 18, 2023	SYSTEM	(\$226,260.00)	
					2023		\$377,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user raybol1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	
					6	Oct 2, 2023	SYSTEM	(\$377,100.00)	
					7	Oct 16, 2023	SYSTEM	\$377,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user raybol1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					7	Oct 16, 2023	SYSTEM	(\$377,100.00)	
					8	Nov 2, 2023	SYSTEM	\$377,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user raybol1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$377,100.00)	
					9	Nov 16, 2023	SYSTEM	\$377,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					9	Nov 16, 2023	SYSTEM	(\$377,100.00)	
					10	Dec 4, 2023	SYSTEM	\$377,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					10	Dec 4, 2023	SYSTEM	(\$377,100.00)	
					11	Dec 18, 2023	SYSTEM	\$377,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					11	Dec 18, 2023	SYSTEM	(\$377,100.00)	
					12	Jan 2, 2024	SYSTEM	\$377,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user mosesj2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					12	Jan 2, 2024	SYSTEM	(\$377,100.00)	
					13	Jan 17, 2024	SYSTEM	\$377,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					13	Jan 17, 2024	SYSTEM	(\$377,100.00)	
				- Total				\$0.00	
	2020 -	Total	Material - To	tal				\$0.00 \$0.00	
	2030	FORM LINERS	Material		6	Oct 2, 2023	SYSTEM	\$14,141.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user raybol1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					6	Oct 2, 2023	SYSTEM	(\$14,141.00)	
					7	Oct 16, 2023	SYSTEM	\$14,141.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user raybol1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					7	Oct 16, 2023	SYSTEM	(\$14,141.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	2030 -	Total						\$0.00	
	2050	NU 43, PRESTRESSED CONC NU-GIRDER	Material		4	Sep 5, 2023	SYSTEM	\$211,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					4	Sep 5, 2023	SYSTEM	(\$211,140.00)	
					5	Sep 18, 2023	SYSTEM	\$422,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user raybol1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					5	Sep 18,	SYSTEM	(\$422,280.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4P3443	2050	NU 43,	Material			2023				
		PRESTRESSED CONC NU-GIRDER		- Total				\$0.00		
			Material - Tot	al				\$0.00		
	2050 -	Total						\$0.00		
	2060	CONDUIT SYSTEM ON STRUCTURE	Material		6	Oct 2, 2023	SYSTEM	\$27,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user raybol1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	
					6	Oct 2, 2023	SYSTEM	(\$27,500.00)		
				- Total				\$0.00		
			Material - Tot	tal				\$0.00		
	2060 -	Total						\$0.00		
	2070	REINFORCING STEEL (EPOXY COATED)	Material		3	Aug 16, 2023	SYSTEM	\$32,592.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					3	Aug 16, 2023	SYSTEM	(\$32,592.00)		
					4	Sep 5, 2023	SYSTEM	\$32,592.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	
					4	Sep 5, 2023	SYSTEM	(\$32,592.00)		
					5	Sep 18, 2023	SYSTEM	\$32,592.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user raybol1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	
					5	Sep 18, 2023	SYSTEM	(\$32,592.00)	-	
					6	Oct 2, 2023	SYSTEM	\$32,592.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user raybol1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	
					6	Oct 2, 2023	SYSTEM	(\$32,592.00)		
					7	Oct 16, 2023	SYSTEM	\$32,592.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user raybol1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	
					7	Oct 16, 2023	SYSTEM	(\$32,592.00)		
					8	Nov 2, 2023	SYSTEM	\$32,592.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user raybol1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	
					8	Nov 2, 2023	SYSTEM	(\$32,592.00)		
					9	Nov 16, 2023	SYSTEM	\$32,592.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user raybol1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
					9	Nov 16, 2023	SYSTEM	(\$32,592.00)		
						10	Dec 4, 2023	SYSTEM	\$32,592.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					10	Dec 4, 2023	SYSTEM	(\$32,592.00)		
					11	Dec 18, 2023	SYSTEM	\$32,592.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	
					11	Dec 18, 2023	SYSTEM	(\$32,592.00)		
					12	Jan 2, 2024	SYSTEM	\$32,592.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user mosesj2 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
					12	Jan 2, 2024	SYSTEM	(\$32,592.00)		
					13	Jan 17, 2024	SYSTEM	\$32,592.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
					13	Jan 17, 2024	SYSTEM	(\$32,592.00)		



March   1990   Marc	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1000   VERTICAL (STAM)   Material	J4P3443	2070							\$0.00	
Sept 16   Sept			COATED)	Material - To	tal					
## AT END BENTS   ##   ##   ##   ##   ##   ##   ##										
2023   6		2090		Material		5		SYSTEM	\$3,800.00	Estimate Item Adjustment (0024) due to user raybol1 overridding Payment
August						5		SYSTEM	(\$3,800.00)	
2023						6		SYSTEM	\$3,800.00	Estimate Item Adjustment (0026) due to user raybol1 overridding Payment
2023   Sep 18   SYSTEM   St. 480.00   SYSTEM   St. 480.00   St. 480.						6		SYSTEM	(\$3,800.00)	
2023   SySTEM   S3,800.00   This adjustment offsets the original system-generated Material Payment Edimate Exception 35 on the current Payment Edimate Dayment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Dayment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the current Payment Edimate Payment Edimate Exception 35 on the c						7		SYSTEM	\$3,800.00	Estimate Item Adjustment (0024) due to user raybol1 overridding Payment
2023   SysTeM   Estimate Exception 30 on the current Payment Estimate						7		SYSTEM	(\$3,800.00)	
2023   SySTEM   S3,800.00   This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate Exception 22 on the current Payment Estimate Exception 22 on the current Payment Estimate Exception 22 on the current Payment Estimate Exception 32 on the current Payment Estimate Estimate Exception 32 on the current Payment Estimate Exception 32 on the current Payment Estimate Estimate Exception 32 on the current Payment Estimate Exception 32 on the current Payment Estimate Estimate Exception 32 on the current Payment Estimate Estimate Exception 32 on the current Payment Estimate Estimate Exception 33 on the current Payment Estimate Estimate Exception 34 on the current Payment Estimate Estimate Exception 35 on the current Payment Estimate Estimate Exception 35 on the current Payment Estimate Estimate Exception 35 on the current Payment Estimate Exception						8		SYSTEM	\$3,800.00	Estimate Item Adjustment (0031) due to user raybol1 overridding Payment
2023   September   September						8		SYSTEM	(\$3,800.00)	
PLAIN NEOPRENE   BEARING PAD   Material - Total						9		SYSTEM	\$3,800.00	Estimate Item Adjustment (0030) due to user raybol1 overridding Payment
National - Total   S0.00						9		SYSTEM	(\$3,800.00)	
2009 - Total   2009					- Total				\$0.00	
2100   PLAIN NEOPRENE   BEARING PAD				Material - Total					\$0.00	
BEARING PAD		2090 -	Total						\$0.00	
2023   SYSTEM   \$1,480.00   This adjustment offsets the original system-generated Material Payment Estimate Exception 35 on the current Payment Estimate.		2100			erial	4		SYSTEM	\$1,480.00	Estimate Item Adjustment (0010) due to user raybol1 overridding Payment
2023   Estimate Item Adjustment (0025) due to user raybol1 overridding Payment Estimate Exception 35 on the current Payment Estimate.						4		SYSTEM	(\$1,480.00)	
2023						5		SYSTEM	\$1,480.00	Estimate Item Adjustment (0025) due to user raybol1 overridding Payment
2023   Estimate Item Adjustment (0027) due to user raybol1 overridding Payment Estimate Exception 39 on the current Payment Estimate.						5		SYSTEM	(\$1,480.00)	
Total   \$0.00						6		SYSTEM	\$1,480.00	Estimate Item Adjustment (0027) due to user raybol1 overridding Payment
Sumarial   Sumarial						6		SYSTEM	(\$1,480.00)	
Sep 18, 2023   SYSTEM   \$3,360.00   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 23 on the current Payment Estimate.					- Total				\$0.00	
LAMINATED NEOPRENE BEARING PAD  A Sep 5, 2023  A SYSTEM \$3,360.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate.  A Sep 5, 2023  SYSTEM (\$3,360.00)  This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate.  Sep 18, 2023  SYSTEM \$3,360.00 This adjustment (0026) due to user raybol1 overridding Payment Estimate Exception 36 on the current Payment Estimate.  Sep 18, 2023  SYSTEM (\$3,360.00)  This adjustment offsets the original system-generated Material Payment Estimate Exception 36 on the current Payment Estimate.  Sep 18, 2023  SYSTEM \$3,360.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 36 on the current Payment Estimate.  Sep 18, 2023  SYSTEM \$3,360.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user raybol1 overridding Payment Estimate Exception 41 on the current Payment Estimate.				Material - To	al - Total				\$0.00	
NEOPRENE BEARING PAD  2023 Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 23 on the current Payment Estimate.  4 Sep 5, 2023 SYSTEM (\$3,360.00)  5 Sep 18, 2023 SYSTEM \$3,360.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 36 on the current Payment Estimate.  5 Sep 18, 2023 SYSTEM (\$3,360.00)  6 Oct 2, 2023 SYSTEM \$3,360.00 This adjustment (0026) due to user raybol1 overridding Payment Estimate Exception 36 on the current Payment Estimate.  6 Oct 2, 2023 SYSTEM \$3,360.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user raybol1 overridding Payment Estimate Exception 41 on the current Payment Estimate.		2100 -	Total						\$0.00	
5 Sep 18, 2023 SYSTEM \$3,360.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user raybol1 overridding Payment Estimate Exception 36 on the current Payment Estimate.  5 Sep 18, 2023 SYSTEM (\$3,360.00)  6 Oct 2, 2023 SYSTEM \$3,360.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user raybol1 overridding Payment Estimate Exception 41 on the current Payment Estimate.  6 Oct 2, 2023 SYSTEM (\$3,360.00)		2110	NEOPRENE	E	/laterial	4		SYSTEM	\$3,360.00	Estimate Item Adjustment (0011) due to user raybol1 overridding Payment
Estimate Item Adjustment (0026) due to user raybol1 overridding Payment Estimate Exception 36 on the current Payment Estimate.  5 Sep 18, 2023 (\$3,360.00)  6 Oct 2, 2023 SYSTEM \$3,360.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user raybol1 overridding Payment Estimate Exception 41 on the current Payment Estimate.  6 Oct 2, 2023 SYSTEM (\$3,360.00)						4		SYSTEM	(\$3,360.00)	
6 Oct 2, 2023  SYSTEM \$3,360.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user raybol1 overridding Payment Estimate Exception 41 on the current Payment Estimate.  Oct 2, 2023  SYSTEM (\$3,360.00)						5		SYSTEM	\$3,360.00	Estimate Item Adjustment (0026) due to user raybol1 overridding Payment
2023 Estimate Item Adjustment (0028) due to user raybol1 overridding Payment Estimate Exception 41 on the current Payment Estimate.  6 Oct 2, 2023 (\$3,360.00)						5		SYSTEM	(\$3,360.00)	
2023						6		SYSTEM	\$3,360.00	Estimate Item Adjustment (0028) due to user raybol1 overridding Payment
- Total \$0.00						6		SYSTEM	(\$3,360.00)	
					- Total				\$0.00	





AP3-443   2110	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
SECANO PAD	J4P3443	2110		Material - Tot	al				\$0.00	
1120   NECHTENES   Page   Pa										
NEOPRENE BEARING PAD   4   Sep 5, SYSTEM   S2,520.00   Estimate Exception 24 on the current Payment Estimate Exception 37 on the current Payment Estimate Estimate Exception 37 on the current Payment Estimate Estimate Exception 37 on the current Payment Estimate Estimate Exception 37 on the current Payment Estimate Exception 47 on the current Payment Estimate Exception 47 on the current Payment Estimate Estimate Exception 49 on th		2110 -	Total						\$0.00	
4		2120	NEOPRENE BEARING PAD	Material		4		SYSTEM	\$2,520.00	Estimate Item Adjustment (0012) due to user raybol1 overridding Payment
2023   Estimate Exemption 2027 due to user raybolf overridding Payment			(TAPERED)			4		SYSTEM	(\$2,520.00)	
2023						5		SYSTEM	\$2,520.00	Estimate Item Adjustment (0027) due to user raybol1 overridding Payment
2023   Estimate Item Aglistment (0029) due to user rayboil overridding Payment						5		SYSTEM	(\$2,520.00)	
Total   S0.00     S0.00						6		SYSTEM	\$2,520.00	Estimate Item Adjustment (0029) due to user raybol1 overridding Payment
Material - Total   Support						6		SYSTEM	(\$2,520.00)	
2120 - Total   \$0.00   TEMPORARY PIPE   Material   4					- Total				\$0.00	
Sep				Material - Tot	al				\$0.00	
2023   Estimate Item Adjustment (0014) due to user raybort overridding Payment Estimate Exception 25 on the current Payment Estimate.		2120 -	20 - Total						\$0.00	
Total   S0.00   S0.0		5002	TEMPORARY PIPE	Material		4	Sep 5, 2023	SYSTEM	\$7,200.00	Estimate Item Adjustment (0014) due to user raybol1 overridding Payment
Material - Total   Summer						4		SYSTEM	(\$7,200.00)	
S002 - Total   S0.00					- Total					
South   Sout				Material - Tot	al				\$0.00	
SAND BARREL   2023   Estimate Item Adjustment (0032) due to user raybol1 overridding Payment Estimate Exception 19 on the current Payment Estimate.		5002 -	Total						\$0.00	
Total   \$0.00		5005		Material		8		SYSTEM	\$4,725.00	Estimate Item Adjustment (0032) due to user raybol1 overridding Payment
Material - Total   \$0.00						8		SYSTEM	(\$4,725.00)	
S005 - Total   S0.00					- Total				\$0.00	
TEMPORARY PIPE Material 8 Nov 2, 2023 SYSTEM \$3,422.40 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user raybol1 overridding Payment Estimate Exception 40 on the current Payment Estimate.  8 Nov 2, 2023 SYSTEM (\$3,422.40)  - Total \$0.00  Material - Total \$0.00  5006 - Total \$0.00  J4P3443 - Total \$50,383.06				Material - Tot	al				\$0.00	
2023   Estimate Item Adjustment (0033) due to user raybol1 overridding Payment Estimate Exception 40 on the current Payment Estimate.    Nov 2		5005 -	Total						\$0.00	
2023		5006	TEMPORARY PIPE	Material		8		SYSTEM	\$3,422.40	Estimate Item Adjustment (0033) due to user raybol1 overridding Payment
Material - Total \$0.00  5006 - Total \$0.00  J4P3443 - Total \$50,383.06						8		SYSTEM	(\$3,422.40)	
5006 - Total     \$0.00       J4P3443 - Total     \$50,383.06					- Total				\$0.00	
J4P3443 - Total \$50,383.06				Material - Tot	al				\$0.00	
		5006 -	Total						\$0.00	
Overall - Total \$50,383.06	J4P3443 -	Total							\$50,383.06	
	Overall -	Total							\$50,383.06	



#### Contract Adjustments for Contract - 230519-C04

Estimate Project Number		Adjustment Type	Other Adjustment Type	Adjustment Amount	Adjustment Percentage by Project	Created Date	Created By	Comments
7	J4P3443	Other Contract Adjustment	SIGN	(\$155.26)	100	Oct 16, 2023	raybol1	9/25/2023 to 9/26/2023 - Signing Materials Inspection by Sam Marshall
7 - Total					(\$155.26)			
Overall - Total					(\$155.26)			

Revision 3/23/2023 Page 34 of 34