74.95%



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: February 2, 2024

June 28, 2024

| Progress Estimate Number | Contract ID | 230519-C04 | Pay Period Start | January 16, 2024 | Original Contract Amount | \$10,985,676.85 |
|-----------------------------|---------------------|--|---------------------|----------------------------------|--|---------------------------------------|
| 14 | Prime Contractor | Radmacher Brothers Excavating Co.,Inc. | Pay Period En | d ^{February 1,} 2024 | Net Change Order Amount Current Contract Amo | (\$135,132.66) unt \$10,850,544.19 |

| Approval Date | | | | | By User | | | | | |
|------------------|-------------|--|------------------------------------|--|--------------|--|--|--|--|--|
| February 2, 2024 | | Generated and Approved (and should be considered Draft) at the Project Office Level by | | | | | | | | |
| February 2, 2024 | | Reviewed and Appr | oved (and should be considered Dra | aft) at the Resident Engineer Level by | penner1 | | | | | |
| February 5, 2024 | | Reviewed and Approved at the Central Office Controllers Office Level by | | | | | | | | |
| Original Comp | letion Date | Current Completion Date | Actual Completion Date | % of Current Contract Amou | int Complete | | | | | |

| | Contract Informational Dates | | | | | | | | |
|------------------------|------------------------------|--------------------------------|----------------------------------|--|--|--|--|--|--|
| Date Description | Original Completion Date | Current Completion Date | No Milestones Exist for Contract | | | | | | |
| Acceptance Date | | | | | | | | | |
| Awarded Date | June 7, 2023 | June 7, 2023 | | | | | | | |
| Letting Date | May 19, 2023 | May 19, 2023 | | | | | | | |
| Notice to Proceed Date | July 10, 2023 | July 10, 2023 | | | | | | | |
| Open to Traffic Date | | | | | | | | | |
| Work Began Date | July 17, 2023 | July 17, 2023 | | | | | | | |

June 28, 2024

| Contract Total Pa | y For Estimate No. 14 | | | |
|--------------------------|--|--|---|---|
| | | This Estimate | Previous | To Date |
| 230519-C04 | Total Posted Items Pay Gross Item Adjustments Incentive Disincentive Liquidated Damage Other Contract Adjustments | \$378,463.20 (\$9,792.00) \$0.00 \$0.00 \$0.00 \$0.00 | \$7,754,414.27 \$50,383.06 \$0.00 \$0.00 \$0.00 (\$155.26) \$7,804,642.07 | \$8,132,877.47 \$40,591.06 \$0.00 \$0.00 \$0.00 (\$155.26) \$8,173,313.27 |
| Contract Total Pa | yable This Estimate: | \$368,671.20 | Ç.,,cc.,,c.1=1c. | \$ 0, 0,0 . 0. 1 |

Items Paid This Estimate Period

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount | |
|-------------------|----------------|--------------|--|------|---------------|--------------------------|-----------------------------|--|
| J4P3443 | 0110 | 3049905 | MISC.OPTIONAL BASE | SQYD | \$14.000 | 880.2 | \$12,322.80 | |
| | 0120 | 4019905 | MISC.OPTIONAL PAVEMENT | SQYD | \$105.000 | 391.2 | \$41,076.00 | |
| | 0210 | 6097000 | ROCK LINING | CUYD | \$136.000 | 97 | \$13,192.00 | |
| | 0940 | 3049905 | MISC.ALTERNATE BASE | SQYD | \$12.000 | 1,832 | \$21,984.00 | |
| | 0950 | 5021334 | CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS) | SQYD | \$98.000 | 1,912.7 | \$187,444.60 | |
| | 1590 | 9039901 | MISC.NB ON RAMP TRUSS #48 | LS | \$136,800.000 | 0.25 | \$34,200.00 | |
| | 1610 | 9039901 | MISC.SB AT EXIT 158 TRUSS #41 | LS | \$136,800.000 | 0.25 | \$34,200.00 | |
| | 1620 | 9039901 | MISC.SB OFF RAMP CANT. TRUSS #42 | LS | \$89,500.000 | 0.25 | \$22,375.00 | |
| | 5010 | 6205301B | TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE | LF | \$2.200 | 4,344 | \$9,556.80 | |
| | 5011 | 6205303B | TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW | LF | \$2.200 | 960 | \$2,112.00 | |
| Project J4P3 | 443 - Total | | | | | | \$378,463.20 | |
| Overall - Total | | | | | | | | |

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Revision 3/23/2023 Page 1 of 36



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: February 2, 2024

Progress Estimate Pay Period **Original Contract** January 16, Contract ID 230519-C04 \$10,985,676.85 Number Start 2024 Amount Pay Period End February 1, 2024 Net Change Order Amount Radmacher Brothers Excavating Prime 14 (\$135,132.66) Contractor Co.,Inc. Current Contract Amount \$10,850,544.19

| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment | Comments | Adjustment Quantity | Line Item Adjustment | Adjustment amount |
|-------------------|-------------|---|--------------------|--------------------------|--|------------------------|-------------------------|-------------------|
| | | | | Туре | | • | Unit Price | |
| J4P3443 | 0160 | PIPE COLLAR, TYPE A | Material | | | -1 | \$1,600.00 | (\$1,600.00) |
| | 0160 | PIPE COLLAR, TYPE A | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | 1 | \$1,600.00 | \$1,600.00 |
| | 0210 | ROCK LINING | Overrun | | | -72 | \$136.00 | (\$9,792.00) |
| | 0210 | ROCK LINING | Material | | | -199 | \$136.00 | (\$27,064.00) |
| | 0210 | ROCK LINING | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | 199 | \$136.00 | \$27,064.00 |
| | 0500 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | Material | | | -8 | \$340.00 | (\$2,720.00) |
| | 0500 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | 8 | \$340.00 | \$2,720.00 |
| (| 0680 | REINFORCING STEEL (CULVERTS) | Material | | | -8,330 | \$2.70 | (\$22,491.00) |
| | 0680 | REINFORCING STEEL (CULVERTS) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | 8,330 | \$2.70 | \$22,491.00 |
| | 0770 | 18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION | Material | | | -1 | \$1,900.00 | (\$1,900.00) |
| | 0770 | 18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate. | 1 | \$1,900.00 | \$1,900.00 |
| | 0950 | CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS) | Material | | | -8,568.451 | \$98.00 | (\$839,708.20) |
| | 0950 | CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | 8,568.451 | \$98.00 | \$839,708.20 |
| | 1590 | MISC. | Material | | | -0.25 | \$136,800.00 | (\$34,200.00) |
| | 1590 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 15 on the current Payment Estimate. | 0.25 | \$136,800.00 | \$34,200.00 |
| | 1610 | MISC. | Material | | | -0.25 | \$136,800.00 | (\$34,200.00) |
| | 1610 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate. | 0.25 | \$136,800.00 | \$34,200.00 |
| | 1620 | MISC. | Material | | | -0.25 | \$89,500.00 | (\$22,375.00) |

Revision 3/23/2023 Page 2 of 36



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: February 2, 2024

Progress Estimate Pay Period **Original Contract** January 16, Contract ID 230519-C04 \$10,985,676.85 Number Start 2024 Amount Pay Period End February 1, 2024 Net Change Order (\$135,132.66)
Amount Current Contract Amount \$10,850,544.19 Prime Radmacher Brothers Excavating 14 Contractor Co.,Inc.

| | | | | | | Julioni Jone | uot / iiiiouiit ¢ | 10,050,544.19 |
|-------------------|-------------|---|--------------------|----------------------------------|--|------------------------|---------------------------------------|-------------------|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J4P3443 | 1620 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate. | 0.25 | \$89,500.00 | \$22,375.00 |
| | 1880 | REINFORCING STEEL (EPOXY COATED) | Material | | | -10,970 | \$2.10 | (\$23,037.00) |
| | 1880 | REINFORCING STEEL (EPOXY COATED) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 12 on the current Payment Estimate. | 10,970 | \$2.10 | \$23,037.00 |
| | 2020 | SLAB ON CONCRETE NU- GIRDER | Material | | | -838 | \$450.00 | (\$377,100.00) |
| | 2020 | SLAB ON CONCRETE NU- GIRDER | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | 838 | \$450.00 | \$377,100.00 |
| 2 | 2070 | REINFORCING STEEL (EPOXY COATED) | Material | | | -15,520 | \$2.10 | (\$32,592.00) |
| | 2070 | REINFORCING STEEL (EPOXY COATED) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user raybol1 overridding Payment Estimate Exception 13 on the current Payment Estimate. | 15,520 | \$2.10 | \$32,592.00 |
| | 5010 | TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE | Material | | | -4,344 | \$2.20 | (\$9,556.80) |
| | 5010 | TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user raybol1 overridding Payment Estimate Exception 6 on the current Payment Estimate. | 4,344 | \$2.20 | \$9,556.80 |
| | 5011 | 011 TEMPORARY REMOVABLE Material MARKING TAPE 4 IN., YELLOW | | | | -960 | \$2.20 | (\$2,112.00) |
| | 5011 | TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user raybol1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | 960 | \$2.20 | \$2,112.00 |
| Total | | | | | | | | (\$9,792.00) |

Revision 3/23/2023 Page 3 of 36



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | | Contract Project Information | |
|-------------------|----------------------------|---|-------|----------|-----------------------------|------------------------------|------------------|
| Project Number | Federal Proj. Number | Project Description | Route | County | | | Location of Work |
| J4P3443 | FAF 7-1(46) | 2 Bridge replacements and intersection improvements | 7 | CASS | on Rte. 7 (275th Street) or | ver I-49 | |
| Γotals by . | Job Numbe | ers | | | | | |
| J4P3443 | | | | | This Estimate | Previous | To Date |
| | Poste | d Item Pay | | | \$378,463.20 | \$7,754,414.27 | \$8,132,877.47 |
| | | s Item Adjustme | ents | | (\$9,792.00) | \$50.383.06 | \$40.591.06 |
| | | | | Item Pay | \$368,671.20 | \$7,804,797.33 | \$8,173,468.53 |
| | Incen | tive | | | \$0.00 | \$0.00 | \$0.00 |
| | Disin | centive | | | \$0.00 | \$0.00 | \$0.00 |
| | Lieuri | dated Damages | | | \$0.00 | \$0.00 | \$0.00 |
| | Liqui | | | | | | |

Revision 3/23/2023 Page 4 of 36



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| xceptions (Discrepancies) This Estimate Period | | | |
|---|---|---------------|-------------|
| Exceptions / Discrepencies | Explanation | Entered By | Status |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 5021334, Project Item Line Number 0950, Material Set 502133496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | Need QC and QCQA materials report for the rock. | raybol1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 5021334, Project Item Line Number 0950, Material Set 502133496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | Need QC materials report for the sand. | raybol1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 6044011, Project Item Line Number 0160, Material Set 604401196, Material 0604CPCR - Collar for Pipe Connection, Acceptance Action Generic 0604CPCR is insufficient. | Need materials report for the pipe collar. | raybol1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 6097000, Project Item Line Jumber 0210, Material Set 609700096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient. | Need materials report for the rock lining. | raybol1 | Overridden |
| estimate Exception Type: Insufficient Materials: Project J4P3443, Item 6200021, Project Item Line Jumber 0500, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient. | Need materials report for the preformed arrows. | raybol1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 6205301B, Project Item Line Jumber 5010, Material Set 6205301B96, Material 1048PMRPMTWH - Marking Tape Removable White, Acceptance Action Generic 1048PMRPMTWH is insufficient. | Need materials report for the temporary tape. | raybol1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project J4P3443, Item 6205303B, Project Item Line lumber 5011, Material Set 6205303B96, Material 1048PMRPMTYL - Marking Tape Removable Yellow, acceptance Action Generic 1048PMRPMTYL is insufficient. | Need materials report for the temporary tape. | raybol1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7034221, Project Item Line lumber 2020, Material Set 703422196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance action Generic 0501CCB2.A is insufficient. | Need QC materials report for the concrete. | raybol1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project J4P3443, Item 7061030, Project Item Line lumber 0680, Material Set 706103096, Material 1036RSDFPL42M29 - Reinforcing Steel No. 9/M29 Gr 0/M420 @, Acceptance Action Generic ReSteelBars is insufficient. | Need PAL materials report for the rebar. | raybol1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7061030, Project Item Line Jumber 0680, Material Set 706103096, Material 1036RSDFPL42M32 - Reinforcing Steel No. 10/M32 Gr 0/M420@, Acceptance Action Generic ReSteelBars is insufficient. | Need PAL materials report for the rebar. | raybol1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7061030, Project Item Line Jumber 0680, Material Set 706103096, Material 1036RSDFPL42M36 - Reinforcing Steel No. 11/M36 Gr 0/M420@, Acceptance Action Generic ReSteelBars is insufficient. | Need PAL materials report for the rebar. | raybol1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project J4P3443, Item 7101000, Project Item Line lumber 1880, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch lolts @, Acceptance Action Generic ReinforcingMisc is insufficient. | Need PAL materials report for the anchor bolts. | raybol1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7101000, Project Item Line Jumber 2070, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Jolts @, Acceptance Action Generic ReinforcingMisc is insufficient. | Need PAL materials report for the anchor bolts. | raybol1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project J4P3443, Item 7320018A, Project Item Line lumber 0770, Material Set 7320018A96, Material 1020ESAC - Flared End Section Aluminum coated teel, Acceptance Action Generic 1020ESAC is insufficient. | Need materials report for the 18" Flared End Section. | raybol1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project J4P3443, Item 9039901, Project Item Line umber 1590, Material Set 9039901, Material 0903HSXX - Highway Signing Material, Acceptance Action teneric 0903HSXX is insufficient. | Need materials report for the sign truss. | raybol1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project J4P3443, Item 9039901, Project Item Line lumber 1610, Material Set 9039901, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. | Need materials report for the sign truss. | raybol1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project J4P3443, Item 9039901, Project Item Line lumber 1620, Material Set 9039901, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. | Need materials report for the sign truss. | raybol1 | Overridden |
| estimate Exception Type: Item Overrun: Contract 230519-C04, Contract Project J4P3443, Project Item ine Number 0210, Contract Line Item Number 0210, Item 6097000, Minor Item. | No Remark was entered by Engineer | raybol1 | Acknowledge |
| estimate Exception Type: Item Overrun: Contract 230519-C04, Contract Project J4P3443, Project Item ine Number 0900, Contract Line Item Number 0900, Item 8064138, Minor Item. | No Remark was entered by Engineer | raybol1 | Acknowledge |
| stimate Exception Type: Item Overrun: Contract 230519-C04, Contract Project J4P3443, Project Item ine Number 1390, Contract Line Item Number 1390, Item 9027400, Minor Item. | No Remark was entered by Engineer | raybol1 | Acknowledge |

Revision 3/23/2023 Page 5 of 36



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Note: Posted Q | uantities | and Valu | es are b | ased on R | eport Generated date and can differ from the posted amo | ount at the | time the E | estimate was | s Gener | ated. | | |
|-------------------------|----------------|----------|-------------|--------------|---|-----------------|------------------------|------------------------------|---------|------------------------------------|--------------|--|
| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
| 230519-C04 | J4P3443 | 0001 | 0010 | 2013000 | CLEARING AND GRUBBING | 2.00 | 0.00 | 2.00 | ACRE | 2.00 | \$9,000.00 | \$18,000.00 |
| | | 0001 | 0020 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | -1.00 | 0.00 | LS | 0.00 | \$202,700.00 | \$0.00 |
| | | 0001 | 0021 | 2022010 | REMOVAL OF IMPROVEMENTS | 0.00 | 1.00 | 1.00 | LS | 0.90 | \$200,750.00 | \$180,675.00 |
| | | 0001 | 0030 | 2031000 | CLASS A EXCAVATION | 14,656.00 | 0.00 | 14,656.00 | CUYD | 14,656.00 | \$15.00 | \$219,840.00 |
| | | 0001 | 0040 | 2035500 | EMBANKMENT IN PLACE | 28,657.00 | 0.00 | 28,657.00 | CUYD | 28,657.00 | \$19.00 | \$544,483.00 |
| | | 0001 | 0050 | 2036000 | COMPACTING EMBANKMENT | 12,365.00 | 0.00 | 12,365.00 | CUYD | 12,365.00 | \$3.10 | \$38,331.50 |
| | | 0001 | 0060 | 2037075 | COMPACTING IN CUT | 92.90 | 0.00 | 92.90 | STA | 92.90 | \$660.00 | \$61,314.00 |
| | | 0001 | 0070 | 2063000 | CLASS 3 EXCAVATION | 2,628.00 | 142.00 | 2,770.00 | CUYD | 1,839.00 | \$14.00 | \$25,746.00 |
| | | 0001 | 0080 | 2063300 | CLASS 4 EXCAVATION | 17.00 | 0.00 | 17.00 | CUYD | 17.00 | \$144.00 | \$2,448.00 |
| | | 0001 | 0090 | 2063500 | CULVERT CLEANOUT | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$1,600.00 | \$0.00 |
| | | 0001 | 0095 | 2065500 | TEMPORARY SHORING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$44,800.00 | \$44,800.00 |
| | | 0001 | 0100 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 1,854.00 | -764.00 | 1,090.00 | SQYD | 406.00 | \$14.00 | \$5,684.00 |
| | | 0001 | 0110 | 3049905 | MISC.OPTIONAL BASE | 3,027.00 | 0.00 | 3,027.00 | SQYD | 3,027.00 | \$14.00 | \$42,378.00 |
| | | 0001 | 0120 | 4019905 | MISC.OPTIONAL PAVEMENT | 3,026.90 | 0.00 | 3,026.90 | SQYD | 3,026.90 | \$105.00 | \$317,824.50 |
| | | 0001 | 0130 | 5021308 | CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. | 762.50 | -762.50 | 0.00 | SQYD | 0.00 | \$105.00 | \$0.00 |
| | | | | | JOINTS) | | | | | | | |
| | | 0001 | 0140 | 5021334 | CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS) | 761.30 | 0.00 | 761.30 | SQYD | 404.10 | \$137.00 | \$55,361.70 |
| | | 0001 | 0150 | 5041000 | CONCRETE APPROACH PAVEMENT | 275.20 | 0.00 | 275.20 | SQYD | 216.00 | \$180.00 | \$38,880.00 |
| | | 0001 | 0160 | 6044011 | PIPE COLLAR, TYPE A | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$1,600.00 | \$1,600.00 |
| | | 0001 | 0170 | 6053030A | PIPE AGGREGATE PAVEMENT EDGE DRAIN | 515.00 | -515.00 | 0.00 | LF | 0.00 | \$36.00 | \$0.00 |
| | | 0001 | 0180 | 6054020 | OUTLET PIPES AND SPLASH PADS | 2.00 | -2.00 | 0.00 | EA | 0.00 | \$1,400.00 | \$0.00 |
| | | 0001 | 0190 | 6081000 | CONCRETE MEDIAN | 2,298.80 | 0.00 | 2,298.80 | SQYD | 0.00 | \$64.00 | \$0.00 |
| | | 0001 | 0200 | 6091011 | CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S | 1,780.00 | 0.00 | 1,780.00 | LF | 0.00 | \$25.00 | \$0.00 |
| | | 0001 | 0210 | 6097000 | ROCK LINING | 127.00 | 97.00 | 224.00 | CUYD | 199.00 | \$136.00 | \$27,064.00 |
| | | 0001 | 0220 | 6113010 | FURNISHING TYPE 1 ROCK BLANKET | 2,429.00 | 0.00 | 2,429.00 | CUYD | 2,421.00 | \$56.00 | \$135,576.00 |
| | | 0001 | 0230 | 6113030 | PLACING TYPE 1 ROCK BLANKET | 2,429.00 | 0.00 | 2,429.00 | CUYD | 2,421.00 | \$22.00 | \$53,262.00 |
| | | 0001 | 0240 | 6122008 | IMPACT ATTENUATOR 40 MPH (SAND BARREL ARRAY) | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$4,500.00 | \$4,500.00 |
| | | 0001 | 0250 | 6122010 | IMPACT ATTENUATOR 50 MPH (SAND BARREL ARRAY) | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$4,500.00 | \$4,500.00 |
| | | 0001 | 0260 | 6122019 | IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY) | 5.00 | 0.00 | 5.00 | EA | 5.00 | \$4,500.00 | \$22,500.00 |
| | | 0001 | 0270 | 6122030 | IMPACT ATTENUATOR (RELOCATION) | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$4,500.00 | \$0.00 |
| | | 0001 | 0280 | 6123000A | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) | 6.00 | 0.00 | 6.00 | EA | 0.00 | \$1,100.00 | \$0.00 |
| | | 0001 | 0290 | 6132018 | FURNISHING AND PLACING CONCRETE MATERIAL FOR | 202.70 | 0.00 | 202.70 | CUYD | 0.00 | \$620.00 | \$0.00 |
| | | 0001 | 0300 | 6139905 | CLASS A PARTIAL DEPTH PAVEMENT REPAIR MISC.RAPID STRENGTH CONCRETE FOR PAVEMENT REPAIR | 321.60 | 0.00 | 321.60 | SQYD | 0.00 | \$170.00 | \$0.00 |
| | | 0001 | 0310 | 6143014 | MANHOLE FRAME AND COVER, TYPE 4 | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$1,200.00 | \$1,200.00 |
| | | 0001 | 0320 | 6161005 | CONSTRUCTION SIGNS | 2,497.00 | 0.00 | 2,497.00 | SQFT | 2,186.10 | \$6.30 | \$13,772.43 |
| | | 0001 | 0330 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 20.00 | 0.00 | 20.00 | EA | 7.00 | \$68.00 | \$476.00 |
| | | 0001 | 0340 | 6161025 | CHANNELIZER (TRIM LINE) | 141.00 | 263.00 | 404.00 | EA | 404.00 | \$19.00 | \$7,676.00 |
| | | | 0350 | 6161030 | TYPE III MOVEABLE BARRICADE | 25.00 | 0.00 | 25.00 | EA | 9.00 | \$170.00 | \$1,530.00 |
| | | 0001 | | | DIRECTIONAL INDICATOR BARRICADE | 68.00 | 0.00 | 68.00 | | 56.00 | \$79.00 | |
| | | 0001 | 0360 | 6161033 | | | | | EA | | | \$4,424.00 |
| | | 0001 | 0370 | 6161040 | FLASHING ARROW PANEL | 5.00 | 0.00 | 5.00 | EA | 3.00 | \$3,400.00 | \$10,200.00 |
| | | 0001 | 0380 | 6161055 | SEQUENTIAL FLASHING WARNING LIGHT | 68.00 | 0.00 | 68.00 | EA | 56.00 | \$68.00 | \$3,808.00 |
| | | 0001 | 0390 | 6161099 | CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 6.00 | 0.00 | 6.00 | EA | 4.00 | \$5,800.00 | \$23,200.00 |
| | | 0001 | 0400 | 6162002 | TEMPORARY LONG-TERM RUMBLE STRIPS | 30.00 | 0.00 | 30.00 | EA | 10.00 | \$1,500.00 | \$15,000.00 |
| | | 0001 | 0410 | 6173103 | CONCRETE TRAFFIC BARRIER, TYPE D (MOMENT SLAB) | 1,233.00 | -515.00 | 718.00 | LF | 213.00 | \$180.00 | \$38,340.00 |
| | | 0001 | 0420 | 6173600D | TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED | 4,723.00 | 866.00 | 5,589.00 | LF | 5,589.00 | \$16.00 | \$89,424.00 |
| | | 0001 | 0430 | 6175010A | RELOCATING TEMPORARY TRAFFIC BARRIER | 9,130.00 | 0.00 | 9,130.00 | LF | 2,301.00 | \$10.00 | \$23,010.00 |
| Revision 3/23/20 | าวว | | | | | | | | | | | Page 6 of 36 |

Page 6 of 36 Revision 3/23/2023



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| | Project | | | | eport Generated date and can differ from the posted ame Description | ount at the | Net | stimate was | Gener Unit | ated. Total | Unit Price | Total Value POSTED |
|-------------------------|---------|----------|-------------|--------------|--|-------------|-----------------|---------------------|---------------|---------------------------|--------------|-------------------------------------|
| Contract Nm.CONTRACT | No. | Category | Line No. | Item Code | Description | Quantity | Change Order | Current Quantity | Offic | Posted Approved Qty | Offit Price | To Date (See report generated date) |
| 230519-C04 | J4P3443 | 0001 | 0440 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | | \$825,000.00 | \$825,000.00 |
| | | 0001 | 0450 | 6181020 | ADDITIONAL MOBILIZATION FOR SEEDING | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$600.00 | \$0.00 |
| | | 0001 | 0460 | 6191000 | PAVEMENT EDGE TREATMENT | 790.00 | 480.00 | 1,270.00 | LF | 1,270.00 | \$6.80 | \$8,636.00 |
| | | 0001 | 0470 | 6200009 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE | 831.00 | 0.00 | 831.00 | LF | 0.00 | \$6.90 | \$0.00 |
| | | 0001 | 0480 | 6200012 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE | 409.00 | 0.00 | 409.00 | LF | 0.00 | \$12.00 | \$0.00 |
| | | 0001 | 0490 | 6200015 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | 196.00 | 0.00 | 196.00 | LF | 0.00 | \$21.00 | \$0.00 |
| | | 0001 | 0500 | 6200021 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | 18.00 | 0.00 | 18.00 | EA | 8.00 | \$340.00 | \$2,720.00 |
| | | 0001 | 0510 | 6200024 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW | 10.00 | 0.00 | 10.00 | EA | 0.00 | \$290.00 | \$0.00 |
| | | 0001 | 0520 | 6200027 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT | 5.00 | 0.00 | 5.00 | EA | 0.00 | \$680.00 | \$0.00 |
| | | 0001 | 0530 | 6200039 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, OFF RAMP WRONG WAY ARROW | 6.00 | 0.00 | 6.00 | EA | 0.00 | \$680.00 | \$0.00 |
| | | 0001 | 0540 | 6200042 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES | 39.00 | 0.00 | 39.00 | EA | 0.00 | \$68.00 | \$0.00 |
| | | 0001 | 0550 | 6205309 | TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE | 228.00 | 0.00 | 228.00 | LF | 96.00 | \$13.00 | \$1,248.00 |
| | | 0001 | 0560 | 6205440A | TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW | 9.00 | 0.00 | 9.00 | EA | 1.00 | \$160.00 | \$160.00 |
| | | 0001 | 0570 | 6205442 | TEMPORARY NON-REMOVABLE MARKING TAPE STRAIGHT ARROW | 3.00 | 4.00 | 7.00 | EA | 7.00 | \$132.00 | \$924.00 |
| | | 0001 | 0580 | 6205443A | TEMPORARY NON-REMOVABLE MARKING TAPE COMBINATION STRAIGHT- LEFT/RIGHT ARROW | 3.00 | 1.00 | 4.00 | EA | 4.00 | \$260.00 | \$1,040.00 |
| | | 0001 | 0590 | 6205902A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 10,103.00 | 0.00 | 10,103.00 | LF | 0.00 | \$0.25 | \$0.00 |
| | | 0001 | 0600 | 6205903A | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 5,838.00 | 0.00 | 5,838.00 | LF | 0.00 | \$0.25 | \$0.00 |
| | | 0001 | 0610 | 6205906A | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 1,394.00 | 0.00 | 1,394.00 | LF | 0.00 | \$0.50 | \$0.00 |
| | | 0001 | 0620 | 6207001 | PAVEMENT MARKING REMOVAL | 27,040.00 | 0.00 | 27,040.00 | LF | 4,815.00 | \$0.60 | \$2,889.00 |
| | | 0001 | 0630 | 6207002 | PAVEMENT MARKING REMOVAL (SYMBOLS) | 15.00 | 0.00 | 15.00 | EA | 4.00 | \$100.00 | \$400.00 |
| | | 0001 | 0640 | 6208076 | 4 IN TEMPORARY PAVEMENT MARKING PAINT | 31,370.00 | 0.00 | 31,370.00 | LF | 26,684.00 | \$0.15 | \$4,002.60 |
| | | 0001 | 0650 | 6240103A | PERMANENT EROSION CONTROL GEOTEXTILE | 3,683.00 | 0.00 | 3,683.00 | SQYD | 3,647.00 | \$3.80 | \$13,858.60 |
| | | 0001 | 0660 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 0.75 | \$100,000.00 | \$75,000.00 |
| | | 0001 | 0670 | 7034041 | CLASS B-1 CONCRETE (CULVERTS) | 43.70 | 10.70 | 54.40 | CUYD | 54.40 | \$1,800.00 | \$97,920.00 |
| | | 0001 | 0680 | 7061030 | REINFORCING STEEL (CULVERTS) | 6,370.00 | 1,960.00 | 8,330.00 | LB | 8,330.00 | \$2.70 | \$22,491.00 |
| | | 0001 | 0690 | 7250318A | 18 IN. PIPE GROUP B | 76.00 | 0.00 | 76.00 | LF | 76.00 | \$106.00 | \$8,056.00 |
| | | 0001 | 0700 | 7261018 | 18 IN. PIPE GROUP A | 805.00 | 0.00 | 805.00 | LF | 112.00 | \$89.00 | \$9,968.00 |
| | | 0001 | 0710 | 7261024 | 24 IN. PIPE GROUP A | 220.00 | 0.00 | 220.00 | LF | 0.00 | \$125.00 | \$0.00 |
| | | 0001 | 0720 | 7261036 | 36 IN. PIPE GROUP A | 103.00 | 0.00 | 103.00 | LF | 103.00 | \$190.00 | \$19,570.00 |
| | | 0001 | 0730 | 7261042 | 42 IN. PIPE GROUP A | 383.00 | 94.00 | 477.00 | LF | 477.00 | \$230.00 | \$109,710.00 |
| | | 0001 | 0735 | 7265442 | JACKED 42 IN. CLASS V REINFORCED CONCRETE PIPE CULVERT (GASKET TYPE) | 66.00 | -66.00 | 0.00 | LF | 0.00 | \$3,000.00 | \$0.00 |
| | | 0001 | 0740 | 7310048 | PRECAST CONCRETE MANHOLE - 48 IN. | 11.00 | 0.00 | 11.00 | FT | 11.00 | \$460.00 | \$5,060.00 |
| | | 0001 | 0750 | 7311033 | PRECAST CONCRETE DROP INLET 3 FT X 3 FT | 8.00 | 0.00 | 8.00 | FT | 0.00 | \$1,000.00 | \$0.00 |
| | | 0001 | 0760 | 7311053 | PRECAST CONCRETE DROP INLET 5 FT X 3 FT | 1.00 | 0.00 | 1.00 | FT | 1.00 | \$6,800.00 | \$6,800.00 |
| | | 0001 | 0770 | 7320018A | 18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$1,900.00 | \$1,900.00 |
| | | 0001 | 0780 | 7320618A | 18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 16.00 | 0.00 | 16.00 | EA | 0.00 | \$1,900.00 | \$0.00 |
| | | 0001 | 0790 | 7320624A | 24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$2,200.00 | \$0.00 |
| | | 0001 | 0800 | 7320636A | 36 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$2,800.00 | \$5,600.00 |
| | | 0001 | 0810 | 7320642A | 42 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$3,600.00 | \$14,400.00 |
| | | 0001 | 0820 | 8025006 | MULCHING | 10.40 | 0.00 | 10.40 | ACRE | 6.00 | \$470.00 | \$2,820.00 |
| | | 0001 | 0830 | 8051000A | SEEDING - COOL SEASON GRASSES | 10.40 | 0.00 | 10.40 | ACRE | 6.00 | \$2,700.00 | \$16,200.00 |
| | | 0001 | 0840 | 8061004 | SEDIMENT TRAP ROCK | 56.20 | 0.00 | 56.20 | CUYD | 7.60 | \$108.00 | \$820.80 |

Page 7 of 36 Revision 3/23/2023



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | eport Generated date and can differ from the posted am Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|----------|-------------|--------------|---|-----------------|------------------------|------------------------|------|-----------------------------|-------------|--|
| 230519-C04 | J4P3443 | 0001 | 0850 | 8061005 | ROCK DITCH CHECK | 1,008.00 | 0.00 | 1,008.00 | LF | Qty 613.00 | \$19.00 | \$11,647.00 |
| | | 0001 | 0860 | 8061007A | CURB INLET CHECK | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$132.00 | \$0.00 |
| | | 0001 | 0870 | 8061016 | SEDIMENT REMOVAL | 262.00 | 0.00 | 262.00 | CUYD | 50.00 | \$27.00 | \$1,350.00 |
| | | 0001 | 0880 | 8061019 | SILT FENCE | 6,862.00 | 0.00 | 6,862.00 | LF | 220.00 | \$1.30 | \$286.00 |
| | | 0001 | 0890 | 8064128 | TYPE 1 TURF REINFORCEMENT MAT | 1,227.00 | 0.00 | 1,227.00 | SQYD | 0.00 | \$3.10 | \$0.00 |
| | | 0001 | 0900 | 8064138 | TYPE 2D EROSION CONTROL BLANKET | 6,262.00 | 0.00 | 6,262.00 | SQYD | 6,903.00 | \$2.40 | \$16,567.20 |
| | | 0003 | 0940 | 3049905 | MISC.ALTERNATE BASE | 20,225.00 | 49.00 | 20,274.00 | SQYD | 19,769.80 | \$12.00 | \$237,237.60 |
| | | 0003 | 0950 | 5021334 | CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. | 18,416.60 | 49.00 | 18,465.60 | SQYD | 17,138.90 | \$98.00 | \$1,679,612.20 |
| | | 0003 | 0960 | 6262000A | JOINTS) PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP | 12.70 | 0.00 | 12.70 | STA | 0.00 | \$700.00 | \$0.00 |
| | | 0005 | 0980 | 5021340 | TYPE A2 SHOULDER | 1,808.20 | 0.00 | 1,808.20 | SQYD | 1,392.10 | \$55.00 | \$76,565.50 |
| | | 0010 | 0990 | 6061061 | MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING | 2,114.00 | 538.00 | 2,652.00 | LF | 0.00 | \$35.00 | \$0.00 |
| | | 0010 | 1000 | 6061069 | MGS BRIDGE APPROACH TRANSITION SECTION | 2.00 | -2.00 | 0.00 | EA | 0.00 | \$4,100.00 | \$0.00 |
| | | 0010 | 1010 | 6061074 | (REGULAR/NO CURB) MGS HEIGHT AND BLOCK TRANSITION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$1,000.00 | \$0.00 |
| | | 0010 | 1020 | 6061080 | MGS END ANCHOR | 6.00 | 2.00 | 8.00 | EA | 0.00 | \$1,400.00 | \$0.00 |
| | | 0010 | 1030 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 7.00 | 0.00 | 7.00 | EA | 0.00 | \$3,400.00 | \$0.00 |
| | | 0010 | 1040 | 6064500 | AGGREGATE BEDDING FOR 3 - STRAND GUARD CABLE | 31.00 | 0.00 | 31.00 | CUYD | 0.00 | \$125.00 | \$0.00 |
| | | 0010 | 1050 | 6069902 | MISC.HTGC ANCHOR ASSEMBLY | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$5,400.00 | \$0.00 |
| | | 0010 | 1060 | 6069903 | MISC.HIGH TENSION GUARD CABLE | 410.00 | 0.00 | 410.00 | LF | 0.00 | \$39.00 | \$0.00 |
| | | 0010 | 1070 | 6240104A | SEPARATION GEOTEXTILE | 274.00 | 0.00 | 274.00 | SQYD | 0.00 | \$5.10 | \$0.00 |
| | | 0020 | 1080 | 9011062 | LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2 | 16.00 | 0.00 | 16.00 | EA | 0.00 | \$3,200.00 | \$0.00 |
| | | 0020 | 1090 | 9011115 | BRACKET ARM, 15 FT. OR 4.6 M | 16.00 | 0.00 | 16.00 | EA | 0.00 | \$1,500.00 | \$0.00 |
| | | 0020 | 1100 | 9011312 | LUMINAIRE, LED-B | 16.00 | 0.00 | 16.00 | EA | 0.00 | \$840.00 | \$0.00 |
| | | 0020 | 1110 | 9012230 | BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$9,000.00 | \$0.00 |
| | | 0020 | 1120 | 9013002 | CONDUIT, 2 IN. RIGID, IN TRENCH | 460.00 | 0.00 | 460.00 | LF | 77.00 | \$23.00 | \$1,771.00 |
| | | 0020 | 1130 | 9014004 | CONDUIT, 4 IN. RIGID, PUSHED | 527.00 | 0.00 | 527.00 | LF | 405.00 | \$35.00 | \$14,175.00 |
| | | 0020 | 1140 | 9015010 | TRENCHING TYPE I | 5,804.00 | 0.00 | 5,804.00 | LF | 0.00 | \$11.00 | \$0.00 |
| | | 0020 | 1150 | 9016110 | PULL BOX, PREFORMED CLASS 1 | 5.00 | 0.00 | 5.00 | EA | 0.00 | \$2,500.00 | \$0.00 |
| | | 0020 | 1160 | 9016112 | PULL BOX, PREFORMED CLASS 3 | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$4,800.00 | \$0.00 |
| | | 0020 | 1170 | 9017002 | CABLE, 2 AWG 1 CONDUCTOR | 810.00 | 0.00 | 810.00 | LF | 0.00 | \$5.30 | \$0.00 |
| | | 0020 | 1180 | 9017110 | CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET | 1,920.00 | 0.00 | 1,920.00 | LF | 0.00 | \$2.40 | \$0.00 |
| | | 0020 | 1190 | 9017407 | CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE | 5,780.00 | 0.00 | 5,780.00 | LF | 0.00 | \$4.80 | \$0.00 |
| | | 0020 | 1200 | 9018245 | NEUTRAL, 8 AWG POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT) | 16.00 | 0.00 | 16.00 | EA | 0.00 | \$3,200.00 | \$0.00 |
| | | 0020 | 1210 | 9018612 | POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE. | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$8,100.00 | \$0.00 |
| | | | | | LIGHTING ONLY | | | | | | | |
| | | 0030 | 1220 | 9020113 | SIGNAL HEAD, TYPE 3T | 5.00 | 0.00 | 5.00 | EA | 0.00 | \$1,300.00 | \$0.00 |
| | | 0030 | 1230 | 9020213 | SIGNAL HEAD, TYPE 3S | 5.00 | 0.00 | 5.00 | EA | 0.00 | \$1,300.00 | \$0.00 |
| | | 0030 | 1240 | 9020513 | SIGNAL HEAD, TYPE 3B | 8.00 | 0.00 | 8.00 | EA | 0.00 | \$1,500.00 | \$0.00 |
| | | 0030 | 1250 | 9020833 | SH-FLAT SHEET - SIGNAL SIGN | 60.00 | 0.00 | 60.00 | SQFT | 0.00 | \$66.00 | \$0.00 |
| | | 0030 | 1260 | 9020834 | SIGNAL SIGN, MOUNTING HARDWARE | 8.00 | 0.00 | 8.00 | EA | 0.00 | \$380.00 | \$0.00 |
| | | 0030 | 1270 | 9022651 | LUMINAIRE LED-A, 120 VOLT COMPATIBLE | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$680.00 | \$0.00 |
| | | 0030 | 1280 | 9022715 | POST, SIGNAL 15 FT. | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$1,900.00 | \$0.00 |
| | | 0030 | 1290 | 9023115 | POST, TYPE CL. 20 ET ARM OR 4.6 M ARM | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$9,700.00 | \$0.00 |
| | | 0030 | 1300 | 9023120 | POST, TYPE CL, 20 FT. ARM OR 6.1 M ARM | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$11,800.00 | \$0.00 |
| | | 0030 | 1310 | 9023130 | POST, TYPE CL. 36 FT. ARM OR 9.1 M ARM | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$14,900.00 | \$0.00 |
| | | 0030 | 1320 | 9023135 | POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM | 1.00 | | 1.00 | EA | 0.00 | \$15,600.00 | \$0.00 |
| | | 0030 | 1330 | 9023215 | POST, TYPE C, 15 FT. ARM OR 4.6 M ARM | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$9,300.00 | \$0.00 |

Page 8 of 36 Revision 3/23/2023



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | es are b Line No. | Item Code | eport Generated date and can differ from the posted am Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|----------|-------------------------|--------------|--|-----------------|------------------------|------------------------|----------|-----------------------|-------------------|--|
| 020540 001 | MEG | | 4040 | 0000000 | DOCT TYPE C 20 FT ADM OD 24 MAD. | | | | | Qty | 040 400 00 | |
| 230519-C04 | J4P3443 | 0030 | 1340 | 9023230 | POST, TYPE C, 30 FT. ARM OR 9.1 M ARM | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$12,400.00 | \$0.00 |
| | | 0030 | 1350 | 9024975 | VIDEO DETECTION SYSTEM | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$71,500.00 | \$0.00 |
| | | 0030 | 1360 | 9025300 | CONDUIT, 3 IN., TRENCH WITH TRACER WIRE | 789.00 | 0.00 | 789.00 | LF | 211.00 | \$34.00 | \$7,174.00 |
| | | 0030 | 1370 | 9025400 | CONDUIT, 4 IN., TRENCH WITH TRACER WIRE | 137.00 | 0.00 | 137.00 | LF LF | 0.00 | \$45.00 | \$0.00 |
| | | 0030 | 1380 | 9027300 | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE CONDUIT. 4 IN., PUSHED WITH TRACER WIRE | 115.00 | 0.00 | 115.00 | LF | 0.00 | \$49.00 | \$0.00 |
| | | 0030 | 1390 | 9027400 | CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET | 193.00 | 0.00 | 193.00 | LF | 214.00 | \$44.00 \$2.70 | \$9,416.00 |
| | | 0030 | | | CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET | | | | | | | \$0.00 |
| | | 0030 | 1410 | 9028202 | CABLE, 12 AWG 1 CONDUCTOR CABLE, 12 AWG 2 CONDUCTOR | 490.00 | 0.00 | 490.00 | LF LF | 0.00 | \$5.40 | \$0.00 |
| | | 0030 | 1420 | | | 1,260.00 | 0.00 | 1,260.00 | | | \$5.30 | \$0.00 |
| | | 0030 | 1430 | 9028311 | CABLE, 16 AWG 7 CONDUCTOR | 10,050.00 | 0.00 | 10,050.00 | LF | 0.00 | \$3.30 | \$0.00 |
| | | 0030 | 1440 | 9028811 | PULL BOX, PREFORMED CLASS 2 | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$3,400.00 | \$0.00 |
| | | 0030 | 1450 | 9028812 | PULL BOX, PREFORMED CLASS 3 | 6.00 | 0.00 | 6.00 | EA | 0.00 | \$4,900.00 | \$0.00 |
| | | 0030 | 1460 | 9029100 | BASE, CONCRETE | 21.40 | 0.00 | 21.40 | CUYD | 0.00 | \$2,700.00 | \$0.00 |
| | | 0030 | 1470 | 9029401 | TEMPORARY TRAFFIC SIGNALS AND LIGHTING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$236,000.00 | \$236,000.00 |
| | | 0040 | 1480 | 9031020 | CONCRETE FOOTINGS, BOLT DOWN | 7.30 | 0.00 | 7.30 | CUYD | 0.00 | \$1,300.00 | \$0.00 |
| | | 0040 | 1490 | 9031210 | STRUCTURAL STEEL POSTS | 4,640.00 | 0.00 | 4,640.00 | LB | 0.00 | \$5.30 | \$0.00 |
| | | 0040 | 1500 | 9031241 | BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE) | 8.00 | 0.00 | 8.00 | EA | 0.00 | \$420.00 | \$0.00 |
| | | 0040 | 1510 | 9031270A | 2 IN. PSST POST - 12 GA. | 624.00 | 0.00 | 624.00 | LF | 0.00 | \$21.00 | \$0.00 |
| | | 0040 | 1520 | 9031271A | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. | 39.00 | 0.00 | 39.00 | EA | 0.00 | \$84.00 | \$0.00 |
| | | 0040 | 1530 | 9031272A | 2.25 IN. PSST POST INSERT (6 FT.) - 12 GA. | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$137.00 | \$0.00 |
| | | 0040 | 1540 | 9031280 | 2.5 IN. PSST POST - 12 GA. | 192.00 | 0.00 | 192.00 | LF | 0.00 | \$24.00 | \$0.00 |
| | | 0040 | 1550 | 9031281A | DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA. | 12.00 | 0.00 | 12.00 | EA | 0.00 | \$105.00 | \$0.00 |
| | | 0040 | 1560 | 9035004A | SH-FLAT SHEET | 365.00 | 0.00 | 365.00 | SQFT | 0.00 | \$21.00 | \$0.00 |
| | | 0040 | 1570 | 9035011A | ST-STRUCTURAL | 756.00 | 0.00 | 756.00 | SQFT | 0.00 | \$32.00 | \$0.00 |
| | | 0040 | 1580 | 9035069A | SHF-FLAT SHEET FLUORESCENT | 116.00 | 0.00 | 116.00 | SQFT | 0.00 | \$24.00 | \$0.00 |
| | | 0040 | 1590 | 9039901 | MISC.NB ON RAMP TRUSS #48 | 1.00 | 0.00 | 1.00 | LS | 0.25 | \$136,800.00 | \$34,200.00 |
| | | 0040 | 1600 | 9039901 | MISC.NEW TRUSS SIGNS ON EXISTING TRUSS #45 | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$13,200.00 | \$0.00 |
| | | 0040 | 1610 | 9039901 | MISC.SB AT EXIT 158 TRUSS #41 | 1.00 | 0.00 | 1.00 | LS | 0.25 | \$136,800.00 | \$34,200.00 |
| | | 0040 | 1620 | 9039901 | MISC.SB OFF RAMP CANT. TRUSS #42 | 1.00 | 0.00 | 1.00 | LS | 0.25 | \$89,500.00 | \$22,375.00 |
| | | 0040 | 1630 | 9039901 | MISC.TUBULAR SUPPORT, TYPE S-1310, TRUSS #43 | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$52,600.00 | \$0.00 |
| | | 0050 | 1640 | 9105200 | CONDUIT, 2 IN., RIGID, IN TRENCH | 1,384.00 | 0.00 | 1,384.00 | LF | 1,155.00 | \$20.00 | \$23,100.00 |
| | | 0050 | 1650 | 9107202 | CONDUIT, 4 IN., RIGID, PUSHED | 284.00 | 0.00 | 284.00 | LF | 284.00 | \$51.00 | \$14,484.00 |
| | | 0050 | 1660 | 9108202 | CABLE, 2 AWG, 1 CONDUCTOR, POWER | 210.00 | 0.00 | 210.00 | LF | 0.00 | \$5.30 | \$0.00 |
| | | 0050 | 1670 | 9108353 | FIBER OPTIC CABLE, 12-STRAND, SINGLE MODE | 1,880.00 | 0.00 | 1,880.00 | LF | 0.00 | \$8.40 | \$0.00 |
| | | 0050 | 1680 | 9108811 | PULL BOX, PREFORMED CLASS 2 | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$3,500.00 | \$3,500.00 |
| | | 0050 | 1690 | 9108816 | PULL BOX, PREFORMED CLASS 5 | 8.00 | 0.00 | 8.00 | EA | 0.00 | \$4,000.00 | \$0.00 |
| | | 0050 | 1700 | 9109901 | MISC.FIBER OPTIC SPLICING, TESTING AND DOCUMENTATION | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$13,100.00 | \$0.00 |
| | | 0050 | 1710 | 9109901 | MISC.RELOCATE SCOUT CAMERA POLE | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$27,900.00 | \$27,900.00 |
| | | 0050 | 1720 | 9109901 | MISC.SALVAGING EXISTING ITS EQUIPMENT | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$760.00 | \$0.00 |
| | | 0050 | 1730 | 9109902 | MISC.FIBER MEDIA CONVERTER | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$610.00 | \$0.00 |
| | | 0050 | 1740 | 9109902 | MISC.SCOUT FIBER SPLICE VAULT | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$7,200.00 | \$7,200.00 |
| | | 0070 | 1750 | 2061000 | CLASS 1 EXCAVATION | 123.00 | 22.00 | 145.00 | CUYD | 145.00 | \$88.00 | \$12,760.00 |
| | | 0070 | 1760 | 2061003 | CLASS 1 EXCAVATION IN ROCK | 22.00 | -22.00 | 0.00 | CUYD | 0.00 | \$520.00 | \$0.00 |
| | | 0070 | 1770 | 2160500 | REMOVAL OF BRIDGES | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$108,800.00 | \$0.00 |
| | | 0070 | 1780 | 5031010A | BRIDGE APPROACH SLAB (MAJOR) | 128.00 | 0.00 | 128.00 | SQYD | 128.00 | \$340.00 | \$43,520.00 |
| | | 0070 | 1790 | 7021212 | GALVANIZED STRUCTURAL STEEL PILES (12 IN) | 325.00 | 25.00 | 350.00 | LF | 350.00 | \$120.00 | \$42,000.00 |
| Revision 3/23/20 | 200 | | | | | | | | | | | Page 9 of 36 |

Page 9 of 36 Revision 3/23/2023



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|-------------|-------------|---------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 230519-C04 | J4P3443 | 0070 | 1800 | 7026000 | PRE-BORE FOR PILING | 215.00 | 0.00 | 215.00 | LF | 215.00 | \$34.00 | \$7,310.00 |
| | | 0070 | 1810 | 7027000 | PILE POINT REINFORCEMENT | 10.00 | 0.00 | 10.00 | EA | 10.00 | \$135.00 | \$1,350.00 |
| | | 0070 | 1820 | 7032003 | CLASS B CONCRETE (SUBSTRUCTURE) | 89.80 | 0.00 | 89.80 | CUYD | 89.80 | \$1,300.00 | \$116,740.00 |
| | | 0070 | 1830 | 7034219A | TYPE D BARRIER | 487.00 | 0.00 | 487.00 | LF | 0.00 | \$250.00 | \$0.00 |
| | | 0070 | 1840 | 7034221 | SLAB ON CONCRETE NU-GIRDER | 664.00 | 0.00 | 664.00 | SQYD | 664.00 | \$460.00 | \$305,440.00 |
| | | 0070 | 1850 | 7034620 | FORM LINERS | 179.00 | 0.00 | 179.00 | SQYD | 179.00 | \$79.00 | \$14,141.00 |
| | | 0070 | 1860 | 7039902 | MISC.Cast Stone Sign | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$8,900.00 | \$0.00 |
| | | 0070 | 1870 | 7056022 | NU 43, PRESTRESSED CONCRETE NU-GIRDER | 621.00 | 0.00 | 621.00 | LF | 621.00 | \$510.00 | \$316,710.00 |
| | | 0070 | 1880 | 7101000 | REINFORCING STEEL (EPOXY COATED) | 10,970.00 | 0.00 | 10,970.00 | LB | 10,970.00 | \$2.10 | \$23,037.00 |
| | | 0070 | 1890 | 7123610 | SLAB DRAIN | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$890.00 | \$1,780.00 |
| | | 0070 | 1900 | 7151001 | VERTICAL DRAIN AT END BENTS | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,900.00 | \$3,800.00 |
| | | 0070 | 1910 | 7161000 | PLAIN NEOPRENE BEARING PAD | 3.00 | 0.00 | 3.00 | EA | 3.00 | \$370.00 | \$1,110.00 |
| | | 0070 | 1920 | 7161002 | LAMINATED NEOPRENE BEARING PAD | 6.00 | 0.00 | 6.00 | EA | 6.00 | \$420.00 | \$2,520.00 |
| | | 0070 | 1930 | 7161003 | LAMINATED NEOPRENE BEARING PAD (TAPERED) | 3.00 | 0.00 | 3.00 | EA | 3.00 | \$630.00 | \$1,890.00 |
| | | 0071 | 1940 | 2061000 | CLASS 1 EXCAVATION | 158.00 | 33.00 | 191.00 | CUYD | 191.00 | \$88.00 | \$16,808.00 |
| | | 0071 | 1950 | 2061003 | CLASS 1 EXCAVATION IN ROCK | 33.00 | -33.00 | 0.00 | CUYD | 0.00 | \$440.00 | \$0.00 |
| | | 0071 | 1960 | 5031010A | BRIDGE APPROACH SLAB (MAJOR) | 168.00 | 0.00 | 168.00 | SQYD | 168.00 | \$320.00 | \$53,760.00 |
| | | 0071 | 1970 | 7021212 | GALVANIZED STRUCTURAL STEEL PILES (12 IN) | 402.00 | 74.00 | 476.00 | LF | 476.00 | \$120.00 | \$57,120.00 |
| | | 0071 | 1980 | 7026000 | PRE-BORE FOR PILING | 312.00 | 0.00 | 312.00 | LF | 312.00 | \$27.00 | \$8,424.00 |
| | | 0071 | 1990 | 7027000 | PILE POINT REINFORCEMENT | 12.00 | 0.00 | 12.00 | EA | 12.00 | \$135.00 | \$1,620.00 |
| | | 0071 | 2000 | 7032003 | CLASS B CONCRETE (SUBSTRUCTURE) | 123.60 | 0.00 | 123.60 | CUYD | 123.60 | \$1,000.00 | \$123,600.00 |
| | | 0071 | 2010 | 7034219A | TYPE D BARRIER | 479.00 | 0.00 | 479.00 | LF | 479.00 | \$250.00 | \$119,750.00 |
| | | 0071 | 2020 | 7034221 | SLAB ON CONCRETE NU-GIRDER | 838.00 | 0.00 | 838.00 | SQYD | 838.00 | \$450.00 | \$377,100.00 |
| | | 0071 | 2030 | 7034620 | FORM LINERS | 179.00 | 0.00 | 179.00 | SQYD | 179.00 | \$79.00 | \$14,141.00 |
| | | 0071 | 2040 | 7039902 | MISC.Cast Stone Sign | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$8,900.00 | \$8,900.00 |
| | | 0071 | 2050 | 7056022 | NU 43, PRESTRESSED CONCRETE NU-GIRDER | 828.00 | 0.00 | 828.00 | LF | 828.00 | \$510.00 | \$422,280.00 |
| | | 0071 | 2060 | 7071000 | CONDUIT SYSTEM ON STRUCTURE | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$27,500.00 | \$27,500.00 |
| | | 0071 | 2070 | 7101000 | REINFORCING STEEL (EPOXY COATED) | 15,520.00 | 0.00 | 15,520.00 | LB | 15,520.00 | \$2.10 | \$32,592.00 |
| | | 0071 | 2080 | 7123610 | SLAB DRAIN | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$890.00 | \$1,780.00 |
| | | 0071 | 2090 | 7151001 | VERTICAL DRAIN AT END BENTS | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,900.00 | \$3,800.00 |
| | | 0071 | 2100 | 7161000 | PLAIN NEOPRENE BEARING PAD | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$370.00 | \$1,480.00 |
| | | 0071 | 2110 | 7161002 | LAMINATED NEOPRENE BEARING PAD | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$420.00 | \$3,360.00 |
| | | 0071 | 2120 | 7161003 | LAMINATED NEOPRENE BEARING PAD (TAPERED) | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$630.00 | \$2,520.00 |
| | | 0001 | 5001 | 7310072 | PRECAST CONCRETE MANHOLE - 72 IN. | 0.00 | 26.00 | 26.00 | FT | 26.00 | \$500.77 | \$13,020.02 |
| | | 0001 | 5002 | 8061020 | TEMPORARY PIPE | 0.00 | 60.00 | 60.00 | LF | 60.00 | \$120.00 | \$7,200.00 |
| | | 0001 | 5003 | 7269902 | MISC.RIGID PIPE CULVERT DESIGN COSTS | 0.00 | 1.00 | 1.00 | EA | 1.00 | \$8,000.00 | \$8,000.00 |
| | | 0001 | 5004 | 1046002 | VALUE ENGINEERING | 0.00 | 73,085.99 | 73,085.99 | EA | 73,085.99 | \$1.00 | \$73,085.99 |
| | | 0001 | 5005 | 6122020 | REPLACEMENT SAND BARREL | 0.00 | 3.00 | 3.00 | EA | 3.00 | \$1,575.00 | \$4,725.00 |
| | | 0001 | 5006 | 8061020 | TEMPORARY PIPE | 0.00 | 80.00 | 80.00 | LF | 80.00 | \$42.78 | \$3,422.40 |
| | | 0001 | 5007 | 1046002 | VALUE ENGINEERING | 0.00 | 48,329.63 | 48,329.63 | EA | 48,329.63 | \$1.00 | \$48,329.63 |
| | | 0030 | 5008 | 9029901 | MISC.SIGNAL CONTROLLER INSTALLATION | 0.00 | 1.00 | 1.00 | LS | 0.00 | \$4,347.00 | \$0.00 |
| | | 0010 | 5009 | 6066610 | END ANCHOR | 0.00 | 1.00 | 1.00 | EA | 0.00 | \$1,980.00 | \$0.00 |
| | | 0001 | 5010 | 6205301B | TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE | 0.00 | 4,344.00 | 4,344.00 | LF | 4,344.00 | \$2.20 | \$9,556.80 |
| | | 0001 | 5011 | 6205303B | TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW | 0.00 | 960.00 | 960.00 | LF | 960.00 | \$2.20 | \$2,112.00 |
| | Project J | 4P3443 - To | otal Value | Posted to D | Date as of Report Generated Date | | | | | | | \$8,132,877.47 |
| 230519-C04 Ove | rall - Total | Value Post | ted to Dat | te as of Repo | ort Generated Date | | | | | | | \$8,132,877.47 |

Revision 3/23/2023 Page 10 of 36



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4P3443

| Line | Item | Description | DWR | DWR | Quantity | Units | Location | From | Offset/ | То | Offset/ | Comments |
|--------|----------|--|---------|------------------|----------|-------|--|----------------------|----------|----------------------|----------|----------|
| Number | Code | | Date | Approval Date | Posted | | | Station/ Log Mile | Distance | Station/ Log Mile | Distance | |
| 0110 | 3049905 | MISC. AGGREGATE FOR BASE | 1/31/24 | 2/2/24 | 173.30 | SQYD | Correcting pay quantity for Phase 1B | | | | | |
| | | | | 2/2/24 | 325.40 | SQYD | Phase 1C Temp Pavement | | | | | |
| | | | | 2/2/24 | 381.50 | SQYD | Phase 2 Temp Pavement | | | | | |
| 0120 | 4019905 | MISC. | 1/31/24 | 2/2/24 | -488.90 | SQYD | Correcting temp pavement quantity for Phase 1B | | | | | |
| | | | | 2/2/24 | 173.20 | SQYD | Correcting pay quantity for Phase 1B | | | | | |
| | | | | 2/2/24 | 325.40 | SQYD | Phase 1C Temp Pavement | | | | | |
| | | | | 2/2/24 | 381.50 | SQYD | Phase 2 Temp Pavement | | | | | |
| 0210 | 6097000 | ROCK LINING | 1/29/24 | 1/30/24 | 40.00 | CUYD | Ramp 1 | 5+75 | LT | | | |
| | | | | 1/30/24 | 57.00 | CUYD | Ramp 1 | 7+50 | LT | | | |
| 0940 | 3049905 | MISC. AGGREGATE FOR BASE | 1/31/24 | 2/2/24 | 1,832.00 | SQYD | SB MO-7 | 15+71.02 | LT/RT | 20+31.63 | LT/RT | |
| 0950 | 5021334 | CONCRETE PAVEMENT (10 1/2 IN. NON-REINF, | 1/31/24 | 2/2/24 | 916.00 | SQYD | SB MO-7 | 15+71.02 | LT | 20+31.63 | LT | |
| | | | | 2/2/24 | 996.70 | SQYD | Ramp 4 | 0+00 | LT/RT | 5+40 | LT/RT | |
| 1590 | 9039901 | MISC. HIGHWAY SIGNING | 1/31/24 | 2/2/24 | 0.25 | LS | NB I-49 | 1085+25 | LT/RT | | | |
| 1610 | 9039901 | MISC. HIGHWAY SIGNING | 1/31/24 | 2/2/24 | 0.25 | LS | SB I-49 | 24.9 | LT/RT | | | |
| 1620 | 9039901 | MISC. HIGHWAY SIGNING | 1/31/24 | 2/2/24 | 0.25 | LS | SB I-49 Off Ramp to MO-7 | 1088+72 | RT | | | |
| 5010 | 6205301B | TEMPORARY REMOVABLE MARKING TAPE 4 IN., | 1/25/24 | 1/29/24 | 4,344.00 | LF | Phase 1, 2, and 3 temporary striping | | | | | |
| 5011 | 6205303B | TEMPORARY REMOVABLE MARKING TAPE | 1/25/24 | 1/29/24 | 960.00 | LF | Phase 1, 2, and 3 temporary striping | | | | | |

| Project | Line Number | DWR Date | Total Quantity Posted For DWR Date | Sign Information | Station | Log Mile | Location | Number of Items | SF Each Sign | Special Sign | SF Each Special Sign | Total SF to Post | | | | | |
|---------|----------------|----------------|---------------------------------------|--|---------|-------------|----------------------|---|---|---------------------|--|---------------------|--------|---------|------|-------|----|
| P3443 | | July 25, 2023 | 218 | EO5-1 36x48 12.00 GORE EXIT | | 157.255 | NB I-49 | 1.00 | 12.00 | | 2.911 | 12.0 | | | | | |
| | | | | R2-1 36x48 12.00 SPEED LIMIT XX | | 156.91 | NB I-49 | 2.00 | 12.00 | | | 24.0 | | | | | |
| | | | | GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE) | | 156.91 | NB I-49 | 2.00 | 6.00 | | | 12.0 | | | | | |
| | | | | WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED | | 156.71 | NB I-49 | 1.00 | 16.00 | | | 16.0 | | | | | |
| | | | | CONST-5 96x48 32.00 POINT OF PRESENCE | | 155.42 | NB I-49 | 1.00 | 32.00 | | | 32.0 | | | | | |
| | | | | WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD | | 156.41 | NB I-49 | 2.00 | 16.00 | | | 32. | | | | | |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 155.887 | NB I-49 | 2.00 | 16.00 | | | 32. | | | | | |
| | | | | CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE | | 155.71 | NB I-49 | 2.00 | 12.00 | | | 24. | | | | | |
| | | | | CONST-7 72x36 18.00 RATE OUR WORK ZONE | | 155.611 | NB I-49 | 1.00 | 18.00 | | | 18. | | | | | |
| | | | | WO4-1aL 48x48 16.00 MERGE (ARROW SYMBOL) | | 156.71 | NB I-49 | 1.00 | 16.00 | | | 16. | | | | | |
| | | July 26, 2023 | 470 | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 146.183 | MO-7 N | 2.00 | 16.00 | | | 32. | | | | | |
| | | | | CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE | | 145.847 | MO-7 N | 2.00 | 12.00 | | | 24. | | | | | |
| | | | | CONST-7 72x36 18.00 RATE OUR WORK ZONE | | 145.745 | MO-7 N | 1.00 | 18.00 | | | 18. | | | | | |
| | | | | CONST-5 96x48 32.00 POINT OF PRESENCE | | 145.647 | MO-7 N | 1.00 | 32.00 | | | 32. | | | | | |
| | | | | WO21-5 48x48 16.00 SHOULDER WORK AHEAD | | 1.463 | EB 275th | 1.00 | 16.00 | | | 16 | | | | | |
| | | | | CONST-5 96x48 32.00 POINT OF PRESENCE | | 1.409 | EB 275th | 1.00 | 32.00 | | | 32 | | | | | |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 1.158 | EB 275th | 1.00 | 16.00 | | | 16 | | | | | |
| | | | | CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE | | 0.946 | EB 275th | 1.00 | 12.00 | | | 12 | | | | | |
| | | | | CONST-7 72x36 18.00 RATE OUR WORK ZONE | | 0.831 | EB 275th | 1.00 | 18.00 | | | 18 | | | | | |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 0.0 | NB Brookhart | 1.00 | 16.00 | | | 16 | | | | | |
| | | | | WO21-5 48x48 16.00 SHOULDER WORK AHEAD | | 146.491 | MO-7 N | 1.00 | 16.00 | | | 16 | | | | | |
| | | | | WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD | | | SB I-49 | 2.00 | 16.00 | | | 32 | | | | | |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | | SB I-49 | 2.00 | 16.00 | | | 32 | | | | | |
| | | | | R2-1 36x48 12.00 SPEED LIMIT XX | | | SB I-49 | 2.00 | 12.00 | | | 24 | | | | | |
| | | | | GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE) | | | SB I-49 | 2.00 | 6.00 | | | 12 | | | | | |
| | | | | WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED | | | SB I-49 | 1.00 | 16.00 | | | 16 | | | | | |
| | | | | | | | | | WO4-1aR 48x48 16.00 MERGE (ARROW SYMBOL) | | | SB I-49 | 1.00 | 16.00 | | | 16 |
| | | | | | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 25.302 | SB I-49 | 2.00 | 16.00 | | | 32 | |
| | | | | | | | | | | | CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE | | 25.197 | SB I-49 | 2.00 | 12.00 | |
| | | | | CONST-7 72x36 18.00 RATE OUR WORK ZONE | | 25.093 | SB I-49 | 1.00 | 18.00 | | | 18 | | | | | |
| | | | | CONST-5 96x48 32.00 POINT OF PRESENCE | | 24.846 | SB I-49 | 1.00 | 32.00 | | | 32 | | | | | |
| | | August 8, 2023 | 16 | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 0.109 | MO-2 RAMP TO SB I-49 | 1.00 | 16.00 | | | 16 | | | | | |
| | | | 32 | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 156.279 | NB I-49 | 32.00 | 1.00 | RUMBLE STRIPS AHEAD | | 32 | | | | | |
| | | | 157 | R11-2 48x30 10.00 ROAD CLOSED | | 146.474 | MO-7 N | 1.00 | 10.00 | | | 10 | | | | | |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 146.447 | MO-7 N | 17.00 | 1.00 | DETOUR N 49 ARROW | | 17. | | | | | |
| | | | | WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED | | 146.184 | MO-7 N | 1.00 | 16.00 | | | 16. | | | | | |

Revision 3/23/2023 Page 11 of 36



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

| able). |
|--------|
| |
| |

| | | iow tino inic arc | details for Construction Si | giis (ii applicable). | | | | | | | | |
|--------|----------------|----------------------|---------------------------------------|--|---------|----------------|----------------------------------|--------------------|-----------------|--|-------------------------|---------------------|
| roject | Line Number | DWR Date | Total Quantity Posted For DWR Date | Sign Information | Station | Log Mile | Location | Number of Items | SF Each Sign | Special Sign | SF Each Special Sign | Total SF to Post |
| P3443 | 0320 | August 8, 2023 | 157 | WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD | | 146.045 | MO-7 N | 2.00 | 16.00 | | | 32.00 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 145.981 | MO-7 N | 32.00 | 1.00 | RUMBLE STRIPS AHEAD | 16.00 | 32.00 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 146.518 | MO-7 N | 17.00 | 1.00 | DETOUR N 49 ARROW 50B | | 17.00 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 146.563 | MO-7 N | 17.00 | 1.00 | DETOUR N 49 ARROW 50C | | 17.00 |
| | | | | WO4-1aL 48x48 16.00 MERGE (ARROW SYMBOL) | | 146.184 | MO-7 N | 1.00 | 16.00 | | | 16.00 |
| | | August 14, 2023 | 16 | WO5-1 48x48 16.00 | 1+00 | | Ramp 1 to NB I-49 | 1.00 | 16.00 | | | 16.00 |
| | | September 14, | 148 | ROAD/BRIDGE/RAMP NARROWS WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 1.894 | SB Orchard Rd | 1.00 | 16.00 | | | 16.00 |
| | | 2023 | | WO1-4L 48x48 16.00 REVERSE | | 146.326 | MO-7 N | 1.00 | 16.00 | | | 16.00 |
| | | | | CURVE (SYMBOL LEFT ARROW) WO4-1R 48x48 16.00 MERGE (SYMBOL FROM RIGHT) | | 146.477 | MO-7 N | 1.00 | 16.00 | | | 16.00 |
| | | | | WO3-3 48x48 16.00 SIGNAL AHEAD (SYMBOL) | | 146.521 | MO-7 N | 1.00 | 16.00 | | | 16.0 |
| | | | | WO5-1 48x48 16.00 | | 26.142 | SB I-49 | 1.00 | 16.00 | | | 16.0 |
| | | | | ROAD/BRIDGE/RAMP NARROWS WO13-1 30x30 6.25 ADVISORY | | 26.142 | SB I-49 | 1.00 | 6.25 | | | 6.2 |
| | | | | SPEED (PLAQUE) WO1-4R 48x48 16.00 REVERSE | | 40.058 | MO-7 S | 1.00 | 16.00 | | | 16.0 |
| | | | | CURVE (SYMBOL RIGHT ARROW) WO1-4L 48x48 16.00 REVERSE | | 40.212 | MO-7 S | 1.00 | 16.00 | | | 16.0 |
| | | | | CURVE (SYMBOL LEFT ARROW) R10-6 24x36 6.00 STOP HERE | | | MO-7 N, MO-7 S, Ramp 2 | 5.00 | 6.00 | | | 30.0 |
| | | September 21, | 58 | ON RED (45 DEGREE ARROW WO1-4L 48x48 16.00 REVERSE | | | NB I-49 | 1.00 | 16.00 | | | 16.0 |
| | | 2023 | | CURVE (SYMBOL LEFT ARROW) R11-2 48x30 10.00 ROAD | 24+00 | | MO-7 N | 1.00 | 10.00 | | | 10.0 |
| | | | | CLOSED Variable ??x?? 1.00 SPECIAL SIGN | | | | 16.00 | 1.00 | Added Lane | | 16.0 |
| | | | | BY QUANTITY OF SQUARE FEET WO1-4R 48x48 16.00 REVERSE | | | NB I-49 | 1.00 | 16.00 | | | 16.0 |
| | | October 23, 2023 | 262 | CURVE (SYMBOL RIGHT ARROW) Variable ??x?? 1.00 SPECIAL SIGN | | 2.439 | EB 299th St | 27.70 | 1.00 | 50Q, Detour 49 | | 27.7 |
| | | 00.0001 20, 2020 | | BY QUANTITY OF SQUARE FEET Variable ??x?? 1.00 SPECIAL SIGN | | 2.472 | SB Outer Rd | 29.70 | 1.00 | 50A, Detour N 49 | | 29.7 |
| | | | | BY QUANTITY OF SQUARE FEET W020-2 48x48 16.00 DETOUR | | 1.556 | SB Brookhart Dr | 1.00 | 16.00 | 001, 500011140 | | 16.0 |
| | | | | AHEAD Variable ??x?? 1.00 SPECIAL SIGN | | 1.486 | EB 289th St | 27.70 | 1.00 | 50Q, Detour 49 | | 27.7 |
| | | | | BY QUANTITY OF SQUARE FEET W020-2 48x48 16.00 DETOUR | | 1.045 | EB 275th St | 1.00 | 16.00 | Jou, Detour 49 | | 16.0 |
| | | | | AHEAD | | | | | | 500 Determ 40 | | |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET Variable ??x?? 1.00 SPECIAL SIGN | | 0.816 3.609 | EB 283rd St SB Outer Rd | 27.70 | 1.00 | 50Q, Detour 49 50A. Detour N 49 | | 27.7 |
| | | | | BY QUANTITY OF SQUARE FEET | | | | | | | | |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 5.509 | SB Outer Rd | 29.70 | 1.00 | 50E, Detour N 49 | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 5.398 | SB Outer Rd | 29.70 | 1.00 | 50D, Detour N 49 | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 3.783 | WB 283rd St | 27.70 | 1.00 | 50R, Detour 49 | | 27.7 |
| | | October 26, 2023 | 208 | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 0.734 | WB 275th St | 29.70 | 1.00 | 50E, Detour N 49 | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 1.267 | EB 275th St | 29.70 | 1.00 | 50C, Detour N 49 | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 1.394 | EB 275th St | 29.70 | 1.00 | 50E, Detour N 49 | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 1.672 | SB Brookhart Dr | 29.70 | 1.00 | 50E, Detour N 49 | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 1.64 | SB Brookhart Dr | 29.70 | 1.00 | 50A, Detour N 49 | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 1.568 | SB Outer Rd | 29.70 | 1.00 | 50E, Detour N 49 | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 4.327 | NB Outer Rd | 29.70 | 1.00 | 50C, Detour N 49 | | 29.7 |
| | | November 8, 2023 | 59 | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 1.672 | SB Brookhart Dr | 29.70 | 1.00 | 50E, Detour N 49 | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 2.536 | SB Outer Rd | 29.70 | 1.00 | 50A, Detour N 49 | | 29.7 |
| | | November 17, 2023 | 504 | R11-2 48x30 10.00 ROAD CLOSED | | 0.03 | NB I-49 ramp to MO-7 | 1.00 | 10.00 | Ramp Closed | | 10.00 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | | various | 26.00 | 1.00 | M3-3 South (on 13 existing detour signs) | | 26.0 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 0.086 | NB I-49 ramp to Commercial St | 29.70 | 1.00 | 50P, Detour S 7 | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 1.361 | Commercial St | 29.70 | 1.00 | 50J, Detour S 49 | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 1.361 | Commercial St | 29.70 | 1.00 | 50P, Detour S 7 | | 29.7 |
| | | | | R1-2 48 TRI 6.93 YIELD | | 1.489 | EB 275th St | 1.00 | 6.93 | Yield Sign (changed to 2 Stop signs) | | 6.9 |
| | | | | R1-1 48x48 13.25 STOP WO20-2 48x48 16.00 DETOUR | | 1.489 | EB 275th St MO-7 N | 1.00 | 13.25 | | | 26.5 16.0 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN | | 146.53 | MO-7 N ramp to NB 49 | 29.70 | 1.00 | 50A, Detour S 49 | | 29.7 |
| | | | | BY QUANTITY OF SQUARE FEET Variable ??x?? 1.00 SPECIAL SIGN | | | NB I-49 | 29.70 | 1.00 | 50K, Detour S 7 | | 29.7 |
| | | | | BY QUANTITY OF SQUARE FEET WO20-2 48x48 16.00 DETOUR | | | NB I-49 | 1.00 | 16.00 | | | 16.0 |
| | | | | AHEAD Variable ??x?? 1.00 SPECIAL SIGN | | | NB I-49 | 16.00 | 1.00 | Ramp Closed Ahead | | 16.00 |

Revision 3/23/2023 Page 12 of 36



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Stone (if applicable).

| roject | Line Number | DWR Date | Total Quantity Posted For DWR Date | Sign Information | Station | Log Mile | Location | Number of Items | SF Each Sign | Special Sign | SF Each Special Sign | Total SF to Post |
|--------|----------------|----------------------|---------------------------------------|--|---------|-------------|----------------------------------|--------------------|-----------------|--|-------------------------|---------------------|
| P3443 | 0320 | November 17, 2023 | 504 | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 157.535 | NB I-49 | 29.70 | 1.00 | 50K, Detour S 7 | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 158.153 | NB I-49 | 29.70 | 1.00 | 50A, Detour S 49 | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 158.183 | NB I-49 | 29.70 | 1.00 | 50K, Detour S 7 | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 158.623 | NB I-49 | 29.70 | 1.00 | 50F, Detour S 7 | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 158.623 | NB I-49 | 29.70 | 1.00 | 50K, Detour S 7 | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 26.208 | SB I-49 | 29.70 | 1.00 | 50F, Detour S 49 (shown in plans, didn't need) | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 26.208 | SB I-49 | 29.70 | 1.00 | 50K, Detour S 7 | | 29.7 |
| | | | | Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET | | 0.086 | NB I-49 ramp to Commercial St | 29.70 | 1.00 | 50J, Detour S 49 | | 29.7 |
| | 0320 - Total | | | | | | | | | | | 2147.6 |

Revision 3/23/2023 Page 13 of 36



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| J4P3443 | 0040 | EMBANKMENT IN PLACE | Material | | 2 | Aug 2, 2023 | SYSTEM | \$77,140.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 2 | Aug 2, 2023 | SYSTEM | (\$77,140.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0040 - | Total | | | | | | \$0.00 | |
| | 0100 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material | | 7 | Oct 16, 2023 | SYSTEM | \$1,918.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | THION) | | | 7 | Oct 16, 2023 | SYSTEM | (\$1,918.00) | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | \$3,220.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$3,220.00) | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | \$3,220.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | (\$3,220.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0100 - | Total | | | | | | \$0.00 | |
| | 0110 | MISC. AGGREGATE FOR BASE | Material | | 5 | Sep 18, 2023 | SYSTEM | \$5,808.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | (\$5,808.60) | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | \$5,808.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$5,808.60) | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | \$17,988.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | (\$17,988.60) | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | \$17,988.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$17,988.60) | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | \$30,055.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | (\$30,055.20) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0110 - | Total | | | | | | \$0.00 | |
| | 0140 | CONCRETE PAVEMENT (10 1/2 IN. NON-REINF, | Material | | 8 | Nov 2, 2023 | SYSTEM | \$31,386.70 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$31,386.70) | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | \$31,386.70 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | (\$31,386.70) | |
| | | | | | 10 | Dec 4, 2023 | SYSTEM | \$31,386.70 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment |



| J4P3443 O140 | ated Material Payment ol1 overridding Payment mate. ated Material Payment ol1 overridding Payment timate. |
|--|--|
| 10 | ol1 overridding Payment mate. sted Material Payment ol1 overridding Payment timate. |
| 2023 Estimate Item Adjustment (0001) due to user raybe Estimate Exception 2 on the current Payment Estin | ol1 overridding Payment mate. sted Material Payment ol1 overridding Payment timate. |
| Total \$0.00 | ol1 overridding Payment timate. sted Material Payment ol1 overridding Payment |
| Material - Total S0.00 | ol1 overridding Payment timate. sted Material Payment ol1 overridding Payment |
| Solid Soli | ol1 overridding Payment timate. sted Material Payment ol1 overridding Payment |
| O150 CONCRETE APPROACH PAVEMENT Material APPROACH PAVEMENT 8 | ol1 overridding Payment timate. sted Material Payment ol1 overridding Payment |
| APPROACH PAVEMENT 2023 Estimate Item Adjustment (0005) due to user raybor Estimate Exception 17 on the current Payment Est. 8 Nov 2, 2023 9 Nov 16, 2023 This adjustment offsets the original system-general Estimate Item Adjustment (0005) due to user raybor Estimate Exception 12 on the current Payment Est. 9 Nov 16, SYSTEM (\$28,332.00) - Total \$0.00 | ol1 overridding Payment timate. sted Material Payment ol1 overridding Payment |
| 2023 9 | ol1 overridding Payment |
| 2023 Estimate Item Adjustment (0005) due to user raybo Estimate Exception 12 on the current Payment Estimat | ol1 overridding Payment |
| 2023 | |
| Material - Total \$0.00 | |
| | |
| 0450 Total | |
| 0150 - Total \$0.00 | |
| 0160 PIPE COLLAR, TYPE A TYPE A 12 Jan 2, 2024 13 Jan 2, 2024 14 SYSTEM \$1,600.00 This adjustment offsets the original system-general Estimate Item Adjustment (0002) due to user mose Estimate Exception 6 on the current Payment Estimate Estimate Exception 6 on the current Payment Estimate Estimate Exception 6 on the current Payment Estimate | esj2 overridding Payment |
| 12 Jan 2, SYSTEM (\$1,600.00) | |
| 13 Jan 17, 2024 \$1,600.00 This adjustment offsets the original system-general Estimate Item Adjustment (0002) due to user raybor Estimate Exception 6 on the current Payment Estim | ol1 overridding Payment |
| 13 Jan 17, SYSTEM (\$1,600.00) | |
| 14 Feb 2, 2024 \$1,600.00 This adjustment offsets the original system-general Estimate Item Adjustment (0003) due to user raybo Estimate Exception 3 on the current Payment Estim | ol1 overridding Payment |
| 14 Feb 2, SYSTEM (\$1,600.00) | |
| -Total \$0.00 | |
| Material - Total \$0.00 | |
| 0160 - Total \$0.00 | |
| 0210 ROCK LINING Material 12 Jan 2, 2024 \$13,872.00 This adjustment offsets the original system-genera Estimate Item Adjustment (0003) due to user mose Estimate Exception 7 on the current Payment Estim | esj2 overridding Payment |
| 12 Jan 2, SYSTEM (\$13,872.00) | |
| 13 Jan 17, 2024 \$13,872.00 This adjustment offsets the original system-general Estimate Item Adjustment (0003) due to user raybo Estimate Exception 7 on the current Payment Estim | ol1 overridding Payment |
| 13 Jan 17, 2024 (\$13,872.00) | |
| 14 Feb 2, 2024 \$YSTEM \$27,064.00 This adjustment offsets the original system-general Estimate Item Adjustment (0002) due to user raybo Estimate Exception 4 on the current Payment Estim | ol1 overridding Payment |
| 14 Feb 2, SYSTEM (\$27,064.00) | |
| - Total \$0.00 | |
| Material - Total \$0.00 | |
| Overrun Overrun 14 Feb 2, 2024 SYSTEM (\$9,792.00) | |
| Overrun - Total (\$9,792.00) | |
| Overrun - Total (\$9,792.00) | |
| 0210 - Total (\$9,792.00) | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| J4P3443 | 0340 | CHANNELIZER (TRIM LINE) | Overrun | Overrun | 6 | Oct 2, 2023 | SYSTEM | (\$4,997.00) | |
| | | , | | | 9 | Nov 16, 2023 | SYSTEM | \$4,997.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',19.00000 - 19.00000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - To | tal | | | | \$0.00 | |
| | 0340 - | Total | | | | | | \$0.00 | |
| | 0390 | CMS WITH COMMUNICATION INTERFACE, CONT F | Material | | 1 | Jul 17, 2023 | SYSTEM | \$23,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | OOM | | | 1 | Jul 17, 2023 | SYSTEM | (\$23,200.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0390 - | Total | | | | | | \$0.00 | |
| | 0420 | TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE | Material | | 2 | Aug 2, 2023 | SYSTEM | \$28,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | FUKN/KE | | | 2 | Aug 2, 2023 | SYSTEM | (\$28,800.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | | | Overrun | Overrun | 3 | Aug 16, 2023 | SYSTEM | (\$3,584.00) | |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | (\$10,272.00) | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | \$13,856.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',16.00000 - 16.00000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - To | tal | | | | \$0.00 | |
| | 0420 - | Total | | | | | | \$0.00 | |
| | 0460 | PAVEMENT EDGE TREATMENT | Material | | 7 | Oct 16, 2023 | SYSTEM | \$5,576.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | (\$5,576.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | | | Overrun | Overrun | 7 | Oct 16, 2023 | SYSTEM | (\$204.00) | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$3,060.00) | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | \$3,264.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',6.80000 - 6.80000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - To | tal | | | | \$0.00 | |
| | 0460 - | Total | | | | | | \$0.00 | |
| | 0500 | PREF THERMO PVMT MARK, LT/RT ARROW | Material | | 10 | Dec 4, 2023 | SYSTEM | \$2,720.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 10 | Dec 4, 2023 | SYSTEM | (\$2,720.00) | |
| | | | | | 11 | Dec 18, 2023 | SYSTEM | \$2,720.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 11 | Dec 18, 2023 | SYSTEM | (\$2,720.00) | |
| | | | | | 12 | Jan 2, 2024 | SYSTEM | \$2,720.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mosesj2 overridding Payment Estimate Exception 8 on the current Payment Estimate. |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| J4P3443 | 0500 | PREF THERMO PVMT MARK, | Material | | 12 | Jan 2, 2024 | SYSTEM | (\$2,720.00) | |
| | | LT/RT ARROW | | | 13 | Jan 17, 2024 | SYSTEM | \$2,720.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 13 | Jan 17, 2024 | SYSTEM | (\$2,720.00) | |
| | | | | | 14 | Feb 2, 2024 | SYSTEM | \$2,720.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 14 | Feb 2, 2024 | SYSTEM | (\$2,720.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 0500 - | Total | | | | | | \$0.00 | |
| | 0550 | TEMPORARY REMOVABLE MARKING TAPE, 24 IN. | Material | | 5 | Sep 18, 2023 | SYSTEM | \$624.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user raybol1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | 24 IN. | | | 5 | Sep 18, 2023 | SYSTEM | (\$624.00) | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | \$936.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$936.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 0550 - | Total | | | | | | \$0.00 | |
| | 0560 | TEMPORARY NON-REMOVABLE TAPE LT/RT ARROW | Material | | 5 | Sep 18, 2023 | SYSTEM | \$160.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user raybol1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | ANNOW | | | 5 | Sep 18, 2023 | SYSTEM | (\$160.00) | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | \$160.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$160.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0560 - | Total | | | | | | \$0.00 | |
| | 0570 | TEMPORARY NON-REMOVABLE MARKING TAPE | Material | | 5 | Sep 18, 2023 | SYSTEM | \$924.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | (\$924.00) | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | \$924.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user raybol1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$924.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | | | | | \$0.00 | |
| | | | Overrun | Overrun | | Sep 18, 2023 | SYSTEM | (\$528.00) | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | \$528.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',132.00000 - 132.00000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - To | tal | | | | \$0.00 | |
| | 0570 - | Total | | | | | | \$0.00 | |
| | 0580 | TEMPORARY N/R MARK TAPE COMBO ST LT/RT | Material | | 5 | Sep 18, 2023 | SYSTEM | \$1,040.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | |
|---------|--------|-------------------------------------|--------------------|-----------------------------|----------------|-----------------|----------------|---------------|---|---|--------|---------------|--|
| J4P3443 | 0580 | TEMPORARY N/R MARK TAPE | Material | | 5 | Sep 18, 2023 | SYSTEM | (\$1,040.00) | | | | | |
| | | COMBO ST LT/RT | | | 6 | Oct 2, 2023 | SYSTEM | \$1,040.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 13 on the current Payment Estimate. | | | | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$1,040.00) | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | |
| | | | Overrun | Overrun | 5 | Sep 18, 2023 | SYSTEM | (\$260.00) | | | | | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | \$260.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',260.00000 - 260.00000, 'is applied (if non-zero). | | | | |
| | | | | Overrun - T | otal | | | \$0.00 | | | | | |
| | | | Overrun - To | tal | | | | \$0.00 | | | | | |
| | 0580 - | Total | | | | | | \$0.00 | | | | | |
| | 0650 | PERMANENT EROSION CONTROL | Material | | 2 | Aug 2, 2023 | SYSTEM | \$266.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | | |
| | | GEOTEXTILE | | | 2 | Aug 2, 2023 | SYSTEM | (\$266.00) | | | | | |
| | | | | | 3 | Aug 16, 2023 | SYSTEM | \$4,335.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | |
| | | | | | 3 | Aug 16, 2023 | SYSTEM | (\$4,335.80) | | | | | |
| | | | | 4 | 4 | Sep 5, 2023 | SYSTEM | \$4,335.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | | | |
| | | | | | | 4 | Sep 5, 2023 | SYSTEM | (\$4,335.80) | | | | |
| | | | | - Total | | | | \$0.00 | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | |
| | 0650 - | Total | | | | | | \$0.00 | | | | | |
| | 0670 | CLASS B-1 CONCRETE (CULVERTS) | Material | | 6 | Oct 2, 2023 | SYSTEM | \$78,660.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user raybol1 overridding Payment Estimate Exception 24 on the current Payment Estimate. | | | | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$78,660.00) | | | | | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | \$78,660.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 24 on the current Payment Estimate. | | | | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | (\$78,660.00) | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | |
| | 0670 - | Total | | | | | | \$0.00 | | | | | |
| | 0680 | REINFORCING STEEL (CULVERTS) | Material | | 4 | Sep 5, 2023 | SYSTEM | \$13,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate. | | | | |
| | | | | | | | | | 4 | Sep 5, 2023 | SYSTEM | (\$13,500.00) | |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | \$13,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user raybol1 overridding Payment Estimate Exception 29 on the current Payment Estimate. | | | | |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | (\$13,500.00) | | | | | |
| | | | | | | 6 Oct 2, 2023 | | SYSTEM | \$17,199.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user raybol1 overridding Payment Estimate Exception 30 on the current Payment Estimate. | | | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$17,199.00) | | | | | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | \$17,199.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user raybol1 overridding Payment | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| J4P3443 | 0680 | REINFORCING | Material | | | | | | Estimate Exception 31 on the current Payment Estimate. |
| | | STEEL (CULVERTS) | | | 7 | Oct 16, 2023 | SYSTEM | (\$17,199.00) | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | \$17,199.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybo11 overridding Payment Estimate Exception 33 on the current Payment Estimate. |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$17,199.00) | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | \$17,199.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | (\$17,199.00) | |
| | | | | | 10 | Dec 4, 2023 | SYSTEM | \$17,199.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 10 | Dec 4, 2023 | SYSTEM | (\$17,199.00) | |
| | | | | | 11 | Dec 18, 2023 | SYSTEM | \$22,491.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 11 | Dec 18, 2023 | SYSTEM | (\$22,491.00) | |
| | | | | | 12 | Jan 2, 2024 | SYSTEM | \$22,491.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mosesj2 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 12 | Jan 2, 2024 | SYSTEM | (\$22,491.00) | |
| | | | | | 13 | Jan 17, 2024 | SYSTEM | \$22,491.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 13 | Jan 17, 2024 | SYSTEM | (\$22,491.00) | |
| | | | | | 14 | Feb 2, 2024 | SYSTEM | \$22,491.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 14 | Feb 2, 2024 | SYSTEM | (\$22,491.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0680 - | Total | | | | | | \$0.00 | |
| | 0760 | PRECAST CONCRETE DROP INLET 5 FT X 3 FT | Material | | 11 | Dec 18, 2023 | SYSTEM | \$6,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 11 | Dec 18, 2023 | SYSTEM | (\$6,800.00) | |
| | | | | | 12 | Jan 2, 2024 | SYSTEM | \$6,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mosesj2 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 12 | Jan 2, 2024 | SYSTEM | (\$6,800.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0760 - | Total | | | | | | \$0.00 | |
| | 0770 | 18 IN. GROUP B FLARED END SEC | Material | | 12 | Jan 2, 2024 | SYSTEM | \$1,900.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mosesj2 overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | | 12 | Jan 2, 2024 | SYSTEM | (\$1,900.00) | |
| | | | | | 13 | Jan 17, 2024 | SYSTEM | \$1,900.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 13 | Jan 17, 2024 | SYSTEM | (\$1,900.00) | |
| | | | | | 14 | Feb 2, 2024 | SYSTEM | \$1,900.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |



| Project | Line | Description | Adjustment Type | Other Adjustment | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | | | | | |
|---------|--------|-------------------------------------|--------------------|---------------------|----------------|-----------------|-----------------|------------------|---|---|-------------|---|--|--|--|--|--|--|--|--|---|-----------------|--------|--------------|
| J4P3443 | 0770 | 18 IN. GROUP B | Material | Туре | 14 | Feb 2, | SYSTEM | (\$1,900.00) | | | | | | | | | | | | | | | | |
| | | FLARED END SEC | | | | 2024 | | 40.40 | | | | | | | | | | | | | | | | |
| | | | Material - To | - Total | | | | \$0.00 | | | | | | | | | | | | | | | | |
| | 0770 - | Total | wateriai - 10 | iai | | | | \$0.00 \$0.00 | | | | | | | | | | | | | | | | |
| | 0820 | MULCHING | Material | | 7 | Oct 16, 2023 | SYSTEM | \$235.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 37 on the current Payment Estimate. | | | | | | | | | | | | | | | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | (\$235.00) | | | | | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | | | | | |
| | 0820 - | Total | | | | | | \$0.00 | | | | | | | | | | | | | | | | |
| | 0830 | SEEDING - COOL SEASON GRASSES | Material | | 5 | Sep 18, 2023 | SYSTEM | \$7,290.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 38 on the current Payment Estimate. | | | | | | | | | | | | | | | |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | (\$7,290.00) | | | | | | | | | | | | | | | | |
| | | | | | | 6 | Oct 2, 2023 | SYSTEM | \$7,290.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 44 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$7,290.00) | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | 7 | Oct 16, 2023 | SYSTEM | \$8,640.00 |
| | | | | | | | | | | | | | | | | | | | | | 7 | Oct 16, 2023 | SYSTEM | (\$8,640.00) |
| | | | | | | | | 8 | Nov 2, 2023 | SYSTEM | \$10,260.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 39 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$10,260.00) | | | | | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | | | | | |
| | 0830 - | | | | | | | \$0.00 | | | | | | | | | | | | | | | | |
| | 0840 | SEDIMENT TRAP ROCK | Material | | 6 | Oct 2, 2023 | SYSTEM | \$140.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 46 on the current Payment Estimate. | | | | | | | | | | | | | | | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$140.40) | | | | | | | | | | | | | | | | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | \$140.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 39 on the current Payment Estimate. | | | | | | | | | | | | | | | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | (\$140.40) | | | | | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | | | | | |
| | 0840 - | | | | | | 2) (2) | \$0.00 | | | | | | | | | | | | | | | | |
| | 0850 | ROCK DITCH CHECK | Material | | 1 | Jul 17, 2023 | SYSTEM | \$1,653.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | | | | | | | | | | | | | |
| | | | | | 1 | Jul 17, 2023 | SYSTEM | (\$1,653.00) | | | | | | | | | | | | | | | | |
| | | | | 2 2 3 | 2 | Aug 2, 2023 | SYSTEM | \$1,653.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | | | | | | | | | | | | |
| | | | | | Aug 2, 2023 | SYSTEM | (\$1,653.00) | | | | | | | | | | | | | | | | | |
| | | | | | 3 | Aug 16, 2023 | SYSTEM | \$3,287.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | | | | | | | | | |
| | | | | | | 3 | Aug 16, 2023 | SYSTEM | (\$3,287.00) | | | | | | | | | | | | | | | |
| | | | | | | | | \$0.00 | | | | | | | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|----------------|-------------------------------------|--------------------|-----------------------------|---------------------------------|--|---|---|---|
| J4P3443 | 0850 | ROCK DITCH CHECK | Material - To | | | | | \$0.00 | |
| | 0850 - | - Total | | | | | | \$0.00 | |
| | 0890 | TYPE 1 TURF REINFORCEMENT MAT | Material | | 5 | Sep 18, 2023 | SYSTEM | \$2,731.10 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user raybol1 overridding Payment Estimate Exception 40 on the current Payment Estimate. |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | (\$2,731.10) | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | \$2,731.10 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 47 on the current Payment Estimate. |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$2,731.10) | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | \$2,731.10 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 40 on the current Payment Estimate. |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | (\$2,731.10) | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | \$2,731.10 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 41 on the current Payment Estimate. |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$2,731.10) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0890 - | - Total | | | | | | \$0.00 | |
| | 0900 | TYPE 2D EROSION CONTROL | Overrun | Overrun | | Dec 4, 2023 | SYSTEM | (\$1,538.40) | |
| | | BLANKET | | Overrun - T | otal | | | (\$1,538.40) | |
| | 0000 | Takal | Overrun - To | tal | | | | (\$1,538.40) | |
| | 0900 - 0940 | MISC. | Material | | 4 | Sep 5, | SYSTEM | (\$1,538.40) \$52,567.20 | This adjustment offsets the original system-generated Material Payment |
| | 0940 | AGGREGATE FOR BASE | Material | | | 2023 | | | Estimate Item Adjustment (0001) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 4 | Sep 5, 2023 | SYSTEM | (\$52,567.20) | |
| | | | | | 5 | Sep 18, | SYSTEM | | T |
| | | | | | | 2023 | OTOTEW | \$52,567.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 5 | 2023 Sep 18, 2023 | SYSTEM | \$52,567.20 (\$52,567.20) | Estimate Item Adjustment (0013) due to user raybol1 overridding Payment |
| | | | | | 5 | Sep 18, | | | Estimate Item Adjustment (0013) due to user raybol1 overridding Payment |
| | | | | | | Sep 18, 2023 Oct 2, | SYSTEM | (\$52,567.20) | Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment |
| | | | | | 6 | Sep 18, 2023 Oct 2, 2023 | SYSTEM | (\$52,567.20) \$113,109.60 | Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment |
| | | | | | 6 | Sep 18, 2023 Oct 2, 2023 Oct 2, 2023 Oct 16, | SYSTEM SYSTEM SYSTEM | (\$52,567.20) \$113,109.60 (\$113,109.60) | Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment |
| | | | | | 6 7 | Sep 18, 2023 Oct 2, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 | SYSTEM SYSTEM SYSTEM SYSTEM | (\$52,567.20) \$113,109.60 (\$113,109.60) \$119,905.20 | Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment |
| | | | | | 6 7 7 | Sep 18, 2023 Oct 2, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 2, | SYSTEM SYSTEM SYSTEM SYSTEM | (\$52,567.20) \$113,109.60 (\$113,109.60) \$119,905.20 | Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment |
| | | | | | 6 6 7 7 8 | Sep 18, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 2, 2023 Nov 2, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$52,567.20) \$113,109.60 (\$113,109.60) \$119,905.20 (\$119,905.20) \$156,393.60 | Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment |
| | | | | | 6 6 7 7 8 8 8 | Sep 18, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 2, 2023 Nov 16, Nov 16, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$52,567.20) \$113,109.60 (\$113,109.60) \$119,905.20 (\$119,905.20) \$156,393.60 | Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | - Total | 6 6 7 7 8 8 8 | Sep 18, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 2, 2023 Nov 16, 2023 Nov 16, 2023 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$52,567.20) \$113,109.60 (\$113,109.60) \$119,905.20 (\$119,905.20) \$156,393.60 (\$156,393.60) \$178,377.60 | Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | Material - To | | 6 6 7 7 8 8 8 | Sep 18, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 2, 2023 Nov 16, 2023 Nov 16, 2023 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$52,567.20) \$113,109.60 (\$113,109.60) \$119,905.20 (\$119,905.20) \$156,393.60 (\$156,393.60) \$178,377.60 | Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. |
| | 0940 - | - Total | Material - To | | 6 6 7 7 8 8 8 | Sep 18, 2023 Oct 2, 2023 Oct 16, 2023 Oct 16, 2023 Nov 2, 2023 Nov 16, 2023 Nov 16, 2023 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$52,567.20) \$113,109.60 (\$113,109.60) \$119,905.20 (\$119,905.20) \$156,393.60 (\$156,393.60) \$178,377.60 (\$178,377.60) | Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. |



| PA NON-REINT | | Remarks | Amount | Created By | Created Date | Est. Number | Other Adjustment Type | Adjustment Type | Description | Line | Project |
|---|---------------|---|------------------|---------------|-----------------|----------------|-----------------------------|--------------------|-------------|------|---------|
| 2023 SYSTEM S429,298.00 This adjustment offsets the original system-generated Material Estimate Lenn Aglustramet (2014) due to user grippol overvide Estimate Lenn Aglustramet (2014) due to user grippol overvide Estimate Lenn Aglustramet (2014) due to user grippol overvide Estimate Lenn Aglustramet (2014) due to user grippol overvide Estimate Lenn Aglustramet (2016) due to user grippol overvide Estimate Lenn Aglustramet (2016) due to user grippol overvide Estimate Lenn Aglustramet (2016) due to user grippol overvide Estimate Lenn Aglustramet (2016) due to user grippol overvide Estimate Exception 5 on the current Payment Estimate Lenn Aglustramet (2017) due to user grippol overvide Estimate Exception 6 on the current Payment Estimate (2017) due to user grippol overvide Estimate Exception 6 on the current Payment Estimate (2017) due to user grippol overvide Estimate Exception 6 on the current Payment Estimate (2017) due to user grippol overvide Estimate Exception 6 on the current Payment Estimate (2017) due to user grippol overvide Estimate Exception 6 on the current Payment Estimate (2017) due to user grippol overvide Estimate Exception 6 on the current Payment Estimate (2017) due to user grippol overvide Estimate Exception 6 on the current Payment Estimate (2017) due to user grippol overvide Estimate Exception 6 on the current Payment Estimate (2017) due to user grippol overvide Estimate Exception 6 on the current Payment Estimate (2017) due to user grippol overvide Estimate Exception 6 on the current Payment Estimate (2017) due to user grippol overvide Estimate Exception 6 on the current Payment Estimate (2017) due to user grippol overvide Estimate Exception 6 on the current Payment Estimate (2018) due to user grippol overvide Estimate Exception 6 on the current Payment Estimate (2018) due to user grippol overvide Estimate Exception 6 on the current Payment Estimate (2018) due to user grippol overvide Estimate Exception 6 on the current Payment Estimate (2018) due to user grippol overvide Estimate Excep | dding Payment | Estimate Item Adjustment (0002) due to user raybol1 overridding Pa Estimate Exception 3 on the current Payment Estimate. | | | | | | Material | | 0950 | P3443 |
| 2023 SysTEM (\$429,298,80) SysTEM (\$439,298,80) SysTEM | | | (\$340,040.40) | SYSTEM | | 4 | | | | | |
| 2023 SYSTEM 9649,147.10 This adjustment offsets the original system-generated Maleria Estimate Item Adjustment (0009) due to user raybot override Estimate Exception 5 on the current Payment Estimate (1974) (1974) SYSTEM SYSTE | | This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0014) due to user raybol1 overridding Patestimate Exception 5 on the current Payment Estimate. | \$429,298.80 | SYSTEM | | 5 | | | | | |
| 2023 SYSTEM (\$649,147.10) | | | (\$429,298.80) | SYSTEM | | 5 | | | | | |
| 2023 7 Cot 16, SYSTEM S870,798.60 This adjustment offsets the original system-generated Material Estimate Example Internal Adjustment (D010) due to user raybot override Estimate Example Internal Adjustment (D010) due to user raybot override Estimate Example Internal Adjustment (D010) due to user raybot override Estimate Exception 7 on the current Payment Estimate. 7 | | This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0009) due to user raybol1 overridding Pa Estimate Exception 5 on the current Payment Estimate. | \$649,147.10 | SYSTEM | | 6 | | | | | |
| 2023 SYSTEM \$820,798.00 | | | (\$649,147.10) | SYSTEM | | 6 | | | | | |
| 8 | | This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0010) due to user raybol1 overridding Patestimate Exception 6 on the current Payment Estimate. | \$870,798.60 | SYSTEM | | 7 | | | | | |
| 2023 Estimate tem Adjustment (0011) due to user raybort override Estimate Exception 7 on the current Payment Estimate Estimate Exception 7 on the current Payment Estimate Estimate Estimate Exception 7 on the current Payment Estimate Estimate Estimate Estimate (013) due to user raybort override Estimate Estimate Estimate Exception 6 on the current Payment Estimate Es | | | (\$870,798.60) | SYSTEM | | 7 | | | | | |
| 10 | | This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0011) due to user raybol1 overridding Pa Estimate Exception 7 on the current Payment Estimate. | \$926,296.00 | SYSTEM | | 8 | | | | | |
| 2023 Settinate Item Adjustment (0013) due to user raybort override. Estimate Item Adjustment (0013) due to user raybort override. Simate Exception 6 on the current Payment Estimate. | | | (\$926,296.00) | SYSTEM | | 8 | | | | | |
| 10 | | This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0013) due to user raybol1 overridding Pa Estimate Exception 6 on the current Payment Estimate. | \$1,362,307.80 | SYSTEM | | 9 | | | | | |
| 2023 Estimate Item Adjustment (0003) due to user raybof 1 override Estimate Exception 4 on the current Payment Estimate. | | | (\$1,362,307.80) | SYSTEM | | 9 | | | | | |
| 2023 11 Dec 18, 2023 11 Dec 18, 2023 11 Dec 18, 2023 12 Dec 18, 2023 13 Dec 18, 2023 14 Dec 18, 2023 2024 | | This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0003) due to user raybol1 overridding Pa Estimate Exception 4 on the current Payment Estimate. | \$1,362,307.80 | SYSTEM | | 10 | | | | | |
| 2023 Estimate Item Adjustment (0003) due to user raybol 1 override Estimate Exception 4 on the current Payment Estimate. | | | (\$1,362,307.80) | SYSTEM | | 10 | | | | | |
| 12 | | This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0003) due to user raybol1 overridding Pa Estimate Exception 4 on the current Payment Estimate. | \$1,465,051.00 | SYSTEM | | 11 | | | | | |
| 2024 Estimate Item Adjustment (0006) due to user moses)2 overric Estimate Exception 2 on the current Payment Estimate. | | | (\$1,465,051.00) | SYSTEM | | 11 | | | | | |
| 2024 | | This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0006) due to user mosesj2 overridding F Estimate Exception 2 on the current Payment Estimate. | \$1,492,167.60 | SYSTEM | | 12 | | | | | |
| 2024 Estimate Item Adjustment (0005) due to user raybol1 override Estimate Exception 2 on the current Payment Estimate. | | | (\$1,492,167.60) | SYSTEM | | 12 | | | | | |
| 2024 | | This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0005) due to user raybol1 overridding Pa Estimate Exception 2 on the current Payment Estimate. | \$1,492,167.60 | SYSTEM | | 13 | | | | | |
| 2024 Estimate Item Adjustment (0005) due to user raybol1 override Estimate Exception 1 on the current Payment Estimate. 14 Feb 2, 2024 \$\frac{1}{2}\$ SYSTEM (\$\\$839,708.20) \$\frac{1}{2}\$ \$\frac{1}{2 | | | (\$1,492,167.60) | SYSTEM | | 13 | | | | | |
| 2024 \$0.00 | | This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0005) due to user raybol1 overridding Pa Estimate Exception 1 on the current Payment Estimate. | \$839,708.20 | SYSTEM | | 14 | | | | | |
| Material - Total \$0.00 | | | (\$839,708.20) | SYSTEM | | 14 | | | | | |
| 0950 - Total TYPE A2 SHOULDER Material 8 Nov 2, 2023 SYSTEM \$29,700.00 This adjustment offsets the original system-generated Material Estimate Item Adjustment (0012) due to user raybol1 override Estimate Exception 10 on the current Payment Estimate. 8 Nov 2, 2023 SYSTEM (\$29,700.00) | | | | | | | | Material T | | | |
| 0980 TYPE A2 SHOULDER | | | | | | | lai | Material - 10 | - Total | 0950 | |
| 2023 | | This adjustment offsets the original system-generated Material Payr Estimate Item Adjustment (0012) due to user raybol1 overridding Pa Estimate Exception 10 on the current Payment Estimate. | | SYSTEM | | 8 | | Material | TYPE A2 | | |
| - Total \$0.00 | | | (\$29,700.00) | SYSTEM | | 8 | | | | | |
| | | | \$0.00 | | | | | | | | |
| Material - Total \$0.00 | | | | | | | tal | Material - To | | | |
| 0980 - Total \$0.00 | | | | | | | | | | | |
| 0990 MGS GUARDRAIL, Construction 8 FT. POSTS, 6 FT. Stockpile 2023 SYSTEM \$40,057.00 Payment Estimate Item Adjustment generated Stockpile Transport | ansaction | Payment Estimate Item Adjustment generated Stockpile Transaction | \$40,057.00 | SYSTEM | | 8 | | | | 0990 | |



| oject | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | |
|-------|--------|--|-----------------------------------|-----------------------------|----------------|-----------------|---------------|---|---|--------|----------|
| 3443 | 0990 | - 3 IN | STMI | - Total | | | | \$40,057.00 | | | |
| | | | Construction | Stockpile S | TMI - Total | | | \$40,057.00 | | | |
| | 0990 - | Total | | | | | | \$40,057.00 | | | |
| | 1120 | CONDUIT, 2 IN. RIGID, IN TRENCH | Material | | 8 | Nov 2, 2023 | SYSTEM | \$1,771.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 42 on the current Payment Estimate. | | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$1,771.00) | | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - To | tal | | | | \$0.00 | | | |
| | 1120 - | Total | | | | | | \$0.00 | | | |
| | 1130 | CONDUIT, 4 IN. RIGID, PUSHED | Material | | 8 | Nov 2, 2023 | SYSTEM | \$1,680.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user raybol1 overridding Payment Estimate Exception 43 on the current Payment Estimate. | | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$1,680.00) | | | |
| | | | | - Total | | 2020 | | \$0.00 | | | |
| | | | Material - To | tal | | | | \$0.00 | | | |
| | 1130 - | Total | | | | | | \$0.00 | | | |
| | 1360 | CONDUIT, 3 IN., TRENCH WITH TRACER WIRE | Material | | 8 | Nov 2, 2023 | SYSTEM | \$1,530.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user raybol1 overridding Payment Estimate Exception 44 on the current Payment Estimate. | | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$1,530.00) | | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - To | tal | | | | \$0.00 | | | |
| | 1360 - | Total | | | | | | \$0.00 | | | |
| | 1390 | 0 - Total CONDUIT, 4 IN., PUSHED WITH TRACER WIRE | CONDUIT, 4 IN., PUSHED WITH | i | Overrun | Overrun | Overrun | 12 | Jan 2, 2024 | SYSTEM | \$924.00 |
| | | | | | 12 | Jan 2, 2024 | SYSTEM | (\$924.00) | | | |
| | | | | 13 | | SYSTEM | (\$924.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | | | |
| | | | Overrun - Total | | | | | (\$924.00) | | | |
| | | | Overrun - To | tal | | | | (\$924.00) | | | |
| | 1390 - | Total | | | | | | (\$924.00) | | | |
| | 1470 | TEMPORARY TRAFFIC SIGNALS AND LIGHTING | Material | | 3 | Aug 16, 2023 | SYSTEM | \$236,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | |
| | | | | | 3 | Aug 16, 2023 | SYSTEM | (\$236,000.00) | | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - To | tal | | | | \$0.00 | | | |
| | 1470 - | | | | | | | \$0.00 | | | |
| | 1500 | BREAKAWAY ASSEMBLY (PERFORATED | Construction Stockpile STMI | - Total | 9 | Nov 16, 2023 | SYSTEM | \$2,106.00 \$2,106.00 | Payment Estimate Item Adjustment generated Stockpile Transaction | | |
| | | SQUARE STEEL TUBE) | Construction | | TMI - Total | | | \$2,106.00 | | | |
| | 1500 - | Total | | | | | | \$2,106.00 | | | |
| | 1510 | 2 IN. PSST POST - 12 GA. | Construction Stockpile STMI | | 9 | Nov 16, 2023 | SYSTEM | \$6,034.08 | Payment Estimate Item Adjustment generated Stockpile Transaction | | |
| | | | J I IVII | - Total | | | | \$6,034.08 | | | |
| | | | Construction | Stockpile S | TMI - Tota | | | \$6,034.08 | | | |
| | 1510 - | Total | | | | | | \$6,034.08 | | | |
| | 1520 | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. | | | 9 | Nov 16, 2023 | SYSTEM | \$1,195.74 | Payment Estimate Item Adjustment generated Stockpile Transaction | | |
| | | 551 12 OA. | | TMI - Total | | | | \$1,195.74 | | | |
| | | | Construction | Stockpile S | TMI - Tota | | | \$1,195.74 | | | |



| roject | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--------|---|-----------------------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| P3443 | 1520 - | Total | | | | | | \$1,195.74 | |
| | 1530 | 2.25 IN. PSST POST INSERT (6 FT.) - 12 GA. | Stockpile | | 9 | Nov 16, 2023 | SYSTEM | \$245.28 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | F1.) - 12 GA. | STIVII | - Total | | | | \$245.28 | |
| | | | Construction | Stockpile S1 | MI - Tota | | | \$245.28 | |
| | 1530 - | Total | | | | | | \$245.28 | |
| | 1540 | 2.5 IN. PSST POST - 12 GA. | Construction Stockpile STMI | | 9 | Nov 16, 2023 | SYSTEM | \$2,184.96 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | - Total | | | | \$2,184.96 | |
| | | | Construction | Stockpile S | TMI - Total | | | \$2,184.96 | |
| | | Total | 0 1 1 | | | N 40 | OVOTELL | \$2,184.96 | |
| | 1550 | DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA. | Construction Stockpile STMI | Total | 9 | Nov 16, 2023 | SYSTEM | \$1,022.40 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | - Total | | | | \$1,022.40 | |
| | | | Construction | Stockpile S | TMI - Total | | | \$1,022.40 | |
| | | Total | | | | | | \$1,022.40 | |
| | 1590 | MISC. HIGHWAY SIGNING | Material | | 14 | Feb 2, 2024 | SYSTEM | \$34,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 14 | Feb 2, 2024 | SYSTEM | (\$34,200.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 1590 - | Total | | | | | | \$0.00 | |
| | 1610 | | Material | | 14 | Feb 2, 2024 | SYSTEM | \$34,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | | 14 | Feb 2, 2024 | SYSTEM | (\$34,200.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 1610 - | Total | | | | | | \$0.00 | |
| | 1620 | MISC. HIGHWAY SIGNING | Material | | 14 | Feb 2, 2024 | SYSTEM | \$22,375.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 14 | Feb 2, 2024 | SYSTEM | (\$22,375.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 1620 - | Total | | | | | | \$0.00 | |
| | 1640 | CONDUIT, 2 IN., RIGID, IN TRENCH | Material | | 8 | Nov 2, 2023 | SYSTEM | \$21,080.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user raybol1 overridding Payment Estimate Exception 45 on the current Payment Estimate. |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$21,080.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 1640 - | Total | | | | | | \$0.00 | |
| | 1680 | PULL BOX, PREFORMED CLASS 2 | Material | | 8 | Nov 2, 2023 | SYSTEM | \$3,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user raybol1 overridding Payment Estimate Exception 46 on the current Payment Estimate. |
| | | 52.132 | | | 8 | Nov 2, 2023 | SYSTEM | (\$3,500.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 1680 - | Total | | | | | | \$0.00 | |
| | 1710 | MISC. ITS | Material | | 8 | Nov 2, 2023 | SYSTEM | \$27,900.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user raybol1 overridding Payment Estimate Exception 47 on the current Payment Estimate. |
| | | | | | 8 | Nov 2, | SYSTEM | (\$27,900.00) | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|--|--|--|--|--|--|----|----------------|--------|---------------|--|
| J4P3443 | 1710 | MISC. ITS | Material | | | 2023 | | | | | | | | | | | | | | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | \$27,900.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | (\$27,900.00) | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | |
| | | | Material - Tot | tal | | | | \$0.00 | | | | | | | | | | | | |
| | 1710 - | Total | | | | | | \$0.00 | | | | | | | | | | | | |
| | 1740 | MISC. ITS | Material | | 8 | Nov 2, 2023 | SYSTEM | \$7,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user raybol1 overridding Payment Estimate Exception 48 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$7,200.00) | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | |
| | | | Material - Tot | tal | | | | \$0.00 | | | | | | | | | | | | |
| | 1740 - | Total | | | | | | \$0.00 | | | | | | | | | | | | |
| | 1750 | CLASS 1 | Overrun | Overrun | 6 | Oct 2, | SYSTEM | (\$1,936.00) | | | | | | | | | | | | |
| | 1700 | EXCAVATION | Overrain | Overruin | 9 | 2023 Nov 16, | SYSTEM | \$1,936.00 | Unit price based on averaged overrun adjustments for installed quantity on all | | | | | | | | | | | |
| | | | | | | 2023 | | | previous payment estimates. Price Adjustments of ',88.00000 - 88.00000, 'is applied (if non-zero). | | | | | | | | | | | |
| | | | | Overrun - T | otal | | | \$0.00 | | | | | | | | | | | | |
| | | | Overrun - To | tal | | | | \$0.00 | | | | | | | | | | | | |
| | 1750 - | Total | | | | | | \$0.00 | | | | | | | | | | | | |
| | 1780 | BRIDGE APPROACH SLAB (MAJOR ROAD) | Material | | 12 | Jan 2, 2024 | SYSTEM | \$43,520.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mosesj2 overridding Payment Estimate Exception 5 on the current Payment Estimate. | | | | | | | | | | | |
| | | (MAJOR ROAD) | | | | | | | | | | | | | | 12 | Jan 2, 2024 | SYSTEM | (\$43,520.00) | |
| | | | | | 13 | Jan 17, 2024 | SYSTEM | \$43,520.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 13 | Jan 17, 2024 | SYSTEM | (\$43,520.00) | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | |
| | | | Material - Tot | tal | | | | \$0.00 | | | | | | | | | | | | |
| | 1780 - | Total | | | | | | \$0.00 | | | | | | | | | | | | |
| | 1790 | GALVANIZED STRUCTURAL STEEL PILES (12 | Material | | 5 | Sep 18, 2023 | SYSTEM | \$42,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate. | | | | | | | | | | | |
| | | IN | | | 5 | Sep 18, 2023 | SYSTEM | (\$42,000.00) | | | | | | | | | | | | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | \$42,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$42,000.00) | | | | | | | | | | | | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | \$42,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 15 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | (\$42,000.00) | | | | | | | | | | | | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | \$42,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user raybol1 overridding Payment Estimate Exception 20 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$42,000.00) | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | |
| | | | Material - Tot | tal | | | | \$0.00 | | | | | | | | | | | | |
| | | | Overrun | Overrun | 5 | Sep 18, 2023 | SYSTEM | (\$3,000.00) | | | | | | | | | | | | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | \$3,000.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',120.00000 - 120.00000, 'is | | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | |
|---------|----------------|---------------------------------------|--------------------|-----------------------------|----------------|-----------------|----------------|----------------------|--|---|
| J4P3443 | 1790 | GALVANIZED STRUCTURAL | Overrun | Overrun | | | | | applied (if non-zero). | |
| | | STEEL PILES (12 | | Overrun - T | otal | | | \$0.00 | | |
| | | | Overrun - To | tal | | | | \$0.00 | | |
| | 1790 - 1810 | PILE POINT REINFORCEMENT | Material | | 6 | Oct 2, 2023 | SYSTEM | \$0.00 \$1,350.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate. | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$1,350.00) | Estimate Exception to on the current Payment Estimate. | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | \$1,350.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate. | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | (\$1,350.00) | | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | \$1,350.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate. | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$1,350.00) | Estimate Established Establish | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - To | | | | | \$0.00 | | |
| | 1810 - | Total | | | | | | \$0.00 | | |
| | 1820 | CLASS B CONCRETE (SUBSTRUCTURE) | Material | | 3 | Aug 16, 2023 | SYSTEM | \$39,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | |
| | | | | | 3 | Aug 16, 2023 | SYSTEM | (\$39,000.00) | | |
| | | | | | 4 | Sep 5, 2023 | SYSTEM | \$105,950.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | |
| | | | | | 4 | Sep 5, 2023 | SYSTEM | (\$105,950.00) | | |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | \$105,950.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate. | |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | (\$105,950.00) | | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | \$116,740.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user raybol1 overridding Payment Estimate Exception 18 on the current Payment Estimate. | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$116,740.00) | | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | \$116,740.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user raybol1 overridding Payment Estimate Exception 19 on the current Payment Estimate. | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | (\$116,740.00) | | |
| | | | | | 8 | 8 | Nov 2, 2023 | SYSTEM | \$116,740.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user raybol1 overridding Payment Estimate Exception 24 on the current Payment Estimate. |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$116,740.00) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - To | tal | | | | \$0.00 | | |
| | 1820 - | | | | | | | \$0.00 | | |
| | 1840 | SLAB ON CONCRETE NU- GIRDER | Material | | 10 | Dec 4, 2023 | SYSTEM | \$137,448.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | |
| | | | | | 10 | Dec 4, 2023 | SYSTEM | (\$137,448.00) | | |
| | | | | 11 | 11 | Dec 18, 2023 | SYSTEM | \$305,440.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | |
| | | | | | 11 | Dec 18, 2023 | SYSTEM | (\$305,440.00) | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | | | | | |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|---|----------------|-------------|---|-----------------|--------|-------------|---|--|--|--|----|----------------|--------|-------------|---|
| J4P3443 | 1840 | SLAB ON CONCRETE NU- GIRDER | Material | | 12 | Jan 2, 2024 | SYSTEM | \$305,440.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mosesj2 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | | | | | | | | | | | | |
| | | | | | 12 | Jan 2, 2024 | SYSTEM | (\$305,440.00) | | | | | | | | | | | | | | | | |
| | | | | | 13 | Jan 17, 2024 | SYSTEM | \$305,440.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | | | | | | | | | | | | |
| | | | | | 13 | Jan 17, 2024 | SYSTEM | (\$305,440.00) | | | | | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | | | | | |
| | 1840 - | | | | | | | \$0.00 | | | | | | | | | | | | | | | | |
| | 1870 | NU 43, PRESTRESSED CONC NU-GIRDER | Material | | 9 | Nov 16, 2023 | SYSTEM | \$316,710.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user raybol1 overridding Payment Estimate Exception 15 on the current Payment Estimate. | | | | | | | | | | | | | | | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | (\$316,710.00) | | | | | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | | | | | |
| | 1870 - | Total | | | | | | \$0.00 | | | | | | | | | | | | | | | | |
| | 1880 | REINFORCING STEEL (EPOXY COATED) | Material | | 4 | Sep 5, 2023 | SYSTEM | \$23,037.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 20 on the current Payment Estimate. | | | | | | | | | | | | | | | |
| | | | | | 4 | Sep 5, 2023 | SYSTEM | (\$23,037.00) | | | | | | | | | | | | | | | | |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | \$23,037.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user raybol1 overridding Payment Estimate Exception 32 on the current Payment Estimate. | | | | | | | | | | | | | | | |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | (\$23,037.00) | | | | | | | | | | | | | | | | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | \$23,037.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user raybol1 overridding Payment Estimate Exception 35 on the current Payment Estimate. | | | | | | | | | | | | | | | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$23,037.00) | | | | | | | | | | | | | | | | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | \$23,037.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user raybol1 overridding Payment Estimate Exception 34 on the current Payment Estimate. | | | | | | | | | | | | | | | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | (\$23,037.00) | | | | | | | | | | | | | | | | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | \$23,037.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user raybol1 overridding Payment Estimate Exception 36 on the current Payment Estimate. | | | | | | | | | | | | | | | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$23,037.00) | | | | | | | | | | | | | | | | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | \$23,037.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user raybol1 overridding Payment Estimate Exception 19 on the current Payment Estimate. | | | | | | | | | | | | | | | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | (\$23,037.00) | Established Established State | | | | | | | | | | | | | | | |
| | | | | | | | | 10 | Dec 4, 2023 | SYSTEM | \$23,037.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | | | | | | 10 | Dec 4, 2023 | SYSTEM | (\$23,037.00) | | | | | | | | | | | | |
| | | | | | | | | | | | | 11 | Dec 18, 2023 | SYSTEM | \$23,037.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate. | | | | | | | | |
| | | | | | 11 | Dec 18, 2023 | SYSTEM | (\$23,037.00) | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | 11 12 | | | | 12 | Jan 2, 2024 | SYSTEM | \$23,037.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user mosesj2 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 12 | Jan 2, 2024 | SYSTEM | (\$23,037.00) | | | | | | | | | | | | | | | | |
| | | | | | 13 | Jan 17, | SYSTEM | \$23,037.00 | This adjustment offsets the original system-generated Material Payment | | | | | | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|----------------|---|--------------------|-----------------------------|----------------|-----------------|---------------|-----------------------|---|
| J4P3443 | 1880 | REINFORCING STEEL (EPOXY | Material | | | 2024 | | | Estimate Item Adjustment (0012) due to user raybol1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | COATED) | | | 13 | Jan 17, 2024 | SYSTEM | (\$23,037.00) | |
| | | | | | 14 | Feb 2, 2024 | SYSTEM | \$23,037.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 14 | Feb 2, 2024 | SYSTEM | (\$23,037.00) | |
| | | | | - Total | | | | \$0.00 | |
| | 1880 - | T-4-1 | Material - To | tal | | | | \$0.00 | |
| | | | Matarial | | 0 | 0-40 | OVOTEM | \$0.00 | This call to the control of the the control of the |
| | 1910 | PLAIN NEOPRENE BEARING PAD | Material | | 6 | Oct 2, 2023 | SYSTEM | \$1,110.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user raybol1 overridding Payment Estimate Exception 38 on the current Payment Estimate. |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$1,110.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 1910 - | Total | | | | | | \$0.00 | |
| | 1920 | LAMINATED NEOPRENE BEARING PAD | Material | | 6 | Oct 2, 2023 | SYSTEM | \$2,520.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user raybol1 overridding Payment Estimate Exception 40 on the current Payment Estimate. |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$2,520.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 1920 - | Total | | | | | | \$0.00 | |
| | 1930 | LAMINATED NEOPRENE BEARING PAD (TAPERED) | Material | | 6 | Oct 2, 2023 | SYSTEM | \$1,890.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user raybol1 overridding Payment Estimate Exception 42 on the current Payment Estimate. |
| | | (IAI LILLD) | | | 6 | Oct 2, 2023 | SYSTEM | (\$1,890.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 1930 - | | | | | | | \$0.00 | |
| | 1940 | CLASS 1 EXCAVATION | Overrun | Overrun | | Oct 2, 2023 | SYSTEM | (\$2,904.00) | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | \$2,904.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',88.00000 - 88.00000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - To | tal | | | | \$0.00 | |
| | 1940 - 1960 | BRIDGE APPROACH SLAB | Material | | 7 | Oct 16, 2023 | SYSTEM | \$0.00 \$53,760.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user raybol1 overridding Payment |
| | | (MAJOR ROAD) | | | 7 | Oct 16, 2023 | SYSTEM | (\$53,760.00) | Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | \$53,760.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user raybol1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | 8 | 8 | Nov 2, 2023 | SYSTEM | (\$53,760.00) | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | \$53,760.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | (\$53,760.00) | |
| | | | | | 10 | Dec 4, 2023 | SYSTEM | \$53,760.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 10 | Dec 4, 2023 | SYSTEM | (\$53,760.00) | |



| APPROACH SLAB (MAJOR ROAD) | t Line | Description | Adjustment Type | Other Adjustment | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | | |
|---|-----------|-------------------------------|--------------------|---------------------|----------------|-----------------|---------------|---------------|---|---|----------|---|--------|------------|------------|--------------|---|--|--------|------------|--|
| MAJOR ROAD | | | Material | Туре | 11 | Dec 18, | SYSTEM | \$53,760.00 | This adjustment offsets the original system-generated Material Payment | | | | | | | | | | | | |
| 1980 Total 1990 | A | | | | | 2023 | | | Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | | | | | | | | | | | |
| 1900 Total 1900 | | | | | 11 | | SYSTEM | (\$53,760.00) | | | | | | | | | | | | | |
| 1970 SALVANIZED STELL PILES (1) Sep 18, SYSTEM S57,060,00 This adjustment offsets the original system-generates | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | |
| Material | | | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | | |
| STRECTURAL STEEL PILES 1/2 | 1960 - To | otal | | | | | | \$0.00 | | | | | | | | | | | | | |
| Sep 18, SYSTEM (\$57,060.00) | | STRUCTURAL STEEL PILES (12 | Material | | 5 | | SYSTEM | \$57,060.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 15 on the current Payment Estimate. | | | | | | | | | | | | |
| 2023 SYSTEM | | IN | | | 5 | | SYSTEM | (\$57,060.00) | | | | | | | | | | | | | |
| 2023 7 | | | | | 6 | | SYSTEM | \$57,060.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user raybol1 overridding Payment Estimate Exception 15 on the current Payment Estimate. | | | | | | | | | | | | |
| 2023 Estimate Item Adjustment (0017) due to user raybolf | | | | | 6 | | SYSTEM | (\$57,060.00) | | | | | | | | | | | | | |
| 2023 8 | | | | | | 7 | | SYSTEM | \$57,060.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate. | | | | | | | | | | | |
| 8 | | | | | 7 | | SYSTEM | (\$57,060.00) | | | | | | | | | | | | | |
| Total S0.00 | | | | | 8 | Nov 2, 2023 | SYSTEM | \$57,060.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user raybol1 overridding Payment Estimate Exception 21 on the current Payment Estimate. | | | | | | | | | | | | |
| Noverrun Overrun Overrun Social | | | | | 8 | | SYSTEM | (\$57,060.00) | | | | | | | | | | | | | |
| Material - Total | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | |
| 2023 9 | | | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | | |
| 2023 Spreyous payment estimates. Price Adjustments of ',1 applied (if non-zero). | | | | | Overrun | 5 | | SYSTEM | (\$8,820.00) | | | | | | | | | | | | |
| 1970 - Total 1970 - Total 1990 PILE POINT REINFORCEMENT Material 4 Sep 5, 2023 SYSTEM \$810.00 This adjustment offsets the original system-generated Estimate Item Adjustment (0006) due to user raybol's Estimate Exception 8 on the current Payment Estimate Exception 8 on the current Payment Estimate Exception 8 on the current Payment Estimate Estimate Item Adjustment (0019) due to user raybol's Estimate Exception 16 on the current Payment Estimate Exception 16 on the current Payment Estimate Exception 16 on the current Payment Estimate Exception 17 on the current Payment Estimate Estimate Item Adjustment (0020) due to user raybol's Estimate Exception 17 on the current Payment Estimate Exception 18 on the current | | | | | 9 | | SYSTEM | \$8,820.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',120.00000 - 120.00000, 'is applied (if non-zero). | | | | | | | | | | | | |
| 1970 - Total 1990 PILE POINT REINFORCEMENT Material 4 Sep 5, 2023 SYSTEM \$810.00 This adjustment offsets the original system-generated Estimate Exception 8 on the current Payment Estimate Estimate Item Adjustment (0006) due to user raybol1 Estimate Item Adjustment (0019) due to user raybol1 Estimate Item Adjustment (0019) due to user raybol1 Estimate Exception 16 on the current Payment Estimate Estimate Item Adjustment (0019) due to user raybol1 Estimate Exception 16 on the current Payment Estimate Item Adjustment (0020) due to user raybol1 Estimate Item Adjustment (0020) due to user raybol1 Estimate Exception 17 on the current Payment Estimate Item Adjustment (0020) due to user raybol1 Estimate Exception 17 on the current Payment Estimate Item Adjustment (0020) due to user raybol1 Estimate Exception 17 on the current Payment Estimate Item Adjustment (0020) due to user raybol1 Estimate Exception 17 on the current Payment Estimate Item Adjustment (0020) due to user raybol1 Estimate Exception 17 on the current Payment Estimate Item Adjustment (0020) due to user raybol1 Estimate Item Adjustment (0020) due to user raybol2 Estimate Item Adjustment (0020) due to user raybol2 Estimate Item Adjustment (0020) due to user raybol3 Estimate Item Adjustment (0020) due to user raybol3 Estimate Item Adjustment (0020) due to user raybol3 Esti | | | | Overrun - To | otal | | | \$0.00 | | | | | | | | | | | | | |
| PILE POINT REINFORCEMENT Material 4 Sep 5, 2023 SYSTEM \$810.00 This adjustment offsets the original system-generated Estimate Item Adjustment (0006) due to user raybold Estimate Exception 8 on the current Payment Estimate Item Adjustment (0019) due to user raybold Estimate Item Adjustment (0019) due to user raybold Estimate Item Adjustment (0019) due to user raybold Estimate Exception 16 on the current Payment Estim 5 Sep 18, 2023 SYSTEM \$810.00 This adjustment offsets the original system-generated Estimate Item Adjustment (0019) due to user raybold Estimate Item Adjustment (0020) due to user raybold Estimate Item Adjustment (0020) due to user raybold Estimate Exception 17 on the current Payment Estim 6 Oct 2, 2023 7 Oct 16, SYSTEM \$810.00 This adjustment offsets the original system-generated Estimate Item Adjustment (0018) due to user raybold Estimate Item Adjustment (0018) due to us | | | Overrun - To | tal | | | | \$0.00 | | | | | | | | | | | | | |
| REINFORCEMENT 2023 Estimate Item Adjustment (0006) due to user raybol1 Estimate Exception 8 on the current Payment Estimate Exception 8 on the current Payment Estimate Estimate Exception 8 on the current Payment Estimate Estimate Item Adjustment (0019) due to user raybol1 Estimate Exception 16 on the current Payment Estim 5 Sep 18, 2023 SYSTEM (\$810.00) SYSTEM (\$810.00) This adjustment offsets the original system-generated Estimate Item Adjustment (0020) due to user raybol1 Estimate Exception 17 on the current Payment Estim Estimate Exception 17 on the current Payment Estim 6 Oct 2, 2023 SYSTEM (\$810.00) This adjustment offsets the original system-generated Estimate Exception 17 on the current Payment Estim Estimate Exception 17 on the current Payment Estim Estimate Exception 17 on the current Payment Estim Estimate Item Adjustment (0020) due to user raybol1 Estimate Item Adjustment offsets the original system-generated Estimate Item Adjustment (0018) due to user raybol1 | 1970 - To | otal | | | | | | \$0.00 | | | | | | | | | | | | | |
| 5 Sep 18, 2023 SYSTEM \$810.00 This adjustment offsets the original system-generated Estimate Item Adjustment (0019) due to user raybold Estimate Exception 16 on the current Payment Estim 5 Sep 18, 2023 (\$810.00) 6 Oct 2, 2023 SYSTEM \$810.00 This adjustment offsets the original system-generated Estimate Item Adjustment (0020) due to user raybold Estimate Exception 17 on the current Payment Estim 6 Oct 2, 2023 SYSTEM (\$810.00) 7 Oct 16, SYSTEM \$810.00 This adjustment offsets the original system-generated Estimate Item Adjustment (0018) due to user raybold Estimate Item Adjustment (| | | Material | | 4 | | SYSTEM | \$810.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | | | | | | |
| Estimate Item Adjustment (0019) due to user raybol1 Estimate Exception 16 on the current Payment Estim 5 Sep 18, 2023 6 Oct 2, 2023 SYSTEM \$810.00 This adjustment offsets the original system-generater Estimate Item Adjustment (0020) due to user raybol1 Estimate Exception 17 on the current Payment Estim 6 Oct 2, 2023 7 Oct 16, SYSTEM \$810.00 This adjustment offsets the original system-generater (system) This adjustment offsets the original system-generater (2023) This adjustment offsets the original system-generater (2023) | | | | | | | | | | | | 4 | | SYSTEM | (\$810.00) | | | | | | |
| 6 Oct 2, 2023 6 Oct 2, 2023 6 Oct 2, 2023 Cot 16, 2023 7 Oct 16, 2023 SYSTEM \$810.00 This adjustment offsets the original system-generated Estimate Item Adjustment (0020) due to user raybol1 Estimate Exception 17 on the current Payment Estim (\$810.00) This adjustment offsets the original system-generated Estimate Item Adjustment (0018) due to user raybol1 | | | | | | | | | | | | | | | | | | | | 5 | |
| 2023 Estimate Item Adjustment (0020) due to user raybol1 Estimate Exception 17 on the current Payment Estim 6 Oct 2, 2023 7 Oct 16, SYSTEM \$810.00 This adjustment offsets the original system-generated Estimate Item Adjustment (0018) due to user raybol1 | | | | 6 | 6 | 6 | 6 | | | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | | SYSTEM | (\$810.00) | |
| 7 Oct 16, SYSTEM \$810.00 This adjustment offsets the original system-generated Estimate Item Adjustment (0018) due to user raybol1 | | | | | | | | 6 | | SYSTEM | \$810.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate. | | | | | | | | | |
| 7 Oct 16, SYSTEM \$810.00 This adjustment offsets the original system-generated Estimate Item Adjustment (0018) due to user raybol1 | | | | | | | | 6 | 6 | 6 | 6 | | SYSTEM | (\$810.00) | | | | | | | |
| | | | | | | 7 | Oct 16, | SYSTEM | \$810.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user raybo11 overridding Payment Estimate Exception 18 on the current Payment Estimate. | | | | | | | | | | | |
| 7 Oct 16, 2023 (\$810.00) | | | | | 7 | | SYSTEM | (\$810.00) | | | | | | | | | | | | | |
| 2023 Estimate Item Adjustment (0026) due to user raybol1 | | | | | 8 | 8 | | SYSTEM | \$1,620.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user raybol1 overridding Payment Estimate Exception 23 on the current Payment Estimate. | | | | | | | | | | | |
| 8 Nov 2, 2023 (\$1,620.00) | | | | | | | | | | | | | 8 | | SYSTEM | (\$1,620.00) | | | | | |
| - Total \$0.00 | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | |
| Material - Total \$0.00 | | | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | |
|---------|--------|---------------------------------------|--------------------|-----------------------------|----------------|-----------------|----------------|------------------------|---|---|
| 4P3443 | 1990 - | Total | | | | | | \$0.00 | | |
| | 2000 | CLASS B CONCRETE (SUBSTRUCTURE) | Material | rial | 3 | Aug 16, 2023 | SYSTEM | \$75,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | |
| | | | | | 3 | Aug 16, 2023 | SYSTEM | (\$75,000.00) | | |
| | | | | | 4 | Sep 5, 2023 | SYSTEM | \$123,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 15 on the current Payment Estimate. | |
| | | | | | 4 | Sep 5, 2023 | SYSTEM | (\$123,600.00) | | |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | \$123,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user raybol1 overridding Payment Estimate Exception 21 on the current Payment Estimate. | |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | (\$123,600.00) | | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | \$123,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user raybol1 overridding Payment Estimate Exception 21 on the current Payment Estimate. | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$123,600.00) | | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | \$123,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user raybol1 overridding Payment Estimate Exception 21 on the current Payment Estimate. | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | (\$123,600.00) | | |
| | | | | | | 8 | Nov 2, 2023 | SYSTEM | \$123,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user raybol1 overridding Payment Estimate Exception 26 on the current Payment Estimate. |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$123,600.00) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - To | | | | | \$0.00 | | |
| | 2000 - | Total | | | | | | \$0.00 | | |
| | 2010 | TYPE D BARRIER | Material | Material | 7 | Oct 16, 2023 | SYSTEM | \$119,750.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user raybol1 overridding Payment Estimate Exception 25 on the current Payment Estimate. | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | (\$119,750.00) | | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | \$119,750.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user raybol1 overridding Payment Estimate Exception 28 on the current Payment Estimate. | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$119,750.00) | | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | \$119,750.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user raybol1 overridding Payment Estimate Exception 13 on the current Payment Estimate. | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | (\$119,750.00) | | |
| | | | | | | 10 | Dec 4, 2023 | SYSTEM | \$119,750.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 10 | Dec 4, 2023 | SYSTEM | (\$119,750.00) | | |
| | | | | | 11 | Dec 18, 2023 | SYSTEM | \$119,750.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | |
| | | | | | 11 | Dec 18, 2023 | SYSTEM | (\$119,750.00) | | |
| | | | | - Total | | | | \$0.00 | | |
| | 2040- | Total | Material - To | tal | | | | \$0.00 | | |
| | 2010 - | SLAB ON CONCRETE NU- | Material | | 5 | Sep 18, 2023 | SYSTEM | \$0.00 \$226,260.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user raybol1 overridding Payment | |
| | | GIRDER | | | 5 | Sep 18, | SYSTEM | (\$226,260.00) | Estimate Exception 24 on the current Payment Estimate. | |
| | | | | | | 2023 | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|-----------------|------------------------------|---|---|--------------|---|--------|-------------|---|
| J4P3443 | 2020 | SLAB ON CONCRETE NU- GIRDER | Material | | 6 | Oct 2, 2023 | SYSTEM | \$377,100.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user raybol1 overridding Payment Estimate Exception 25 on the current Payment Estimate. | | | | | | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$377,100.00) | | | | | | | |
| | | | | | | 7 | Oct 16, 2023 | SYSTEM | \$377,100.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user raybol1 overridding Payment Estimate Exception 26 on the current Payment Estimate. | | | | | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | (\$377,100.00) | | | | | | | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | \$377,100.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user raybol1 overridding Payment Estimate Exception 29 on the current Payment Estimate. | | | | | | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$377,100.00) | | | | | | | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | \$377,100.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate. | | | | | | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | (\$377,100.00) | | | | | | | |
| | | | | | 10 | Dec 4, 2023 | SYSTEM | \$377,100.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 13 on the current Payment Estimate. | | | | | | |
| | | | | | 10 | Dec 4, 2023 | SYSTEM | (\$377,100.00) | | | | | | | |
| | | | | | 11 | Dec 18, 2023 | SYSTEM | \$377,100.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 13 on the current Payment Estimate. | | | | | | |
| | | | | | 11 | Dec 18, 2023 | SYSTEM | (\$377,100.00) | | | | | | | |
| | | | | | 12 | Jan 2, 2024 | SYSTEM | \$377,100.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user moses 2 overridding Payment Estimate Exception 11 on the current Payment Estimate. | | | | | | |
| | | | | | 12 | Jan 2, 2024 | SYSTEM | (\$377,100.00) | | | | | | | |
| | | | | | | | | 13 | Jan 17, 2024 | SYSTEM | \$377,100.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 11 on the current Payment Estimate. | | | |
| | | | | | 13 | Jan 17, 2024 | SYSTEM | (\$377,100.00) | | | | | | | |
| | | | | | 14 | Feb 2, 2024 | SYSTEM | \$377,100.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | |
| | | | | | 14 | Feb 2, 2024 | SYSTEM | (\$377,100.00) | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | |
| | | _ | Material - To | al | | | | \$0.00 | | | | | | | |
| | 2020 - | FORM LINERS | Material | | 6 | Oct 2, 2023 | SYSTEM | \$0.00 \$14,141.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user raybol1 overridding Payment Estimate Exception 29 on the current Payment Estimate. | | | | | | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$14,141.00) | | | | | | | |
| | | | | | | | | | | | 7 | Oct 16, 2023 | SYSTEM | \$14,141.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user raybol1 overridding Payment Estimate Exception 30 on the current Payment Estimate. |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | (\$14,141.00) | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | |
| | 2020 | Total | Material - To | al | | | | \$0.00 | | | | | | | |
| | 2030 - | NU 43, PRESTRESSED CONC NU-GIRDER | Material | | 4 | Sep 5, 2023 | SYSTEM | \$0.00 \$211,140.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate. | | | | | | |
| | | CONC NU-GIRDER | | | 4 | Sep 5, 2023 | SYSTEM | (\$211,140.00) | | | | | | | |
| | | | | | 5 | Sep 18, | SYSTEM | \$422,280.00 | This adjustment offsets the original system-generated Material Payment | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|-----------------|-----------------|---|---|---|-----------------|-----------------|---------------|-------------|---|---|----------------|--------|-------------|
| J4P3443 | 2050 | NU 43, PRESTRESSED CONC NU-GIRDER | Material | | | 2023 | | | Estimate Item Adjustment (0022) due to user raybol1 overridding Payment Estimate Exception 28 on the current Payment Estimate. | | | | | | | | | | | |
| | | CONC NO-GINDEN | | | 5 | Sep 18, 2023 | SYSTEM | (\$422,280.00) | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | |
| | 2050 - | | | | | | | \$0.00 | | | | | | | | | | | | |
| | 2060 | CONDUIT SYSTEM ON STRUCTURE | Material | | 6 | Oct 2, 2023 | SYSTEM | \$27,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user raybol1 overridding Payment Estimate Exception 33 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$27,500.00) | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | |
| | 2060 - | Total | | | | | | \$0.00 | | | | | | | | | | | | |
| | 2070 | REINFORCING STEEL (EPOXY COATED) | Material | | 3 | Aug 16, 2023 | SYSTEM | \$32,592.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 6 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 3 | Aug 16, 2023 | SYSTEM | (\$32,592.00) | | | | | | | | | | | | |
| | | | | | 4 | Sep 5, 2023 | SYSTEM | \$32,592.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 21 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | | | | | 4 | Sep 5, 2023 | SYSTEM | (\$32,592.00) | | | | | | | | |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | \$32,592.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user raybol1 overridding Payment Estimate Exception 33 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | (\$32,592.00) | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | 6 | Oct 2, 2023 | SYSTEM | \$32,592.00 |
| | | | | | | | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$32,592.00) | | | | | | |
| | | | | | | | 7 | Oct 16, 2023 | SYSTEM | \$32,592.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user raybol1 overridding Payment Estimate Exception 35 on the current Payment Estimate. | | | | | | | | | |
| | | | | | | 7 | Oct 16, 2023 | SYSTEM | (\$32,592.00) | | | | | | | | | | | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | \$32,592.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user raybol1 overridding Payment Estimate Exception 37 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$32,592.00) | | | | | | | | |
| | | | | | | | | | | | | 9 | Nov 16, 2023 | SYSTEM | \$32,592.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user raybol1 overridding Payment Estimate Exception 20 on the current Payment Estimate. | | | | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | (\$32,592.00) | | | | | | | | | | | | |
| | | | | | 10 | Dec 4, 2023 | SYSTEM | \$32,592.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 18 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 10 | Dec 4, 2023 | SYSTEM | (\$32,592.00) | | | | | | | | | | | | |
| | | | | | 11 | Dec 18, 2023 | SYSTEM | \$32,592.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 18 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | | | | | | | 11 | Dec 18, 2023 | SYSTEM | (\$32,592.00) | | | | | | |
| | | | | | | 12 | Jan 2, 2024 | SYSTEM | \$32,592.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user mosesj2 overridding Payment Estimate Exception 16 on the current Payment Estimate. | | | | | | | | | | |
| | | | | | 12 | Jan 2, 2024 | SYSTEM | (\$32,592.00) | | | | | | | | | | | | |
| | | | | | | 13 | Jan 17, 2024 | SYSTEM | \$32,592.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--------------------------------------|--------------------|-----------------------------|----------------|-----------------|-----------------|---------------|---|
| J4P3443 | 2070 | REINFORCING | Material | | | | | | Estimate Exception 16 on the current Payment Estimate. |
| | | STEEL (EPOXY COATED) | | | 13 | Jan 17, 2024 | SYSTEM | (\$32,592.00) | |
| | | | | | 14 | Feb 2, 2024 | SYSTEM | \$32,592.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user raybol1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 14 | Feb 2, 2024 | SYSTEM | (\$32,592.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 2070 - | Total | | | | | | \$0.00 | |
| | 2090 | VERTICAL DRAIN AT END BENTS | Material | | 5 | Sep 18, 2023 | SYSTEM | \$3,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user raybol1 overridding Payment Estimate Exception 34 on the current Payment Estimate. |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | (\$3,800.00) | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | \$3,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user raybol1 overridding Payment Estimate Exception 37 on the current Payment Estimate. |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$3,800.00) | |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | \$3,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user raybol1 overridding Payment Estimate Exception 36 on the current Payment Estimate. |
| | | | | | 7 | Oct 16, 2023 | SYSTEM | (\$3,800.00) | |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | \$3,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user raybol1 overridding Payment Estimate Exception 38 on the current Payment Estimate. |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$3,800.00) | |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | \$3,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user raybol1 overridding Payment Estimate Exception 21 on the current Payment Estimate. |
| | | | | | 9 | Nov 16, 2023 | SYSTEM | (\$3,800.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 2090 - | Total | | | | | | \$0.00 | |
| | 2100 | PLAIN NEOPRENE BEARING PAD | Material | Material | 4 | Sep 5, 2023 | SYSTEM | \$1,480.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate. |
| | | | | | 4 | Sep 5, 2023 | SYSTEM | (\$1,480.00) | |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | \$1,480.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user raybol1 overridding Payment Estimate Exception 35 on the current Payment Estimate. |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | (\$1,480.00) | |
| | | | | | 6 | 6 | Oct 2, 2023 | SYSTEM | \$1,480.00 |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$1,480.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 2100 - | | | | | | | \$0.00 | |
| | 2110 | LAMINATED NEOPRENE BEARING PAD | Material | | 4 | Sep 5, 2023 | SYSTEM | \$3,360.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 23 on the current Payment Estimate. |
| | | | | | 4 | Sep 5, 2023 | SYSTEM | (\$3,360.00) | |
| | | | | | | 5 | Sep 18, 2023 | SYSTEM | \$3,360.00 |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| J4P3443 | 2110 | LAMINATED NEOPRENE BEARING PAD | Material | | 5 | Sep 18, 2023 | SYSTEM | (\$3,360.00) | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | \$3,360.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user raybol1 overridding Payment Estimate Exception 41 on the current Payment Estimate. |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$3,360.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 2110 - | Total | | | | | | \$0.00 | |
| | 2120 | LAMINATED NEOPRENE BEARING PAD | Material | | 4 | Sep 5, 2023 | SYSTEM | \$2,520.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user raybol1 overridding Payment Estimate Exception 24 on the current Payment Estimate. |
| | | (TAPERED) | | | 4 | Sep 5, 2023 | SYSTEM | (\$2,520.00) | |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | \$2,520.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user raybol1 overridding Payment Estimate Exception 37 on the current Payment Estimate. |
| | | | | | 5 | Sep 18, 2023 | SYSTEM | (\$2,520.00) | |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | \$2,520.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user raybol1 overridding Payment Estimate Exception 43 on the current Payment Estimate. |
| | | | | | 6 | Oct 2, 2023 | SYSTEM | (\$2,520.00) | |
| | | | | - Total | | 2020 | | \$0.00 | |
| | | | Material - Tot | | | | | \$0.00 | |
| | 2120 - | Total | | | | | | \$0.00 | |
| | | TEMPORARY PIPE | Material | | 4 | Sep 5, 2023 | SYSTEM | \$7,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user raybol1 overridding Payment Estimate Exception 25 on the current Payment Estimate. |
| | | | | | 4 | Sep 5, 2023 | SYSTEM | (\$7,200.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 5002 - | Total | | | | | | \$0.00 | |
| | 5005 | REPLACEMENT SAND BARREL | Material | | 8 | Nov 2, 2023 | SYSTEM | \$4,725.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user raybol1 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$4,725.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 5005 - | Total | | | | | | \$0.00 | |
| | 5006 | TEMPORARY PIPE | Material | | 8 | Nov 2, 2023 | SYSTEM | \$3,422.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user raybol1 overridding Payment Estimate Exception 40 on the current Payment Estimate. |
| | | | | | 8 | Nov 2, 2023 | SYSTEM | (\$3,422.40) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 5006 - | Total | | | | | | \$0.00 | |
| | 5010 | TEMPORARY REMOVABLE MARKING TAPE 4 | Material | | 14 | Feb 2, 2024 | SYSTEM | \$9,556.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user raybol1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | IN., | | | 14 | Feb 2, 2024 | SYSTEM | (\$9,556.80) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 5010 - | Total | | | | | | \$0.00 | |
| | 5011 | TEMPORARY REMOVABLE MARKING TAPE | Material | | 14 | Feb 2, 2024 | SYSTEM | \$2,112.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user raybol1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |

Feb 6, 2024



Line Item Adjustments by Estimate

| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------|------------------|--|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---------|
| J4P3443 | 5011 | TEMPORARY REMOVABLE MARKING TAPE | Material | | 14 | Feb 2, 2024 | SYSTEM | (\$2,112.00) | |
| | | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | | \$0.00 | |
| | 5011 - Total | | | | | | | | |
| J4P3443 - | Total | | | | | | \$40,591.06 | | |
| Overall - | Total | | | | | | \$40,591.06 | | |



Contract Adjustments for Contract - 230519-C04

| Estimate Number | Project | Adjustment Type | Other Adjustment Type | Adjustment Amount | Adjustment Percentage by Project | Created Date | Created By | Comments |
|--------------------|---------|------------------------------|--------------------------|----------------------|-------------------------------------|-----------------|---------------|---|
| 7 | J4P3443 | Other Contract Adjustment | | (\$155.26) | 100 | Oct 16, 2023 | raybol1 | 9/25/2023 to 9/26/2023 - Signing Materials Inspection by Sam Marshall |
| 7 - Total | | | | | (\$155.26) | | | |
| Overall - Total | | | | | (\$155.26) | | | |

Revision 3/23/2023 Page 36 of 36