

| Progress Es<br>N<br>9 | timate<br>umber  | Contract ID<br>Prime<br>Contractor | Rad        | 519-C04<br>macher Brothers Exc<br>Inc. | cavating                              | Pay Period<br>Start<br>Pay Period End | November 2, 202<br>November 15,<br>2023 | <sup>23</sup> Original Contract<br>Amount<br>Net Change Order<br>Amount | \$10,985,676.85<br>(\$196,262.46) |
|-----------------------|--|------------------------------------|------------|--|---------------------------------------|---------------------------------------|---|---|-----------------------------------|
|                       |  |                                    | - ,        |  |                                       |                                       |   | Current Contract Amou   | nt \$10,789,414.39                |
| Approval Date         |  |                                    |            |  |                                       |                                       |   |   | By User                           |
| November 16,<br>2023  |  |                                    |            | Generated and                          | Approve                               | ed (and should be con                 | ne Project Office Level by              | raybol1   |                                   |
| November 16,<br>2023  | Reviewed and Approved (and should be considered Draft) at the Resident Er  |                                    |            |  |                                       |                                       |   |   | penner1                           |
| November 17,<br>2023  | r 17, Reviewed and Approved at the Central Office Controllers Office Level |                                    |            |  |                                       |                                       |   |   |                                   |
| Original Complet      | ion Date   | e C                                | urrent Co  | mpletion Date                          | pletion Date Actual Completion Date % |                                       |   | f Current Contract Amou   | nt Complete                       |
| June 28, 20           | 24   |                                    | June       | 28, 2024 55                            |                                       |                                       | 59.81%                                  |   |                                   |
|                       | Cont   | ract Informa                       | tional Dat | tes                                    |                                       | Mileston                              | es                                      |   |                                   |
| Date Description      | Origi  | inal Complet                       | ion Date   | Current Completio                      | on Date                               | No Milestones Exist                   | for Contract                            |   |                                   |
| Acceptance Date       |  |                                    |            |  |                                       |                                       |   |   |                                   |
| Awarded Date          | June   | 7, 2023                            |            | June 7, 2023                           |                                       |                                       |   |   |                                   |
| Letting Date          | Date May 19, 2023 May 19, 2023   |                                    |            |  |                                       |                                       |   |   |                                   |
| Notice to Proceed Da  | e July   | 10, 2023                           |            | July 10, 2023                          |                                       |                                       |   |   |                                   |
| Open to Traffic Date  |  |                                    |            |  |                                       |                                       |   |   |                                   |
| Work Began Date       | July '   | 17, 2023                           |            | July 17, 2023                          |                                       |                                       |   |   |                                   |

| Contract Total Pay F        | or Estimate No. 9          |               |                |                |
|-----------------------------|----------------------------|---------------|----------------|----------------|
|                             |                            | This Estimate | Previous       | To Date        |
| 230519-C04                  |                            |               |                |                |
|                             | Total Posted Items Pay     | \$919,510.30  | \$5,533,670.57 | \$6,453,180.87 |
|                             | Gross Item Adjustments     | \$52,353.46   | \$492.00       | \$52,845.46    |
|                             | Incentive                  | \$0.00        | \$0.00         | \$0.00         |
|                             | Disincentive               | \$0.00        | \$0.00         | \$0.00         |
|                             | Liquidated Damage          | \$0.00        | \$0.00         | \$0.00         |
|                             | Other Contract Adjustments | \$0.00        | (\$155.26)     | (\$155.26)     |
|                             | -                          |               | \$5,534,007.31 | \$6,505,871.07 |
| <b>Contract Total Payab</b> | le This Estimate:          | \$971.863.76  |                |                |

# Items Paid This Estimate Period

| Project<br>Number | Line<br>Number | Item<br>Code | Item Description   | Unit | Unit Price  | Current Installed<br>Qty | Current Installed<br>Amount |
|-------------------|----------------|--------------|--|------|-------------|--------------------------|-----------------------------|
| J4P3443           | 0110           | 3049905      | MISC.OPTIONAL BASE   | SQYD | \$14.000    | 861.9                    | \$12,066.60                 |
|                   | 0120           | 4019905      | MISC.OPTIONAL PAVEMENT                                       | SQYD | \$105.000   | 861.9                    | \$90,499.50                 |
|                   | 0150           | 5041000      | CONCRETE APPROACH PAVEMENT                                   | SQYD | \$180.000   | 76                       | \$13,680.00                 |
|                   | 0220           | 6113010      | FURNISHING TYPE 1 ROCK BLANKET                               | CUYD | \$56.000    | 5                        | \$280.00                    |
|                   | 0230           | 6113030      | PLACING TYPE 1 ROCK BLANKET                                  | CUYD | \$22.000    | 5                        | \$110.00                    |
|                   | 0320           | 6161005      | CONSTRUCTION SIGNS   | SQFT | \$6.300     | 59                       | \$371.70                    |
|                   | 0620           | 6207001      | PAVEMENT MARKING REMOVAL                                     | LF   | \$0.600     | 1,457                    | \$874.20                    |
|                   | 0650           | 6240103A     | PERMANENT EROSION CONTROL GEOTEXTILE                         | SQYD | \$3.800     | 22                       | \$83.60                     |
|                   | 0820           | 8025006      | MULCHING   | ACRE | \$470.000   | 1.6                      | \$752.00                    |
|                   | 0830           | 8051000A     | SEEDING - COOL SEASON GRASSES                                | ACRE | \$2,700.000 | 1.6                      | \$4,320.00                  |
|                   | 0890           | 8064128      | TYPE 1 TURF REINFORCEMENT MAT                                | SQYD | \$3.100     | -881                     | (\$2,731.10                 |
|                   | 0900           | 8064138      | TYPE 2D EROSION CONTROL BLANKET                              | SQYD | \$2.400     | 500                      | \$1,200.00                  |
|                   | 0940           | 3049905      | MISC.ALTERNATE BASE  | SQYD | \$12.000    | 1,832                    | \$21,984.00                 |
|                   | 0950           | 5021334      | CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS) | SQYD | \$98.000    | 4,449.1                  | \$436,011.80                |
|                   | 0980           | 5021340      | TYPE A2 SHOULDER   | SQYD | \$55.000    | 423.6                    | \$23,298.00                 |
|                   | 1870           | 7056022      | NU 43, PRESTRESSED CONCRETE NU-GIRDER                        | LF   | \$510.000   | 621                      | \$316,710.00                |
| roject J4P3       | 443 - Total    |              |  |      |             |                          | \$919,510.30                |



|                   | Progre<br>9 | ess Estimat<br>Numbe |   |                    | 230519-C04<br>Radmacher E<br>Co.,Inc. | Brothers Exca                    | vating  | Pay Period<br>Start<br>Pay Period En   |                                     | per 15,                                  | Original Con<br>Amount<br>Net Change<br>Amount<br>Current Cont | Order                                 | \$10,985,676.85<br>(\$196,262.46)<br>t \$10,789,414.39 |
|-------------------|-------------|----------------------|---|--------------------|---------------------------------------|----------------------------------|---|--|-------------------------------------|--|--|---------------------------------------|--|
| Proje<br>Numb     |             | Line<br>Number       | ltem<br>Code                                  |                    |                                       | Item Descrip                     | otion   |  | Unit                                | Unit Price                               | e Current Ins<br>Qty   | stalled Cu                            | urrent Installed<br>Amount                             |
| Overall           | - Total     |                      |   |                    |                                       |                                  |   |  |                                     |  |  |                                       | \$919,510.30   |
| ontract /         | Adjustr     | nents This           | Estimate                                      |                    |                                       |                                  |   |  |                                     |  |  |                                       |  |
|                   |             | stments Exis         |   | act                |                                       |                                  |   |  |                                     |  |  |                                       |  |
|                   |             | ments This           |   | uor                |                                       |                                  |   |  |                                     |  |  |                                       |  |
| Project<br>Number | Line<br>No. | Iten                 | n Descriptio                                  | on                 | Adjustment<br>Type                    | Other Item<br>Adjustment<br>Type |   | Commen   | ts                                  |  | Adjustment<br>Quantity   | Line Item<br>Adjustment<br>Unit Price | Adjustment<br>amount                                   |
| 4P3443            | 0100        |                      | AGGREGA<br>BASE (6 IN                         |                    | Material                              |                                  |   |  |                                     |  | -230   | \$14.00                               | (\$3,220.00  |
|                   | 0100        |                      | AGGREGA<br>BASE (6 IN                         |                    | Material                              |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0002) due to user raybol1<br>overridding Payment Estimate Exception 1 on<br>the current Payment Estimate. |  |                                     | 230                                      | \$14.00  | \$3,220.00                            |  |
|                   | 0110        |                      |   | MISC.              | Material                              |                                  |   |  |                                     |  | -2,146.8   | \$14.00                               | (\$30,055.20   |
|                   | 0110        |                      |   | MISC.              | Material                              |                                  | gener<br>A  | djustment offsets<br>rated Material Pay<br>djustment (0003)<br>ing Payment Estin<br>the current  | ment Est<br>due to us<br>nate Exce  | imate Item<br>ser raybol1<br>eption 2 on | 2,146.8  | \$14.00                               | \$30,055.20  |
|                   | 0140        |                      | TE PAVEN<br>ON-REINF<br>15 FT.                |                    | Material                              |                                  |   |  |                                     |  | -229.1   | \$137.00                              | (\$31,386.70   |
|                   | 0140        |                      | TE PAVEM<br>ON-REINF<br>15 FT.                |                    | Material                              |                                  | gene<br>A   | djustment offsets<br>rated Material Pay<br>djustment (0004)<br>ing Payment Estin<br>the current  | ment Est<br>due to us<br>nate Exce  | imate Item<br>ser raybol1<br>eption 4 on | 229.1  | \$137.00                              | \$31,386.70  |
|                   | 0150        | CONC                 | RETE APP<br>PA                                | PROACH<br>VEMENT   | Material                              |                                  |   |  |                                     |  | -157.4   | \$180.00                              | (\$28,332.00   |
|                   | 0150        | CONC                 | RETE APP<br>PA                                | PROACH<br>VEMENT   | Material                              |                                  | gene<br>A   | djustment offsets<br>rated Material Pay<br>djustment (0005)<br>dding Payment Es<br>on the current  | ment Est<br>due to us<br>timate Ex  | imate Item<br>ser raybol1<br>ception 12  | 157.4  | \$180.00                              | \$28,332.00  |
|                   | 0340        | CHANNE               | LIZER (TR                                     | IM LINE)           | Overrun                               |                                  | a   | Unit price based o<br>djustments for inst<br>previous paym<br>ustments of ',19.0<br>a  | alled qua<br>ent estim<br>0000 - 19 | antity on all<br>ates. Price             | 263  | \$19.00                               | \$4,997.00   |
|                   | 0420        | BARRIE               | PORARY <sup>-</sup><br>ER, CONTE<br>SHED / RE | RACTOR             | Overrun                               |                                  | a   | Unit price based o<br>djustments for inst<br>previous paym<br>ustments of ',16.0<br>a  | alled qua<br>ent estim<br>0000 - 16 | antity on all<br>ates. Price             | 866  | \$16.00                               | \$13,856.00  |
|                   | 0460        |                      | PAVEMEN<br>TRE                                | IT EDGE<br>ATMENT  | Overrun                               |                                  | a   | Unit price based o<br>djustments for inst<br>previous payments of ',6.80000 -  | alled qua<br>ent estim<br>6.80000,  | antity on all<br>ates. Price             | 480  | \$6.80                                | \$3,264.00   |
|                   | 0570        | REMO                 | EMPORAL<br>SVABLE M<br>STRAIGHT               | IARKING            | Overrun                               |                                  | a   | Unit price based on averaged overrun<br>adjustments for installed quantity on all<br>previous payment estimates. Price<br>ljustments of ',132.00000 - 132.00000, 'is<br>applied (if non-zero). |                                     |  | 4  | \$132.00                              | \$528.00   |
|                   | 0580        | REM0<br>TA           | EMPORAL<br>DVABLE M<br>PE COMB<br>IGHT- LEF   | IARKING<br>INATION | Overrun                               |                                  | a   | Unit price based o<br>djustments for inst<br>previous paym<br>tments of ',260.00<br>a  | alled qua<br>ent estim<br>000 - 260 | antity on all<br>ates. Price             | 1  | \$260.00                              | \$260.00   |

|                   | Progre<br>9  | ess Estimate<br>Number                                 | Contract ID<br>Prime<br>Contractor              | 230519-C04<br>Radmacher E<br>Co.,Inc. | Brothers Exca                    | Pay Period<br>Start<br><sup>vating</sup> Pay Period En          | ating Pay Period End <sup>November 15, 2023</sup>  |                        |                                       | \$10,985,676.85<br>(\$196,262.46)<br>: \$10,789,414.39 |
|-------------------|--|--|---|---------------------------------------|----------------------------------|---|--|------------------------|---------------------------------------|--|
| Project<br>Number | Line<br>No.  | Item D   | Description                                     | Adjustment<br>Type                    | Other Item<br>Adjustment<br>Type | Commen  | its  | Adjustment<br>Quantity | Line Item<br>Adjustment<br>Unit Price | Adjustment<br>amount                                   |
| J4P3443           | 0680   | REINF  | ORCING STEEL<br>(CULVERTS)                      | Material                              |                                  |   |  | -6,370                 | \$2.70                                | (\$17,199.00   |
|                   | 0680   | REINF  | ORCING STEEL<br>(CULVERTS)                      | Material                              |                                  | overridding Payment Es  | ment Estimate Item<br>due to user raybol1  |                        | \$2.70                                | \$17,199.00  |
|                   | 0940   |  | MISC.   | Material                              |                                  |   |  | -14,864.8              | \$12.00                               | (\$178,377.60  |
|                   | 0940   |  | MISC.   | Material                              |                                  | overridding Payment Estir                                       | ment Estimate Item<br>due to user raybol1  | 14,864.8               | \$12.00                               | \$178,377.60   |
|                   | 0950 CONCRETE PAVEMENT (1<br>1/2 IN. NON-REINFORCEL<br>15 FT. JOINTS |  |   | Material                              |                                  |   |  | -13,901.1              | \$98.00                               | (\$1,362,307.80  |
|                   | 0950   |  | PAVEMENT (10<br>N-REINFORCED,<br>15 FT. JOINTS) | Material                              |                                  | overridding Payment Estir                                       | /ment Estimate Item<br>due to user raybol1   |                        | \$98.00                               | \$1,362,307.80   |
|                   | 1500   | BREAKAWAY ASSEMBLY<br>(PERFORATED SQUARE<br>STEEL TUBE |   | Construction<br>Stockpile             |                                  | Payment Estimate Item Ac  | djustment generated<br>tockpile Transaction  |                        |                                       | \$2,106.00   |
|                   | 1510   | 2 IN. PSST POST - 12 GA                                |   | Construction<br>Stockpile             |                                  | Payment Estimate Item Ac  | ljustment generated<br>tockpile Transaction  |                        |                                       | \$6,034.08   |
|                   | 1520   |  | POST ANCHOR<br>N. PSST - 12 GA.                 | Construction<br>Stockpile             |                                  | Payment Estimate Item Ac<br>Si                                  | djustment generated<br>tockpile Transaction  |                        |                                       | \$1,195.74   |
|                   | 1530   | 2.25 IN. PSS   | T POST INSERT<br>(6 FT.) - 12 GA.               | Construction<br>Stockpile             |                                  | Payment Estimate Item Ac<br>Si                                  | djustment generated<br>tockpile Transaction  |                        |                                       | \$245.28   |
|                   | 1540   | 2.5 IN. PSS  | T POST - 12 GA.                                 | Construction<br>Stockpile             |                                  | Payment Estimate Item Ac<br>Si                                  | djustment generated<br>tockpile Transaction  |                        |                                       | \$2,184.96   |
|                   | 1550   |  | POST ANCHOR<br>IN. PSST - 7 GA.                 | Construction<br>Stockpile             |                                  | Payment Estimate Item Ac  | djustment generated<br>tockpile Transaction  |                        |                                       | \$1,022.40   |
|                   | 1710   |  | MISC.   | Material                              |                                  |   |  | -1                     | \$27,900.00                           | (\$27,900.00   |
|                   | 1710   |  | MISC.   | Material                              |                                  | overridding Payment Es  | ment Estimate Item<br>due to user raybol1  |                        | \$27,900.00                           | \$27,900.00  |
|                   | 1750   | CLASS  | 1 EXCAVATION                                    | Overrun                               |                                  | adjustments for ins<br>previous paym<br>Adjustments of ',88.0   | n averaged overrun<br>talled quantity on all<br>ent estimates. Price<br>0000 - 88.00000, 'is<br>applied (if non-zero). |                        | \$88.00                               | \$1,936.00   |
|                   | 1790   |  | D STRUCTURAL<br>EL PILES (12 IN)                | Overrun                               |                                  | adjustments for ins<br>previous paym<br>Adjustments of ',120.00 | n averaged overrun<br>talled quantity on all<br>ent estimates. Price<br>000 - 120.00000, 'is<br>applied (if non-zero). |                        | \$120.00                              | \$3,000.00   |
|                   | 1870   |  | PRESTRESSED<br>TE NU-GIRDER                     | Material                              |                                  |   |  | -621                   | \$510.00                              | (\$316,710.00  |
|                   | 1870   |  | PRESTRESSED<br>ETE NU-GIRDER                    | Material                              |                                  | overridding Payment Es  | ment Estimate Item<br>due to user raybol1  |                        | \$510.00                              | \$316,710.00   |
|                   | 1880   | REINF  | ORCING STEEL                                    | Material                              |                                  |   |  | -10,970                | \$2.10                                | (\$23,037.00   |



|                   | Progre<br>9 | ss Estimate<br>Number | Contract ID<br>Prime<br>Contractor | 230519-C04<br>Radmacher B<br>Co.,Inc. | rothers Exca                     | Pay Period<br>Start<br><sup>vating</sup> Pay Period E              | November 2, 2023<br>nd November 15,<br>2023  | Net Change (<br>Amount | Order                                 | \$10,985,676.85<br>(\$196,262.46)<br>t \$10,789,414.39 |  |  |  |  |  |  |            |             |
|-------------------|-------------|-----------------------|------------------------------------|---------------------------------------|----------------------------------|--|--|------------------------|---------------------------------------|--|--|--|--|--|--|--|------------|-------------|
| Project<br>Number | Line<br>No. | Item D                | escription                         | Adjustment<br>Type                    | Other Item<br>Adjustment<br>Type | Comme  | ents   | Adjustment<br>Quantity | Line Item<br>Adjustment<br>Unit Price | Adjustment<br>amount                                   |  |  |  |  |  |  |            |             |
| 4P3443            |             | (E                    | POXY COATED)                       |                                       |                                  |  |  |                        |                                       |  |  |  |  |  |  |  |            |             |
|                   | 1880        |                       | ORCING STEEL<br>POXY COATED)       | Material                              |                                  | generated Material Pa<br>Adjustment (0023<br>overridding Payment E | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0023) due to user raybol1<br>overridding Payment Estimate Exception 19<br>on the current Payment Estimate. |                        |                                       | \$23,037.00  |  |  |  |  |  |  |            |             |
|                   | 1940        | CLASS                 | 1 EXCAVATION                       | Overrun                               |                                  | adjustments for in<br>previous payr<br>Adjustments of ',88.        | on averaged overrun<br>stalled quantity on all<br>nent estimates. Price<br>00000 - 88.00000, 'is<br>applied (if non-zero).   |                        | \$88.00                               | \$2,904.00   |  |  |  |  |  |  |            |             |
|                   | 1960        | BRIDGE AF             | PPROACH SLAB<br>(MAJOR)            | Material                              |                                  |  |  | -168                   | \$320.00                              | (\$53,760.00   |  |  |  |  |  |  |            |             |
|                   | 1960        | BRIDGE AF             | PPROACH SLAB<br>(MAJOR)            | Material                              |                                  | overridding Payment Est  | ayment Estimate Item<br>5) due to user raybol1   |                        | \$320.00                              | \$53,760.00  |  |  |  |  |  |  |            |             |
|                   | 1970        |                       | O STRUCTURAL<br>EL PILES (12 IN)   | Overrun                               |                                  | adjustments for in<br>previous payr<br>Adjustments of ',120.0      | on averaged overrun<br>stalled quantity on all<br>nent estimates. Price<br>0000 - 120.00000, 'is<br>applied (if non-zero).   |                        | \$120.00                              | \$8,820.00   |  |  |  |  |  |  |            |             |
|                   | 2010        | T                     | YPE D BARRIER                      | Material                              |                                  |  |  | -479                   | \$250.00                              | (\$119,750.00  |  |  |  |  |  |  |            |             |
|                   | 2010        | Ϋ́                    | YPE D BARRIER                      | Material                              |                                  | overridding Payment E  | ayment Estimate Item<br>') due to user raybol1   |                        | \$250.00                              | \$119,750.00   |  |  |  |  |  |  |            |             |
|                   | 2020        | SLAB ON               | CONCRETE NU-<br>GIRDER             | Material                              |                                  |  |  | -838                   | \$450.00                              | (\$377,100.00  |  |  |  |  |  |  |            |             |
|                   | 2020        | SLAB ON (             | CONCRETE NU-<br>GIRDER             | Material                              |                                  | overridding Payment E  | ayment Estimate Item<br>3) due to user raybol1   |                        | \$450.00                              | \$377,100.00   |  |  |  |  |  |  |            |             |
|                   | 2070        |                       | ORCING STEEL<br>POXY COATED)       | Material                              |                                  |  |  | -15,520                | \$2.10                                | (\$32,592.00   |  |  |  |  |  |  |            |             |
|                   | 2070        |                       | ORCING STEEL<br>POXY COATED)       | Material                              |                                  | overridding Payment E  | ayment Estimate Item<br>)) due to user raybol1   |                        | \$2.10                                | \$32,592.00  |  |  |  |  |  |  |            |             |
|                   | 2090        | VERTICAL              | DRAIN AT END<br>BENTS              | Material                              | al                               |  |  |                        |                                       |  |  |  |  |  |  |  | \$1,900.00 | (\$3,800.00 |
|                   | 2090        | VERTICAL              | DRAIN AT END<br>BENTS              | Material                              |                                  | overridding Payment E  | ayment Estimate Item<br>)) due to user raybol1   |                        | \$1,900.00                            | \$3,800.00   |  |  |  |  |  |  |            |             |
| Total             |             |                       |                                    |                                       |                                  |  |  |                        |                                       | \$52,353.46  |  |  |  |  |  |  |            |             |



# Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

|                   | Contract Project Information |   |       |        |                                    |  |  |  |  |  |  |  |  |
|-------------------|------------------------------|---|-------|--------|------------------------------------|--|--|--|--|--|--|--|--|
| Project<br>Number | Federal<br>Proj.<br>Number   | Project<br>Description  | Route | County | Location of Work                   |  |  |  |  |  |  |  |  |
| J4P3443           | FAF<br>7-1(46)               | 2 Bridge<br>replacements<br>and<br>intersection<br>improvements | 7     | CASS   | on Rte. 7 (275th Street) over I-49 |  |  |  |  |  |  |  |  |

#### Totals by Job Numbers

| J4P3443                   |             | This Estimate | Previous       | To Date        |
|---------------------------|-------------|---------------|----------------|----------------|
| Posted Item Pay           |             | \$919,510.30  | \$5,533,670.57 | \$6,453,180.87 |
| Gross Item Adjustments    |             | \$52,353.46   | \$492.00       | \$52,845.46    |
| Gros                      | ss Item Pay | \$971,863.76  | \$5,534,162.57 | \$6,506,026.33 |
|                           |             |               |                |                |
| Incentive                 |             | \$0.00        | \$0.00         | \$0.00         |
| Disincentive              |             | \$0.00        | \$0.00         | \$0.00         |
| Liquidated Damages        |             | \$0.00        | \$0.00         | \$0.00         |
| Other Contract Adjustment | s           | \$0.00        | (\$155.26)     | (\$155.26)     |



# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### Exceptions (Discrepancies) This Estimate Period

| Exceptions (Discrepancies) This Estimate Period<br>Exceptions / Discrepencies  | Explanation  | Entered       | Status     |
|--|--|---------------|------------|
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 3040506, Project Item Line Number 0100, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.           | Need materials report for the Type 5 Aggregate rock.   | By<br>raybol1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 3049905, Project Item Line Number 0110, Material Set 304990596, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.           | Need materials report for the Type 5 Aggregate rock.<br>Temporary Pavement.  | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 3049905, Project Item Line Number 0940, Material Set 304990596, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.           | Need materials report for the Type 5 Aggregate rock.   | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 5021334, Project Item Line Number 0140, Material Set 502133496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.                    | Need materials report for the sand.  | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 5021334, Project Item Line Number 0140, Material Set 502133496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.                     | Need materials report for the rock.  | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 5021334, Project Item Line Number 0950, Material Set 502133496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.                     | Need materials report for the rock.  | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 5021334, Project Item Line Number 0950, Material Set 502133496, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action 0501CCPAQCQA 10 1/2 in. is insufficient.      | Waiting on 28 Day cylinder breaks.   | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 5021334, Project Item Line Number 0950, Material Set 502133496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.                    | Need materials report for the sand.  | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 5031010A, Project Item Line<br>Number 1960, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker,<br>Acceptance Action Generic 1058PSBB is insufficient.           | Need the certification from the contractor to enter a materials<br>report for the polyethylene sheeting used for bond breaker for<br>the bridge approach slab. | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 5031010A, Project Item Line<br>Number 1960, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix<br>or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient. | Waiting for 28 Day cylinder breaks.  | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 5031010A, Project Item Line<br>Number 1960, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE<br>4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.      | Need certification from the contractor to enter a materials report for the 4" corrugated underdrain.   | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 5041000, Project Item Line Number 0150, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.              | Need certification from the contractor to enter a materials report for the 4" corrugated underdrain.   | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7034219A, Project Item Line<br>Number 2010, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance<br>Action Generic 0501CCB1.A is insufficient.                    | Waiting on 28 Day cylinder breaks.   | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7034221, Project Item Line Number 2020, Material Set 703422196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.                            | Need materials report for the concrete.  | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7056022, Project Item Line Number 1870, Material Set 705602296, Material 0705INCRCPSXX - Girder Nebraska Dsn Various Leng, Acceptance Action Generic 0705INCRCPSXX is insufficient.               | Need materials report for the girders.   | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7061030, Project Item Line Number 0680, Material Set 706103096, Material 1036RSDFPL42M29 - Reinforcing Steel No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.       | Need PAL materials report for the rebar.   | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7061030, Project Item Line Number 0680, Material Set 706103096, Material 1036RSDFPL42M32 - Reinforcing Steel No. 10/M32 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.       | Need PAL materials report for the rebar.   | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7061030, Project Item Line Number 0680, Material Set 706103096, Material 1036RSDFPL42M36 - Reinforcing Steel No. 11/M36 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.       | Need PAL materials report for the rebar.   | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7101000, Project Item Line Number 1880, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.      | Need PAL materials report for the anchor bolts.  | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7101000, Project Item Line Number 2070, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.      | Need PAL materials report for the anchor bolts.  | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 7151001, Project Item Line Number 2090, Material Set 715100196, Material 0715DRVT - Vertical Drain at End Bents, Acceptance Action Generic 0715DRVT is insufficient.                              | Need materials report for the vertical drain.  | raybol1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4P3443, Item 9109901, Project Item Line Number 1710, Material Set 9109901, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.                    | Need materials report for the scout camera pole relocation.  | raybol1       | Overridden |



#### Total Paid / All Items / All Estimates (Including this Estimate)

| Contract    | Project | Category | Line | Item     | eport Generated date and can differ from the posted amo<br>Description                                | Bid       | Net             | Total               | Unit | Total                     | Unit Price   | Total Value POSTED                  |
|-------------|---------|----------|------|----------|---|-----------|-----------------|---------------------|------|---------------------------|--------------|-------------------------------------|
| Nm.CONTRACT | No.     |          | No.  | Code     |   | Quantity  | Change<br>Order | Current<br>Quantity |      | Posted<br>Approved<br>Qty |              | To Date (See report generated date) |
| 230519-C04  | J4P3443 | 0001     | 0010 | 2013000  | CLEARING AND GRUBBING   | 2.00      | 0.00            | 2.00                | ACRE | 2.00                      | \$9,000.00   | \$18,000.0                          |
|             |         | 0001     | 0020 | 2022010  | REMOVAL OF IMPROVEMENTS   | 1.00      | -1.00           | 0.00                | LS   | 0.00                      | \$202,700.00 | \$0.0                               |
|             |         | 0001     | 0021 | 2022010  | REMOVAL OF IMPROVEMENTS   | 0.00      | 1.00            | 1.00                | LS   | 0.70                      | \$200,750.00 | \$140,525.0                         |
|             |         | 0001     | 0030 | 2031000  | CLASS A EXCAVATION  | 14,656.00 | 0.00            | 14,656.00           | CUYD | 11,102.00                 | \$15.00      | \$166,530.0                         |
|             |         | 0001     | 0040 | 2035500  | EMBANKMENT IN PLACE   | 28,657.00 | 0.00            | 28,657.00           | CUYD | 15,489.00                 | \$19.00      | \$294,291.0                         |
|             |         | 0001     | 0050 | 2036000  | COMPACTING EMBANKMENT   | 12,365.00 | 0.00            | 12,365.00           | CUYD | 9,363.00                  | \$3.10       | \$29,025.3                          |
|             |         | 0001     | 0060 | 2037075  | COMPACTING IN CUT   | 92.90     | 0.00            | 92.90               | STA  | 30.80                     | \$660.00     | \$20,328.0                          |
|             |         | 0001     | 0070 | 2063000  | CLASS 3 EXCAVATION  | 2,628.00  | 142.00          | 2,770.00            | CUYD | 962.00                    | \$14.00      | \$13,468.0                          |
|             |         | 0001     | 0080 | 2063300  | CLASS 4 EXCAVATION  | 17.00     | 0.00            | 17.00               | CUYD | 17.00                     | \$144.00     | \$2,448.00                          |
|             |         | 0001     | 0090 | 2063500  | CULVERT CLEANOUT  | 3.00      | 0.00            | 3.00                | EA   | 0.00                      | \$1,600.00   | \$0.00                              |
|             |         | 0001     | 0095 | 2065500  | TEMPORARY SHORING   | 1.00      | 0.00            | 1.00                | LS   | 1.00                      | \$44,800.00  | \$44,800.00                         |
|             |         | 0001     | 0100 | 3040506  | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)   | 1,854.00  | -764.00         | 1,090.00            | SQYD | 230.00                    | \$14.00      | \$3,220.00                          |
|             |         | 0001     | 0110 | 3049905  | MISC.OPTIONAL BASE  | 3,027.00  | 0.00            | 3,027.00            | SQYD | 2,146.80                  | \$14.00      | \$30,055.20                         |
|             |         | 0001     | 0120 | 4019905  | MISC.OPTIONAL PAVEMENT  | 3,026.90  | 0.00            | 3,026.90            | SQYD | 2,635.70                  | \$105.00     | \$276,748.50                        |
|             |         | 0001     | 0130 | 5021308  | CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)   | 762.50    | -762.50         | 0.00                | SQYD | 0.00                      | \$105.00     | \$0.00                              |
|             |         | 0001     | 0140 | 5021334  | CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)  | 761.30    | 0.00            | 761.30              | SQYD | 229.10                    | \$137.00     | \$31,386.70                         |
|             |         | 0001     | 0150 | 5041000  | CONCRETE APPROACH PAVEMENT  | 275.20    | 0.00            | 275.20              | SQYD | 157.40                    | \$180.00     | \$28,332.00                         |
|             |         | 0001     | 0160 | 6044011  | PIPE COLLAR, TYPE A   | 1.00      | 0.00            | 1.00                | EA   | 0.00                      | \$1,600.00   | \$0.00                              |
|             |         | 0001     | 0170 | 6053030A | PIPE AGGREGATE PAVEMENT EDGE DRAIN  | 515.00    | -515.00         | 0.00                | LF   | 0.00                      | \$36.00      | \$0.00                              |
|             |         | 0001     | 0180 | 6054020  | OUTLET PIPES AND SPLASH PADS  | 2.00      | -2.00           | 0.00                | EA   | 0.00                      | \$1,400.00   | \$0.00                              |
|             |         | 0001     | 0190 | 6081000  | CONCRETE MEDIAN   | 2,298.80  | 0.00            | 2,298.80            | SQYD | 0.00                      | \$64.00      | \$0.00                              |
|             |         | 0001     | 0200 | 6091011  | CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S  | 1,780.00  | 0.00            | 1,780.00            | LF   | 0.00                      | \$25.00      | \$0.00                              |
|             |         | 0001     | 0210 | 6097000  | ROCK LINING   | 127.00    | 0.00            | 127.00              | CUYD | 0.00                      | \$136.00     | \$0.00                              |
|             |         | 0001     | 0220 | 6113010  | FURNISHING TYPE 1 ROCK BLANKET  | 2,429.00  | 0.00            | 2,429.00            | CUYD | 1,557.00                  | \$56.00      | \$87,192.00                         |
|             |         | 0001     | 0230 | 6113030  | PLACING TYPE 1 ROCK BLANKET   | 2,429.00  | 0.00            | 2,429.00            | CUYD | 1,557.00                  | \$22.00      | \$34,254.00                         |
|             |         | 0001     | 0240 | 6122008  | IMPACT ATTENUATOR 40 MPH (SAND BARREL ARRAY)  | 1.00      | 0.00            | 1.00                | EA   | 1.00                      | \$4,500.00   | \$4,500.0                           |
|             |         | 0001     | 0250 | 6122010  | IMPACT ATTENUATOR 50 MPH (SAND BARREL ARRAY)  | 1.00      | 0.00            | 1.00                | EA   | 1.00                      | \$4,500.00   | \$4,500.0                           |
|             |         | 0001     | 0260 | 6122019  | IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)  | 5.00      | 0.00            | 5.00                | EA   | 5.00                      | \$4,500.00   | \$22,500.00                         |
|             |         | 0001     | 0270 | 6122030  | IMPACT ATTENUATOR (RELOCATION)  | 3.00      | 0.00            | 3.00                | EA   | 0.00                      | \$4,500.00   | \$0.00                              |
|             |         | 0001     | 0280 | 6123000A | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)   | 6.00      | 0.00            | 6.00                | EA   | 0.00                      | \$1,100.00   | \$0.00                              |
|             |         | 0001     | 0290 | 6132018  | FURNISHING AND PLACING CONCRETE MATERIAL FOR<br>CLASS A PARTIAL DEPTH PAVEMENT REPAIR                 | 202.70    | 0.00            | 202.70              | CUYD | 0.00                      | \$620.00     | \$0.00                              |
|             |         | 0001     | 0300 | 6139905  | MISC.RAPID STRENGTH CONCRETE FOR PAVEMENT REPAIR  | 321.60    | 0.00            | 321.60              | SQYD | 0.00                      | \$170.00     | \$0.00                              |
|             |         | 0001     | 0310 | 6143014  | MANHOLE FRAME AND COVER, TYPE 4   | 1.00      | 0.00            | 1.00                | EA   | 0.00                      | \$1,200.00   | \$0.00                              |
|             |         | 0001     | 0320 | 6161005  | CONSTRUCTION SIGNS  | 2,497.00  | 0.00            | 2,497.00            | SQFT | 1,682.10                  | \$6.30       | \$10,597.23                         |
|             |         | 0001     | 0330 | 6161008  | ADVANCED WARNING RAIL SYSTEM  | 20.00     | 0.00            | 20.00               | EA   | 7.00                      | \$68.00      | \$476.00                            |
|             |         | 0001     | 0340 | 6161025  | CHANNELIZER (TRIM LINE)   | 141.00    | 263.00          | 404.00              | EA   | 404.00                    | \$19.00      | \$7,676.00                          |
|             |         | 0001     | 0350 | 6161030  | TYPE III MOVEABLE BARRICADE   | 25.00     | 0.00            | 25.00               | EA   | 9.00                      | \$170.00     | \$1,530.00                          |
|             |         | 0001     | 0360 | 6161033  | DIRECTIONAL INDICATOR BARRICADE   | 68.00     | 0.00            | 68.00               | EA   | 56.00                     | \$79.00      | \$4,424.0                           |
|             |         | 0001     | 0370 | 6161040  | FLASHING ARROW PANEL  | 5.00      | 0.00            | 5.00                | EA   | 3.00                      | \$3,400.00   | \$10,200.00                         |
|             |         | 0001     | 0380 | 6161055  | SEQUENTIAL FLASHING WARNING LIGHT   | 68.00     | 0.00            | 68.00               | EA   | 56.00                     | \$68.00      | \$3,808.0                           |
|             |         | 0001     | 0390 | 6161099  | CHANGEABLE MESSAGE SIGN WITH COMMUNICATION<br>INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR<br>RETAINED | 6.00      | 0.00            | 6.00                | EA   | 4.00                      | \$5,800.00   | \$23,200.00                         |
|             |         | 0001     | 0400 | 6162002  | TEMPORARY LONG-TERM RUMBLE STRIPS   | 30.00     | 0.00            | 30.00               | EA   | 10.00                     | \$1,500.00   | \$15,000.0                          |
|             |         | 0001     | 0410 | 6173103  | CONCRETE TRAFFIC BARRIER, TYPE D (MOMENT SLAB)  | 1,233.00  | -515.00         | 718.00              | LF   | 213.00                    | \$180.00     | \$38,340.00                         |
|             |         | 0001     | 0420 | 6173600D | TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED  | 4,723.00  | 866.00          | 5,589.00            | LF   | 5,589.00                  | \$16.00      | \$89,424.00                         |
|             |         | 0001     | 0430 | 6175010A |   | 9,130.00  | 0.00            | 9,130.00            | LF   | 961.00                    | \$10.00      | \$9,610.00                          |

#### Total Paid / All Items / All Estimates (Including this Estimate)

| Contract    | Project | Category | Line | Item     | eport Generated date and can differ from the posted amo<br>Description         | Bid       | Net             | Total               | Unit | Total                     | Unit Price   | Total Value POSTED                     |
|-------------|---------|----------|------|----------|--|-----------|-----------------|---------------------|------|---------------------------|--------------|--|
| Nm.CONTRACT | No.     |          | No.  | Code     |  | Quantity  | Change<br>Order | Current<br>Quantity |      | Posted<br>Approved<br>Qty |              | To Date (See report<br>generated date) |
| 230519-C04  | J4P3443 | 0001     | 0440 | 6181000  | MOBILIZATION   | 1.00      | 0.00            | 1.00                | LS   |                           | \$825,000.00 | \$825,000.0                            |
|             |         | 0001     | 0450 | 6181020  | ADDITIONAL MOBILIZATION FOR SEEDING  | 1.00      | 0.00            | 1.00                | EA   | 0.00                      | \$600.00     | \$0.0                                  |
|             |         | 0001     | 0460 | 6191000  | PAVEMENT EDGE TREATMENT  | 790.00    | 480.00          | 1,270.00            | LF   | 1,270.00                  | \$6.80       | \$8,636.0                              |
|             |         | 0001     | 0470 | 6200009  | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE                          | 831.00    | 0.00            | 831.00              | LF   | 0.00                      | \$6.90       | \$0.0                                  |
|             |         | 0001     | 0480 | 6200012  | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE                          | 409.00    | 0.00            | 409.00              | LF   | 0.00                      | \$12.00      | \$0.0                                  |
|             |         | 0001     | 0490 | 6200015  | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE                         | 196.00    | 0.00            | 196.00              | LF   | 0.00                      | \$21.00      | \$0.0                                  |
|             |         | 0001     | 0500 | 6200021  | PREFORMED THERMOPLASTIC PAVEMENT MARKING,<br>LEFT/RIGHT ARROW                  | 18.00     | 0.00            | 18.00               | EA   | 0.00                      | \$340.00     | \$0.0                                  |
|             |         | 0001     | 0510 | 6200024  | PREFORMED THERMOPLASTIC PAVEMENT MARKING,<br>STRAIGHT ARROW                    | 10.00     | 0.00            | 10.00               | EA   | 0.00                      | \$290.00     | \$0.0                                  |
|             |         | 0001     | 0520 | 6200027  | PREFORMED THERMOPLASTIC PAVEMENT MARKING,                                      | 5.00      | 0.00            | 5.00                | EA   | 0.00                      | \$680.00     | \$0.0                                  |
|             |         | 0001     | 0530 | 6200039  | COMBINATION STR/LT/RT<br>PREFORMED THERMOPLASTIC PAVEMENT MARKING, OFF         | 6.00      | 0.00            | 6.00                | EA   | 0.00                      | \$680.00     | \$0.0                                  |
|             |         | 0001     | 0540 | 6200042  | RAMP WRONG WAY ARROW<br>PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN        | 39.00     | 0.00            | 39.00               | EA   | 0.00                      | \$68.00      | \$0.0                                  |
|             |         | 0001     | 0550 | 6205309  | WHITE, YIELD LINE TRIANGLES<br>TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE | 228.00    | 0.00            | 228.00              | LF   | 84.00                     | \$13.00      | \$1.092.0                              |
|             |         | 0001     | 0560 | 6205440A | TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT                                | 9.00      | 0.00            | 9.00                | EA   | 1.00                      | \$160.00     | \$160.0                                |
|             |         |          |      |          | ARROW  |           |                 |                     |      |                           |              |  |
|             |         | 0001     | 0570 | 6205442  | TEMPORARY NON-REMOVABLE MARKING TAPE STRAIGHT<br>ARROW                         | 3.00      | 4.00            | 7.00                | EA   | 7.00                      | \$132.00     | \$924.0                                |
|             |         | 0001     | 0580 | 6205443A | TEMPORARY NON-REMOVABLE MARKING TAPE<br>COMBINATION STRAIGHT- LEFT/RIGHT ARROW | 3.00      | 1.00            | 4.00                | EA   | 4.00                      | \$260.00     | \$1,040.0                              |
|             |         | 0001     | 0590 | 6205902A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS         | 10,103.00 | 0.00            | 10,103.00           | LF   | 0.00                      | \$0.25       | \$0.0                                  |
|             |         | 0001     | 0600 | 6205903A | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT<br>MARKING PAINT, TYPE L BEADS     | 5,838.00  | 0.00            | 5,838.00            | LF   | 0.00                      | \$0.25       | \$0.0                                  |
|             |         | 0001     | 0610 | 6205906A | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT<br>MARKING PAINT, TYPE L BEADS     | 1,394.00  | 0.00            | 1,394.00            | LF   | 0.00                      | \$0.50       | \$0.0                                  |
|             |         | 0001     | 0620 | 6207001  | PAVEMENT MARKING REMOVAL   | 27,040.00 | 0.00            | 27,040.00           | LF   | 3,981.00                  | \$0.60       | \$2,388.6                              |
|             |         | 0001     | 0630 | 6207002  | PAVEMENT MARKING REMOVAL (SYMBOLS)   | 15.00     | 0.00            | 15.00               | EA   | 4.00                      | \$100.00     | \$400.0                                |
|             |         | 0001     | 0640 | 6208076  | 4 IN TEMPORARY PAVEMENT MARKING PAINT  | 31,370.00 | 0.00            | 31,370.00           | LF   | 19,854.00                 | \$0.15       | \$2,978.                               |
|             |         | 0001     | 0650 | 6240103A | PERMANENT EROSION CONTROL GEOTEXTILE   | 3,683.00  | 0.00            | 3,683.00            | SQYD | 2,351.00                  | \$3.80       | \$8,933.                               |
|             |         | 0001     | 0660 | 6274000  | CONTRACTOR FURNISHED SURVEYING AND STAKING                                     | 1.00      | 0.00            | 1.00                | LS   | 0.50                      | \$100,000.00 | \$50,000.                              |
|             |         | 0001     | 0670 | 7034041  | CLASS B-1 CONCRETE (CULVERTS)  | 43.70     | 0.00            | 43.70               | CUYD | 43.70                     | \$1,800.00   | \$78,660.                              |
|             |         | 0001     | 0680 | 7061030  | REINFORCING STEEL (CULVERTS)   | 6,370.00  | 0.00            | 6,370.00            | LB   | 6,370.00                  | \$2.70       | \$17,199.0                             |
|             |         | 0001     | 0690 | 7250318A | 18 IN. PIPE GROUP B  | 76.00     | 0.00            | 76.00               | LF   | 0.00                      | \$106.00     | \$0.0                                  |
|             |         | 0001     | 0700 | 7261018  | 18 IN. PIPE GROUP A  | 805.00    | 0.00            | 805.00              | LF   | 0.00                      | \$89.00      | \$0.0                                  |
|             |         | 0001     | 0710 | 7261024  | 24 IN. PIPE GROUP A  | 220.00    | 0.00            | 220.00              | LF   | 0.00                      | \$125.00     | \$0.0                                  |
|             |         | 0001     | 0720 | 7261036  | 36 IN. PIPE GROUP A  | 103.00    | 0.00            | 103.00              | LF   | 103.00                    | \$190.00     | \$19,570.0                             |
|             |         | 0001     | 0730 | 7261042  | 42 IN. PIPE GROUP A  | 383.00    | 94.00           | 477.00              | LF   | 295.00                    | \$230.00     | \$67,850.0                             |
|             |         | 0001     | 0735 | 7265442  | JACKED 42 IN. CLASS V REINFORCED CONCRETE PIPE<br>CULVERT (GASKET TYPE)        | 66.00     | -66.00          | 0.00                | LF   | 0.00                      | \$3,000.00   | \$0.0                                  |
|             |         | 0001     | 0740 | 7310048  | PRECAST CONCRETE MANHOLE - 48 IN.  | 11.00     | 0.00            | 11.00               | FT   | 0.00                      | \$460.00     | \$0.0                                  |
|             |         | 0001     | 0750 | 7311033  | PRECAST CONCRETE DROP INLET 3 FT X 3 FT  | 8.00      | 0.00            | 8.00                | FT   | 0.00                      | \$1,000.00   | \$0.0                                  |
|             |         | 0001     | 0760 | 7311053  | PRECAST CONCRETE DROP INLET 5 FT X 3 FT  | 1.00      | 0.00            | 1.00                | FT   | 0.00                      | \$6,800.00   | \$0.                                   |
|             |         | 0001     | 0770 | 7320018A | 18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END<br>SECTION                     | 1.00      | 0.00            | 1.00                | EA   | 0.00                      | \$1,900.00   | \$0.0                                  |
|             |         | 0001     | 0780 | 7320618A | 18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION                        | 16.00     | 0.00            | 16.00               | EA   | 0.00                      | \$1,900.00   | \$0.0                                  |
|             |         | 0001     | 0790 | 7320624A | 24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION                        | 1.00      | 0.00            | 1.00                | EA   | 0.00                      | \$2,200.00   | \$0.0                                  |
|             |         | 0001     | 0800 | 7320636A | 36 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION                        | 2.00      | 0.00            | 2.00                | EA   | 2.00                      | \$2,800.00   | \$5,600.0                              |
|             |         | 0001     | 0810 | 7320642A | 42 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END<br>SECTION                     | 4.00      | 0.00            | 4.00                | EA   | 2.00                      | \$3,600.00   | \$7,200.0                              |
|             |         | 0001     | 0820 | 8025006  | MULCHING   | 10.40     | 0.00            | 10.40               | ACRE | 5.40                      | \$470.00     | \$2,538.0                              |
|             |         | 0001     | 0830 | 8051000A | SEEDING - COOL SEASON GRASSES  | 10.40     | 0.00            | 10.40               | ACRE | 5.40                      | \$2,700.00   | \$14,580.0                             |
|             |         | 0001     | 0840 | 8061004  | SEDIMENT TRAP ROCK   | 56.20     | 0.00            | 56.20               | CUYD | 1.30                      | \$108.00     | \$140.4                                |

#### Total Paid / All Items / All Estimates (Including this Estimate)

| lote: Posted Q          | uantities      | and Valu | es are b    | ased on R    | eport Generated date and can differ from the posted am             | ount at the     | time the E             | stimate was                  | s Genera | ated.                              |             |  |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|----------|------------------------------------|-------------|--|
| Contract<br>Nm.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | Description  | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit     | Total<br>Posted<br>Approved<br>Qty | Unit Price  | Total Value POSTED<br>To Date (See report<br>generated date) |
| 230519-C04              | J4P3443        | 0001     | 0850        | 8061005      | ROCK DITCH CHECK   | 1,008.00        | 0.00                   | 1,008.00                     | LF       | 598.00                             | \$19.00     | \$11,362.00  |
|                         |                | 0001     | 0860        | 8061007A     | CURB INLET CHECK   | 1.00            | 0.00                   | 1.00                         | EA       | 0.00                               | \$132.00    | \$0.00   |
|                         |                | 0001     | 0870        | 8061016      | SEDIMENT REMOVAL   | 262.00          | 0.00                   | 262.00                       | CUYD     | 50.00                              | \$27.00     | \$1,350.00   |
|                         |                | 0001     | 0880        | 8061019      | SILT FENCE   | 6,862.00        | 0.00                   | 6,862.00                     | LF       | 0.00                               | \$1.30      | \$0.00   |
|                         |                | 0001     | 0890        | 8064128      | TYPE 1 TURF REINFORCEMENT MAT                                      | 1,227.00        | 0.00                   | 1,227.00                     | SQYD     | 0.00                               | \$3.10      | \$0.00   |
|                         |                | 0001     | 0900        | 8064138      | TYPE 2D EROSION CONTROL BLANKET                                    | 6,262.00        | 0.00                   | 6,262.00                     | SQYD     | 2,679.00                           | \$2.40      | \$6,429.60   |
|                         |                | 0003     | 0940        | 3049905      | MISC.ALTERNATE BASE  | 20,225.00       | 0.00                   | 20,225.00                    | SQYD     | 14,864.80                          | \$12.00     | \$178,377.60   |
|                         |                | 0003     | 0950        | 5021334      | CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)       | 18,416.60       | 0.00                   | 18,416.60                    | SQYD     | 13,901.10                          | \$98.00     | \$1,362,307.80   |
|                         |                | 0003     | 0960        | 6262000A     | PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP                     | 12.70           | 0.00                   | 12.70                        | STA      | 0.00                               | \$700.00    | \$0.00   |
|                         |                | 0005     | 0980        | 5021340      | TYPE A2 SHOULDER   | 1,808.20        | 0.00                   | 1,808.20                     | SQYD     | 963.60                             | \$55.00     | \$52,998.00  |
|                         |                | 0010     | 0990        | 6061061      | MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING                     | 2,114.00        | 538.00                 | 2,652.00                     | LF       | 0.00                               | \$35.00     | \$0.00   |
|                         |                | 0010     | 1000        | 6061069      | MGS BRIDGE APPROACH TRANSITION SECTION<br>(REGULAR/NO CURB)        | 2.00            | -2.00                  | 0.00                         | EA       | 0.00                               | \$4,100.00  | \$0.00   |
|                         |                | 0010     | 1010        | 6061074      | MGS HEIGHT AND BLOCK TRANSITION                                    | 1.00            | 0.00                   | 1.00                         | EA       | 0.00                               | \$1,000.00  | \$0.0  |
|                         |                | 0010     | 1020        | 6061080      | MGS END ANCHOR   | 6.00            | 2.00                   | 8.00                         | EA       | 0.00                               | \$1,400.00  | \$0.00   |
|                         |                | 0010     | 1030        | 6063014      | TYPE A CRASHWORTHY END TERMINAL (MASH)                             | 7.00            | 0.00                   | 7.00                         | EA       | 0.00                               | \$3,400.00  | \$0.00   |
|                         |                | 0010     | 1040        | 6064500      | AGGREGATE BEDDING FOR 3 - STRAND GUARD CABLE                       | 31.00           | 0.00                   | 31.00                        | CUYD     | 0.00                               | \$125.00    | \$0.00   |
|                         |                | 0010     | 1050        | 6069902      | MISC.HTGC ANCHOR ASSEMBLY  | 1.00            | 0.00                   | 1.00                         | EA       | 0.00                               | \$5,400.00  | \$0.00   |
|                         |                | 0010     | 1060        | 6069903      | MISC.HIGH TENSION GUARD CABLE                                      | 410.00          | 0.00                   | 410.00                       | LF       | 0.00                               | \$39.00     | \$0.00   |
|                         |                | 0010     | 1070        | 6240104A     | SEPARATION GEOTEXTILE  | 274.00          | 0.00                   | 274.00                       | SQYD     | 0.00                               | \$5.10      | \$0.00   |
|                         |                | 0020     | 1080        | 9011062      | LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2                  | 16.00           | 0.00                   | 16.00                        | EA       | 0.00                               | \$3,200.00  | \$0.00   |
|                         |                |          | 1090        | 9011115      | BRACKET ARM, 15 FT. OR 4.6 M                                       | 16.00           | 0.00                   | 16.00                        | EA       | 0.00                               | \$1,500.00  | \$0.00   |
|                         |                | 0020     | 1100        | 9011312      | LUMINAIRE, LED-B   | 16.00           | 0.00                   | 16.00                        | EA       | 0.00                               | \$840.00    | \$0.00   |
|                         |                | 0020     | 1110        | 9012230      | BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT                  | 4.00            | 0.00                   | 4.00                         | EA       | 0.00                               | \$9,000.00  | \$0.00   |
|                         |                | 0020     | 1120        | 9013002      | CONDUIT, 2 IN. RIGID, IN TRENCH                                    | 460.00          | 0.00                   | 460.00                       | LF       | 77.00                              | \$23.00     | \$1,771.00   |
|                         |                | 0020     | 1130        | 9014004      | CONDUIT, 4 IN. RIGID, PUSHED                                       | 527.00          | 0.00                   | 527.00                       | LF       | 48.00                              | \$35.00     | \$1,680.00   |
|                         |                | 0020     | 1140        | 9015010      | TRENCHING TYPE I   | 5,804.00        | 0.00                   | 5,804.00                     | LF       | 0.00                               | \$11.00     | \$0.00   |
|                         |                | 0020     | 1150        | 9016110      | PULL BOX, PREFORMED CLASS 1  | 5.00            | 0.00                   | 5.00                         | EA       | 0.00                               | \$2,500.00  | \$0.00   |
|                         |                | 0020     | 1160        | 9016112      | PULL BOX, PREFORMED CLASS 3  | 1.00            | 0.00                   | 1.00                         | EA       | 0.00                               | \$4,800.00  | \$0.00   |
|                         |                | 0020     | 1170        | 9017002      | CABLE, 2 AWG 1 CONDUCTOR   | 810.00          | 0.00                   | 810.00                       | LF       | 0.00                               | \$5.30      | \$0.00   |
|                         |                | 0020     | 1180        | 9017110      | CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET                        | 1,920.00        | 0.00                   | 1,920.00                     | LF       | 0.00                               | \$2.40      | \$0.00   |
|                         |                | 0020     | 1190        | 9017407      | CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE<br>NEUTRAL, 8 AWG    | 5,780.00        | 0.00                   | 5,780.00                     | LF       | 0.00                               | \$4.80      | \$0.00   |
|                         |                | 0020     | 1200        | 9018245      | POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)                 | 16.00           | 0.00                   | 16.00                        | EA       | 0.00                               | \$3,200.00  | \$0.00   |
|                         |                | 0020     | 1210        | 9018612      | POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY | 1.00            | 0.00                   | 1.00                         | EA       | 0.00                               | \$8,100.00  | \$0.00   |
|                         |                | 0030     | 1220        | 9020113      | SIGNAL HEAD, TYPE 3T   | 5.00            | 0.00                   | 5.00                         | EA       | 0.00                               | \$1,300.00  | \$0.00   |
|                         |                | 0030     | 1230        | 9020213      | SIGNAL HEAD, TYPE 3S   | 5.00            | 0.00                   | 5.00                         | EA       | 0.00                               | \$1,300.00  | \$0.00   |
|                         |                | 0030     | 1240        | 9020513      | SIGNAL HEAD, TYPE 3B   | 8.00            | 0.00                   | 8.00                         | EA       | 0.00                               | \$1,500.00  | \$0.00   |
|                         |                | 0030     | 1250        | 9020833      | SH-FLAT SHEET - SIGNAL SIGN  | 60.00           | 0.00                   | 60.00                        | SQFT     | 0.00                               | \$66.00     | \$0.00   |
|                         |                | 0030     | 1260        | 9020834      | SIGNAL SIGN, MOUNTING HARDWARE                                     | 8.00            | 0.00                   | 8.00                         | EA       | 0.00                               | \$380.00    | \$0.00   |
|                         |                | 0030     | 1270        | 9022651      | LUMINAIRE LED-A, 120 VOLT COMPATIBLE                               | 3.00            | 0.00                   | 3.00                         | EA       | 0.00                               | \$680.00    | \$0.0  |
|                         |                | 0030     | 1280        | 9022715      | POST, SIGNAL 15 FT.  | 4.00            | 0.00                   | 4.00                         | EA       | 0.00                               | \$1,900.00  | \$0.00   |
|                         |                | 0030     | 1290        | 9023115      | POST, TYPE CL, 15 FT. ARM OR 4.6 M ARM                             | 1.00            | 0.00                   | 1.00                         | EA       | 0.00                               | \$9,700.00  | \$0.00   |
|                         |                | 0030     | 1300        | 9023120      | POST, TYPE CL, 20 FT. ARM OR 6.1 M ARM                             | 1.00            | 0.00                   | 1.00                         | EA       | 0.00                               | \$11,800.00 | \$0.00   |
|                         |                | 0030     | 1310        | 9023130      | POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM                             | 1.00            | 0.00                   | 1.00                         | EA       | 0.00                               | \$14,900.00 | \$0.00   |
|                         |                | 0030     | 1320        | 9023135      | POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM                            | 1.00            | 0.00                   | 1.00                         | EA       | 0.00                               | \$15,600.00 | \$0.00   |
|                         |                | 0030     | 1330        | 9023215      | POST, TYPE C, 15 FT. ARM OR 4.6 M ARM                              | 1.00            | 0.00                   | 1.00                         | EA       | 0.00                               | \$9,300.00  | \$0.00   |

#### Total Paid / All Items / All Estimates (Including this Estimate)

| Note: Posted Q          | uantities      | and Valu | es are b    | ased on R    | eport Generated date and can differ from the posted an | nount at the    | time the E             | Estimate was                 | Genera | ated.                              |              |  |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|--------|------------------------------------|--------------|--|
| Contract<br>Nm.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | Description  | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit   | Total<br>Posted<br>Approved<br>Qty | Unit Price   | Total Value POSTED<br>To Date (See report<br>generated date) |
| 230519-C04              | J4P3443        | 0030     | 1340        | 9023230      | POST, TYPE C, 30 FT. ARM OR 9.1 M ARM                  | 1.00            | 0.00                   | 1.00                         | EA     | 0.00                               | \$12,400.00  | \$0.00   |
|                         |                | 0030     | 1350        | 9024975      | VIDEO DETECTION SYSTEM                                 | 1.00            | 0.00                   | 1.00                         | EA     | 0.00                               | \$71,500.00  | \$0.00   |
|                         |                | 0030     | 1360        | 9025300      | CONDUIT, 3 IN., TRENCH WITH TRACER WIRE                | 789.00          | 0.00                   | 789.00                       | LF     | 45.00                              | \$34.00      | \$1,530.00   |
|                         |                | 0030     | 1370        | 9025400      | CONDUIT, 4 IN., TRENCH WITH TRACER WIRE                | 137.00          | 0.00                   | 137.00                       | LF     | 0.00                               | \$45.00      | \$0.00   |
|                         |                | 0030     | 1380        | 9027300      | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE                | 115.00          | 0.00                   | 115.00                       | LF     | 0.00                               | \$49.00      | \$0.00   |
|                         |                | 0030     | 1390        | 9027400      | CONDUIT, 4 IN., PUSHED WITH TRACER WIRE                | 193.00          | 0.00                   | 193.00                       | LF     | 0.00                               | \$44.00      | \$0.00   |
|                         |                | 0030     | 1400        | 9028100      | CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET            | 180.00          | 0.00                   | 180.00                       | LF     | 0.00                               | \$2.70       | \$0.00   |
|                         |                | 0030     | 1410        | 9028202      | CABLE, 2 AWG 1 CONDUCTOR, POWER                        | 490.00          | 0.00                   | 490.00                       | LF     | 0.00                               | \$5.40       | \$0.00   |
|                         |                | 0030     | 1420        | 9028302      | CABLE, 12 AWG 2 CONDUCTOR                              | 1,260.00        | 0.00                   | 1,260.00                     | LF     | 0.00                               | \$5.30       | \$0.00   |
|                         |                | 0030     | 1430        | 9028311      | CABLE, 16 AWG 7 CONDUCTOR                              | 10,050.00       | 0.00                   | 10,050.00                    | LF     | 0.00                               | \$3.30       | \$0.00   |
|                         |                | 0030     | 1440        | 9028811      | PULL BOX, PREFORMED CLASS 2                            | 4.00            | 0.00                   | 4.00                         | EA     | 0.00                               | \$3,400.00   | \$0.00   |
|                         |                | 0030     | 1450        | 9028812      | PULL BOX, PREFORMED CLASS 3                            | 6.00            | 0.00                   | 6.00                         | EA     | 0.00                               | \$4,900.00   | \$0.00   |
|                         |                | 0030     | 1460        | 9029100      | BASE, CONCRETE   | 21.40           | 0.00                   | 21.40                        | CUYD   | 0.00                               | \$2,700.00   | \$0.00   |
|                         |                | 0030     | 1470        | 9029401      | TEMPORARY TRAFFIC SIGNALS AND LIGHTING                 | 1.00            | 0.00                   | 1.00                         | LS     | 1.00                               | \$236,000.00 | \$236,000.00   |
|                         |                | 0040     | 1480        | 9031020      | CONCRETE FOOTINGS, BOLT DOWN                           | 7.30            | 0.00                   | 7.30                         | CUYD   | 0.00                               | \$1,300.00   | \$0.00   |
|                         |                | 0040     | 1490        | 9031210      | STRUCTURAL STEEL POSTS                                 | 4,640.00        | 0.00                   | 4,640.00                     | LB     | 0.00                               | \$5.30       | \$0.00   |
|                         |                | 0040     | 1500        | 9031241      | BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL<br>TUBE)   | 8.00            | 0.00                   | 8.00                         | EA     | 0.00                               | \$420.00     | \$0.00   |
|                         |                | 0040     | 1510        | 9031270A     | 2 IN. PSST POST - 12 GA.                               | 624.00          | 0.00                   | 624.00                       | LF     | 0.00                               | \$21.00      | \$0.00   |
|                         |                | 0040     | 1520        | 9031271A     | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.             | 39.00           | 0.00                   | 39.00                        | EA     | 0.00                               | \$84.00      | \$0.00   |
|                         |                | 0040     | 1530        | 9031272A     | 2.25 IN. PSST POST INSERT (6 FT.) - 12 GA.             | 4.00            | 0.00                   | 4.00                         | EA     | 0.00                               | \$137.00     | \$0.00   |
|                         |                | 0040     | 1540        | 9031280      | 2.5 IN. PSST POST - 12 GA.                             | 192.00          | 0.00                   | 192.00                       | LF     | 0.00                               | \$24.00      | \$0.00   |
|                         |                | 0040     | 1550        | 9031281A     | DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.            | 12.00           | 0.00                   | 12.00                        | EA     | 0.00                               | \$105.00     | \$0.00   |
|                         |                | 0040     | 1560        | 9035004A     | SH-FLAT SHEET  | 365.00          | 0.00                   | 365.00                       | SQFT   | 0.00                               | \$21.00      | \$0.00   |
|                         |                | 0040     | 1570        | 9035011A     | ST-STRUCTURAL  | 756.00          | 0.00                   | 756.00                       | SQFT   | 0.00                               | \$32.00      | \$0.00   |
|                         |                | 0040     | 1580        | 9035069A     | SHF-FLAT SHEET FLUORESCENT                             | 116.00          | 0.00                   | 116.00                       | SQFT   | 0.00                               | \$24.00      | \$0.00   |
|                         |                | 0040     | 1590        | 9039901      | MISC.NB ON RAMP TRUSS #48                              | 1.00            | 0.00                   | 1.00                         | LS     | 0.00                               | \$136,800.00 | \$0.00   |
|                         |                | 0040     | 1600        | 9039901      | MISC.NEW TRUSS SIGNS ON EXISTING TRUSS #45             | 1.00            | 0.00                   | 1.00                         | LS     | 0.00                               | \$13,200.00  | \$0.00   |
|                         |                | 0040     | 1610        | 9039901      | MISC.SB AT EXIT 158 TRUSS #41                          | 1.00            | 0.00                   | 1.00                         | LS     | 0.00                               | \$136,800.00 | \$0.00   |
|                         |                | 0040     | 1620        | 9039901      | MISC.SB OFF RAMP CANT. TRUSS #42                       | 1.00            | 0.00                   | 1.00                         | LS     | 0.00                               | \$89,500.00  | \$0.00   |
|                         |                | 0040     | 1630        | 9039901      | MISC.TUBULAR SUPPORT, TYPE S-1310, TRUSS #43           | 1.00            | 0.00                   | 1.00                         | LS     | 0.00                               | \$52,600.00  | \$0.00   |
|                         |                | 0050     | 1640        | 9105200      | CONDUIT, 2 IN., RIGID, IN TRENCH                       | 1,384.00        | 0.00                   | 1,384.00                     | LF     | 1,054.00                           | \$20.00      | \$21,080.00  |
|                         |                | 0050     | 1650        | 9107202      | CONDUIT, 4 IN., RIGID, PUSHED                          | 284.00          | 0.00                   | 284.00                       | LF     | 0.00                               | \$51.00      | \$0.00   |
|                         |                | 0050     | 1660        | 9108202      | CABLE, 2 AWG, 1 CONDUCTOR, POWER                       | 210.00          | 0.00                   | 210.00                       | LF     | 0.00                               | \$5.30       | \$0.00   |
|                         |                | 0050     | 1670        | 9108353      | FIBER OPTIC CABLE, 12-STRAND, SINGLE MODE              | 1,880.00        | 0.00                   | 1,880.00                     | LF     | 0.00                               | \$8.40       | \$0.00   |
|                         |                | 0050     | 1680        | 9108811      | PULL BOX, PREFORMED CLASS 2                            | 1.00            | 0.00                   | 1.00                         | EA     | 1.00                               | \$3,500.00   | \$3,500.00   |
|                         |                | 0050     | 1690        | 9108816      | PULL BOX, PREFORMED CLASS 5                            | 8.00            | 0.00                   | 8.00                         | EA     | 0.00                               | \$4,000.00   | \$0.00   |
|                         |                | 0050     | 1700        | 9109901      | MISC.FIBER OPTIC SPLICING, TESTING AND DOCUMENTATION   | 1.00            | 0.00                   | 1.00                         | LS     | 0.00                               | \$13,100.00  | \$0.00   |
|                         |                | 0050     | 1710        | 9109901      | MISC.RELOCATE SCOUT CAMERA POLE                        | 1.00            | 0.00                   | 1.00                         | LS     | 1.00                               | \$27,900.00  | \$27,900.00  |
|                         |                | 0050     | 1720        | 9109901      | MISC.SALVAGING EXISTING ITS EQUIPMENT                  | 1.00            | 0.00                   | 1.00                         | LS     | 0.00                               | \$760.00     | \$0.00   |
|                         |                | 0050     | 1730        | 9109902      | MISC.FIBER MEDIA CONVERTER                             | 2.00            | 0.00                   | 2.00                         | EA     | 0.00                               | \$610.00     | \$0.00   |
|                         |                | 0050     | 1740        | 9109902      | MISC.SCOUT FIBER SPLICE VAULT                          | 1.00            | 0.00                   | 1.00                         | EA     | 1.00                               | \$7,200.00   | \$7,200.00   |
|                         |                | 0070     | 1750        | 2061000      | CLASS 1 EXCAVATION                                     | 123.00          | 22.00                  | 145.00                       | CUYD   | 145.00                             | \$88.00      | \$12,760.00  |
|                         |                | 0070     | 1760        | 2061003      | CLASS 1 EXCAVATION IN ROCK                             | 22.00           | -22.00                 | 0.00                         | CUYD   | 0.00                               | \$520.00     | \$0.00   |
|                         |                | 0070     | 1770        | 2160500      | REMOVAL OF BRIDGES                                     | 1.00            | 0.00                   | 1.00                         | LS     | 0.00                               | \$108,800.00 | \$0.00   |
|                         |                | 0070     | 1780        | 5031010A     | BRIDGE APPROACH SLAB (MAJOR)                           | 128.00          | 0.00                   | 128.00                       | SQYD   | 0.00                               | \$340.00     | \$0.00   |
|                         |                | 0070     | 1790        | 7021212      | GALVANIZED STRUCTURAL STEEL PILES (12 IN)              | 325.00          | 25.00                  | 350.00                       | LF     | 350.00                             | \$120.00     | \$42,000.00  |
|                         |                |          |             |              |  |                 |                        |                              |        |                                    |              |  |

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Note: Posted Qi<br>Contract | Project      | Category    | es are b<br>Line | ltem          | eport Generated date and can differ from the posted ar Description | nount at the<br>Bid | Net             | stimate was         | Unit | Total                     | Unit Price  | Total Value POSTED                     |
|-----------------------------|--------------|-------------|------------------|---------------|--|---------------------|-----------------|---------------------|------|---------------------------|-------------|--|
| Nm.CONTRACT                 | No.          | outogory    | No.              | Code          | Decomption   | Quantity            | Change<br>Order | Current<br>Quantity | Unit | Posted<br>Approved<br>Qty | onit i noo  | To Date (See report<br>generated date) |
| 230519-C04                  | J4P3443      | 0070        | 1800             | 7026000       | PRE-BORE FOR PILING  | 215.00              | 0.00            | 215.00              | LF   | 215.00                    | \$34.00     | \$7,310.00                             |
|                             |              | 0070        | 1810             | 7027000       | PILE POINT REINFORCEMENT   | 10.00               | 0.00            | 10.00               | EA   | 10.00                     | \$135.00    | \$1,350.00                             |
|                             |              | 0070        | 1820             | 7032003       | CLASS B CONCRETE (SUBSTRUCTURE)                                    | 89.80               | 0.00            | 89.80               | CUYD | 89.80                     | \$1,300.00  | \$116,740.00                           |
|                             |              | 0070        | 1830             | 7034219A      | TYPE D BARRIER   | 487.00              | 0.00            | 487.00              | LF   | 0.00                      | \$250.00    | \$0.00                                 |
|                             |              | 0070        | 1840             | 7034221       | SLAB ON CONCRETE NU-GIRDER   | 664.00              | 0.00            | 664.00              | SQYD | 0.00                      | \$460.00    | \$0.00                                 |
|                             |              | 0070        | 1850             | 7034620       | FORM LINERS  | 179.00              | 0.00            | 179.00              | SQYD | 0.00                      | \$79.00     | \$0.00                                 |
|                             |              | 0070        | 1860             | 7039902       | MISC.Cast Stone Sign   | 1.00                | 0.00            | 1.00                | EA   | 0.00                      | \$8,900.00  | \$0.00                                 |
|                             |              | 0070        | 1870             | 7056022       | NU 43, PRESTRESSED CONCRETE NU-GIRDER                              | 621.00              | 0.00            | 621.00              | LF   | 621.00                    | \$510.00    | \$316,710.00                           |
|                             |              | 0070        | 1880             | 7101000       | REINFORCING STEEL (EPOXY COATED)                                   | 10,970.00           | 0.00            | 10,970.00           | LB   | 10,970.00                 | \$2.10      | \$23,037.00                            |
|                             |              | 0070        | 1890             | 7123610       | SLAB DRAIN   | 2.00                | 0.00            | 2.00                | EA   | 0.00                      | \$890.00    | \$0.00                                 |
|                             |              | 0070        | 1900             | 7151001       | VERTICAL DRAIN AT END BENTS  | 2.00                | 0.00            | 2.00                | EA   | 0.00                      | \$1,900.00  | \$0.00                                 |
|                             |              | 0070        | 1910             | 7161000       | PLAIN NEOPRENE BEARING PAD   | 3.00                | 0.00            | 3.00                | EA   | 3.00                      | \$370.00    | \$1,110.00                             |
|                             |              | 0070        | 1920             | 7161002       | LAMINATED NEOPRENE BEARING PAD                                     | 6.00                | 0.00            | 6.00                | EA   | 6.00                      | \$420.00    | \$2,520.00                             |
|                             |              | 0070        | 1930             | 7161003       | LAMINATED NEOPRENE BEARING PAD (TAPERED)                           | 3.00                | 0.00            | 3.00                | EA   | 3.00                      | \$630.00    | \$1,890.00                             |
|                             |              | 0071        | 1940             | 2061000       | CLASS 1 EXCAVATION   | 158.00              | 33.00           | 191.00              | CUYD | 191.00                    | \$88.00     | \$16,808.00                            |
|                             |              | 0071        | 1950             | 2061003       | CLASS 1 EXCAVATION IN ROCK   | 33.00               | -33.00          | 0.00                | CUYD | 0.00                      | \$440.00    | \$0.00                                 |
|                             |              | 0071        | 1960             | 5031010A      | BRIDGE APPROACH SLAB (MAJOR)                                       | 168.00              | 0.00            | 168.00              | SQYD | 168.00                    | \$320.00    | \$53,760.00                            |
|                             |              | 0071        | 1970             | 7021212       | GALVANIZED STRUCTURAL STEEL PILES (12 IN)                          | 402.00              | 74.00           | 476.00              | LF   | 475.50                    | \$120.00    | \$57,060.00                            |
|                             |              | 0071        | 1980             | 7026000       | PRE-BORE FOR PILING  | 312.00              | 0.00            | 312.00              | LF   | 312.00                    | \$27.00     | \$8,424.00                             |
|                             |              | 0071        | 1990             | 7027000       | PILE POINT REINFORCEMENT   | 12.00               | 0.00            | 12.00               | EA   | 12.00                     | \$135.00    | \$1,620.00                             |
|                             |              | 0071        | 2000             | 7032003       | CLASS B CONCRETE (SUBSTRUCTURE)                                    | 123.60              | 0.00            | 123.60              | CUYD | 123.60                    | \$1,000.00  | \$123,600.00                           |
|                             |              | 0071        | 2010             | 7034219A      | TYPE D BARRIER   | 479.00              | 0.00            | 479.00              | LF   | 479.00                    | \$250.00    | \$119,750.00                           |
|                             |              | 0071        | 2020             | 7034221       | SLAB ON CONCRETE NU-GIRDER   | 838.00              | 0.00            | 838.00              | SQYD | 838.00                    | \$450.00    | \$377,100.00                           |
|                             |              | 0071        | 2030             | 7034620       | FORM LINERS  | 179.00              | 0.00            | 179.00              | SQYD | 179.00                    | \$79.00     | \$14,141.00                            |
|                             |              | 0071        | 2040             | 7039902       | MISC.Cast Stone Sign   | 1.00                | 0.00            | 1.00                | EA   | 1.00                      | \$8,900.00  | \$8,900.00                             |
|                             |              | 0071        | 2050             | 7056022       | NU 43, PRESTRESSED CONCRETE NU-GIRDER                              | 828.00              | 0.00            | 828.00              | LF   | 828.00                    | \$510.00    | \$422,280.00                           |
|                             |              | 0071        | 2060             | 7071000       | CONDUIT SYSTEM ON STRUCTURE  | 1.00                | 0.00            | 1.00                | LS   | 1.00                      | \$27,500.00 | \$27,500.00                            |
|                             |              | 0071        | 2070             | 7101000       | REINFORCING STEEL (EPOXY COATED)                                   | 15,520.00           | 0.00            | 15,520.00           | LB   | 15,520.00                 | \$2.10      | \$32,592.00                            |
|                             |              | 0071        | 2080             | 7123610       | SLAB DRAIN   | 2.00                | 0.00            | 2.00                | EA   | 2.00                      | \$890.00    | \$1,780.00                             |
|                             |              | 0071        | 2090             | 7151001       | VERTICAL DRAIN AT END BENTS  | 2.00                | 0.00            | 2.00                | EA   | 2.00                      | \$1,900.00  | \$3,800.00                             |
|                             |              | 0071        | 2100             | 7161000       | PLAIN NEOPRENE BEARING PAD   | 4.00                | 0.00            | 4.00                | EA   | 4.00                      | \$370.00    | \$1,480.00                             |
|                             |              | 0071        | 2110             | 7161002       | LAMINATED NEOPRENE BEARING PAD                                     | 8.00                | 0.00            | 8.00                | EA   | 8.00                      | \$420.00    | \$3,360.00                             |
|                             |              | 0071        | 2120             | 7161003       | LAMINATED NEOPRENE BEARING PAD (TAPERED)                           | 4.00                | 0.00            | 4.00                | EA   | 4.00                      | \$630.00    | \$2,520.00                             |
|                             |              | 0001        | 5001             | 7310072       | PRECAST CONCRETE MANHOLE - 72 IN.                                  | 0.00                | 26.00           | 26.00               | FT   | 26.00                     | \$500.77    | \$13,020.02                            |
|                             |              | 0001        | 5002             | 8061020       | TEMPORARY PIPE   | 0.00                | 60.00           | 60.00               | LF   | 60.00                     | \$120.00    | \$7,200.00                             |
|                             |              | 0001        | 5003             | 7269902       | MISC.RIGID PIPE CULVERT DESIGN COSTS                               | 0.00                | 1.00            | 1.00                | EA   | 1.00                      | \$8,000.00  | \$8,000.00                             |
|                             |              | 0001        | 5004             | 1046002       | VALUE ENGINEERING  | 0.00                | 73,085.99       | 73,085.99           | EA   | 73,085.99                 | \$1.00      | \$73,085.99                            |
|                             |              | 0001        | 5005             | 6122020       | REPLACEMENT SAND BARREL  | 0.00                | 3.00            | 3.00                | EA   | 3.00                      | \$1,575.00  | \$4,725.00                             |
|                             |              | 0001        | 5006             | 8061020       | TEMPORARY PIPE   | 0.00                | 80.00           | 80.00               | LF   | 80.00                     | \$42.78     | \$3,422.40                             |
|                             |              | 0001        | 5007             | 1046002       | VALUE ENGINEERING  | 0.00                | 48,329.63       | 48,329.63           | EA   | 48,329.63                 | \$1.00      | \$48,329.63                            |
|                             | Project J4   | 4P3443 - To | otal Value       | Posted to D   | Date as of Report Generated Date                                   | 1                   |                 |                     |      |                           |             | \$6,454,449.87                         |
| 230519-C04 Ove              | rall - Total | Value Pos   | ted to Dat       | te as of Repo | ort Generated Date   |                     |                 |                     |      |                           |             | \$6,454,449.87                         |



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

| Line<br>Number | Item<br>Code |  | Description                          | DWR<br>Date    | DWR<br>Approval                                 | Quantity<br>Posted     | Units        |                       |                          | L       | ocation                      | From<br>Station/ | Offset/<br>Distance | To<br>Station/       | Offset/<br>Distance | Comments               |     |
|----------------|--------------|--|--------------------------------------|----------------|---|------------------------|--------------|-----------------------|--------------------------|---------|------------------------------|------------------|---------------------|----------------------|---------------------|------------------------|-----|
| 0100           |              | TYPE 5 AGGREGATE                         | FOR BASE (6 IN. THICK)               | 11/3/23        | Date  | 0.00                   | SQYD         | Change C              | rder 0004                | PDVF    | CP 23-22 Underrun            | Log Mile         |                     | Log Mile             |                     |                        |     |
| 0110           |              | MISC. AGGREGATE                          |                                      | 11/15/23       |   | 381.50                 |              |                       | mporary p                |         |                              |                  |                     |                      |                     |                        |     |
| 0120           | 4019905      | MIRC                                     |                                      | 1414510-       | 11/16/23<br>11/16/23                            | 480.40<br>381.50       |              |                       | temporary                |         |                              |                  |                     |                      |                     |                        |     |
| 0120           | 4019905      | MISC.                                    |                                      | 11/15/23       | 11/16/23  | 480.40                 |              | Phase 2 t<br>Phase 1C | emporary p<br>temporary  |         |                              |                  |                     |                      |                     |                        |     |
| 0130           | 5021308      | CONCRETE PAVEMEN                         | NT (8 IN. NON-REINFORCED,            | 11/3/23        | 11/7/23   | 0.00                   | SQYD         | Change C              | rder 0004 I              | PDVE    | CP 23-22 Underrun            |                  |                     |                      |                     |                        |     |
| 0150           |              | CONCRETE APPROAC                         | CH PAVEMENT                          | 11/8/23        | 11/9/23<br>11/7/23                              | 76.00                  | SQYD<br>LF   |                       | Bridge A92               |         | CP 23-22 Underrun            | 15+51.02         |                     | 15+71.02             |                     |                        |     |
| 0180           |              | OUTLET PIPES AND S                       |                                      |                | 11/7/23   | 0.00                   | EA           |                       |                          |         | CP 23-22 Underrun            |                  |                     |                      |                     |                        |     |
| 0220           | 6113010      | FURNISHING TYPE 1                        | ROCK BLANKET                         | 11/9/23        | 11/14/23  | 5.00                   | CUYD         | SB MO-7               | by Ramp 2                | 2A)     |                              | 12+74.90         |                     | 13+16.57             | LT                  |                        |     |
| 0230           |              | PLACING TYPE 1 ROC<br>CONSTRUCTION SIGN  |                                      |                | 11/14/23  | 5.00<br>59.00          |              |                       | by Ramp 2<br>losure Dete |         | ano                          | 12+74.90         | LT                  | 13+16.57             | LT                  |                        |     |
| 0620           |              | PAVEMENT MARKING                         |                                      |                | 11/9/23   | 1,457.00               | LF           | Phase 1B              | losure Dela              | tour Si | gns                          |                  |                     |                      |                     |                        |     |
| 0650           | 6240103A     | PERMANENT EROSIO                         | N CONTROL GEOTEXTILE                 | 11/9/23        | 11/14/23  | 22.00                  | SQYD         | SB MO-7               | by Ramp 2                | 2A)     |                              | 12+74.90         | LT                  | 13+16.57             | LT                  |                        |     |
| 0820           | 8025006      | MULCHING                                 |                                      | 11/14/23       | 11/15/23<br>11/15/23                            | 0.30                   | ACRE         | Ramp 2A<br>Ramp 1     |                          |         |                              | 0+00             |                     | 2+13.34<br>7+91      |                     |                        |     |
|                |              |  |                                      |                | 11/15/23  | 0.40                   |              | Ramp 1                |                          |         |                              | 6+30             |                     | 12+80.56             |                     |                        |     |
| 0830           | 8051000A     | SEEDING - COOL SEA                       | SON GRASSES                          | 11/14/23       | 11/15/23  | 0.30                   | ACRE         |                       |                          |         |                              | 0+00             |                     | 2+13.34              |                     |                        |     |
|                |              |  |                                      |                | 11/15/23  | 0.40                   |              |                       |                          |         |                              | 0+00             |                     | 7+91                 |                     |                        |     |
| 0890           | 8064128      | TYPE 1 TURF REINFO                       | RCEMENT MAT                          | 11/13/23       | 11/15/23<br>11/15/23                            | 0.90                   |              | Ramp 2<br>NB I-49 A   | cel Lane (i              | (instal | led erosion control blanket) | 6+30<br>1082+00  |                     | 12+80.56<br>1086+40  |                     |                        |     |
| 0900           |              | TYPE 2D EROSION CO                       |                                      |                | 11/15/23  | 500.00                 |              |                       |                          |         | led blanket instead of TRM)  | 1082+00          |                     | 1086+40              |                     |                        |     |
| 0940           |              | MISC. AGGREGATE F                        |                                      | 11/14/23       |   | 1,832.00               | SQYD         | SB MO-7               |                          |         |                              | 15+71.02         |                     | 20+31.63             |                     |                        |     |
| 0950           | 5021334      | CONCRETE PAVEMEN                         | NT (10 1/2 IN. NON-REINF,            |                | 11/14/23<br>11/16/23                            | 2,617.10<br>1,832.00   | SQYD<br>SQYD | Ramp 1<br>SB MO-7     |                          |         |                              | 0+09.97          |                     | 10+42.12<br>20+31.63 |                     |                        |     |
| 0980           | 5021340      | TYPE A2 SHOULDER                         |                                      |                | 11/14/23  | 423.60                 | SQYD         | Ramp 1                |                          |         |                              | 1+55.79          |                     | 7+91.00              |                     |                        |     |
| 1000           |              |  | RANS SEC (REG/NO CURB)               |                | 11/7/23   | 0.00                   | EA           |                       |                          |         | CP 23-22 Underrun            |                  |                     |                      |                     |                        |     |
| 1760<br>1870   |              | CLASS 1 EXCAVATION<br>NU 43, PRESTRESSED |                                      |                | 11/16/23<br>11/14/23                            | 0.00                   | CUYD         | Change C<br>Bridge A9 |                          | 005 U   | nderrun                      | 13+34.91         |                     | 15+44.41             |                     |                        |     |
| 1950           |              | CLASS 1 EXCAVATION                       |                                      |                | 11/14/23  |                        |              | Change C              |                          | 005 U   | Inderrun                     | 13+34.91         |                     | 13744.41             |                     |                        |     |
| e info         | mation be    | low this line are de                     | etails for Construction Sig          | ins (if app    |   |                        |              |                       |                          |         |                              |                  |                     |                      |                     |                        |     |
| Project        | Line Numbe   |  | Total Quantity Posted For DWF<br>218 |                | Siç<br>04-1aL 48                                | gn Informat            |              | Sta                   | tion Log                 |         | Location<br>NB I-49          | Number of Ite    | ms SF E             | ach Sign             | Special S           | Sign SF Each Special S | *   |
| IP3443         | 0320         | July 25, 2023                            | 210                                  | (AF            | ROW SYM   | BOL)                   | MERGE        |                       | 156.3                    |         |                              | 1.00             |                     |                      |                     |                        | 16  |
|                |              |  |                                      | RIC            | 020-5 48x<br>GHT/CENTE<br>EAD                   |                        | NE CLO       | SED                   | 156.4                    | .41     | NB I-49                      | 2.00             | 16.00               |                      |                     |                        | 32  |
|                |              |  |                                      | wo             | 020-1 48>                                       | 48 16.00               |              |                       | 155.8                    | .887    | NB I-49                      | 2.00             | 16.00               |                      |                     |                        | 32  |
|                |              |  |                                      |                | AD/BRIDGI<br>NST-8 48                           |                        |              | AD                    | 155.3                    | 71      | NB I-49                      | 2.00             | 12.00               |                      |                     |                        | 24  |
|                |              |  |                                      | ZO             | NE NO PHO                                       | ONE ZONE               |              |                       |                          |         |                              |                  |                     |                      |                     |                        |     |
|                |              |  |                                      |                | 5-1 36x4<br>NST-5 96                            | 8 12.00 0              |              |                       | 157.2                    |         | NB I-49<br>NB I-49           | 1.00             | 12.00               |                      |                     |                        | 12  |
|                |              |  |                                      | PR             | ESENCE  |                        |              |                       |                          |         |                              |                  |                     |                      |                     |                        |     |
|                |              |  |                                      | RIC            | 020-6a 48<br>GHT/CENTE                          | x48 16.00<br>R/LEFT L/ | NE CLO       | SED                   | 156.7                    | .71     | NB I-49                      | 1.00             | 16.00               |                      |                     |                        | 16  |
|                |              |  |                                      | GC<br>(PL      | 20-5aP 36<br>AQUE)                              | ix24 6.00              | WORK Z       | ONE                   | 156.9                    | .91     | NB I-49                      | 2.00             | 6.00                |                      |                     |                        | 12  |
|                |              |  |                                      | R2-<br>XX      |   | 3 12.00 SI             | PEED LIN     | ΙΙΤ                   | 156.9                    | .91     | NB I-49                      | 2.00             | 12.00               |                      |                     |                        | 24  |
|                |              |  |                                      | со             | NST-7 72  | x36 18.00              | RATE O       | UR                    | 155.6                    | .611    | NB I-49                      | 1.00             | 18.00               |                      |                     |                        | 18  |
|                |              | July 26, 2023                            | 470                                  |                | 0RK ZONE<br>021-5 48x                           | 48 16.00               | SHOULD       | ER                    | 1.463                    | 33      | EB 275th                     | 1.00             | 16.00               |                      |                     |                        | 16  |
|                |              |  |                                      | wo             | NST-5 96  | )                      |              |                       | 1 409                    | 20      | FB 275th                     | 1.00             | 32.00               |                      |                     |                        | 32  |
|                |              |  |                                      | PR             | ESENCE  |                        |              | <i>J</i> F            |                          |         |                              |                  |                     |                      |                     |                        |     |
|                |              |  |                                      |                | 20-1 48<br>AD/BRIDGI                            |                        |              | AD                    | 1.158                    | 58      | EB 275th                     | 1.00             | 16.00               |                      |                     |                        | 16  |
|                |              |  |                                      | CO<br>ZO       | NST-8 48<br>NE NO PHO                           | x36 12.00<br>DNE ZONE  | WORK         |                       | 0.946                    | 46      | EB 275th                     | 1.00             | 12.00               |                      |                     |                        | 12  |
|                |              |  |                                      | co             | NST-7 72<br>ORK ZONE                            | x36 18.00              |              | UR                    | 0.83                     | 31      | EB 275th                     | 1.00             | 18.00               |                      |                     |                        | 18  |
|                |              |  |                                      | wo             | 020-1 48>                                       | 48 16.00               |              |                       | 0.0                      |         | NB Brookhart                 | 1.00             | 16.00               |                      |                     |                        | 16  |
|                |              |  |                                      |                | AD/BRIDGI<br>NST-5 96                           |                        |              |                       | 145.6                    | .647    | MO-7 N                       | 1.00             | 32.00               |                      |                     |                        | 32  |
|                |              |  |                                      | PR             | ESENCE  |                        |              |                       |                          |         |                              | 0.00             | 40.00               |                      |                     |                        |     |
|                |              |  |                                      | RIC            | 020-5 48x<br>GHT/CENTE<br>EAD                   | 48 16.00<br>R/LEFT L/  | NE CLO       | SED                   |                          |         | SB I-49                      | 2.00             | 16.00               |                      |                     |                        | 32  |
|                |              |  |                                      | со             | NST-7 72  | x36 18.00              | RATE O       | UR                    | 145.                     | .745    | MO-7 N                       | 1.00             | 18.00               |                      |                     |                        | 18  |
|                |              |  |                                      |                | NRK ZONE  | x36 12 00              | WORK         |                       | 145 /                    | .847    | MO-7 N                       | 2.00             | 12.00               |                      |                     |                        | 24  |
|                |              |  |                                      | ZO             | NE NO PHO                                       | ONE ZONE               |              |                       |                          |         |                              |                  |                     |                      |                     |                        |     |
|                |              |  |                                      | RO             | 020-1 48x<br>AD/BRIDGI                          | RAMP W                 | ORK AHE      |                       |                          |         | MO-7 N                       | 2.00             | 16.00               |                      |                     |                        | 32  |
|                |              |  |                                      | WC             | 021-5 48x<br>ORK AHEAD                          | 48 16.00<br>)          | SHOULD       | ER                    | 146.4                    | .491    | MO-7 N                       | 1.00             | 16.00               |                      |                     |                        | 16  |
|                |              |  |                                      | CO             | NST-5 96<br>ESENCE                              | x48 32.00              | POINT        | DF                    | 24.84                    | 346     | SB I-49                      | 1.00             | 32.00               |                      |                     |                        | 32  |
|                |              |  |                                      | со             | NST-7 72  | x36 18.00              | RATE O       | UR                    | 25.09                    | )93     | SB I-49                      | 1.00             | 18.00               |                      |                     |                        | 11  |
|                |              |  |                                      |                | NRK ZONE  | x36 12 00              | WORK         |                       | 25.19                    | 197     | SB I-49                      | 2.00             | 12.00               |                      |                     |                        | 24  |
|                |              |  |                                      |                | NE NO PHO                                       |                        |              |                       |                          |         |                              |                  |                     |                      |                     |                        |     |
|                |              |  |                                      |                |   | 40                     |              |                       |                          |         |                              |                  |                     |                      |                     |                        |     |
|                |              |  |                                      | W0<br>R0       | 020-1 48x<br>AD/BRIDGI                          | E/RAMP W               |              |                       | 25.30                    | 302     | SB I-49                      | 2.00             | 16.00               |                      |                     |                        | 32. |
|                |              |  |                                      | WC<br>RO<br>WC | 020-1 48x<br>AD/BRIDGI<br>04-1aR 48<br>RROW SYM | E/RAMP W               |              |                       | 25.30                    | 302     | SB 1-49<br>SB 1-49           | 1.00             | 16.00               |                      |                     |                        | 32  |



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Sime (if applicable)

|     | e Number  | DWR Date           | Total Quantity Posted For DWR Date |  | Station | Log Mile | Location               | Number of Items |       | Special Sign          | SF Each Special Sign |    |
|-----|-----------|--------------------|------------------------------------|--|---------|----------|------------------------|-----------------|-------|-----------------------|----------------------|----|
| 032 | 0         | July 26, 2023      | 470                                | GO20-5aP 36x24 6.00 WORK ZONE<br>(PLAQUE)                      |         |          | SB I-49                | 2.00            | 6.00  |                       |                      | 12 |
|     |           |                    |                                    | R2-1 36x48 12.00 SPEED LIMIT XX                                |         |          | SB I-49                | 2.00            | 12.00 |                       |                      | 2  |
|     |           |                    |                                    | WO20-1 48x48 16.00<br>ROAD/BRIDGE/RAMP WORK AHEAD              |         |          | SB I-49                | 2.00            | 16.00 |                       |                      | 3  |
|     |           | August 8, 2023     | 16                                 | WO20-1 48x48 16.00<br>ROAD/BRIDGE/RAMP WORK AHEAD              |         | 0.109    | MO-2 RAMP TO SB I-49   | 1.00            | 16.00 |                       |                      | 1  |
|     |           |                    | 32                                 | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 156.279  | NB I-49                | 32.00           | 1.00  | RUMBLE STRIPS AHEAD   |                      | 5  |
|     |           |                    | 157                                | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 145.981  | MO-7 N                 | 32.00           | 1.00  | RUMBLE STRIPS AHEAD   | 16.00                | 3  |
|     |           |                    |                                    | WO20-5 48x48 16.00<br>RIGHT/CENTER/LEFT LANE CLOSED<br>AHEAD   |         | 146.045  | MO-7 N                 | 2.00            | 16.00 |                       |                      | 3  |
|     |           |                    |                                    | WO4-1aL 48x48 16.00 MERGE<br>(ARROW SYMBOL)                    |         | 146.184  | MO-7 N                 | 1.00            | 16.00 |                       |                      |    |
|     |           |                    |                                    | WO20-6a 48x48 16.00<br>RIGHT/CENTER/LEFT LANE CLOSED           |         | 146.184  | MO-7 N                 | 1.00            | 16.00 |                       |                      |    |
|     |           |                    |                                    | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 146.447  | MO-7 N                 | 17.00           | 1.00  | DETOUR N 49 ARROW     |                      |    |
|     |           |                    |                                    | R11-2 48x30 10.00 ROAD<br>CLOSED                               |         | 146.474  | MO-7 N                 | 1.00            | 10.00 |                       |                      |    |
|     |           |                    |                                    | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 146.518  | MO-7 N                 | 17.00           | 1.00  | DETOUR N 49 ARROW 50B |                      |    |
|     |           |                    |                                    | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 146.563  | MO-7 N                 | 17.00           | 1.00  | DETOUR N 49 ARROW 50C |                      |    |
|     |           | August 14, 2023    | 16                                 | WO5-1 48x48 16.00  | 1+00    |          | Ramp 1 to NB I-49      | 1.00            | 16.00 |                       |                      |    |
|     |           | September 14, 2023 | 148                                | ROAD/BRIDGE/RAMP NARROWS                                       |         | 146.326  | MO-7 N                 | 1.00            | 16.00 |                       |                      |    |
|     |           |                    |                                    | CURVE (SYMBOL LEFT ARROW)                                      |         | 146.477  | MO-7 N                 | 1.00            | 16.00 |                       |                      |    |
|     |           |                    |                                    | (SYMBOL FROM RIGHT)<br>W03-3 48x48 16.00 SIGNAL                |         | 146.521  | MO-7 N                 | 1.00            | 16.00 |                       |                      |    |
|     |           |                    |                                    | AHEAD (SYMBOL)<br>WO5-1 48x48 16.00                            |         | 26.142   | SB I-49                | 1.00            | 16.00 |                       |                      |    |
|     |           |                    |                                    | ROAD/BRIDGE/RAMP NARROWS<br>W020-1 48x48 16.00                 |         | 1.894    | SB Orchard Rd          | 1.00            | 16.00 |                       |                      |    |
|     |           |                    |                                    | ROAD/BRIDGE/RAMP WORK AHEAD<br>W013-1 30x30 6.25 ADVISORY      |         | 26.142   | SB I-49                | 1.00            | 6.25  |                       |                      |    |
|     |           |                    |                                    | SPEED (PLAQUE)<br>R10-6 24x36 6.00 STOP HERE                   |         |          | MO-7 N, MO-7 S, Ramp 2 | 5.00            | 6.00  |                       |                      |    |
|     |           |                    |                                    | ON RED (45 DEGREE ARROW<br>WO1-4L 48x48 16.00 REVERSE          |         | 40.212   | MO-7 S                 | 1.00            | 16.00 |                       |                      |    |
|     |           |                    |                                    | CURVE (SYMBOL LEFT ARROW)<br>W01-4R 48x48 16.00 REVERSE        |         | 40.058   | MO-7 S                 | 1.00            | 16.00 |                       |                      |    |
|     |           | September 21, 2023 | 58                                 | CURVE (SYMBOL RIGHT ARROW)<br>WO1-4R 48x48 16.00 REVERSE       |         |          | NB I-49                | 1.00            | 16.00 |                       |                      |    |
|     |           |                    |                                    | CURVE (SYMBOL RIGHT ARROW)<br>WO1-4L 48x48 16.00 REVERSE       |         |          | NB I-49                | 1.00            | 16.00 |                       |                      |    |
|     |           |                    |                                    | CURVE (SYMBOL LEFT ARROW)<br>R11-2 48x30 10.00 ROAD            | 24+00   |          | MO-7 N                 | 1.00            | 10.00 |                       |                      |    |
|     |           |                    |                                    | CLOSED<br>Variable ??x?? 1.00 SPECIAL SIGN                     | 21.00   |          |                        | 16.00           | 1.00  | Added Lane            |                      |    |
|     |           | October 23, 2023   | 262                                | BY QUANTITY OF SQUARE FEET<br>W020-2 48x48 16.00 DETOUR        |         | 1.045    | EB 275th St            | 1.00            | 16.00 | Audou Lano            |                      |    |
|     |           | 0010061 20, 2020   | 202                                | AHEAD<br>Variable ??x?? 1.00 SPECIAL SIGN                      |         |          | EB 283rd St            |                 |       | 500 Dataua (0         |                      |    |
|     |           |                    |                                    | BY QUANTITY OF SQUARE FEET                                     |         | 0.816    |                        | 27.70           | 1.00  | 50Q, Detour 49        |                      |    |
|     |           |                    |                                    | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 1.486    | EB 289th St            | 27.70           | 1.00  | 50Q, Detour 49        |                      |    |
|     |           |                    |                                    | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 5.509    | SB Outer Rd            | 29.70           | 1.00  | 50E, Detour N 49      |                      |    |
|     |           |                    |                                    | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 5.398    | SB Outer Rd            | 29.70           | 1.00  | 50D, Detour N 49      |                      |    |
|     |           |                    |                                    | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 3.783    | WB 283rd St            | 27.70           | 1.00  | 50R, Detour 49        |                      |    |
|     |           |                    |                                    | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 3.609    | SB Outer Rd            | 29.70           | 1.00  | 50A, Detour N 49      |                      |    |
|     |           |                    |                                    | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 2.472    | SB Outer Rd            | 29.70           | 1.00  | 50A, Detour N 49      |                      |    |
|     |           |                    |                                    | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 2.439    | EB 299th St            | 27.70           | 1.00  | 50Q, Detour 49        |                      |    |
|     |           |                    |                                    | WO20-2 48x48 16.00 DETOUR<br>AHEAD                             |         | 1.556    | SB Brookhart Dr        | 1.00            | 16.00 |                       |                      |    |
|     |           | October 26, 2023   | 208                                | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 0.734    | WB 275th St            | 29.70           | 1.00  | 50E, Detour N 49      |                      |    |
|     |           |                    |                                    | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 1.64     | SB Brookhart Dr        | 29.70           | 1.00  | 50A, Detour N 49      |                      |    |
|     |           |                    |                                    | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 1.267    | EB 275th St            | 29.70           | 1.00  | 50C, Detour N 49      |                      |    |
|     |           |                    |                                    | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 4.327    | NB Outer Rd            | 29.70           | 1.00  | 50C, Detour N 49      |                      |    |
|     |           |                    |                                    | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 1.672    | SB Brookhart Dr        | 29.70           | 1.00  | 50E, Detour N 49      |                      |    |
|     |           |                    |                                    | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 1.568    | SB Outer Rd            | 29.70           | 1.00  | 50E, Detour N 49      |                      |    |
|     |           |                    |                                    | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 1.394    | EB 275th St            | 29.70           | 1.00  | 50E, Detour N 49      |                      |    |
|     |           | November 8, 2023   | 59                                 | Variable ??x?? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 2.536    | SB Outer Rd            | 29.70           | 1.00  | 50A, Detour N 49      |                      |    |
|     |           |                    |                                    | Variable ????? 1.00 SPECIAL SIGN<br>BY QUANTITY OF SQUARE FEET |         | 1.672    | SB Brookhart Dr        | 29.70           | 1.00  | 50E, Detour N 49      |                      |    |
|     | 0 - Total |                    |                                    | BT QUANTITY OF SQUARE FEET                                     |         |          |                        |                 |       |                       |                      | 16 |



| Project | Line                 | Description                                    | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By   | Amount        | Remarks  |  |
|---------|----------------------|--|--------------------|-----------------------------|----------------|-----------------|-----------------|---------------|--|--|
| J4P3443 | 0040                 | EMBANKMENT IN<br>PLACE                         | Material           |                             | 2              | Aug 2,<br>2023  | SYSTEM          | \$77,140.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0001) due to user raybol1 overridding Payment<br>Estimate Exception 1 on the current Payment Estimate. |  |
|         |                      |  |                    |                             | 2              | Aug 2,<br>2023  | SYSTEM          | (\$77,140.00) |  |  |
|         |                      |  |                    | - Total                     |                |                 |                 | \$0.00        |  |  |
|         |                      |  | Material - To      | tal                         |                |                 |                 | \$0.00        |  |  |
|         | 0040 -               | Total  |                    |                             |                |                 |                 | \$0.00        |  |  |
|         | 0100                 | AGGREGATE FOR<br>BASE (6 IN.                   | Material           |                             | 7              | Oct 16,<br>2023 | SYSTEM          | \$1,918.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0003) due to user raybol1 overridding Payment<br>Estimate Exception 1 on the current Payment Estimate. |  |
|         |                      | THICK)   |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM          | (\$1,918.00)  |  |  |
|         |                      |  |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM          | \$3,220.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0002) due to user raybol1 overridding Payment<br>Estimate Exception 1 on the current Payment Estimate. |  |
|         |                      |  |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM          | (\$3,220.00)  |  |  |
|         |                      |  |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM          | \$3,220.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0002) due to user raybol1 overridding Payment<br>Estimate Exception 1 on the current Payment Estimate. |  |
|         |                      |  |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM          | (\$3,220.00)  |  |  |
|         |                      |  |                    | - Total                     |                |                 |                 | \$0.00        |  |  |
|         |                      |  | Material - To      | tal                         |                |                 |                 | \$0.00        |  |  |
|         | 0100 - Total<br>0110 | Total  |                    |                             |                |                 |                 | \$0.00        |  |  |
|         | 0110                 | MISC.<br>AGGREGATE FOR<br>BASE                 | Material           |                             | 5              | Sep 18,<br>2023 | SYSTEM          | \$5,808.60    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0010) due to user raybol1 overridding Payment<br>Estimate Exception 1 on the current Payment Estimate. |  |
|         |                      | DAGE   |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM          | (\$5,808.60)  |  |  |
|         |                      |  |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM          | \$5,808.60    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0004) due to user raybol1 overridding Payment<br>Estimate Exception 1 on the current Payment Estimate. |  |
|         |                      |  |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM          | (\$5,808.60)  |  |  |
|         |                      |  |                    |                             |                | 7               | Oct 16,<br>2023 | SYSTEM        | \$17,988.60  | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0004) due to user raybol1 overridding Payment<br>Estimate Exception 2 on the current Payment Estimate. |
|         |                      |  |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM          | (\$17,988.60) |  |  |
|         |                      |  |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM          | \$17,988.60   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0003) due to user raybol1 overridding Payment<br>Estimate Exception 2 on the current Payment Estimate. |  |
|         |                      |  |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM          | (\$17,988.60) |  |  |
|         |                      |  |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM          | \$30,055.20   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0003) due to user raybol1 overridding Payment<br>Estimate Exception 2 on the current Payment Estimate. |  |
|         |                      |  |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM          | (\$30,055.20) |  |  |
|         |                      |  |                    | - Total                     |                |                 |                 | \$0.00        |  |  |
|         |                      |  | Material - To      | tal                         |                |                 |                 | \$0.00        |  |  |
|         | 0110 -               | Total  |                    |                             |                |                 |                 | \$0.00        |  |  |
|         | 0140                 | CONCRETE<br>PAVEMENT (10 1/2<br>IN. NON-REINF, | Material           |                             | 8              | Nov 2,<br>2023  | SYSTEM          | \$31,386.70   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0004) due to user raybol1 overridding Payment<br>Estimate Exception 4 on the current Payment Estimate. |  |
|         |                      |  |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM          | (\$31,386.70) |  |  |
|         |                      |  |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM          | \$31,386.70   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0004) due to user raybol1 overridding Payment<br>Estimate Exception 4 on the current Payment Estimate. |  |
|         |                      |  |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM          | (\$31,386.70) |  |  |
|         |                      |  |                    | - Total                     |                |                 |                 | \$0.00        |  |  |
|         |                      |  |                    |                             |                |                 |                 |               |  |  |



Nov 18, 2023

| oject | Line                  | Description                                       | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks   |
|-------|-----------------------|---|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| 3443  | 0140                  | CONCRETE<br>PAVEMENT (10 1/2<br>IN. NON-REINF,    | Material - To      | tal                         |                |                 |               | \$0.00        |   |
|       | 0140 -                | Total   |                    |                             |                |                 |               | \$0.00        |   |
|       | 0150                  | CONCRETE<br>APPROACH<br>PAVEMENT                  | Material           |                             | 8              | Nov 2,<br>2023  | SYSTEM        | \$14,652.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0005) due to user raybol1 overridding Payment<br>Estimate Exception 17 on the current Payment Estimate. |
|       |                       |   |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | (\$14,652.00) |   |
|       |                       |   |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | \$28,332.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0005) due to user raybol1 overridding Payment<br>Estimate Exception 12 on the current Payment Estimate. |
|       |                       |   |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | (\$28,332.00) |   |
|       |                       |   |                    | - Total                     |                |                 |               | \$0.00        |   |
|       |                       |   | Material - To      | tal                         |                |                 |               | \$0.00        |   |
|       | 0150 -                | Total   |                    |                             |                |                 |               | \$0.00        |   |
|       | 0340                  | CHANNELIZER<br>(TRIM LINE)                        | Overrun            | Overrun                     | 6              | Oct 2,<br>2023  | SYSTEM        | (\$4,997.00)  |   |
|       |                       |   |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | \$4,997.00    | Unit price based on averaged overrun adjustments for installed quantity on all<br>previous payment estimates. Price Adjustments of ',19.00000 - 19.00000, 'is<br>applied (if non-zero).                     |
|       |                       |   |                    | Overrun - T                 | otal           |                 |               | \$0.00        |   |
|       |                       |   | H Material         | tal                         |                |                 |               | \$0.00        |   |
|       | <b>0340</b> -<br>0390 | Total   | N                  |                             |                |                 |               | \$0.00        |   |
|       | 0390                  | CMS WITH<br>COMMUNICATION<br>INTERFACE,<br>CONT F | Material           |                             | 1              | Jul 17,<br>2023 | SYSTEM        | \$23,200.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0002) due to user raybol1 overridding Payment<br>Estimate Exception 1 on the current Payment Estimate.  |
|       |                       | CONTE   | CONT F             |                             | 1              | Jul 17,<br>2023 | SYSTEM        | (\$23,200.00) |   |
|       |                       |   |                    | - Total                     |                |                 |               | \$0.00        |   |
|       |                       |   | Material - To      | tal                         |                |                 |               | \$0.00        |   |
|       | 0390 -                | Total   |                    |                             |                |                 |               | \$0.00        |   |
|       | 0420                  | TEMPORARY<br>TRAFFIC<br>BARRIER, CONT.<br>FURN/RE | Material           |                             | 2              | Aug 2,<br>2023  | SYSTEM        | \$28,800.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0003) due to user raybol1 overridding Payment<br>Estimate Exception 2 on the current Payment Estimate.  |
|       |                       |   |                    |                             | 2              | Aug 2,<br>2023  | SYSTEM        | (\$28,800.00) |   |
|       |                       |   |                    | - Total                     |                |                 |               | \$0.00        |   |
|       |                       |   | Material - To      | tal                         |                |                 |               | \$0.00        |   |
|       |                       |   | Overrun            | Overrun                     |                | Aug 16,<br>2023 | SYSTEM        | (\$3,584.00)  |   |
|       |                       |   |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | (\$10,272.00) |   |
|       |                       |   |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | \$13,856.00   | Unit price based on averaged overrun adjustments for installed quantity on al<br>previous payment estimates. Price Adjustments of ',16.00000 - 16.00000, 'is<br>applied (if non-zero).                      |
|       |                       |   |                    | Overrun - T                 | otal           |                 |               | \$0.00        |   |
|       |                       |   | Overrun - To       | tal                         |                |                 |               | \$0.00        |   |
|       | 0420 -                | Total   |                    |                             |                |                 |               | \$0.00        |   |
|       | 0460                  | PAVEMENT EDGE<br>TREATMENT                        | Material           |                             | 7              | Oct 16,<br>2023 | SYSTEM        | \$5,576.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0002) due to user raybol1 overridding Payment<br>Estimate Exception 14 on the current Payment Estimate. |
|       |                       |   |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM        | (\$5,576.00)  |   |
|       |                       |   |                    | - Total                     |                |                 |               | \$0.00        |   |
|       |                       |   | Material - To      |                             |                |                 |               | \$0.00        |   |
|       |                       |   | Overrun            | Overrun                     |                | Oct 16,<br>2023 | SYSTEM        | (\$204.00)    |   |
|       |                       |   |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | (\$3,060.00)  |   |
|       |                       |   |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | \$3,264.00    | Unit price based on averaged overrun adjustments for installed quantity on all<br>previous payment estimates. Price Adjustments of ',6.80000 - 6.80000, 'is   |



| Project | Line   | Description                                  | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount       | Remarks   |
|---------|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| J4P3443 | 0460   | PAVEMENT EDGE                                | Overrun            | Overrun                     |                |                 |               |              | applied (if non-zero).  |
|         |        | TREATMENT                                    |                    | Overrun - To                | otal           |                 |               | \$0.00       |   |
|         |        |  | Overrun - To       | tal                         |                |                 |               | \$0.00       |   |
|         | 0460 - | Total  |                    |                             |                |                 |               | \$0.00       |   |
|         | 0550   | TEMPORARY<br>REMOVABLE<br>MARKING TAPE,      | Material           |                             | 5              | Sep 18,<br>2023 | SYSTEM        | \$624.00     | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0015) due to user raybol1 overridding Payment<br>Estimate Exception 10 on the current Payment Estimate. |
|         |        | 24 IN.                                       |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | (\$624.00)   |   |
|         |        |  |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$936.00     | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0010) due to user raybol1 overridding Payment<br>Estimate Exception 10 on the current Payment Estimate. |
|         |        |  |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$936.00)   |   |
|         |        |  |                    | - Total                     |                |                 |               | \$0.00       |   |
|         |        |  | Material - Tot     | tal                         |                |                 |               | \$0.00       |   |
|         | 0550 - | Total  |                    |                             |                |                 |               | \$0.00       |   |
|         | 0560   | TEMPORARY<br>NON-REMOVABLE<br>TAPE LT/RT     | Material           |                             | 5              | Sep 18,<br>2023 | SYSTEM        | \$160.00     | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0016) due to user raybol1 overridding Payment<br>Estimate Exception 11 on the current Payment Estimate. |
|         |        | ARROW  |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | (\$160.00)   |   |
|         |        |  |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$160.00     | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0011) due to user raybol1 overridding Payment<br>Estimate Exception 11 on the current Payment Estimate. |
|         |        |  |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$160.00)   |   |
|         |        |  |                    | - Total                     |                |                 |               | \$0.00       |   |
|         |        | ) - Total                                    | Material - Tot     | tal                         |                |                 |               | \$0.00       |   |
|         | 0560 - | Total  |                    |                             |                |                 |               | \$0.00       |   |
|         | 0570   |  | Material           |                             | 5              | Sep 18,<br>2023 | SYSTEM        | \$924.00     | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0003) due to user raybol1 overridding Payment<br>Estimate Exception 12 on the current Payment Estimate. |
|         |        |  |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | (\$924.00)   |   |
|         |        |  |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$924.00     | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0012) due to user raybol1 overridding Payment<br>Estimate Exception 12 on the current Payment Estimate. |
|         |        |  |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$924.00)   |   |
|         |        |  |                    | - Total                     |                |                 |               | \$0.00       |   |
|         |        |  | Material - Tot     | tal                         |                |                 |               | \$0.00       |   |
|         |        |  | Overrun            | Overrun                     | 5              | Sep 18,<br>2023 | SYSTEM        | (\$528.00)   |   |
|         |        |  |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | \$528.00     | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',132.00000 - 132.00000, 'is applied (if non-zero).                         |
|         |        |  |                    | Overrun - T                 | otal           |                 |               | \$0.00       |   |
|         |        |  | Overrun - To       | tal                         |                |                 |               | \$0.00       |   |
|         | 0570 - | Total  |                    |                             |                |                 |               | \$0.00       |   |
|         | 0580   | TEMPORARY N/R<br>MARK TAPE<br>COMBO ST LT/RT | Material           |                             | 5              | Sep 18,<br>2023 | SYSTEM        | \$1,040.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0005) due to user raybol1 overridding Payment<br>Estimate Exception 13 on the current Payment Estimate. |
|         |        |  |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | (\$1,040.00) |   |
|         |        |  |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$1,040.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0013) due to user raybol1 overridding Payment<br>Estimate Exception 13 on the current Payment Estimate. |
|         |        |  |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$1,040.00) |   |
|         |        |  |                    | - Total                     |                |                 |               | \$0.00       |   |
|         |        |  | Material - Tot     | tal                         |                |                 |               | \$0.00       |   |
|         |        |  | Overrun            | Overrun                     | 5              | Sep 18,         | SYSTEM        | (\$260.00)   |   |
|         |        |  |                    |                             |                |                 |               |              |   |



Nov 18, 2023

| Project | Line   | Description                                    | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By  | Amount          | Remarks   |   |   |
|---------|--------|--|--------------------|-----------------------------|----------------|-----------------|----------------|-----------------|---|---|---|
| J4P3443 | 0580   | TEMPORARY N/R                                  | Overrun            | Overrun                     |                | 2023            |                |                 |   |   |   |
|         |        | MARK TAPE<br>COMBO ST LT/RT                    |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM         | \$260.00        | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',260.00000 - 260.00000, 'is applied (if non-zero).                         |   |   |
|         |        |  |                    | Overrun - T                 | otal           |                 |                | \$0.00          |   |   |   |
|         |        |  | Overrun - To       | tal                         |                |                 |                | \$0.00          |   |   |   |
|         | 0580 - | Total  |                    |                             |                |                 |                | \$0.00          |   |   |   |
|         | 0650   | PERMANENT<br>EROSION<br>CONTROL                | Material           |                             | 2              | Aug 2,<br>2023  | SYSTEM         | \$266.00        | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0004) due to user raybol1 overridding Payment<br>Estimate Exception 3 on the current Payment Estimate.  |   |   |
|         |        | GEOTEXTILE                                     |                    |                             | 2              | Aug 2,<br>2023  | SYSTEM         | (\$266.00)      |   |   |   |
|         |        |  |                    |                             | 3              | Aug 16,<br>2023 | SYSTEM         | \$4,335.80      | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0004) due to user raybol1 overridding Payment<br>Estimate Exception 1 on the current Payment Estimate.  |   |   |
|         |        |  |                    |                             | 3              | Aug 16,<br>2023 | SYSTEM         | (\$4,335.80)    |   |   |   |
|         |        |  |                    |                             | 4              | Sep 5,<br>2023  | SYSTEM         | \$4,335.80      | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0003) due to user raybol1 overridding Payment<br>Estimate Exception 7 on the current Payment Estimate.  |   |   |
|         |        | - Total<br>CLASS B-1<br>CONCRETE<br>(CULVERTS) |                    |                             | 4              | Sep 5,<br>2023  | SYSTEM         | (\$4,335.80)    |   |   |   |
|         |        |  |                    | - Total                     |                |                 |                | \$0.00          |   |   |   |
|         |        |  | Material - To      | tal                         |                |                 |                | \$0.00          |   |   |   |
|         | 0650 - | Total  |                    |                             |                |                 |                | \$0.00          |   |   |   |
|         | 0670   | CONCRETE                                       | Material           | Material                    |                | 6               | Oct 2,<br>2023 | SYSTEM          | \$78,660.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0014) due to user raybol1 overridding Payment<br>Estimate Exception 24 on the current Payment Estimate. |   |
|         |        |  |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM         | (\$78,660.00)   |   |   |   |
|         |        |  |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM         | \$78,660.00     | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0011) due to user raybol1 overridding Payment<br>Estimate Exception 24 on the current Payment Estimate. |   |   |
|         |        |  |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM         | (\$78,660.00)   |   |   |   |
|         |        |  |                    | - Total                     |                |                 |                | \$0.00          |   |   |   |
|         |        |  | Material - To      | tal                         |                |                 |                | \$0.00          |   |   |   |
|         | 0670 - | Total  |                    | _                           |                |                 |                | \$0.00          |   |   |   |
|         | 0680   | REINFORCING<br>STEEL<br>(CULVERTS)             | Material           |                             | 4              | Sep 5,<br>2023  | SYSTEM         | \$13,500.00     | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0004) due to user raybol1 overridding Payment<br>Estimate Exception 17 on the current Payment Estimate. |   |   |
|         |        |  |                    |                             | 4              | Sep 5,<br>2023  | SYSTEM         | (\$13,500.00)   |   |   |   |
|         |        |  |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM         | \$13,500.00     | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0017) due to user raybol1 overridding Payment<br>Estimate Exception 29 on the current Payment Estimate. |   |   |
|         |        |  |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM         | (\$13,500.00)   |   |   |   |
|         |        |  |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM         | \$17,199.00     | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0015) due to user raybol1 overridding Payment<br>Estimate Exception 30 on the current Payment Estimate. |   |   |
|         |        |  |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM         | (\$17,199.00)   |   |   |   |
|         |        |  |                    |                             |                |                 | 7              | Oct 16,<br>2023 | SYSTEM  | \$17,199.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0012) due to user raybol1 overridding Payment<br>Estimate Exception 31 on the current Payment Estimate. |
|         |        |  |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM         | (\$17,199.00)   |   |   |   |
|         |        |  |                    |                             |                | 8               | Nov 2,<br>2023 | SYSTEM          | \$17,199.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0007) due to user raybol1 overridding Payment<br>Estimate Exception 33 on the current Payment Estimate. |   |
|         |        |  |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM         | (\$17,199.00)   |   |   |   |
|         |        |  |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM         | \$17,199.00     | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0011) due to user raybol1 overridding Payment<br>Estimate Exception 16 on the current Payment Estimate. |   |   |



Nov 18, 2023

| Project | Line           | Description              | Adjustment<br>Type | Other<br>Adjustment | Est.<br>Number | Created<br>Date | Created<br>By          | Amount                      | Remarks   |   |        |            |
|---------|----------------|--------------------------|--------------------|---------------------|----------------|-----------------|------------------------|-----------------------------|---|---|--------|------------|
| 4P3443  | 0680           | REINFORCING              | Material           | Туре                | 9              | Nov 16,         | SYSTEM                 | (\$17,199.00)               |   |   |        |            |
|         |                | STEEL<br>(CULVERTS)      |                    |                     | -              | 2023            |                        | (, , ,                      |   |   |        |            |
|         |                | (002121(10)              |                    | - Total             |                |                 |                        | \$0.00                      |   |   |        |            |
|         |                |                          | Material - To      | tal                 |                |                 |                        | \$0.00                      |   |   |        |            |
|         | 0680 -         |                          |                    |                     |                |                 |                        | \$0.00                      |   |   |        |            |
|         | 0820           | MULCHING                 | Material           |                     | 7              | Oct 16,<br>2023 | SYSTEM                 | \$235.00                    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0005) due to user raybol1 overridding Payment<br>Estimate Exception 37 on the current Payment Estimate. |   |        |            |
|         |                |                          |                    |                     | 7              | Oct 16,<br>2023 | SYSTEM                 | (\$235.00)                  |   |   |        |            |
|         |                |                          |                    | - Total             |                |                 |                        | \$0.00                      |   |   |        |            |
|         |                |                          | Material - To      | tal                 |                |                 |                        | \$0.00                      |   |   |        |            |
|         | 0820 -<br>0830 | SEEDING - COOL<br>SEASON | Material           |                     | 5              | Sep 18,<br>2023 | SYSTEM                 | <b>\$0.00</b><br>\$7,290.00 | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0011) due to user raybol1 overridding Payment   |   |        |            |
|         |                | GRASSES                  |                    |                     | 5              | Sep 18,         | SYSTEM                 | (\$7,290.00)                | Estimate Exception 38 on the current Payment Estimate.  |   |        |            |
|         |                |                          |                    |                     |                | 6               | 2023<br>Oct 2,<br>2023 | SYSTEM                      | \$7,290.00  | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0005) due to user raybol1 overridding Payment<br>Estimate Exception 44 on the current Payment Estimate. |        |            |
|         |                |                          |                    |                     |                | 6               | Oct 2,<br>2023         | SYSTEM                      | (\$7,290.00)  |   |        |            |
|         |                |                          |                    |                     |                |                 |                        |                             | 7   | Oct 16,<br>2023   | SYSTEM | \$8,640.00 |
|         |                |                          |                    |                     | 7              | Oct 16,<br>2023 | SYSTEM                 | (\$8,640.00)                |   |   |        |            |
|         |                |                          |                    |                     | 8              | Nov 2,<br>2023  | SYSTEM                 | \$10,260.00                 | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0008) due to user raybol1 overridding Payment<br>Estimate Exception 39 on the current Payment Estimate. |   |        |            |
|         |                |                          |                    |                     | 8              | Nov 2,<br>2023  | SYSTEM                 | (\$10,260.00)               |   |   |        |            |
|         |                |                          |                    | - Total             |                |                 |                        | \$0.00                      |   |   |        |            |
|         |                |                          | Material - To      | tal                 |                |                 |                        | \$0.00                      |   |   |        |            |
|         | 0830 -         |                          |                    |                     |                |                 |                        | \$0.00                      |   |   |        |            |
|         | 0840           | SEDIMENT TRAP<br>ROCK    | Material           |                     | 6              | Oct 2,<br>2023  | SYSTEM                 | \$140.40                    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0006) due to user raybol1 overridding Payment<br>Estimate Exception 46 on the current Payment Estimate. |   |        |            |
|         |                |                          |                    |                     | 6              | Oct 2,<br>2023  | SYSTEM                 | (\$140.40)                  |   |   |        |            |
|         |                |                          |                    |                     | 7              | Oct 16,<br>2023 | SYSTEM                 | \$140.40                    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0007) due to user raybol1 overridding Payment<br>Estimate Exception 39 on the current Payment Estimate. |   |        |            |
|         |                |                          |                    |                     | 7              | Oct 16,<br>2023 | SYSTEM                 | (\$140.40)                  |   |   |        |            |
|         |                |                          |                    | - Total             |                |                 |                        | \$0.00                      |   |   |        |            |
|         |                |                          | Material - To      | tal                 |                |                 |                        | \$0.00                      |   |   |        |            |
|         | 0840 -         | Total                    |                    |                     |                |                 |                        | \$0.00                      |   |   |        |            |
|         | 0850           | ROCK DITCH<br>CHECK      | Material           |                     | 1              | Jul 17,<br>2023 | SYSTEM                 | \$1,653.00                  | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0001) due to user raybol1 overridding Payment<br>Estimate Exception 2 on the current Payment Estimate.  |   |        |            |
|         |                |                          |                    |                     | 1              | Jul 17,<br>2023 | SYSTEM                 | (\$1,653.00)                |   |   |        |            |
|         |                |                          |                    | 2                   | 2              | Aug 2,<br>2023  | SYSTEM                 | \$1,653.00                  | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0002) due to user raybol1 overridding Payment<br>Estimate Exception 4 on the current Payment Estimate.  |   |        |            |
|         |                |                          |                    |                     | 2              | Aug 2,<br>2023  | SYSTEM                 | (\$1,653.00)                |   |   |        |            |
|         |                |                          |                    |                     | 3              | Aug 16,<br>2023 | SYSTEM                 | \$3,287.00                  | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0002) due to user raybol1 overridding Payment<br>Estimate Exception 8 on the current Payment Estimate.  |   |        |            |
|         |                |                          |                    |                     | 3              | Aug 16,<br>2023 | SYSTEM                 | (\$3,287.00)                |   |   |        |            |
|         |                |                          |                    | - Total             |                |                 |                        | \$0.00                      |   |   |        |            |



Nov 18, 2023

| ct | Line   | Description                                    | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount         | Remarks  |
|----|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|--|
| 43 | 0850   | ROCK DITCH<br>CHECK                            | Material - To      | tal                         |                |                 |               | \$0.00         |  |
|    | 0850 - | Total  |                    |                             |                |                 |               | \$0.00         |  |
|    | 0890   | TYPE 1 TURF<br>REINFORCEMENT<br>MAT            | Material           |                             | 5              | Sep 18,<br>2023 | SYSTEM        | \$2,731.10     | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0012) due to user raybol1 overridding Paymen<br>Estimate Exception 40 on the current Payment Estimate. |
|    |        |  |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | (\$2,731.10)   |  |
|    |        |  |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$2,731.10     | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0007) due to user raybol1 overridding Payme<br>Estimate Exception 47 on the current Payment Estimate.  |
|    |        |  |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$2,731.10)   |  |
|    |        |  |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM        | \$2,731.10     | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0008) due to user raybol1 overridding Payme<br>Estimate Exception 40 on the current Payment Estimate.  |
|    |        |  |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM        | (\$2,731.10)   |  |
|    |        |  |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | \$2,731.10     | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0009) due to user raybol1 overridding Payme<br>Estimate Exception 41 on the current Payment Estimate.  |
|    |        |  |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | (\$2,731.10)   |  |
|    |        |  |                    | - Total                     |                |                 |               | \$0.00         |  |
|    |        |  | Material - To      | tal                         |                |                 |               | \$0.00         |  |
|    | 0890 - | Total  |                    |                             |                |                 |               | \$0.00         |  |
|    | 0940   | MISC.<br>AGGREGATE FOR<br>BASE                 | Material           |                             | 4              | Sep 5,<br>2023  | SYSTEM        | \$52,567.20    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0001) due to user raybol1 overridding Payme<br>Estimate Exception 1 on the current Payment Estimate.   |
|    |        |  |                    |                             | 4              | Sep 5,<br>2023  | SYSTEM        | (\$52,567.20)  |  |
|    |        |  |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | \$52,567.20    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0013) due to user raybol1 overridding Paymen<br>Estimate Exception 3 on the current Payment Estimate.  |
|    |        |  |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | (\$52,567.20)  |  |
|    |        |  |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$113,109.60   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0008) due to user raybol1 overridding Payment<br>Estimate Exception 3 on the current Payment Estimate. |
|    |        |  |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$113,109.60) |  |
|    |        |  |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM        | \$119,905.20   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0009) due to user raybol1 overridding Paymer<br>Estimate Exception 4 on the current Payment Estimate.  |
|    |        |  |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM        | (\$119,905.20) |  |
|    |        |  |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | \$156,393.60   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0010) due to user raybol1 overridding Payment<br>Estimate Exception 3 on the current Payment Estimate. |
|    |        |  |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | (\$156,393.60) |  |
|    |        |  |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | \$178,377.60   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0012) due to user raybol1 overridding Paymer<br>Estimate Exception 3 on the current Payment Estimate.  |
|    |        |  |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | (\$178,377.60) |  |
|    |        |  |                    | - Total                     |                |                 |               | \$0.00         |  |
|    |        |  | Material - To      | tal                         |                |                 |               | \$0.00         |  |
|    | 0940 - |  |                    |                             |                |                 |               | \$0.00         |  |
|    | 0950   | CONCRETE<br>PAVEMENT (10 1/2<br>IN. NON-REINF, | Material           |                             | 4              | Sep 5,<br>2023  | SYSTEM        | \$340,040.40   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0002) due to user raybol1 overridding Payment<br>Estimate Exception 3 on the current Payment Estimate. |
|    |        |  |                    |                             | 4              | Sep 5,<br>2023  | SYSTEM        | (\$340,040.40) |  |
|    |        |  |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | \$429,298.80   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0014) due to user raybol1 overridding Payme<br>Estimate Exception 5 on the current Payment Estimate.   |



| ect | Line                  | Description  | Adjustment<br>Type                | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date                                    | Created<br>By    | Amount   | Remarks   |
|-----|-----------------------|--|-----------------------------------|-----------------------------|----------------|--|------------------|--|---|
| 443 | 0950                  | CONCRETE<br>PAVEMENT (10 1/2   | Material                          | 1360                        | 5              | Sep 18,<br>2023                                    | SYSTEM           | (\$429,298.80)   |   |
|     |                       | IN. NON-REINF,   |                                   |                             | 6              | Oct 2,<br>2023                                     | SYSTEM           | \$649,147.10   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0009) due to user raybol1 overridding Payment<br>Estimate Exception 5 on the current Payment Estimate.  |
|     |                       |  |                                   |                             | 6              | Oct 2,<br>2023                                     | SYSTEM           | (\$649,147.10)   |   |
|     |                       |  |                                   |                             | 7              | Oct 16,<br>2023                                    | SYSTEM           | \$870,798.60   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0010) due to user raybol1 overridding Payment<br>Estimate Exception 6 on the current Payment Estimate.  |
|     |                       |  |                                   |                             | 7              | Oct 16,<br>2023                                    | SYSTEM           | (\$870,798.60)   |   |
|     |                       |  |                                   |                             | 8              | Nov 2,<br>2023                                     | SYSTEM           | \$926,296.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0011) due to user raybol1 overridding Payment<br>Estimate Exception 7 on the current Payment Estimate.  |
|     |                       |  |                                   |                             | 8              | Nov 2,<br>2023                                     | SYSTEM           | (\$926,296.00)   |   |
|     |                       |  |                                   |                             | 9              | Nov 16,<br>2023                                    | SYSTEM           | \$1,362,307.80   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0013) due to user raybol1 overridding Payment<br>Estimate Exception 6 on the current Payment Estimate.  |
|     |                       |  |                                   |                             | 9              | Nov 16,<br>2023                                    | SYSTEM           | (\$1,362,307.80)   |   |
|     |                       |  |                                   | - Total                     |                |  |                  | \$0.00   |   |
|     |                       |  | Material - To                     | tal                         |                |  |                  | \$0.00   |   |
|     | 0950 -                | Total  |                                   |                             |                |  |                  | \$0.00   |   |
|     | 0980                  | TYPE A2<br>SHOULDER  | Material                          |                             | 8              | Nov 2,<br>2023                                     | SYSTEM           | \$29,700.00  | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0012) due to user raybol1 overridding Payment<br>Estimate Exception 10 on the current Payment Estimate. |
|     |                       |  |                                   |                             | 8              | Nov 2,<br>2023                                     | SYSTEM           | (\$29,700.00)  |   |
|     |                       |  |                                   | - Total                     |                |  |                  | \$0.00   |   |
|     |                       |  | Material - To                     | tal                         |                |  |                  | \$0.00   |   |
|     | 0980 -                |  |                                   |                             |                |  |                  | \$0.00   |   |
|     | 0990                  | MGS GUARDRAIL,<br>8 FT. POSTS, 6 FT.<br>- 3 IN                             | Construction<br>Stockpile<br>STMI |                             | 8              | Nov 2,<br>2023                                     | SYSTEM           | \$40,057.00  | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|     |                       |  |                                   | - Total                     |                |  |                  | \$40,057.00  |   |
|     | 0000                  | <b>T</b> -4-1  | Construction                      | 1 Stockpile S               | IMI - Tota     |  |                  | \$40,057.00  |   |
|     | 0990 -<br>1120        | CONDUIT, 2 IN.<br>RIGID, IN TRENCH   | Material                          |                             | 8              | Nov 2,<br>2023                                     | SYSTEM           | \$40,057.00<br>\$1,771.00  | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0013) due to user raybol1 overridding Payment<br>Estimate Exception 42 on the current Payment Estimate. |
|     |                       |  |                                   |                             | 8              | Nov 2,<br>2023                                     | SYSTEM           | (\$1,771.00)   |   |
|     |                       |  |                                   | - Total                     |                |  |                  | \$0.00   |   |
|     |                       |  | Material - To                     | tal                         |                |  |                  | \$0.00   |   |
| 1.1 |                       |  |                                   |                             |                |  |                  |  |   |
|     | 1120 -                | Total  |                                   |                             |                |  |                  | \$0.00   |   |
|     | <b>1120</b> -<br>1130 | CONDUIT, 4 IN.<br>RIGID, PUSHED  | Material                          |                             | 8              | Nov 2,<br>2023                                     | SYSTEM           | <b>\$0.00</b><br>\$1,680.00  | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0014) due to user raybol1 overridding Payment<br>Estimate Exception 43 on the current Payment Estimate. |
|     |                       | CONDUIT, 4 IN.   | Material                          |                             | 8              |  | SYSTEM<br>SYSTEM |  | Estimate Item Adjustment (0014) due to user raybol1 overridding Payment   |
|     |                       | CONDUIT, 4 IN.   |                                   | - Total                     |                | 2023<br>Nov 2,                                     |                  | \$1,680.00   | Estimate Item Adjustment (0014) due to user raybol1 overridding Payment   |
|     | 1130                  | CONDUIT, 4 IN.<br>RIGID, PUSHED  | Material<br>Material - To         |                             |                | 2023<br>Nov 2,                                     |                  | \$1,680.00<br>(\$1,680.00)   | Estimate Item Adjustment (0014) due to user raybol1 overridding Payment   |
|     |                       | CONDUIT, 4 IN.<br>RIGID, PUSHED  |                                   |                             |                | 2023<br>Nov 2,                                     |                  | \$1,680.00<br>(\$1,680.00)<br><b>\$0.00</b>                                  | Estimate Item Adjustment (0014) due to user raybol1 overridding Payment   |
|     | 1130                  | CONDUIT, 4 IN.<br>RIGID, PUSHED  |                                   |                             |                | 2023<br>Nov 2,                                     |                  | \$1,680.00<br>(\$1,680.00)<br>\$0.00<br>\$0.00                               | Estimate Item Adjustment (0014) due to user raybol1 overridding Payment   |
|     | 1130<br>1130 -        | CONDUIT, 4 IN.<br>RIGID, PUSHED<br>Total<br>CONDUIT, 3 IN.,<br>TRENCH WITH | Material - To                     |                             | 8              | 2023<br>Nov 2,<br>2023<br>Nov 2,                   | SYSTEM           | \$1,680.00<br>(\$1,680.00)<br>\$0.00<br>\$0.00<br>\$0.00                     | Estimate Item Adjustment (0014) due to user raybol1 overridding Payment<br>Estimate Exception 43 on the current Payment Estimate.   |
|     | 1130<br>1130 -        | CONDUIT, 4 IN.<br>RIGID, PUSHED<br>Total<br>CONDUIT, 3 IN.,<br>TRENCH WITH | Material - To<br>Material         | tal<br>- Total              | 8<br>8         | 2023<br>Nov 2,<br>2023<br>Nov 2,<br>2023<br>Nov 2, | SYSTEM           | \$1,680.00<br>(\$1,680.00)<br>\$0.00<br>\$0.00<br>\$0.00<br>\$1,530.00       | Estimate Item Adjustment (0014) due to user raybol1 overridding Payment<br>Estimate Exception 43 on the current Payment Estimate.   |
|     | 1130<br>1130 -        | CONDUIT, 4 IN.<br>RIGID, PUSHED<br>Total<br>CONDUIT, 3 IN.,<br>TRENCH WITH | Material - To                     | tal<br>- Total              | 8<br>8         | 2023<br>Nov 2,<br>2023<br>Nov 2,<br>2023<br>Nov 2, | SYSTEM           | \$1,680.00<br>(\$1,680.00)<br>\$0.00<br>\$0.00<br>\$1,530.00<br>(\$1,530.00) | Estimate Item Adjustment (0014) due to user raybol1 overridding Payment<br>Estimate Exception 43 on the current Payment Estimate.   |



| Project | Line           | Description                                      | Adjustment<br>Type   | Other<br>Adjustment             | Est.<br>Number | Created<br>Date | Created<br>By | Amount                   | Remarks   |
|---------|----------------|--|--|---------------------------------|----------------|-----------------|---------------|--------------------------|---|
| P3443   | 1470           | TEMPORARY  | Material   | Туре                            | 3              | Aug 16,         | SYSTEM        | \$236,000.00             | This adjustment offsets the original system-generated Material Payment  |
|         |                | TRAFFIC SIGNALS<br>AND LIGHTING                  |  |                                 |                | 2023            |               | ,                        | Estimate Item Adjustment (0003) due to user raybol1 overridding Payment<br>Estimate Exception 9 on the current Payment Estimate.  |
|         |                |  |  |                                 | 3              | Aug 16,<br>2023 | SYSTEM        | (\$236,000.00)           |   |
|         |                |  |  | - Total                         |                |                 |               | \$0.00                   |   |
|         |                |  | Material - To  | tal                             |                |                 |               | \$0.00                   |   |
|         | 1470 -         | Total  |  |                                 |                |                 |               | \$0.00                   |   |
|         | 1500           | BREAKAWAY<br>ASSEMBLY<br>(PERFORATED             | Construction<br>Stockpile<br>STMI                          |                                 | 9              | Nov 16,<br>2023 | SYSTEM        | \$2,106.00               | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|         |                | SQUARE STEEL<br>TUBE)                            | 0  | - Total                         |                |                 |               | \$2,106.00               |   |
|         |                | ,  | Construction   | 1 Stockpile S                   | IMI - Tota     |                 |               | \$2,106.00               |   |
|         |                | Total  |  |                                 |                |                 |               | \$2,106.00               |   |
|         | 1510           | 2 IN. PSST POST -<br>12 GA.                      | Construction<br>Stockpile<br>STMI                          | Total                           | 9              | Nov 16,<br>2023 | SYSTEM        | \$6,034.08               | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|         |                |  |  | - Total                         |                |                 |               | \$6,034.08               |   |
|         |                | <b>T</b>   | Construction   | n Stockpile S                   | IMI - Tota     |                 |               | \$6,034.08               |   |
|         | 1510 -         |  | 0  |                                 |                | N               | 0)(27         | \$6,034.08               |   |
|         | 1520           | DRIVEN POST<br>ANCHOR FOR 2<br>IN. PSST - 12 GA. | Construction<br>Stockpile<br>STMI                          | Total                           | 9              | Nov 16,<br>2023 | SYSTEM        | \$1,195.74               | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|         |                |  | 0 1 1  | - Total                         |                |                 |               | \$1,195.74               |   |
|         | 1500           |  | Construction   | n Stockpile S                   | IMI - Tota     |                 |               | \$1,195.74               |   |
|         |                | Total  |  |                                 |                |                 |               | \$1,195.74               |   |
|         | 1530           | 2.25 IN. PSST<br>POST INSERT (6<br>FT.) - 12 GA. | Construction<br>Stockpile<br>STMI - Total 9 Nov 16, SYSTEM |                                 |                |                 |               | \$245.28<br>\$245.28     | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|         |                |  | 0  |                                 | T.4.           |                 |               |                          |   |
|         | 4520           | Tetal  | Construction   | n Stockpile S                   | rivii - Tota   |                 |               | \$245.28                 |   |
|         |                | Total  | 0 1 1  |                                 | 0              |                 | OVOTEN        | \$245.28                 |   |
|         | 1540           | 2.5 IN. PSST POST<br>- 12 GA.                    | Construction<br>Stockpile<br>STMI                          | - Total                         | 9              | Nov 16,<br>2023 | SYSTEM        | \$2,184.96<br>\$2,184.96 | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|         |                |  | Construction   | 1 Stockpile S                   | TML - Total    |                 |               | \$2,184.96               |   |
|         | 1540 -         | Total  | Construction   |                                 |                |                 |               | \$2,184.96               |   |
|         | 1550           | DRIVEN POST<br>ANCHOR FOR 2.5                    | Construction<br>Stockpile                                  |                                 | 9              | Nov 16,<br>2023 | SYSTEM        | \$1,022.40               | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|         |                | IN. PSST - 7 GA.                                 | STMI   | - Total                         |                |                 |               | \$1,022.40               |   |
|         |                |  | Construction   | I<br>1 Stockpile S <sup>*</sup> | TMI - Tota     |                 |               | \$1,022.40               |   |
|         | 1 <u>550</u> - | Total  |  |                                 |                |                 |               | \$1,022.40               |   |
|         | 1640           | CONDUIT, 2 IN.,<br>RIGID, IN TRENCH              | Material   |                                 | 8              | Nov 2,<br>2023  | SYSTEM        | \$21,080.00              | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0016) due to user raybol1 overridding Payment<br>Estimate Exception 45 on the current Payment Estimate. |
|         |                |  |  |                                 | 8              | Nov 2,<br>2023  | SYSTEM        | (\$21,080.00)            |   |
|         |                |  |  | - Total                         |                |                 |               | \$0.00                   |   |
|         |                |  | Material - To  |                                 |                |                 |               | \$0.00                   |   |
|         | 16 <u>40 -</u> | Total  |  |                                 |                |                 |               | \$0.00                   |   |
|         | 1680           | PULL BOX,<br>PREFORMED<br>CLASS 2                | Material   |                                 | 8              | Nov 2,<br>2023  | SYSTEM        | \$3,500.00               | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0017) due to user raybol1 overridding Payment<br>Estimate Exception 46 on the current Payment Estimate. |
|         |                | 02400 2  |  |                                 | 8              | Nov 2,<br>2023  | SYSTEM        | (\$3,500.00)             |   |
|         |                |  |  | - Total                         |                |                 |               | \$0.00                   |   |
|         |                |  | Material - To  |                                 |                |                 |               | \$0.00                   |   |
|         | 16 <u>80</u> - | Total  |  |                                 |                |                 |               | \$0.00                   |   |
|         | 1710           | MISC. ITS  | Material   |                                 | 8              | Nov 2,<br>2023  | SYSTEM        | \$27,900.00              | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0018) due to user raybol1 overridding Payment<br>Estimate Evenation 4.7 as the overant Bayment Estimate |
|         |                |  |  |                                 | 8              | Nov 2,<br>2023  | SYSTEM        | (\$27,900.00)            | Estimate Exception 47 on the current Payment Estimate.  |
|         |                |  |  |                                 |                | 2020            |               |                          |   |



Nov 18, 2023

| Project | Line   | Description                                       | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks   |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| J4P3443 | 1710   | MISC. ITS   | Material           |                             | 9              | Nov 16,<br>2023 | SYSTEM        | \$27,900.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0019) due to user raybol1 overridding Payment<br>Estimate Exception 22 on the current Payment Estimate. |
|         |        |   |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | (\$27,900.00) |   |
|         |        |   |                    | - Total                     |                |                 |               | \$0.00        |   |
|         |        |   | Material - Tot     | al                          |                |                 |               | \$0.00        |   |
|         | 1710 - | Total   |                    |                             |                |                 |               | \$0.00        |   |
|         | 1740   | MISC. ITS   | Material           |                             | 8              | Nov 2,<br>2023  | SYSTEM        | \$7,200.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0019) due to user raybol1 overridding Payment<br>Estimate Exception 48 on the current Payment Estimate. |
|         |        |   |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | (\$7,200.00)  |   |
|         |        |   |                    | - Total                     |                |                 |               | \$0.00        |   |
|         |        |   | Material - Tot     | al                          |                |                 |               | \$0.00        |   |
|         | 1740 - | Total   |                    |                             |                |                 |               | \$0.00        |   |
|         | 1750   | CLASS 1<br>EXCAVATION                             | Overrun            | Overrun                     | 6              | Oct 2,<br>2023  | SYSTEM        | (\$1,936.00)  |   |
|         |        |   |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | \$1,936.00    | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',88.00000 - 88.00000, 'is applied (if non-zero).                           |
|         |        |   |                    | Overrun - Total             |                |                 | \$0.00        |               |   |
|         |        |   | Overrun - Total    |                             |                |                 |               | \$0.00        |   |
|         | 1750 - | Total   |                    |                             |                |                 |               | \$0.00        |   |
|         | 1790   | GALVANIZED<br>STRUCTURAL<br>STEEL PILES (12<br>IN | Material           |                             | 5              | Sep 18,<br>2023 | SYSTEM        | \$42,000.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0007) due to user raybol1 overridding Payment<br>Estimate Exception 14 on the current Payment Estimate. |
|         |        |   |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | (\$42,000.00) |   |
|         |        |   |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$42,000.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0016) due to user raybol1 overridding Payment<br>Estimate Exception 14 on the current Payment Estimate. |
|         |        |   |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$42,000.00) |   |
|         |        |   |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM        | \$42,000.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0013) due to user raybol1 overridding Payment<br>Estimate Exception 15 on the current Payment Estimate. |
|         |        |   |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM        | (\$42,000.00) |   |
|         |        |   |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | \$42,000.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0020) due to user raybol1 overridding Payment<br>Estimate Exception 20 on the current Payment Estimate. |
|         |        |   |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | (\$42,000.00) |   |
|         |        |   |                    | - Total                     |                |                 |               | \$0.00        |   |
|         |        |   | Material - Tot     | al                          |                |                 |               | \$0.00        |   |
|         |        |   | Overrun            | Overrun                     | 5              | Sep 18,<br>2023 | SYSTEM        | (\$3,000.00)  |   |
|         |        |   |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | \$3,000.00    | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',120.00000 - 120.00000, 'is applied (if non-zero).                         |
|         |        |   |                    | Overrun - T                 | otal           |                 |               | \$0.00        |   |
|         |        |   | Overrun - Total    |                             |                |                 |               | \$0.00        |   |
|         | 1790 - | Total   |                    |                             |                |                 |               | \$0.00        |   |
|         | 1810   | PILE POINT<br>REINFORCEMENT                       | Material           |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$1,350.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0017) due to user raybol1 overridding Payment<br>Estimate Exception 16 on the current Payment Estimate. |
|         |        |   |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$1,350.00)  |   |
|         |        |   |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM        | \$1,350.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0014) due to user raybol1 overridding Payment<br>Estimate Exception 17 on the current Payment Estimate. |
|         |        |   |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM        | (\$1,350.00)  |   |



| ect | Line           | Description                             | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date         | Created<br>By | Amount                       | Remarks   |
|-----|----------------|---|--------------------|-----------------------------|----------------|-------------------------|---------------|------------------------------|---|
| 443 | 1810           | PILE POINT<br>REINFORCEMENT             | Material           |                             | 8              | Nov 2,<br>2023          | SYSTEM        | \$1,350.00                   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0021) due to user raybol1 overridding Payment<br>Estimate Exception 22 on the current Payment Estimate. |
|     |                |   |                    |                             | 8              | Nov 2,<br>2023          | SYSTEM        | (\$1,350.00)                 |   |
|     |                |   |                    | - Total                     |                |                         |               | \$0.00                       |   |
|     |                |   | Material - Tot     | al                          |                |                         |               | \$0.00                       |   |
|     | 1810 -         | Total                                   |                    |                             |                |                         |               | \$0.00                       |   |
|     | 1820           | CLASS B<br>CONCRETE<br>(SUBSTRUCTURE)   | Material           |                             | 3              | Aug 16,<br>2023         | SYSTEM        | \$39,000.00                  | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0005) due to user raybol1 overridding Payment<br>Estimate Exception 2 on the current Payment Estimate.  |
|     |                |   |                    |                             | 3              | Aug 16,<br>2023         | SYSTEM        | (\$39,000.00)                |   |
|     |                |   |                    |                             | 4              | Sep 5,<br>2023          | SYSTEM        | \$105,950.00                 | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0005) due to user raybol1 overridding Payment<br>Estimate Exception 9 on the current Payment Estimate.  |
|     |                |   |                    |                             | 4              | Sep 5,<br>2023          | SYSTEM        | (\$105,950.00)               |   |
|     |                |   |                    |                             | 5              | Sep 18,<br>2023         | SYSTEM        | \$105,950.00                 | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0018) due to user raybol1 overridding Payment<br>Estimate Exception 17 on the current Payment Estimate. |
|     |                |   |                    |                             | 5              | Sep 18,<br>2023         | SYSTEM        | (\$105,950.00)               |   |
|     |                |   |                    |                             | 6              | Oct 2,<br>2023          | SYSTEM        | \$116,740.00                 | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0018) due to user raybol1 overridding Payment<br>Estimate Exception 18 on the current Payment Estimate. |
|     |                |   |                    | 6                           | 6              | Oct 2,<br>2023          | SYSTEM        | (\$116,740.00)               |   |
|     |                |   |                    |                             | 7              | Oct 16,<br>2023         | SYSTEM        | \$116,740.00                 | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0015) due to user raybol1 overridding Payment<br>Estimate Exception 19 on the current Payment Estimate. |
|     |                |   |                    |                             | 7              | Oct 16,<br>2023         | SYSTEM        | (\$116,740.00)               |   |
|     |                |   |                    |                             | 8              | Nov 2,<br>2023          | SYSTEM        | \$116,740.00                 | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0022) due to user raybol1 overridding Payment<br>Estimate Exception 24 on the current Payment Estimate. |
|     |                |   |                    |                             | 8              | Nov 2,<br>2023          | SYSTEM        | (\$116,740.00)               |   |
|     |                |   |                    | - Total                     |                |                         |               | \$0.00                       |   |
|     |                |   | Material - Tot     | tal                         |                |                         |               | \$0.00                       |   |
|     | 1820 -         | Total                                   |                    |                             |                |                         |               | \$0.00                       |   |
|     | 1870           | NU 43,<br>PRESTRESSED<br>CONC NU-GIRDER | Material           |                             | 9              | Nov 16,<br>2023         | SYSTEM        | \$316,710.00                 | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0022) due to user raybol1 overridding Payment<br>Estimate Exception 15 on the current Payment Estimate. |
|     |                |   |                    |                             | 9              | Nov 16,<br>2023         | SYSTEM        | (\$316,710.00)               |   |
|     |                |   |                    | - Total                     |                |                         |               | \$0.00                       |   |
|     |                |   | Material - Tot     | al                          |                |                         |               | \$0.00                       |   |
|     | 1870 -<br>1880 | Total<br>REINFORCING<br>STEEL (EPOXY    | Material           |                             | 4              | Sep 5,<br>2023          | SYSTEM        | <b>\$0.00</b><br>\$23,037.00 | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0013) due to user raybol1 overridding Payment<br>Estimate Evenation 20 on the current Payment Estimate  |
|     |                | COATED)                                 |                    |                             | 4              | Sep 5,                  | SYSTEM        | (\$23,037.00)                | Estimate Exception 20 on the current Payment Estimate.  |
|     |                |   |                    |                             | 5              | 2023<br>Sep 18,<br>2023 | SYSTEM        | \$23,037.00                  | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0028) due to user raybol1 overridding Payment<br>Estimate Exception 32 on the current Payment Estimate. |
|     |                |   |                    |                             | 5              | Sep 18,<br>2023         | SYSTEM        | (\$23,037.00)                |   |
|     |                |   |                    |                             | 6              | Oct 2,<br>2023          | SYSTEM        | \$23,037.00                  | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0031) due to user raybol1 overridding Payment<br>Estimate Exception 35 on the current Payment Estimate. |
|     |                |   |                    |                             | 6              | Oct 2,                  | SYSTEM        | (\$23,037.00)                |   |
|     |                |   |                    |                             |                | 2023                    |               |                              |   |



| Project | Line   | Description                                       | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks   |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| J4P3443 | 1880   |   | Material           |                             |                |                 |               |               | Estimate Exception 34 on the current Payment Estimate.  |
|         |        | STEEL (EPOXY<br>COATED)                           |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM        | (\$23,037.00) |   |
|         |        |   |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | \$23,037.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0023) due to user raybol1 overridding Payment<br>Estimate Exception 36 on the current Payment Estimate. |
|         |        |   |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | (\$23,037.00) |   |
|         |        |   |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | \$23,037.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0023) due to user raybol1 overridding Payment<br>Estimate Exception 19 on the current Payment Estimate. |
|         |        |   |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | (\$23,037.00) |   |
|         |        |   |                    | - Total                     |                |                 |               | \$0.00        |   |
|         |        |   | Material - To      | tal                         |                |                 |               | \$0.00        |   |
|         | 1880 - | Total   |                    |                             |                |                 |               | \$0.00        |   |
|         | 1910   | PLAIN NEOPRENE<br>BEARING PAD                     | Material           |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$1,110.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0030) due to user raybol1 overridding Payment<br>Estimate Exception 38 on the current Payment Estimate. |
|         |        |   |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$1,110.00)  |   |
|         |        |   |                    | - Total                     |                |                 |               | \$0.00        |   |
|         |        |   | Material - To      | tal                         |                |                 |               | \$0.00        |   |
|         | 1910 - | Total   |                    |                             |                |                 |               | \$0.00        |   |
|         | 1920   | LAMINATED<br>NEOPRENE<br>BEARING PAD              |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$2,520.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0032) due to user raybol1 overridding Payment<br>Estimate Exception 40 on the current Payment Estimate. |
|         |        |   |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$2,520.00)  |   |
|         |        |   |                    | - Total                     |                |                 |               | \$0.00        |   |
|         |        |   | Material - To      | tal                         |                |                 |               | \$0.00        |   |
|         | 1920 - | Total   |                    |                             |                |                 |               | \$0.00        |   |
|         | 1930   | LAMINATED<br>NEOPRENE<br>BEARING PAD<br>(TAPERED) | Material           |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$1,890.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0033) due to user raybol1 overridding Payment<br>Estimate Exception 42 on the current Payment Estimate. |
|         |        |   |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$1,890.00)  |   |
|         |        |   |                    | - Total                     |                |                 |               | \$0.00        |   |
|         |        |   | Material - To      | tal                         |                |                 |               | \$0.00        |   |
|         | 1930 - | Total   |                    |                             |                |                 |               | \$0.00        |   |
|         | 1940   | CLASS 1<br>EXCAVATION                             | Overrun            | Overrun                     |                | Oct 2,<br>2023  | SYSTEM        | (\$2,904.00)  |   |
|         |        |   |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | \$2,904.00    | Unit price based on averaged overrun adjustments for installed quantity on all<br>previous payment estimates. Price Adjustments of ',88.00000 - 88.00000, 'is<br>applied (if non-zero).                     |
|         |        |   |                    | Overrun - T                 | otal           |                 |               | \$0.00        |   |
|         |        |   | Overrun - To       | tal                         |                |                 |               | \$0.00        |   |
|         | 1940 - | Total   |                    |                             |                |                 |               | \$0.00        |   |
|         | 1960   | BRIDGE<br>APPROACH SLAB<br>(MAJOR ROAD)           | Material           |                             | 7              | Oct 16,<br>2023 | SYSTEM        | \$53,760.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0016) due to user raybol1 overridding Payment<br>Estimate Exception 9 on the current Payment Estimate.  |
|         |        |   |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM        | (\$53,760.00) |   |
|         |        |   |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | \$53,760.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0024) due to user raybol1 overridding Payment<br>Estimate Exception 12 on the current Payment Estimate. |
|         |        |   |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | (\$53,760.00) |   |
|         |        |   |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | \$53,760.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0025) due to user raybol1 overridding Payment<br>Estimate Exception 9 on the current Payment Estimate.  |
|         |        |   |                    |                             |                |                 |               |               |   |



Nov 18, 2023

| Project | Line                  | Description                                 | Adjustment<br>Type       | Other<br>Adjustment<br>Type | Est.<br>Number                  | Created<br>Date  | Created<br>By  | Amount   | Remarks   |
|---------|-----------------------|---|--------------------------|-----------------------------|---------------------------------|--|--|--|---|
| J4P3443 | 1960                  | BRIDGE<br>APPROACH SLAB                     | Material                 | - Total                     |                                 |  |  | \$0.00   |   |
|         |                       | (MAJOR ROAD)                                | Material - To            | tal                         |                                 |  |  | \$0.00   |   |
|         | 1960 -                | - Total                                     |                          |                             |                                 |  |  | \$0.00   |   |
|         | 1970                  | GALVANIZED<br>STRUCTURAL<br>STEEL PILES (12 | Material                 |                             | 5                               | Sep 18,<br>2023  | SYSTEM   | \$57,060.00  | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0009) due to user raybol1 overridding Payment<br>Estimate Exception 15 on the current Payment Estimate.   |
|         |                       | IN  |                          |                             | 5                               | Sep 18,<br>2023  | SYSTEM   | (\$57,060.00)  |   |
|         |                       |   |                          |                             | 6                               | Oct 2,<br>2023   | SYSTEM   | \$57,060.00  | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0019) due to user raybol1 overridding Payment<br>Estimate Exception 15 on the current Payment Estimate.   |
|         |                       |   |                          |                             | 6                               | Oct 2,<br>2023   | SYSTEM   | (\$57,060.00)  |   |
|         |                       |   |                          |                             | 7                               | Oct 16,<br>2023  | SYSTEM   | \$57,060.00  | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0017) due to user raybol1 overridding Payment<br>Estimate Exception 16 on the current Payment Estimate.   |
|         |                       |   |                          |                             | 7                               | Oct 16, 2023   | SYSTEM   | (\$57,060.00)  |   |
|         |                       |   |                          |                             | 8                               | Nov 2,<br>2023   | SYSTEM   | \$57,060.00  | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0025) due to user raybol1 overridding Payment<br>Estimate Exception 21 on the current Payment Estimate.   |
|         |                       |   |                          |                             | 8                               | Nov 2,<br>2023   | SYSTEM   | (\$57,060.00)  |   |
|         |                       |   |                          | - Total                     |                                 |  |  | \$0.00   |   |
|         |                       |   | Material - To            |                             |                                 |  |  | \$0.00   |   |
|         |                       |   | Overrun                  | Overrun                     | 5                               | Sep 18,<br>2023  | SYSTEM   | (\$8,820.00)   |   |
|         |                       |   |                          |                             | 9                               | Nov 16,<br>2023  | SYSTEM   | \$8,820.00   | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',120.00000 - 120.00000, 'is applied (if non-zero).   |
|         |                       |   |                          | Overrun - T                 | otal                            |  |  | \$0.00   |   |
|         |                       |   |                          |                             |                                 |  |  |  |   |
|         |                       |   | Overrun - To             | tal                         |                                 |  |  | \$0.00   |   |
|         | 1970 -                | - Total                                     | Overrun - To             | otal                        |                                 |  |  | \$0.00<br>\$0.00   |   |
|         | <b>1970</b> -<br>1990 | Total<br>PILE POINT<br>REINFORCEMENT        | Overrun - To<br>Material | otal                        | 4                               | Sep 5,<br>2023   | SYSTEM   |  | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0006) due to user raybol1 overridding Payment<br>Estimate Exception 8 on the current Payment Estimate.  |
|         |                       | PILE POINT                                  |                          | otal                        | 4                               |  | SYSTEM   | \$0.00   | Estimate Item Adjustment (0006) due to user raybol1 overridding Payment   |
|         |                       | PILE POINT                                  |                          | tal                         |                                 | 2023<br>Sep 5,   |  | <b>\$0.00</b><br>\$810.00  | Estimate Item Adjustment (0006) due to user raybol1 overridding Payment   |
|         |                       | PILE POINT                                  |                          | tal                         | 4                               | 2023<br>Sep 5,<br>2023<br>Sep 18,  | SYSTEM   | <b>\$0.00</b><br>\$810.00<br>(\$810.00)  | Estimate Item Adjustment (0006) due to user raybol1 overridding Payment<br>Estimate Exception 8 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0019) due to user raybol1 overridding Payment   |
|         |                       | PILE POINT                                  |                          | tal                         | 4                               | 2023<br>Sep 5,<br>2023<br>Sep 18,<br>2023<br>Sep 18,   | SYSTEM<br>SYSTEM   | \$0.00<br>\$810.00<br>(\$810.00)<br>\$810.00<br>(\$810.00)   | Estimate Item Adjustment (0006) due to user raybol1 overridding Payment<br>Estimate Exception 8 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0019) due to user raybol1 overridding Payment   |
|         |                       | PILE POINT                                  |                          | tal                         | 4<br>5<br>5                     | 2023<br>Sep 5,<br>2023<br>Sep 18,<br>2023<br>Sep 18,<br>2023<br>Oct 2,   | SYSTEM<br>SYSTEM<br>SYSTEM   | \$0.00<br>\$810.00<br>(\$810.00)<br>\$810.00<br>(\$810.00)   | Estimate Item Adjustment (0006) due to user raybol1 overridding Payment<br>Estimate Exception 8 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0019) due to user raybol1 overridding Payment<br>Estimate Exception 16 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0020) due to user raybol1 overridding Payment  |
|         |                       | PILE POINT                                  |                          | tal                         | 4<br>5<br>5<br>6                | 2023<br>Sep 5,<br>2023<br>Sep 18,<br>2023<br>Sep 18,<br>2023<br>Oct 2,<br>2023<br>Oct 2,   | SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM                               | \$0.00<br>\$810.00<br>(\$810.00)<br>\$810.00<br>(\$810.00)<br>\$810.00   | Estimate Item Adjustment (0006) due to user raybol1 overridding Payment<br>Estimate Exception 8 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0019) due to user raybol1 overridding Payment<br>Estimate Exception 16 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0020) due to user raybol1 overridding Payment  |
|         |                       | PILE POINT                                  |                          | tal                         | 4<br>5<br>5<br>6<br>6           | 2023<br>Sep 5,<br>2023<br>Sep 18,<br>2023<br>Oct 2,<br>2023<br>Oct 2,<br>2023<br>Oct 2,<br>2023<br>Oct 16,                                       | SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM                     | \$0.00<br>\$810.00<br>(\$810.00)<br>\$810.00<br>(\$810.00)<br>\$810.00<br>(\$810.00)   | Estimate Item Adjustment (0006) due to user raybol1 overridding Payment<br>Estimate Exception 8 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0019) due to user raybol1 overridding Payment<br>Estimate Exception 16 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0020) due to user raybol1 overridding Payment<br>Estimate Exception 17 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Exception 17 on the current Payment Estimate.  |
|         |                       | PILE POINT                                  |                          | tal                         | 4<br>5<br>5<br>6<br>7           | 2023<br>Sep 5,<br>2023<br>Sep 18,<br>2023<br>Sep 18,<br>2023<br>Oct 2,<br>2023<br>Oct 2,<br>2023<br>Oct 16,<br>2023                              | SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM                     | \$0.00<br>\$810.00<br>(\$810.00)<br>\$810.00<br>(\$810.00)<br>\$810.00<br>(\$810.00)<br>\$810.00   | Estimate Item Adjustment (0006) due to user raybol1 overridding Payment<br>Estimate Exception 8 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0019) due to user raybol1 overridding Payment<br>Estimate Exception 16 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0020) due to user raybol1 overridding Payment<br>Estimate Exception 17 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Exception 17 on the current Payment Estimate.  |
|         |                       | PILE POINT                                  |                          | tal                         | 4<br>5<br>5<br>6<br>7<br>7      | 2023<br>Sep 5,<br>2023<br>Sep 18,<br>2023<br>Sep 18,<br>2023<br>Oct 2,<br>2023<br>Oct 2,<br>2023<br>Oct 16,<br>2023<br>Oct 16,<br>2023<br>Nov 2, | SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM           | \$0.00<br>\$810.00<br>(\$810.00)<br>\$810.00<br>(\$810.00)<br>(\$810.00)<br>\$810.00<br>(\$810.00)   | Estimate Item Adjustment (0006) due to user raybol1 overridding Payment<br>Estimate Exception 8 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0019) due to user raybol1 overridding Payment<br>Estimate Exception 16 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0020) due to user raybol1 overridding Payment<br>Estimate Exception 17 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Exception 17 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0018) due to user raybol1 overridding Payment<br>Estimate Exception 18 on the current Payment Estimate. |
|         |                       | PILE POINT                                  |                          | - Total                     | 4<br>5<br>5<br>6<br>7<br>7<br>8 | 2023<br>Sep 5,<br>2023<br>Sep 18,<br>2023<br>Oct 2,<br>2023<br>Oct 2,<br>2023<br>Oct 16,<br>2023<br>Oct 16,<br>2023<br>Nov 2,<br>Nov 2,          | SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM | \$0.00<br>\$810.00<br>(\$810.00)<br>\$810.00<br>(\$810.00)<br>\$810.00<br>(\$810.00)<br>\$810.00<br>(\$810.00)<br>\$810.00                                   | Estimate Item Adjustment (0006) due to user raybol1 overridding Payment<br>Estimate Exception 8 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0019) due to user raybol1 overridding Payment<br>Estimate Exception 16 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0020) due to user raybol1 overridding Payment<br>Estimate Exception 17 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Exception 17 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0018) due to user raybol1 overridding Payment<br>Estimate Exception 18 on the current Payment Estimate. |
|         |                       | PILE POINT                                  |                          | - Total                     | 4<br>5<br>5<br>6<br>7<br>7<br>8 | 2023<br>Sep 5,<br>2023<br>Sep 18,<br>2023<br>Oct 2,<br>2023<br>Oct 2,<br>2023<br>Oct 16,<br>2023<br>Oct 16,<br>2023<br>Nov 2,<br>Nov 2,          | SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM | \$0.00<br>\$810.00<br>(\$810.00)<br>\$810.00<br>(\$810.00)<br>\$810.00<br>(\$810.00)<br>\$810.00<br>(\$810.00)<br>\$1,620.00                                 | Estimate Item Adjustment (0006) due to user raybol1 overridding Payment<br>Estimate Exception 8 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0019) due to user raybol1 overridding Payment<br>Estimate Exception 16 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0020) due to user raybol1 overridding Payment<br>Estimate Exception 17 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Exception 17 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0018) due to user raybol1 overridding Payment<br>Estimate Exception 18 on the current Payment Estimate. |
|         | 1990                  | PILE POINT                                  | Material                 | - Total                     | 4<br>5<br>5<br>6<br>7<br>7<br>8 | 2023<br>Sep 5,<br>2023<br>Sep 18,<br>2023<br>Oct 2,<br>2023<br>Oct 2,<br>2023<br>Oct 16,<br>2023<br>Oct 16,<br>2023<br>Nov 2,<br>Nov 2,          | SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM | \$0.00<br>\$810.00<br>(\$810.00)<br>\$810.00<br>(\$810.00)<br>(\$810.00)<br>(\$810.00)<br>(\$810.00)<br>(\$810.00)<br>(\$1,620.00)<br>(\$1,620.00)           | Estimate Item Adjustment (0006) due to user raybol1 overridding Payment<br>Estimate Exception 8 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0019) due to user raybol1 overridding Payment<br>Estimate Exception 16 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0020) due to user raybol1 overridding Payment<br>Estimate Exception 17 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Exception 17 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0018) due to user raybol1 overridding Payment<br>Estimate Exception 18 on the current Payment Estimate. |
|         | 1990                  | PILE POINT<br>REINFORCEMENT                 | Material                 | - Total                     | 4<br>5<br>5<br>6<br>7<br>7<br>8 | 2023<br>Sep 5,<br>2023<br>Sep 18,<br>2023<br>Oct 2,<br>2023<br>Oct 2,<br>2023<br>Oct 16,<br>2023<br>Oct 16,<br>2023<br>Nov 2,<br>Nov 2,          | SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM<br>SYSTEM | \$0.00<br>\$810.00<br>(\$810.00)<br>\$810.00<br>(\$810.00)<br>(\$810.00)<br>(\$810.00)<br>(\$810.00)<br>(\$810.00)<br>(\$1,620.00)<br>(\$1,620.00)<br>\$0.00 | Estimate Item Adjustment (0006) due to user raybol1 overridding Payment<br>Estimate Exception 8 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0019) due to user raybol1 overridding Payment<br>Estimate Exception 16 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0020) due to user raybol1 overridding Payment<br>Estimate Exception 17 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Exception 17 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0018) due to user raybol1 overridding Payment<br>Estimate Exception 18 on the current Payment Estimate. |



| Project | Line                  | Description                | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date  | Created<br>By              | Amount   | Remarks   |
|---------|-----------------------|----------------------------|--------------------|-----------------------------|----------------|--|----------------------------|--|---|
| J4P3443 | 2000                  | CLASS B                    | Material           | 1360                        |                | 2023   |                            |  |   |
|         |                       | CONCRETE<br>(SUBSTRUCTURE) |                    |                             | 4              | Sep 5,<br>2023   | SYSTEM                     | \$123,600.00                                   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0007) due to user raybol1 overridding Payment<br>Estimate Exception 15 on the current Payment Estimate.   |
|         |                       |                            |                    |                             | 4              | Sep 5,<br>2023   | SYSTEM                     | (\$123,600.00)                                 |   |
|         |                       |                            |                    |                             | 5              | Sep 18,<br>2023  | SYSTEM                     | \$123,600.00                                   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0020) due to user raybol1 overridding Payment<br>Estimate Exception 21 on the current Payment Estimate.   |
|         |                       |                            |                    |                             | 5              | Sep 18,<br>2023  | SYSTEM                     | (\$123,600.00)                                 |   |
|         |                       |                            |                    |                             | 6              | Oct 2,<br>2023   | SYSTEM                     | \$123,600.00                                   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0021) due to user raybol1 overridding Payment<br>Estimate Exception 21 on the current Payment Estimate.   |
|         |                       |                            |                    |                             | 6              | Oct 2,<br>2023   | SYSTEM                     | (\$123,600.00)                                 |   |
|         |                       |                            |                    |                             | 7              | Oct 16,<br>2023  | SYSTEM                     | \$123,600.00                                   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0019) due to user raybol1 overridding Payment<br>Estimate Exception 21 on the current Payment Estimate.   |
|         |                       |                            |                    |                             | 7              | Oct 16,<br>2023  | SYSTEM                     | (\$123,600.00)                                 |   |
|         |                       |                            |                    |                             | 8              | Nov 2,<br>2023   | SYSTEM                     | \$123,600.00                                   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0027) due to user raybol1 overridding Payment<br>Estimate Exception 26 on the current Payment Estimate.   |
|         |                       |                            |                    |                             | 8              | Nov 2,<br>2023   | SYSTEM                     | (\$123,600.00)                                 |   |
|         |                       |                            |                    | - Total                     |                |  |                            | \$0.00   |   |
|         |                       |                            | Material - Tot     | tal                         |                |  |                            | \$0.00   |   |
|         | 2000 -                | Total                      |                    |                             |                |  |                            | \$0.00   |   |
|         | 2010                  | TYPE D BARRIER             | Material           |                             | 7              | Oct 16,<br>2023  | SYSTEM                     | \$119,750.00                                   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0020) due to user raybol1 overridding Payment<br>Estimate Exception 25 on the current Payment Estimate.   |
|         |                       |                            |                    |                             | 7              | Oct 16,<br>2023  | SYSTEM                     | (\$119,750.00)                                 |   |
|         |                       |                            |                    |                             | 8              | Nov 2,<br>2023   | SYSTEM                     | \$119,750.00                                   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0028) due to user raybol1 overridding Payment<br>Estimate Exception 28 on the current Payment Estimate.   |
|         |                       |                            |                    | - Total                     | 8              | Nov 2,<br>2023   | SYSTEM                     | (\$119,750.00)                                 |   |
|         |                       |                            |                    |                             | 9              | Nov 16,<br>2023  | SYSTEM                     | \$119,750.00                                   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0027) due to user raybol1 overridding Payment<br>Estimate Exception 13 on the current Payment Estimate.   |
|         |                       |                            |                    |                             | 9              | Nov 16,<br>2023  | SYSTEM                     | (\$119,750.00)                                 |   |
|         |                       |                            |                    |                             |                |  |                            | \$0.00   |   |
|         |                       |                            | Material - Tot     | tal                         |                |  | \$0.00                     |  |   |
|         | <b>2010</b> -<br>2020 | SLAB ON<br>CONCRETE NU-    | Material           |                             | 5              | Sep 18,<br>2023  | SYSTEM                     | <b>\$0.00</b><br>\$226,260.00                  | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0021) due to user raybol1 overridding Payment   |
|         |                       | GIRDER                     |                    |                             | 5              | Sep 18,  | SYSTEM                     | (\$226,260.00)                                 | Estimate Exception 24 on the current Payment Estimate.  |
|         |                       |                            |                    |                             | 6              | 2023<br>Oct 2,<br>2023   | SYSTEM                     | \$377,100.00                                   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0022) due to user raybol1 overridding Payment<br>Estimate Exception 25 on the current Payment Estimate.   |
|         |                       |                            |                    |                             | 6              | Oct 2,   | SYSTEM                     | (\$377,100.00)                                 | Loundle Exception 20 on the current Payment Estimate.   |
|         |                       |                            |                    |                             | 7              | 2023<br>Oct 16,<br>2023  | SYSTEM                     | \$377,100.00                                   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0021) due to user raybol1 overridding Payment<br>Estimate Exception 26 on the current Payment Estimate.   |
|         |                       |                            |                    |                             | 7              | Oct 16, 2023   | SYSTEM                     | (\$377,100.00)                                 |   |
|         |                       |                            |                    |                             | 8              | Nov 2,<br>2023   | SYSTEM                     | \$377,100.00                                   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0029) due to user raybol1 overridding Payment<br>Estimate Exception 29 on the current Payment Estimate.   |
|         |                       |                            |                    |                             | 8              | Nov 2,<br>2023   | SYSTEM                     | (\$377,100.00)                                 |   |
|         |                       |                            |                    |                             | 7<br>7<br>8    | 2023<br>Oct 16,<br>2023<br>Oct 16,<br>2023<br>Nov 2,<br>2023<br>Nov 2, | SYSTEM<br>SYSTEM<br>SYSTEM | \$377,100.00<br>(\$377,100.00)<br>\$377,100.00 | Estimate Item Adjustment (0021) due to user raybol1 overridding Par<br>Estimate Exception 26 on the current Payment Estimate.<br>This adjustment offsets the original system-generated Material Paym<br>Estimate Item Adjustment (0029) due to user raybol1 overridding Par |



Nov 18, 2023

| Project | Line   | Description                             | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount             | Remarks   |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|--------------------|---|
| J4P3443 | 2020   | SLAB ON<br>CONCRETE NU-<br>GIRDER       | Material           |                             | 9              | Nov 16,<br>2023 | SYSTEM        | \$377,100.00       | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0028) due to user raybol1 overridding Payment<br>Estimate Exception 14 on the current Payment Estimate. |
|         |        |   |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | (\$377,100.00)     |   |
|         |        |   |                    | - Total                     |                |                 |               | \$0.00             |   |
|         |        |   | Material - To      | tal                         |                |                 |               | \$0.00             |   |
|         | 2020 - | Total                                   |                    |                             |                |                 |               | \$0.00             |   |
|         | 2030   | FORM LINERS                             | Material           |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$14,141.00        | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0023) due to user raybol1 overridding Payment<br>Estimate Exception 29 on the current Payment Estimate. |
|         |        |   |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$14,141.00)      |   |
|         |        |   |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM        | \$14,141.00        | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0022) due to user raybol1 overridding Payment<br>Estimate Exception 30 on the current Payment Estimate. |
|         |        |   |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM        | (\$14,141.00)      |   |
|         |        |   |                    | - Total                     |                |                 |               | \$0.00             |   |
|         |        |   | Material - To      |                             |                |                 |               | \$0.00             |   |
|         | 2030 - | Total                                   |                    |                             |                |                 |               | \$0.00             |   |
|         | 2030   | NU 43,<br>PRESTRESSED<br>CONC NU-GIRDER | Material           |                             | 4              | Sep 5,<br>2023  | SYSTEM        | \$211,140.00       | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0008) due to user raybol1 overridding Payment<br>Estimate Exception 16 on the current Payment Estimate. |
|         |        |   |                    |                             | 4              | Sep 5,<br>2023  | SYSTEM        | (\$211,140.00)     |   |
|         |        |   |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | \$422,280.00       | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0022) due to user raybol1 overridding Payment<br>Estimate Exception 28 on the current Payment Estimate. |
|         |        |   |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | (\$422,280.00)     |   |
|         |        |   |                    | - Total                     |                |                 |               | \$0.00             |   |
|         |        |   | Material - To      | tal                         |                |                 |               | \$0.00             |   |
|         | 2050 - | Total                                   |                    |                             |                |                 |               | \$0.00             |   |
|         | 2060   | CONDUIT<br>SYSTEM ON<br>STRUCTURE       | Material           |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$27,500.00        | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0024) due to user raybol1 overridding Payment<br>Estimate Exception 33 on the current Payment Estimate. |
|         |        |   |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$27,500.00)      |   |
|         |        |   |                    | - Total                     |                |                 |               | \$0.00             |   |
|         |        |   | Material - To      | tal                         |                |                 |               | \$0.00             |   |
|         | 2060 - | Total                                   |                    |                             |                |                 |               | \$0.00             |   |
|         | 2070   | REINFORCING<br>STEEL (EPOXY<br>COATED)  | Material           |                             | 3              | Aug 16,<br>2023 | SYSTEM        | \$32,592.00        | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0007) due to user raybol1 overridding Payment<br>Estimate Exception 6 on the current Payment Estimate.  |
|         |        |   |                    |                             | 3              | Aug 16,<br>2023 | SYSTEM        | (\$32,592.00)      |   |
|         |        |   |                    |                             | 4              | Sep 5,<br>2023  | SYSTEM        | \$32,592.00        | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0009) due to user raybol1 overridding Payment<br>Estimate Exception 21 on the current Payment Estimate. |
|         |        |   |                    |                             | 4              | Sep 5,<br>2023  | SYSTEM        | (\$32,592.00)      |   |
|         |        |   |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | \$32,592.00        | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0023) due to user raybol1 overridding Payment<br>Estimate Exception 33 on the current Payment Estimate. |
|         |        |   |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | STEM (\$32,592.00) |   |
|         |        |   |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$32,592.00        | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0025) due to user raybol1 overridding Payment<br>Estimate Exception 36 on the current Payment Estimate. |
|         |        |   |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$32,592.00)      |   |
|         |        |   |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM        | \$32,592.00        | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0023) due to user raybol1 overridding Payment<br>Estimate Exception 35 on the current Payment Estimate. |



| Project | Line   | Description                          | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks   |
|---------|--------|--------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| J4P3443 | 2070   | REINFORCING<br>STEEL (EPOXY          | Material           |                             | 7              | Oct 16,<br>2023 | SYSTEM        | (\$32,592.00) |   |
|         |        | COATED)                              |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | \$32,592.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0030) due to user raybol1 overridding Payment<br>Estimate Exception 37 on the current Payment Estimate. |
|         |        |                                      |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | (\$32,592.00) |   |
|         |        |                                      |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | \$32,592.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0029) due to user raybol1 overridding Payment<br>Estimate Exception 20 on the current Payment Estimate. |
|         |        |                                      |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | (\$32,592.00) |   |
|         |        |                                      |                    | - Total                     |                |                 |               | \$0.00        |   |
|         |        |                                      | Material - Tot     | tal                         |                |                 |               | \$0.00        |   |
|         | 2070 - | Total                                |                    |                             |                |                 |               | \$0.00        |   |
|         | 2090   | VERTICAL DRAIN<br>AT END BENTS       | Material           |                             | 5              | Sep 18,<br>2023 | SYSTEM        | \$3,800.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0024) due to user raybol1 overridding Payment<br>Estimate Exception 34 on the current Payment Estimate. |
|         |        |                                      |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | (\$3,800.00)  |   |
|         |        |                                      |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$3,800.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0026) due to user raybol1 overridding Payment<br>Estimate Exception 37 on the current Payment Estimate. |
|         |        |                                      |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$3,800.00)  |   |
|         |        |                                      |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM        | \$3,800.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0024) due to user raybol1 overridding Payment<br>Estimate Exception 36 on the current Payment Estimate. |
|         |        |                                      |                    |                             | 7              | Oct 16,<br>2023 | SYSTEM        | (\$3,800.00)  |   |
|         |        |                                      |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | \$3,800.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0031) due to user raybol1 overridding Payment<br>Estimate Exception 38 on the current Payment Estimate. |
|         |        |                                      |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | (\$3,800.00)  |   |
|         |        |                                      |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | \$3,800.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0030) due to user raybol1 overridding Payment<br>Estimate Exception 21 on the current Payment Estimate. |
|         |        |                                      |                    |                             | 9              | Nov 16,<br>2023 | SYSTEM        | (\$3,800.00)  |   |
|         |        |                                      |                    | - Total                     |                |                 |               | \$0.00        |   |
|         |        |                                      | Material - Tot     | tal                         |                |                 |               | \$0.00        |   |
|         | 2090 - | Total                                |                    |                             |                |                 |               | \$0.00        |   |
|         | 2100   | PLAIN NEOPRENE<br>BEARING PAD        | Material           |                             | 4              | Sep 5,<br>2023  | SYSTEM        | \$1,480.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0010) due to user raybol1 overridding Payment<br>Estimate Exception 22 on the current Payment Estimate. |
|         |        |                                      |                    |                             | 4              | Sep 5,<br>2023  | SYSTEM        | (\$1,480.00)  |   |
|         |        |                                      |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | \$1,480.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0025) due to user raybol1 overridding Payment<br>Estimate Exception 35 on the current Payment Estimate. |
|         |        |                                      |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | (\$1,480.00)  |   |
|         |        |                                      |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$1,480.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0027) due to user raybol1 overridding Payment<br>Estimate Exception 39 on the current Payment Estimate. |
|         |        |                                      |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$1,480.00)  |   |
|         |        |                                      |                    | - Total                     |                |                 |               | \$0.00        |   |
|         |        |                                      | Material - Tot     | tal                         |                |                 |               | \$0.00        |   |
|         | 2100 - | Total                                |                    |                             |                |                 |               | \$0.00        |   |
|         | 2110   | LAMINATED<br>NEOPRENE<br>BEARING PAD | Material           |                             | 4              | Sep 5,<br>2023  | SYSTEM        | \$3,360.00    | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0011) due to user raybol1 overridding Payment<br>Estimate Exception 23 on the current Payment Estimate. |
|         |        |                                      |                    |                             |                |                 |               |               |   |



| Project   | Line   | Description                          | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount       | Remarks   |
|-----------|--------|--------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| J4P3443   | 2110   | LAMINATED<br>NEOPRENE<br>BEARING PAD | Material           |                             | 5              | Sep 18,<br>2023 | SYSTEM        | \$3,360.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0026) due to user raybol1 overridding Payment<br>Estimate Exception 36 on the current Payment Estimate. |
|           |        |                                      |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | (\$3,360.00) |   |
|           |        |                                      |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$3,360.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0028) due to user raybol1 overridding Payment<br>Estimate Exception 41 on the current Payment Estimate. |
|           |        |                                      |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$3,360.00) |   |
|           |        |                                      |                    | - Total                     |                |                 |               | \$0.00       |   |
|           |        |                                      | Material - To      | tal                         |                |                 |               | \$0.00       |   |
|           | 2110 - | Total                                |                    |                             |                |                 |               | \$0.00       |   |
|           | 2120   | LAMINATED<br>NEOPRENE<br>BEARING PAD | Material           |                             | 4              | Sep 5,<br>2023  | SYSTEM        | \$2,520.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0012) due to user raybol1 overridding Payment<br>Estimate Exception 24 on the current Payment Estimate. |
|           |        | (TAPERED)                            |                    |                             | 4              | Sep 5,<br>2023  | SYSTEM        | (\$2,520.00) |   |
|           |        |                                      |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | \$2,520.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0027) due to user raybol1 overridding Payment<br>Estimate Exception 37 on the current Payment Estimate. |
|           |        |                                      |                    |                             | 5              | Sep 18,<br>2023 | SYSTEM        | (\$2,520.00) |   |
|           |        |                                      |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | \$2,520.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0029) due to user raybol1 overridding Payment<br>Estimate Exception 43 on the current Payment Estimate. |
|           |        |                                      |                    |                             | 6              | Oct 2,<br>2023  | SYSTEM        | (\$2,520.00) |   |
|           |        |                                      |                    | - Total                     |                |                 |               | \$0.00       |   |
|           |        |                                      | Material - To      | tal                         |                |                 |               | \$0.00       |   |
|           | 2120 - | Total                                |                    |                             |                |                 |               | \$0.00       |   |
|           | 5002   | TEMPORARY PIPE                       | Material           |                             | 4              | Sep 5,<br>2023  | SYSTEM        | \$7,200.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0014) due to user raybol1 overridding Payment<br>Estimate Exception 25 on the current Payment Estimate. |
|           |        |                                      |                    |                             | 4              | Sep 5,<br>2023  | SYSTEM        | (\$7,200.00) |   |
|           |        |                                      |                    | - Total                     |                |                 |               | \$0.00       |   |
|           |        |                                      | Material - To      | tal                         |                |                 |               | \$0.00       |   |
|           | 5002 - | Total                                |                    |                             |                |                 |               | \$0.00       |   |
|           | 5005   | REPLACEMENT<br>SAND BARREL           | Material           |                             | 8              | Nov 2,<br>2023  | SYSTEM        | \$4,725.00   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0032) due to user raybol1 overridding Payment<br>Estimate Exception 19 on the current Payment Estimate. |
|           |        |                                      |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | (\$4,725.00) |   |
|           |        |                                      |                    | - Total                     |                |                 |               | \$0.00       |   |
|           |        |                                      | Material - To      | tal                         |                |                 |               | \$0.00       |   |
|           | 5005 - | Total                                |                    |                             |                |                 |               | \$0.00       |   |
|           | 5006   | TEMPORARY PIPE                       | Material           |                             | 8              | Nov 2,<br>2023  | SYSTEM        | \$3,422.40   | This adjustment offsets the original system-generated Material Payment<br>Estimate Item Adjustment (0033) due to user raybol1 overridding Payment<br>Estimate Exception 40 on the current Payment Estimate. |
|           |        |                                      |                    |                             | 8              | Nov 2,<br>2023  | SYSTEM        | (\$3,422.40) |   |
|           |        |                                      |                    | - Total                     |                |                 |               | \$0.00       |   |
|           |        |                                      | Material - To      | tal                         |                |                 |               | \$0.00       |   |
|           | 5006 - | Total                                |                    |                             |                |                 |               | \$0.00       |   |
| J4P3443 - | Total  |                                      |                    |                             |                |                 |               | \$52,845.46  |   |
| Overall - | Total  |                                      |                    |                             |                |                 | \$52,845.46   |              |   |



# Contract Adjustments for Contract - 230519-C04

| Estimate<br>Number | Project | Adjustment Type              | Other Adjustment<br>Type | Adjustment<br>Amount | Adjustment Percentage by<br>Project | Created<br>Date | Created<br>By | Comments   |  |
|--------------------|---------|------------------------------|--------------------------|----------------------|-------------------------------------|-----------------|---------------|--|--|
| 7                  | J4P3443 | Other Contract<br>Adjustment | SIGN                     | (\$155.26)           | 100                                 | Oct 16,<br>2023 | raybol1       | 9/25/2023 to 9/26/2023 - Signing Materials Inspection by<br>Sam Marshall |  |
| 7 - Total          |         |                              |                          |                      | (\$155.26)                          |                 |               |  |  |
| Overall - Tota     | I       |                              |                          |                      | (\$155.26)                          |                 |               |  |  |