

Missouri Department of Transportation Contractor's Pay Estimate Summary

July 11, 2023

February 27, 2024

Pay Estimate Created Date: July 16, 2024

Notice to Proceed Date July 11, 2023

February 27, 2024

Open to Traffic Date
Work Began Date

Progress Estin		Contract ID Prime Contra	230519-D0 ctor Aplex, Inc.		Period Start Period End	July 1, 2024 July 15, 2024	4 Net 0	inal Contract Amount Change Order Amount ent Contract Amount	\$1,230,276.54 \$3,344.00 \$1,233,620.54		
Approval Date									By User		
July 22, 2024		Generated and Approved (and should be considered Draft) at the Project Office Lev									
July 22, 2024		R	eviewed and Appro	ved (and	should be co	nsidered Draft)	at the R	esident Engineer Level by	browns1		
July 22, 2024		Reviewed and Approved at the Central Office Controllers Office Lev									
Original Comp	letion Date	Current Con	pletion Date	Actu	ıal Completi	on Date	Date % of Current Contract Amount Complete				
December '	1, 2024	Decembe	er 1, 2024					49.82%			
	Contract	Informational Dat	es			Vilestones					
Date Description	Description Original Completion Date Current Completion Date No Milestones Exist for Contract										
Acceptance Date	е										
Awarded Date	June 7, 20	023	June 7, 2023								
Letting Date	Letting Date May 19, 2023 May 19, 2023										

Contract Total Pay For Estimate No. 10									
		This Estimate	Previous	To Date					
230519-D03									
	Total Posted Items Pay	\$74,594.05	\$539,941.79	\$614,535.84					
	Gross Item Adjustments	\$0.00	(\$1,500.00)	(\$1,500.00)					
	Incentive	\$0.00	\$0.00	\$0.00					
	Disincentive	\$0.00	\$0.00	\$0.00					
	Liquidated Damage	\$0.00	\$0.00	\$0.00					
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00					
	,		\$538,441.79	\$613,035.84					
Contract Total Pa	yable This Estimate:	\$74,594.05							

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount			
J5P3490	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$125,765.000	0.09	\$11,318.85			
	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$11.000	645.7	\$7,102.70			
	0140	6081010	CONCRETE CURB RAMP	SQYD	\$135.000	73.2	\$9,882.00			
	0150	6081012	TRUNCATED DOMES	SQFT	\$35.000	20	\$700.00			
	0180	6085007	PAVED APPROACH, 7 IN.	SQYD	\$87.000	199.1	\$17,321.70			
	0200	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$59.000	373.2	\$22,018.80			
	0270	6091052	CURB AND GUTTER TYPE B	LF	\$50.000	125	\$6,250.00			
Project J5P349	Project J5P3490 - Total									
Overall - Total							\$74,594.05			

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

140 Contia	VO CONTRACT Adjustments Exist on Contract											
Line Item .	<u>Adjust</u>	ments This Estimate										
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount				
J5P3490	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Overrun			-29.85	\$11.00	(\$328.35)				
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-3,582.85	\$11.00	(\$39,411.35)				
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item	29.85	\$11.00	\$328.35				

Revision 3/23/2023 Page 1 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 16, 2024

Progre	ess Estimate Number 10	Contract ID Prime Contractor	Pay Period Start Pay Period End	. , .	Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,230,276.54 \$3,344.00 \$1,233,620.54

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3490					Adjustment (0001) due to user ricksc3 overridding Payment Estimate Exception 10 on the current Payment Estimate.			
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user ricksc3 overridding Payment Estimate Exception 1 on the current Payment Estimate.	3,582.85	\$11.00	\$39,411.35
	0070	CONCRETE PAVEMENT (8 IN. NON-REINF)	Material			-101	\$115.00	(\$11,615.00
	0070	CONCRETE PAVEMENT (8 IN. NON-REINF)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user ricksc3 overridding Payment Estimate Exception 2 on the current Payment Estimate.	101	\$115.00	\$11,615.00
	0140	CONCRETE CURB RAMP	Material			-467.65	\$135.00	(\$63,132.75)
	0140	CONCRETE CURB RAMP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate.	467.65	\$135.00	\$63,132.75
	0180	PAVED APPROACH, 7 IN.	Material			-199.1	\$87.00	(\$17,321.70)
	0180	PAVED APPROACH, 7 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user ricksc3 overridding Payment Estimate Exception 4 on the current Payment Estimate.	199.1	\$87.00	\$17,321.70
	0190	PAVED APPROACH, 8 IN.	Material			-522	\$95.00	(\$49,590.00)
	0190	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user ricksc3 overridding Payment Estimate Exception 6 on the current Payment Estimate.	522	\$95.00	\$49,590.00
	0200	CONCRETE SIDEWALK, 4 IN.	Material			-2,318.98	\$59.00	(\$136,819.82)
	0200	CONCRETE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user ricksc3 overridding Payment Estimate Exception 8 on the current Payment Estimate.	2,318.98	\$59.00	\$136,819.82
	0260	CONCRETE GUTTER TYPE A	Material			-8	\$100.00	(\$800.00)
	0260	CONCRETE GUTTER TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user ricksc3 overridding Payment Estimate Exception 9 on the current Payment Estimate.	8	\$100.00	\$800.00
Total								\$0.00

Revision 3/23/2023 Page 2 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Informat	tion					
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work						
J5P3490	FAS S402(68)	ADA improvements	Various	COLE	at various locations in Central District							
Totals by J	Job Numbe	ers										
J5P3490		d Item Pay Item Adjustme	nts Gross It	em Pay	This Estimate \$74,594.05 \$0.00 \$74,594.05	Previous \$539,941.79 (\$1,500.00) \$538,441.79	To Date \$614,535.84 (\$1,500.00) \$613,035.84					
	Liquid	tive centive dated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					

Revision 3/23/2023 Page 3 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3490, Item 3040504, Project Item Line Number 0060, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	ricksc3: Contractor was not aware that more tests were necessary. We will now wait till we have another Paved Approach to complete this testing.	ricksc3	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3490, Item 5021108, Project Item Line Number 0070, Material Set 502110896, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	ricksc3: Inspector has received the testing data. Working with QCC to get tests entered in AWP with the proper items attached to them.	ricksc3	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3490, Item 6081010, Project Item Line Number 0140, Material Set 608101096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	ricksc3: Inspector has received the testing data. Working with QCC to get tests entered into AWP with the proper items attached to them.	ricksc3	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3490, Item 6085007, Project Item Line Number 0180, Material Set 608500796, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	ricksc3: Inspector has received the testing data. Working with QCC to get tests entered into AWP with the proper items attached to them.	ricksc3	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3490, Item 6085007, Project Item Line Number 0180, Material Set 608500796, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	ricksc3: Inspector has received the testing data. Working with QCC to get tests entered into AWP with the proper items attached to them.	ricksc3	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3490, Item 6085008, Project Item Line Number 0190, Material Set 608500896, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	ricksc3: Inspector has received the testing data. Working with QCC to get tests entered into AWP with the proper items attached to them.	ricksc3	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3490, Item 6085008, Project Item Line Number 0190, Material Set 608500896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	ricksc3: Inspector has received the testing data. Working with QCC to get tests entered into AWP with the proper items attached to them.	ricksc3	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3490, Item 6086004, Project Item Line Number 0200, Material Set 608600496, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	ricksc3: Inspector has received the testing data. Working with QCC to get tests entered into AWP with the proper items attached to them.	ricksc3	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3490, Item 6091041, Project Item Line Number 0260, Material Set 609104196, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	ricksc3: Inspector has received the testing data. Working with QCC to get tests entered into AWP with the proper items attached to them.	ricksc3	Overridden
Estimate Exception Type: Item Overrun: Contract 230519-D03, Contract Project J5P3490, Project Item Line Number 0060, Contract Line Item Number 0060, Item 3040504, Minor Item.	ricksc3: Inspector is aware of the issue and will be working on Change Order 0005 to adjust.	ricksc3	Overridden
Estimate Exception Type: Item Overrun: Contract 230519-D03, Contract Project J5P3490, Project Item Line Number 0120, Contract Line Item Number 0120, Item 6049902, Minor Item.	ricksc3: Inspector is aware of the issue and will be working on Change Order 0005 to adjust.	ricksc3	Overridden

Revision 3/23/2023 Page 4 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
0519-D03	J5P3490	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.72	\$125,765.00	\$90,550.8
		0001	0020	2063000	CLASS 3 EXCAVATION	13.00	0.00	13.00	CUYD	0.00	\$100.00	\$0.
		0001	0030	2063500	CULVERT CLEANOUT	3.00	0.00	3.00	EA	3.00	\$1,500.00	\$4,500.
		0001	0040	2071000	LINEAR GRADING CLASS 1	6.80	0.00	6.80	STA	5.60	\$1,500.00	\$8,400.
		0001	0050	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	1,230.00	0.00	1,230.00	SQYD	43.10	\$11.00	\$474.
		0001	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	3,309.00	244.00	3,553.00	SQYD	3,582.85	\$11.00	\$39,411.
		0001	0070	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)	329.90	0.00	329.90	SQYD	101.00	\$115.00	\$11,615.
		0001	0800	6039902	WATER	5.00	0.00	5.00	EA	3.00	\$750.00	\$2,250
		0001	0090	6039932	GAS	1.00	0.00	1.00	EA	1.00	\$752.00	\$752.
		0001	0100	6049902	MISC.ADJUSTING INLET GRATE	1.00	0.00	1.00	EA	0.00	\$2,000.00	\$0
		0001	0110	6049902	MISC.ADJUSTING INLET TOP	7.00	0.00	7.00	EA	0.00	\$2,000.00	\$0
		0001	0120	6049902	MISC.ADJUSTING MANHOLES	2.00	0.00	2.00	EA	3.00	\$1,500.00	\$4,500
		0001	0130	6049902	MISC.ADJUSTING PULL BOX	2.00	0.00	2.00	EA	2.00	\$1,300.00	\$2,600
		0001	0140	6081010	CONCRETE CURB RAMP	645.50	0.00	645.50	SQYD	467.65	\$135.00	\$63,132
		0001	0150	6081012	TRUNCATED DOMES	738.00	0.00	738.00	SQFT	380.40	\$35.00	\$13,314
		0001	0160	6083003	3 IN. CONCRETE MEDIAN STRIP	4.40	0.00	4.40	SQYD	4.40	\$200.00	\$880
		0001	0170	6084023	SIDEWALK HAND-RAILING WITHOUT BALUSTERS	130.00	0.00	130.00	LF	0.00	\$150.00	\$0
		0001	0180	6085007	PAVED APPROACH, 7 IN.	199.10	0.00	199.10	SQYD	199.10	\$87.00	\$17,321
		0001	0190	6085008	PAVED APPROACH, 8 IN.	701.10	0.00	701.10	SQYD	522.00	\$95.00	\$49,590
		0001	0200	6086004	CONCRETE SIDEWALK, 4 IN.	2,607.50	0.00	2,607.50	SQYD	2,318.98	\$59.00	\$136,819
		0001	0210	6089902	MISC.REMOVE AND RELOCATE BENCH	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0
		0001	0220	6089902	MISC.REPAIR HANDRAIL	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0
		0001	0230	6089905	MISC.7" CONCRETE CURB RAMP	22.40	0.00	22.40	SQYD	0.00	\$135.00	\$0
		0001	0240	6089905	MISC.PAVEMENT AND MEDIAN REPLACEMENT	54.50	0.00	54.50	SQYD	0.00	\$85.00	\$0
		0001	0250	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	195.00	0.00	195.00	LF	67.16	\$60.00	\$4,029
		0001	0260	6091041	CONCRETE GUTTER TYPE A	8.00	0.00	8.00	LF	8.00	\$100.00	\$800
		0001	0270	6091052	CURB AND GUTTER TYPE B	407.00	0.00	407.00	LF	321.00	\$50.00	\$16,050
		0001	0280	6099903	MISC.CONCRETE TROUGH WITH STEEL PLATE	54.00	0.00	54.00	LF	0.00	\$562.00	\$0
		0001	0290	6099903	MISC.MODIFIED CURB AND GUTTER TYPE B	392.00	0.00	392.00	LF	98.00	\$52.00	\$5,096
		0001	0300	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$10,000.00	\$0
		0001	0310	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	6.00	0.00	6.00	EA	6.00	\$8,700.00	\$52,200
		0001	0320	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.00	\$71,265.00	\$0
		0001	0330	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	400.00	0.00	400.00	LF	0.00	\$25.00	\$0
		0001	0340	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	800.00	0.00	800.00	LF	0.00	\$12.00	\$0
		0001	0350	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$70,165.00	\$52,623
		0001	0360	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	134.00	0.00	134.00	LF	0.00	\$17.50	\$0
		0001	0370	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	1.00	0.00	1.00	EA	0.00	\$325.00	\$0
		0001	0380	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	3.00	0.00	3.00	EA	0.00	\$325.00	\$(
			0390	6229903	STRAIGHT ARROW MISC.SIDEWALK JOINT GRINDING	30.00	0.00	30.00	LF	2.00	\$100.00	\$200
		0001	0400	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LF	0.00	\$55,000.00	\$200
		0001	0400	7250312A	12 IN. PIPE GROUP B	22.00	0.00	22.00	LS	0.00	\$100.00	\$(
		0001							LF			
		0001	0420	7250315A	15 IN. PIPE GROUP B	80.00	0.00	80.00	LF	9.00	\$100.00	\$900
		0001	0430	7259903	MISC.6" PVC PIPE	8.00	0.00	8.00		0.00	\$100.00	\$0
		0001	0440	8061003	SEDIMENT TRAP EXCAVATION	7.00	0.00	7.00	CUYD	0.00	\$300.00	\$

Revision 3/23/2023 Page 5 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See report generated date)
0519-D03	J5P3490	0001	0450	8061004	SEDIMENT TRAP ROCK	7.00	0.00	7.00	CUYD	0.00	\$300.00	\$0.0
		0001	0460	8061006	ALTERNATE DITCH CHECK	420.00	0.00	420.00	LF	270.00	\$29.50	\$7,965.0
		0001	0470	8061007A	CURB INLET CHECK	74.00	0.00	74.00	EA	29.00	\$190.00	\$5,510.0
		0001	0480	8061016	SEDIMENT REMOVAL	7.00	0.00	7.00	CUYD	0.00	\$100.00	\$0.
		0001	0490	8061019	SILT FENCE	1,191.00	0.00	1,191.00	LF	786.00	\$15.00	\$11,790.
		0001	0500	8064129	TYPE 2 TURF REINFORCEMENT MAT	412.00	0.00	412.00	SQYD	375.00	\$11.50	\$4,312.
		0030	0510	9020811	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	4.00	0.00	4.00	EA	0.00	\$831.00	\$0.
		0030	0520	9020833	SH-FLAT SHEET - SIGNAL SIGN	4.00	0.00	4.00	SQFT	0.00	\$60.00	\$0.0
		0030	0530	9020834	SIGNAL SIGN, MOUNTING HARDWARE	4.00	0.00	4.00	EA	0.00	\$190.00	\$0.
		0030	0540	9022708	POST, SIGNAL 8 FT.	4.00	0.00	4.00	EA	0.00	\$1,179.00	\$0.0
		0030	0550	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	56.00	0.00	56.00	LF	0.00	\$100.00	\$0.0
		0030	0560	9028308	CABLE, 16 AWG 2 CONDUCTOR	800.00	0.00	800.00	LF	0.00	\$2.00	\$0.
		0030	0570	9028310	CABLE, 16 AWG 5 CONDUCTOR	800.00	0.00	800.00	LF	0.00	\$2.30	\$0.
		0030	0580	9029100	BASE, CONCRETE	1.80	0.00	1.80	CUYD	0.00	\$3,000.00	\$0.
		0030	0590	9029902	MISC.CENTRAL MASTER CONTROL UNIT	12.00	0.00	12.00	EA	0.00	\$3,475.00	\$0.
		0030	0600	9029902	MISC.DETECTOR, PUSHBUTTON (NEW INSTALLATION) APS	50.00	0.00	50.00	EA	0.00	\$800.00	\$0.
		0030	0610	9029902	MISC.PEDESTRIAN PUSH BUTTON EXTENSION (2" OR 4")	6.00	0.00	6.00	EA	0.00	\$235.00	\$0.
		0030	0620	9029902	MISC.RELOCATE PEDESTRIAN PUSH BUTTON POST	1.00	0.00	1.00	EA	0.00	\$240.00	\$0.
		0040	0630	9031220	PIPE POSTS	80.00	0.00	80.00	LB	0.00	\$19.61	\$0.
		0040	0640	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	4.00	0.00	4.00	EA	0.00	\$482.85	\$0.
		0040	0650	9031270A	2 IN. PSST POST - 12 GA.	240.00	0.00	240.00	LF	55.50	\$41.39	\$2,297.
		0040	0660	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	9.00	0.00	9.00	EA	4.00	\$662.58	\$2,650.
		0040	0670	9031274	CONCRETE POST ANCHOR FOR 2 IN. PSST 7 GA.	12.00	0.00	12.00	EA	0.00	\$734.63	\$0.
		0040	0680	9031280	2.5 IN. PSST POST - 12 GA.	34.00	0.00	34.00	LF	0.00	\$52.03	\$0.
		0040	0690	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	2.00	0.00	2.00	EA	0.00	\$759.89	\$0.
		0040	0700	9035004A	SH-FLAT SHEET	42.00	0.00	42.00	SQFT	0.00	\$83.88	\$0.
		0040	0710	9039902	MISC.RELOCATE GROUND SIGNS	17.00	0.00	17.00	EA	4.00	\$500.00	\$2,000
		0001	5001	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	0.00	22.00	22.00	LF	0.00	\$30.00	\$0.
	Project J	5P3490 - To	otal Value	Posted to D	ate as of Report Generated Date							\$614,535.
0519-D03 Ove	erall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$614,535.

Revision 3/23/2023 Page 6 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5P3490

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	7/12/24	7/16/24	0.09	LS	Rolla, MO, Phelps County - Rte. O					The final items to be removed have been removed. Therefor, 9% of the Removal Lump Sum shall be paid.
0060	3040504	TYPE 5 AGGREGATE FOR BASE	7/9/24	7/12/24	171.50	SQYD	Rolla, MO, Phelps County - Rte. O					Base Rock for under R6's Curb Ramps as well as all of R5's Base Rock.
			7/10/24	7/12/24	255.50	SQYD	Rolla, MO, Phelps County - Rte. O					Base Rock under all locations at R4 and R3
			7/11/24	7/12/24	143.20	SQYD	Rolla, MO, Phelps County - Rte. O					Base Rock under Sidewalk at R1 and R2
			7/12/24	7/16/24	75.50	SQYD	Rolla, MO, Phelps County - Rte. O					Base Rock under Curb Ramp and Sidewalk for R11 and R12.
0140	6081010	CONCRETE CURB RAMP	7/9/24	7/12/24	29.10	SQYD	Rolla, MO, Phelps County - Rte. O					Curb Ramps at R6 and R5
			7/10/24	7/12/24	21.60	SQYD	Rolla, MO, Phelps County - Rte. O					Curb Ramps poured at R4 and R3
			7/12/24	7/16/24	22.50	SQYD	Rolla, MO, Phelps County - Rte. O					Curb ramp poured at R11 and R12
0150	6081012	TRUNCATED DOMES	7/12/24	7/16/24	20.00	SQFT	Rolla, MO, Phelps County - Rte. O					Truncated Domes placed at R11 and R12. These were not identified on the Quantity sheets but were depicted the Plans.
0180	6085007	PAVED APPROACH, 7 IN.	7/9/24	7/12/24	60.00	SQYD	Rolla, MO, Phelps County - Rte. O					Paved approach at R5. Southermost Driveway.
			7/10/24	7/12/24	139.10	SQYD	Rolla, MO, Phelps County - Rte. O					Paved approaches at R4 and R3. Both remaining driveways for the Rolla Portion of this job.
0200	6086004	CONCRETE SIDEWALK, 4 IN.	7/9/24	7/12/24	82.40	SQYD	Rolla, MO, Phelps County - Rte. O					Sidewalks at R5 and R6.
			7/10/24	7/12/24	94.60	SQYD	Rolla, MO, Phelps County - Rte. O					Sidewalks at R4 and R3
			7/11/24	7/12/24	143.20	SQYD	Rolla, MO, Phelps County - Rte. O					Sidewalk poured at R1 and R2
			7/12/24	7/16/24	53.00	SQYD	Rolla, MO, Phelps County - Rte. O					Sidewalk poured at R11 and R12
0270	6091052	CURB AND GUTTER TYPE B	7/12/24	7/16/24	125.00	LF	Rolla, MO, Phelps County - Rte. O					Type B Curb and Gutter at R11 and R12

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023 Page 7 of 15



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3490	0060	TYPE 5 AGGREGATE FOR	Material		3	Apr 3, 2024	SYSTEM	(\$2,852.85)	
		BASE			4	Apr 17, 2024	SYSTEM	\$7,866.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ricksc3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Apr 17, 2024	SYSTEM	(\$7,866.65)	
					5	May 1, 2024	SYSTEM	\$14,399.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ricksc3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	May 1, 2024	SYSTEM	(\$14,399.55)	
					6	May 16, 2024	SYSTEM	\$18,138.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ricksc3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	May 16, 2024	SYSTEM	(\$18,138.45)	
					7	Jun 3, 2024	SYSTEM	\$22,413.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ricksc3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jun 3, 2024	SYSTEM	(\$22,413.05)	
					8	Jun 17, 2024	SYSTEM	\$26,535.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ricksc3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jun 17, 2024	SYSTEM	(\$26,535.85)	
					9	Jul 1, 2024	SYSTEM	\$32,308.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ricksc3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Jul 1, 2024	SYSTEM	(\$32,308.65)	
					10	Jul 16, 2024	SYSTEM	\$39,411.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ricksc3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Jul 16, 2024	SYSTEM	(\$39,411.35)	
				- Total				(\$2,852.85)	
			Material - Tota		4	Ann 47	OVOTEN	(\$2,852.85)	
			MaterialCredit		4	Apr 17, 2024	SYSTEM	\$2,852.85	
				- Total				\$2,852.85	
			MaterialCredit	- Total				\$2,852.85	
			Overrun	Overrun	10	Jul 16, 2024	SYSTEM	\$328.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user ricksc3 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					10	Jul 16, 2024	SYSTEM	(\$328.35)	
				Overrun - T	otal			\$0.00	
	0000	Total	Overrun - Tota	ı				\$0.00	
	0060 -	CONCRETE PAVEMENT (8 IN. NON-REINF)	Material		3	Apr 3, 2024	SYSTEM	\$0.00 \$7,739.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user bashoa1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		,			3	Apr 3, 2024	SYSTEM	(\$7,739.50)	
					4	Apr 17, 2024	SYSTEM	(\$9,027.50)	
					5	May 1, 2024	SYSTEM	\$9,027.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ricksc3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	May 1, 2024	SYSTEM	(\$9,027.50)	·
					6	May 16, 2024	SYSTEM	\$10,154.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ricksc3 overridding Payment Estimate Exception 2 on the current Payment Estimate.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Fioject	Litte	Безсприон	Type	Adjustment Type	Number	Date	By	Amount	remany.
J5P3490	0070	CONCRETE PAVEMENT (8 IN. NON-REINF)	Material		6	May 16, 2024	SYSTEM	(\$10,154.50)	
					7	Jun 3, 2024	SYSTEM	\$11,615.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ricksc3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Jun 3, 2024	SYSTEM	(\$11,615.00)	
					8	Jun 17, 2024	SYSTEM	\$11,615.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ricksc3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Jun 17, 2024	SYSTEM	(\$11,615.00)	
					9	Jul 1, 2024	SYSTEM	\$11,615.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ricksc3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Jul 1, 2024	SYSTEM	(\$11,615.00)	Edilinate Exception 2 of the edilion of dyllion Edulinate.
					10	Jul 16, 2024	SYSTEM	\$11,615.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ricksc3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Jul 16, 2024	SYSTEM	(\$11,615.00)	Edilinate Exception 2 of the editoric Layment Edilinate.
				- Total	2024			(\$9,027.50)	
			Material - Tota					(\$9,027.50)	
			MaterialCredit		5	May 1,	SYSTEM	\$9,027.50	
				Total	-	2024			
				- Total				\$9,027.50	
	0050		MaterialCredit	- Iotai				\$9,027.50	
	0070 -			0				\$0.00	
	0120	MISC. DRAINAGE ITEM	Overrun	Overrun	7	Jun 3, 2024	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user ricksc3 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					7	Jun 3, 2024	SYSTEM	(\$1,500.00)	
					8	Jun 17, 2024	SYSTEM	(\$1,500.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					8	Jun 17, 2024	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user ricksc3 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					9	Jul 1, 2024	SYSTEM	(\$1,500.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				Overrun - T	otal			(\$1,500.00)	
			Overrun - Tota	ıl					
	0120 -	Total						(\$1,500.00)	
		Total						(\$1,500.00)	
		CONCRETE CURB RAMP	Material		7	Jun 3, 2024	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		CONCRETE CURB	Material		7		SYSTEM SYSTEM	(\$1,500.00)	Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment
		CONCRETE CURB	Material			2024 Jun 3,		(\$1,500.00) \$45,528.75	Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment
		CONCRETE CURB	Material		7	Jun 3, 2024 Jun 17,	SYSTEM	(\$1,500.00) \$45,528.75 (\$45,528.75)	Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment
		CONCRETE CURB	Material		7	Jun 3, 2024 Jun 17, 2024 Jun 17,	SYSTEM SYSTEM	(\$1,500.00) \$45,528.75 (\$45,528.75) \$50,739.75	Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment
		CONCRETE CURB	Material		7 8	Jun 3, 2024 Jun 17, 2024 Jun 17, 2024 Jul 1,	SYSTEM SYSTEM SYSTEM	(\$1,500.00) \$45,528.75 (\$45,528.75) \$50,739.75 (\$50,739.75)	Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment
		CONCRETE CURB	Material		7 8 8 9	2024 Jun 3, 2024 Jun 17, 2024 Jun 17, 2024 Jul 1, 2024 Jul 1, 2024 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,500.00) \$45,528.75 (\$45,528.75) \$50,739.75 (\$50,739.75) \$53,250.75	Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.
		CONCRETE CURB	Material		7 8 8 9 9	2024 Jun 3, 2024 Jun 17, 2024 Jun 17, 2024 Jul 1, 2024 Jul 1, 2024 Jul 1, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,500.00) \$45,528.75 (\$45,528.75) \$50,739.75 (\$50,739.75) \$53,250.75 (\$53,250.75) \$63,132.75	Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		CONCRETE CURB	Material		7 8 8 9	2024 Jun 3, 2024 Jun 17, 2024 Jun 17, 2024 Jul 1, 2024 Jul 1, 2024 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,500.00) \$45,528.75 (\$45,528.75) \$50,739.75 (\$50,739.75) \$53,250.75	Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
23490	0140	CONCRETE CURB RAMP	Material - Tota	**				\$0.00	
	0140 -							\$0.00	
	0150	TRUNCATED DOMES	Material		1	Mar 4, 2024	SYSTEM	\$350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user bashoa1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Mar 4, 2024	SYSTEM	(\$350.00)	
					2	Mar 18, 2024	SYSTEM	\$350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user bashoa1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Mar 18, 2024	SYSTEM	(\$350.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0150 -	Total						\$0.00	
	0180	PAVED APPROACH, 7 IN.	Material		10	Jul 16, 2024	SYSTEM	\$17,321.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ricksc3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					10	Jul 16, 2024	SYSTEM	(\$17,321.70)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0180 -	Total						\$0.00	
	0190	PAVED APPROACH, 8 IN.	Material		6	May 16, 2024	SYSTEM	\$16,834.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	May 16, 2024	SYSTEM	(\$16,834.00)	
					7	Jun 3, 2024	SYSTEM	\$26,590.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ricksc3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Jun 3, 2024	SYSTEM	(\$26,590.50)	
					8	Jun 17, 2024	SYSTEM	\$26,590.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ricksc3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Jun 17, 2024	SYSTEM	(\$26,590.50)	
					9	Jul 1, 2024	SYSTEM	\$49,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ricksc3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Jul 1, 2024	SYSTEM	(\$49,590.00)	
					10	Jul 16, 2024	SYSTEM	\$49,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user ricksc3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					10	Jul 16, 2024	SYSTEM	(\$49,590.00)	
				- Total				\$0.00 \$0.00	
		Material - Total							
J	0190 -	Total						\$0.00	
	0200	CONCRETE SIDEWALK, 4 IN.	Material		4	Apr 17, 2024	SYSTEM	\$30,219.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Apr 17, 2024	SYSTEM	(\$30,219.80)	
					5	May 1, 2024	SYSTEM	\$63,460.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	May 1, 2024	SYSTEM	(\$63,460.40)	
					6	May 16, 2024	SYSTEM	\$69,608.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ricksc3 overridding Payment Estimate Exception 5 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3490	0200	CONCRETE SIDEWALK, 4 IN.	Material	. 750	6	May 16, 2024	SYSTEM	(\$69,608.20)	
					7	Jun 3, 2024	SYSTEM	\$79,277.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user ricksc3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Jun 3, 2024	SYSTEM	(\$79,277.12)	
					8	Jun 17, 2024	SYSTEM	\$99,219.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user ricksc3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					8	Jun 17, 2024	SYSTEM	(\$99,219.12)	
					9	Jul 1, 2024	SYSTEM	\$114,801.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user ricksc3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Jul 1, 2024	SYSTEM	(\$114,801.02)	
					10	Jul 16, 2024	SYSTEM	\$136,819.82	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ricksc3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					10	Jul 16, 2024	SYSTEM	(\$136,819.82)	
				- Total				\$0.00	
			Material - Tota	tal				\$0.00	
	0200 -	Total						\$0.00	
	0260	CONCRETE GUTTER TYPE A	Material		4	Apr 17, 2024	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ricksc3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Apr 17, 2024	SYSTEM	(\$800.00)	
					5	May 1, 2024	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ricksc3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	May 1, 2024	SYSTEM	(\$800.00)	
					6	May 16, 2024	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ricksc3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	May 16, 2024	SYSTEM	(\$800.00)	
					7	Jun 3, 2024	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ricksc3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Jun 3, 2024	SYSTEM	(\$800.00)	
					8	Jun 17, 2024	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ricksc3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Jun 17, 2024	SYSTEM	(\$800.00)	
					9	Jul 1, 2024	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ricksc3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Jul 1, 2024	SYSTEM	(\$800.00)	
					10	Jul 16, 2024	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user ricksc3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Jul 16, 2024	SYSTEM	(\$800.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0260 -	Total						\$0.00	
	0310	CMS WITH COMMUNICATION INTERFACE, CONT F	Material		1	Mar 4, 2024	SYSTEM	\$52,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user bashoa1 overridding Payment Estimate Exception 2 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3490	0310	CMS WITH COMMUNICATION INTERFACE, CONT F	Material		1	Mar 4, 2024	SYSTEM	(\$52,200.00)	
					2	Mar 18, 2024	SYSTEM	\$52,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user bashoa1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Mar 18, 2024	SYSTEM	(\$52,200.00)	
					3	Apr 3, 2024	SYSTEM	\$52,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user bashoa1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Apr 3, 2024	SYSTEM	(\$52,200.00)	
					4	Apr 17, 2024	SYSTEM	\$52,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user ricksc3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Apr 17, 2024	SYSTEM	(\$52,200.00)	
					5	May 1, 2024	SYSTEM	\$52,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user ricksc3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	May 1, 2024	SYSTEM	(\$52,200.00)	
					6	May 16, 2024	SYSTEM	\$52,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user ricksc3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					6	May 16, 2024	SYSTEM	(\$52,200.00)	
					7	Jun 3, 2024	SYSTEM	\$52,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user ricksc3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Jun 3, 2024	SYSTEM	(\$52,200.00)	
				- Total				\$0.00	
			Material - Tota	<u> </u>				\$0.00	
	0310 -							\$0.00	
	0460	ALTERNATE DITCH CHECK	Material		4	Apr 17, 2024	SYSTEM	\$796.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ricksc3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Apr 17, 2024	SYSTEM	(\$796.50)	
					5	May 1, 2024	SYSTEM	\$796.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ricksc3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	May 1, 2024	SYSTEM	(\$796.50)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0460	Total						\$0.00	
	0470	CURB INLET CHECK	Material		4	Apr 17, 2024	SYSTEM	\$950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user ricksc3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Apr 17, 2024	SYSTEM	(\$950.00)	
					5	May 1, 2024	SYSTEM	\$5,510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user ricksc3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	May 1, 2024	SYSTEM	(\$5,510.00)	
					6	May 16, 2024	SYSTEM	\$5,510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ricksc3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	May 16, 2024	SYSTEM	(\$5,510.00)	
					7	Jun 3, 2024	SYSTEM	\$5,510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user ricksc3 overridding Payment Estimate Exception 9 on the current Payment Estimate.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J5P3490	0470	CURB INLET CHECK	Material		7	Jun 3, 2024	SYSTEM	(\$5,510.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
		Total						\$0.00	
	0500	TYPE 2 TURF REINFORCEMENT MAT	Material		5	May 1, 2024	SYSTEM	\$4,312.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user ricksc3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	May 1, 2024	SYSTEM	(\$4,312.50)	
					6	May 16, 2024	SYSTEM	\$4,312.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user ricksc3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					6	May 16, 2024	SYSTEM	(\$4,312.50)	
					7	Jun 3, 2024	SYSTEM	\$4,312.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user ricksc3 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					7	Jun 3, 2024	SYSTEM	(\$4,312.50)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0500 -	Total						\$0.00	
	0650	2 IN. PSST POST - 12 GA.	Material		6	May 16, 2024	SYSTEM	\$2,297.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user ricksc3 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	May 16, 2024	SYSTEM	(\$2,297.14)	
					7	Jun 3, 2024	SYSTEM	\$2,297.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user ricksc3 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					7	Jun 3, 2024	SYSTEM	(\$2,297.14)	
					8	Jun 17, 2024	SYSTEM	(\$2,297.14)	
				- Total				(\$2,297.14)	
			Material - Tota					(\$2,297.14)	
			MaterialCredit		9	Jul 1, 2024	SYSTEM	\$2,297.14	
				- Total				\$2,297.14	
			MaterialCredit - Total					\$2,297.14	
		Total			-			\$0.00	
	0660	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	Material		6	May 16, 2024	SYSTEM	\$2,650.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user ricksc3 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	May 16, 2024	SYSTEM	(\$2,650.32)	
					7	Jun 3, 2024	SYSTEM	\$2,650.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user ricksc3 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					7	Jun 3, 2024	SYSTEM	(\$2,650.32)	
					8	Jun 17, 2024	SYSTEM	(\$2,650.32)	
				- Total				(\$2,650.32)	
			Material - Tota					(\$2,650.32)	
			MaterialCredit		9	Jul 1, 2024	SYSTEM	\$2,650.32	
				- Total				\$2,650.32	
			MaterialCredit	- Total				\$2,650.32	
		Total						\$0.00	
J5P3490 -	Total							(\$1,500.00)	



Jul 23, 2024

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Overall - Total									

MoDOT

Contract Adjustments for Contract - 230519-D03

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 15 of 15