

Pay Estimate Created Date: September 16, 2024

Progress Estimate Number	Contract ID	230616-H02	Pay Period Start	September 2, 2024	Original Contract Amount	\$4,142,000.00
4	Prime Contractor	Pace Construction Company, LLC	Pay Period End	September 15, 2024	Net Change Order Amount Current Contract Amount	\$0.00 \$4,142,000.00

Approval Date		By User
September 16, 2024	Generated and Approved (and should be considered Draft) at the Project Office Level by	plottk1
September 16, 2024	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	plottk1
September 17, 2024	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2024	November 1, 2024		72.60%

	Contract Informational Dates									
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract							
Acceptance Date										
Awarded Date	July 12, 2023	July 12, 2023								
Letting Date	June 16, 2023	June 16, 2023								
Notice to Proceed Date	August 14, 2023	August 14, 2023								
Open to Traffic Date										
Work Began Date										

Contract Total Pay For Estimate No. 4									
		This Estimate	Previous	To Date					
230616-H02									
	Total Posted Items Pay	\$1,204,965.66	\$1,802,031.03	\$3,006,996.69					
	Gross Item Adjustments	(\$146,620.07)	\$152,491.00	\$5,870.93					
	Incentive	\$0.00	\$0.00	\$0.00					
	Disincentive	\$0.00	\$0.00	\$0.00					
	Liquidated Damage	\$0.00	\$0.00	\$0.00					
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00					
			\$1,954,522.03	\$3,012,867.62					
Contract Total Pay	/able This Estimate:	\$1.058.345.59							

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9S3525	0150	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$25.000	44	\$1,100.00
	0160	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	EA	\$1,200.000	2	\$2,400.00
	0170	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	100,827	\$13,107.51		
			4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.130	31,760	\$4,128.80
	0260	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	LF	\$36.000	50	\$1,800.00
	0270	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	EA	\$4,200.000	4	\$16,800.00
	0280	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$3,200.000	4	\$12,800.00
Project J9	S3525 - To	tal					\$52,136.31
J9S3826	0360	2022010	REMOVAL OF IMPROVEMENTS	LS	\$35,000.000	-0.224	(\$7,840.00)
	0370	2071000	LINEAR GRADING CLASS 1	STA	\$712.000	1	\$712.00
	0380	2159903	MISC.MODIFIED SHAPING SLOPES CLASS III	LF	\$14.000	480	\$6,720.00
	0410	4011208	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-2)	TONS	\$80.000	12,182.1	\$974,568.00
	0420	4071005	TACK COAT	GAL	\$3.000	9,694	\$29,082.00

Revision 3/23/2023 Page 1 of 23



Pay Estimate Created Date: September 16, 2024

Progress Estimate Number	Contract ID	230616-H02	Pay Period Start	September 2, 2024	Original Contract Amount	\$4,142,000.00
4	Prime Contractor	Pace Construction Company, LLC	Pay Period End	September 15, 2024	Net Change Order Amount	\$0.00
					Current Contract Amount	\$4,142,000.00

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount	
J9S3826	0450	6113010	FURNISHING TYPE 1 ROCK BLANKET	CUYD	\$46.000	89	\$4,094.00	
	0460	6113030	PLACING TYPE 1 ROCK BLANKET	CUYD	\$32.000	89	\$2,848.00	
	0710	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$5.450	13,602.79	\$74,135.21	
	0720	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	SQYD	\$5.450	3,048.3	\$16,613.24	
	0730	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	SQYD	\$4.300	133	\$571.90	
	0800	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	LF	\$30.000	537.5	\$16,125.00	
	0810	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$4,000.000	4	\$16,000.00	
	0830	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$3,200.000	6	\$19,200.00	
Project J9S3826 - Total								
Overall - Total								

Contract Adjustments This Estimate

		stments Exist on Contract ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3525	0040	MISC.	Material			-5,920.72	\$36.00	(\$213,145.92
	0040	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	5,920.72	\$36.00	\$213,145.92
	0050	GRAVEL (A) OR CRUSHED STONE (B)	Material			-243	\$2.50	(\$607.50)
	0050	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	243	\$2.50	\$607.50
	0070	TACK COAT	Material			-8,626	\$3.00	(\$25,878.00)
	0070	TACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user brophm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	8,626	\$3.00	\$25,878.00
	0100	CONSTRUCTION SIGNS	Material			-636	\$6.25	(\$3,975.00)
	0100	CONSTRUCTION SIGNS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user brophm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	636	\$6.25	\$3,975.00
	0130	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material			-2	\$3,000.00	(\$6,000.00)
	0130	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	2	\$3,000.00	\$6,000.00

Revision 3/23/2023 Page 2 of 23



Pay Estimate Created Date: September 16, 2024

Project	Lino	Item Description	Adjustment	Other Item	Comments	Adjustment	Line Item	Adjustment
Number	Line No.	Item Description	Adjustment Type	Adjustment Type	Connents	Adjustment Quantity	Adjustment Unit Price	Adjustment amount
J9S3525		RETAINED						
	0150	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-44	\$25.00	(\$1,100.00)
	0150	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user brophm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	44	\$25.00	\$1,100.00
	0160	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	Material			-2	\$1,200.00	(\$2,400.00)
	0160	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user brophm1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	2	\$1,200.00	\$2,400.00
	0170	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-100,827	\$0.13	(\$13,107.51)
	0170	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user brophm1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	100,827	\$0.13	\$13,107.51
	0170	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Other	Holding 10% until reflectivity has been performed. (10%)*(100,087-ft)*(\$0.13) = \$1,310.75 7,667 LF has not been paid and will be held until a determination is made in regard to paint being applied on asphalt that was paved over grass and is causing the paint to fall due to asphalt failing.			(\$1,310.75)
	0180	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-31,760	\$0.13	(\$4,128.80)
	0180	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user brophm1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	31,760	\$0.13	\$4,128.80
	0180	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Other	Holding 10% until reflectivity has been performed. (10%)*(31760-ft)*(\$0.13) = -\$412.88			(\$412.88)
	0260	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Other Item Adjustment	Stockpiled Materials Closure	Closing Stockpile. Valtir, LLC Invoice Number HS789673			(\$834.00)
	0270	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	Other Item Adjustment	Stockpiled Materials Closure	Closing Stockpile. Valtir, LLC Invoice Number HS789673			(\$7,900.00)
	0280	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material			-4	\$3,200.00	(\$12,800.00)
	0280	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	4	\$3,200.00	\$12,800.00

Revision 3/23/2023 Page 3 of 23



Pay Estimate Created Date: September 16, 2024

Progress Estimate Number
4 Contract ID 230616-H02 Prime Contractor LLC Page Page Period Start Page Period End September 2, 2024 Original Contract Amount \$4,142,000.00 Prime Contractor LLC Page Period End September 15, Page Period End September 15, 2024 Original Contract Amount \$4,142,000.00 Prime Contract Amount \$4,1

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
19S3525					Adjustment (0019) due to user brophm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
	0280	TYPE A CRASHWORTHY END TERMINAL (MASH)	Other Item Adjustment	Stockpiled Materials Closure	Closing Stockpile. Valtir, LLC Invoice Number HS789673			(\$7,500.00
I9S3826	0370	LINEAR GRADING CLASS 1	Overrun			-1	\$712.00	(\$712.00
	0380	MISC.	Material			-1,200	\$14.00	(\$16,800.00
	0380	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user brophm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,200	\$14.00	\$16,800.00
	0410	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-2)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	471.8	(\$0.40)	(\$186.40)
	0410	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-2)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	562.3	(\$0.40)	(\$222.15
	0410	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-2)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,335.2	(\$0.40)	(\$527.51
	0410	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-2)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,345.6	(\$0.40)	(\$531.62
	0410	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-2)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	2,183.7	(\$0.40)	(\$862.74
	0410	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-2)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,617.2	(\$0.40)	(\$638.92
	0410	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-2)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	2,519	(\$0.40)	(\$995.21
	0410	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-2)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	2,147.3	(\$0.40)	(\$848.36
	0410	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-2)	Material			-12,182.1	\$80.00	(\$974,568.00
	0410	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-2)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user brophm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	12,182.1	\$80.00	\$974,568.00
	0410	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-2)	Other Item Adjustment	Asphalt Cement Price Adjustment	For 12,182.1 tons using SL24-11 mix with 4.4% AC			(\$38,190.88
	0420	TACK COAT	Material			-9,694	\$3.00	(\$29,082.00
	0420	TACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user brophm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	9,694	\$3.00	\$29,082.00
	0450	FURNISHING TYPE 1 ROCK BLANKET	Overrun			-89	\$46.00	(\$4,094.00
	0450	FURNISHING TYPE 1 ROCK BLANKET	Material			-537	\$46.00	(\$24,702.00
	0450	FURNISHING TYPE 1 ROCK BLANKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	537	\$46.00	\$24,702.00

Revision 3/23/2023 Page 4 of 23



Pay Estimate Created Date: September 16, 2024

Progress Estimate Number
4 Contract ID 230616-H02 Prime Pace Construction Company, LLC Paperiod Start September 2, 2024 Original Contract Amount \$4,142,000.00 Prime Contractor Paperiod End September 15, 2024 Original Contract Amount \$4,142,000.00 Prime Contract Amount \$4,142,000.00

oject mber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3826	0460	PLACING TYPE 1 ROCK BLANKET	Overrun			-89	\$32.00	(\$2,848.00
	0470	CONSTRUCTION SIGNS	Material			-252	\$6.25	(\$1,575.00
	0470	CONSTRUCTION SIGNS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user brophm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	252	\$6.25	\$1,575.00
	0520	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material			-2	\$3,000.00	(\$6,000.00
(0520	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user brophm1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	2	\$3,000.00	\$6,000.00
	0710	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	Overrun			-1,386	\$5.45	(\$7,553.70
	0710	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	Overrun			-1,230.1	\$5.45	(\$6,704.05
	0730	PERMANENT EROSION CONTROL GEOTEXTILE	Overrun			-133	\$4.30	(\$571.90
	0730	PERMANENT EROSION CONTROL GEOTEXTILE	Material			-1,164	\$4.30	(\$5,005.20
	0730	PERMANENT EROSION CONTROL GEOTEXTILE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0031) due to user brophm1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	1,164	\$4.30	\$5,005.20
	0800	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Other Item Adjustment	Stockpiled Materials Closure	Closing Stockpile. Valtir, LLC Invoice Number HS789673			(\$22,935.00
	0810	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Other Item Adjustment	Stockpiled Materials Closure	Closing Stockpile. Valtir, LLC Invoice Number HS789673			(\$15,120.00
	0820	MGS END ANCHOR	Material			-4	\$1,600.00	(\$6,400.00
	0820	MGS END ANCHOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user brophm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	4	\$1,600.00	\$6,400.00
	0820	MGS END ANCHOR	Other Item Adjustment	Stockpiled Materials Closure	Closing out stockpile. Valtir, LLC Invoice Number HS789673			(\$2,620.00
	0830	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material			-15	\$3,200.00	(\$48,000.00
(0830	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user brophm1 overridding Payment Estimate Exception 10	15	\$3,200.00	\$48,000.00

Revision 3/23/2023 Page 5 of 23



Pay Estimate Created Date: September 16, 2024

	Progress Estimate Number 4 Contract ID 230616-H02 Prime Pace Construction Company, LLC		Contract ID	230616-H	02	Pay Period Start	September 2, 2024	Original Cont	nt \$4,142,000.00	
			pany, Pay Period En	September 15, 2024	Net Change C Amount Current Cont		\$0.00 \$4,142,000.00			
Project Number	Line No.	Item De	escription	Adjustment Type	Other Item Adjustment Type	Comm	nents	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3826						on the curr	ent Payment Estimate			
	0830		RASHWORTHY RMINAL (MASH)	Other Item Adjustment	Stockpiled Materials Closure	Closing out stock	pile. Valtir, LLC Invoice Number HS789673			(\$22,500.00)
Total										(\$146,620.07)

Revision 3/23/2023 Page 6 of 23



						Contract Project Information						
				_		John act i Toject information						
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work					
J9S3525	FAS S703(37)	Resurface	91	SCOTT	from Route P in Sto	oddard County to Route C in	Scott County near Morley					
J9S3826	FAS S705(002)	Resurface and ADA improvements	W	CAPE GIRARDEAU								
Totals by Job Numbers												
J9S3525					This Estimate	Previous	To Date					
		Item Pay Item Adjustmen		D	\$52,136.31 (\$17,957.63)	\$1,582,330.09 \$89,316.00	\$1,634,466.40 \$71,358.37					
			Gross It	em Pay	\$34,178.68	\$1,671,646.09	\$1,705,824.77					
	Incenti	ve			\$0.00	\$0.00	\$0.00					
	Disince				\$0.00	\$0.00	\$0.00					
		ated Damages			\$0.00	\$0.00	\$0.00					
	Other 0	Contract Adjusti	ments		\$0.00	\$0.00	\$0.00					
J9S3826					This Estimate	Previous	To Date					
0300020	Postad	Item Pay			\$1,152,829.35	\$219.700.94	\$1,372,530.29					
		ltem Adjustmen	ts		(\$128,662.44)	\$63,175.00	(\$65,487.44)					
	51033		Gross It	em Pay	\$1,024,166.91	\$282,875.94	\$1,307,042.85					
				-	#0.00	#0.00	#0.00					
	Incenti				\$0.00	\$0.00	\$0.00					
		ated Damages			\$0.00 \$0.00 \$0.00							
		Contract Adjusti	ments		\$0.00 \$0.00 \$0.00 \$0.00 \$0.00							
	Stile: \	zoaot Aajaoti			Ψ0.00	ψ0.00	Ψ0.00					

Revision 3/23/2023 Page 7 of 23



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period	Funda	Fatered	Chatric
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9S3826, Item 2159903, Project Item Line Number 0380, Material Set 215990396, Material 3304AGBS - Aggregate Base JSP, Acceptance Action Generic 3304AGBS is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3525, Item 3049910, Project Item Line Number 0040, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3525, Item 3049910, Project Item Line Number 0040, Material Set 304991096, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3525, Item 3105003, Project Item Line Number 0050, Material Set 310500396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3826, Item 4011208, Project Item Line Number 0410, Material Set 401120896, Material 0401BPPMBP2 - Plant Mix for Bit Pavement BP-2, Acceptance Action Generic AspLow is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3525, Item 4071005, Project Item Line Number 0070, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3826, Item 4071005, Project Item Line Number 0420, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3826, Item 6061080, Project Item Line Number 0820, Material Set 606108096, Material 1040GRBEESCAT2 - Breakaway End Anchor End Sect CI A Typ 2, Acceptance Action Generic 1040GRBEESCAT2 is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3525, Item 6063014, Project Item Line Number 0280, Material Set 606301496, Material 1040GRCWA - Crashworthy End Terminal Type A, Acceptance Action Generic 1040GRCWA is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3826, Item 6063014, Project Item Line Number 0830, Material Set 606301496, Material 1040GRCWA - Crashworthy End Terminal Type A, Acceptance Action Generic 1040GRCWA is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3826, Item 6113010, Project Item Line Number 0450, Material Set 611301096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3525, Item 6161005, Project Item Line Number 0100, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3826, Item 6161005, Project Item Line Number 0470, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3525, Item 6161098A, Project Item Line Number 0130, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3826, Item 6161098A, Project Item Line Number 0520, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3525, Item 6200015, Project Item Line Number 0150, Material Set 620001596, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3525, Item 6200033, Project Item Line Number 0160, Material Set 620003396, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indicat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3525, Item 6206000C, Project Item Line Number 0170, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3525, Item 6206000C, Project Item Line Number 0170, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3525, Item 6206001C, Project Item Line Number 0180, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3525, Item 6206001C, Project Item Line Number 0180, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3826, Item 6240103A, Project Item Line Number 0730, Material Set 6240103A96, Material 1011GXT3 - Geotextile Fabric for ErosionControl(T3), Acceptance Action Generic 1011GXT3 is insufficient.	No Remark was entered by Engineer	brophm1	Overridden
Estimate Exception Type: Item Overrun: Contract 230616-H02, Contract Project J9S3826, Project Item Line Number 0370, Contract Line Item Number 0370, Item 2071000, Minor Item.	No Remark was entered by Engineer	brophm1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230616-H02, Contract Project J9S3826, Project Item Line Number 0450, Contract Line Item Number 0450, Item 6113010, Minor Item.	No Remark was entered by Engineer	brophm1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230616-H02, Contract Project J9S3826, Project Item	No Remark was entered by Engineer	brophm1	Acknowledged

Revision 3/23/2023 Page 8 of 23



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Line Number 0460, Contract Line Item Number 0460, Item 6113030, Minor Item.			
Estimate Exception Type: Item Overrun: Contract 230616-H02, Contract Project J9S3826, Project Item Line Number 0710, Contract Line Item Number 0710, Item 6221001, Minor Item.	No Remark was entered by Engineer	brophm1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230616-H02, Contract Project J9S3826, Project Item Line Number 0730, Contract Line Item Number 0730, Item 6240103A, Minor Item.	No Remark was entered by Engineer	brophm1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230616-H02, Contract Project J9S3525, Project Item Line Number 0040, Contract Line Item Number 0040, Item 3049910, Minor Item.	No Remark was entered by Engineer	brophm1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230616-H02, Contract Project J9S3525, Project Item Line Number 0060, Contract Line Item Number 0060, Item 4020520, Minor Item.	No Remark was entered by Engineer	brophm1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230616-H02, Contract Project J9S3525, Project Item Line Number 0200, Contract Line Item Number 0200, Item 6221001, Minor Item.	No Remark was entered by Engineer	brophm1	Acknowledged

Revision 3/23/2023 Page 9 of 23



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
30616-H02	J9S3525	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$34,233.06	\$0.0
		0001	0020	2079909	MISC.MODIFIED LINEAR GRADING CLASS 2	4.00	0.00	4.00	STA	0.00	\$1,455.00	\$0.0
		0001	0030	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	200.00	0.00	200.00	LF	0.00	\$14.00	\$0.0
		0001	0040	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	3,986.80	0.00	3,986.80	TONS	5,920.72	\$36.00	\$213,145.9
		0001	0050	3105003	GRAVEL (A) OR CRUSHED STONE (B)	243.00	0.00	243.00	SQYD	243.00	\$2.50	\$607.5
		0001	0060	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	10,693.10	0.00	10,693.10	TONS	11,191.80	\$92.00	\$1,029,645.6
		0001	0070	4071005	TACK COAT	10,987.00	0.00	10,987.00	GAL	8,626.00	\$3.00	\$25,878.0
		0001	0800	6083004	4 IN. CONCRETE MEDIAN STRIP	198.40	0.00	198.40	SQYD	0.00	\$92.36	\$0.0
		0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	0.00	\$500.00	\$0.0
		0001	0100	6161005	CONSTRUCTION SIGNS	1,467.00	0.00	1,467.00	SQFT	636.00	\$6.25	\$3,975.0
		0001	0104	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	0.00	\$60.00	\$0.0
		0001	0106	6161025	CHANNELIZER (TRIM LINE)	40.00	0.00	40.00	EA	0.00	\$20.00	\$0.0
		0001	0110	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	0.00	\$750.00	\$0.0
		0001	0120	6161070	TUBULAR MARKER	50.00	0.00	50.00	EA	0.00	\$110.00	\$0.0
		0001	0130	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	2.00	\$3,000.00	\$6,000.0
		0001	0134	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	650.00	0.00	650.00	LF	0.00	\$60.00	\$0.0
		0001	0136	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	1,300.00	0.00	1,300.00	LF	0.00	\$10.00	\$0.0
		0001	0140	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$215,000.00	\$215,000.0
		0001	0150	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	44.00	0.00	44.00	LF	44.00	\$25.00	\$1,100.0
		0001	0160	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	2.00	0.00	2.00	EA	2.00	\$1,200.00	\$2,400.
		0001	0163	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	2,250.00	0.00	2,250.00	LF	0.00	\$2.50	\$0.
		0001	0165	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	6,000.00	0.00	6,000.00	LF	0.00	\$2.50	\$0.0
		0001	0167	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	66.00	0.00	66.00	LF	0.00	\$5.00	\$0.
		0001	0170	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	108,494.00	0.00	108,494.00	LF	100,827.00	\$0.13	\$13,107.
		0001	0180	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	31,760.00	0.00	31,760.00	LF	31,760.00	\$0.13	\$4,128.
		0001	0190	6206108A	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,066.00	0.00	1,066.00	LF	0.00	\$1.00	\$0.
		0001	0195	6207001	PAVEMENT MARKING REMOVAL	3,600.00	0.00	3,600.00	LF	0.00	\$0.50	\$0.
		0001	0200	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	3,692.00	0.00	3,692.00	SQYD	4,128.40	\$9.30	\$38,394.
		0001	0210	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	3,526.00	0.00	3,526.00	SQYD	3,281.80	\$7.75	\$25,433.
		0001	0220	7250318A	18 IN. PIPE GROUP B	50.00	0.00	50.00	LF	50.00	\$106.00	\$5,300.
		0001	0230	7250324A	24 IN. PIPE GROUP B	50.00	0.00	50.00	LF	50.00	\$112.00	\$5,600.
		0001	0240	7250336A	36 IN. PIPE GROUP B	75.00	0.00	75.00	LF	75.00	\$124.00	\$9,300.
		0001	0250	7250348A	48 IN. PIPE GROUP B	25.00	0.00	25.00	LF	25.00	\$162.00	\$4,050.
		0001	0255	9029401	TEMPORARY TRAFFIC SIGNALS AND LIGHTING	1.00	0.00	1.00	LS	0.00	\$13,000.00	\$0.
		0010	0260	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	50.00	0.00	50.00	LF	50.00	\$36.00	\$1,800.
		0010	0270	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED	4.00	0.00	4.00	EA	4.00	\$4,200.00	\$16,800.
		0010	0280	6063014	CURB) TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$3,200.00	\$12,800.
		0010	0290	6063020	TYPE C CRASHWORTHY END TERMINAL (MASH)	12.00	0.00	12.00	EA	0.00	\$28,600.00	\$0.
		0040	0300		2 IN. PSST POST - 12 GA.	18.00	0.00	18.00	LF	0.00	\$30.00	\$0.
		0040	0310	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	2.00	0.00	2.00	EA	0.00	\$200.00	\$0.
		0040	0320	9035004A	SH-FLAT SHEET	18.00	0.00	18.00	SQFT	0.00	\$36.00	\$0.
		0040	0330	7039902	MISC.BARRIER END MODIFICATION	4.00	0.00	4.00	EA	0.00	\$9,500.00	\$0.0
												\$0.0
		0071	0340	7039902	MISC.BARRIER END MODIFICATION	4.00	0.00	4.00	EA	0.00	\$9,500.00	

Revision 3/23/2023 Page 10 of 23



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Total Value POST To Date (See represented date)	Unit Price	Total Posted Approved Qty	Unit	Total Current Quantity	Net Change Order	Bid Quantity	Description	Item Code	Line No.	Category	Project No.	Contract m.CONTRACT
\$0	\$9,500.00	0.00	EA	4.00	0.00	4.00	MISC.BARRIER END MODIFICATION	7039902	0350	0072	J9S3525	30616-H02
\$1,634,466							ate as of Report Generated Date			9 S3525 - To		
\$27,160	\$35,000.00	0.78	LS	1.00	0.00	1.00	REMOVAL OF IMPROVEMENTS	2022010	0360	0001	J9S3826	
\$4,841	\$712.00	6.80	STA	5.80	0.00	5.80	LINEAR GRADING CLASS 1	2071000	0370	0001		
\$16,800	\$14.00	1,200.00	LF	1,200.00	0.00	1,200.00	MISC.MODIFIED SHAPING SLOPES CLASS III	2159903	0380	0001		
\$0	\$39.00	0.00	TONS	1,707.90	0.00	1,707.90	MISC.PERMANENT AGGREGATE EDGE TREATMENT	3049910	0390	0001		
\$0	\$16.00	0.00	TONS	37.00	0.00	37.00	GRAVEL (A) OR CRUSHED STONE (B)	3105002	0400	0001		
\$974,568	\$80.00	12,182.10	TONS	15,822.60	0.00	15,822.60	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-2)	4011208	0410	0001		
\$29,082	\$3.00	9,694.00	GAL	13,320.00	0.00	13,320.00	TACK COAT	4071005	0420	0001		
\$0	\$3.05	0.00	GAL	11,133.00	0.00	11,133.00	BITUMINOUS FOG SEAL	4134000	0430	0001		
\$0	\$44.00	0.00	SQFT	40.00	0.00	40.00	TRUNCATED DOMES	6081012	0440	0001		
\$24,702	\$46.00	537.00	CUYD	448.00	0.00	448.00	FURNISHING TYPE 1 ROCK BLANKET	6113010	0450	0001		
\$17,184	\$32.00	537.00	CUYD	448.00	0.00	448.00	PLACING TYPE 1 ROCK BLANKET	6113030	0460	0001		
\$1,575	\$6.25	252.00	SQFT	1,288.00	0.00	1,288.00	CONSTRUCTION SIGNS	6161005	0470	0001		
\$0	\$60.00	0.00	EA	2.00	0.00	2.00	ADVANCED WARNING RAIL SYSTEM	6161008	0480	0001		
\$0	\$20.00	0.00	EA	100.00	0.00	100.00	CHANNELIZER (TRIM LINE)	6161025	0490	0001		
\$0	\$150.00	0.00	EA	32.00	0.00	32.00	TYPE III MOVEABLE BARRICADE	6161030	0500	0001		
\$0	\$750.00	0.00	EA	1.00	0.00	1.00	FLASHING ARROW PANEL	6161040	0510	0001		
\$6,000	\$3,000.00	2.00	EA	6.00	0.00	6.00	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	6161098A	0520	0001		
\$27,500	\$110,000.00	0.25	LS	1.00	0.00	1.00	MOBILIZATION	6181000	0530	0001		
\$0	\$3.00	0.00	LF	1,367.00	0.00	1,367.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN YELLOW	6200006	0540	0001		
\$0	\$5.00	0.00	LF	1,629.00	0.00	1,629.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	6200009	0550	0001		
\$0	\$25.00	0.00	LF	217.00	0.00	217.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	6200015	0560	0001		
\$0	\$25.00	0.00	LF	308.00	0.00	308.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	6200018	0570	0001		
\$0	\$325.00	0.00	EA	4.00	0.00	4.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	6200021	0580	0001		
\$0	\$500.00	0.00	EA	8.00	0.00	8.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT FISH HOOK ARROW	6200051	0590	0001		
\$0	\$1.00	0.00	LF	530.00	0.00	530.00	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	6205901A	0600	0001		
\$1	\$1.00	0.00	LF	3,324.00	0.00	3,324.00	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	6205902A	0610	0001		
\$1	\$0.13	0.00	LF	98,153.00	0.00	98,153.00	4 IN, WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6206000C	0620	0001		
\$0	\$0.13	0.00	LF	91,257.00	0.00	91,257.00	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6206001C	0630	0001		
\$0	\$0.50	0.00	LF	1,899.00	0.00	1,899.00	PAVEMENT MARKING REMOVAL	6207001	0640	0001		
\$0	\$25.00	0.00	EA	4.00	0.00	4.00	PAVEMENT MARKING REMOVAL (SYMBOLS)	6207002	0650	0001		
\$0	\$1.05	0.00	LF	6,850.00	0.00	6,850.00	4 IN TEMPORARY PAVEMENT MARKING PAINT	6208076	0660	0001		
\$0	\$110.00	0.00	EA	16.00	0.00	16.00	MISC.ISLAND TUBULAR MARKERS	6209902	0670	0001		
\$0	\$50.00	0.00	EA	36.00	0.00	36.00	MISC.TYPE 2 PREFORMED GROOVED TAPE 24 IN YIELD WHITE TRIANGLE	6209902	0680	0001		
\$	\$250.00	0.00	EA	2.00	0.00	2.00	MISC.TYPE 2 PREFORMED GROOVED TAPE STRAIGHT ARROW	6209902	0690	0001		
\$	\$350.00	0.00	EA	4.00	0.00	4.00	MISC.TYPE 2 PREFORMED GROOVED TAPE STRAIGHT/LEFT ARROW	6209902	0700	0001		
\$82,76	\$5.45	15,186.10	SQYD	12,570.00	0.00	12,570.00	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	6221001	0710	0001		
\$23,69	\$5.45	4,348.30	SQYD	6,563.00	0.00	6,563.00	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	6224010	0720	0001		
\$5,00	\$4.30	1,164.00	SQYD	1,031.00	0.00	1,031.00	0730 6240103A PERMANENT EROSION CONTROL GEOTEXTILE			0001		
\$0	\$24.15	0.00	STA	799.80	0.00	799.80	BITUMINOUS SHOULDER RUMBLE STRIP	6261000A	0740	0001		
\$0	\$36.75	0.00	STA	152.50	0.00	152.50	0001 0750 6261001 BITUMINOUS CENTERLINE RUMBLE STRIP					
\$0	\$109.00	0.00	LF	10.00	0.00	10.00	18 IN. PIPE GROUP C	7250418	0760	0001		

Revision 3/23/2023 Page 11 of 23



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230616-H02	J9S3826	0001	0770	7250424	24 IN. PIPE GROUP C	10.00	0.00	10.00	LF	0.00	\$115.00	\$0.00
		0001	0780	7261015	15 IN. PIPE GROUP A	12.00	0.00	12.00	LF	0.00	\$98.00	\$0.00
		0001	0790	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	0.00	\$1,140.00	\$0.00
		0010	0800	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	1,375.00	0.00	1,375.00	LF	1,375.00	\$30.00	\$41,250.00
		0010	0810	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	9.00	0.00	9.00	EA	9.00	\$4,000.00	\$36,000.00
		0010	0820	6061080	MGS END ANCHOR	4.00	0.00	4.00	EA	4.00	\$1,600.00	\$6,400.00
		0010	0830	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	15.00	0.00	15.00	EA	15.00	\$3,200.00	\$48,000.00
	Project J	9S3826 - To	otal Value	Posted to D	late as of Report Generated Date							\$1,372,530.28
230616-H02 Ove	S-H02 Overall - Total Value Posted to Date as of Report Generated Date											

Revision 3/23/2023 Page 12 of 23



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9S3525

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0150	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	9/9/24	9/16/24	11.00	LF	Route 91 RR Crossing	26.382	LT	26.382	LT	Field Verified brophm1
				9/16/24	11.00	LF	Route 91 RR Crossing	26.382	RT	26.382	RT	Field Verified brophm1
				9/16/24	11.00	LF	Route 91 and Route 61 Intersection	28.102	RT	28.102	RT	Field Verified brophm1
				9/16/24	11.00	LF	Route 91 and Route P Intersection	27.571	LT	27.571	LT	Field Verified brophm1
0160	6200033	PREF THERMO PVMT MARK, R/R XING	9/9/24	9/16/24	1.00	EA	Route 91	26.268	RT	26.268	RT	Field Verified brophm1
				9/16/24	1.00	EA	Route 91	26.509	LT	26.509	LT	Field Verified brophm1
0170	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	9/9/24	9/16/24	100,827.00	LF	Route 91	17.922	LT/RT	27.571	LT/LT	Field Verified and Measured brophm1
0180	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	9/9/24	9/16/24	400.00	LF	Route 91	28.102	CL	28.828	CL	Solid Yellow Field Verified and Measured brophm1
				9/16/24	958.00	LF	Route 91	28.102	CL	28.828	CL	Inter Yellow Field Verified and Measured brophm1
				9/16/24	10,951.00	LF	Route 91	17.922	CL	27.571	CL	Inter Yellow Field Verified and Measured brophm1
				9/16/24	19,451.00	LF	Route 91	17.722	CL	27.571		Solid Yellow Field Verified and Measured brophm1
0260	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	9/9/24	9/16/24	50.00	LF	Route 91 A5034 SB Approach	23.499	RT	23.499	RT	Field Verified brophm1
0270	6061068	MGS BRIDGE APP. TRANS SEC (EXT CURB)	9/9/24	9/16/24	1.00	EA	Route 91 A5034 NB Approach	23.499	LT	23.499	LT	Field Verified brophm1
				9/16/24	1.00	EA	Route 91 A5034 NB Depart	23.499	LT	23.499	LT	Field Verified brophm1
				9/16/24	1.00	EA	Route 91 A5034 SB Approach	23.499	RT	23.499	RT	Field Verified brophm1
				9/16/24	1.00	EA	Route 91 A5034 SB Depart	23.499	RT	23.499	RT	Field Verified brophm1
0280	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	9/9/24	9/16/24	1.00	EA	Route 91 A5034 NB Approach	23.499	LT	23.499	LT	Field Verified brophm1
				9/16/24	1.00	EA	Route 91 A5034 NB Depart	23.499	LT	23.499	LT	Field Verified brophm1
				9/16/24	1.00	EA	Route 91 A5034 SB Approach	23.499	RT	23.499	RT	Field Verified brophm1
				9/16/24	1.00	EA	Route 91 A5034 SB Depart	23.499	RT	23.499	RT	Field Verified brophm1

Line lumber	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments	
0360	2022010	REMOVAL OF IMPROVEMENTS	8/29/24	9/4/24	0.06	LS	Route W	8.787	LT	8.808	LT	Guardrail at Bridge A3947 brophm1	
				9/4/24	0.06	LS	Route W	8.855	RT	8.881	RT	Guardrail at Bridge A3947 brophm1	
			8/30/24	9/4/24	0.06	LS	Route W	8.849	LT	8.886	LT	Guardrail at Bridge A3947 brophm1	
			9/3/24	9/9/24	0.06	LS	Route W	9.031	RT	9.118	RT	Guardrail at Bridge A3947 brophm1	
			9/4/24	9/9/24	0.06	LS	Route W	501+49.36	RT	500+24.18	RT	Guardrail in the Rundabout. Field Verified brophm1	
			9/6/24		-0.56	LS	Route W	8.778		8.812		Inspector Error	
				9/16/24	0.06		Route W	8.778		8.812		Inspector Error	
0370	2071000	LINEAR GRADING CLASS 1	9/3/24	9/9/24	1.00	STA	Route W	6.211			LT	Field Verified brophm1	
0380		MISC. SHAPING SLOPES	8/29/24		80.00		Route W, Cape Girardeau County	7.787		8.808		Field Verified brophm1	
3000	2100000	INIOC. SI DE INC SESI ES	0/20/24	9/4/24	80.00	LF	Route W. Cape Girardeau County	8 855		8 808		Field Verified brophm1	
			8/30/24	9/4/24	80.00	LF	Route W, Cape Girardeau County	8 849		8 886		Field Verified brophm1	
			9/3/24	9/9/24	160.00	LF	Route W, Cape Girardeau County	9.031		9.118		Field Verified brophm1	
			9/4/24	9/9/24	80.00	LF	Route W, Cape Girardeau County	501+49.93		500+24.18		Field Verified brophm1	
	4044000	DIT DAYEMENT MINER DOTA OF OD O											
)410	4011208	BIT. PAVEMENT MIXTURE PG70-22 (BP-2)	9/3/24	9/9/24	9.30	TONS	In Front of Islands Roundabout 1 (Special Sheet 5 of 6)	502+58.14	CL	501+00.00	CL	2(7')(60')(1.75/12)/27 = 4.54CY (4.54 CY)(2.04 Ton/CY) = 9.3 Ton brophm1	
				9/9/24	19.00	TONS	Cut through Roundabout 1 (Special Sheet 5 of 6)	502+58.14	CL	501+00.00	CL	(75')(22')(1.75/12)/27 = 9.32 CY (9.32 CY)(2.04 Ton/CY) = 19 Ton brophm1	
				9/9/24	41.70	TONS	Kingsway Dr Northbound Roundabout 1 (Special Sheet 5 of 6)	502+58.14	CL	501+00.00	CL	(158.14')(24')(1.75/12)/27 = 20.50 CY (20.50CY)(2.04 Ton/CY) = 41.7 Ton brophm1	
				9/9/24	129.30	TONS	Route W Northbound Roundabout 3 (Special Sheet 5 of 6)	497+42.46	CL	499+28.48	CL	(186')(24')(1.75/12)/27 = 24.11 CY (24.11CY)(2.04 Ton/CY) = 49.2 Ton brophm1	
													Tonnage for roundabout is over plan quantity. Refeasphalt tickets and ticket tabs.
				9/9/24	272.50	TONS	Mainline Route W	9.546	LT	9.227	LT	(0.319 mile)*(5280 ft/mile) = 1684.32 ft (1684.32*)(30*)(1.5/12)(27 = 272.9 CY (272.9 CY)(2.04 Ton/CY) = 272.9 Ton	
												(801.5 ton/mile/lane)(0.319 mile) = 255.7 ton 272.9 ton - 255.7 ton = 17.1 tons over brophm1	
			9/4/24	9/9/24	133.90	TONS	Mainline Route W	9.546	RT	9.360	RT	(0.186 mile)*(5280 ft/mile) = 982.08 ft (982.08')(30')(1.5/12)/27 = 136.4 CY (136.4 CY)(2.04 Ton/CY) = 278.3 Ton	
												(801.5 ton/mile/lane)(0.186 mile) = 149.1 ton 149.1 ton - 133.9 ton = 15.2 tons under brophm1	
				9/9/24	428.40	TONS	Route W to Lexington Roundabout 1 (Special Sheet 5 of 6)	501+36	CL	9+59	CL	2(520')(36')(1.75/12)/27 = 202.22 CY (202.22 CY)(2.04 Ton/CY) = 404.4 Ton	
												Tonnage for roundabout is over plan quantity. Refe asphalt tickets and ticket tabs. brophm1	
			9/5/24	9/10/24	667.60	TONS	Route W	9.227	LT	8.375	LT	(0.852 mile)*(5280 ft/mile) = 4498.56 ft (4498.56)*(15)*(1.5/12)/27 = 312.4 CY (312.4 CY)(2.04 Ton/CY) = 637.3 Ton	
												(801.5 ton/mile/lane)(0.852 mile) = 682.9 ton 682.6 ton - 667.2 ton = 15.3 tons under brophm1	
				9/10/24	667.60	TONS	Route W	9.360	RT	8.375	RT	(0.871 mile)*(5280 ft/mile) = 4598.88 ft (4598.88*)(15')(1.5/12)/27 = 319.37 CY (319.37 CY)(2.04 Ton/CY) = 651.5 Ton	
												(801.5 ton/mile/lane)(0.871 mile) = 698.1 ton 698.1 ton - 667.2 ton = 30.9 tons under brophm1	
			9/6/24	9/11/24	310.40	TONS	Route W	8.489	RT	8.074	RT	(0.415 mile)*(5280 ft/mile) = 2191.2 ft (2191.2')(15')(1.5/12)/27 = 152.17 CY (152.17 CY)(2.04 Ton/CY) = 310.4 Ton	
												brophm1	
				9/11/24	1,035.20	TONS	Route W	8.375	LT	7.283	LT	(1.092 mile)*(5280 ft/mile) = 5765.76 ft (5765.76')(15')(1.5/12)/27 = 400.4 CY (400.4 CY)(2.04 Ton/CY) = 816.8 Ton	
												(801.5 ton/mile/lane)(1.092 mile) = 875.2 ton 1035.2 ton - 875.2 ton = 160 tons over brophm1	

Revision 3/23/2023 Page 13 of 23



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0410	4011208	BIT. PAVEMENT MIXTURE PG70-22 (BP-2)	9/9/24		57.40	TONS	Route W	5.345	CL	5.538	CL	(0.096 mile)*(5280 ft/mile) = 506.88 ft (506.88*)*(12*)*(1.5/12*)*27 = 28.16 CY (28.16 CY)*(2.04 Ton/CY) = 57.4 Ton brophm1
				9/16/24	591.70	TONS	Route W	9.360	RT	8.375	RT	(0.791 mile)*(5280 ft/mile) = 4176.48 ft (4176.48")(15")(1.5/12)/27 = 290.03 CY (290.03 CY)(2.04 Ton/CY) = 591.7 Ton
												(801.5 ton/mile/lane)(0.791 mile) = 634 ton 634 ton - 591.7 ton = 42.3 tons under brophm1
				9/16/24	1,534.60	TONS	Route W	7.283	LT	4.523	LT	(2.760 mile)*(5280 ft/mile) = 14572.8 ft (14572.8)*(12)*(1.5/12)*27 = 809.6 CY (809.6 CY)(2.04 Ton/CY) = 1651.6 Ton (801.5 ton/mile/lane)(0.852 mile) = 682.9 ton
			9/10/24	9/11/24	1,617.20	TONS	Route W	7.283	RT	4.591	RT	1651.6 ton - 1534.6 ton = 117 tons under brophm1 (2.692 mile)*(5280 ft/mile) = 14213.76 ft
			3/10/24	3/11/24	1,017.20	10140	rodic W	7.203	Ki	4.551	NI	(14213.76)(12)(1.51/2)(27 = 789.65 CY (789.65 CY)(2.04 Ton/CY) = 1610.9 Ton Over 6.3 tons for irregularities.
			9/11/24	9/12/24	2,519.00	TONS	Route W	4.505	LT	0.793	LT	(3.712 mile)*(5280 ft/mile) = 19599.36 ft (19599.36)*(13)*(1.51/2)/27 = 1179.56 CY (1179.59 CY)/2.04 Ton/CY) = 2359.2 Ton 159.8 tons for irregularities. brophm1
			9/12/24	9/16/24	2,147.30	TONS	Route W	4.591	RT	1.923	RT	(2.668 mile)*(5280 ft/mile) = 14087.04 ft (14087.047)(13)*(1.57/2)27 = 847.83 CY (847.83 CY)(24 76n/CY) = 1779.95 Ton 50 ton/mile for rutting * 2.668 mile = 133.4 tons 133.4 + 1729.6 = 1863 tons 284.3 tons over due to rutting.
0420	4071005	TACK COAT	9/3/24	9/9/24	436.00	GAL	Roundabout and Mainline Route W	9.532	LT	8.852	LT	Field Verified brophm1
			9/4/24	9/9/24	484.00	GAL	Roundabout and Mainline Route W	9.546	RT	9.360	RT	Field Verified brophm1
			9/5/24	9/10/24	1,113.00				LT/RT LT/RT		LT/RT	Field Verified brophm1
			9/9/24	9/11/24	1,985.00			8.074			LT/RT	Field Verified brophm1
			9/10/24	9/11/24	1,359.00			7.283		4.591		Field Verified brophm1
			9/11/24	9/12/24	1,796.00	GAL	Route W	4.505		0.793		Field Verified brophm1
			9/12/24	9/16/24	1,359.00	GAL		4.591		1.923		Field Verified brophm1
0450	6113010	FURNISHING TYPE 1 ROCK BLANKET	9/3/24	9/9/24	89.00	CUYD	Route W	6.211	LT	6.230	LT	[(49)(16)(2) + 0.5(51.5)(16)(2)]/27 = 89 CY brophm1
0460			9/3/24	9/9/24	89.00			6.211		6.230		[(49)(16)(2) + 0.5(51.5)(16)(2)]/27 = 89 CY brophm1
0710	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	9/3/24	9/9/24	233.30 486.30		Roundabout Kingsway Dr. Roundabout Lexington Ave.	501+70.53 8+67.11		502+58.03 9+54.61		(87.50')*(24')/9 = 233.3 SY brophm1 (87.50')*(50')/9 = 486.3 SY
				9/9/24	666.40	SQYD	Roundabout Route W	500+49.25	CL	501+36.76		brophm1 (87.50')*(68.54')/9 = 666.4 SY
			9/4/24	9/9/24	2,750.00	SQYD	Route W Walden Dr. to Bridge A3947	8.811	CL	8.699	CL	brophm1 (591.36')*(41.85')/9 = 2750 SY brophm1
				9/9/24	4,146.80	SQYD	Roundabout Route W	0+00	CL	6+28.32	CL	(628.32')*(59.4')/9 = 4146.8 SY brophm1
			9/5/24	9/10/24	1,230.09	SQYD	Route W Box Culvert N0791	8.419	CL	8.489	CL	(369')*(30')/9 = 1230.09 SY This milling was added so the guardrali at this location would be at proper height due to the barrier walls be lot than the 31-inch standard. brophm1
				9/10/24			Route W	7.210		7.269		(311.52')*(57.7')/9 = 1997.3 SY brophm1
0720	6224040	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	0/2/24	9/10/24	2,092.60		Route W	8.489 9.532		8.534 9.546		(237.6')*(79.27')/9 = 2092.6 SY brophm1 (75')*(30')/9 = 250 SY
0720	0224010	MODIFIED COLDMILLING (DEFTH TRANSHTONS)	3/3/24	9/9/24			Route W	8.852		8.866		(75')(30')(9 - 250'ST brophm1 (75')*(42')(9 = 350 SY
			9/4/24	9/9/24	250.00	SQYD	Route W	8.534	CL	8.548	CL	brophm1 (75')*(30')/9 = 250 SY
				9/9/24	258.30	SQYD	Route W	8.685	CL	8.699	CL	brophm1 (75')*(31')/9 = 350 SY brophm1
			9/5/24	9/10/24	250.00	SQYD	Route W	7.196	CL	7.210	CL	(75')*(30')/9 = 250 SY brophm1
				9/10/24	250.00	SQYD	Route W	7.269	CL	7.283	CL	(75')*(30')/9 = 250 SY brophm1
				9/10/24	250.00	SQYD	Route W	8.475	CL	8.489	CL	(75')*(30')/9 = 250 SY brophm1
				9/10/24	250.00	SQYD	Route W	8.534	CL	8.548	CL	(75)*(310)/9 = 350 SY This milling was added so the guardrail at this location would be at proper height due to the barrier walls be lot than the 31-inch standard.
					200.00	SQYD	Route W Driveways	9.227	LT/RT	8.375	LT/RT	27(50')*(2')/9 = 300 SY brophm1
				9/10/24	300.00							Diopiliii
			9/6/24	9/10/24		SQYD	Route W Driveways	8.489	CL	7.500	CL	27(4')*(45)/9 = 540 SY
			9/6/24 9/9/24		540.00		Route W Driveways Route W Driveways	8.489 8.074		7.500 4.523		
	6240103A		9/9/24	9/11/24 9/16/24 9/9/24	540.00 100.00 133.00	SQYD	Route W Driveways Route W	8.074 6.211	CL	4.523 6.230	CL LT	27(4')*(45)/9 = 540 SY 15(2')*(30')/9 = 100 SY brophm1 [(49)(16) + 0.5(51.5)(16)]/9 = 133.0 SY brophm1
0730 0800	6240103A 6061061	PERMANENT EROSION CONTROL GEOTEXTILE MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	9/9/24	9/11/24 9/16/24 9/9/24 9/4/24	540.00 100.00 133.00 25.00	SQYD SQYD LF	Route W Driveways Route W Route W, Cape Girardeau County	8.074 6.211 8.787	CL LT LT	4.523 6.230 8.808	CL LT LT	27(4')'(45)'9 = 540 SY 15(2')'(30')'9 = 100 SY brophm¹ [(49)(16) + 0.5(51.5)(16)]'9 = 133.0 SY brophm¹ Field Verified brophm¹
			9/9/24	9/11/24 9/16/24 9/9/24 9/4/24 9/4/24	540.00 100.00 133.00	SQYD SQYD LF LF	Route W Driveways Route W	8.074 6.211	CL LT LT RT	4.523 6.230 8.808 8.808	CL LT LT RT	27(4')*(45)/9 = 540 SY 15(2')*(30')/9 = 100 SY brophm1 [(49)(16) + 0.5(51.5)(16)]/9 = 133.0 SY brophm1
			9/9/24 9/3/24 8/29/24	9/11/24 9/16/24 9/9/24 9/4/24 9/4/24	540.00 100.00 133.00 25.00 50.00	SQYD SQYD LF LF	Route W Driveways Route W Route W, Cape Girardeau County Route W, Cape Girardeau County Route W, Cape Girardeau County	8.074 6.211 8.787 8.855	CL LT LT RT RT	4.523 6.230 8.808 8.808	CL LT LT RT RT	27(4")*(45)*9 = 540 SY 15(2")*(30")*9 = 100 SY brophm1 ([49)*(16) + 0.5(51.5)*(16))*9 = 133.0 SY brophm1 Field Verified brophm1 Field Verified brophm1

Revision 3/23/2023 Page 14 of 23



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0810	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	8/29/24	9/4/24	1.00	EA	Route W, Cape Girardeau County	8.855	RT	8.881	RT	Field Verified brophm1
			8/30/24	9/4/24	1.00	EA	Route W, Cape Girardeau County	8.849	RT	8.886	RT	Field Verified brophm1
			9/4/24	9/9/24	1.00	EA	Route W, Roundabout	501+49.36	RT	500+24.18	RT	Field Verified brophm1
0830	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8/29/24	9/4/24	1.00	EA	Route W, Cape Girardeau County	8.787	LT	8.808	LT	Field Verified brophm1
				9/4/24	1.00	EA	Route W, Cape Girardeau County	8.855	RT	8.881	RT	Field Verified brophm1
			8/30/24	9/4/24	1.00	EA	Route W, Cape Girardeau County	8.849	RT	8.886	RT	Field Verified brophm1
			9/3/24	9/9/24	2.00	EA	Route W, Cape Girardeau County	9.031	RT	9.118	RT	Field Verified brophm1
			9/4/24	9/9/24	1.00	EA	Route W, Cape Girardeau County	501+49.36	RT	500+24.18	RT	Field Verified brophm1

The information	halaw this line or	dotaile for Conetre	ction Signs (if applicable)

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
983525	0100	August 15, 2024	332	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		0.1 N	Route CC	1.00	16.00			16.0
				GO20-2 48x24 8.00 END ROAD WORK		17.922	Route 91	1.00	8.00			8.0
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		17.936	Route 91	1.00	10.00			10.0
				WO8-12 48x48 16.00 NO CENTER LINE		18.165	Route 91	2.00	16.00			32.0
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		18.972	Route 91	1.00	12.00			12.0
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		9.978	Route P	1.00	16.00			16.0
				GO20-2 48x24 8.00 END ROAD WORK		4.715	Route C	1.00	8.00			8.0
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		4.721	Route C	1	10.00			10.0
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		4.804	Route C	1.00	12.00			12.0
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		83.588	US Route 61	1.00	16.00			16.0
				WO8-12 48x48 16.00 NO CENTER LINE		19.800, 20.959, 21.706, 23.299, 25.521, 26.966, 27.488	Route 91	12.00	16.00			192.0
		August 26, 2024	304	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		18.000 LT, 19.000 LT, 21.500 RT, 23.750 RT	Route 91	4.00	16.00			64.0
				GO20-4 36x18 4.50 PILOT CAR FOLLOW ME		22.140	Route 91	1.00	4.50			4.5
				WO20-7 48x48 16.00 FLAGGER (SYMBOL) WITH FLAGS		19.500 LT, 20.500 LT, 23.000 RT, 25.250 RT	Route 91	4.00	16.00			64.0
				WO3-4 8x48 16.00 BE PREPARED TO STOP		19.000 LT, 20.000 LT, 22.500 RT, 24.750 RT	Route 91	4.00	16.00			64.0
				GO20-4a 42x30 8.75 PLEASE WAIT FOR PILOT CAR		18.861 RT, 19.162 LT, 19.861 LT, 21.589 LT, 22.160 RT	Route 91	5.00	8.75			43.7
				WO20-4 48x48 16.00 ONE LANE ROAD AHEAD		18.500 LT, 19.500 LT, 22.000 RT, 24.250 RT	Route 91	4.00	16.00			64.0
	0100 - Total											636.2
9S3826	0470	August 20, 2024	252	GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		0.020, 9.327	Rt W	2.00	10.00			20.0
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		2.784 East, 2.981 East	Rt Y	2.00	16.00			32.0
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		2.461 East	Co Rd 620	1.00	16.00			16.0
				WO8-12 48x48 16.00 NO CENTER LINE		2.016, 2.167, 0.245, 4.340, 5.493, 8.160, 6.018, 3.912	Rt W	8.00	16.00			128.0
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		0.132, 9.327	Rt W	2.00	12.00			24.0
				GO20-2 48x24 8.00 END ROAD WORK		0.09, 9.564	Rt W	2.00	8.00			16.0
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		9.554	Rt W	1.00	16.00			16.0
	0470 - Total			·				,				25

Revision 3/23/2023 Page 15 of 23



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
525	0040	MISC. AGGREGATE FOR BASE	Material		3	Sep 3, 2024	SYSTEM	\$213,145.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Sep 3, 2024	SYSTEM	(\$213,145.92)	
					4	Sep 16, 2024	SYSTEM	\$213,145.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$213,145.92)	
				- Total				\$0.00	
			Material - Total					\$0.00	
			Overrun	Overrun	3	Sep 3, 2024	SYSTEM	(\$69,621.12)	
				Overrun - T	otal			(\$69,621.12)	
			Overrun - T	otal				(\$69,621.12)	
	0040 -	Total						(\$69,621.12)	
	0050	GRAVEL (A) OR CRUSHED STONE (B)	Material		3	Sep 3, 2024	SYSTEM	\$607.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Sep 3, 2024	SYSTEM	(\$607.50)	
					4	Sep 16, 2024	SYSTEM	\$607.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$607.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0050 -	Total						\$0.00	
	0060	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Material		2	Aug 16, 2024	SYSTEM	\$3,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brophm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Aug 16, 2024	SYSTEM	(\$3,680.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Material - To Other Item Adjustment	otal ACAD	2	Aug 16, 2024	brophm1	\$0.00 (\$46.20)	The Contractor selected AC adjustment on the contract. Refer to the document called "230616-H02 J9S3525 Estimate 0002 AC_Index_Price_Adjustment_Hot_Mix_Asphalt_Ton" on ePorjects for further information. brophm1
			Other Item		3		brophm1	(\$46.20)	document called "230616-H02 J9S3525 Estimate 0002 AC_Index_Price_Adjustment_Hot_Mix_Asphalt_Ton" on ePorjects for further
			Other Item Adjustment	ACAD - Total	3 al	2024 Sep 3,	·	(\$46.20)	document called "230616-H02 J9S3525 Estimate 0002 AC_Index_Price_Adjustment_Hot_Mix_Asphalt_Ton" on ePorjects for further information. brophm1
			Other Item Adjustment	ACAD	3 al	2024 Sep 3,	·	(\$46.20) (\$23,307.26)	document called "230616-H02 J9S3525 Estimate 0002 AC_Index_Price_Adjustment_Hot_Mix_Asphalt_Ton" on ePorjects for further information. brophm1
			Other Item Adjustment	ACAD - Total	3 al Total	2024 Sep 3,	·	(\$46.20) (\$23,307.26) (\$23,353.46)	document called "230616-H02 J9S3525 Estimate 0002 AC_Index_Price_Adjustment_Hot_Mix_Asphalt_Ton" on ePorjects for further information. brophm1
			Other Item Adjustment	ACAD - Tot ACJustment -	3 al Total	2024 Sep 3, 2024	plottk1	(\$46.20) (\$23,307.26) (\$23,353.46) (\$23,353.46)	document called "230616-H02 J9S3525 Estimate 0002 AC_Index_Price_Adjustment_Hot_Mix_Asphalt_Ton" on ePorjects for further information. brophm1 For 11,151.80 tons using SL24-11 mix with 4.4% AC
			Other Item Adjustment	ACAD - Tot Adjustment - Overrun	3 al Total	2024 Sep 3, 2024	plottk1	(\$46.20) (\$23,307.26) (\$23,353.46) (\$23,353.46) (\$45,875.43)	document called "230616-H02 J9S3525 Estimate 0002 AC_Index_Price_Adjustment_Hot_Mix_Asphalt_Ton" on ePorjects for further information. brophm1 For 11,151.80 tons using SL24-11 mix with 4.4% AC
			Other Item Adjustment Other Item Overrun	ACAD - Tot Adjustment - Overrun	3 al Total	2024 Sep 3, 2024	plottk1	(\$46.20) (\$23,307.26) (\$23,353.46) (\$23,353.46) (\$45,875.43)	document called "230616-H02 J9S3525 Estimate 0002 AC_Index_Price_Adjustment_Hot_Mix_Asphalt_Ton" on ePorjects for further information. brophm1 For 11,151.80 tons using SL24-11 mix with 4.4% AC
			Other Item Adjustment Other Item Overrun Overrun - T Price	ACAD - Tot Adjustment - Overrun	3 Total 3 otal	2024 Sep 3, 2024 Sep 3, 2024	plottk1	(\$46.20) (\$23,307.26) (\$23,353.46) (\$23,353.46) (\$45,875.43) (\$45,875.43)	document called "230616-H02 J9S3525 Estimate 0002 AC_Index_Price_Adjustment_Hot_Mix_Asphalt_Ton" on ePorjects for further information. brophm1 For 11,151.80 tons using SL24-11 mix with 4.4% AC Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			Other Item Adjustment Other Item Overrun Overrun - T Price	ACAD - Tot Adjustment - Overrun	3 Total 3 otal	2024 Sep 3, 2024 Sep 3, 2024 Aug 16, 2024 Sep 3,	plottk1 SYSTEM	(\$46.20) (\$23,307.26) (\$23,353.46) (\$23,353.46) (\$45,875.43) (\$45,875.43) (\$45,875.43) (\$0.40)	document called "230616-H02 J9S3525 Estimate 0002 AC_Index_Price_Adjustment_Hot_Mix_Asphalt_Ton" on ePorjects for further information. brophm1 For 11,151.80 tons using SL24-11 mix with 4.4% AC Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			Other Item Adjustment Other Item Overrun Overrun - T Price	ACAD - Tot. Adjustment - Overrun Overrun - T otal	3 Total 3 otal	2024 Sep 3, 2024 Sep 3, 2024 Aug 16, 2024 Sep 3,	plottk1 SYSTEM	(\$46.20) (\$23,307.26) (\$23,353.46) (\$23,353.46) (\$45,875.43) (\$45,875.43) (\$45,875.43) (\$0.40)	document called "230616-H02 J9S3525 Estimate 0002 AC_Index_Price_Adjustment_Hot_Mix_Asphalt_Ton" on ePorjects for further information. brophm1 For 11,151.80 tons using SL24-11 mix with 4.4% AC Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL
	0060 -	Total	Other Item Adjustment Other Item Overrun Overrun - T Price FUEL	ACAD - Tot. Adjustment - Overrun Overrun - T otal	3 Total 3 otal	2024 Sep 3, 2024 Sep 3, 2024 Aug 16, 2024 Sep 3,	plottk1 SYSTEM	(\$46.20) (\$23,307.26) (\$23,353.46) (\$23,353.46) (\$45,875.43) (\$45,875.43) (\$45,875.43) (\$111.47)	document called "230616-H02 J9S3525 Estimate 0002 AC_Index_Price_Adjustment_Hot_Mix_Asphalt_Ton" on ePorjects for further information. brophm1 For 11,151.80 tons using SL24-11 mix with 4.4% AC Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL
	0060 - 0070	Total TACK COAT	Other Item Adjustment Other Item Overrun Overrun - T Price FUEL	ACAD - Tot. Adjustment - Overrun Overrun - T otal	3 Total 3 otal	2024 Sep 3, 2024 Sep 3, 2024 Aug 16, 2024 Sep 3,	plottk1 SYSTEM	(\$46.20) (\$23,307.26) (\$23,353.46) (\$23,353.46) (\$45,875.43) (\$45,875.43) (\$45,875.43) (\$111.07) (\$111.47)	document called "230616-H02 J9S3525 Estimate 0002 AC_Index_Price_Adjustment_Hot_Mix_Asphalt_Ton" on ePorjects for further information. brophm1 For 11,151.80 tons using SL24-11 mix with 4.4% AC Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL



ect	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks	
525 (0070	TACK COAT		Туре				¢25 070 00	This adjustment effects the adjuing outtons appareted Material Demonstra	
525 (0070	TACK COAT	Material		3	Sep 3, 2024	SYSTEM	\$25,878.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brophm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					3	Sep 3, 2024	SYSTEM	(\$25,878.00)		
						Sep 16, 2024	SYSTEM	\$25,878.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brophm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					4	Sep 16, 2024	SYSTEM	(\$25,878.00)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0070 -	Total						\$0.00		
(0100	CONSTRUCTION SIGNS	Material		2	Aug 16, 2024	SYSTEM	\$2,075.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brophm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					2	Aug 16, 2024	SYSTEM	(\$2,075.00)		
					3	Sep 3, 2024	SYSTEM	\$3,975.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brophm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					3	Sep 3, 2024	SYSTEM	(\$3,975.00)		
						4	Sep 16, 2024	SYSTEM	\$3,975.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brophm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$3,975.00)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0100 -	Total						\$0.00		
	0130	CMS W/O COMMUNICATION INTERFACE,								
	0130	COMMUNICATION INTERFACE,	Material		2	Aug 16, 2024	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
	0130	COMMUNICATION	Material		2	Aug 16, 2024 Aug 16, 2024	SYSTEM SYSTEM	\$6,000.00 (\$6,000.00)	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment	
	0130	COMMUNICATION INTERFACE,	Material			2024 Aug 16,			Estimate Item Adjustment (0005) due to user brophm1 overridding Payment	
	0130	COMMUNICATION INTERFACE,	Material		2	2024 Aug 16, 2024 Sep 3,	SYSTEM	(\$6,000.00)	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment	
	0130	COMMUNICATION INTERFACE,	Material		3	2024 Aug 16, 2024 Sep 3, 2024 Sep 3,	SYSTEM	(\$6,000.00)	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment	
1	0130	COMMUNICATION INTERFACE,	Material		3	2024 Aug 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00)	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment	
	0130	COMMUNICATION INTERFACE,		- Total	3 3 4	2024 Aug 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00) \$6,000.00	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment	
		COMMUNICATION INTERFACE, CONT F/	Material - To		3 3 4	2024 Aug 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00) \$6,000.00 (\$6,000.00)	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment	
	0130	COMMUNICATION INTERFACE, CONT F/			3 3 4	2024 Aug 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00) \$6,000.00 (\$6,000.00)	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment	
(COMMUNICATION INTERFACE, CONT F/	Material - To		3 3 4	2024 Aug 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00) \$6,000.00 (\$6,000.00)	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment	
(0130 -	COMMUNICATION INTERFACE, CONT F/ Total PREF THERMO PVMT MARK, 24	Material - To		2 3 3 4	2024 Aug 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00) \$6,000.00 (\$6,000.00) \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brophm1 overridding Payment Estimate Item Adjustment (0015) due to user brophm1 overridding Payment Estimate Item Adjustment (0015) due to user brophm1 overridding Payment	
(0130 -	COMMUNICATION INTERFACE, CONT F/ Total PREF THERMO PVMT MARK, 24	Material - To		2 3 3 4 4	2024 Aug 16, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Sep 16, 2024 Sep 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00) \$6,000.00 (\$6,000.00) \$0.00 \$0.00 \$1,100.00	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brophm1 overridding Payment Estimate Item Adjustment (0015) due to user brophm1 overridding Payment Estimate Item Adjustment (0015) due to user brophm1 overridding Payment	
(0130 -	COMMUNICATION INTERFACE, CONT F/ Total PREF THERMO PVMT MARK, 24	Material - To	otal - Total	2 3 3 4 4	2024 Aug 16, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Sep 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00) \$6,000.00 \$0.00 \$0.00 \$1,100.00	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brophm1 overridding Payment Estimate Item Adjustment (0015) due to user brophm1 overridding Payment	
	0130 -	Total PREF THERMO PVMT MARK, 24 IN WHIT	Material - To	otal - Total	2 3 3 4 4	2024 Aug 16, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Sep 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00) \$6,000.00 \$0.00 \$0.00 \$1,100.00 \$0.00	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brophm1 overridding Payment Estimate Item Adjustment (0015) due to user brophm1 overridding Payment	
	0130 - 0150	Total PREF THERMO PVMT MARK, 24 IN WHIT	Material - To	otal - Total	2 3 3 4 4	2024 Aug 16, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Sep 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00) \$6,000.00 \$0.00 \$0.00 \$1,100.00 \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brophm1 overridding Payment Estimate Item Adjustment (0015) due to user brophm1 overridding Payment	
	0130 - 0150	Total PREF THERMO PVMT MARK, 24 IN WHIT	Material - To	otal - Total	2 3 4 4	2024 Aug 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Sep 16, 2024 Sep 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00) \$6,000.00 \$0.00 \$0.00 \$1,100.00) \$0.00 \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brophm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	



		5		011		0 1 1	0 1 1		0 1
ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
525	0160	PREF THERMO PVMT MARK, R/R XING	Material - To	otal				\$0.00	
	0160 -	0160 - Total						\$0.00	
	0170	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		4	Sep 16, 2024	SYSTEM	\$13,107.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brophm1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$13,107.51)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	OTHR	4	Sep 16, 2024	brophm1	(\$1,310.75)	Holding 10% until reflectivity has been performed. $(10\%)^*(100,087-ft)^*(\$0.13) = \$1,310.75$ 7,667 LF has not been paid and will be held until a determination is made in regard to paint being applied on asphalt that was paved over grass and is causing the paint to fall due to asphalt failing.
				OTHR - Tota	al			(\$1,310.75)	
			Other Item	Adjustment -	Total			(\$1,310.75)	
	0170 -	Total						(\$1,310.75)	
	0180	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		4	Sep 16, 2024	SYSTEM	\$4,128.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user brophm1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
		MARKING			4	Sep 16, 2024	SYSTEM	(\$4,128.80)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	OTHR		Sep 16, 2024	brophm1	(\$412.88)	Holding 10% until reflectivity has been performed. (10%)*(31760-ft)*(\$0.13) = -\$412.88
				OTHR - Tota				(\$412.88)	
			Other Item	Adjustment -	Total			(\$412.88)	
	0180 -	Total						(\$412.88)	
	0200	COLDMILLING BIT. PAVT FOR REM OF SURF.	Overrun	Overrun		Sep 3, 2024	SYSTEM	(\$4,058.52)	
				Overrun - Total				(\$4,058.52)	
			Overrun - T	otal				(\$4,058.52)	
	0200 -							(\$4,058.52)	
	0260	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Other Item Adjustment	STMC		Sep 16, 2024	brophm1	(\$834.00)	Closing Stockpile. Valtir, LLC Invoice Number HS789673
				STMC - Tota	al			(\$834.00)	
				STMI	1	Nov 1, 2023	brophm1	\$834.00	Initial Invoice Payment. Valtir, LLC Invoice Number HS789673
				STMI - Total				\$834.00	
			Other Item /	Adjustment -	Total			\$0.00	
	0260 - 0270	Total MGS BRIDGE	Other Item	STMC	4	Sep 16,	brophm1	\$0.00 (\$7,900.00)	Closing Stockpile. Valtir, LLC Invoice Number HS789673
		APP. TRANS SEC (EXT CURB)	Adjustment	STMC - Tota		2024		(\$7,900.00)	
				STMI		Nov 1,	brophm1	\$7,900.00	Initial Invoice Payment. Valtir, LLC Invoice Number HS789673
				STMI - Tota		2023	2.0pm.	\$7,900.00	
			Other Items					\$0.00	
	0270	Total	Other Item /	Adjustment -	TOLAI				
	0270 - 0280	TYPE A CRASHWORTHY	Material		4	Sep 16, 2024	SYSTEM	\$0.00 \$12,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user brophm1 overridding Payment
		END TERMINAL (MASH)			4	Sep 16, 2024	SYSTEM	(\$12,800.00)	Estimate Exception 9 on the current Payment Estimate.
				- Total		2024		\$0.00	
			Material - To					\$0.00	
			material - I	Jai					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3525	0280	TYPE A CRASHWORTHY END TERMINAL	Other Item Adjustment	STMC		Sep 16, 2024	brophm1	(\$7,500.00)	Closing Stockpile. Valtir, LLC Invoice Number HS789673
		(MASH)		STMC - Tota	al			(\$7,500.00)	
				STMI		Nov 1, 2023	brophm1	\$7,500.00	Initial Invoice Payment. Valtir, LLC Invoice Number HS789673
				STMI - Total			\$7,500.00		
			Other Item /	Adjustment -	Total			\$0.00	
	0280 -	Total						\$0.00	
	0290	TYPE C CRASHWORTHY END TERMINAL	Other Item Adjustment	STMI	1	Nov 1, 2023	brophm1	\$216,102.00	Initial Invoice Payment. The Hoosier Company Invoice Number 15403
		(MASH)		STMI - Total				\$216,102.00	
			Other Item /	Adjustment -	Total			\$216,102.00	
	0290 -	Total						\$216,102.00	
J9S3525 -	- Total							\$71,358.37	
J9S3826	0370	LINEAR GRADING CLASS 1	Overrun	Overrun	4	Sep 16, 2024	SYSTEM	(\$712.00)	
				Overrun - To	otal			(\$712.00)	
			Overrun - To	otal				(\$712.00)	
	0370 -	Total						(\$712.00)	
	0380	MISC. SHAPING SLOPES	Material		3	Sep 3, 2024	SYSTEM	\$10,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brophm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Sep 3, 2024	SYSTEM	(\$10,080.00)	
					4	Sep 16, 2024	SYSTEM	\$16,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user brophm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$16,800.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0380 -	Total	otal						
	0410		Material		4	Sep 16, 2024	SYSTEM	\$974,568.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brophm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$974,568.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	ACAD	4	Sep 16, 2024	brophm1	(\$38,190.88)	For 12,182.1 tons using SL24-11 mix with 4.4% AC
				ACAD - Tota	al			(\$38,190.88)	
			Other Item /	Adjustment -	Total			(\$38,190.88)	
			Price FUEL		4	Sep 16, 2024	SYSTEM	(\$4,812.91)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				(\$4,812.91)	
			Price FUEL	- Total				(\$4,812.91)	
	0410 -	Total						(\$43,003.79)	
	0420	TACK COAT	Material		4	Sep 16, 2024	SYSTEM	\$29,082.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user brophm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$29,082.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0420 -	Total						\$0.00	
	0450	FURNISHING TYPE 1 ROCK BLANKET	Material		3	Sep 3, 2024	SYSTEM	\$20,608.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brophm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3826	0450	FURNISHING TYPE 1 ROCK	Material		3	Sep 3, 2024	SYSTEM	(\$20,608.00)	
		BLANKET			4	Sep 16, 2024	SYSTEM	\$24,702.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$24,702.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	4	Sep 16, 2024	SYSTEM	(\$4,094.00)	
				Overrun - T	otal			(\$4,094.00)	
			Overrun - T	otal				(\$4,094.00)	
	0450 -	Total						(\$4,094.00)	
	0460	PLACING TYPE 1 ROCK BLANKET	Overrun	Overrun	4	Sep 16, 2024	SYSTEM	(\$2,848.00)	
				Overrun - T	otal			(\$2,848.00)	
			Overrun - T	otal				(\$2,848.00)	
	0460 -	Total						(\$2,848.00)	
	0470	CONSTRUCTION SIGNS	Material		3	Sep 3, 2024	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user brophm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					3	Sep 3, 2024	SYSTEM	(\$1,575.00)	
					4	Sep 16, 2024	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user brophm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$1,575.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0470 -	Total						\$0.00	
	0520	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material		3	Sep 3, 2024	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user brophm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				3	Sep 3, 2024	SYSTEM	(\$6,000.00)		
					4	Sep 16, 2024	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user brophm1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$6,000.00)	
				- Total			\$0.00		
			Material - To	otal				\$0.00	
	0520 -	Total						\$0.00	
	0710	COLDMILLING BIT. PAVT FOR	Overrun	Overrun	4	Sep 16, 2024	SYSTEM	(\$14,257.75)	
		REM OF SURF.		Overrun - T	otal			(\$14,257.75)	
			Overrun - T	otal				(\$14,257.75)	
	0710 -	Total						(\$14,257.75)	
	0730	PERMANENT EROSION CONTROL	Material		3	Sep 3, 2024	SYSTEM	\$4,433.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user brophm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
		GEOTEXTILE			3	Sep 3, 2024	SYSTEM	(\$4,433.30)	
					4	Sep 16, 2024	SYSTEM	\$5,005.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user brophm1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$5,005.20)	
				- Total				\$0.00	
									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J9S3826	0730	PERMANENT	Material - To					\$0.00			
		EROSION CONTROL GEOTEXTILE	Overrun	Overrun	4	Sep 16, 2024	SYSTEM	(\$571.90)			
				Overrun - To	otal			(\$571.90)			
			Overrun - T	otal				(\$571.90)			
	0730 -	Total						(\$571.90)			
	0800	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Other Item Adjustment	STMC	4	Sep 16, 2024	brophm1	(\$22,935.00)	Closing Stockpile. Valtir, LLC Invoice Number HS789673		
		113114		STMC - Tota	ıl		(\$22,935.00)				
				STMI	1	Nov 1, 2023	brophm1	\$22,935.00	Initial Invoice Payment. Valtir, LLC Invoice Number HS789673		
				STMI - Total				\$22,935.00			
			Other Item	Adjustment -	Total			\$0.00			
	0800 -	Total						\$0.00			
	0810	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Other Item Adjustment	STMC		Sep 16, 2024	brophm1	(\$15,120.00)	Closing Stockpile. Valtir, LLC Invoice Number HS789673		
		,		STMC - Tota				(\$15,120.00)			
				STMI		Nov 1, 2023	brophm1	\$15,120.00	Initial Invoice Payment. Valtir, LLC Invoice Number HS789673		
				STMI - Total				\$15,120.00			
			Other Item	Adjustment -	Total			\$0.00			
	0810 -						0)/0==1/	\$0.00			
	0820	MGS END ANCHOR	Material		3	Sep 3, 2024	SYSTEM	\$6,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user brophm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
					3	Sep 3, 2024	SYSTEM	(\$6,400.00)			
							4	Sep 16, 2024	SYSTEM	\$6,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user brophm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$6,400.00)			
				- Total				\$0.00			
			Material - T	otal				\$0.00			
			Other Item Adjustment	STMC		Sep 16, 2024	brophm1	(\$2,620.00)	Closing out stockpile. Valtir, LLC Invoice Number HS789673		
				STMC - Tota				(\$2,620.00)			
				STMI	1	Nov 1, 2023	brophm1	\$2,620.00	Initial Invoice Payment. Valtir, LLC Invoice Number HS789673		
				STMI - Total				\$2,620.00			
			Other Item	Adjustment -	Total			\$0.00			
	0820 -	Total						\$0.00			
	0830	TYPE A CRASHWORTHY END TERMINAL	Material		3	Sep 3, 2024	SYSTEM	\$28,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user brophm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
		(MASH)			3	Sep 3, 2024	SYSTEM	(\$28,800.00)	·		
					4	Sep 16, 2024	SYSTEM	\$48,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user brophm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.		
					4	Sep 16, 2024	SYSTEM	(\$48,000.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
			Other Item Adjustment	STMC	4	Sep 16, 2024	brophm1	(\$22,500.00)	Closing out stockpile. Valtir, LLC Invoice Number HS789673		
				STMC - Tota	al			(\$22,500.00)			
				STMI	1	Nov 1,	brophm1	\$22,500.00	Initial Invoice Payment. Valtir, LLC Invoice Number HS789673		
						2023					

Sep 18, 2024



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3826	0830	TYPE A CRASHWORTHY END TERMINAL	Other Item Adjustment					\$22,500.00	
		(MASH)	Other Item Adjustment - Total					\$0.00	
	0830 -	Total						\$0.00	
J9S3826	J9S3826 - Total								
Overall - Total								\$5,870.93	

MoDOT

Contract Adjustments for Contract - 230616-H02

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 23 of 23