

## Pay Estimate Created Date: August 16, 2024

Progress Estimate N 11	umber	Contract ID Prime Contractor	230818-B02 Emery Sapp & So	ons, Inc.	Pay Period Start Pay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	\$2,670,937.40 \$0.00 \$2,670,937.40	
Approval Date								By User	
August 16, 2024			Generated and	Approved	(and should be co	nsidered Draft) a	t the Project Office Level by	burtoc4	
August 16, 2024		Resident Engineer Level by	vierss						
August 19, 2024	Reviewed and Approved at the Central Office Controllers Office Leve								
Original Completion	n Date	Current Cor	npletion Date	Act	ual Completion Da	ate %	6 of Current Contract Amount	t Complete	
October 1, 2024	1	Octobe	r 1, 2024				94.53%		
	Contrac	t Informational Dat	tes		Miles	tones			
Date Description	Original	Completion Date	Current Complet	ion Date	No Milestones E	xist for Contract			
Acceptance Date									
Awarded Date	Septemb	per 7, 2023	September 7, 202	3					
Letting Date	August 1	18, 2023	August 18, 2023						
Notice to Proceed Date	October	9, 2023	October 9, 2023						
Open to Traffic Date									
Work Began Date									

Contract Total Pay	/ For Estimate No. 11				
		This Estimate	Previous	To Date	
230818-B02					
	Total Posted Items Pay	\$366,764.05	\$2,157,966.30	\$2,524,730.35	
	Gross Item Adjustments	\$0.00	(\$12,297.95)	(\$12,297.95)	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	(\$40,000.00)	(\$40,000.00)	
	-		\$2,105,668.35	\$2,472,432.40	
Contract Total Pay	able This Estimate:	\$366,764.05			

## Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J2S3448	0050	2037075	COMPACTING IN CUT	STA	\$445.000	28.2	\$12,549.00
	0120	3105003	GRAVEL (A) OR CRUSHED STONE (B)	SQYD	\$14.500	358.4	\$5,196.80
	0130	6085008	PAVED APPROACH, 8 IN.	SQYD	\$89.000	140.2	\$12,477.80
	0140	6097000	ROCK LINING	CUYD	\$106.000	12	\$1,272.00
	0190	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	EA	\$600.000	1	\$600.0
	0440	5021333	CONCRETE PAVEMENT (9 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	SQYD	\$81.000	4,080.45	\$330,516.4
	0450	9031270A	2 IN. PSST POST - 12 GA.	LF	\$36.000	64	\$2,304.0
	0460	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	EA	\$300.000	4	\$1,200.0
	0470	9035004A	SH-FLAT SHEET	SQFT	\$48.000	13.5	\$648.00
Project J2S3	448 - Total						\$366,764.0
Overall - Tot	al						\$366,764.0

Contract Adjustments This Estimate

# No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2S3448	0120	GRAVEL (A) OR CRUSHED STONE (B)	Material			-1,575	\$14.50	(\$22,837.50)
	0120	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	1,575	\$14.50	\$22,837.50



## Pay Estimate Created Date: August 16, 2024

Progr			Contract ID Prime Conti	23081 ractor Emery		s, Inc. Pay Period End August 15, 2024 Ne	iginal Contrac t Change Orde rrent Contract	er Amount	\$2,670,937.40 \$0.00 \$2,670,937.40	
Project Number	Line No.	Item Descri	ption	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
2S3448						Adjustment (0001) due to user burtoc- overridding Payment Estimate Exception 1 o the current Payment Estimate	n			
	0130	PAVED APPRO	DACH, 8 IN.	Material			-140.2	\$89.00	(\$12,477.80	
	0130	PAVED APPRO	DACH, 8 IN.	Material		This adjustment offsets the original system generated Material Payment Estimate Iten Adjustment (0002) due to user burtoc overridding Payment Estimate Exception 5 or the current Payment Estimate	n 4 n	\$89.00	\$12,477.80	
	0140	RO	CK LINING	Material			-12	\$106.00	(\$1,272.00	
	0140	RO	OCK LINING	Material		This adjustment offsets the original system generated Material Payment Estimate Iten Adjustment (0003) due to user burtoco overridding Payment Estimate Exception 7 or the current Payment Estimate	n 4 n	\$106.00	\$1,272.00	
	0280	15 IN. OR SUBSTITUTE FLARED ENI		Material			-4	\$465.00	(\$1,860.00)	
	0280	15 IN. OR SUBSTITUTE FLARED ENE		Material		This adjustment offsets the original system generated Material Payment Estimate Iten Adjustment (0004) due to user burtoco overridding Payment Estimate Exception 9 or the current Payment Estimate	n 4 n	\$465.00	\$1,860.00	
	0290	18 IN. OR SUBSTITUTE FLARED END		Material			-4	\$525.00	(\$2,100.00)	
	0290	18 IN. OR SUBSTITUTE FLARED ENE		Material		This adjustment offsets the original system generated Material Payment Estimate Iten Adjustment (0005) due to user burtoc overridding Payment Estimate Exception 10 on the current Payment Estimate	n 4 0	\$525.00	\$2,100.00	
	0300	15 IN. OR SUBSTITUTE FLARED END		Material			-6	\$465.00	(\$2,790.00	
	0300	15 IN. OR SUBSTITUTE FLARED ENE		Material		This adjustment offsets the original system generated Material Payment Estimate Iten Adjustment (0006) due to user burtoco overridding Payment Estimate Exception 1 on the current Payment Estimate	n 4 1	\$465.00	\$2,790.00	
	0440	CONCRETE PA 1/2 IN. NON-REII 15 F		Material			-8,160.9	\$81.00	(\$661,032.90	
	0440	CONCRETE PA 1/2 IN. NON-REII 15 F		Material		This adjustment offsets the original system generated Material Payment Estimate Iten Adjustment (0007) due to user burtoco overridding Payment Estimate Exception 2 of the current Payment Estimate	n 4 n	\$81.00	\$661,032.90	
	0450	2 IN. PSST PO	ST - 12 GA.	Material			-64	\$36.00	(\$2,304.00)	
	0450	2 IN. PSST PO	ST - 12 GA.	Material		This adjustment offsets the original system generated Material Payment Estimate Iten Adjustment (0008) due to user burtoc overridding Payment Estimate Exception 12 on the current Payment Estimate	n 4 2	\$36.00	\$2,304.00	
	0460	DRIVEN POS FOR 2 IN. PS		Material			-4	\$300.00	(\$1,200.00	
	0460	DRIVEN POS FOR 2 IN. PS		Material		This adjustment offsets the original system generated Material Payment Estimate Iten Adjustment (0009) due to user burtoc overridding Payment Estimate Exception 13 on the current Payment Estimate	n 4 3	\$300.00	\$1,200.00	



## Pay Estimate Created Date: August 16, 2024

Progre		imate Number I1	Contract ID Prime Contr	23081 ractor Emery		Pay Period Start August 2, 2024 Orig   s, Inc. Pay Period End August 15, 2024 Net   Curr Curr Curr Curr		er Amount	\$2,670,937.40 \$0.00 \$2,670,937.40
Project Number	Line No.	Item Desc	ription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2S3448	0470	SH-F	LAT SHEET	Material			-13.5	\$48.00	(\$648.00)
	0470	SH-F	LAT SHEET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user burtoc4 overridding Payment Estimate Exception 14 on the current Payment Estimate.	13.5	\$48.00	\$648.00
Total									\$0.00



# Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J2S3448	FAS S202(59)	Slide repair, grading and pavement	3	RANDOLPH	from 0.2 mile south of 0	County Road 2130 to Sweet	Spring Creek
Totals by J	Job Numbe	rs					
J2S3448		d Item Pay Item Adjustm		item Pay	This Estimate \$366,764.05 \$0.00 <b>\$366,764.05</b>	Previous \$2,157,966.30 (\$12,297.95) <b>\$2,145,668.35</b>	To Date \$2,524,730.35 (\$12,297.95) <b>\$2,512,432.40</b>
	Liquid	tive centive lated Damages Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 (\$40,000.00)	\$0.00 \$0.00 \$0.00 (\$40,000.00)



# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

# Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J2S3448, Item 3105003, Project Item Line Number 0120, Material Set 310500396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3448, Item 5021333, Project Item Line Number 0440, Material Set 502133396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3448, Item 5021333, Project Item Line Number 0440, Material Set 502133396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3448, Item 5021333, Project Item Line Number 0440, Material Set 502133396, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3448, Item 6085008, Project Item Line Number 0130, Material Set 608500896, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3448, Item 6085008, Project Item Line Number 0130, Material Set 608500896, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3448, Item 6097000, Project Item Line Number 0140, Material Set 609700096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3448, Item 7250415, Project Item Line Number 0270, Material Set 725041596, Material 1020CPCSZC.015 - CulvPipe Zn Ctd Corrug Stl 15" 375mm, Acceptance Action Generic 1020CPCSZC.015 is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3448, Item 7320015A, Project Item Line Number 0280, Material Set 7320015A96, Material 1020ESAC - Flared End Section Aluminum coated steel, Acceptance Action Generic 1020ESAC is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3448, Item 7320018A, Project Item Line Number 0290, Material Set 7320018A96, Material 1020ESAC - Flared End Section Aluminum coated steel, Acceptance Action Generic 1020ESAC is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3448, Item 7320815A, Project Item Line Number 0300, Material Set 7320815A96, Material 1020ESZN - Flared End Section Zinc galvanized steel, Acceptance Action Generic 1020ESZN is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3448, Item 9031270A, Project Item Line Number 0450, Material Set 9031270A96, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3448, Item 9031271A, Project Item Line Number 0460, Material Set 9031271A, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3448, Item 9035004A, Project Item Line Number 0470, Material Set 9035004A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Item Overrun: Contract 230818-B02, Contract Project J2S3448, Project Item Line Number 0280, Contract Line Item Number 0280, Item 7320015A, Minor Item.	No Remark was entered by Engineer	burtoc4	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230818-B02, Contract Project J2S3448, Project Item Line Number 0060, Contract Line Item Number 0060, Item 2063000, Minor Item.	No Remark was entered by Engineer	burtoc4	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230818-B02, Contract Project J2S3448, Project Item Line Number 0220, Contract Line Item Number 0220, Item 6240104A, Minor Item.	No Remark was entered by Engineer	burtoc4	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230818-B02, Contract Project J2S3448, Project Item Line Number 0250, Contract Line Item Number 0250, Item 7250315A, Minor Item.	No Remark was entered by Engineer	burtoc4	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230818-B02, Contract Project J2S3448, Project Item Line Number 0360, Contract Line Item Number 0360, Item 8061010A, Minor Item.	No Remark was entered by Engineer	burtoc4	Acknowledged



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

## Total Paid / All Items / All Estimates (Including this Estimate)

and can differ from the posted amount at the time the Estimate was Generated ater

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted am Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
30818-B02	J2S3448	0001	0010	2013000	CLEARING AND GRUBBING	3.00	0.00	3.00	ACRE	3.00	\$8,250.00	\$24,750.0
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$29,500.00	\$29,500.0
		0001	0030	2035000	UNCLASSIFIED EXCAVATION	113,970.00	0.00	113,970.00	CUYD	111,230.00	\$5.10	\$567,273.0
		0001	0040	2036000	COMPACTING EMBANKMENT	13,062.00	0.00	13,062.00	CUYD	11,865.00	\$2.50	\$29,662.5
		0001	0050	2037075	COMPACTING IN CUT	28.20	0.00	28.20	STA	28.20	\$445.00	\$12,549.0
		0001	0060	2063000	CLASS 3 EXCAVATION	86.00	0.00	86.00	CUYD	126.00	\$5.60	\$705.6
		0001	0070	2071000	LINEAR GRADING CLASS 1	2.60	0.00	2.60	STA	2.60	\$1,015.00	\$2,639.0
		0001	0080	2072000	LINEAR GRADING CLASS 2	1.70	0.00	1.70	STA	1.70	\$8,850.00	\$15,045.0
		0001	0090	2142000	FURNISHING ROCK FILL	18,451.00	0.00	18,451.00	CUYD	18,116.00	\$35.00	\$634,060.0
		0001	0100	2143000	PLACING ROCK FILL	18,451.00	0.00	18,451.00	CUYD	18,116.00	\$2.20	\$39,855.2
		0001	0110	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	8,161.00	0.00	8,161.00	SQYD	8,161.00	\$13.85	\$113,029.8
		0001	0120	3105003	GRAVEL (A) OR CRUSHED STONE (B)	1,634.40	0.00	1,634.40	SQYD	1,575.00	\$14.50	\$22,837.5
		0001	0130	6085008	PAVED APPROACH, 8 IN.	140.20	0.00	140.20	SQYD	140.20	\$89.00	\$12,477.8
		0001	0140	6097000	ROCK LINING	12.00	0.00	12.00	CUYD	12.00	\$106.00	\$1,272.0
		0001	0150	6161005	CONSTRUCTION SIGNS	134.00	0.00	134.00	SQFT	134.00	\$15.00	\$2,010.0
		0001	0160	6161025	CHANNELIZER (TRIM LINE)	50.00	0.00	50.00	EA	50.00	\$24.00	\$1,200.0
		0001	0170	6161030	TYPE III MOVEABLE BARRICADE	8.00	0.00	8.00	EA	8.00	\$165.00	\$1,320.0
		0001	0180	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$235,000.00	\$235,000.0
		0001	0190	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	1.00	\$600.00	\$600.0
		0001	0200	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	5,941.00	0.00	5,941.00	LF	0.00	\$0.50	\$0.0
		0001	0210	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	4,915.00	0.00	4,915.00	LF	0.00	\$0.50	\$0.0
		0001	0220	6240104A	SEPARATION GEOTEXTILE	7,169.00	0.00	7,169.00	SQYD	8,400.00	\$3.65	\$30,660.0
		0001	0230	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	41.50	0.00	41.50	STA	0.00	\$300.00	\$0.0
		0001	0240	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$18,500.00	\$18,500.0
		0001	0250	7250315A	15 IN. PIPE GROUP B	45.00	0.00	45.00	LF	139.00	\$67.00	\$9,313.0
		0001	0260	7250318A	18 IN. PIPE GROUP B	162.00	0.00	162.00	LF	162.00	\$63.00	\$10,206.0
		0001	0270	7250415	15 IN. PIPE GROUP C	206.00	0.00	206.00	LF	206.00	\$48.00	\$9,888.0
		0001	0280	7320015A	15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	2.00	0.00	2.00	EA	4.00	\$465.00	\$1,860.0
		0001	0290	7320018A	18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	4.00	0.00	4.00	EA	4.00	\$525.00	\$2,100.0
		0001	0300	7320815A	15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	6.00	0.00	6.00	EA	6.00	\$465.00	\$2,790.0
		0001	0310	8025006	MULCHING	10.70	0.00	10.70	ACRE	0.00	\$1,550.00	\$0.0
		0001	0320	8051000A	SEEDING - COOL SEASON GRASSES	6.10	0.00	6.10	ACRE	3.00	\$2,375.00	\$7,125.0
		0001	0330	8061003	SEDIMENT TRAP EXCAVATION	5.50	0.00	5.50	CUYD	0.00	\$35.00	\$0.0
		0001	0340	8061004	SEDIMENT TRAP ROCK	7.40	0.00	7.40	CUYD	0.00	\$55.00	\$0.0
		0001	0350	8061005	ROCK DITCH CHECK	3,855.00	0.00	3,855.00	LF	984.00	\$12.00	\$11,808.0
		0001	0360	8061010A	TYPE B BERM	404.00	0.00	404.00	LF	530.00	\$2.80	\$1,484.0
		0001	0370	8061011	SLOPE DRAINS	312.00	0.00	312.00	LF	0.00	\$35.00	\$0.0
		0001	0380	8061016	SEDIMENT REMOVAL	312.00	0.00	312.00	CUYD	85.00	\$17.00	\$1,445.0
		0001	0390	8061017	TEMPORARY SEEDING	4.60	0.00	4.60	ACRE	0.00	\$1,650.00	\$0.0
		0001	0400	8061019	SILT FENCE	4,474.00	0.00	4,474.00	LF	2,350.00	\$2.80	\$6,580.0
		0001	0410	8061050	TYPE C BERM	367.00	0.00	367.00	LF	0.00	\$38.00	\$0.0
		0001	0420	8064138	TYPE 2D EROSION CONTROL BLANKET	3,626.00	0.00	3,626.00	SQYD	0.00	\$2.00	\$0.0
		0003	0440	5021333	CONCRETE PAVEMENT (9 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	8,160.90	0.00	8,160.90	SQYD	8,160.90	\$81.00	\$661,032.9
		0040	0450	9031270A	2 IN. PSST POST - 12 GA.	64.00	0.00	64.00	LF	64.00	\$36.00	\$2,304.0
		0040	0460	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	4.00	0.00	4.00	EA	4.00	\$300.00	\$1,200.0



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230818-B02	J2S3448	0040	0470	9035004A	SH-FLAT SHEET	14.00	0.00	14.00	SQFT	13.50	\$48.00	\$648.00
	Project J2	2S3448 - To	otal Value	Posted to D	e as of Report Generated Date							\$2,524,730.35
230818-B02 Ove	rall - Total	Value Post	ed to Dat	e as of Repo	ort Generated Date							\$2,524,730.35



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail. location and quantity of work.

Project: J2S3448 DWR DWR Approval Date DWR To Offset/ Station/ Distance Log Mile From Offset/ Station/ Distance Log Mile Line Item Number Code Description Location Comments 0050 2037075 COMPACTING IN CUT 8/12/24 8/16/24 28.20 STA Throughout the project including the roadbed and ditches. 93+00.05 121+24.94 0120 3105003 GRAVEL (A) OR CRUSHED STONE (B) 8/9/24 8/16/24 180.10 SQYD Quarry entrance on the east side of Highway 3. 99+05.00 98+29 8/12/24 8/16/24 178.30 SQYD Capital lot entrance on the west side of Highway 3. 98+32.00 99+09.00 0130 6085008 PAVED APPROACH 8 IN 8/8/24 8/16/24 140.20 SQYD North quarry drive on east side of Highway 3. 94+00.00 94+90.00 0140 6097000 ROCK LINING 8/14/24 8/16/24 2.00 CUYD On County Road 2040 for the Capital Drive. 0+68 8/16/24 2.00 CUYD On the east side of Highway 3. 113+81 2.00 CUYD On the east side of Highway 3. 8/16/24 99+16 8/16/24 2.00 CUYD On the west side of Highway 3. 93+93 8/16/24 2.00 CUYD On the west side of Highway 3. 99+21 8/16/24 2.00 CUYD West side of Highway 3 south of County Road 2040 0+38 6181020 ADDITIONAL MOBILIZATION FOR SEEDING 8/13/24 8/16/24 91+00 122+00 0190 1.00 EA 0440 5021333 CONCRETE PAVEMENT (9.1/2 IN NON-REINE 8/6/24 8/16/24 1,987.10 SQYD The northbound lane of Highway 3. 121+24.94 107+45 8/7/24 8/16/24 2,093.35 SQYD Northbound lane of Highway 3. 107+45 93+00.05 0450 9031270A 2 IN. PSST POST - 12 GA. 8/14/24 8/16/24 16.00 LF No Parking sign on the east side of Highway 3. 93+77 8/16/24 16.00 LF No Parking sign on the east side of Highway 3. 95+64 8/16/24 16.00 LF No Parking sign on the west side of Highway 3. 95+66 8/16/24 16.00 LF Stop sign at County Road 2040 106+20 0460 9031271A DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. 8/14/24 8/16/24 EA No Parking sign on the east side of Highway 3. 93+77 1.00 8/16/24 EA No Parking sign on the east side of Highway 3. 1.00 95+64 8/16/24 1.00 EA No Parking sign on the west side of Highway 3. 95+66 8/16/24 1.00 EA Stop sign at County Road 2040 106+20 0470 9035004A SH-FLAT SHEET 8/14/24 8/16/24 1.50 SQFT No Parking sign on the east side of Highway 3. 93+77 8/16/24 1.50 SQFT No Parking sign on the east side of Highway 3. 95+64 8/16/24 1.50 SQFT No Parking sign on the west side of Highway 3. 95+66 8/16/24 9.00 SQFT Stop sign at County Road 2040 106+20

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2S3448	0040	COMPACTING EMBANKMENT	Material		2	Mar 4, 2024	SYSTEM	\$14,377.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burtoc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Mar 4, 2024	SYSTEM	(\$14,377.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	MDPA	2	Mar 4, 2024	burtoc4	(\$10,000.00)	Money withheld pending test results for Compacting Embankment.
					3	Mar 15, 2024	burtoc4	\$10,000.00	\$10,000 withheld on Estimate 2 pending test results. Test results received, adjustment made to offset the previous adjustment.
				MDPA - Tot	al			\$0.00	
			Other Item	Adjustment -				\$0.00	
	0040 -	Total						\$0.00	
	0060	CLASS 3	Overrun	Overrun	9	Jul 16,	SYSTEM	(\$224.00)	
	0000	EXCAVATION	ovoliuli	ovenun	0	2024	OTOTEM	(\$224.00)	
				Overrun - T	otal			(\$224.00)	
			Overrun - T	otal				(\$224.00)	
	0060 -	Total						(\$224.00)	
	0090	FURNISHING ROCK FILL	Material		7	Jun 17, 2024	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burtoc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jun 17, 2024	SYSTEM	(\$3,500.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0090 -	Total						\$0.00	
	0110	TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		10	Aug 2, 2024	SYSTEM	\$113,029.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vierss overridding Payment Estimate Exception 2 on the current Payment Estimate.
		THICK)			10	Aug 2, 2024	SYSTEM	(\$113,029.85)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0110 -	Total						\$0.00	
	0120	GRAVEL (A) OR CRUSHED STONE (B)	Material		10	Aug 2, 2024	SYSTEM	\$17,640.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Aug 2, 2024	SYSTEM	(\$17,640.70)	
					11	Aug 16, 2024	SYSTEM	\$22,837.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burtoc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Aug 16, 2024	SYSTEM	(\$22,837.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0120 -	Total						\$0.00	
	0130	PAVED APPROACH, 8 IN.	Material		11	Aug 16, 2024	SYSTEM	\$12,477.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burtoc4 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Aug 16, 2024	SYSTEM	(\$12,477.80)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0130 -	Total						\$0.00	
	0140	ROCK LINING	Material		11	Aug 16, 2024	SYSTEM	\$1,272.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user burtoc4 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Aug 16,	SYSTEM	(\$1,272.00)	Examples Exception 7 on the outrent r ayment Estimate.



Aug 20, 2024

ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
48	0140	ROCK LINING	Material			2024											
				- Total				\$0.00									
			Material - To	otal				\$0.00									
	0140 -	Total						\$0.00									
	0150	CONSTRUCTION SIGNS	Material		8	Jul 1, 2024	SYSTEM	\$2,010.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burtoc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					8	Jul 1, 2024	SYSTEM	(\$2,010.00)									
					9	Jul 16, 2024	SYSTEM	\$2,010.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user burtoc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					9	Jul 16, 2024	SYSTEM	(\$2,010.00)									
					10	Aug 2, 2024	SYSTEM	\$2,010.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vierss overridding Payment Estimate Exception 7 on the current Payment Estimate.								
					10	Aug 2, 2024	SYSTEM	(\$2,010.00)									
				- Total				\$0.00									
			Material - To	otal				\$0.00									
	0150 -	Total						\$0.00									
	0160	CHANNELIZER I (TRIM LINE)	Material		8	Jul 1, 2024	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user burtoc4 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					8	Jul 1, 2024	SYSTEM	(\$1,200.00)									
					9	Jul 16, 2024	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user burtoc4 overridding Paymen Estimate Exception 2 on the current Payment Estimate.								
					9	Jul 16, 2024	SYSTEM	(\$1,200.00)									
													10	Aug 2, 2024	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vierss overridding Payment Estimate Exception 8 on the current Payment Estimate.
					10	Aug 2, 2024	SYSTEM	(\$1,200.00)									
				- Total				\$0.00									
			Material - To	otal				\$0.00									
	0160 -	Total						\$0.00									
	0170	TYPE III MOVEABLE BARRICADE	Material		8	Jul 1, 2024	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user burtoc4 overridding Paymen Estimate Exception 3 on the current Payment Estimate.								
					8	Jul 1, 2024	SYSTEM	(\$1,320.00)									
					9	Jul 16, 2024	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user burtoc4 overridding Paymen Estimate Exception 3 on the current Payment Estimate.								
					9	Jul 16, 2024	SYSTEM	(\$1,320.00)									
					10	Aug 2, 2024	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vierss overridding Payment Estimate Exception 9 on the current Payment Estimate.								
					10	Aug 2, 2024	SYSTEM	(\$1,320.00)									
				- Total				\$0.00									
			Material - To	otal				\$0.00									
	0170 -	Total						\$0.00									
		SEPARATION	Material		6	Jun 3, 2024	SYSTEM	\$10,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burtoc4 overridding Payment								
	0220	GEOTEXTILE				2024			Estimate Exception 1 on the current Payment Estimate.								



Aug 20, 2024

J2S3448 0220	CEDADATION		Туре	Number	Date	Ву		
	SEPARATION	Material	- Total				\$0.00	
	GEOTEXTILE	Material - Total					\$0.00	
		Overrun	Overrun	8	Jul 1, 2024	SYSTEM	(\$4,493.15)	
			Overrun - T	otal			(\$4,493.15)	
		Overrun - Total					(\$4,493.15)	
0220	- Total						(\$4,493.15)	
0250	15 IN. PIPE CULVERT	Overrun	Overrun	9	Jul 16, 2024	SYSTEM	(\$6,298.00)	
	GROUP B		Overrun - Total				(\$6,298.00)	
		Overrun - Total					(\$6,298.00)	
0250	- Total						(\$6,298.00)	
0270	15 IN. PIPE CULVERT GROUP C	Material		9	Jul 16, 2024	SYSTEM	\$9,888.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user burtoc4 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				9	Jul 16, 2024	SYSTEM	(\$9,888.00)	
			- Total				\$0.00	
		Material - T	otal				\$0.00	
0270	- Total						\$0.00	
0280	15 IN. GROUP B FLARED END SEC	Material		9	Jul 16, 2024	SYSTEM	\$1,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user burtoc4 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				9	Jul 16, 2024	SYSTEM	(\$1,860.00)	
				10	Aug 2, 2024	SYSTEM	\$1,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vierss overridding Payment Estimate Exception 11 on the current Payment Estimate.
				10	Aug 2, 2024	SYSTEM	(\$1,860.00)	
				11	Aug 16, 2024	SYSTEM	\$1,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user burtoc4 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				11	Aug 16, 2024	SYSTEM	(\$1,860.00)	
			- Total				\$0.00	
		Material - T	otal				\$0.00	
		Overrun	Overrun	9	Jul 16, 2024	SYSTEM	(\$930.00)	
			Overrun - Total				(\$930.00)	
		Overrun - Total					(\$930.00)	
0280	- Total						(\$930.00)	
0290	18 IN. GROUP B FLARED END SEC	Material		9	Jul 16, 2024	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user burtoc4 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				9	Jul 16, 2024	SYSTEM	(\$2,100.00)	
				10	Aug 2, 2024	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vierss overridding Payment Estimate Exception 12 on the current Payment Estimate.
				10	Aug 2, 2024	SYSTEM	(\$2,100.00)	
				11	Aug 16, 2024	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user burtoc4 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				11	Aug 16, 2024	SYSTEM	(\$2,100.00)	
			- Total				\$0.00	
		Material - T	otal				\$0.00	
0290	- Total						\$0.00	



Ducient	Line	Description	A	Others	Est	Onestad	Orrestad	A	Dementer
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2S3448	0300	15 IN. GROUP C FLARED END SEC	Material		9	Jul 16, 2024	SYSTEM	\$2,790.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user burtoc4 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Jul 16, 2024	SYSTEM	(\$2,790.00)	
					10	Aug 2, 2024	SYSTEM	\$2,790.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vierss overridding Payment Estimate Exception 13 on the current Payment Estimate.
					10	Aug 2, 2024	SYSTEM	(\$2,790.00)	
					11	Aug 16, 2024	SYSTEM	\$2,790.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user burtoc4 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					11	Aug 16, 2024	SYSTEM	(\$2,790.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0300 -	Total						\$0.00	
	0320	SEEDING - COOL SEASON GRASSES	Material		4	Apr 2, 2024	SYSTEM	\$7,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burtoc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Apr 2, 2024	SYSTEM	(\$7,125.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0320 -	Total							
	0350	ROCK DITCH CHECK	Material		1	Feb 16, 2024	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burtoc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Feb 16, 2024	SYSTEM	(\$360.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0350 -	Total						\$0.00	
	0360	TYPE B BERM	Overrun	Overrun	2	Mar 4, 2024	SYSTEM	(\$212.80)	
					4	Apr 2, 2024	SYSTEM	(\$140.00)	
				Overrun - Total				(\$352.80)	
			Overrun - Total					(\$352.80)	
	0360 -	Total						(\$352.80)	
	0400	SILT FENCE	Material		1	Feb 16, 2024	SYSTEM	\$6,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burtoc4 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Feb 16, 2024	SYSTEM	(\$6,580.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0400 -	Total	ptal						
	0440	CONCRETE PAVEMENT (9 1/2 IN. NON- REINF,	Material		10	Aug 2, 2024	SYSTEM	\$330,516.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vierss overridding Payment Estimate Exception 4 on the current Payment Estimate.
					10	Aug 2, 2024	SYSTEM	(\$330,516.45)	
					11	Aug 16, 2024	SYSTEM	\$661,032.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user burtoc4 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Aug 16, 2024	SYSTEM	(\$661,032.90)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	



Aug 20, 2024

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2S3448	0440 -	I0 - Total						\$0.00	
	0450	2 IN. PSST POST - 12 GA.	Material		11	Aug 16, 2024	SYSTEM	\$2,304.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user burtoc4 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					11	Aug 16, 2024	SYSTEM	(\$2,304.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0450 -	Total						\$0.00	
	0460	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	Material		11	Aug 16, 2024	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user burtoc4 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					11	Aug 16, 2024	SYSTEM	(\$1,200.00)	
				- Total					
			Material - To	otal				\$0.00	
	0460 -	0460 - Total							
	0470	SH-FLAT SHEET	Material		11	Aug 16, 2024	SYSTEM	\$648.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user burtoc4 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					11	Aug 16, 2024	SYSTEM	(\$648.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0470 -	Total						\$0.00	
J2S3448 -	- Total							(\$12,297.95)	
Overall -	Dverall - Total								



# Contract Adjustments for Contract - 230818-B02

Estimate Number	Project	Adjustment Type	Other Adjustment Type	Adjustment Amount	Adjustment Percentage by Project	Created Date	Created By	Comments
10	J2S3448	Other Contract Adjustment	OTHR	(\$40,000.00)	100	Aug 2, 2024	vierss	missing QC and material information
10 - Total					(\$40,000.00)			
Overall - Total					(\$40,000.00)			