

Progress Estimate Nu 4			231020-D04 Willard Asphalt Pav				24 Original Contract Amount 24 Net Change Order Amoun Current Contract Amount	<b>t</b> \$21,849.40
Approval Date								By User
October 1, 2024		t the Project Office Level by	knotta1					
October 1, 2024		Resident Engineer Level by	gabelj3					
October 2, 2024		Controllers Office Level by	ramses1					
Original Completion	of Current Contract Amount	f Current Contract Amount Complete						
November 1, 202	24	Novemb	er 1, 2024				94.75%	
	Contract	Informational Dat	tes		Milestones			
Date Description	Original	Completion Date	Current Complet	tion Date	No Milestones Exist for	Contract		
Acceptance Date								
Awarded Date	Novembe	er 1, 2023	November 1, 2023	3				
Letting Date	20, 2023	October 20, 2023						
Notice to Proceed Date	tice to Proceed Date December 4, 2023 December 4, 2023							
Open to Traffic Date								
Work Began Date								

Contract Total Pa	y For Estimate No. 4			
		This Estimate	Previous	To Date
231020-D04				
	Total Posted Items Pay	\$105,518.53	\$2,283,943.03	\$2,389,461.56
	Gross Item Adjustments	\$0.00	(\$94,908.68)	(\$94,908.68)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$2,189,034.35	\$2,294,552.88
Contract Total Pa	yable This Estimate:	\$105,518.53		

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount										
J5S3352	0030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	TONS	\$132.000	320	\$42,240.00										
	0070	6123000A	RUCK OR TRAILER MOUNTED ATTENUATOR (TMA) EA \$1.000 2								TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) EA \$1.000 2						
	0080	6161005	CONSTRUCTION SIGNS	SQFT	\$6.000	9	\$54.0										
	0130	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	LF	\$4.750	307	\$1,458.2										
	0140	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$18.250	209	\$3,814.2										
	0150	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	EA	\$300.000	2	\$600.0										
	0160	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	EA	\$25.000	9	\$225.0										
	0170	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.150	143,028	\$21,454.2										
	0180	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.110	142,690	\$15,695.9										
	0210	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	STA	\$33.870	77.5	\$2,624.9										
	0230	8025006	MULCHING	ACRE	\$1,550.000	5	\$7,750.0										
	0240 8051000A SEEDING - COOL SEASON GRASSES ACRE \$2,400.000 4																
Project J5	83352 - To	tal					\$105,518.5										
Overall - T	otal						\$105,518.5										

No Contract Adjustments Exist on Contract



Progre		imate Number 4	Contract ID Prime Contra	231020- I <b>ctor</b> Willard A		Pay Period Start September 16, 2024 Or g, Inc. Pay Period End September 30, 2024 Ne CL	t Change Or	der Amount	
ine Item	Adjust	<u>ments This Esti</u>	mate						
Project Number	Line No.	Item De	scription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3352	0030	GRAVEL (A)	OR CRUSHED STONE (B)	Material			-508	\$132.00	(\$67,056.0
	0030	GRAVEL (A)	OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user knotta1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	508	\$132.00	\$67,056.00
	0060		TACK COAT	Material			-15,053	\$3.00	(\$45,159.00
	0060		TACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user knotta1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	15,053	\$3.00	\$45,159.00
	0070		COR TRAILER ATTENUATOR (TMA)	Material			-2	\$1.00	(\$2.00
	0070		COR TRAILER ATTENUATOR (TMA)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user knotta1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	2	\$1.00	\$2.00
	0080	CONSTRU	ICTION SIGNS	Material			-2,692	\$6.00	(\$16,152.00
	0080	CONSTRU	ICTION SIGNS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user knotta1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	2,692	\$6.00	\$16,152.00
	0090	CHANNELIZE	R (TRIM LINE)	Material			-112	\$8.00	(\$896.00
	0090	CHANNELIZE	R (TRIM LINE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user knotta1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	112	\$8.00	\$896.00
	0100	S		Material			-6	\$3,000.00	(\$18,000.00
	0100	S		Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user knotta1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	6	\$3,000.00	\$18,000.00
	0130	THE PAVEMENT M	PREFORMED RMOPLASTIC ARKING, 6 IN. WHITE	Material			-307	\$4.75	(\$1,458.25
	0130			Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user knotta1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	307	\$4.75	\$1,458.25
	0140		PREFORMED RMOPLASTIC MARKING, 24 IN. WHITE	Material			-209	\$18.25	(\$3,814.2
	0140		PREFORMED	Material		This adjustment offsets the original system-	209	\$18.25	\$3,814.25



Progre		imate Number 4	Contract ID         231020-D04         Pay Period Start         September 16, 2024         Original Contract Amou           Prime Contractor         Willard Asphalt Paving, Inc.         Pay Period End         September 30, 2024         Net Change Order Amou           Current Contract Amou         Current Contract Amou         Current Contract Amou         Current Contract Amou									
Project Number	Line No.	Item Des	scription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount			
J5S3352			RMOPLASTIC MARKING, 24 IN. WHITE			generated Material Payment Estimate Item Adjustment (0007) due to user knotta1 overridding Payment Estimate Exception 9 on the current Payment Estimate.						
	0150	THE PAVEME	PREFORMED RMOPLASTIC NT MARKING, IGHT ARROW	Material			-2	\$300.00	(\$600.00			
	0150	THE PAVEME	PREFORMED RMOPLASTIC NT MARKING, IGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user knotta1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	2	\$300.00	\$600.00			
	0160	THE PAVEMENT MA	PREFORMED RMOPLASTIC ARKING, 12 IN E, YIELD LINE TRIANGLES	Material			-9	\$25.00	(\$225.00			
	0160	THE PAVEMENT MA	PREFORMED RMOPLASTIC ARKING, 12 IN E, YIELD LINE TRIANGLES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user knotta1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	9	\$25.00	\$225.00			
	0170	WATERBORN	E STANDARD E PAVEMENT AINT, TYPE P BEADS	Material			-143,028	\$0.15	(\$21,454.20			
	0170	WATERBORN	E STANDARD E PAVEMENT AINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user knotta1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	143,028	\$0.15	\$21,454.20			
	0180	WATERBORN	V STANDARD E PAVEMENT AINT, TYPE P BEADS	Material			-142,690	\$0.11	(\$15,695.90			
	0180	WATERBORN	W STANDARD E PAVEMENT AINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user knotta1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	142,690	\$0.11	\$15,695.90			
	0230		MULCHING	Material			-5	\$1,550.00	(\$7,750.00			
	0230		MULCHING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user knotta1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	5	\$1,550.00	\$7,750.00			
	0240	SEEDING - C	OOL SEASON GRASSES	Material			-4	\$2,400.00	(\$9,600.00			
	0240	SEEDING - C	OOL SEASON GRASSES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user knotta1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	4	\$2,400.00	\$9,600.00			
	0260	ROCK	DITCH CHECK	Material			-59	\$14.00	(\$826.00)			
	0260	ROCK	DITCH CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user knotta1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	59	\$14.00	\$826.00			



Progress Estimate Number         Contract ID         231020-D04         Pay Period Start September 16, 2024 Original Contract           4         Prime Contractor Willard Asphalt Paving, Inc.         Pay Period End         September 30, 2024 Net Change Order									\$21,849.40
Project Number	Line No.	Item Des	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3352	0270	ALTERNATE D	ITCH CHECK	Material			-873	\$10.50	(\$9,166.50
	0270	ALTERNATE D	DITCH CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user knotta1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	873	\$10.50	\$9,166.50
	0350	MIXT	S PAVEMENT URE PG64-22 E LEVELING)	Material			-4,200.1	\$96.75	(\$406,359.68
	0350	MIXT	S PAVEMENT URE PG64-22 E LEVELING)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user knotta1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	4,200.1	\$96.75	\$406,359.68
Total									\$0.00



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information						
Project Number												
J5S3352	SS3352 FAS S403(10) PULASKI on Route O from Route 28 to end of state maintenance (SME), on Route W from Route 7 to SME											
fotals by .	Job Numbe	ers										
J5S3352		d Item Pay Item Adjustm		Item Pay	This Estimate \$105,518.53 \$0.00 <b>\$105,518.53</b>	Previous \$2,283,943.03 (\$94,908.68) <b>\$2,189,034.35</b>	To Date \$2,389,461.56 (\$94,908.68) <b>\$2,294,552.88</b>					
	Liqui	tive centive dated Damages Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00					



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate renou			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 3105002, Project Item Line Number 0030, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 4020520, Project Item Line Number 0350, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 4071005, Project Item Line Number 0060, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 6123000A, Project Item Line Number 0070, Material Set 6123000A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 6161005, Project Item Line Number 0080, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 6161025, Project Item Line Number 0090, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 6161098A, Project Item Line Number 0100, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 6200009, Project Item Line Number 0130, Material Set 620000996, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 6200015, Project Item Line Number 0140, Material Set 620001596, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 6200021, Project Item Line Number 0150, Material Set 620002196, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 6200042, Project Item Line Number 0160, Material Set 620004296, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 6206000C, Project Item Line Number 0170, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 6206000C, Project Item Line Number 0170, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 6206001C, Project Item Line Number 0180, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 6206001C, Project Item Line Number 0180, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 8025006, Project Item Line Number 0230, Material Set 8025006, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 8061005, Project Item Line Number 0260, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Waiting on material reports.	knotta1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3352, Item 8061006, Project Item Line Number 0270, Material Set 806100696, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Waiting on material reports.	knotta1	Overridden

#### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
231020-D04	J5S3352	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$600.00	\$0.00
		0001	0020	2079909	MISC.MODIFIED LINEAR GRADING, CLASS 2	198.10	0.00	198.10	STA	198.10	\$790.00	\$156,499.00
		0001	0030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	595.00	0.00	595.00	TONS	508.00	\$132.00	\$67,056.00
		0001	0040	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	9,051.50	0.00	9,051.50	TONS	8,928.70	\$99.50	\$888,405.65
		0001	0050	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	1,421.70	0.00	1,421.70	TONS	1,416.80	\$88.00	\$124,678.40
		0001	0060	4071005	TACK COAT	17,220.00	0.00	17,220.00	GAL	15,053.00	\$3.00	\$45,159.00
		0001	0070	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$1.00	\$2.00
		0001	0080	6161005	CONSTRUCTION SIGNS	2,964.00	0.00	2,964.00	SQFT	2,692.00	\$6.00	\$16,152.00
		0001	0090	6161025	CHANNELIZER (TRIM LINE)	300.00	0.00	300.00	EA	112.00	\$8.00	\$896.00
		0001	0100	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	6.00	0.00	6.00	EA	6.00	\$3,000.00	\$18,000.00
		0001	0110	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$75,000.00	\$75,000.00
		0001	0120	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0130	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	307.00	0.00	307.00	LF	307.00	\$4.75	\$1,458.25
		0001	0140	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	209.00	0.00	209.00	LF	209.00	\$18.25	\$3,814.25
		0001	0150	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	2.00	0.00	2.00	EA	2.00	\$300.00	\$600.00
		0001	0160	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	14.00	0.00	14.00	EA	9.00	\$25.00	\$225.00
		0001	0170	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	178,785.00	0.00	178,785.00	LF	143,028.00	\$0.15	\$21,454.20
		0001	0180	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	178,362.00	0.00	178,362.00	LF	142,690.00	\$0.11	\$15,695.90
		0001	0190	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	5,122.00	0.00	5,122.00	SQYD	3,892.00	\$9.50	\$36,974.00
		0001	0200	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	845.00	0.00	845.00	SQYD	845.00	\$38.25	\$32,321.25
		0001	0210	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	77.50	0.00	77.50	STA	77.50	\$33.87	\$2,624.92
		0001	0220	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$1.00	\$0.00
		0001	0230	8025006	MULCHING	6.40	0.00	6.40	ACRE	5.00	\$1,550.00	\$7,750.00
		0001	0240	8051000A	SEEDING - COOL SEASON GRASSES	5.30	0.00	5.30	ACRE	4.00	\$2,400.00	\$9,600.00
		0001	0250	8061004	SEDIMENT TRAP ROCK	13.20	0.00	13.20	CUYD	0.00	\$65.00	\$0.00
		0001	0260	8061005	ROCK DITCH CHECK	881.00	0.00	881.00	LF	59.00	\$14.00	\$826.00
		0001	0270	8061006	ALTERNATE DITCH CHECK	22.00	851.00	873.00	LF	873.00	\$10.50	\$9,166.50
		0001	0280	8061016	SEDIMENT REMOVAL	281.00	0.00	281.00	CUYD	0.00	\$53.00	\$0.00
		0001	0290	8061017	TEMPORARY SEEDING	1.10	0.00	1.10	ACRE	0.00	\$1,050.00	\$0.00
		0001	0300	8061019	SILT FENCE	220.00	-220.00	0.00	LF	0.00	\$3.80	\$0.00
		0030	0310	9029902	MISC.VIDEO DETECTION SYSTEM	1.00	-1.00	0.00	EA	0.00	\$28,276.00	\$0.00
		0040	0320	9031250A	U-CHANNEL POST, 3 LB	1,190.00	0.00	1,190.00	LF	0.00	\$15.25	\$0.00
		0040	0330	9035069A	SHF-FLAT SHEET FLUORESCENT	255.00	0.00	255.00	SQFT	0.00	\$50.00	\$0.00
		0040	0340	9039901	MISC.ADJUSTING EXISTING SIGNS	1.00	0.00	1.00	LS	0.00	\$8,000.00	\$0.00
		0050	0350	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	4,200.50	0.00	4,200.50	TONS	4,200.10	\$96.75	\$406,359.68
		0051	0360	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	4,222.10	0.00	4,222.10	TONS	4,203.80	\$96.75	\$406,717.65
		0030	5001	1099902		0.00	1.00	1.00	EA	1.00	\$40,269.10	\$40,269.10
		0001	5002	8069903	MISC.Alternante Silt Fence	0.00	366.00	366.00	LF	366.00	\$4.80	\$1,756.80
231020-D04 Ove					Date as of Report Generated Date Ort Generated Date							\$2,389,461.55 <b>\$2,389,461.55</b>



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5S3352

Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	9/30/24	10/1/24	320.00	TONS	0030 Gravel (A) or Crushed Stone (B) Route O got a total of 66.88 tons on 9/16/24 Route W got a total of 153.52 tons on 9/19/24 Route W got a total of 79.66 tons on 9/20/24 Total = 320.06 tons Pay = 520 Tons					0030 Gravel (A) or Crushed Stone (B) Route 0 got a total of 68.88 tons on 9/16/24 Route W got a total of 153.52 tons on 9/19/24 Route W got a total of 79.66 tons on 9/20/24 Total = 320.06 tons Pay = 320 Tons
0070	6123000A	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	9/30/24	10/1/24	2.00	EA	0070 Truck or Trailer Mounted Attenuator 1 TMA was used for the seeding operation at various locations 1 TMA was used for the stripe operation. Total = 2 EA Pay = 2 EA					0070 Truck or Trailer Mounted Attenuator 1 TMA was used for the seeding operation at various locations 1 TMA was used for the stripe operation. Total = 2 EA Pay = 2 EA
0080	6161005	CONSTRUCTION SIGNS	9/30/24	10/1/24	9.00	SQFT	0080 Construction Signs 4 wet paint arrow pivots were used during the stripe operation at various locations Each one is 2.19 SF Total = 2.19 SF = 876 SF Pay = 8.76 SF = 9 SF					0080 Construction Signs 4 wet paint arrow pivots were used during the stripe operation at various locations Each one is 2.19 SF Total = 2.19 x 4 = 8.76 SF Pay = 8.76 SF = 9 SF
0130	6200009	PREF THERMO PAVMT MARKING, 6 IN WHITE	9/30/24	10/1/24	307.00	LF	0130 Preformed Thermoplastic Pavement Marking 6in White A total of 307 LF was used at the intersection of Route Y and St. Robert Blvd. Pay = 307 LF					0130 Preformed Thermoplastic Pavement Marking 6in White A total of 307 LF was used at the intersection of Route Y and SL Robert Blvd. Pay = 307 LF
0140	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	9/30/24	10/1/24	209.00	LF	0140 Preformed Thermoplastic Pavement Marking 24in White 209 LF was used for the stop bars and markings at the Pay = 209 LF $\rm Pay = 209 \ LF$					0140 Preformed Thermoplastic Pavement Marking 24in White 209 LF was used for the stop bars and markings at the intersection Pay = 209 LF
0150	6200021	PREF THERMO PVMT MARK, LT/RT ARROW	9/30/24	10/1/24	2.00	EA	0150 Preformed Thermoplastic Pavement Marking Left Right Arrow 1 left arrow was installed at LM 6.372 1 right arrow was installed at LM 6.372 Total = 2 EA Pay = 2 EA					0150 Preformed Thermoplastic Pavement Marking Left Right Arrow 1 left arrow was installed at LM 6.372 1 right arrow was installed at LM 6.372 Total = 2 EA Pay = 2 EA
0160	6200042	PREF THERMO PVMT MARK, YIELD TRIAN	9/30/24	10/1/24	9.00	EA	0160 Preformed Thermoplastic Pavement Marking 12in White Yield Triangles 9 yield triangles were installed at the intersection of St. Robert Blvd, and Route Y Total = 9 EA Pay = 9 EA					0160 Preformed Thermoplastic Pavement Marking 12in White Yield Triangles 9 yield triangles were installed at the intersection of St. Robert Bivd. and Route Y Total = 9 EA Pay = 9 EA
0170	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	9/30/24	10/1/24	143,028.00	LF	0170 4 in White Pavement Marking with Type P Beads Striped the white edge lines on Route Y, Route O, and Route W Will hold back 20% until retro testing is complete Plan quantity = 178785 LF P187058 x 0.8 = 143028 LF Pay = 143028 LF					0170 4 in White Pavement Marking with Type P Beads Striped the white edge lines on Route Y, Route O, and Route W Will hold back 20% until retro testing is complete Plan quantity = 178785 LF 178785 x 0.8 = 143028 LF Pay = 143028 LF
0180	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	9/30/24	10/1/24	142,690.00	LF	0180.4 in Yellow Pavement Marking with Type P Beads Striped the yellow center lines on Route Y, Route O, and Route W Will hold back 20% until retro testing is complete Plan quantity = 173862 LF 178362 x 0.3 = 142690 LF Pay = 142690 LF					0180 4 in Yellow Pavement Marking with Type P Beads Striped the yellow center lines on Route Y, Route O, and Route W Will hold back 20% until retro testing is complete Plan quantity = 178362 LF 178362 x 0.6 = 142990 LF Pay = 142690 LF
0210	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	9/30/24	10/1/24	77.50	STA	0210 Bituminous Shoulder Rumble Strip Rumbled 77.5 Sta from LM 3.767 to LM 5.970 Pay = 77.5 Sta.					0210 Bituminous Shoulder Rumble Strip Rumbled 77.5 Sta from LM 3.767 to LM 5.970 Pay = 77.5 Sta.
0230	8025006	MULCHING	9/30/24	10/1/24	5.00	ACRE	0230 Mulching Schrimpf mulched and seeded the area where the new shoulder was installed. Mulched from LM 3.767 to LM 5.970 a total of 5 Acres Pay = 5 ACRES					0230 Mulching Schrimpf mulched and seeded the area where the new shoulder was installed. Mulched from LM 3.767 to LM 5.970 a total of 5 Acres Pay = 5 ACRES
0240	8051000A	SEEDING - COOL SEASON GRASSES	9/30/24	10/1/24	4.00	ACRE	0240 Seeding Cool Season Grasses Schringr multiched and seeded the area where the new shoulder was installed. Mulched from LM 3.767 to LM 5.970 a total of 5 Acres Hold back 20% until seed growth is established. 5 x 0.2 = 1 5 1 = 4 ACRES Pay = 4 ACRES					0240 Seeding Cool Season Grasses Schimpt Muched and seeded the area where the new shoulder was installed. Muched from UN 3.767 to LM 5.970 a total of 5 Acres Hold back 20% until seed growth is established. 5 $\times$ 0.2 = 1 5.1 = 4 ACRES Pay = 4 ACRES

The information below this line are details for Construction Signs (if applicable). No Data Available



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks				
J5S3352	0030	GRAVEL (A) OR	Material	Туре	3	Sep 16,	SYSTEM	\$24,816.00	This adjustment offsets the original system-generated Material Payment				
		CRUSHED STONE (B)				2024			Estimate Item Adjustment (0002) due to user knotta1 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					3	Sep 16, 2024	SYSTEM	(\$24,816.00)					
					4	Oct 1, 2024	SYSTEM	\$67,056.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user knotta1 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					4	Oct 1, 2024	SYSTEM	(\$67,056.00)					
				- Total				\$0.00					
			Material - T	otal				\$0.00					
	0030 -	Total						\$0.00					
	0040	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Material		2	Sep 3, 2024	SYSTEM	\$782,657.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user knotta1 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					2	Sep 3, 2024	SYSTEM	(\$782,657.05)					
				- Total									
			Material - T	otal				\$0.00					
			Other Item Adjustment	ACAD	2	Sep 3, 2024	knotta1	(\$15,692.47)	See excel AC calculation sheet.				
					3	Sep 16, 2024	knotta1	(\$3,180.43)	See excel calculations sheet for AC adjustment.				
				ACAD - Tot	al			(\$18,872.90)					
			Other Item	Adjustment -	Total			(\$18,872.90)					
			Price FUEL		2	Sep 3, 2024	SYSTEM	(\$18,802.65)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
					3	Sep 16, 2024	, SYSTEM	(\$2,949.82)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
				- Total				(\$21,752.47)					
			Price FUEL	- Total				(\$21,752.47)					
	0040 -	- Total						(\$40,625.37)					
	0050	BITUMINOUS PAVEMENT MXTURE PG64-22 (BAS	Other Item Adjustment	ACAD	1	Aug 16, 2024	knotta1	(\$1,729.67)	Knotta1 Original Factor = 598.75 Current Factor = 551.25 Difference = -47.5 Virgin AC = 3.6 (1011.5)(-47.5)(3.6%)= -\$1,729.67				
					2	Sep 3, 2024	knotta1	(\$693.06)	See excel spreadsheet calculation.				
				ACAD - Tot	al			(\$2,422.73)					
			Other Item	Adjustment -	Total			(\$2,422.73)					
			Price FUEL		1	Aug 16, 2024	SYSTEM	(\$2,417.89)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
					2	Sep 3, 2024	SYSTEM	(\$968.83)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
				- Total				(\$3,386.72)					
			Price FUEL	- Total				(\$3,386.72)					
	0050 -	Total						(\$5,809.45)					
	0060	TACK COAT	Material		2	Sep 3, 2024	SYSTEM	\$17,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user knotta1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					2	Sep 3, 2024	SYSTEM	(\$17,424.00)					
					3	Sep 16, 2024	SYSTEM	\$45,159.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user knotta1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
					3	Sep 16, 2024	SYSTEM	(\$45,159.00)					



Oct 3, 2024

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J5S3352	0060	TACK COAT	Material		4	Oct 1, 2024	SYSTEM	(\$45,159.00)								
				- Total				\$0.00								
			Material - T	otal				\$0.00								
	0060 -	Total						\$0.00								
	0070	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	Material		4	Oct 1, 2024	SYSTEM	\$2.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user knotta1 overridding Payment Estimate Exception 4 on the current Payment Estimate.							
		(TMA)			4	Oct 1, 2024	SYSTEM	(\$2.00)								
				- Total				\$0.00								
			Material - T	otal				\$0.00								
	0070 -	Total						\$0.00								
	0080	CONSTRUCTION SIGNS	Material		1	Aug 16, 2024	SYSTEM	\$5,730.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user knotta1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					1	Aug 16, 2024	SYSTEM	(\$5,730.00)								
					2	Sep 3, 2024	SYSTEM	\$7,746.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user knotta1 overridding Payment Estimate Exception 3 on the current Payment Estimate.							
					2	Sep 3, 2024	SYSTEM	(\$7,746.00)								
												3	Sep 16, 2024	SYSTEM	\$16,098.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user knotta1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
														3	Sep 16, 2024	SYSTEM
					4	Oct 1, 2024	SYSTEM	\$16,152.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user knotta1 overridding Payment Estimate Exception 5 on the current Payment Estimate.							
					4	Oct 1, 2024	SYSTEM	(\$16,152.00)								
				- Total				\$0.00								
			Material - T	otal				\$0.00								
	0080 -	Total						\$0.00								
	0090	CHANNELIZER (TRIM LINE)	Material		1	Aug 16, 2024	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user knotta1 overridding Payment Estimate Exception 2 on the current Payment Estimate.							
					1	Aug 16, 2024	SYSTEM	(\$80.00)								
					2	Sep 3, 2024	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user knotta1 overridding Payment Estimate Exception 4 on the current Payment Estimate.							
					2	Sep 3, 2024	SYSTEM	(\$80.00)								
					3	Sep 16, 2024	SYSTEM	\$896.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user knotta1 overridding Payment Estimate Exception 6 on the current Payment Estimate.							
					3	Sep 16, 2024	SYSTEM	(\$896.00)								
					4	Oct 1, 2024	SYSTEM	\$896.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user knotta1 overridding Payment Estimate Exception 6 on the current Payment Estimate.							
			4	Oct 1, 2024	SYSTEM	(\$896.00)										
		- Total				\$0.00										
			Material - T	otal				\$0.00								
	0090 -	Total						\$0.00								
	0100	CMS W/O COMMUNICATION INTERFACE,	Material		1	Aug 16, 2024	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user knotta1 overridding Payment Estimate Exception 3 on the current Payment Estimate.							
	CONT F/					1	Aug 16,	SYSTEM	(\$6,000.00)							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3352	0100	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material			2024			
					2	Sep 3, 2024	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user knotta1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	Sep 3, 2024	SYSTEM	(\$18,000.00)	
					3	Sep 16, 2024	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user knotta1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	Sep 16, 2024	SYSTEM	(\$18,000.00)	
					4	Oct 1, 2024	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user knotta1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Oct 1, 2024	SYSTEM	(\$18,000.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0100 -	Total						\$0.00	
	0130	PREF THERMO PAVMT MARKING, 6 IN WHITE	Material		4	Oct 1, 2024	SYSTEM	\$1,458.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user knotta1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Oct 1, 2024	SYSTEM	(\$1,458.25)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0130 -	Total				_		\$0.00	
	0140	PREF THERMO PVMT MARK, 24 IN WHIT	Material		4	Oct 1, 2024	SYSTEM	\$3,814.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user knotta1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					4	Oct 1, 2024	SYSTEM	(\$3,814.25)	
				- Total				\$0.00	
		Material - Total						\$0.00	
	0140 -	0140 - Total						\$0.00	
	0150	PREF THERMO PVMT MARK, LT/RT ARROW	Material		4	Oct 1, 2024	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user knotta1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	Oct 1, 2024	SYSTEM	(\$600.00)	
			- Total					\$0.00	
			Material - Total					\$0.00	
	0150 -							\$0.00	
	0160	PREF THERMO PVMT MARK, YIELD TRIAN	Material		4	Oct 1, 2024	SYSTEM	\$225.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user knotta1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	Oct 1, 2024	SYSTEM	(\$225.00)	
				- Total				\$0.00	
	Material - Total							\$0.00	
		- Total						\$0.00	
	0170	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		4	Oct 1, 2024	SYSTEM	\$21,454.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user knotta1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					4	Oct 1, 2024	SYSTEM	(\$21,454.20)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0170 -	Total						\$0.00	
	0180	4 IN. YELLOW WATERBORNE	Material		4	Oct 1, 2024	SYSTEM	\$15,695.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user knotta1 overridding Payment



Oct 3, 2024

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3352	0180	PAVEMENT	Material						Estimate Exception 14 on the current Payment Estimate.
		MARKING			4	Oct 1, 2024	SYSTEM	(\$15,695.90)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0180 -	Total						\$0.00	
	0230	MULCHING	Material		4	Oct 1, 2024	SYSTEM	\$7,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user knotta1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					4	Oct 1, 2024	SYSTEM	(\$7,750.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0230 -	Total						\$0.00	
	0240	SEEDING - COOL SEASON GRASSES	Material		4	Oct 1, 2024	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user knotta1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					4	Oct 1, 2024	SYSTEM	(\$9,600.00)	
				- Total				\$0.00	
			Material - To	Material - Total				\$0.00	
	0240 -	Total						\$0.00	
	0260	ROCK DITCH CHECK	Material		1	Aug 16, 2024	SYSTEM	\$826.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user knotta1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					1	Aug 16, 2024	SYSTEM	(\$826.00)	
					2	Sep 3, 2024	SYSTEM	\$826.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user knotta1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					2	Sep 3, 2024	SYSTEM	(\$826.00)	
					3	Sep 16, 2024	SYSTEM	\$826.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user knotta1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Sep 16, 2024	SYSTEM	(\$826.00)	
					4	Oct 1, 2024	SYSTEM	\$826.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user knotta1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					4	Oct 1, 2024	SYSTEM	(\$826.00)	
				- Total				\$0.00	
			Material - T	Material - Total				\$0.00	
	0260 -	Total						\$0.00	
	0270	ALTERNATE DITCH CHECK	Material		1	Aug 16, 2024	SYSTEM	\$231.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user knotta1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					1	Aug 16, 2024	SYSTEM	(\$231.00)	
					2	Sep 3, 2024	SYSTEM	\$9,166.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user knotta1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					2	Sep 3, 2024	SYSTEM	(\$9,166.50)	
					3	Sep 16, 2024	SYSTEM	\$9,166.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user knotta1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					3	Sep 16, 2024	SYSTEM	(\$9,166.50)	
					4	Oct 1, 2024	SYSTEM	\$9,166.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user knotta1 overridding Payment Estimate Exception 19 on the current Payment Estimate.



Oct 3, 2024

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5&3352	0270	ALTERNATE DITCH CHECK	Material		4	Oct 1, 2024	SYSTEM	(\$9,166.50)	
				- Total				\$0.00	
	Material - Total							\$0.00	
	0270 -	Total						\$0.00	
	0350	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Material		3	Sep 16, 2024	SYSTEM	\$406,359.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user knotta1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Sep 16, 2024	SYSTEM	(\$406,359.68)	
					4	Oct 1, 2024	SYSTEM	\$406,359.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user knotta1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Oct 1, 2024	SYSTEM	(\$406,359.68)	
				- Total				\$0.00	
			Material - Total					\$0.00	
			Other Item Adjustment	ACAD	3	Sep 16, 2024	knotta1	(\$12,568.80)	See excel calculations sheet for AC adjustment.
				ACAD - Total				(\$12,568.80)	
			Other Item Adjustment - Total					(\$12,568.80)	
			Price FUEL		3	Sep 16, 2024	SYSTEM	(\$11,657.46)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total					
			Price FUEL - Total					(\$11,657.46)	
	0350 -	Total						(\$24,226.26)	
	0360	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Material		3	Sep 16, 2024	SYSTEM	\$406,717.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user knotta1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Sep 16, 2024	SYSTEM	(\$406,717.65)	
				- Total				\$0.00	
			Material - To	al - Total				\$0.00	
			Other Item Adjustment	ACAD	3	Sep 16, 2024	knotta1	(\$12,579.87)	See excel calculations sheet for AC adjustment.
				ACAD - Total				(\$12,579.87)	
			Other Item Adjustment - Total					(\$12,579.87)	
			Price FUEL		3	Sep 16, 2024	SYSTEM	(\$11,667.73)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				(\$11,667.73)	
			Price FUEL - Total					(\$11,667.73)	
	0360 -	Total						(\$24,247.60)	
J5S3352 -	Total							(\$94,908.68)	
Overall - 1	Total							(\$94,908.68)	



There are no contract adjustments to display for this contract.