

Pay Estimate Created Date: July 1, 2024

Progress Estimate 12	Number	Contract ID Prime Contracto	231117-F05 or Gerstner Electi		Pay Period Start Pay Period End			Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,595,781.00 \$256,531.45 \$1,852,312.45			
Approval Date									By User			
July 1, 2024			Generated and A	Approved	(and should be co	nsiderec	l Draft) a	at the Project Office Level by	norton1			
July 2, 2024		Re	viewed and Appro	ved (and	should be conside	ered Drat	t) at the	Resident Engineer Level by	HELLET			
July 2, 2024			F	Reviewed	and Approved at	the Cent	ral Offic	e Controllers Office Level by	ramses1			
Original Completion	on Date	Current Com	pletion Date	Actu	al Completion D	ate	Q	% of Current Contract Amou	nt Complete			
December 31, 2	024	Decembe	31, 2024			36.54%						
	Contract	Informational Dat	es		Mile	stones						
Date Description	Original	Completion Date	Current Comple	tion Date	No Milestones	Exist for	Contra	ct				
Acceptance Date												
Awarded Date	Decembe	er 6, 2023	December 6, 202	23								
Letting Date	Novembe	er 17, 2023	November 17, 20)23								
Notice to Proceed Date	January	8, 2024	January 8, 2024									
Open to Traffic Date												
Work Began Date	January	11, 2024	January 11, 2024	Ļ								

Contract Total Pay For Estimate No. 12				
	This Estimate	Previous	To Date	
231117-F05				
Total Posted Items Pay	\$41,180.00	\$635,711.50	\$676,891.50	
Gross Item Adjustments	\$5,330.00	(\$5,330.00)	\$0.00	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
		<mark>\$630,381.50</mark>	\$676,891.50	
Contract Total Payable This Estimate:	\$46,510.00			

Contract Total Payable This Estimate:

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6Q3174E	0010	2019902	MISCCLEARING, GRUBBING, MOWING & TREE CLEARING	EA	\$2,000.000	2	\$4,000.00
	0120	9029902	MISC.REMOVAL OF VIDEO DETECTION CAMERA	EA	\$350.000	1	\$350.00
	0210	9109902	MISC.ADVANCED DIAGNOSTICS	EA	\$150.000	65	\$9,750.00
	0250	9109902	MISC.F&I FIBER OPTIC FUSION SPLICE, SINGLE MODE	EA	\$20.000	12	\$240.00
	1010	9109903	MISC.F&I TRACE WIRE	LF	\$2.000	665	\$1,330.00
	1040	9109902	MISC.PM CCTV CAMERA, ASSEMBLY, POLE, & FIELD CABINET	EA	\$390.000	29	\$11,310.00
	1100	9109902	MISC.PM NON-INTRUSIVE VEHICLE DETECTOR STATIONS (MICROWAVE)	EA	\$310.000	16	\$4,960.00
	1130	9109902	MISC.PM VIDEO DETECTION CAMERAS	EA	\$140.000	66	\$9,240.00
Project J6Q	3174E - Tota	d					\$41,180.00
Overall - Tot	tal						\$41,180.00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6Q3174E	0280	MISC.	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3800.00000 - 3800.00000, 'is		\$3,800.00	\$3,800.00



Pay Estimate Created Date: July 1, 2024

Progres	ss Estin 12	nate Number	Contract ID Prime Contra	23111 actor Gerstn	7-F05 er Electric, Inc	.		nount \$256	95,781.00 6,531.45 52,312.45
Project Number	Line No.	Item Des	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6Q3174E						applied (if non-zero).			
	0350		MISC.	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',30.00000 - 30.00000, 'is applied (if non-zero).	2	\$30.00	\$60.00
	1000		MISC.	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3.75000 - 3.75000, 'is applied (if non-zero).	392	\$3.75	\$1,470.00
Total									\$5,330.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	Contract Project Informati	on
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6Q3174E	FAS S503(89)	ITS Maintenance	Various	ST LOUIS	at various locations in th	e St Louis District	
Totals by Jo	b Numbers	6					
J6Q3174E		Item Pay tem Adjustmer	nts Gross Ite	em Pay	This Estimate \$41,180.00 \$5,330.00 \$46,510.00	Previous \$635,711.50 (\$5,330.00) \$630,381.50	To Date \$676,891.50 \$0.00 \$676,891.50
			ments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00



Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Total Paid / All Items / All Estimates (Including this Estimate)

date and can differ from the posted amount at the time the Estimate was Generated.

Contract	Project	Category	Line	Item	Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTED
Nm.CONTRACT	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)
231117-F05	J6Q3174E	0001	0010	2019902	MISCCLEARING, GRUBBING, MOWING & TREE CLEARING	5.00	0.00	5.00	EA	3.00	\$2,000.00	\$6,000.00
		0001	0020	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	0.00	\$1,000.00	\$0.00
		0001	0030	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.00	\$30,000.00	\$0.00
		0001	0040	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED & RETAINED)	3.00	0.00	3.00	EA	0.00	\$100.00	\$0.00
		0001	0050	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.25	\$70,000.00	\$17,500.00
		0030	0060	9028308	CABLE, 16 AWG 2 CONDUCTOR	500.00	0.00	500.00	LF	0.00	\$2.00	\$0.00
		0030	0070	9028309	CABLE, 16 AWG 3 CONDUCTOR	500.00	0.00	500.00	LF	0.00	\$2.00	\$0.00
		0030	0080	9028310	CABLE, 16 AWG 5 CONDUCTOR	500.00	0.00	500.00	LF	0.00	\$2.25	\$0.00
		0030	0090	9029902	MISC.INSTALL & CONFIGURE VIDEO DETECTION CAMERA	40.00	0.00	40.00	EA	15.00	\$650.00	\$9,750.00
		0030	0100	9029902	MISC.INSTALL AND CONFIGURE AUDIBLE PEDESTRIAN SYSTEM	70.00	0.00	70.00	EA	12.00	\$950.00	\$11,400.00
		0030	0110	9029902	MISC.REMOVAL OF AUDIBLE PEDESTRIAN SYSTEM	70.00	0.00	70.00	EA	12.00	\$90.00	\$1,080.00
		0030	0120	9029902	MISC.REMOVAL OF VIDEO DETECTION CAMERA	40.00	0.00	40.00	EA	17.00	\$350.00	\$5,950.00
		0030	0130	9029903	MISC.CABLE, 18 AWG 4 CONDUCTOR	500.00	0.00	500.00	LF	0.00	\$2.25	\$0.00
		0050	0140	9103700	CCTV CAMERA ASSEMBLY, INSTALLED	30.00	0.00	30.00	EA	14.00	\$830.00	\$11,620.00
		0050	0150	9105200	CONDUIT, 2 IN., RIGID, IN TRENCH	250.00	0.00	250.00	LF	189.00	\$11.00	\$2,079.00
		0050	0160	9105201	CONDUIT, 3 IN., RIGID, IN TRENCH	100.00	0.00	100.00	LF	13.00	\$14.00	\$182.00
		0050	0170	9105202	CONDUIT, 4 IN., RIGID, IN TRENCH	100.00	0.00	100.00	LF	0.00	\$17.00	\$0.00
		0050	0180	9107201	CONDUIT, 3 IN., RIGID, PUSHED	50.00	0.00	50.00	LF	0.00	\$24.00	\$0.00
		0050	0190	9107202	CONDUIT, 4 IN., RIGID, PUSHED	50.00	0.00	50.00	LF	0.00	\$26.00	\$0.00
		0050	0200	9108352	FIBER OPTIC CABLE, 24-STRAND, 18 SINGLE MODE, 6 MULTIMODE	500.00	0.00	500.00	LF	0.00	\$3.75	\$0.00
		0050	0210	9109902	MISC.ADVANCED DIAGNOSTICS	500.00	500.00	1,000.00	EA	888.00	\$150.00	\$133,200.00
		0050	0220	9109902	MISC.DAKTRONICS' VANGUARD VX-2420 (DYNAMIC TRAIL BLAZER SIGN) PURCHASE	1.00	0.00	1.00	EA	0.00	\$15,750.00	\$0.00
		0050	0230	9109902	MISC.F&I CAMERA POLE (60FT) AND LOWERING SYSTEM	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0050	0240	9109902	MISC.F&I FIBER OPTIC FUSION SPLICE, MULTI MODE	50.00	0.00	50.00	EA	0.00	\$30.00	\$0.00
		0050	0250	9109902	MISC.F&I FIBER OPTIC FUSION SPLICE, SINGLE MODE	1,250.00	750.00	2,000.00	EA	1,572.00	\$20.00	\$31,440.00
		0050	0260	9109902	MISC.F&I ITS PULL BOX CLASS 1	2.00	0.00	2.00	EA	0.00	\$1,920.00	\$0.00
		0050	0270	9109902	MISC.F&I ITS PULL BOX CLASS 2 WITH CONCRETE PAD	2.00	0.00	2.00	EA	2.00	\$3,200.00	\$6,400.00
		0050	0280	9109902	MISC.F&I ITS PULL BOX CLASS 5 WITH CONCRETE PAD	2.00	6.00	8.00	EA	5.00	\$3,800.00	\$19,000.00
		0050	0290	9109902	MISC.F&I NON-INTRUSIVE VEHICLE DETECTOR POLE	5.00	0.00	5.00	EA	0.00	\$1,000.00	\$0.00
		0050	0300	9109902	MISC.F&I TYPE 1 ITS CABINET	1.00	0.00	1.00	EA	0.00	\$5,000.00	\$0.00
		0050	0310	9109902	MISC.F&I TYPE 2 ITS CABINET	1.00	0.00	1.00	EA	0.00	\$2,500.00	\$0.00
		0050	0320	9109902	MISC.F&I TYPE 5 ITS CABINET	1.00	0.00	1.00	EA	0.00	\$500.00	\$0.00
		0050	0330	9109902	MISC.F&I TYPE 7 ITS CABINET	1.00	0.00	1.00	EA	1.00	\$1,000.00	\$1,000.00
		0050	0340	9109902	MISC.FIBER OPTIC SPLICE ENCLOSURE	6.00	14.00	20.00	EA	14.00	\$925.00	\$12,950.00
		0050	0350	9109902	MISC.FIBER OPTIC TERMINATION	150.00	100.00	250.00	EA	156.00	\$30.00	\$4,680.00
		0050	0360	9109902	MISC.INSTALL IN-PAVEMENT WIRELESS SENSORS	50.00	0.00	50.00	EA	0.00	\$50.00	\$0.00
		0050	0370	9109902	MISC.INSTALL NON-INTRUSIVE ACCESS POINT & ASSEMBLY	5.00	0.00	5.00	EA	0.00	\$325.00	\$0.00
		0050	0380	9109902	MISC.INSTALL NON-INTRUSIVE VEHICLE DETECTOR ASSEMBLY	15.00	0.00	15.00	EA	3.00	\$720.00	\$2,160.00
		0050	0390	9109902	MISC.INSTALL NON-INTRUSIVE WIRELESS REPEATER	5.00	0.00	5.00	EA	0.00	\$250.00	\$0.00
		0050	0400	9109902	MISC.INSTALL SALVAGED CAMERA POLE	1.00	0.00	1.00	EA	0.00	\$1,290.00	\$0.00
		0050	0410	9109902	MISC.INSTALL SALVAGED FIELD CABINET (DUAL)	1.00	0.00	1.00	EA	0.00	\$950.00	\$0.00
		0050	0420	9109902	MISC.INSTALL SALVAGED FIELD CABINET (SINGLE)	10.00	0.00	10.00	EA	0.00	\$650.00	\$0.00
		0050	0430	9109902	MISC.INSTALL SALVAGED NON-INTRUSIVE VEHICLE DETECTOR POLE	10.00	0.00	10.00	EA	2.00	\$1,000.00	\$2,000.00
		0050	0440	9109902	MISC.INSTALL SOLAR POWER SYSTEM	1.00	0.00	1.00	EA	0.00	\$5,300.00	\$0.00
		0050	0450	9109902	MISC.INSTALL SPREAD SPECTRUM WIRELESS COMMUNICATION EQUIPMENT	2.00	0.00	2.00	EA	0.00	\$120.00	\$0.00

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q					port Generated date and can differ from the posted amou	nt at the ti	me the Es	timate was	Generat	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
231117-F05	J6Q3174E	0050	0460	9109902	MISC.INSTALL UPS AUTOMATIC GENERATOR SWITCH	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0470	9109902	MISC.INSTALL UPS AUTOMATIC TRANSFER SWITCH	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0480	9109902	MISC.INSTALL UPS BATTERY	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0490	9109902	MISC.INSTALL UPS BATTERY MONITOR	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0500	9109902	MISC.INSTALL UPS POWER INVERTER	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0510	9109902	MISC.INSTALL UPS SYSTEM ASSEMBLY	10.00	0.00	10.00	EA	0.00	\$685.00	\$0.00
		0050	0520	9109902	MISC.INSTALL WIRELESS ETHERNET BRIDGE COMMUNICATION EQUIPMENT	5.00	0.00	5.00	EA	3.00	\$1,200.00	\$3,600.00
		0050	0530	9109902	MISC.ITS PULL BOX LID REPLACEMENT (32-INCH DIAMETER)	5.00	0.00	5.00	EA	0.00	\$800.00	\$0.00
		0050	0540	9109902	MISC.ITS PULL BOX LID REPLACEMENT (40.5 INCH DIAMETER)	5.00	0.00	5.00	EA	0.00	\$800.00	\$0.00
		0050	0550	9109902	MISC.PAD MOUNTED POWER SUPPLY, 120V ITS	2.00	0.00	2.00	EA	1.00	\$5,000.00	\$5,000.00
		0050	0560	9109902	MISC.PEDESTAL BASE FOR SENSYS REPEATER POLE	1.00	0.00	1.00	EA	0.00	\$720.00	\$0.00
		0050	0570	9109902	MISC.RACK MOUNTED INTERCONNECT CENTER	5.00	0.00	5.00	EA	0.00	\$800.00	\$0.00
		0050	0580	9109902	MISC.REMOVE & REPLACE DTB (DYNAMIC TRAIL BLAZER) SIGN ASSEMBLY (16.5'-18' AT POLE)	1.00	0.00	1.00	EA	0.00	\$5,865.00	\$0.00
		0050	0590	9109902	MISC.REMOVE & REPLACE DTB (DYNAMIC TRAIL BLAZER) SIGN ASSEMBLY (30' AT POLE)	1.00	0.00	1.00	EA	0.00	\$5,865.00	\$0.00
		0050	0600	9109902	MISC.REMOVE & REPLACE DTB (DYNAMIC TRAIL BLAZER) SIGN FOUNDATION	1.00	0.00	1.00	EA	0.00	\$4,000.00	\$0.00
		0050	0610	9109902	MISC.REMOVE AND REPLACE UPS BATTERY	4.00	0.00	4.00	EA	0.00	\$120.00	\$0.00
		0050	0620	9109902	MISC.REMOVE CAMERA POLE	1.00	0.00	1.00	EA	0.00	\$750.00	\$0.00
		0050	0630	9109902	MISC.REMOVE CCTV CAMERA & ASSEMBLY	30.00	0.00	30.00	EA	12.00	\$120.00	\$1,440.00
		0050	0640	9109902	MISC.REMOVE COMMUNICATION FIELD CABINET (DOUBLE CABINET)	1.00	0.00	1.00	EA	0.00	\$650.00	\$0.00
		0050	0650	9109902	MISC.REMOVE COMMUNICATION NODE FIELD CABINET (SINGLE CABINET)	1.00	0.00	1.00	EA	0.00	\$375.00	\$0.00
		0050	0660	9109902	MISC.REMOVE IN-PAVEMENT WIRELESS SENSORS	50.00	0.00	50.00	EA	0.00	\$20.00	\$0.00
		0050	0670	9109902	MISC.REMOVE NON-INTRUSIVE ACCESS POINT & ASSEMBLY	5.00	0.00	5.00	EA	0.00	\$125.00	\$0.00
		0050	0680	9109902	MISC.REMOVE NON-INTRUSIVE VEHICLE DETECTOR ASSEMBLY	15.00	0.00	15.00	EA	2.00	\$120.00	\$240.00
		0050	0690	9109902	MISC.REMOVE NON-INTRUSIVE VEHICLE DETECTOR POLE	10.00	0.00	10.00	EA	2.00	\$475.00	\$950.00
		0050	0700	9109902	MISC.REMOVE NON-INTRUSIVE WIRELESS REPEATER	5.00	0.00	5.00	EA	0.00	\$150.00	\$0.00
		0050	0710	9109902	MISC.REMOVE SOLAR POWER SYSTEM	1.00	0.00	1.00	EA	0.00	\$900.00	\$0.00
		0050	0720	9109902	MISC.REMOVE UPS AUTOMATIC GENERATOR SWITCH	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0730	9109902	MISC.REMOVE UPS AUTOMATIC TRANSFER SWITCH	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0740	9109902	MISC.REMOVE UPS BATTERY	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0750	9109902	MISC.REMOVE UPS BATTERY MONITOR	1.00	0.00	1.00	EA	0.00	\$120.00	\$0.00
		0050	0760	9109902	MISC.REMOVE UPS POWER INVERTER	1.00	0.00	1.00	EA	0.00	\$120.00	\$0.00
		0050	0770	9109902	MISC.REMOVE UPS SYSTEM ASSEMBLY	10.00	0.00	10.00	EA	0.00	\$300.00	\$0.00
		0050	0780	9109902	MISC.REMOVE WIRELESS COMMUNICATION EQUIPMENT	2.00	0.00	2.00	EA	1.00	\$235.00	\$235.00
		0050	0790	9109902	MISC.SENSYS REPEATER POLE BASE ALUMINUM SQUARE	1.00	0.00	1.00	EA	0.00	\$720.00	\$0.00
		0050	0800	9109902	MISC.TB1-17 ALUMINUM BASE FOR RTMS POLE	1.00	1.00	2.00	EA	1.00	\$800.00	\$800.00
		0050	0810	9109902	MISC.TB3-17 ALUMINUM BASE FOR RTMS POLE	1.00	1.00	2.00	EA	1.00	\$875.00	\$875.00
		0050	0820	9109902	MISC.TROUBLESHOOTING	100.00	0.00	100.00	EA	43.00	\$200.00	\$8,600.00
		0050	0830	9109902	MISC.WALL MOUNTED INTERCONNECT CENTER	5.00	0.00	5.00	EA	0.00	\$800.00	\$0.00
		0050	0840	9109902	MISC.WRONG WAY ALERT SYSTEMS EQUIPMENT PURCHASE	2.00	0.00	2.00	EA	0.00	\$66,850.00	\$0.00
		0050	0850	9109902	MISC.WRONG WAY ALERT SYSTEMS INSTALLATION	2.00	0.00	2.00	EA	0.00	\$7,500.00	\$0.00
		0050	0860	9109902	MISC.WRONG WAY ALERT SYSTEMS SOFTWARE AND CERTIFICATION BY TAPCO OF NEW INSTALLATION	2.00	0.00	2.00	EA	0.00	\$9,915.00	\$0.00
		0050	0870	9109903	MISC.CONDUIT, 2 IN., RIGID, PUSHED	250.00	0.00	250.00	LF	0.00	\$19.00	\$0.00
		0050	0880	9109903	MISC.CONDUIT, HIGH-DENSITY POLYETHYLENE, 2 IN., IN TRENCH	50.00	0.00	50.00	LF	0.00	\$11.00	\$0.00
		0050	0890	9109903	MISC.CONDUIT, HIGH-DENSITY POLYETHYLENE, 2 IN., PUSHED	300.00	0.00	300.00	LF	0.00	\$19.00	\$0.00



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
231117-F05	J6Q3174E	0050	0900	9109903	MISC.F&I CABLE IN CONDUIT, #1/0 WIRE, VARIABLE CONDUCTORS	500.00	0.00	500.00	LF	0.00	\$4.20	\$0.0
		0050	0910	9109903	MISC.F&I CABLE IN CONDUIT, #14 WIRE, VARIABLE CONDUCTORS	250.00	0.00	250.00	LF	0.00	\$2.00	\$0.0
		0050	0920	9109903	MISC.F&I CABLE IN CONDUIT, #2 WIRE, VARIABLE CONDUCTORS	100.00	2,900.00	3,000.00	LF	2,770.00	\$3.50	\$9,695.0
		0050	0930	9109903	MISC.F&I CABLE IN CONDUIT, #2/0 WIRE, VARIABLE CONDUCTORS	100.00	0.00	100.00	LF	0.00	\$4.75	\$0.0
		0050	0940	9109903	MISC.F&I CABLE IN CONDUIT, #4 WIRE, VARIABLE CONDUCTORS	100.00	0.00	100.00	LF	0.00	\$2.50	\$0.0
		0050	0950	9109903	MISC.F&I CABLE IN CONDUIT, #6 WIRE, VARIABLE CONDUCTORS	500.00	0.00	500.00	LF	0.00	\$2.00	\$0.0
		0050	0960	9109903	MISC.F&I CABLE IN CONDUIT, #8 WIRE, VARIABLE CONDUCTORS	1,000.00	0.00	1,000.00	LF	0.00	\$1.50	\$0.0
		0050	0970	9109903	MISC.F&I CABLE IN CONDUIT, VIDEO COAXIAL CABLE	250.00	0.00	250.00	LF	0.00	\$2.00	\$0.0
		0050	0980	9109903	MISC.F&I CABLE IN CONDUIT: CAT5E OUTDOOR RATED CABLE	5,000.00	0.00	5,000.00	LF	260.00	\$2.00	\$520.0
		0050	0990	9109903	MISC.F&I FIBER OPTIC CABLE, 24-STRAND SINGLE MODE	17,000.00	7,000.00	24,000.00	LF	21,390.00	\$3.15	\$67,378.
		0050	1000	9109903	MISC.F&I FIBER OPTIC CABLE, 72-STRAND SINGLE MODE	5,000.00	25,000.00	30,000.00	LF	20,392.00	\$3.75	\$76,470.0
		0050	1010	9109903	MISC.F&I TRACE WIRE	7,000.00	0.00	7,000.00	LF	6,995.00	\$2.00	\$13,990.0
		0051	1020	9109902	MISC.MODOT BURIED CABLE DRIVABLE DELINEATOR POST	70.00	0.00	70.00	EA	1.00	\$115.00	\$115.0
		0051	1030	9109902	MISC.PM AIR CONDITIONING UNITS FOR NODE CABINETS	64.00	0.00	64.00	EA	32.00	\$276.00	\$8,832.0
		0051	1040	9109902	MISC.PM CCTV CAMERA, ASSEMBLY, POLE, & FIELD CABINET	618.00	0.00	618.00	EA	478.00	\$390.00	\$186,420.0
		0051	1050	9109902	MISC.PM COMMUNICATION LINK AND ASSEMBLY	333.00	0.00	333.00	EA	0.00	\$145.00	\$0.0
		0051	1060	9109902	MISC.PM COMMUNICATION NODE FIELD CABINET	33.00	0.00	33.00	EA	0.00	\$440.00	\$0.0
		0051	1070	9109902	MISC.PM DMP, ASSEMBLY, POLES, FOUNDATION, AND CABINET	2.00	0.00	2.00	EA	0.00	\$440.00	\$0.
		0051	1080	9109902	MISC.PM DMS, ASSEMBLY, POLE, FOUNDATION & FIELD CABINET	180.00	0.00	180.00	EA	0.00	\$450.00	\$0.
		0051	1090	9109902	MISC.PM DTB (DYNAMIC TRAIL BLAZER) SIGN ASSEMBLY	15.00	0.00	15.00	EA	0.00	\$240.00	\$0.
		0051	1100	9109902	MISC.PM NON-INTRUSIVE VEHICLE DETECTOR STATIONS (MICROWAVE)	297.00	0.00	297.00	EA	16.00	\$310.00	\$4,960.
		0051	1110	9109902	MISC.PM SOLAR POWER SYSTEM	34.00	0.00	34.00	EA	0.00	\$220.00	\$0.
		0051	1120	9109902	MISC.PM UNINTERRUPTIBLE POWER SUPPLY (UPS) AND ASSEMBLY	32.00	0.00	32.00	EA	0.00	\$220.00	\$0.
		0051	1130	9109902	MISC.PM VIDEO DETECTION CAMERAS	645.00	0.00	645.00	EA	85.00	\$140.00	\$11,900.
		0051	1140	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV CABLES AND WIRES	1.00	0.00	1.00	EA	0.00	\$440.00	\$0.
		0051	1150	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV CAMERA	1.00	0.00	1.00	EA	1.00	\$1,000.00	\$1,000
		0051	1160	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV CAMERA, ASSEMBLY, POLE, & FIELD CABINET	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.
		0051	1170	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV CONNECTORS	1.00	0.00	1.00	EA	0.00	\$375.00	\$0.
		0051	1180	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV DEVICE SERVER	1.00	0.00	1.00	EA	0.00	\$1.00	\$0.
		0051	1190	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV ENCODER	1.00	0.00	1.00	EA	0.00	\$1.00	\$0.
		0051	1200	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV POLE ACCESS PANEL	1.00	0.00	1.00	EA	0.00	\$440.00	\$0.
		0051	1210	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV POWER SUPPLY	1.00	0.00	1.00	EA	0.00	\$440.00	\$0.
		0051	1220	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV SURGE PROTECTOR	1.00	0.00	1.00	EA	0.00	\$390.00	\$0.
		0051	1230	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DMP,	1.00	0.00	1.00	EA	0.00	\$440.00	\$0.
		0051	1240	9109902	ASSEMBLY, POLE, FOUNDATION, & FIELD CABINET MISC.PM WITH REPAIRS - MODOT APPROVED DMS	1.00	0.00	1.00	EA	0.00	\$665.00	\$0.
		0051	1250	9109902	CONTROLLER MISC.PM WITH REPAIRS - MODOT APPROVED DMS DRIVER	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.
		0051	1260	9109902	BOARD MISC.PM WITH REPAIRS - MODOT APPROVED DMS FAN	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.0
		0051	1200	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DWS PAN MISC.PM WITH REPAIRS - MODOT APPROVED DMS LCA	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.
		0051	1270	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DWS LCA	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.
			1200	9109902	BOARD MISC.PM WITH REPAIRS - MODOT APPROVED DMS POWER	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.
		0051			SUPPLY							
		0051	1300	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED IP ADDRESSABLE POWER STRIP	1.00	0.00	1.00	EA	0.00	\$440.00	\$0.0

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
231117-F05	J6Q3174E	0051	1310	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED SIGNAL VIDEO DETECTION CAMERA	1.00	0.00	1.00	EA	0.00	\$130.00	\$0.00
		0051	1320	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED UPS DEVICE AND COMPONENTS	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
		0051	1330	9109902	MISC.PM WITH REPAIRS - MODOT SOLAR POWER SYSTEM	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
		0051	1340	9109902	MISC.REMOVE AND REPLACE NODE CABINET AIR CONDITIONER SYSTEM	2.00	0.00	2.00	EA	0.00	\$12,100.00	\$0.00
		0051	1350	9109902	MISC.WRONG WAY ALERT SYSTEMS PREVENTATIVE MAINTENANCE, SOFTWARE & RECERTIFICATION	12.00	0.00	12.00	EA	0.00	\$7,900.00	\$0.00
		0050	5001	9109901	MISC.Misc. ITS Air Conditioner Repair at Node 19	0.00	1.00	1.00	LS	0.00	\$156.45	\$0.00
	Project J60	Q3174E - To	otal Value	Posted to D	Date as of Report Generated Date							\$681,411.50
231117-F05 Ove	rall - Total V	alue Poste	d to Date	as of Repor	t Generated Date							\$681,411.50



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval	Quantity Posted	Units	Location	From Station/	Offset/ Distance	To Station/	Offset/ Distance	Comments
				Date				Log Mile		Log Mile		
0010	2019902	MISC.	6/18/24		1.00		Node 09 Power Supply t at I-170 @ I-270					-Cleared Power Supply near Node Cabinet at I-170 @ I-270
			6/19/24		1.00	EA	Node 03 Power Supply, I-44 @ I-270					Clearing and Grubbing at Node 3 Power Supply, I-44 @ I-270
0120	9029902	MISC.	6/20/24	6/26/24	1.00	EA	MO-100 @ Baxter-Sulphur Springs - Per IssueTrak Ticket #2001					Removed 4 Existing Video Detection Cameras at MO 10 @ Baxter-Sulphur Springs - Per IssueTrak Ticket #2001 NOT COMPLETE (Still need to return to troubleshoot Gridsmart Camera with local Representativ on Monday 6/24)
0210	9109902	MISC. ITS	6/17/24	6/26/24	10.00	EA	IS070W223.7 - Node 19 I-70 at I-64 - Per IssueTrak Ticket #2359					-Investigate from Node 19 to TMC, Traced down to Splicing possibly at Node 15 causing issues, will investigate more at a later date - Per IssueTrak Ticket #2359 - NOT COMPLETE
			6/20/24	6/26/24	4.00	EA	IS 170N000.6 Node 06 _I-170 @ Galleria - Per IssueTrak Ticket #2437					-Completed Cleanup for Class 5 Replacement at Node I-170 @ Galleria Parkway - Per IssueTrak Ticket #2437 COMPLETE
				6/26/24	4.00	EA	IS064E001.6 Interstate Dr/I-64 between I-70 and Prospect Dr - Per IssueTrak Ticket #2479					-Completed Cleanup for Class 5 Pullbox along Interstat Dr/I-84 between I-70 and Prospect Dr - Per IssueTrak Ticket #2479 - NOT COMPLETE >Still need to splice 72 SM Fiber in this pullbox
				6/26/24	16.00	EA	IS070W223.7 Node 19 I-70 at I-64 - Per IssueTrak Ticket #2359					-Investigate Issue from Node 19 to TMC - Per IssueTra Ticket #2359 - NOT COMPLETE
							6662					Found Fiber that was spliced incorrectly at Node 15, flipped to match Node 10 and Fiber now shoots 200,000LF. Seems repaired, but ran out of time before could shoot light.
			6/25/24	6/27/24	11.00	EA	MO100W102.6 MO 100 @ Baxter-Sulphur Springs - Per IssueTrak Ticket #2001					install and tightened all screws tightened all set screws models are screws not screws tastilled reveally offware meet up with cody and readjusted camera and zones redid drip loop contacted mo dot and they informed me that they can p and can communicate with it
			6/27/24	6/28/24	3.00	EA	IS270N022.9 - Node 11_I-270 @ MO Bottom history Issuetrak # 2354					We started OTDR 3 pairs that go WEST on the 72sm
			6/28/24	7/1/24	17.00	EA	Node 00 TMC - 141 WOR @ S. Outer Forty IS044E290.1 Node 08 H44 @ I-55 - Issuetrak #2364 IS27UN022 9 Mode 11 I-270 @ Missouri Bottom R4 - Issuetrak # 2354 IS070W223.7 Node 19 I-70 @ I-64 - Issuetrak # 2359					Node 0, 8, 11, 19 (6-28-24) TICKET #+s 2354, 2359, 2364 "We tested with the OTDR, as well tested a section will the OLTS of the Redundant PATH#1, #2 of the above locations. The Results from the Bidirectional testing look good(#+ matching up). Used the OLTS for a questionable, very
0250	9109902	MISC. ITS	6/17/24	6/26/24	12.00	EA	IS064E001.6 Interstate Dr/I-64 between I-70 and Prospect Dr - Per IssueTrak Ticket #2479					Iong stretch from N19-N0 this checked out good too" -Completed Remaining 12 Splices for 24 SM Fiber in Coyote Enclosure along Interstate Dr/I-64 between I-7 and Prospect Dr - Per IssueTrak Ticket #2479 - NOT COMPLETE
1010	9109903	MISC. ITS	6/18/24	6/26/24	665.00	LF	MO340E016.1 - 340 @ Price - Per IssueTrak Ticket #2498					-Installed 665 LF of Tracer Wire along MO 340 from Hilltop to Price - Per IssueTrak Ticket #2498 - COMPLETE
1040	9109902	MISC. ITS	6/20/24		1.00		IS270N005.7 I-270 at I-44 SEQ					IS270N005.7 I-270 at I-44 SEQ
			6/21/24	6/26/24	7.00	EA	RT00NE0096.6 RTE N RT00NE0104 RTE N REAGAN-SOMMERS RT00NE0107 RTE N HAWK RIDGE RT00NE0129 RTE E BRIAN-WINGHAVEN US06181353 RTE 61 A NB RAMP US06181353 RTE 61 A SB RAMP US0618136.1 RTE 61 EAST PITMAN SB RAMP					RT00NE006.6 ESPIRIT-ES6230 RTE N RT00NE010.4 XAIS G6155-E RTE N REAGAN- SOMMERS RT00NE010.7 BOSCH INTEOX 7000I RTE N HAWK RIDGE RT00NE012.9 AXIS G6315-LE RTE E BRIAN- WINGHAVEN US0615135.3 AXIS G6315-E RTE 61 A SB RAMP US0615135.3 AXIS G6315-E RTE 61 A SB RAMP US0615135.1 AXIS G6075-E RTE 61 EAST PITMAN RAMP
			6/24/24	6/26/24	8.00	EA	MO094E097.8 MO 94 at Francis Howell High School MO094E098.3 MO 94 at D MO094F102.4 MO 94 West of Wolfrum MO094F103.1 MO 94 at MO 364 NEQ MO094F109.1 MO 94 at Prail MO094F109.8 MO 94 at Zumbeh-Friedens MO094W101.2 MO 94 at Cecar Gien MO094W101.0 MO 94 West of S Breeze					MO094E097.8 MO 94 at Francis Howell High School MO094E093.3 MO 94 at D MO094E102.2 MO 94 West of Wolfrum MO094E103.1 MO 94 at MO 364 NEQ MO094E109.1 MO 94 at Pralle MO094E109.8 MO 94 at Zumbehi-Friedens MO094W101.2 MO 94 at Cedar Glen MO094W101.0 MO 94 West of S Breeze
			6/25/24	6/27/24	7.00	EA	RT00DE003.1 Route D at LinPage RT00DE005.2 Route D at Woodson RT00DE007.1 Route D at Hanley RT00DE006.0 Route D at Pennsylvania RT00DE009.6 Route D at Hamilton RT00DE013.2 Route D at Grand RT00DE013.2 Route D at Grand					RT00DE003.1 Route D at LinPage RT00DE005.2 Route D at Woodson RT00DE005.1 Route D at Hanley RT00DE008.0 Route D at Hanley RT00DE009.8 Route D at Hamilton RT00DE013.2 Route D at Grand RT00DE013.2 Route D at Vandeventer
			6/28/24	7/1/24	6.00	EA	IS055N186.7 I-55 S of Imperial Main IS0555180.1 I-55 South of Z IS0555184.4 I-55 South of Z IS0555184.0 I-55 aut W5 61/Lindbergh IS0555201.8 I-55 at W56ber IS0555207.4 I-55 at Krsenal SWQ					IS055N188.7 I-55 S of Imperial Main IS0555180.1 I-55 South of Z IS0555184.4 I-55 South of M IS05555184.0 I-55 at US 61/Lindbergh IS0555201.8 I-55 at Weber IS0555207.4 I-55 at Arsenal SWQ
1100	9109902	MISC. ITS	6/17/24	6/26/24	4.00	EA	IS070E233.8 Echo I-70 w/o MO 180 (at Mark Twain) IS070E239.7 Echo I-70 W of North Hanley IS070E245.4 Echo I-70 e/o Shreve IS070E247.0 Echo I-70 e/o Adelaide					IS070E233.8 Echo I-70 w/o MO 180 (at Mark Twain) IS070E239.7 Echo I-70 W of North Hanley IS070E245.4 Echo I-70 e/o Shreve IS070E247.0 Echo I-70 e/o Adelaide
			6/18/24	6/26/24	4.00	EA	IS070W203.7 Echo I-70 w/o Routes W-T IS070W203.6 Echo I-70 w/o I-64 IS070W213.6 Echo I-70 w/o MO 370 (370 to 70 WB Ramp)					IS070W203.7 Echo I-70 w/o Routes W-T IS070W203.7 Echo I-70 w/o Routes W-T IS070W210.0 EIS - Echo I-70 w/o HO 370 (370 to 70 WB Ramp)
			6/19/24	6/26/24	3.00	EA	IS070W223.6 Echo I-70 w/o MO 370 (70 WB) IS070W238.8 Echo I-70 at I-170 (WB Ramp) IS270S021.4 Echo I-270 at Woodford Way					IS070W223.6 Echo I-70 w/o MO 370 (70 WB) IS070W238.8 Echo I-70 at I-170 (WB Ramp) IS270S021.4 Echo I-270 at Woodford Way
			6/20/24	6/26/24	5.00	EA	IS2709020.0 Echo I-270 at I-70 IS270N005.7 Echo I-270 at I-44 SEQ IS270N013.6 Echo I-270 at I-44 SEQ IS2708013.6 Echo I-270 at IAC 370 IS2708022.3 Echo I-270 SOR-Pershall @ Pedestrian OR270E030.1 Echo I-270 SOR-Pershall @ Vedest Envised					IS270502.0 Echo I-270 al I-70 IS270N005.7 Echo I-270 al I-44 SEQ IS270N0135 Echo I-270 al I-44 SEQ IS270522.3 Echo I-270 al MO 370 Orti705027.1 Echo I-270 SOR-Pershall @ Pedestriar OR270E030.1 Echo I-270 SOR-Pershall e/o West Enviseant
1130	9109902	MISC. ITS	6/17/24	6/26/24	17.00	EA	Florssant MO1415003.7 St. Louis MO 141 at Riverport Dr North St. Louis MO 180 at Woodson St. Louis MO 180 at Lucas and Hunt St. Louis MO 180 at Fee Fee Rd					Fionssant MO1415003.7 St. Louis MO 141 at Riverport Dr North Cameras) St. Louis MO 180 at Woodson (4 Cameras) St. Louis MO 180 at Lucas and Hunt (3 Cameras)



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
1130	9109902	MISC. ITS	6/18/24	6/26/24	14.00	EA	MO141N002.9 St. Louis MO 141 at Prichard Farm MO141S004.1 St. Louis MO 141 at Casino Center Drive MO141S004.9 St. Louis MO 141 at Creve Coeur North MO141S005.2 St. Louis MO 141 at Marine					MO1411000.9 St. Louis MO 141 at Prichard Farm 3 Cameras MO141 S004.1 St. Louis MO 141 at Casino Center Drive : Cameras MO141 S004.9 St. Louis MO 141 at Creve Coeur North 4 Cameras MO141 S005.2 St. Louis MO 141 at Marine 4 Cameras
			6/19/24	6/26/24	19.00	EA	MO1415005.8 St. Louis MO 141 at Gullport Dr-Sportport MO1415005.7 St. Louis MO 141 at River Valley St. Louis MO 141 SB Ramp at Clayton Rd St. Louis MO 141 West Outer Road at Clayton Rd MO141N027.0 Jefferson MO 141 at Schneider					NO1413005.8 St. Louis MO 141 at Gulfport Dr-Sportport 4 Cameras MO1413006.7 St. Louis MO 141 at River Valley 4 Cameras St. Louis MO 141 SB Ramp at Clayton Rd 3 Cameras St. Louis MO 141 West Outer Road at Clayton Rd 4 Cameras MO141N027.0 Jefferson MO 141 at Schneider 4 Camera
			6/20/24	6/26/24	16.00	EA	MO 340 at Ladue MO 340 at Woodchase MO 340 at Cross Creek-Woodcrest MO 340 at Kehrs Mill Rd					MO 340 at Ladue 4 Cameras MO 340 at Woodchase 4 Cameras MO 340 at Cross Creek-Woodcrest 4 Cameras MO 340 at Kehrs Mill Rd 4 Cameras

The information below this line are details for Construction Signs (if applicable). No Data Available



ject	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks					
			Туре	Adjustment Type	Number	Date	Ву							
3174E	0150	CONDUIT, 2 IN., RIGID, IN TRENCH	Material		2	Feb 1, 2024	SYSTEM	\$55.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					2	Feb 1, 2024	SYSTEM	(\$55.00)						
					3	Feb 16, 2024	SYSTEM	\$55.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					3	Feb 16, 2024	SYSTEM	(\$55.00)						
					4	Mar 4, 2024	SYSTEM	\$1,045.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					4	Mar 4, 2024	SYSTEM	(\$1,045.00)						
				- Total										
			Material - Total					\$0.00						
	0150 -	Total						\$0.00						
	0160	CONDUIT, 3 IN., RIGID, IN TRENCH	Material		3	Feb 16, 2024	SYSTEM	\$182.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					3	Feb 16, 2024	SYSTEM	(\$182.00)						
					4	Mar 4, 2024	SYSTEM	\$182.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					4	Mar 4, 2024	SYSTEM	(\$182.00)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0160 -	Total						\$0.00						
	0210	MISC. ITS	Material		1	Jan 16, 2024	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					1	Jan 16, 2024	SYSTEM	(\$600.00)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
			Overrun	Overrun	Overrun	9	May 16, 2024	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
									_	9	May 16, 2024	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	May 16, 2024	SYSTEM	(\$4,200.00)						
				Overrun - Total				\$0.00						
			Overrun - Total					\$0.00						
	0210 -	Total						\$0.00						
	0250	MISC. ITS	Overrun	Overrun	9	May 16, 2024	SYSTEM	\$2,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user norton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
						May 16,	SYSTEM	(\$2,120.00)						
					9	2024								
				Overrun - T				\$0.00						
			Overrun - T					\$0.00 \$0.00						
	0250 -	· Total	Overrun - T											



Line Item Adjustments by Estimate

Project Line Description Adjustment Type Other Adjustment Type Est. Number Created Date Created By Amount J6Q3174E 0280 MISC. ITS Material	
2024 2024 4 Mar 4, 2024 \$YSTEM \$7,600.0 4 Mar 4, SYSTEM \$7,600.0	0)
2024 4 Mar 4, SYSTEM (\$7,600.0	
	10 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
2024	0)
- Total \$0.0	0
Material - Total \$0.0	0
OverrunOverrun11Jun 17, 2024SYSTEM(\$3,800.0)	0)
12 Jul 1, SYSTEM \$3,800.0	00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3800.00000 - 3800.00000, 'is applied (if non-zero).
Overrun - Total \$0.0	0
Overrun - Total \$0.0	0
0280 - Total \$0.0	0
0330 MISC. ITS Material 8 May 2, 2024 SYSTEM \$1,000.0	0 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
8 May 2, 2024 SYSTEM (\$1,000.0	0)
9 May 16, SYSTEM \$1,000.0	10 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
9 May 16, SYSTEM (\$1,000.0	0)
2024	
- Total \$0.0	0
- Total \$0.0	0
- Total \$0.0 Material - Total \$0.0	10 10
• Total \$0.0 Material - Total \$0.0 0330 - Total \$0.0 0340 MISC. ITS Overrun 8 May 2, SYSTEM \$925.0	00 00 00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
• Total \$0.0 Material - Total \$0.0 0330 - Total \$0.0 0330 - Total \$0.0 \$0.0 0340 MISC. ITS Overrun Overrun 8 May 2, 2024 \$YSTEM \$995.0 8 May 2, SYSTEM \$\$925.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0	00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 00) 00
• Total \$0.0 Material - Total \$0.0 0330 - Total \$0.0 0330 - Total \$0.0 0330 - Total \$0 \$0.0 0340 MISC. ITS Overrun Overrun 8 May 2, 2024 \$YSTEM \$925.0 8 May 2, 2024 \$YSTEM \$(\$925.0) \$9 May 16, \$YSTEM \$(\$925.0)	00 Image: Constraint of the set of the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 00 Image: Constraint of the set of the
• Total \$0.0 Material - Total \$0.0 0330 - Total \$0.0 0340 MISC. ITS Overrun 8 May 2, 2024 \$YSTEM \$925.0 0340 MISC. ITS Overrun 8 May 2, 2024 \$YSTEM \$\$925.0 8 May 16, SYSTEM (\$925.0 9 May 16, SYSTEM (\$925.0	00 Image: Constraint of the set of the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 00 Image: Constraint of the set of the current Payment Estimate is the current Payment Estimate. 00 Image: Constraint of the current Payment Estimate. 010 Image: Constraint of the current Payment Estimate. 020 Image: Constraint of the current Payment estimates of '0.00000' is applied (if non-zero). 020 Image: Constraint of the current Payment estimate is the current Payment estimate is of '0.00000' is applied (if non-zero). 030 Image: Constraint of the current Payment estimate is the current Payment estimate is of '0.00000' is applied (if non-zero).
- Total \$0.0 Material - Total \$0.0 0330 - Total \$0.0 0340 MISC. ITS Overrun Overrun 8 May 2, 2024 SYSTEM \$925.0 8 May 16, 2024 SYSTEM (\$925.0 9 May 16, 2024 \$YSTEM (\$925.0 9 May 16, 2024 SYSTEM (\$925.0 10 Jun 3, SYSTEM \$\$1,850.0	00 Initial System-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 000 Initial System Payment Estimate. 001 Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). 001 Initial Price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',925.00000 - 925.00000, 'is applied (if non-zero).
- Total \$0.0 Material - Total \$0.0 0330 - Total \$0.0 0340 MISC. ITS Overrun Overrun 8 May 2, 2024 SYSTEM \$925.0 8 May 16, 2024 SYSTEM (\$925.0 9 May 16, 2024 SYSTEM (\$925.0 9 May 16, 2024 SYSTEM (\$925.0 10 Jun 3, 2024 \$1,850.0	00 Image: Second Se
• Total \$0.0 Material - Total \$0.0 0330 - Total \$0.0 0340 MISC. ITS Overrun 8 May 2, 2024 SYSTEM \$925.0 0340 MISC. ITS Overrun 9 May 16, SYSTEM \$(\$925.0) 9 May 16, SYSTEM \$(\$925.0) \$0.0 \$(\$925.0) \$0.0 10 Jun 3, 2024 \$YSTEM \$(\$925.0) \$0.0 \$0.00	00 Image: Second Se
• Total \$0.0 Material - Total \$0.0 0330 - Total \$0.0 0330 - Total \$0.0 0340 MISC. ITS Overrun A May 2, 2024 SYSTEM \$925.0 8 May 2, 2024 SYSTEM \$\$925.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0 \$\$0.0	00 Initial adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 00 Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). 00 Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). 00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',925.00000 - 925.00000, 'is applied (if non-zero). 00 Init price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',925.00000 - 925.00000, 'is applied (if non-zero). 00 Init price based on averaged overrun adjustments of ',925.00000 - 925.00000, 'is applied (if non-zero). 00 Init price based on averaged overrun adjustments of ',925.00000 - 925.00000, 'is applied (if non-zero). 01 Init price based on averaged overrun adjustments of ',925.00000 - 925.00000, 'is applied (if non-zero). 02 Init price based on averaged overrun adjustments of ',925.00000 - 925.00000, 'is applied (if non-zero). 03 Init price based on averaged overrun adjustments of ',925.00000 - 925.00000, 'is applied (if non-zero). 04 Init price based on averaged overrun adjustments of ',925.00000 - 925.00000, 'is applied (if non-zero).
O330 - Total - Total \$0.0 0330 - Total \$0.0 0340 MISC. ITS Overrun 8 May 2, 2024 SYSTEM \$925.0 0340 MISC. ITS Overrun 8 May 2, 2024 SYSTEM \$925.0 9 May 16, SYSTEM (\$925.0 9 May 16, SYSTEM \$925.0 9 May 16, SYSTEM \$925.0 \$0.0 \$0.0 0 Verrun - Total \$0.0 \$1,850.0 \$0.0 0 Stol Total \$0.0 \$0.0	00 Image: Second Se
- Total \$0.0 Material - Total \$0.0 0330 - Total \$0.0 0340 MISC. ITS Overrun A May 2, 2024 SYSTEM \$925.0 0340 MISC. ITS Overrun A May 2, 2024 SYSTEM \$925.0 0 May 16, SYSTEM \$100 SYSTEM \$925.0 0 May 16, SYSTEM \$925.0 \$0.0 0 May 16, SYSTEM \$100 \$2024 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 <	00 Initial sequence of the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 000 Veraged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). 000 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',925.00000 - 925.00000, 'is applied (if non-zero). 00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',925.00000 - 925.00000, 'is applied (if non-zero). 00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments for installed quantity on all previous payment estimates. Price Adjustments for installed quantity on all previous payment estimates. Price Adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',30.00000 - 30.00000, 'is applied (if non-zero).
- Total \$0.0 Material - Total \$0.0 0330 - Total \$0.0 0340 MISC. ITS Overrun Overrun 8 May 2, 2024 SYSTEM \$925.0 0340 MISC. ITS Overrun Overrun 8 May 2, 2024 SYSTEM \$925.0 8 May 16, SYSTEM \$9 May 16, SYSTEM \$9 \$100 \$2024 \$100 \$9 \$100 \$000 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$	00 Image: Second Se
O330 - Total Material - Total SO.0 0330 - Total SO.0	00 Image: Second Se
- Total \$0.0 Material - Total \$0.0 0330 - Total \$0.0 0340 MISC. ITS Overrun Overrun 8 May 2, 2024 SYSTEM \$925.0 0340 MISC. ITS Overrun 0 8 May 2, 2024 SYSTEM \$(\$925.0) 9 May 16, SYSTEM \$(\$925.0) 2024 9 May 16, SYSTEM \$(\$925.0) 9 May 16, SYSTEM \$(\$925.0) 2024 \$10 Jun 3, 2024 \$1,850.0 040 - Total Overrun - Total \$0.0 \$0.0 \$0.0 0340 - Total Overrun - Total \$10 Jun 3, 2024 \$1,850.0 \$0.0 0340 - Total Overrun - Total \$0.0 \$0.0 \$0.0 \$0.0 0340 - Total Overrun - Total \$0.0 \$0.0 \$0.0 \$0.0 0350 MISC. ITS Overrun Overrun - Total \$0.0 \$0.0 0verrun - Total Overrun - Total \$0	00 Initial adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 00 Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). 00 Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). 00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',925.00000 - 925.00000, 'is applied (if non-zero). 00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',30.00000 - 30.00000, 'is applied (if non-zero). 00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',30.00000 - 30.00000, 'is applied (if non-zero). 00 Init price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',30.00000 - 30.00000, 'is applied (if non-zero). 00 Init price based on averaged overrun adjustments of ',30.00000 - 30.00000, 'is applied (if non-zero). 01 Init price based on averaged overrun adjustments of ',30.00000 - 30.00000, 'is applied (if non-zero).
- Total \$0.0 Material - Total Material - Total \$0.0 0330 - Total \$0.0 0340 MISC. ITS Overrun 8 May 2, 2024 SYSTEM \$925.0 8 May 2, 2024 SYSTEM \$925.0 9 May 16, SYSTEM \$925.0 9 May 16, SYSTEM \$925.0 9 May 16, SYSTEM \$925.0 9 May 16, SYSTEM \$925.0 9 May 16, SYSTEM \$925.0 9 May 16, SYSTEM \$925.0 \$925.0 \$925.0 \$925.0 9 May 16, SYSTEM \$925.0 \$925.0 \$925.0 \$925.0 9 May 16, SYSTEM \$925.0 \$925.0 \$925.0 \$925.0 0 Overrun - Total \$9 May 16, SYSTEM \$925.0 \$925.0 0 Overrun - Total \$9 May 16, SYSTEM \$9.00 \$9 0350 MISC. ITS Overrun Overrun - Total \$9.00 \$9.00 0350 - Total <td< td=""><td>00 Image: Second Se</td></td<>	00 Image: Second Se



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6Q3174E	0820	MISC. ITS	SC. ITS Material - Total					\$0.00	
	0820 -	Total						\$0.00	
	0920	MISC. ITS			4	Mar 4, 2024	SYSTEM	\$280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user norton1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Mar 4, 2024	SYSTEM	(\$280.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
			Overrun	Overrun	7	Apr 16, 2024	SYSTEM	\$7,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Apr 16, 2024	SYSTEM	(\$7,980.00)	
					9	May 16, 2024	SYSTEM	\$595.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	May 16, 2024	SYSTEM	(\$595.00)	
				Overrun - Total				\$0.00	
			Overrun - Total					\$0.00	
	0920 -	Total						\$0.00	
	0990	MISC. ITS			3	Feb 16, 2024	SYSTEM	\$7,490.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user norton1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Feb 16, 2024	SYSTEM	(\$7,490.70)	
					4	Mar 4, 2024	SYSTEM	\$33,660.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Mar 4, 2024	SYSTEM	(\$33,660.90)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0990 -	Total						\$0.00	
	1000	MISC. ITS			3	Feb 16, 2024	SYSTEM	\$17,670.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Feb 16, 2024	SYSTEM	(\$17,670.00)	
					4	Mar 4, 2024	SYSTEM	\$22,012.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Mar 4, 2024	SYSTEM	(\$22,012.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	4	Mar 4, 2024	SYSTEM	\$3,262.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Mar 4, 2024	SYSTEM	(\$3,262.50)	
					9	May 16, 2024	SYSTEM	\$1,125.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	May 16, 2024	SYSTEM	\$6,795.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	May 16,	SYSTEM	(\$7,920.00)	



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6Q3174E	1000	MISC. ITS	Overrun	Overrun	11	Jun 17, 2024	SYSTEM	(\$1,470.00)	
					12	Jul 1, 2024	SYSTEM	\$1,470.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3.75000 - 3.75000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - Total					\$0.00	
	1000 - Total							\$0.00	
	1010	MISC. ITS	Material		1	Jan 16, 2024	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user norton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Jan 16, 2024	SYSTEM	(\$700.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1010 - Total							\$0.00	
J6Q3174E - Total								\$0.00	
Overall - Total								\$0.00	



There are no contract adjustments to display for this contract.