ramses1



August 5, 2024

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 2, 2024

Progress Estim	Progress Estimate Number		231117-F05 Gerstner Electric, Inc.	Pay Period Start Pay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,595,781.00 \$281,022.90 \$1,876,803.90		
Approval Date							By User		
August 2, 2024		(Generated and Approve	d (and should be co	onsidered Draft) a	at the Project Office Level by	norton1		
August 2, 2024	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by								

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 31, 2024	December 31, 2024		43.81%

Reviewed and Approved at the Central Office Controllers Office Level by

	Contract Informational Dates										
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract								
Acceptance Date											
Awarded Date	December 6, 2023	December 6, 2023									
Letting Date	November 17, 2023	November 17, 2023									
Notice to Proceed Date	January 8, 2024	January 8, 2024									
Open to Traffic Date											
Work Began Date	January 11, 2024	January 11, 2024									

Contract Total Pa	ay For Estimate No. 14				
		This Estimate	Previous	To Date	
231117-F05					
	Total Posted Items Pay	\$126,389.00	\$695,772.95	\$822,161.95	
	Gross Item Adjustments	\$1,235.00	(\$1,235.00)	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$694,537.95	\$822,161.95	
Contract Total Pa	avable This Estimate:	\$127 624 00			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount				
J6Q3174E	0140	9103700	CCTV CAMERA ASSEMBLY, INSTALLED	EA	\$830.000	9	\$7,470.00				
	0210	9109902	MISC.ADVANCED DIAGNOSTICS	EA	\$150.000	34	\$5,100.00				
	0630	9109902	MISC.REMOVE CCTV CAMERA & ASSEMBLY	EA	\$120.000	8	\$960.00				
	0820	9109902	MISC.TROUBLESHOOTING	EA	\$200.000	4	\$800.00				
	0980	9109903	MISC.F&I CABLE IN CONDUIT: CAT5E OUTDOOR RATED CABLE	LF	\$2.000	372	\$744.00				
	1020	9109902	MISC.MODOT BURIED CABLE DRIVABLE DELINEATOR POST	EA	\$115.000	17	\$1,955.00				
	1040	9109902	MISC.PM CCTV CAMERA, ASSEMBLY, POLE, & FIELD CABINET	EA	\$390.000	12	\$4,680.00				
	1070	9109902	MISC.PM DMP, ASSEMBLY, POLES, FOUNDATION, AND CABINET	EA	\$440.000	2	\$880.00				
	1080	9109902	MISC.PM DMS, ASSEMBLY, POLE, FOUNDATION & FIELD CABINET	EA	\$450.000	20	\$9,000.00				
	1350	9109902	MISC.WRONG WAY ALERT SYSTEMS PREVENTATIVE MAINTENANCE, SOFTWARE & RECERTIFICATION	EA	\$7,900.000	12	\$94,800.00				
Project J6Q3174E - Total											
Overall - Total											

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

	Line Item Adjustments This Estimate												
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount					
J6Q3174E	0330	MISC.	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all		\$1,000.00	\$1,000.00					

Revision 3/23/2023 Page 1 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 2, 2024

Progres	ss Estin 14	nate Number	Contract ID 231117-F05 Prime Contractor Gerstner Electric, Inc.			c. Pay Period End August 1, 2024 Net Cha	Contract Am nge Order Ar Contract Am	nount \$28	1,595,781.00 281,022.90 1,876,803.90	
Project Number	Line No.	Item Des	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
J6Q3174E							previous payment estimates. Price Adjustments of ',1000.00000 - 1000.00000, 'is applied (if non-zero).			
	0780		MISC.	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',235.00000 - 235.00000, 'is applied (if non-zero).	1	\$235.00	\$235.00	
Total									\$1,235.00	


Revision 3/23/2023 Page 2 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information						
Project Number Proj. Number Pro												
J6Q3174E FAS S503(89) ITS Various ST LOUIS at various locations in the St Louis District												
Totals by Jo	b Numbers	3										
J6Q3174E					This Estimate	Previous	To Date					
	Posted	Item Pay			\$126,389.00	\$695,772.95	\$822,161.95					
	Gross I	tem Adjustmer	nts		\$1,235.00	(\$1,235.00)	\$0.00					
			Gross Ite	m Pay	\$127,624.00	\$694,537.95	\$822,161.95					
	11				\$0.00	\$0.00	\$0.00					
	Incentiv											
	Incentiv				\$0.00	\$0.00	\$0.00					
	Disince				\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00					

Revision 3/23/2023 Page 3 of 15





Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 3/23/2023 Page 4 of 15



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract .CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
117-F05	J6Q3174E	0001	0010	2019902	MISCCLEARING, GRUBBING, MOWING & TREE CLEARING	5.00	0.00	5.00	EA	3.00	\$2,000.00	\$6,000.0
		0001	0020	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	0.00	\$1,000.00	\$0.0
		0001	0030	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.00	\$30,000.00	\$0.0
		0001	0040	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED & RETAINED)	3.00	0.00	3.00	EA	0.00	\$100.00	\$0.0
		0001	0050	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.25	\$70,000.00	\$17,500.0
		0030	0060	9028308	CABLE, 16 AWG 2 CONDUCTOR	500.00	0.00	500.00	LF	0.00	\$2.00	\$0.0
		0030	0070	9028309	CABLE, 16 AWG 3 CONDUCTOR	500.00	0.00	500.00	LF	0.00	\$2.00	\$0.0
		0030	0080	9028310	CABLE, 16 AWG 5 CONDUCTOR	500.00	0.00	500.00	LF	0.00	\$2.25	\$0.0
		0030	0090	9029902	MISC.INSTALL & CONFIGURE VIDEO DETECTION CAMERA	40.00	0.00	40.00	EA	15.00	\$650.00	\$9,750.0
		0030	0100	9029902	MISC.INSTALL AND CONFIGURE AUDIBLE PEDESTRIAN	70.00	0.00	70.00	EA	12.00	\$950.00	\$11,400.0
		0030	0110	9029902	SYSTEM MISC.REMOVAL OF AUDIBLE PEDESTRIAN SYSTEM	70.00	0.00	70.00	EA	12.00	\$90.00	\$1,080.0
		0030	0120	9029902	MISC.REMOVAL OF VIDEO DETECTION CAMERA	40.00	0.00	40.00	EA	17.00	\$350.00	\$5,950.0
		0030	0130	9029903	MISC.CABLE, 18 AWG 4 CONDUCTOR	500.00	0.00	500.00	LF	0.00	\$2.25	\$0.0
		0050	0140	9103700	CCTV CAMERA ASSEMBLY, INSTALLED	30.00	0.00	30.00	EA	24.00	\$830.00	\$19,920.0
		0050	0150	9105200	CONDUIT, 2 IN., RIGID, IN TRENCH	250.00	0.00	250.00	LF	189.00	\$11.00	\$2,079.0
		0050	0160	9105201	CONDUIT, 3 IN., RIGID, IN TRENCH	100.00	0.00	100.00	LF	13.00	\$14.00	\$182.0
		0050	0170	9105202	CONDUIT, 4 IN., RIGID, IN TRENCH	100.00	0.00	100.00	LF	0.00	\$17.00	\$0.0
		0050	0180	9107201	CONDUIT, 3 IN., RIGID, PUSHED	50.00	0.00	50.00	LF	0.00	\$24.00	\$0.0
		0050	0190	9107202	CONDUIT, 4 IN., RIGID, PUSHED	50.00	0.00	50.00	LF	0.00	\$26.00	\$0.0
		0050	0200	9108352	FIBER OPTIC CABLE, 24-STRAND, 18 SINGLE MODE, 6	500.00	0.00	500.00	LF	0.00	\$3.75	\$0.0
					MULTIMODE							
		0050	0210	9109902	MISC.ADVANCED DIAGNOSTICS	500.00	600.00	1,100.00	EA	925.00	\$150.00	\$138,750.0
		0050	0220	9109902	MISC.DAKTRONICS' VANGUARD VX-2420 (DYNAMIC TRAIL BLAZER SIGN) PURCHASE	1.00	0.00	1.00	EA	0.00	\$15,750.00	\$0.
		0050	0230	9109902	MISC.F&I CAMERA POLE (60FT) AND LOWERING SYSTEM	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.0
		0050	0240	9109902	MISC.F&I FIBER OPTIC FUSION SPLICE, MULTI MODE	50.00	0.00	50.00	EA	0.00	\$30.00	\$0.
		0050	0250	9109902	MISC.F&I FIBER OPTIC FUSION SPLICE, SINGLE MODE	1,250.00	750.00	2,000.00	EA	1,602.00	\$20.00	\$32,040.0
		0050	0260	9109902	MISC.F&I ITS PULL BOX CLASS 1	2.00	0.00	2.00	EA	0.00	\$1,920.00	\$0.0
		0050	0270	9109902	MISC.F&I ITS PULL BOX CLASS 2 WITH CONCRETE PAD	2.00	0.00	2.00	EA	2.00	\$3,200.00	\$6,400.0
		0050	0280	9109902	MISC.F&I ITS PULL BOX CLASS 5 WITH CONCRETE PAD	2.00	6.00	8.00	EA	5.00	\$3,800.00	\$19,000.0
		0050	0290	9109902	MISC.F&I NON-INTRUSIVE VEHICLE DETECTOR POLE	5.00	0.00	5.00	EA	0.00	\$1,000.00	\$0.0
		0050	0300	9109902	MISC.F&I TYPE 1 ITS CABINET	1.00	0.00	1.00	EA	0.00	\$5,000.00	\$0.0
		0050	0310	9109902	MISC.F&I TYPE 2 ITS CABINET	1.00	0.00	1.00	EA	0.00	\$2,500.00	\$0.0
		0050	0320	9109902	MISC.F&I TYPE 5 ITS CABINET	1.00	0.00	1.00	EA	0.00	\$500.00	\$0.0
		0050	0330	9109902	MISC.F&I TYPE 7 ITS CABINET	1.00	2.00	3.00	EA	2.00	\$1,000.00	\$2,000.0
		0050	0340	9109902	MISC.FIBER OPTIC SPLICE ENCLOSURE	6.00	14.00	20.00	EA	14.00	\$925.00	\$12,950.0
		0050	0350	9109902	MISC.FIBER OPTIC TERMINATION	150.00	100.00	250.00	EA	164.00	\$30.00	\$4,920.0
		0050	0360	9109902	MISC.INSTALL IN-PAVEMENT WIRELESS SENSORS	50.00	0.00	50.00	EA	0.00	\$50.00	\$0.0
		0050	0370	9109902	MISC.INSTALL NON-INTRUSIVE ACCESS POINT & ASSEMBLY	5.00	0.00	5.00	EA	0.00	\$325.00	\$0.0
		0050	0380	9109902	MISC.INSTALL NON-INTRUSIVE VEHICLE DETECTOR ASSEMBLY	15.00	0.00	15.00	EA	3.00	\$720.00	\$2,160.0
		0050	0390	9109902	MISC.INSTALL NON-INTRUSIVE WIRELESS REPEATER	5.00	0.00	5.00	EA	0.00	\$250.00	\$0.0
		0050	0400	9109902	MISC.INSTALL SALVAGED CAMERA POLE	1.00	0.00	1.00	EA	1.00	\$1,290.00	\$1,290.0
		0050	0410	9109902	MISC.INSTALL SALVAGED FIELD CABINET (DUAL)	1.00	0.00	1.00	EA	0.00	\$950.00	\$0.0
		0050	0420	9109902	MISC.INSTALL SALVAGED FIELD CABINET (SINGLE)	10.00	0.00	10.00	EA	0.00	\$650.00	\$0.0
		0050	0430	9109902	MISC.INSTALL SALVAGED NON-INTRUSIVE VEHICLE DETECTOR POLE	10.00	0.00	10.00	EA	2.00	\$1,000.00	\$2,000.0
		0050	0440	9109902	MISC.INSTALL SOLAR POWER SYSTEM	1.00	0.00	1.00	EA	0.00	\$5,300.00	\$0.0
		0050	0450	9109902	MISC.INSTALL SPREAD SPECTRUM WIRELESS	2.00	0.00	2.00	EA	0.00	\$120.00	\$0.0

Page 5 of 15 Revision 3/23/2023



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					port Generated date and can differ from the posted amou						Unit Price	Total Value BOSTED
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
231117-F05	J6Q3174E	0050	0460	9109902	MISC.INSTALL UPS AUTOMATIC GENERATOR SWITCH	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0470	9109902	MISC.INSTALL UPS AUTOMATIC TRANSFER SWITCH	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0480	9109902	MISC.INSTALL UPS BATTERY	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0490	9109902	MISC.INSTALL UPS BATTERY MONITOR	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0500	9109902	MISC.INSTALL UPS POWER INVERTER	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0510	9109902	MISC.INSTALL UPS SYSTEM ASSEMBLY	10.00	0.00	10.00	EA	0.00	\$685.00	\$0.00
		0050	0520	9109902	MISC.INSTALL WIRELESS ETHERNET BRIDGE COMMUNICATION EQUIPMENT	5.00	5.00	10.00	EA	5.00	\$1,200.00	\$6,000.00
		0050	0530	9109902	MISC.ITS PULL BOX LID REPLACEMENT (32-INCH DIAMETER)	5.00	0.00	5.00	EA	0.00	\$800.00	\$0.00
		0050	0540	9109902	MISC.ITS PULL BOX LID REPLACEMENT (40.5 INCH DIAMETER)	5.00	0.00	5.00	EA	0.00	\$800.00	\$0.00
		0050	0550	9109902	MISC.PAD MOUNTED POWER SUPPLY, 120V ITS	2.00	0.00	2.00	EA	1.00	\$5,000.00	\$5,000.00
		0050	0560	9109902	MISC.PEDESTAL BASE FOR SENSYS REPEATER POLE	1.00	0.00	1.00	EA	0.00	\$720.00	\$0.00
		0050	0570	9109902	MISC.RACK MOUNTED INTERCONNECT CENTER	5.00	0.00	5.00	EA	0.00	\$800.00	\$0.00
		0050	0580	9109902	MISC.REMOVE & REPLACE DTB (DYNAMIC TRAIL BLAZER)	1.00	0.00	1.00	EA	0.00	\$5,865.00	\$0.00
		0050	0590	9109902	SIGN ASSEMBLY (16.5'-18' AT POLE) MISC.REMOVE & REPLACE DTB (DYNAMIC TRAIL BLAZER)	1.00	0.00	1.00	EA	0.00	\$5,865.00	\$0.00
					SIGN ASSEMBLY (30' AT POLE)							
		0050	0600	9109902	MISC.REMOVE & REPLACE DTB (DYNAMIC TRAIL BLAZER) SIGN FOUNDATION	1.00	0.00	1.00	EA	0.00	\$4,000.00	\$0.00
		0050	0610	9109902	MISC.REMOVE AND REPLACE UPS BATTERY	4.00	0.00	4.00	EA	0.00	\$120.00	\$0.00
		0050	0620	9109902	MISC.REMOVE CAMERA POLE	1.00	0.00	1.00	EA	0.00	\$750.00	\$0.00
		0050	0630	9109902	MISC.REMOVE CCTV CAMERA & ASSEMBLY	30.00	0.00	30.00	EA	21.00	\$120.00	\$2,520.00
		0050	0640	9109902	MISC.REMOVE COMMUNICATION FIELD CABINET (DOUBLE CABINET)	1.00	0.00	1.00	EA	0.00	\$650.00	\$0.00
		0050	0650	9109902	MISC.REMOVE COMMUNICATION NODE FIELD CABINET (SINGLE CABINET)	1.00	0.00	1.00	EA	0.00	\$375.00	\$0.00
		0050	0660	9109902	MISC.REMOVE IN-PAVEMENT WIRELESS SENSORS	50.00	0.00	50.00	EA	0.00	\$20.00	\$0.00
		0050	0670	9109902	MISC.REMOVE NON-INTRUSIVE ACCESS POINT & ASSEMBLY	5.00	0.00	5.00	EA	0.00	\$125.00	\$0.00
		0050	0680	9109902	MISC.REMOVE NON-INTRUSIVE VEHICLE DETECTOR ASSEMBLY	15.00	0.00	15.00	EA	2.00	\$120.00	\$240.00
		0050	0690	9109902	MISC.REMOVE NON-INTRUSIVE VEHICLE DETECTOR POLE	10.00	0.00	10.00	EA	2.00	\$475.00	\$950.00
		0050	0700	9109902	MISC.REMOVE NON-INTRUSIVE WIRELESS REPEATER	5.00	0.00	5.00	EA	0.00	\$150.00	\$0.00
		0050	0710	9109902	MISC.REMOVE SOLAR POWER SYSTEM	1.00	0.00	1.00	EA	0.00	\$900.00	\$0.00
		0050	0720	9109902	MISC.REMOVE UPS AUTOMATIC GENERATOR SWITCH	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0730	9109902	MISC.REMOVE UPS AUTOMATIC TRANSFER SWITCH	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0740	9109902	MISC.REMOVE UPS BATTERY	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0750	9109902	MISC.REMOVE UPS BATTERY MONITOR	1.00	0.00	1.00	EA	0.00	\$120.00	\$0.00
		0050	0760	9109902	MISC.REMOVE UPS POWER INVERTER	1.00	0.00	1.00	EA	0.00	\$120.00	\$0.00
		0050	0770	9109902	MISC.REMOVE UPS SYSTEM ASSEMBLY	10.00	0.00	10.00	EA	0.00	\$300.00	\$0.00
		0050	0780	9109902	MISC.REMOVE WIRELESS COMMUNICATION EQUIPMENT	2.00	3.00	5.00	EA	3.00	\$235.00	\$705.00
		0050	0790	9109902	MISC.SENSYS REPEATER POLE BASE ALUMINUM SQUARE	1.00	0.00	1.00	EA	0.00	\$720.00	\$0.00
		0050	0800	9109902	MISC.TB1-17 ALUMINUM BASE FOR RTMS POLE	1.00	1.00	2.00	EA	1.00	\$800.00	\$800.00
		0050	0810	9109902	MISC.TB3-17 ALUMINUM BASE FOR RTMS POLE	1.00	1.00	2.00	EA	2.00	\$875.00	\$1,750.00
		0050	0820	9109902	MISC.TROUBLESHOOTING	100.00	0.00	100.00	EA	49.00	\$200.00	\$9,800.00
		0050	0830	9109902	MISC.WALL MOUNTED INTERCONNECT CENTER	5.00	0.00	5.00	EA	0.00	\$800.00	\$0.00
		0050	0840	9109902	MISC.WRONG WAY ALERT SYSTEMS EQUIPMENT PURCHASE	2.00	0.00	2.00	EA	0.00	\$66,850.00	\$0.00
		0050	0850	9109902	MISC.WRONG WAY ALERT SYSTEMS INSTALLATION	2.00	0.00	2.00	EA	0.00	\$7,500.00	\$0.00
		0050	0860	9109902	MISC.WRONG WAY ALERT SYSTEMS SOFTWARE AND CERTIFICATION BY TAPCO OF NEW INSTALLATION	2.00	0.00	2.00	EA	0.00	\$9,915.00	\$0.00
		0050	0870	9109903	MISC.CONDUIT, 2 IN., RIGID, PUSHED	250.00	0.00	250.00	LF	0.00	\$19.00	\$0.00
		0050	0880	9109903	MISC.CONDUIT, HIGH-DENSITY POLYETHYLENE, 2 IN., IN TRENCH	50.00	0.00	50.00	LF	0.00	\$11.00	\$0.00
		0050	0890	9109903	MISC.CONDUIT, HIGH-DENSITY POLYETHYLENE, 2 IN., PUSHED	300.00	0.00	300.00	LF	0.00	\$19.00	\$0.00

Page 6 of 15 Revision 3/23/2023



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract												
Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
231117-F05	J6Q3174E	0050	0900	9109903	MISC.F&I CABLE IN CONDUIT, #1/0 WIRE, VARIABLE CONDUCTORS	500.00	0.00	500.00	LF	0.00	\$4.20	\$0.00
		0050	0910	9109903	MISC.F&I CABLE IN CONDUIT, #14 WIRE, VARIABLE CONDUCTORS	250.00	0.00	250.00	LF	0.00	\$2.00	\$0.00
		0050	0920	9109903	MISC.F&I CABLE IN CONDUIT, #2 WIRE, VARIABLE CONDUCTORS	100.00	2,900.00	3,000.00	LF	2,770.00	\$3.50	\$9,695.00
		0050	0930	9109903	MISC.F&I CABLE IN CONDUIT, #2/0 WIRE, VARIABLE CONDUCTORS	100.00	0.00	100.00	LF	0.00	\$4.75	\$0.00
		0050	0940	9109903	MISC.F&I CABLE IN CONDUIT, #4 WIRE, VARIABLE CONDUCTORS	100.00	0.00	100.00	LF	0.00	\$2.50	\$0.00
		0050	0950	9109903	MISC.F&I CABLE IN CONDUIT, #6 WIRE, VARIABLE CONDUCTORS	500.00	0.00	500.00	LF	0.00	\$2.00	\$0.00
		0050	0960	9109903	MISC.F&I CABLE IN CONDUIT, #8 WIRE, VARIABLE CONDUCTORS	1,000.00	0.00	1,000.00	LF	0.00	\$1.50	\$0.00
		0050	0970	9109903	MISC.F&I CABLE IN CONDUIT, VIDEO COAXIAL CABLE	250.00	0.00	250.00	LF	0.00	\$2.00	\$0.00
		0050	0980	9109903	MISC.F&I CABLE IN CONDUIT: CAT5E OUTDOOR RATED CABLE	5,000.00	0.00	5,000.00	LF	632.00	\$2.00	\$1,264.00
		0050	0990	9109903	MISC.F&I FIBER OPTIC CABLE, 24-STRAND SINGLE MODE	17,000.00	7,000.00	24,000.00	LF	21,390.00	\$3.15	\$67,378.50
		0050	1000	9109903	MISC.F&I FIBER OPTIC CABLE, 72-STRAND SINGLE MODE	5,000.00	25,000.00	30,000.00	LF	20,392.00	\$3.75	\$76,470.00
		0050	1010	9109903	MISC.F&I TRACE WIRE	7,000.00	0.00	7,000.00	LF	6,995.00	\$2.00	\$13,990.00
		0051	1020	9109902	MISC.MODOT BURIED CABLE DRIVABLE DELINEATOR POST	70.00	0.00	70.00	EA	18.00	\$115.00	\$2,070.00
		0051	1030	9109902	MISC.PM AIR CONDITIONING UNITS FOR NODE CABINETS	64.00	0.00	64.00	EA	32.00	\$276.00	\$8,832.00
		0051	1040	9109902	MISC.PM CCTV CAMERA, ASSEMBLY, POLE, & FIELD CABINET MISC.PM COMMUNICATION LINK AND ASSEMBLY	618.00 333.00	0.00	618.00	EA EA	0.00	\$390.00 \$145.00	\$195,390.00 \$0.00
		0051	1060	9109902	MISC.PM COMMUNICATION LINK AND ASSEMBLY MISC.PM COMMUNICATION NODE FIELD CABINET	33.00	0.00	33.00	EA	0.00	\$145.00	\$0.00
		0051	1070	9109902	MISC.PM DMP, ASSEMBLY, POLES, FOUNDATION, AND	2.00	0.00	2.00	EA	2.00	\$440.00	\$880.00
		0051	1080	9109902	CABINET MISC.PM DMS, ASSEMBLY, POLE, FOUNDATION & FIELD	180.00	0.00	180.00	EA	20.00	\$450.00	\$9,000.00
		0051	1090	9109902	CABINET MISC.PM DTB (DYNAMIC TRAIL BLAZER) SIGN ASSEMBLY	15.00	0.00	15.00	EA	0.00	\$240.00	\$0.00
		0051	1100	9109902	MISC.PM NON-INTRUSIVE VEHICLE DETECTOR STATIONS	297.00	0.00	297.00	EA	20.00	\$310.00	\$6,200.00
		0051	1110	9109902	(MICROWAVE) MISC.PM SOLAR POWER SYSTEM	34.00	0.00	34.00	EA	0.00	\$220.00	\$0.00
		0051	1120	9109902	MISC.PM UNINTERRUPTIBLE POWER SUPPLY (UPS) AND ASSEMBLY	32.00	0.00	32.00	EA	0.00	\$220.00	\$0.00
		0051	1130	9109902	MISC.PM VIDEO DETECTION CAMERAS	645.00	0.00	645.00	EA	85.00	\$140.00	\$11,900.00
		0051	1140	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV CABLES AND WIRES	1.00	0.00	1.00	EA	0.00	\$440.00	\$0.00
		0051	1150	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV CAMERA	1.00	0.00	1.00	EA	1.00	\$1,000.00	\$1,000.00
		0051	1160	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV CAMERA, ASSEMBLY, POLE, & FIELD CABINET	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0051	1170	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV CONNECTORS	1.00	0.00	1.00	EA	0.00	\$375.00	\$0.00
		0051	1180	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV DEVICE SERVER	1.00	0.00	1.00	EA	0.00	\$1.00	\$0.00
		0051	1190	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV ENCODER	1.00	0.00	1.00	EA	0.00	\$1.00	\$0.00
		0051	1200	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV POLE ACCESS PANEL	1.00	0.00	1.00	EA	0.00	\$440.00	\$0.00
		0051	1210	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV POWER SUPPLY	1.00	0.00	1.00	EA	0.00	\$440.00	\$0.00
		0051	1220	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV SURGE PROTECTOR	1.00	0.00	1.00	EA	0.00	\$390.00	\$0.00
		0051	1230	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DMP, ASSEMBLY, POLE, FOUNDATION, & FIELD CABINET	1.00	0.00	1.00	EA	0.00	\$440.00	\$0.00
		0051	1240	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DMS	1.00	0.00	1.00	EA	0.00	\$665.00	\$0.00
		0051	1250	9109902	CONTROLLER MISC.PM WITH REPAIRS - MODOT APPROVED DMS DRIVER	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
		0051	1260	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DMS FAN	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
		0051	1270	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DMS LCA	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
		0051	1280	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DMS PIXEL BOARD	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
		0051	1290	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DMS POWER SUPPLY	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
		0051	1300	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED IP	1.00	0.00	1.00	EA	0.00	\$440.00	\$0.00

Page 7 of 15 Revision 3/23/2023



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
231117-F05	J6Q3174E	0051	1310	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED SIGNAL VIDEO DETECTION CAMERA	1.00	0.00	1.00	EA	0.00	\$130.00	\$0.00
		0051	1320	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED UPS DEVICE AND COMPONENTS	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
		0051	1330	9109902	MISC.PM WITH REPAIRS - MODOT SOLAR POWER SYSTEM	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
		0051	1340	9109902	MISC.REMOVE AND REPLACE NODE CABINET AIR CONDITIONER SYSTEM	2.00	0.00	2.00	EA	0.00	\$12,100.00	\$0.00
		0051	1350	9109902	MISC.WRONG WAY ALERT SYSTEMS PREVENTATIVE MAINTENANCE, SOFTWARE & RECERTIFICATION	12.00	0.00	12.00	EA	12.00	\$7,900.00	\$94,800.00
		0050	5001	9109901	MISC.Misc. ITS Air Conditioner Repair at Node 19	0.00	1.00	1.00	LS	1.00	\$156.45	\$156.45
		0050	5002	9109901	MISC.Misc. ITS Air Conditioner Repair at Node 03	0.00	1.00	1.00	LS	0.00	\$156.45	\$0.00
		0050	5003	9109901	MISC.Misc. ITS Air Conditioner Repair at Node 25	0.00	1.00	1.00	LS	0.00	\$473.55	\$0.00
		0050	5004	9109901	MISC.Misc. ITS Air Conditioner Repair at Node 27	0.00	1.00	1.00	LS	0.00	\$156.45	\$0.00
	Project J60	Q3174E - To	tal Value	Posted to E	Date as of Report Generated Date							\$822,161.95
231117-F05 Overall - Total Value Posted to Date as of Report Generated Date									\$822,161.95			

Page 8 of 15 Revision 3/23/2023



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6O3174F

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0140	140 9103700 CCTV CAMERA ASSEMBI	CCTV CAMERA ASSEMBLY, INSTALLED	7/17/24	7/25/24	1.00	EA	IS044E290.1 I-44/I-55 @ NWQ - Per IssueTrak Ticket #2617					-Installed NEW Axis Q6075E and Cisco Switch at I-44II-55 NWQ CCTV - Per IssueTrack Ticket #2617 - NOT COMPLETE NEW S/N: B8A44F50C1FB
			7/18/24	7/25/24	1.00	EA	IS270W031.6 I-270 @ MO 367 NWQ - Per IssueTrak Ticket #2328					-Removed Bosch CCTV, Installed new Axis Q6075E at I-270 @ MO 367 NWQ - Per IssueTrak Ticket #2328 - COMPLETE
				7/25/24	1.00	EA	MO030W047.8 MO 30 @ Kingshighway - Per IssueTrak Ticket #2332					Removed Bosch CCTV, Installed new Axis Q6075E at MO 30 @ Kingshighway - Per IssueTrak Ticket #2332 - COMPLETE
			7/19/24	7/25/24	1.00	EA	IS170S007.1 I-170 at MO 115 - Per IssueTrak Ticket #2659					-Troubleshot, Removed and Replaced Bosch with Axis at I-170 at M0 115 - Per IssueTrak Ticket #2659 - COMPLETE NEW Axis S/N: B8A44F50C1F6
				7/25/24	1.00	EA	MO370E011.6 MO 370 E/O St. Louis Mills - Per IssueTrak Ticket#2600					-Troubleshot, Removed and Replaced Bosch with Axis at MO 370 E/O St. Louis Mills - Per IssueTrak Ticket #2600 COMPLETE NEW Axis S/N: B8A44F50C041
			7/22/24	7/25/24	1.00	EA	IS070W249.2 I-70 W/O Madison - Per IssueTrak Ticket #2251					Removed and Replaced CCTV at I-70 W/O Madison with New Axis CCTV - Per IssueTrak Ticket #2251 - COMPLETE NEW Axis S/N: B8A44F50C1EC
				7/25/24	1.00	EA	IS170N000.6 I-170 at Galleria Pkwy - Per IssueTrak Ticket #2562					-Removed and Replaced CCTV at I-170 @ Galleria Parkway with New Axis CCTV - Per IssueTrak Ticket #2562 - COMPLETE NEW Axis S/N: B8A44F50C281
			8/1/24	8/2/24	1.00	EA	IS044E263.3 EB I-44 E/O Six Flags - Per IssueTrak Ticket #2684					
				8/2/24	1.00	EA	RT00DW001.2 Route D W/O Schuetz - Per IssueTrak Ticket #2648					Removed and Replaced CCTV along Route D W/O Schuetz - Per IssueTrak Ticket #2648 - COMPLETE
0210	9109902	MISC. ITS	7/17/24	7/25/24	2.00	EA	IS044E290.1 I-44/I-55 @ NWQ - Per IssueTrak Ticket #2617					-Installed NEW Axis Q6075E and Cisco Switch at I-44/I-55 NWQ CCTV - Per IssueTrack Ticket #2617 - NOT COMPLETE
				7/25/24	5.00	EA	MO340W014.0 MO 340 @ Lindbergh - Per IssueTrak Ticket #2641					NEW S/N: B8A44F50C1FB Investigated Possible Options for MO 340 @ US 67 CCT Power Cable Rerouting. Submitted 3 Options to Nathan/ITS group, waiting on a response Per IssueTral Ticket #2641 - NOT COMPLETE
			7/19/24	7/25/24	10.00	EA	IS044E292.7 Node 21 - Per IssueTrak Ticket #2665					Replaced Pullbox lid for Concrete Single Pullbox near Node 21, Verified all power and fiber cables were not damaged - Per IssueTrak Ticket #2665
			7/25/24	7/31/24	1.00	EA	MO 100 @ Kingshighway - Per IssueTrak Ticket #2299					-Investigate Intersection for Video Detection Upgrades at MO 100 @ Kingshighway - Per IssueTrak Ticket #2299 - NOT COMPLETE
				7/31/24	1.00	EA	MO 141 @ Schneider - Per IssueTrak Ticket #2518					-Investigate Intersection for Video Detection Upgrades at MO 141 @ Schneider - Per IssueTrak Ticket #2518 - NO COMPLETE
				7/31/24	2.00	EA	MO 100 @ 4th St/Broadway - Per IssueTrak Ticket #2298					-Investigated Intersection for Video Detection Upgrades a MO 100 @ 4th St/Broadway - Per IssueTrak Ticket #229 - NOT COMPLETE
			7/26/24	8/2/24	7.00	EA	IS070W239.8 I-70 @ North Hanley Rd - Per IssueTrak Ticket #2729					-Investigate Mouse Damage at I-70 @ North Hanley Signat Cabinet, Verified that mouse damage did not cause outage in the area. OTDR to confirmPer IssueTrack Ticket #2729 - COMPLETE
			7/31/24	8/1/24	6.00	EA	IS055S207.4 Node 8, I-44/I-55 - Per IssueTrak Ticket #2746					-Investigated No Light on Fiber at Node 8 (I-44/I-55). Determined a Fiber was not moved over when new Switc was installed in Node Cabinet. Completed this swap, verified everything was corrected - Per IssueTrak Ticket #2746 - COMPLETE
0630	0 9109902 MISC. ITS	MISC. ITS	7/18/24	7/25/24	1.00	EA	IS270W031.6 I-270 @ MO 367 NWQ - Per IssueTrak Ticket #2328					-Removed Bosch CCTV, Installed new Axis Q6075E at I-270 @ MO 367 NWQ - Per IssueTrak Ticket #2328 - COMPLETE
				7/25/24	1.00	EA	MO030W047.8 MO 30 @ Kingshighway - Per IssueTrak Ticket #2332					Removed Bosch CCTV, Installed new Axis Q6075E at MO 30 @ Kingshighway - Per IssueTrak Ticket #2332 - COMPLETE
			7/19/24	7/25/24	1.00	EA	IS170S007.1 I-170 at MO 115 - Per IssueTrak Ticket #2659					-Troubleshot, Removed and Replaced Bosch with Axis at I-170 at M0 115 - Per IssueTrak Ticket #2659 - COMPLETE NEW Axis S/N: B8A44F50C1F6
				7/25/24	1.00	EA	MO370E011.6 MO 370 E/O St. Louis Mills - Per IssueTrak Ticket#2600					Troubleshot, Removed and Replaced Bosch with Axis at MO 370 E/O St. Louis Mills - Per IssueTrak Ticket #2600 COMPLETE NEW Axis S/N: B8A44F50C041
			7/22/24	7/25/24	1.00	EA	ISO70W249.2 I-70 W/O Madison - Per IssueTrak Ticket #2251					Removed and Replaced CCTV at I-70 W/O Madison with New Axis CCTV - Per IssueTrak Ticket #2251 - COMPLETE NEW Axis S/N: B8A44F50C1EC
				7/25/24	1.00	EA	IS170N000.6 I-170 at Galleria Pkwy - Per IssueTrak Ticket #2562					-Removed and Replaced CCTV at I-170 @ Galleria Parkway with New Axis CCTV - Per IssueTrak Ticket #2562 - COMPLETE NEW Axis S/N: B8A44F50C281
			8/1/24	8/2/24	1.00	EA	IS044E263.3 EB I-44 E/O Six Flags - Per IssueTrak Ticket #2684					-Removed and Replaced CCTV along EB I-44 E/O Six Flags - Per IssueTrak Ticket #2684 - COMPLETE
				8/2/24	1.00	EA	RT00DW001.2 Route D W/O Schuetz - Per IssueTrak Ticket #2648					Removed and Replaced CCTV along Route D W/O Schuetz - Per IssueTrak Ticket #2648 - COMPLETE
0820	9109902	MISC. ITS	7/17/24	7/25/24	1.00	EA	MO340W014.0 MO 340 @ Lindbergh - Per IssueTrak Ticket #2641					Investigated Possible Options for MO 340 @ US 67 CCT/ Power Cable Rerouting. Submitted 3 Options to Nathan/ITS group, waiting on a response Per IssueTral Ticket #2641 - NOT COMPLETE
			7/19/24	7/25/24	1.00	EA	IS044E292.7 Node 21 - Per IssueTrak Ticket #2665					Replaced Pullbox lid for Concrete Single Pullbox near Node 21, Verified all power and fiber cables were not damaged - Per IssueTrak Ticket #2665
			7/26/24	8/2/24	1.00	EA	IS070W239.8 I-70 @ North Hanley Rd - Per IssueTrak Ticket #2729					Investigate Mouse Damage at I-70 @ North Hanley Signat Cabinet, Verified that mouse damage did not cause outage in the area. OTDR to confirmPer IssueTrack Ticket #2729 - COMPLETE
			7/31/24	8/1/24	1.00	EA	IS055S207.4 Node 8, I-44/I-55 - Per IssueTrak Ticket #2746					Investigated No Light on Fiber at Node 8 (I-44/I-55). Determined a Fiber was not moved over when new Switci was installed in Node Cabinet. Completed this swap, verified everything was corrected - Per IssueTrak Ticket #2746 - COMPLETE
0980	9109903	MISC. ITS	7/31/24	8/1/24	372.00	LF	MO021N000.5 MO 21 @ Reavis and Lutheran South HS - Per IssueTrak Ticket #2552					-Replaced Cat5 for Wireless Radios at MO 21 @ Reavis and Lutheran South HS - Per IssueTrak Ticket #2552 - COMPLETE - Lutheran South HS - 197 LF Cat5e

Revision 3/23/2023 Page 9 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
								IVIIIC		IVIIIG		>Reavis - 175 LF Cat5e
1020	9109902	MISC. ITS	7/26/24	8/2/24	17.00	EA	MO 141 between I-70 and MO 364					-Installed Delineator Posts along MO 141 between I-70
												and MO 364 - 17 EACH
1040	1040 9109902	MISC. ITS	7/17/24	7/25/24	10.00	EA	US061N005.8 US 61 at Mueller SEQ US061N006.1 US 61 at MO 21 SEQ US061N008.1 US 61 at MO 30 SEQ US061N008.1 US 61 at Seqver NEQ US061N008.6 US 61 at West Watson-eddiEast & Park US061S005.5 US 61 at East Concord NEQ US061S005.5 US 61 at East Concord NEQ US061S005.9 US 61 at Hackberry NEQ US061S007.7 US 61 at Sappington SEQ US061S010.2 US 61 at Watson NWQ US061S010.2 US 61 at By Bend SEQ US061S010.9 US 61 at By Bend SEQ					US061N005.8 Camera - 40' US 61 at Mueller SEQ US061N005.6 Camera - 40' US 61 at MO 21 SEQ US061N008.1 Camera - 40' US 61 at MO 30 SEQ US061N008.1 Camera - 40' US 61 at MO 30 SEQ US061N009.6 Camera - 40' US 61 at Segver NEQ US061N009.6 Camera - 40' US 61 at West Watsonedificant 8. Page 10' US 61' US 61' at East Concord NEQ US061S005.5 Camera - 40' US 61 at East Concord NEQ US061S005.7 Camera - 40' US 61 at Hackberry NEQ US061S007.7 Camera - 40' US 61 at Sappington SEQ US061S010.2 Camera - 45' US 61 at Watson NWQ US061S010.2 Camera - 50' US 61 at Big Bend SEQ
			7/19/24	7/25/24	2.00	EA	IS170S007.1 I-170 at MO 115 IS270E001.2 I-270 at Theiss					IS170S007.1 Camera - 60' I-170 at MO 115 IS270E001.2 I-270 at Theiss
			7/22/24	7/25/24		EA	IS064W031.7 I-64 at I-170 NWQ (SB170 to eager) IS064W036.5 I-64 at Vandeventer					IS064W031.7 Camera - 70' (4) I-64 at I-170 NWQ (SB170 to eager) IS064W036.5 Camera - 70' I-64 at Vandeventer
1070	9109902	MISC. ITS	7/23/24	7/25/24	2.00	EA	IS044W262.1-44 e/o Allenton-Six Flags IS044W262.1s I-44 e/o Allenton-Six Flags					IS044W262.1m Led DM Panel 1 -middle lane I-44 e/o Allenton-Six Flags(overhead sign) IS044W262.1s Led DM Panel 1 - slow lane I-44 e/o Allenton-Six Flags(overhead sign)
1080	1080 9109902	MISC. ITS	7/23/24	7/25/24	4.00	EA	ISO44E255.0 -44 w/o Allenton ISO44E260.0 -04 e/o Pacific-Viaduct ISO44W265.5 -44 w/o Lewis Rd ISO44W264.0 141 -44 w/o MO 109					ISO44E255.0 DMS - Led 2 135 I-44 w/o Allenton (CTL-23) ISO44E260.0 DMS - Led 4 1 I-44 e/o Pacific-Viaduct (CTL-24) ISO44W265.5 DMS - Led 2 1 (137) I-44 w/o Lewis Rd (CTL-24) ISO44W264.0 DMS - Led 2 141 I-44 w/o MO 109 (CTL-23)
			7/24/24	8/2/24	5.00	EA	MID44E246 4 I-44 wio Shawneetown Ford Rd MID44E249 9 J-44 at American In ISO44W250.2 I-44 wio Six Flags ISO44W255.1 I-44 eio MO 100 Gray Summit ISO44W249.9 I-44 at American Inn					MI044E246 4 Led 3 Statewide 1 - L27-27x90 L44 w/o Shawmeetown Ford R4 (CTL-24) MI044E249 9 Led 2 Statewide 1 - L27-27x90 L44 at American Inn (CTL-23) IS044W260.2 Led 3 Statewide 1 - L27-27x90 L44 w/o Six Flags (CTL-24) IS044W255.1 Led 2 Statewide 1 - L27-27x90 L44 e/o MO 100 Gray Sumit (CTL-23) IS044W249 9 Led 2 Statewide 1 - L27-27x90 L44 at American Inn (CTL-23)
			7/25/24	7/31/24	5.00	EA	IS044E263.4 I-44 w/o MO 109 IS044E271.8 140 I-44 w/o MO 141 IS044E274.9 I-44 at Mraz Ln IS044E279.7 I-44 e/o Sappington IS044W275.1 I-44 e/o Mraz Ln					ISO44E263.4 DMS - Led 4 1 I-44 w/o MO 109 (CTL-24) ISO44E271.8 DMS - Led 2 140 I-44 w/o MO 141 (CTL-23) ISO44E274.9 DMS - Led 2 2 04 I-44 at Mraz Ln (CTL-23) ISO44E279.7 DMS - Led 2 142 I-44 e/o Sappington (CTL-23) ISO44W275.1 DMS - Led 2 143 I-44 e/o Mraz Ln (CTL-23) ISO44W275.1 DMS - Led 2 143 I-44 e/o Mraz Ln (CTL-23)
			7/26/24	8/2/24		EA	ISO44E287.5 I-44 e/o Vandeventer Ave ISO44E292.9 I-44 w/o Cass Ave ISO44WV28.8 1 I-44 w/o Grand ISO44WV28.5 I-44 e/o Murdoch ISO44WV28.7 I-44 e/o Murdoch ISO44WV27.9 7 I-44 w/o Berry Rd ISO5SS193.6 I-55 s/o Meramec Bottom					ISO44E287.9 DMS - Led 2 (1) 138 I-44 e/o Vandeventer Ave (CTIL-23) SE4E292.9 DMS - SESA 1 I-44 w/o Cass Ave (CTIL-23) ISO44E282.1 DMS - Led 3 1 (144) I-44 w/o Grand (CTIL-23) ISO44W283.1 DMS - Led 4 1 I-44 e/o Murdoch (CTIL-24) ISO44W279.7 DMS - Led 2 139 I-44 w/o Berry Rd (CTIL-23) ISO55919.3 DMS - Led 3 157 I-55 s/o Meramec Bottom (CTIL-24) ISO55919.3 DMS - Led 3 157 I-55 s/o Meramec Bottom (CTIL-23) ISO55919.3 DMS - Led 3 157 I-55 s/o Meramec Bottom (CTIL-23)
			7/30/24	8/1/24	6.00	EA	IS055N171.9 I-55 n/o US 61 IS05SN193.3 I-55 at Haeferte (s/o RT M) IS05SN190.3 I-55 slo MO 141 IS05SN3 186.8 I-55 slo Imperial-Main IS05SS1386.8 I-55 slo RT M IS05SS1384.6 I-55 slo RT M IS05SS1377.8 I-55 n/o RT A (s/o McNutt)					ISOS5N171.9 DMS - Led 3 1 I-55 n/o US 61 (CTL-23) ISOS5N193.5 DMS - Led 3 1 I-55 at Haefner (s/o RT M) (CTL-23) ISOS5N190.9 DMS - Led 3 1 I-55 s/o MO 141 (CTL-23) ISOS5196.8 DMS - Led 3 186 I-55 s/o Imperial-Main (CTL-23) ISOS55194.6 DMS - Led 3 1 I-55 s/o RT M (CTL-23) ISOS55177.8 DMS - Led 3 1 I-55 n/o RT A (s/o McNutt) (CTL-23)
1350	9109902	MISC. ITS	7/22/24	7/25/24	3.00	EA	WB I-44 at MO 100 East (Gray Summit) Exit 253 Exit to WB I-44 Rest Stop at St. Clair Exit to EB I-44 Rest Stop at St. Clair					TAPCO Wrong Way Site Preventative Maintenance at 3 Locations: WB I-44 at MO 100 East (Gray Summit) Exit 253 Exit to WB I-44 Rest Stop at St. Clair Exit to EB I-44 Rest Stop at St. Clair
			7/23/24	7/25/24	5.00	EA	WB 370 at 141 Exit 9 EB I-70 to W. Florissant Exit 245B WB I-44 to Jefferson Exit 289 WB I-44 to Grand Exit 288 WB I-44 to Hampton Exit 288					WB 370 at 141 Exit 9 EB I-70 to W. Florissant Exit 245B WB I-44 to Jefferson Exit 289 WB I-44 to Grand Exit 288 WB I-44 to Hampton Exit 286
			7/24/24	8/2/24	4.00	EA	WB I-44 to Arsenal Exit 284B EB I-44 to Hampton Exit 286 EB I-44 to South Jefferson Exit 289 EB I-44 to Lafayette Exit 290B					WB I-44 to Arsenal Exit 284B EB I-44 to Hampton Exit 286 EB I-44 to South Jefferson Exit 289 EB I-44 to Lafayette Exit 290B

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023 Page 10 of 15



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
4E	0150	CONDUIT, 2 IN., RIGID, IN	Material		2	Feb 1, 2024	SYSTEM	\$55.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
		TRENCH			2	Feb 1, 2024	SYSTEM	(\$55.00)				
					3	Feb 16, 2024	SYSTEM	\$55.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					3	Feb 16, 2024	SYSTEM	(\$55.00)				
					4	Mar 4, 2024	SYSTEM	\$1,045.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					4	Mar 4, 2024	SYSTEM	(\$1,045.00)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0150 -	Total						\$0.00				
	0160	CONDUIT, 3 IN., RIGID, IN TRENCH	Material		3	Feb 16, 2024	SYSTEM	\$182.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Paymen Estimate Exception 2 on the current Payment Estimate.			
						3	Feb 16, 2024	SYSTEM	(\$182.00)			
							4	Mar 4, 2024	SYSTEM	\$182.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user norton1 overridding Paymen Estimate Exception 2 on the current Payment Estimate.	
					4	Mar 4, 2024	SYSTEM	(\$182.00)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0160 -	Total						\$0.00				
	0210	MISC. ITS	Material		1	Jan 16, 2024	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user norton1 overridding Paymen Estimate Exception 1 on the current Payment Estimate.			
					1	Jan 16, 2024	SYSTEM	(\$600.00)				
				- Total								
			Material - To	otal				\$0.00				
			Overrun	Overrun	Overrun	Overrun	Overrun	Overrun	9	May 16, 2024	SYSTEM	\$3,600.00
										9	May 16, 2024	SYSTEM
					9	May 16, 2024	SYSTEM	(\$4,200.00)				
				Overrun - T	otal			\$0.00				
								\$0.00				
			Overrun - T	otal								
	0210 -	Total	Overrun - To	otal				\$0.00				
	0210 - 0250	Total MISC. ITS		Overrun	9	May 16, 2024	SYSTEM	\$0.00 \$2,120.00				
					9		SYSTEM SYSTEM					
				Overrun	9	2024 May 16,		\$2,120.00 (\$2,120.00)	Estimate Item Adjustment (0003) due to user norton1 overridding Paymen			
			Overrun	Overrun Overrun - T	9	2024 May 16,		\$2,120.00 (\$2,120.00) \$0.00	Estimate Item Adjustment (0003) due to user norton1 overridding Paymen			
	0250	MISC. ITS		Overrun Overrun - T	9	2024 May 16,		\$2,120.00 (\$2,120.00) \$0.00 \$0.00	Estimate Item Adjustment (0003) due to user norton1 overridding Paymen			
		MISC. ITS	Overrun - To	Overrun Overrun - T	9	2024 May 16,		\$2,120.00 (\$2,120.00) \$0.00	Estimate Item Adjustment (0003) due to user norton1 overridding Paymen			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
6Q3174E	0280	MISC. ITS	Material	,,,	3	Feb 16, 2024	SYSTEM	(\$7,600.00)				
					4	Mar 4, 2024	SYSTEM	\$7,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					4	Mar 4, 2024	SYSTEM	(\$7,600.00)				
				- Total				\$0.00				
			Material - To					\$0.00				
			Overrun	Overrun	11	Jun 17,	SYSTEM	(\$3,800.00)				
					12	Jul 1, 2024	SYSTEM	\$3,800.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3800.00000 - 3800.00000, 'is applied (if non-zero).			
					un Total			00.00	is applied (ii non-zero).			
				Overrun - T	otai			\$0.00				
			Overrun - T	otal ————				\$0.00				
	0280 -	Total						\$0.00				
	0330	MISC. ITS	Material		8	May 2, 2024	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					8	May 2, 2024	SYSTEM	(\$1,000.00)				
								9	May 16, 2024	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	May 16, 2024	SYSTEM	(\$1,000.00)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
			Overrun	Overrun	13	Jul 16, 2024	SYSTEM	(\$1,000.00)				
					14	Aug 2, 2024	SYSTEM	\$1,000.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1000.00000 - 1000.00000, 'is applied (if non-zero).			
				Overrun - T	otal			\$0.00				
			Overrun - T	otal				\$0.00				
	0330 -	Total						\$0.00				
	0340	MISC. ITS	Overrun	Overrun	Overrun	8	May 2, 2024	SYSTEM	\$925.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					8	May 2, 2024	SYSTEM	(\$925.00)				
					9	May 16, 2024	SYSTEM	(\$925.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).			
					9	May 16, 2024	SYSTEM	(\$925.00)				
					10	Jun 3, 2024	SYSTEM	\$1,850.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',925.00000 - 925.00000, 'is applied (if non-zero).			
				Overrun - T	otal			\$0.00				
			Overrun - T	otal				\$0.00				
	0340 -	Total						\$0.00				
	0350	MISC. ITS	Overrun	Overrun	11	Jun 17, 2024	SYSTEM	(\$60.00)				
					12	Jul 1, 2024	SYSTEM	\$60.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',30.00000 - 30.00000, 'is applied (if non-zero).			
				Overrun - T	otal			\$0.00				
			Overrun - T	otal				\$0.00				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J6Q3174E	0350 -	Total						\$0.00			
	0780	MISC. ITS	Overrun	Overrun	13	Jul 16, 2024	SYSTEM	(\$235.00)			
					14	Aug 2, 2024	SYSTEM	\$235.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',235.00000 - 235.00000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - To	otal				\$0.00			
	0780 -	Total						\$0.00			
	0820	MISC. ITS	MISC. ITS	20 MISC. ITS	Material		1	Jan 16, 2024	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Jan 16, 2024	SYSTEM	(\$600.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0820 -	Total						\$0.00			
	0920	20 MISC. ITS	MISC. ITS	Material		4	Mar 4, 2024	SYSTEM	\$280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user norton1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					4	Mar 4, 2024	SYSTEM	(\$280.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
			Overrun	Overrun	7	Apr 16, 2024	SYSTEM	\$7,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					7	Apr 16, 2024	SYSTEM	(\$7,980.00)			
					9	May 16, 2024	SYSTEM	\$595.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
					9	May 16, 2024	SYSTEM	(\$595.00)			
				Overrun - T	otal			\$0.00			
			Overrun - T	otal				\$0.00			
	0920 -	Total						\$0.00			
	0990	MISC. ITS	MISC. ITS	90 MISC. ITS	Material		3	Feb 16, 2024	SYSTEM	\$7,490.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user norton1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Feb 16, 2024	SYSTEM	(\$7,490.70)			
					4	Mar 4, 2024	SYSTEM	\$33,660.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
					4	Mar 4, 2024	SYSTEM	(\$33,660.90)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0990 -	Total									
	1000	MISC. ITS	Material		3	Feb 16, 2024	SYSTEM	\$17,670.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
					3	Feb 16, 2024	SYSTEM	(\$17,670.00)			
					4	Mar 4, 2024	SYSTEM	\$22,012.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
					4	Mar 4,	SYSTEM	(\$22,012.50)			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6Q3174E	1000	MISC. ITS	Material			2024			
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	4	Mar 4, 2024	SYSTEM	\$3,262.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Mar 4, 2024	SYSTEM	(\$3,262.50)	
					9	May 16, 2024	SYSTEM	\$1,125.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	May 16, 2024	SYSTEM	\$6,795.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	May 16, 2024	SYSTEM	(\$7,920.00)	
						11	Jun 17, 2024	SYSTEM	(\$1,470.00)
					12	Jul 1, 2024	SYSTEM	\$1,470.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3.75000 - 3.75000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	otal				\$0.00	
	1000 -	- Total							
	1010	MISC. ITS	Material		1	Jan 16, 2024	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user norton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Jan 16, 2024	SYSTEM	(\$700.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1010 -	Total						\$0.00	
J6Q3174E -	- Total							\$0.00	
Overall - To	otal							\$0.00	

MoDOT

Contract Adjustments for Contract - 231117-F05

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 15 of 15