

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 15, 2024

Progress Esti	mate Number 3	Contract ID Prime Contractor	231215-F04 J M Scheidle, LLC	Pay Period Start Pay Period End	May 2, 2024 May 15, 2024	Original Contract Amount Net Change Order Amount Current Contract Amount	\$948,648.94 \$0.00 \$948,648.94		
Approval Date	proval Date								
May 15, 2024	Generated and Approved (and should be considered Draft) at the Project Office Level by								
May 16, 2024		Review	ved and Approved (a	and should be conside	ered Draft) at the	e Resident Engineer Level by	REDHAC		
May 17, 2024			Revie	wed and Approved at	the Central Offic	ce Controllers Office Level by	ramses1		
Original Comp	Original Completion Date		tion Date	Actual Completion D	ate	% of Current Contract Amoun	t Complete		
November	1 2024	November 1	2024			11 20%			

	Milestones		
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	January 3, 2024	January 3, 2024	
Letting Date	December 15, 2023	December 15, 2023	
Notice to Proceed Date	February 5, 2024	February 5, 2024	
Open to Traffic Date			
Work Began Date			

Contract Total Pa	y For Estimate No. 3				
		This Estimate	Previous	To Date	
231215-F04					
	Total Posted Items Pay	\$7,200.00	\$99,020.25	\$106,220.25	
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$99,020.25	\$106,220.25	
Contract Total Pa	yable This Estimate:	\$7,200.00			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Current Installed Amount					
JSL0040	0100	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN, CONTRACTOR FURNISHED/RETAINED	\$7,200.00					
Project JSL0040 - Total									
Overall - Total									

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JSL0040	0100	MISC.	Material			-2	\$3,600.00	(\$7,200.00)
	0100	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	2	\$3,600.00	\$7,200.00
	0210	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	Material			-5	\$350.00	(\$1,750.00)
	0210	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	5	\$350.00	\$1,750.00

Revision 3/23/2023 Page 1 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 15, 2024

Progress Estimate Number Contract ID 231215-F04 Pay Period Start May 2, 2024 Prime Contractor J M Scheidle, LLC Pay Period End May 15, 2024	- 3 · · · · · · · · · · · · · · · · · · ·	\$948,648.94 \$0.00 \$948.648.94
---	--	--

Number No.	,040.94
U-CHANNEL POST, 3 LB Material This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment Estimate. 0230 2 IN. PSST POST - 12 GA. Material This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. 0240 DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. Material This adjustment offsets the original system- generated Material Exception 5 on the current Payment Estimate. 54 \$135.00 (\$ This adjustment offsets the original system- sequence For 2 IN. PSST - 12 GA. This adjustment offsets the original system- Adjustment (0005) due to user bowmam2 overridding Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 6 on	djustment amount
generated Material Payment Estimate Item Adjustment (0003) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment Estimate. 2 IN. PSST POST - 12 GA. Material 2 IN. PSST POST - 12 GA. Material 3 Inis adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. 3 Inis adjustment Exception 5 on This adjustment offsets the original system- generated Material Payment Estimate. 4 Inis adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 6 on	\$5,016.00
2 IN. PSST POST - 12 GA. Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 6 on	\$5,016.00
generated Material Payment Estimate Item Adjustment (0004) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. Material This adjustment offsets the original system- generated Material Payment Estimate -54 \$135.00 (3) This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 6 on	14,775.00
FOR 2 IN. PSST - 12 GA. DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 6 on	14,775.00
FOR 2 IN. PSST - 12 GA. generated Material Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 6 on	\$7,290.00
the current Payment Estimate.	\$7,290.00
0250 2.25 IN. PSST POST INSERT (6 FT.) - 12 GA.	(\$750.00)
0250 2.25 IN. PSST POST INSERT (6 FT.) - 12 GA. Material (6 FT.) - 12 GA. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate.	\$750.00
0260 2.5 IN. PSST POST - 12 GA. Material -128 \$25.00 (\$3,200.00
0260 2.5 IN. PSST POST - 12 GA. Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 8 on the current Payment Estimate.	\$3,200.00
0270 DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA. Material -9 \$135.00 (\$1,215.00
DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA. Material generated Material Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate.	\$1,215.00
Total	\$0.00

Revision 3/23/2023 Page 2 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Con	tract Project Informat	ion
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
JSL0040	.0040 FAS- S503 (054) Resurface C JEFFERSON from Route B to Route Y						
Totals by J	Job Numbe	ers					
JSL0040		ed Item Pay s Item Adjustn		s Item Pay	This Estimate \$7,200.00 \$0.00 \$7,200.00	Previous \$99,020.25 \$0.00 \$99,020.25	To Date \$106,220.25 \$0.00 \$106,220.25
	Liqui	itive centive dated Damage r Contract Adj		5	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 3/23/2023 Page 3 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JSL0040, Item 6169902, Project Item Line Number 0100, Material Set 616990296, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Wait on certs and sample records.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0040, Item 9031241, Project Item Line Number 0210, Material Set 903124196, Material 0903HSSBPSST - Slip Base PSST Posts, Acceptance Action Generic 0903HSSBPSST is insufficient.	Wait on certs and sample records.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0040, Item 9031241, Project Item Line Number 0210, Material Set 903124196, Material 0903HSBA - Breakaway Assembly for Highway Signing, Acceptance Action Generic 0903HSBA is insufficient.	Wait on certs and sample records.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0040, Item 9031250A, Project Item Line Number 0220, Material Set 9031250A96, Material 0903HSPSUC - U-Channel Post for Highway Signing, Acceptance Action Generic 0903HSPSUC is insufficient.	Wait on certs and sample records.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0040, Item 9031270A, Project Item Line Number 0230, Material Set 9031270A96, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Wait on certs and sample records.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0040, Item 9031271A, Project Item Line Number 0240, Material Set 9031271A, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Wait on certs and sample records.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0040, Item 9031272A, Project Item Line Number 0250, Material Set 9031272A, Material 0903HSSBPSST - Slip Base PSST Posts, Acceptance Action Generic 0903HSSBPSST is insufficient.	Wait on certs and sample records.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0040, Item 9031280, Project Item Line Number 0260, Material Set 903128096, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Wait on certs and sample records.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0040, Item 9031281A, Project Item Line Number 0270, Material Set 9031281A, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Wait on certs and sample records.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0040, Item 9031281A, Project Item Line Number 0270, Material Set 9031281A, Material 0903HSSBPSST - Slip Base PSST Posts, Acceptance Action Generic 0903HSSBPSST is insufficient.	Wait on certs and sample records.	BOWMAM2	Overridden

Revision 3/23/2023 Page 4 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)			
31215-F04	JSL0040	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.75	\$2,400.00	\$1,800.00			
		0001	0020	2159910	MISC.SHAPING SLOPES CLASS III - MODIFIED MATERIAL REQUIREMENTS	11.00	0.00	11.00	100F	0.00	\$1,200.00	\$0.00			
		0001	0030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	67.00	0.00	67.00	TONS	0.00	\$65.00	\$0.00			
		0001	0040	4019910	MISC.BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2LT)	5,377.90	0.00	5,377.90	TONS	0.00	\$91.00	\$0.00			
		0001	0050	4071005	TACK COAT	5,326.00	0.00	5,326.00	GAL	0.00	\$3.00	\$0.00			
		0001	0060	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1,775.00	\$0.00			
		0001	0070	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	966.30	0.00	966.30	TONS	0.00	\$100.00	\$0.00			
		0001	0080	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	5,915.60	0.00	5,915.60	SQYD	0.00	\$12.50	\$0.00			
		0001	0090	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.00	\$9,000.00	\$0.00			
		0001	0100	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN, CONTRACTOR FURNISHED/RETAINED	6.00	0.00	6.00	EA	2.00	\$3,600.00	\$7,200.00			
		0001	0110	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$73,000.00	\$0.00			
		0001	0111	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.25	\$44,541.00	\$11,135.25			
		0001	0120	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	22.00	0.00	22.00	LF	0.00	\$52.00	\$0.00			
		0001	0130	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	48,362.00	0.00	48,362.00	LF	0.00	\$0.16	\$0.00			
		0001	0140	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	48,932.00	0.00	48,932.00	LF	0.00	\$0.16	\$0.00			
		0001	0150	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,348.00	0.00	2,348.00	SQYD	0.00	\$12.50	\$0.00			
		0001	0160	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.25	\$2,500.00	\$625.00			
		0010	0170	6061060	MGS GUARDRAIL	363.00	0.00	363.00	LF	0.00	\$30.00	\$0.00			
		0010	0180	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	0.00	\$3,000.00	\$0.00			
		0010	0190	6061074	MGS HEIGHT AND BLOCK TRANSITION	1.00	0.00	1.00	EA	0.00	\$1,100.00	\$0.00			
		0010	0200	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	5.00	0.00	5.00	EA	0.00	\$3,100.00	\$0.00			
		0040	0210	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	5.00	0.00	5.00	EA	5.00	\$350.00	\$1,750.00			
		0040	0220	9031250A	U-CHANNEL POST, 3 LB	209.00	0.00	209.00	LF	209.00	\$24.00	\$5,016.00			
		0040	0230	9031270A	2 IN. PSST POST - 12 GA.	591.00	0.00	591.00	LF	591.00	\$25.00	\$14,775.00			
		0040	0240	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	54.00	0.00	54.00	EA	54.00	\$135.00	\$7,290.00			
		0040	0250	9031272A	2.25 IN. PSST POST INSERT (6 FT.) - 12 GA.	5.00	0.00	5.00	EA	5.00	\$150.00	\$750.00			
		0040	0260	9031280	2.5 IN. PSST POST - 12 GA.	128.00	0.00	128.00	LF	128.00	\$25.00	\$3,200.00			
		0040	0270	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	9.00	0.00	9.00	EA	9.00	\$135.00	\$1,215.00			
		0040	0280	9035004A	SH-FLAT SHEET	167.00	0.00	167.00	SQFT	163.00	\$25.00	\$4,075.00			
		0040	0290	9035069A	SHF-FLAT SHEET FLUORESCENT	562.00	0.00	562.00	SQFT	547.00	\$30.00	\$16,410.00			
		0040	0300	9035071A	STF-STRUCTURAL FLUORESCENT	72.00	0.00	72.00	SQFT	72.00	\$35.00	35.00 \$2,520.00			
		0001	5001	6189901	MISC.Contract Bond.	0.00	1.00	1.00	LS	1.00	\$28,459.00	\$28,459.00			
	Project J	SL0040 - To	otal Value	Posted to D	Date as of Report Generated Date							\$106,220.25			
1215-F04 Ove	rall - Total	Value Post	ed to Da	te as of Repo	ort Generated Date							\$106,220.25			

Revision 3/23/2023 Page 5 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: JSL0040

Line lumber	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance		Offset/ Distance	Comments
0100	6169902	MISC. TRAFFIC CONTROL DEVICES	5/6/24	5/9/24	2.00	EA	@ Route Y and Route C @ Route B and Route C	0+00		245+94		

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023 Page 6 of 9



Line Item Adjustments by Estimate

Contract ID: 231215-F04

roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
L0040	0100	MISC. TRAFFIC CONTROL DEVICES	Material		3	May 15, 2024	SYSTEM	\$7,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		DEVICES			3	May 15, 2024	SYSTEM	(\$7,200.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0100 -	Total						\$0.00	
	0210	BREAKAWAY ASSEMBLY (PERFORATED	Material		2	May 2, 2024	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		SQUARE STEEL TUBE)			2	May 2, 2024	SYSTEM	(\$1,750.00)	
					3	May 15, 2024	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	May 15, 2024	SYSTEM	(\$1,750.00)	
				- Total				\$0.00	
			Material - To	al - Total				\$0.00	
	0210 -	Total						\$0.00	
	0220	U-CHANNEL POST, 3 LB	Material		2	May 2, 2024	SYSTEM	\$5,016.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user bowmam2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	May 2, 2024	SYSTEM	(\$5,016.00)	
					3	May 15, 2024	SYSTEM	\$5,016.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	May 15, 2024	SYSTEM	(\$5,016.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0220 -	Total						\$0.00	
	0230	2 IN. PSST POST - 12 GA.	Material		2	May 2, 2024	SYSTEM	\$14,775.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	May 2, 2024	SYSTEM	(\$14,775.00)	
					3	May 15, 2024	SYSTEM	\$14,775.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	May 15, 2024	SYSTEM	(\$14,775.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0230 -	Total						\$0.00	
	0240	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12	Material		2	May 2, 2024	SYSTEM	\$7,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		GA.			2	May 2, 2024	SYSTEM	(\$7,290.00)	
					3	May 15, 2024	SYSTEM	\$7,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	May 15, 2024	SYSTEM	(\$7,290.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0240 -	Total						\$0.00	





Line Item Adjustments by Estimate

Contract ID: 231215-F04

	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Type	Adjustment Type	Number	Date	Ву		
SL0040	0250	2.25 IN. PSST POST INSERT (6 FT.) - 12 GA.	Material		2	May 2, 2024	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					2	May 2, 2024	SYSTEM	(\$750.00)	
					3	May 15, 2024	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	May 15, 2024	SYSTEM	(\$750.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0250 -	250 - Total						\$0.00	
	0260	2.5 IN. PSST POST - 12 GA.	Material		2	May 2, 2024	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					2	May 2, 2024	SYSTEM	(\$3,200.00)	
					3	May 15, 2024	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	May 15,	SYSTEM	(\$3,200.00)	
						2024		, ,	
				- Total				\$0.00	
			Material - To		3			,	
	0260 -	· Total	Material - To					\$0.00	
	0260 - 0270	DRIVEN POST ANCHOR FOR 2.5 IN. PSST -	Material - To		2		SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
I		DRIVEN POST ANCHOR FOR				2024 May 2,		\$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment
		DRIVEN POST ANCHOR FOR 2.5 IN. PSST -			2	May 2, 2024 May 2, 2024	SYSTEM	\$0.00 \$0.00 \$0.00 \$1,215.00	Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment
		DRIVEN POST ANCHOR FOR 2.5 IN. PSST -			2	May 2, 2024 May 2, 2024 May 15,	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$1,215.00 (\$1,215.00)	Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment
		DRIVEN POST ANCHOR FOR 2.5 IN. PSST -			2 2 3	May 2, 2024 May 2, 2024 May 15, 2024 May 15,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$1,215.00 (\$1,215.00) \$1,215.00	Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment
		DRIVEN POST ANCHOR FOR 2.5 IN. PSST -		otal - Total	2 2 3	May 2, 2024 May 2, 2024 May 15, 2024 May 15,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$1,215.00 (\$1,215.00) \$1,215.00	Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment
		DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Material	otal - Total	2 2 3	May 2, 2024 May 2, 2024 May 15, 2024 May 15,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$1,215.00 (\$1,215.00) \$1,215.00 (\$1,215.00)	Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment
SL0040 -	0270	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Material	otal - Total	2 2 3	May 2, 2024 May 2, 2024 May 15, 2024 May 15,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,215.00 (\$1,215.00) \$1,215.00 (\$1,215.00)	Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment

MoDOT

Contract Adjustments for Contract - 231215-F04

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 9 of 9