

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 15, 2025

Progress Estimate 9	Number	Contract ID Prime Contracto	240216-H02 or Apex Paving C		eriod Start eriod End	January 2, January 15		Original Contract Amount Net Change Order Amount Current Contract Amount	\$3,009,744.25 \$57,146.39 \$3,066,890.64		
Approval Date									By User		
January 15, 2025			Generated and A	pproved (a	and should b	holtb3					
January 16, 2025		Re	viewed and Approv	ed (and s	hould be co	nsidered Dra	ft) at the	Resident Engineer Level by	plottk1		
January 17, 2025		Reviewed and Approved at the Central Office Controllers Office Level by ramse									
Original Completi	on Date	Current Com	pletion Date	Actu	al Completion	on Date		% of Current Contract Amou	nt Complete		
November 1, 2	025	Novembe	er 1, 2025	r 1, 2025				19.77%			
	Contract	Informational Dat	es			Milestones					
Date Description	Original	Completion Date	Current Complet	ion Date	No Milesto	nes Exist for	Contra	ct			
Acceptance Date											
Awarded Date	March 6,	2024	March 6, 2024								
Letting Date	February	16, 2024	February 16, 2024								
Notice to Proceed Dat	e April 8, 2	024	April 8, 2024								
Open to Traffic Date											
Work Began Date											

Contract Total Pa	ay For Estimate No. 9			
		This Estimate	Previous	To Date
240216-H02				
	Total Posted Items Pay	\$0.00	\$606,459.12	\$606,459.12
	Gross Item Adjustments	\$1,328.00	\$13,714.95	\$15,042.95
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$620,174.07	\$621,502.07
Contract Total Pa	ayable This Estimate:	\$1,328.00		

#### Items Paid This Estimate Period

No Data Available

#### Contract Adjustments This Estimate

	,	ments Exist on Contract ents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3121B	0490	K-31 TALL FESCUE SODDING	Other Item Adjustment		Acceptable growth has been obtained			\$1,328.00
	0500	ALTERNATE DITCH CHECK	Material			-33	\$20.00	(\$660.00)
	0500	ALTERNATE DITCH CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user canton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	33	\$20.00	\$660.00
Total								\$1,328.00

Page 1 of 15 Revision 3/23/2023



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9P3121B	FAF 34-1(47)	Resurface	72	CAPE GIRARDEAU	from Route 34 to Rou	ite61/Route 25 in Jackson	
Totals by Jo	b Number	'S					
•					This Estimate	Previous	To Date
J9P3121B		I Item Pay			This Estimate \$0.00	Previous \$606,459.12	<b>To Date</b> \$606,459.12
•	Posted		ents				
•	Posted	I Item Pay		Item Pay	\$0.00	\$606,459.12	\$606,459.12
•	Posted Gross	I Item Pay Item Adjustme		Item Pay	\$0.00 \$1,328.00 <b>\$1,328.00</b>	\$606,459.12 \$13,714.95 <b>\$620,174.07</b>	\$606,459.12 \$15,042.95 <b>\$621,502.07</b>
•	Posted Gross	I Item Pay Item Adjustme		Item Pay	\$0.00 \$1,328.00 <b>\$1,328.00</b> \$0.00	\$606,459.12 \$13,714.95 <b>\$620,174.07</b> \$0.00	\$606,459.12 \$15,042.95 <b>\$621,502.07</b> \$0.00
•	Posted Gross Incenti Disince	I Item Pay Item Adjustme	Gross	Item Pay	\$0.00 \$1,328.00 <b>\$1,328.00</b>	\$606,459.12 \$13,714.95 <b>\$620,174.07</b>	\$606,459.12 \$15,042.95 <b>\$621,502.07</b>

Revision 3/23/2023 Page 2 of 15



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9P3121B, Item 3040504, Project Item Line Number 0040, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Waiting on QC results	canton1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3121B, Item 6092011, Project Item Line Number 0140, Material Set 609201196, Material 1057JMTBE42013 - Tie Bar Ep Ctd 12" No. 4/M13 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL from contractor	canton1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3121B, Item 6131015, Project Item Line Number 0200, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL from contractor	canton1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3121B, Item 6131018, Project Item Line Number 0220, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL from contractor	canton1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3121B, Item 8061006, Project Item Line Number 0500, Material Set 806100696, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Waiting on certification from contractor	canton1	Overridden
Estimate Exception Type: Item Overrun: Contract 240216-H02, Contract Project J9P3121B, Project Item Line Number 0130, Contract Line Item Number 0130, Item 6091052, Minor Item.	No Remark was entered by Engineer	canton1	Acknowledged

Revision 3/23/2023 Page 3 of 15



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	port Generated date and can differ from the posted amou Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
40040 1100	10004040		0040	0000040	DEMONAL OF IMPROVEMENTS	4.00			1.0	Qty	040,000,00	
240216-H02	J9P3121B	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.50	\$12,990.00	\$6,495.00
		0001	0020	2072000	LINEAR GRADING CLASS 2  MISC.SHAPING SLOPES CLASS III - MODIFIED MATERIAL	3.30 6.00	0.00	3.30 6.00	STA 100F	3.30 0.00	\$2,460.00 \$1,400.00	\$8,118.00
		0001			REQUIREMENT							
		0001	0040	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	233.00	0.00	233.00	SQYD	233.00	\$12.00	\$2,796.00
		0001	0050	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	513.00	71.20	584.20	SQYD	584.20	\$11.00	\$6,426.20
		0001	0060	3105002 4019905	GRAVEL (A) OR CRUSHED STONE (B)  MISC.OPTIONAL PAVEMENT	5.00	0.00	5.00	TONS	0.00 512.20	\$593.19 \$124.00	\$0.00 \$63,512.80
		0001	0080	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	9.131.80	0.00	9,131.80	TONS	828.53	\$136.69	\$113,251.77
		0001	0090	4071005	TACK COAT	9,277.00	0.00	9,277.00	GAL	853.00	\$3.31	\$2,823.43
		0001	0100	6089905	MISC.CONCRETE MEDIAN - TINTED AND STAMPED	232.30	0.00	232.30	SQYD	232.30	\$104.00	\$24,159.20
		0001	0110	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	63.00	0.00	63.00	LF	0.00	\$58.00	\$0.00
		0001	0120	6091042	CONCRETE GUTTER TYPE B	2.00	0.00	2.00	LF	0.00	\$135.00	\$0.00
		0001	0130	6091052	CURB AND GUTTER TYPE B	57.00	0.00	57.00	LF	85.50	\$59.00	\$5,044.50
		0001	0140	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	90.00	0.00	90.00	LF	37.20	\$48.00	\$1,785.60
		0001	0150	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$0.00	\$0.00
		0001	0160	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL	398.50	161.80	560.30	SQYD	560.30	\$321.05	\$179,884.32
		0001	0170	6131012	DEPTH PAVEMENT REPAIR  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	175.00	-117.00	58.00	SQYD	58.00	\$8.40	\$487.20
		0001	0180	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)	175.00	-109.00	66.00	SQYD	66.00	\$12.90	\$851.40
					(PAVEMENT REPAIR)							
		0001	0190	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	1,559.00	406.00	1,965.00	LF	1,965.00	\$9.00	\$17,685.00
		0001	0200	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	490.00	-56.00	434.00	EA	434.00	\$14.55	\$6,314.70
		0001	0210	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	75.00	87.00	162.00	EA	162.00	\$24.00	\$3,888.00
		0001	0220	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	30.00	62.00	92.00	EA	92.00	\$16.00	\$1,472.00
		0001	0230	6132018	FURNISHING AND PLACING CONCRETE MATERIAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	1.80	0.10	1.90	CUYD	1.90	\$2,360.00	\$4,484.00
		0001	0240	6132019	REMOVAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	16.30	2.10	18.40	SQYD	18.40	\$310.00	\$5,704.00
		0001	0250	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X	7.00	0.00	7.00	EA	0.00	\$2,050.00	\$0.00
		0001	0260	6161005	600MM) CONSTRUCTION SIGNS	946.00	0.00	946.00	SQFT	160.00	\$6.50	\$1,040.00
		0001	0270	6161025	CHANNELIZER (TRIM LINE)	250.00	0.00	250.00	EA	225.00	\$12.00	\$2,700.00
		0001	0280	6161030	TYPE III MOVEABLE BARRICADE	14.00	0.00	14.00	EA	0.00	\$125.00	\$0.00
		0001	0290	6161040	FLASHING ARROW PANEL	5.00	0.00	5.00	EA	1.00	\$500.00	\$500.00
		0001	0300	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	3.00	\$2,000.00	\$6,000.00
		0001	0310	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.25	\$225,919.45	\$56,479.86
		0001	0320	6191000	PAVEMENT EDGE TREATMENT	495.40	0.00	495.40	LF	0.00	\$7.00	\$0.00
		0001	0330	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	746.00	0.00	746.00	LF	0.00	\$6.00	\$0.00
		0001	0340	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	775.00	0.00	775.00	LF	155.00	\$20.00	\$3,100.00
		0001	0350	6200018	WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	109.00	0.00	109.00	LF	0.00	\$20.00	\$0.00
		0001	0360	6200021	YELLOW PREFORMED THERMOPLASTIC PAVEMENT MARKING,	55.00	0.00	55.00	EA	7.00	\$290.00	\$2,030.00
		0001	0370	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	3.00	0.00	3.00	EA	2.00	\$250.00	\$500.00
		0001	0380	6200027	STRAIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	4.00	0.00	4.00	EA	1.00	\$500.00	\$500.00
		0001	0390	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R	2.00	0.00	2.00	EA	0.00	\$1,400.00	\$0.00
		0001	0400	6200036	CROSSING MARKER  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN	20.00	0.00	20.00	EA	0.00	\$180.00	\$0.00
		0001	0410	6205901A	WHITE MIDBLOCK  4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT	4,136.00	0.00	4,136.00	LF	1,108.00	\$0.30	\$332.40
		0001	0420	6205902A	MARKING PAINT, TYPE L BEADS 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	55,246.00	0.00	55,246.00	LF	21,249.00	\$0.28	\$5,949.72
		5001			PAINT, TYPE L BEADS	,		,= .0.00		.,0.00	30.20	30,010.12

Page 4 of 15 Revision 3/23/2023



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
240216-H02	J9P3121B	0001	0430	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	35,522.00	0.00	35,522.00	LF	10,928.00	\$0.27	\$2,950.56
		0001	0440	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,476.00	0.00	2,476.00	LF	0.00	\$1.00	\$0.00
		0001	0450	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,598.00	0.00	1,598.00	LF	0.00	\$1.00	\$0.00
		0001	0460	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	92,767.00	0.00	92,767.00	SQYD	8,229.60	\$5.09	\$41,888.66
		0001	0470	7040104	HALF-SOLE REPAIR	3,370.00	0.00	3,370.00	SQFT	0.00	\$134.00	\$0.00
		0001	0480	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	4.00	0.00	4.00	FT	4.00	\$1,036.84	\$4,147.36
		0001	0490	8033000	K-31 TALL FESCUE SODDING	654.00	0.00	654.00	SQYD	415.00	\$16.00	\$6,640.00
		0001	0500	8061006	ALTERNATE DITCH CHECK	33.00	0.00	33.00	LF	33.00	\$20.00	\$660.00
		0001	0510	8061019	SILT FENCE	490.00	0.00	490.00	LF	490.00	\$6.50	\$3,185.00
		0010	0520	6061060	MGS GUARDRAIL	313.00	0.00	313.00	LF	0.00	\$32.00	\$0.00
		0010	0530	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	0.00	\$4,500.00	\$0.00
		0010	0540	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	5.00	0.00	5.00	EA	0.00	\$3,500.00	\$0.00
		0010	0550	6069902	MISC.MODIFIED MGS BRIDGE APPROACH TRANSITION SECTION	1.00	0.00	1.00	EA	0.00	\$6,000.00	\$0.00
		0030	0560	9028500	CABLE, LOOP DETECTOR, IN DUCT	18,260.00	0.00	18,260.00	LF	1,693.00	\$4.65	\$7,872.45
		0040	0570	9039903	MISC.CURB DELINEATOR SYSTEM	80.00	0.00	80.00	LF	80.00	\$60.00	\$4,800.00
	Project J9I	P3121B - To	otal Value	Posted to E	Date as of Report Generated Date							\$606,459.13
240216-H02 Ove	erall - Total \	/alue Poste	d to Date	as of Repor	rt Generated Date							\$606,459.13

Page 5 of 15 Revision 3/23/2023



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 6 of 15



Project   Line   Description   Adjustment   Type   Ty
AGGREGATE FOR BASE
Note   Concept
Material - Total   \$0.00
Nov 4
Nov 4,   2024   SYSTEM   \$2,456.30   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user holtb3 overridding Pay Estimate Item Adjustment (0015) due to user holtb3 overridding Pay Estimate Exception 2 on the current Payment Estimate.
AGGREGATE FOR BASE (6 IN. THICK)  A Dot 16, 2024  A Nov 4, 2024  A Nov 4, 2024  A Nov 4, 2024  Bestimate Item Adjustment (0015) due to user holitb3 overridding Pay Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) due to user holitb3 overridding Payn Estimate Item Adjustment (0003) du
3
2024   Estimate Item Adjustment (0003) due to user holtb3 overridding Pay Estimate Exception 2 on the current Payment Estimate.    A
2024
Material - Total   \$0.00
0050 - Total
ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIXTURE) ACAD - Total ACAD - Total (\$3,653.82) AC Adjustment for period ending 11/1/24.  ACAD - Total (\$3,653.82) AC Adjustment for period ending 11/1/24.  (\$3,653.82) (\$3,653.82)
CONCRETE   Adjustment   2024
TO ZZ (OT IZOS)
Other Item Adjustment - Total (\$3,653.82)
D: FUEL 4 0.00TEM (0445.00) D.C. III D: A.II. A. II. A. II
Price FUEL 4 Nov 4, 2024 (\$415.36) Reference Item Price Adjustment Index Adjustment Type applied is
- Total (\$415.36)  Price FUEL - Total (\$415.36)
0080 - Total (\$4,069.18)
0090 TACK COAT Material 4 Nov 4, SYSTEM \$2,823.43 This adjustment offsets the original system-generated Material Payn
2024 Estimate Item Adjustment (0004) due to user holitb3 overridding Pay Estimate Exception 4 on the current Payment Estimate.
4 Nov 4, 2024 (\$2,823.43)
5 Nov 18, 2024 \$2,823.43 This adjustment offsets the original system-generated Material Payn Estimate Item Adjustment (0001) due to user canton1 overridding Paterial Extension 2 on the current Payment Estimate.
5 Nov 18, SYSTEM (\$2,823.43)
6 Dec 2, 2024 \$2,823.43 This adjustment offsets the original system-generated Material Payn Estimate Item Adjustment (0001) due to user canton1 overridding Paterial Estimate Exception 2 on the current Payment Estimate.
6 Dec 2, 2024 (\$2,823.43)
7 Dec 16, 2024 \$2,823.43 This adjustment offsets the original system-generated Material Payn Estimate Item Adjustment (0001) due to user canton1 overridding Paterial Estimate Exception 2 on the current Payment Estimate.
7 Dec 16, SYSTEM (\$2,823.43)
8 Jan 2, 2025 \$YSTEM \$2,823.43 This adjustment offsets the original system-generated Material Payn Estimate Item Adjustment (0001) due to user canton1 overridding Paterial Estimate Exception 2 on the current Payment Estimate.
2025 Estimate Item Adjustment (0001) due to user canton1 overridding Pa
Estimate Item Adjustment (0001) due to user canton1 overridding Pound    8
2025   Estimate Item Adjustment (0001) due to user canton1 overridding Patestimate Exception 2 on the current Payment Estimate.   8
2025   Estimate Item Adjustment (0001) due to user canton1 overridding Patestimate Exception 2 on the current Payment Estimate.   8
Estimate Item Adjustment (0001) due to user canton1 overridding Patestimate Exception 2 on the current Payment Estimate.  8 Jan 2, 2025 (\$2,823.43)  - Total \$0.00  Material - Total \$0.00



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
				Type					
J9P3121B	0130	CURB AND GUTTER TYPE B	Material		5	Nov 18, 2024	SYSTEM	\$5,044.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user canton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Nov 18, 2024	SYSTEM	(\$5,044.50)	
					6	Dec 2, 2024	SYSTEM	\$5,044.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user canton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Dec 2, 2024	SYSTEM	(\$5,044.50)	
					7	Dec 16, 2024	SYSTEM	\$5,044.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user canton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Dec 16, 2024	SYSTEM	(\$5,044.50)	
					8	Jan 2, 2025	SYSTEM	\$5,044.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user canton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Jan 2,	SYSTEM	(\$5,044.50)	Estimate exception 3 on the current Payment Estimate.
				- Total		2025		\$0.00	
			Material - To					\$0.00	
			Overrun	Overrun	4	Nov 4,	SYSTEM	(\$1,681.50)	
				Overrun - To	otal	2024		(\$1,681.50)	
			Overrun - To					(\$1,681.50)	
	0130 -	Total						(\$1,681.50)	
	0140	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		4	Nov 4, 2024	SYSTEM	\$1,785.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Nov 4, 2024	SYSTEM	(\$1,785.60)	
					5	Nov 18, 2024	SYSTEM	\$1,785.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user canton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Nov 18, 2024	SYSTEM	(\$1,785.60)	
					6	Dec 2, 2024	SYSTEM	\$1,785.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user canton1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Dec 2, 2024	SYSTEM	(\$1,785.60)	
					7	Dec 16, 2024	SYSTEM	\$1,785.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user canton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Dec 16, 2024	SYSTEM	(\$1,785.60)	
					8	Jan 2, 2025	SYSTEM	\$1,785.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user canton1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Jan 2, 2025	SYSTEM	(\$1,785.60)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0140 -	Total						\$0.00	
	0160	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		2	Oct 1, 2024	SYSTEM	\$29,642.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user holtb3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Oct 1, 2024	SYSTEM	(\$29,642.55)	
					3	Oct 16, 2024	SYSTEM	\$127,938.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user holtb3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Oct 16, 2024	SYSTEM	(\$127,938.42)	
					4	Nov 4,	SYSTEM	\$179,884.32	This adjustment offsets the original system-generated Material Payment



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3121B	0160	FURN & PLACE CONC MATL FOR FULL DEPTH	Material			2024			Estimate Item Adjustment (0009) due to user holtb3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		TOLL DEFINI			4	Nov 4, 2024	SYSTEM	(\$179,884.32)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0160 -	- Total						\$0.00	
	0190	FULL DEPTH PAVEMENT REPAIR SAW CUT	Overrun	Overrun	3	Oct 16, 2024	SYSTEM	(\$3,654.00)	
		(FOR			4	Nov 4, 2024	SYSTEM	\$3,654.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',9.00000 - 9.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0190 -	- Total						\$0.00	
	0200	DOWEL BAR (DRILLING, FURNISHING AND	Material		2	Oct 1, 2024	SYSTEM	\$2,182.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user holtb3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		INST			2	Oct 1, 2024	SYSTEM	(\$2,182.50)	
					3	Oct 16, 2024	SYSTEM	\$6,314.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user holtb3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	Oct 16, 2024	SYSTEM	(\$6,314.70)	
					4	Nov 4, 2024	SYSTEM	\$6,314.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user holtb3 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	Nov 4, 2024	SYSTEM	(\$6,314.70)	
				- Total				\$0.00	
			Material - To					\$0.00 \$0.00	
	0200 -	- Total	Material - To						
	0200 - 0210	DOWEL BAR (FURNISH AND INSTALL WITH	Material - To		3	Oct 16, 2024	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		DOWEL BAR (FURNISH AND			3		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0008) due to user holtb3 overridding Payment
		DOWEL BAR (FURNISH AND INSTALL WITH				2024 Oct 16,		\$0.00 \$0.00 \$3,888.00	Estimate Item Adjustment (0008) due to user holtb3 overridding Payment
		DOWEL BAR (FURNISH AND INSTALL WITH			3	2024 Oct 16, 2024 Nov 4,	SYSTEM	\$0.00 \$0.00 \$3,888.00 (\$3,888.00)	Estimate Item Adjustment (0008) due to user holib3 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holib3 overridding Payment
		DOWEL BAR (FURNISH AND INSTALL WITH			3	2024 Oct 16, 2024 Nov 4, 2024	SYSTEM	\$0.00 \$0.00 \$3,888.00 (\$3,888.00) \$3,888.00	Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment
		DOWEL BAR (FURNISH AND INSTALL WITH		tal - Total	3	2024 Oct 16, 2024 Nov 4, 2024	SYSTEM	\$0.00 \$0.00 \$3,888.00 (\$3,888.00) \$3,888.00	Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment
		DOWEL BAR (FURNISH AND INSTALL WITH	Material	tal - Total	3 4	2024 Oct 16, 2024 Nov 4, 2024	SYSTEM	\$0.00 \$0.00 \$3,888.00 (\$3,888.00) \$3,888.00 (\$3,888.00)	Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment
		DOWEL BAR (FURNISH AND INSTALL WITH	Material  Material - To	- Total tal	3 4	2024 Oct 16, 2024 Nov 4, 2024 Nov 4, 2024 Oct 16,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$3,888.00 (\$3,888.00) \$3,888.00 (\$3,888.00)	Estimate Item Adjustment (0008) due to user holib3 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holib3 overridding Payment
		DOWEL BAR (FURNISH AND INSTALL WITH	Material  Material - To	- Total tal	3 4 4	2024 Oct 16, 2024 Nov 4, 2024  Oct 16, 2024  Oct 16, 2024  Nov 4, 4, 2024	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$3,888.00 (\$3,888.00) \$3,888.00 (\$3,888.00) \$0.00 (\$2,088.00)	Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 12 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',24.00000 - 24.00000, 'is
		DOWEL BAR (FURNISH AND INSTALL WITH	Material  Material - To	- Total tal Overrun Overrun - T	3 4 4	2024 Oct 16, 2024 Nov 4, 2024  Oct 16, 2024  Oct 16, 2024  Nov 4, 4, 2024	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$3,888.00 (\$3,888.00) \$3,888.00 (\$3,888.00) \$0.00 \$0.00 (\$2,088.00)	Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 12 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',24.00000 - 24.00000, 'is
	0210	DOWEL BAR (FURNISH AND INSTALL WITH	Material  Material - To  Overrun	- Total tal Overrun Overrun - T	3 4 4	2024 Oct 16, 2024 Nov 4, 2024  Oct 16, 2024  Oct 16, 2024  Nov 4, 4, 2024	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$3,888.00 (\$3,888.00) \$3,888.00 (\$3,888.00) \$0.00 (\$2,088.00) \$2,088.00	Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 12 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',24.00000 - 24.00000, 'is
	0210	DOWEL BAR (FURNISH AND INSTALL WITH BASK	Material - To Overrun Overrun - To	- Total tal Overrun Overrun - T	3 4 4	2024 Oct 16, 2024 Nov 4, 2024  Oct 16, 2024  Oct 16, 2024  Nov 4, 4, 2024	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$3,888.00 (\$3,888.00) \$3,888.00 (\$3,888.00) \$0.00 (\$2,088.00) \$2,088.00 \$0.00	Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 12 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',24.00000 - 24.00000, 'is
	0210	DOWEL BAR (FURNISH AND INSTALL WITH BASK  - Total  TIE BAR (DRILL, FURN & INSTAL)	Material - To Overrun Overrun - To	- Total tal Overrun Overrun - T	3 4 4 otal	2024 Oct 16, 2024 Nov 4, 2024 Nov 4, 2024 Oct 16, 2024 Oct 16, 2024 Oct 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$3,888.00 (\$3,888.00) \$3,888.00 (\$3,888.00) \$0.00 (\$2,088.00) \$2,088.00 \$0.00 \$0.00	Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 12 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',24.00000 - 24.00000, 'is applied (if non-zero).  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user holtb3 overridding Payment
	0210	DOWEL BAR (FURNISH AND INSTALL WITH BASK  - Total  TIE BAR (DRILL, FURN & INSTAL)	Material - To Overrun Overrun - To	- Total tal Overrun Overrun - T	3 4 4 3 4 4 3 3 4 4 5 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	2024 Oct 16, 2024 Nov 4, 2024  Oct 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$3,888.00 (\$3,888.00) \$3,888.00 (\$3,888.00) \$0.00 \$0.00 \$2,088.00 \$0.00 \$0.00 \$1,472.00	Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 12 on the current Payment Estimate.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',24.00000 - 24.00000, 'is applied (if non-zero).  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user holtb3 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3121B	0220	TIE BAR (DRILL,	Material	- Total				\$0.00	
		FURN & INSTAL) (TYPE L	Material - To	tal				\$0.00	
			Overrun	Overrun	3	Oct 16, 2024	SYSTEM	(\$992.00)	
					4	Nov 4, 2024	SYSTEM	\$992.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',16.00000 - 16.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0220 -	Total						\$0.00	
	0230	FURN & PLACE CONC MATL FOR CL A PARTIAL	Material		2	Oct 1, 2024	SYSTEM	\$613.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user holtb3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Oct 1, 2024	SYSTEM	(\$613.60)	
					3	Oct 16, 2024	SYSTEM	\$4,469.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user holtb3 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					3	Oct 16, 2024	SYSTEM	(\$4,469.84)	
					4	Nov 4, 2024	SYSTEM	\$4,484.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user holtb3 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					4	Nov 4, 2024	SYSTEM	(\$4,484.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	3	Oct 16, 2024	SYSTEM	(\$221.84)	
					4	Nov 4, 2024	SYSTEM	\$221.84	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2360.00000 - 2360.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0230 -	Total						\$0.00	
	0240	REMOVAL FOR CLASS A PARTIAL	Overrun	Overrun	3	Oct 16, 2024	SYSTEM	(\$664.64)	
		DEPTH PAVT R			4	Nov 4, 2024	SYSTEM	\$664.64	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',310.00000 - 310.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0240 -	Total						\$0.00	
	0260	CONSTRUCTION SIGNS	Material		2	Oct 1, 2024	SYSTEM	\$312.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user holtb3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					2	Oct 1, 2024	SYSTEM	(\$312.00)	
					3	Oct 16, 2024	SYSTEM	\$312.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user holtb3 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					3	Oct 16, 2024	SYSTEM	(\$312.00)	
					4	Nov 4, 2024	SYSTEM	\$1,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					4	Nov 4, 2024	SYSTEM	(\$1,040.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0260 -	Total						\$0.00	
	0270	CHANNELIZER (TRIM LINE)	Material		2	Oct 1, 2024	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user holtb3 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
19P3121B	0270	CHANNELIZER	Material						Estimate Exception 7 on the current Payment Estimate.
		(TRIM LINE)			2	Oct 1, 2024	SYSTEM	(\$2,700.00)	
					3	Oct 16, 2024	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user holtb3 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					3	Oct 16, 2024	SYSTEM	(\$2,700.00)	
					4	Nov 4, 2024	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user holtb3 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					4	Nov 4, 2024	SYSTEM	(\$2,700.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0270 -	- Total						\$0.00	
	0290	FLASHING ARROW PANEL	Material		2	Oct 1, 2024	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user holtb3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					2	Oct 1, 2024	SYSTEM	(\$500.00)	
					3	Oct 16, 2024	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					3	Oct 16, 2024	SYSTEM	(\$500.00)	
					4	Nov 4, 2024	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user holtb3 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					4	Nov 4, 2024	SYSTEM	(\$500.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0290 -	- Total						\$0.00	
	0300	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material		2	Oct 1, 2024	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user holtb3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		CONTTY			2	Oct 1, 2024	SYSTEM	(\$6,000.00)	
					3	Oct 16,	OVOTERA		
						2024	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					3	2024 Oct 16, 2024	SYSTEM	\$6,000.00 (\$6,000.00)	Estimate Item Adjustment (0021) due to user holtb3 overridding Payment
					3	Oct 16,			Estimate Item Adjustment (0021) due to user holtb3 overridding Payment
						Oct 16, 2024 Nov 4,	SYSTEM	(\$6,000.00)	Estimate Item Adjustment (0021) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user holtb3 overridding Payment
				- Total	4	Oct 16, 2024 Nov 4, 2024 Nov 4,	SYSTEM	(\$6,000.00)	Estimate Item Adjustment (0021) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user holtb3 overridding Payment
			Material - To		4	Oct 16, 2024 Nov 4, 2024 Nov 4,	SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00)	Estimate Item Adjustment (0021) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user holtb3 overridding Payment
	0300 -	- Total	Material - To		4	Oct 16, 2024 Nov 4, 2024 Nov 4,	SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00)	Estimate Item Adjustment (0021) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user holtb3 overridding Payment
	<b>0300</b> - 0340	- Total PREF THERMO PVMT MARK, 24 IN WHIT	Material - To		4	Oct 16, 2024 Nov 4, 2024 Nov 4,	SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00) \$0.00	Estimate Item Adjustment (0021) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user holtb3 overridding Payment
		PREF THERMO PVMT MARK, 24			4	Oct 16, 2024 Nov 4, 2024 Nov 4, 2024	SYSTEM SYSTEM SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00) \$0.00 \$0.00	Estimate Item Adjustment (0021) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user holtb3 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user canton1 overridding Payment
		PREF THERMO PVMT MARK, 24			4	Oct 16, 2024 Nov 4, 2024 Nov 4, 2024 Nov 18, 2024	SYSTEM SYSTEM SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00) \$0.00 \$0.00 \$3,100.00	Estimate Item Adjustment (0021) due to user holib3 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user holib3 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user canton1 overridding Payment
		PREF THERMO PVMT MARK, 24		- Total	4	Oct 16, 2024 Nov 4, 2024 Nov 4, 2024 Nov 18, 2024	SYSTEM SYSTEM SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00) \$0.00 \$0.00 \$3,100.00	Estimate Item Adjustment (0021) due to user holib3 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user holib3 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user canton1 overridding Payment
	0340	PREF THERMO PVMT MARK, 24	Material	- Total	4	Oct 16, 2024 Nov 4, 2024 Nov 4, 2024 Nov 18, 2024	SYSTEM SYSTEM SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00) \$0.00 \$0.00 \$3,100.00 (\$3,100.00)	Estimate Item Adjustment (0021) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user holtb3 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user canton1 overridding Payment
	0340	PREF THERMO PVMT MARK, 24 IN WHIT	Material  Material - Tol	- Total	4	Oct 16, 2024 Nov 4, 2024 Nov 4, 2024 Nov 18, 2024	SYSTEM SYSTEM SYSTEM	(\$6,000.00) \$6,000.00 (\$6,000.00) \$0.00 \$0.00 \$3,100.00 (\$3,100.00)	Estimate Item Adjustment (0021) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user holtb3 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user canton1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3121B	0360	PREF THERMO PVMT MARK, LT/RT ARROW	Material	1,700		2024			
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0360 -	Total						\$0.00	
	0370	PREF THERMO PVMT MRKG, STRIAGHT ARROW	Material		5	Nov 18, 2024	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user canton1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					5	Nov 18, 2024	SYSTEM	(\$500.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0370 -	Total						\$0.00	
	0380	PREF THERMO PVMT MARKING, COMBO	Material		5	Nov 18, 2024	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user canton1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					5	Nov 18, 2024	SYSTEM	(\$500.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0380 -	Total						\$0.00	
	0410	4 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material		5	Nov 18, 2024	SYSTEM	\$332.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user canton1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					5	Nov 18, 2024	SYSTEM	(\$332.40)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0410 -	Total						\$0.00	
	0420	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	Material		5	Nov 18, 2024	SYSTEM	\$1,341.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user canton1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					5	Nov 18, 2024	SYSTEM	(\$1,341.76)	
			- Total					\$0.00	
			Material - Total					\$0.00	
			Other Item Adjustment		7	Dec 16, 2024	canton1	(\$460.80)	Holding 10% for reflectivity results
					8	Jan 2, 2025	canton1	\$460.80	Acceptable reflectivity results obtained
				REFL - Total				\$0.00	
			Other Item Adjustment - Total					\$0.00	
		Total						\$0.00	
	0430	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material		5	Nov 18, 2024	SYSTEM	\$854.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user canton1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					5	Nov 18, 2024	SYSTEM	(\$854.28)	
			- Total					\$0.00	
			Material - To					\$0.00	
			Other Item Adjustment	REFL		Dec 16, 2024	canton1	(\$209.63)	Holding 10& for reflectivity results
					8	Jan 2, 2025	canton1	\$209.63	Acceptable reflectivity results obtained
			REFL - Total					\$0.00	
			Other Item Adjustment - Total					\$0.00	
		Total						\$0.00	
	0480	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material		5	Nov 18, 2024	SYSTEM	\$4,147.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user canton1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					5	Nov 18,	SYSTEM	(\$4,147.36)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3121B	0480	PRECAST	Material			2024			
		CONCRETE DROP INLET 5 FT X 3 FT			6	Dec 2, 2024	SYSTEM	\$4,147.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user canton1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					6	Dec 2, 2024	SYSTEM	(\$4,147.36)	
					7	Dec 16, 2024	SYSTEM	\$4,147.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user canton1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					7	Dec 16, 2024	SYSTEM	(\$4,147.36)	Estimate Exception 13 on the current Payment Estimate.
				- Total		2024		\$0.00	
			Material - Total					\$0.00	
	0480 -	· Total						\$0.00	
	0490	K-31 TALL FESCUE SODDING		OTHR	6	Dec 2, 2024	holtb3	(\$1,328.00)	20% is being withheld until sod has taken root per standard specifications.
				OTHR - Tota	al			(\$1,328.00)	
					9	Jan 15, 2025	canton1	\$1,328.00	Acceptable growth has been obtained
				- Total				\$1,328.00	
			Other Item A	Adjustment - Total				\$0.00	
		· Total					ava ===	\$0.00	
	0500	ALTERNATE DITCH CHECK	Material		3	Oct 16, 2024	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user holtb3 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					3	Oct 16, 2024	SYSTEM	(\$660.00)	
					4	Nov 4, 2024	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user holtb3 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					4	Nov 4, 2024	SYSTEM	(\$660.00)	
					5	Nov 18, 2024	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user canton1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					5	Nov 18, 2024	SYSTEM	(\$660.00)	
					6	Dec 2, 2024	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user canton1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					6	Dec 2, 2024	SYSTEM	(\$660.00)	
					7	Dec 16, 2024	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user canton1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Dec 16, 2024	SYSTEM	(\$660.00)	
					8	Jan 2, 2025	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user canton1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					8	Jan 2, 2025	SYSTEM	(\$660.00)	
					9	Jan 15, 2025	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user canton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Jan 15, 2025	SYSTEM	(\$660.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	OTHR		Oct 16, 2024	holtb3	(\$66.00)	10% is being withheld until contractor provides material documentation/certifications.
				OTHR - Total				(\$66.00)	
			Other Item Adjustment - Total					(\$66.00)	
	0500 -	· Total						(\$66.00)	



Duningt	Lina	Description	A dissatura a m t	Other	Est.	Cupatad	Created	Amazzunt	Remarks
Project	Line	Description	Adjustment Type	Other Adjustment	Number	Created Date	By	Amount	Remarks
J9P3121B	0510	SILT FENCE	Material	Туре	3	Oct 16,	SYSTEM	\$3,185.00	This adjustment offsets the original system-generated Material Payment
						2024			Estimate Item Adjustment (0023) due to user holtb3 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					3	Oct 16, 2024	SYSTEM	(\$3,185.00)	
					4	Nov 4, 2024	SYSTEM	\$3,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user holtb3 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					4	Nov 4, 2024	SYSTEM	(\$3,185.00)	
					5	Nov 18, 2024	SYSTEM	\$3,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user canton1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					5	Nov 18, 2024	SYSTEM	(\$3,185.00)	
					6	Dec 2, 2024	SYSTEM	\$3,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user canton1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					6	Dec 2, 2024	SYSTEM	(\$3,185.00)	
				- Total				\$0.00	
			Material - Tot					\$0.00	
			Other Item Adjustment	OTHR	3	Oct 16, 2024	holtb3	(\$318.50)	10% is being withheld until contractor provides material documentation/certifications.
				OTHR - Total				(\$318.50)	
			Other Item Adjustment - Total						
	0510 -	Total						(\$318.50)	
	0520	MGS GUARDRAIL	Construction Stockpile STMI		1	Jun 17, 2024	SYSTEM	\$4,303.13	Payment Estimate Item Adjustment generated Stockpile Transaction
			O I IVII	- Total				\$4,303.13	
			Construction	Stockpile STMI - Total				\$4,303.13	
	0520 -	Total						\$4,303.13	
	0530	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Stockpile		1	Jun 17, 2024	SYSTEM	\$7,500.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$7,500.00	
			Construction	Stockpile S	ΓΜΙ - Total			\$7,500.00	
	0530 -	Total						\$7,500.00	
	0540	TYPE A CRASHWORTHY END TERMINAL (MASH)	Stockpile		1	Jun 17, 2024	SYSTEM	\$9,375.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$9,375.00	
			Construction	Stockpile S	ΓΜΙ - Total			\$9,375.00	
	0540 -	- Total						\$9,375.00	
	0560	CABLE, LOOP DETECTOR, IN DUCT	Material		4	Nov 4, 2024	SYSTEM	\$7,216.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user holtb3 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					4	Nov 4, 2024	SYSTEM	(\$7,216.80)	
					5	Nov 18, 2024	SYSTEM	\$7,216.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user canton1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					5	Nov 18, 2024	SYSTEM	(\$7,216.80)	
				- Total				\$0.00	
	Material - Total							\$0.00	
	0560 -	· Total						\$0.00	
J9P3121B	- Total							\$15,042.95	
Overall - T	otal							\$15,042.95	

# MoDOT

#### Contract Adjustments for Contract - 240216-H02

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 15 of 15