Progress Estimate Nu 8			40419-F02 Gershenson Constru	ction Co.			024 Original Contract Amount 2024 Net Change Order Amoun Current Contract Amount	t \$0.00	
Approval Date								By User	
October 16, 2024			Generated and	Approved	d (and should be considere	d Draft) a	at the Project Office Level by	fullek2	
October 17, 2024		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by							
October 17, 2024		Reviewed and Approved at the Central Office Controllers Office Level by							
Original Completion Date Current Co			mpletion Date	Actual Completion Date % of Current Contract			% of Current Contract Amount	t Amount Complete	
October 1, 202	5	Octobe	er 1, 2025				24.13%		
	Contract I	nformational Dat	tes		Milestones				
Date Description	Original C	completion Date	Current Completion Date		No Milestones Exist for Contract				
Acceptance Date									
Awarded Date	May 1, 202	24	May 1, 2024						
Letting Date	April 19, 2	024	April 19, 2024						
Notice to Proceed Date	June 3, 20	June 3, 2024 June 3, 2024							
Open to Traffic Date									
Work Began Date									

Contract Total Pay For Estimate No. 8

	This Estimate	Previous	To Date
240419-F02			
Total Posted Items P	ay \$325,329.40	\$1,350,703.70	\$1,676,033.10
Gross Item Adjustme	ents (\$4,023.82)	\$34,274.20	\$30,250.38
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	\$0.00	\$0.00
Other Contract Adjus	stments \$0.00	\$0.00	\$0.00
		\$1,384,977.90	\$1,706,283.48
Contract Total Payable This Estimate:	\$321,305.58		

Contract Total Payable This Estimate:

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3417	0020	2022010	REMOVAL OF IMPROVEMENTS	LS	\$600,000.000	0.05	\$30,000.00
	0090	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$12.500	2,247	\$28,087.50
	0130	4039905	MISC.OPTIONAL PAVEMENT	SQYD	\$78.000	2,246.76	\$175,247.28
	0180	6039902	WATER	EA	\$100.000	1	\$100.00
	0260	6083006	6 IN. CONCRETE MEDIAN STRIP	SQYD	\$118.000	269.12	\$31,756.16
	0480	6143011	MANHOLE FRAME AND COVER, TYPE 1-B	EA	\$588.000	1	\$588.00
	0500	6149902	MISC.CONVERT INLET TO MANHOLE	EA	\$4,010.000	1	\$4,010.00
	0860	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$31,100.000	0.1	\$3,110.00
	0990	8031000A	TURF TYPE TALL FESCUE SODDING	SQYD	\$12.000	3,315	\$39,780.00
	1030	8061006	ALTERNATE DITCH CHECK	LF	\$10.000	144	\$1,440.0
	1040	8061007A	CURB INLET CHECK	EA	\$10.000	16	\$160.0
	1590	9031270A	2 IN. PSST POST - 12 GA.	LF	\$27.810	89.75	\$2,495.9
	1600	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	EA	\$267.370	7	\$1,871.5
	1630	9031280	2.5 IN. PSST POST - 12 GA.	LF	\$29.940	60.75	\$1,818.8
	1640	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	EA	\$320.840	4	\$1,283.3
	1650	9035004A	SH-FLAT SHEET	SQFT	\$29.940	75.75	\$2,267.9
	1660	9035069A	SHF-FLAT SHEET FLUORESCENT	SQFT	\$33.150	39.6	\$1,312.74
Project J6S34	17 - Total						\$325,329.4
Overall - Tota	1						\$325,329.4



Progress Estimate Number	Contract ID	240419-F02	Pay Period StartOctober 1, 2024 Original Contract Amount \$6,946,514.45
9	Prime Contracto	or Gershenson Construction Co., I	nc. Pay Period End October 15, 2024 Net Change Order Amount \$0.00
0			Current Contract Amount \$6,946,514.45

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project lumber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
6S3417	0130	MISC.	Material	51		-3,334.96	\$78.00	(\$260,126.88
	0130	gene			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	3,334.96	\$78.00	\$260,126.88
	0160	TYPE A2 SHOULDER	Material			-1,247	\$67.00	(\$83,549.00
	0160	TYPE A2 SHOULDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1,247	\$67.00	\$83,549.00
	0240	TRUNCATED DOMES	Material			-40	\$28.00	(\$1,120.00
	0240	TRUNCATED DOMES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	40	\$28.00	\$1,120.00
	0260	6 IN. CONCRETE MEDIAN STRIP	Material			-269.12	\$118.00	(\$31,756.16
	0260	6 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	269.12	\$118.00	\$31,756.16
	0270	PAVED APPROACH, 8 IN.	Material			-1,989.4	\$102.00	(\$202,918.80
	0270	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 6 on the current Payment Estimate.	1,989.4	\$102.00	\$202,918.80
	0280	CONCRETE SIDEWALK, 4 IN.	Material			-1,309.6	\$51.00	(\$66,789.60
	0280	CONCRETE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 7 on the current Payment Estimate.	1,309.6	\$51.00	\$66,789.60
	0300	MISC.	Material			-66	\$2,400.00	(\$158,400.00
	0300	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.	66	\$2,400.00	\$158,400.00
	0480	MANHOLE FRAME AND COVER, TYPE 1-B	Material			-2	\$588.00	(\$1,176.00
	0480	MANHOLE FRAME AND COVER, TYPE 1-B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 9 on the current Payment Estimate.	2	\$588.00	\$1,176.00
	0890	12 IN. PIPE GROUP A	Material			-935	\$98.00	(\$91,630.00
	0890	12 IN. PIPE GROUP A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user fullerk2	935	\$98.00	\$91,630.00



Progre	ess Estii 8	mate Number	Contract ID Prime Contrac	240419-F0 Ctor Gershenso		Pay Period Start October 1, 2024 O n Co., Inc. Pay Period End October 15, 2024 N C	et Change O	rder Amount	
Project umber	Line No.	Item De	escription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
6S3417						overridding Payment Estimate Exception 10 on the current Payment Estimate.			
	0900	15 IN. F	15 IN. PIPE GROUP A				-239	\$86.00	(\$20,554.00
	0900	15 IN. F	15 IN. PIPE GROUP A			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment Estimate.	239	\$86.00	\$20,554.00
	0910	18 IN. F	PIPE GROUP A	Material			-4	\$99.00	(\$396.00
	0910	18 IN. F	PIPE GROUP A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	4	\$99.00	\$396.00
	0950	SUBSTIT	OR ALLOWED UTE GROUP A END SECTION	Material			-8	\$870.00	(\$6,960.00
	0950	SUBSTIT	OR ALLOWED UTE GROUP A END SECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate.	8	\$870.00	\$6,960.00
	0970	SUBSTIT	OR ALLOWED UTE GROUP A END SECTION	Material			-1	\$1,800.00	(\$1,800.00
	0970	SUBSTIT	OR ALLOWED UTE GROUP A END SECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 14 on the current Payment Estimate.	1	\$1,800.00	\$1,800.00
	0990	TURF TYPE	TALL FESCUE SODDING	Material			-3,315	\$12.00	(\$39,780.00
	0990	TURF TYPE	TALL FESCUE SODDING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user fullerk2 overridding Payment Estimate Exception 15 on the current Payment Estimate.	3,315	\$12.00	\$39,780.00
	1030	ALTERNATE	DITCH CHECK	Material			-144	\$10.00	(\$1,440.00
	1030	ALTERNATE	DITCH CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate.	144	\$10.00	\$1,440.00
	1040	CURB	INLET CHECK	Material			-16	\$10.00	(\$160.00
	1040	CURB	INLET CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate.	16	\$10.00	\$160.00
	1590	2 IN. PSST	POST - 12 GA.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$924.43
	1590	2 IN. PSST	POST - 12 GA.	Material			-89.75	\$27.81	(\$2,495.95
	1590	2 IN. PSST	2 IN. PSST POST - 12 GA.			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate.	89.75	\$27.81	\$2,495.95
	1600		POST ANCHOR PSST - 12 GA.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$705.60



	rder Amount	et Change O	Pay Period Start October 1, 2024 O on Co., Inc. Pay Period End October 15, 2024 N C		240419-F0 ctor Gershenso	Contract ID Prime Contrac	mate Number	ss Estir 8	Progre	
Adjustment amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	escription	Item Description			
(\$1,871.59	\$267.37	-7			Material	POST ANCHOR PSST - 12 GA.		1600	J6S3417	
\$1,871.59	\$267.37	7	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate.		Material		DRIVEN POST ANCHOF FOR 2 IN. PSST - 12 GA			
(\$711.38			Payment Estimate Item Adjustment generated Stockpile Transaction		Construction Stockpile	POST - 12 GA.	2.5 IN. PSST	1630		
(\$1,818.86	\$29.94	-60.75			Material	POST - 12 GA.	2.5 IN. PSST	1630		
\$1,818.86	\$29.94	60.75	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user fullerk2 overridding Payment Estimate Exception 20 on the current Payment Estimate.		Material	POST - 12 GA.	630 2.5 IN. PSST POST - 12 GA.			
(\$481.04			Payment Estimate Item Adjustment generated Stockpile Transaction		Construction Stockpile		DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.			
(\$1,283.36	\$320.84	-4			Material	POST ANCHOR N. PSST - 7 GA.		1640		
\$1,283.36	\$320.84	4	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.		Material		DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.			
(\$749.93			Payment Estimate Item Adjustment generated Stockpile Transaction		Construction Stockpile	SH-FLAT SHEET		1650		
(\$451.44			Payment Estimate Item Adjustment generated Stockpile Transaction		Construction Stockpile	F-FLAT SHEET	1660			
(\$4,023.82									Total	



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information									
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work					
J6S3417	FAF 115-1(47)	Coldmill and resurface, signal, lighting, drainage and ADA improvements	115	ST LOUIS	from I-70 to North Hanley					

Totals by Job Numbers

J6S3417		This Estimate	Previous	To Date
Posted Item	Pay	\$325,329.40	\$1,350,703.70	\$1,676,033.10
Gross Item	Adjustments	(\$4,023.82)	\$34,274.20	\$30,250.38
	Gross Item Pay	\$321,305.58	\$1,384,977.90	\$1,706,283.48
		* *	*• • • •	AA AA
Incentive		\$0.00	\$0.00	\$0.00
Disincentiv)	\$0.00	\$0.00	\$0.00
Liquidated	Damages	\$0.00	\$0.00	\$0.00
Other Contr	act Adjustments	\$0.00	\$0.00	\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Ferrou			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 4039905, Project Item Line Number 0130, Material Set 403990596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 4039905, Project Item Line Number 0130, Material Set 403990596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 5021340, Project Item Line Number 0160, Material Set 502134096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 6081012, Project Item Line Number 0240, Material Set 608101296, Material 1067TRDO - Truncated Domes for ADA, Acceptance Action Generic 1067TRDO is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 6083006, Project Item Line Number 0260, Material Set 608300696, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 6085008, Project Item Line Number 0270, Material Set 608500896, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 6086004, Project Item Line Number 0280, Material Set 608600496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 6089902, Project Item Line Number 0300, Material Set 608990296, Material 1067TRDO - Truncated Domes for ADA, Acceptance Action Generic 1067TRDO is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 6143011, Project Item Line Number 0480, Material Set 614301196, Material 0614DFMNFC - Manhole Frame and Cover, Acceptance Action Generic 0614DFMNFC is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 7261012, Project Item Line Number 0890, Material Set 726101296, Material 1026CPRCC3.012 - Reinf Conc Culv Pipe Cl3 12" (300 mm), Acceptance Action Generic 1026CPRCC3.012 is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 7261015, Project Item Line Number 0900, Material Set 726101596, Material 1026CPRCC3.015 - Reinf Conc Culv Pipe Cl3 15" (375 mm), Acceptance Action Generic 1026CPRCC3.015 is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 7261018, Project Item Line Number 0910, Material Set 726101896, Material 1026CPRCC3.018 - Reinf Conc Culv Pipe Cl3 18" (450 mm), Acceptance Action Generic 1026CPRCC3.018 is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 7320615A, Project Item Line Number 0950, Material Set 7320615A96, Material 1032ESRCF - Conc End Section for Round Pipe, Acceptance Action Generic 1032ESRCF is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 7320624A, Project Item Line Number 0970, Material Set 7320624A96, Material 1032ESRCF - Conc End Section for Round Pipe, Acceptance Action Generic 1032ESRCF is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 8031000A, Project Item Line Number 0990, Material Set 8031000A96, Material 0803SO - Sod, Acceptance Action Generic 0803SO is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 8061006, Project Item Line Number 1030, Material Set 806100696, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 8061007A, Project Item Line Number 1040, Material Set 8061007A96, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031270A, Project Item Line Number 1590, Material Set 9031270A96, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031271A, Project Item Line Number 1600, Material Set 9031271A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031280, Project Item Line Number 1630, Material Set 903128096, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031281A, Project Item Line Number 1640, Material Set 9031281A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient.	Waiting for material reporting.	fullek2	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
40419-F02	J6S3417	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	0.00	\$10,000.00	\$0.0
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.25	\$600,000.00	\$150,000.0
		0001	0030	2031000	CLASS A EXCAVATION	580.00	0.00	580.00	CUYD	0.00	\$48.00	\$0.0
		0001	0040	2036000	COMPACTING EMBANKMENT	285.00	0.00	285.00	CUYD	0.00	\$40.00	\$0.0
		0001	0050	2063000	CLASS 3 EXCAVATION	1,036.00	0.00	1,036.00	CUYD	754.00	\$8.00	\$6,032.0
		0001	0060	2079909	MISC.LINEAR GRADING CLASS 2, MODIFIED	78.80	0.00	78.80	STA	13.80	\$2,025.00	\$27,945.0
		0001	0070	2159910	MISC.MODIFIED SHAPING SLOPES, CLASS III	2.00	0.00	2.00	100F	0.00	\$1,925.00	\$0.0
		0001	0080	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	10,902.00	0.00	10,902.00	SQYD	4,739.40	\$13.00	\$61,612.2
		0001	0090	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	3,647.00	0.00	3,647.00	SQYD	3,654.00	\$12.50	\$45,675.0
		0001	0100	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	61.80	0.00	61.80	TONS	0.00	\$295.05	\$0.0
		0001	0110	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	5,550.00	0.00	5,550.00	TONS	0.00	\$136.50	\$0.0
		0001	0120	4030208	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP190C MIX)	3,817.40	0.00	3,817.40	TONS	0.00	\$113.42	\$0.0
		0001	0130	4039905	MISC.OPTIONAL PAVEMENT	3,646.80	0.00	3,646.80	SQYD	3,653.21	\$78.00	\$284,950.3
		0001	0140	4079912	MISC.MISC. TACK COAT - LOW-TRACKING OR NON-TRACKING	4,483.00	0.00	4,483.00	GAL	0.00	\$5.00	\$0.0
		0001	0150	4099912	MISC.ASPHALT SEAL EMULSION	721.00	0.00	721.00	GAL	0.00	\$6.50	\$0.0
		0001	0160	5021340	TYPE A2 SHOULDER	1,248.00	0.00	1,248.00	SQYD	1,247.00	\$67.00	\$83,549.0
		0001	0170	6039902	WATER	26.00	0.00	26.00	EA	6.00	\$100.00	\$600.0
		0001	0180	6039902	WATER	39.00	0.00	39.00	EA	34.00	\$100.00	\$3,400.0
		0001	0190	6042010	ADJUSTING MANHOLE	26.00	0.00	26.00	EA	4.00	\$100.00	\$400.0
		0001 0	0200	6042020	ADJUSTING BASIN OR INLET	25.00	0.00	25.00	EA	1.00	\$100.00	\$100.
		0001	0210	6071012A	CHAIN-LINK FENCE (60 IN.)	122.00	0.00	122.00	LF	0.00	\$65.00	\$0.
		0001	0220	6079903	MISC.BLACK ORNAMENTAL FENCE (42 IN.)	191.00	0.00	191.00	LF	0.00	\$193.00	\$0.
		0001 0230		6081000	CONCRETE MEDIAN	609.00	0.00	609.00	SQYD	0.00	\$57.00	\$0.
		0001	0240	6081012	TRUNCATED DOMES	800.00	0.00	800.00	SQFT	40.00	\$28.00	\$1,120.0
		0001	0250	6082024	HAND-RAILING FOR STEPS WITH BALUSTERS	93.00	0.00	93.00	LF	0.00	\$289.00	\$0.1
		0001	0260	6083006	6 IN. CONCRETE MEDIAN STRIP	730.90	0.00	730.90	SQYD	269.12	\$118.00	\$31,756.1
		0001	0270	6085008	PAVED APPROACH, 8 IN.	4,482.80	0.00	4,482.80	SQYD	1,989.40	\$102.00	\$202,918.8
		0001	0280	6086004	CONCRETE SIDEWALK, 4 IN.	3,058.20	0.00	3,058.20	SQYD	1,309.60	\$51.00	\$66,789.6
		0001	0290	6086007	CONCRETE SIDEWALK, 7 IN.	716.50	0.00	716.50	SQYD	17.50	\$68.00	\$1,190.0
		0001	0300	6089902	MISC.ADA CURB RAMP	170.00	0.00	170.00	EA	66.00	\$2,400.00	\$158,400.0
		0001	0310	6089905	MISC.TRUCK APRON	34.10	0.00	34.10	SQYD	0.00	\$169.00	\$0.0
		0001	0320	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	4,551.00	0.00	4,551.00	LF	927.00	\$41.00	\$38,007.0
		0001	0330	6091042	CONCRETE GUTTER TYPE B	156.00	0.00	156.00	LF	0.00	\$63.00	\$0.0
		0001	0340	6091052	CURB AND GUTTER TYPE B	890.00	0.00	890.00	LF	299.00	\$50.00	\$14,950.0
		0001	0350	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	383.00	0.00	383.00	LF	123.00	\$26.00	\$3,198.0
		0001	0360	6092032	CONCRETE CURB LOW PROFILE TYPE F	263.00	0.00	263.00	LF	0.00	\$34.00	\$0.0
		0001	0370	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	346.00	0.00	346.00	CUYD	9.00	\$67.00	\$603.0
		0001	0380	6096042	PLACING TYPE 2 ROCK DITCH LINER	346.00	0.00	346.00	CUYD	9.00	\$40.00	\$360.0
			0390	6097000	ROCK LINING	10.00	0.00	10.00	CUYD	0.00	\$80.00	\$360.0
		0001	0390	6116010A	SLOPE PROTECTION	132.00	0.00	132.00	SQYD	0.00	\$103.00	\$0.0
		0001										
		0001	0410	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	500.00	0.00	500.00	SQYD	0.00	\$225.00	\$0.0
		0001	0420	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	125.00	0.00	125.00	SQYD	0.00	\$1.00	\$0.0
		0001	0430	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	125.00	0.00	125.00	SQYD	0.00	\$5.00	\$0.0
		0001	0440	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	1,914.00	0.00	1,914.00	LF	0.00	\$5.00	\$0.0
		0001	0450	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	440.00	0.00	440.00	EA	0.00	\$5.00	\$0.0

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
40419-F02	J6S3417	0001	0460	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	30.00	0.00	30.00	EA	0.00	\$50.00	\$0.0
		0001	0470	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	56.00	0.00	56.00	EA	0.00	\$5.00	\$0.0
		0001	0480	6143011	MANHOLE FRAME AND COVER, TYPE 1-B	2.00	0.00	2.00	EA	2.00	\$588.00	\$1,176.0
		0001	0490	6143012	MANHOLE FRAME AND COVER, TYPE 2	1.00	0.00	1.00	EA	0.00	\$588.00	\$0.0
		0001	0500	6149902	MISC.CONVERT INLET TO MANHOLE	2.00	0.00	2.00	EA	2.00	\$4,010.00	\$8,020.0
		0001	0510	6149902	MISC.DOUBLE SIDEWALK TRENCH DRAIN	1.00	0.00	1.00	EA	0.00	\$18,890.00	\$0.0
		0001	0520	6149902	MISC.SIDEWALK TRENCH DRAIN	3.00	0.00	3.00	EA	0.00	\$8,500.00	\$0.0
		0001	0530	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	0.00	\$2,352.00	\$0.0
		0001	0540	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$92,163.00	\$46,081.
		0001	0550	6173001	CONCRETE TRAFFIC BARRIER, TYPE C (RETAINING WALL)	156.00	0.00	156.00	LF	0.00	\$291.00	\$0.0
		0001	0560	6173100	CONCRETE TRAFFIC BARRIER, TYPE D	547.00	0.00	547.00	LF	0.00	\$192.00	\$0.
		0001	0570	6179903	MISC.CONCRETE TRAFFIC BARRIER, TYPE C (MODIFIED)	259.00	0.00	259.00	LF	0.00	\$288.00	\$0.
		0001	0580	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$524,175.00	\$262,087.
		0001	0590	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	6.00	0.00	6.00	EA	0.00	\$600.00	\$0.
		0001	0600	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	492.00	0.00	492.00	LF	0.00	\$6.42	\$0.
		0001	0610	6200012	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE	107.00	0.00	107.00	LF	0.00	\$12.83	\$0.
		0001	0620	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	714.00	0.00	714.00	LF	0.00	\$19.25	\$0.
		0001	0630	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	274.00	0.00	274.00	LF	0.00	\$19.25	\$0.
		0001	0640	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	60.00	0.00	60.00	EA	0.00	\$299.45	\$0.
		0001	0650	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	24.00	0.00	24.00	EA	0.00	\$267.37	\$0.
		0001	0660	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	6.00	0.00	6.00	EA	0.00	\$481.26	\$0.
		0001	0670	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	2.00	0.00	2.00	EA	0.00	\$481.26	\$0.
		0001	0680	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	159.00	0.00	159.00	EA	0.00	\$192.50	\$0.
		0001	0690	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	112.00	0.00	112.00	EA	0.00	\$69.52	\$0.
		0001	0700	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	3,725.00	0.00	3,725.00	LF	0.00	\$2.14	\$0.
		0001	0710	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	5,455.00	0.00	5,455.00	LF	0.00	\$2.14	\$0.
		0001	0720	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	13,944.00	0.00	13,944.00	LF	0.00	\$0.21	\$0.
		0001	0730	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	38,349.00	0.00	38,349.00	LF	0.00	\$0.32	\$0
		0001	0740	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	12,202.00	0.00	12,202.00	LF	0.00	\$0.32	\$0
		0001	0750	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	191.00	0.00	191.00	LF	0.00	\$1.07	\$0
		0001	0760	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	3,860.00	0.00	3,860.00	LF	0.00	\$1.07	\$0
		0001	0770	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	4,380.00	0.00	4,380.00	LF	0.00	\$1.07	\$0
		0001	0780	6207001	PAVEMENT MARKING REMOVAL	7,442.00	0.00	7,442.00	LF	0.00	\$1.07	\$0.
		0001	0790	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	45.00	0.00	45.00	EA	0.00	\$58.82	\$0.
		0001	0800	6209902	MISC.18 IN. WHITE TUBULAR MARKER	26.00	0.00	26.00	EA	0.00	\$80.21	\$0
		0001	0810	6209902	MISC.18 IN. YELLOW TUBULAR MARKER	63.00	0.00	63.00	EA	0.00	\$80.21	\$0.
		0001	0820	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION ARROW	2.00	0.00	2.00	EA	0.00	\$1,604.20	\$0
		0001	0830	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	25,268.00	0.00	25,268.00	SQYD	0.00	\$3.65	\$0.
		0001	0840	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	23,171.00	0.00	23,171.00	SQYD	0.00	\$5.60	\$0.
		0001	0850	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,035.00	0.00	1,035.00	SQYD	0.00	\$5.60	\$0.
		0001	0860	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.25	\$31,100.00	\$7,775.



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
40419-F02	J6S3417	0001	0870	7032002	CLASS B CONCRETE (MISC)	3.60	0.00	3.60	CUYD	0.00	\$2,800.00	\$0.
		0001	0880	7061000	REINFORCING STEEL	170.00	0.00	170.00	LB	0.00	\$6.00	\$0.
		0001	0890	7261012	12 IN. PIPE GROUP A	935.00	0.00	935.00	LF	935.00	\$98.00	\$91,630.
		0001	0900	7261015	15 IN. PIPE GROUP A	559.00	0.00	559.00	LF	239.00	\$86.00	\$20,554.
		0001	0910	7261018	18 IN. PIPE GROUP A	175.00	0.00	175.00	LF	4.00	\$99.00	\$396
		0001	0920	7310048	PRECAST CONCRETE MANHOLE - 48 IN.	5.00	0.00	5.00	FT	0.00	\$698.00	\$0
		0001	0930	7319902	MISC.INLET TOP REPLACEMENT (IN KIND)	1.00	0.00	1.00	EA	0.00	\$1,750.00	\$0
		0001	0940	7319913	MISC.SINGLE STREET INLET	25.00	0.00	25.00	FT	21.00	\$1,065.00	\$22,365
		0001	0950	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	9.00	0.00	9.00	EA	8.00	\$870.00	\$6,960
		0001	0960	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$1,225.00	\$0
		0001	0970	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	1.00	\$1,800.00	\$1,800
		0001	0980	8025006	MULCHING	0.10	0.00	0.10	ACRE	0.00	\$5,350.00	\$0
		0001	0990	8031000A	TURF TYPE TALL FESCUE SODDING	5,528.00	0.00	5,528.00	SQYD	3,315.00	\$12.00	\$39,780
		0001	1000	8039905A	MISC.LANDSCAPING RESTORATION	28.00	0.00	28.00	SQYD	0.00	\$105.00	\$0
		0001	1010	8051000A	SEEDING - COOL SEASON GRASSES	0.10	0.00	0.10	ACRE	0.00	\$5,350.00	\$0
		0001	1020	8061005	ROCK DITCH CHECK	120.00	0.00	120.00	LF	0.00	\$10.00	\$1
		0001	1030	8061006	ALTERNATE DITCH CHECK	508.00	0.00	508.00	LF	144.00	\$10.00	\$1,44
		0001	1040	8061007A	CURB INLET CHECK	39.00	0.00	39.00	EA	16.00	\$10.00	\$16
		0001	1050	8061016	SEDIMENT REMOVAL	83.00	0.00	83.00	CUYD	0.00	\$1.00	\$
		0001	1060	8061019	SILT FENCE	3,800.00	0.00	3,800.00	LF	0.00	\$3.25	\$
		0010	1070	6061060	MGS GUARDRAIL	182.00	0.00	182.00	LF	0.00	\$35.00	9
		0010	1080	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	0.00	\$1,925.00	\$
		0010	1090	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$3,850.00	\$
		0020	1100	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	1,695.00	0.00	1,695.00	LF	0.00	\$15.00	\$
		0020	1110	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	20.00	0.00	20.00	LF	0.00	\$19.25	\$
		0020	1120	9014004	CONDUIT, 4 IN. RIGID, PUSHED	499.00	0.00	499.00	LF	0.00	\$25.67	\$
		0020	1130	9014502	CONDUIT, 2 IN. RIGID, EXTERNAL ON STRUCTURE	479.00	0.00	479.00	LF	0.00	\$21.39	\$
		0020	1140	9015010	TRENCHING TYPE I	1,995.00	0.00	1,995.00	LF	0.00	\$8.02	\$
		0020	1150	9016110	PULL BOX, PREFORMED CLASS 1	12.00	0.00	12.00	EA	0.00	\$1,653.39	\$
		0020	1160	9016112	PULL BOX, PREFORMED CLASS 3	2.00	0.00	2.00	EA	0.00	\$2,451.21	\$
		0020	1170	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	1,290.00	0.00	1,290.00	LF	0.00	\$1.07	\$
		0020	1180	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	5,350.00	0.00	5,350.00	LF	0.00	\$3.48	\$
		0020	1190	9018230	POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	1.00	0.00	1.00	EA	0.00	\$1,470.51	\$
		0020	1200	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	13.00	0.00	13.00	EA	0.00	\$2,108.98	\$
		0020	1210	9019902	MISC.170W TOP MOUNTED LED-B LUMINAIRE	5.00	0.00	5.00	EA	0.00	\$609.59	\$
		0020	1220	9019902	MISC.170W TOP MOUNTED LED-B LUMINAIRE, TYPE IV DISTRIBUTION	9.00	0.00	9.00	EA	0.00	\$609.59	\$
		0020	1230	9019902	MISC.30 FT. TOP MOUNT LIGHT POLE	1.00	0.00	1.00	EA	0.00	\$2,819.11	\$
		0020	1240	9019902	MISC.45 FT. TOP MOUNT LIGHT POLE	13.00	0.00	13.00	EA	0.00	\$3,514.26	\$
		0020	1250	9019902	MISC.LUMINAIRE, LED WALL PACK (UNDERPASS)	12.00	0.00	12.00	EA	0.00	\$649.16	\$
	0030 1260 9020113 SIGNAL HEAD, TYPE 3T 0030 1270 9020213 SIGNAL HEAD, TYPE 3S				SIGNAL HEAD, TYPE 3T	1.00	0.00	1.00	EA	0.00	\$1,071.60	\$
					SIGNAL HEAD, TYPE 3S	2.00	0.00	2.00	EA	0.00	\$1,014.92	9
		0030 1280 9020513 SIGNAL HEAD, TYPE 3B 0030 1290 9020514 SIGNAL HEAD, TYPE 4B				16.00	0.00	16.00	EA	0.00	\$1,341.11	\$
						6.00		EA	0.00	\$1,553.93	9	
		0030	1300	9020833	SH-FLAT SHEET - SIGNAL SIGN	198.00	0.00	198.00	SQFT	0.00	\$43.85	\$
		0030	1310	9020834	SIGNAL SIGN, MOUNTING HARDWARE	22.00	0.00	22.00	EA	0.00	\$320.84	ş

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
0419-F02	J6S3417	0030	1320	9022708	POST, SIGNAL 8 FT.	8.00	0.00	8.00	EA	0.00	\$1,233.09	\$0.
		0030	1330	9022715	POST, SIGNAL 15 FT.	1.00	0.00	1.00	EA	0.00	\$1,835.20	\$0.
		0030	1340	9023130	POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	0.00	\$13,047.46	\$0.
		0030	1350	9023230	POST, TYPE C, 30 FT. ARM OR 9.1 M ARM	2.00	0.00	2.00	EA	0.00	\$11,665.71	\$0.
		0030	1360	9023235	POST, TYPE C, 35 FT. ARM OR 10.7 M ARM	4.00	0.00	4.00	EA	0.00	\$12,034.68	\$0
		0030	1370	9023245	POST, TYPE C, 45 FT. ARM OR 13.7 M ARM	1.00	0.00	1.00	EA	0.00	\$14,004.63	\$0
		0030	1380	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	2.00	0.00	2.00	EA	0.00	\$25,576.23	\$0
		0030	1390	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	37.00	0.00	37.00	LF	0.00	\$14.97	\$0
		0030	1400	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	385.00	0.00	385.00	LF	0.00	\$16.04	\$0
		0030	1410	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	773.00	0.00	773.00	LF	0.00	\$24.60	\$0
		0030	1420	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	200.00	0.00	200.00	LF	0.00	\$1.55	\$0
		0030	1430	9028308	CABLE, 16 AWG 2 CONDUCTOR	2,990.00	0.00	2,990.00	LF	0.00	\$1.28	\$C
		0030	1440	9028310	CABLE, 16 AWG 5 CONDUCTOR	3,010.00	0.00	3,010.00	LF	0.00	\$1.44	\$0
		0030	1450	9028311	CABLE, 16 AWG 7 CONDUCTOR	5,890.00	0.00	5,890.00	LF	0.00	\$1.50	\$0
		0030	1460	9028810	PULL BOX, PREFORMED CLASS 1	1.00	0.00	1.00	EA	0.00	\$1,646.97	\$0
			9028811	PULL BOX, PREFORMED CLASS 2	5.00	0.00	5.00	EA	0.00	\$2,451.21	\$0	
		0030	1480	9028812	PULL BOX, PREFORMED CLASS 3	5.00	0.00	5.00		0.00	\$3,632.97	\$
		0030	1490	9029100	BASE, CONCRETE	32.90	0.00	32.90	CUYD	0.00	\$1,550.72	\$
		0030 1		9029901	MISC.TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING	1.00	0.00	1.00	LS	0.00	\$10,052.96	\$
		0030	1510	9029902	MISC.AUDIBLE PEDESTRIAN PUSH BUTTON AND SIGNING WITH VERBAL WALK MESSAGE	14.00	0.00	14.00	EA	0.00	\$1,228.81	\$
	0030 1520 9029902 1		9029902	MISC.COMBINATION PAD MOUNTED 120V/240V POWER SUPPLY AND LIGHTING CONTROLLER WITH UPS	2.00	0.00	2.00	EA	0.00	\$22,765.68	\$	
		0030	1530	9029902	MISC.COUNTDOWN PEDESTRIAN SIGNAL HEAD, TYPE 1S	14.00	0.00	14.00	EA	0.00	\$915.46	\$
		0030	1540	9029902	MISC.NETWORK CONNECTED SIGNAL MONITOR	2.00	0.00	2.00	EA	0.00	\$1,764.62	\$
		0030	1550	9029902	MISC.POTHOLING FOR UTILITY FACILITIES	45.00	0.00	45.00	EA	0.00	\$299.45	\$
		0030	1565	9029902	MISC.RECTANGULAR RAPID FLASHIG BEACON	6.00	0.00	6.00	EA	0.00	\$13,154.41	\$
		0030	1570	9029902	MISC.SL DISTRICT TRAFFIC SIGNAL DETECTION SYSTEM	2.00	0.00	2.00	EA	0.00	\$50,886.16	\$
		0040	1580	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	2.00	0.00	2.00	EA	0.00	\$481.26	\$
		0040	1590	9031270A	2 IN. PSST POST - 12 GA.	475.00	0.00	475.00	LF	89.75	\$27.81	\$2,49
		0040	1600	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	27.00	0.00	27.00	EA	7.00	\$267.37	\$1,87
		0040	1610	9031272A	2.25 IN. PSST POST INSERT (6 FT.) - 12 GA.	2.00	0.00	2.00	EA	0.00	\$128.34	\$
		0040	1620	9031274	CONCRETE POST ANCHOR FOR 2 IN. PSST 7 GA.	18.00	0.00	18.00	EA	0.00	\$641.68	\$
		0040	1630	9031280	2.5 IN. PSST POST - 12 GA.	203.00	0.00	203.00	LF	60.75	\$29.94	\$1,81
		0040	1640	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	13.00	0.00	13.00	EA	4.00	\$320.84	\$1,28
		0040	1650	9035004A	SH-FLAT SHEET	377.00	0.00	377.00	SQFT	75.75	\$29.94	\$2,26
		0040	1660	9035069A	SHF-FLAT SHEET FLUORESCENT	185.00	0.00	185.00	SQFT	39.60	\$33.15	\$1,31
		0040	1670	9039902	MISC.REMOVE AND RELOCATE EXISTING GROUND MOUNT	1.00	0.00	1.00	EA	0.00	\$320.84	\$
		0050	1680	9109901	SIGN MISC.ITS ASSET MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$7,379.30	\$
		0050	1690	9109901	MISC.RELOCATION OF ST. LOUIS COUNTY'S TRAFFIC SIGNAL	1.00	0.00	1.00	LS	0.00	\$1,015.99	\$
			1700	0100002	INTERCONNECT MISC.ADJUST TO GRADE MODOT PULL BOX	8.00	0.00	8.00	EA	0.00	\$953.96	\$
					MISC.ADJUST TO GRADE MODOT POLL BOX	1.00	0.00	1.00	EA	0.00	\$953.96	\$
		0050	1710	9109902	MISC.FIBER OPTIC FUSION SPLICE	16.00	0.00	16.00	EA	0.00	\$5,300.57	۵ \$
				8.00	0.00	8.00	EA	0.00	\$66.31	\$		
						8.00	0.00	8.00	EA	0.00	\$78.07	\$
		0050	1740	9109902	MISC.FIBER OF TIC FIGTALE MISC.INSTALL CCTV CAMERA ASSEMBLY	1.00	0.00	1.00	EA	0.00	\$1,143.26	\$1
		0000		0.00002		1.00	0.00	1.00	-~	0.00	ψ1, 1 1 0.20	φι



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
240419-F02	J6S3417				STRIP							
		0050	1770	9109902	MISC.ITS PULL BOX WITH CONCRETE PAD, PREFORMED CLASS 5	2.00	0.00	2.00	EA	0.00	\$3,703.55	\$0.00
		0050	1780	9109902	MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT	2.00	0.00	2.00	EA	0.00	\$1,207.42	\$0.00
		0050	1790	9109902	MISC.REMOVE IN-PAVEMENT WIRELESS DETECTION SYSTEM PER INTERSECTION	2.00	0.00	2.00	EA	0.00	\$2,027.70	\$0.00
		0050	1800	9109902	MISC.WALL-MOUNTED INTERCONNECT CENTER	2.00	0.00	2.00	EA	0.00	\$1,644.84	\$0.00
		0050	1810	9109903	MISC.CCTV CAMERA CABLE	160.00	0.00	160.00	LF	0.00	\$2.09	\$0.00
		0050	1820	9109903	MISC.CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	28.00	0.00	28.00	LF	0.00	\$16.04	\$0.00
		0050	1830	9109903	MISC.FIBER OPTIC CABLE, 24 STRAND, SINGLE MODE	5,050.00	0.00	5,050.00	LF	0.00	\$3.81	\$0.00
	Project J	6S3417 - To	tal Value	Posted to D	Date as of Report Generated Date							\$1,704,831.59
240419-F02 Ove	rall - Total	Value Post	ed to Dat	te as of Repo	ort Generated Date							\$1,704,831.59



Project: J6S3417

Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

To Offset/ Station/ Distance From Offset/ Station/ Distance Log Mile Description DWR DWR Date Approval Date Quantity Units Posted Location Comments Line Item Number Code 0020 2022010 REMOVAL OF IMPROVEMENTS 10/14/24 10/16/24 0.05 LS 00+00 CL 0090 3040506 TYPE 5 AGGREGATE FOR BASE (6 IN THICK) 10/2/24 10/15/24 122 00 SOYD 21+65 to 22+75 RT 10/15/24 394.00 SQYD 23+47 to 25+20 RT 10/3/24 10/15/24 328.00 SQYD 21+65 to 23+47 RT 10/7/24 10/14/24 165.00 SQYD 23+22.06 CL 25+42.93 CL 22+78 CL 10/8/24 10/14/24 50.00 SQYD beneath the 6 in. median strip 23+88 CL Stationing was approximated from the plan sheets. 10/9/24 10/14/24 313.00 SQYD 22+22.06 CL 25+42.93 CL 10/11/24 10/14/24 387.00 SQYD 25+20 CL 30+00 CL Stationing was approximated using the improvements plan sheets 30+00 CL 31+50 CL 10/14/24 10/16/24 214.00 SQYD Stationing is estimated 31+75 CL 33+50 CL 10/15/24 10/16/24 274.00 SQYD Stationing is estimated 0130 4039905 MISC 10/2/24 10/15/24 122.00 SQYD 21+65 to 22+75 RT 10/15/24 394.00 SQYD 23+47 to 25+20 RT 10/3/24 10/15/24 328.00 SQYD 21+65 to 23+47 RT 10/7/24 10/14/24 165.40 SQYD 23+22.06 CL 25+42.93 CI 50.00 SQYD 22+78 CL 23+88 CL 10/8/24 10/14/24 Stationing was approximated from the plan sheets. 10/9/24 10/14/24 312.50 SQYD 22+22.06 CL 25+42.93 CL 25+20 CL 30+00 CL 10/11/24 10/14/24 386.60 SQYD Stationing was approximated using the improvements plan sheets 30+00 CL 31+50 CL 10/14/24 10/16/24 214.27 SQYD Stationing is estimated 31+75 CL 10/15/24 10/16/24 273.99 SQYD 33+50 CL Stationing is estimated 0180 6039902 WATER - UTILITY ITEM 10/15/24 10/16/24 1.00 EA 31+74 CL Stationing is estimated 0260 6083006 6 IN. CONCRETE MEDIAN STRIP 10/4/24 10/14/24 110.20 SQYD 18+86.36 CL 20+45.20 CL Stationing from plan quantities and does not represent any field measurements. 21+67.50 CL 25+18.81 CL 10/8/24 10/14/24 65.75 SQYD 10/10/24 10/14/24 93.17 SOYD 21+67.50 CI 25+18.81 CI 0480 6143011 MANHOLE FRAME AND COVER, TYPE 1-B 10/14/24 10/16/24 1.00 EA MH-10 31+64.26 CL 0500 6149902 MISC. DRAINAGE FITTINGS 10/14/24 10/16/24 1.00 EA MH-10 31+64.26 CL 6274000 CONTRACTOR FURNISHED SURVEYING AND STAKI 10/14/24 10/16/24 0.10 00+00 CL 0860 LS 13+94.31 LT CL 57+85.13 LT CL 0990 8031000A TURF TYPE TALL FESCUE SODDING 10/15/24 10/16/24 3,315.00 SQYD 1030 8061006 ALTERNATE DITCH CHECK 144.00 10/15/24 10/16/24 LF 20+00 LT 33+00 LT Stationing is estimated 1040 8061007A CURB INLET CHECK 10/15/24 10/16/24 16.00 14+18 LT / CL 52+40 LT/CL EA LF Sign numbers 15, 18, 20, 45, 57, 59, 62 1590 9031270A 2 IN. PSST POST - 12 GA. 10/4/24 10/14/24 89.75 14+33 LT CL 50+70 LT CL 1600 9031271A DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. 7.00 EA Sign numbers 15, 18, 20, 45, 57, 59, 62 14+33 LT CL 10/4/24 10/14/24 50+70 LT CL 1630 9031280 2.5 IN. PSST POST - 12 GA. 10/4/24 10/14/24 60.75 LF Sign numbers 25, 46, 56, 64 19+12 LT CL 53+04 LT CL 1640 9031281A DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA. 10/4/24 10/14/24 4 00 EA Sign numbers 25, 46, 56, 64 19+12 | T CI 53+04 LT CL 1650 9035004A SH-FLAT SHEET 10/4/24 10/14/24 75.75 SQFT Sign numbers 15, 18, 20, 25, 45, 57, 59, 62, 64 00+00 LT CL 1660 9035069A SHF-FLAT SHEET FLUORESCENT 10/4/24 10/14/24 39.60 SQFT Sign numbers 46, 56 00+00 LT CL

The information below this line are details for Construction Signs (if applicable).

No Data Available



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3417	0080	TYPE 5 AGGREGATE FOR BASE	Material	51	1	Jul 1, 2024	SYSTEM	\$4,773.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Jul 1, 2024	SYSTEM	(\$4,773.60)	
					2	Jul 16, 2024	SYSTEM	\$6,552.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Jul 16, 2024	SYSTEM	(\$6,552.00)	
					3	Aug 2, 2024	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Aug 2, 2024	SYSTEM	(\$13,000.00)	
					4	Aug 16, 2024	SYSTEM	\$23,956.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Aug 16, 2024	SYSTEM	(\$23,956.40)	
					5	Sep 3, 2024	SYSTEM	\$39,413.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Sep 3, 2024	SYSTEM	(\$39,413.40)	
					6	Sep 16, 2024	SYSTEM	\$55,377.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Sep 16, 2024	SYSTEM	(\$55,377.40)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0080 -	Total						\$0.00	
	0080 - 0090	TYPE 5 AGGREGATE FOR BASE (6	Material		5	Sep 3, 2024	SYSTEM	\$0.00 \$4,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		TYPE 5 AGGREGATE	Material		5		SYSTEM SYSTEM		Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment
		TYPE 5 AGGREGATE FOR BASE (6	Material			2024 Sep 3,		\$4,200.00	Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment
		TYPE 5 AGGREGATE FOR BASE (6	Material		5	2024 Sep 3, 2024 Sep 16,	SYSTEM	\$4,200.00	Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		TYPE 5 AGGREGATE FOR BASE (6	Material	- Total	5	2024 Sep 3, 2024 Sep 16, 2024 Sep 16,	SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00	Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		TYPE 5 AGGREGATE FOR BASE (6	Material Material - To		5	2024 Sep 3, 2024 Sep 16, 2024 Sep 16,	SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00)	Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment
		TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)			5	2024 Sep 3, 2024 Sep 16, 2024 Sep 16,	SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$0.00	Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
	0090	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)			5	2024 Sep 3, 2024 Sep 16, 2024 Sep 16,	SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
	0090 -	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material - To		5 6 6	2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Sep 3,	SYSTEM SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
	0090 -	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material - To		5 6 5 5	2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Sep 3, 2024 Sep 3, 2024	SYSTEM SYSTEM SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$0.00 \$0.00 \$26,169.00	Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
	0090 -	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material - To		5 6 5 5	2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16, Sep 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$0.00 \$0.00 \$26,169.00 (\$26,169.00)	Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.
	0090 -	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material - To		5 6 5 5 6	2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$0.00 \$0.00 \$26,169.00 (\$26,169.00) \$26,169.00	Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.
	0090 -	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material - To		5 6 5 5 6 6	2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Sep 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$0.00 \$0.00 \$26,169.00 (\$26,169.00) \$26,169.00	Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	0090 -	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material - To		5 5 5 6 2 5 7	2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Sep 16, 2024 Sep 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00 \$0.00 \$0.00 \$26,169.00 (\$26,169.00) \$26,169.00 (\$26,169.00) \$26,169.00	Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.



Oct 18, 2024

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J6S3417	0130	MISC.	Material			2024												
				- Total				\$0.00										
			Material - Tot	al				\$0.00										
	0130 -	Total						\$0.00										
	0160	TYPE A2 SHOULDER	Material		5	Sep 3, 2024	SYSTEM	\$40,133.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 6 on the current Payment Estimate.									
					5	Sep 3, 2024	SYSTEM	(\$40,133.00)										
					6	Sep 16, 2024	SYSTEM	\$83,549.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 6 on the current Payment Estimate.									
					6	Sep 16, 2024	SYSTEM	(\$83,549.00)										
					7	Oct 1, 2024	SYSTEM	\$83,549.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.									
					7	Oct 1, 2024	SYSTEM	(\$83,549.00)										
	0160 - T				8	Oct 16, 2024	SYSTEM	\$83,549.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.									
					8	Oct 16, 2024	SYSTEM	(\$83,549.00)										
				- Total				\$0.00										
			Material - Tot	al				\$0.00										
		Total						\$0.00										
	0170	WATER - UTILITY ITEM	Material		2	Jul 16, 2024	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.									
		UTENTTEM					2	Jul 16, 2024	SYSTEM	(\$100.00)								
															3	Aug 2, 2024	SYSTEM	\$500.00
					3	Aug 2, 2024	SYSTEM	(\$500.00)										
													4	Aug 16, 2024	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					4	Aug 16, 2024	SYSTEM	(\$500.00)										
												5	Sep 3, 2024	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
					5	Sep 3, 2024	SYSTEM	(\$600.00)										
				- Total				\$0.00										
			Material - To	al				\$0.00										
	0170 -	Total						\$0.00										
	0180	WATER - UTILITY ITEM	Material		1	Jul 1, 2024	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.									
					1	Jul 1, 2024	SYSTEM	(\$700.00)										
				2	Jul 16, 2024	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
					2	Jul 16, 2024	SYSTEM	(\$1,100.00)										
					3	Aug 2, 2024	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.									



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
117	0180	WATER - UTILITY ITEM	Material	1360	3	Aug 2, 2024	SYSTEM	(\$2,400.00)	
					4	Aug 16, 2024	SYSTEM	\$2,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Paymer Estimate Exception 3 on the current Payment Estimate.
					4	Aug 16, 2024	SYSTEM	(\$2,600.00)	
					5	Sep 3, 2024	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Paymen Estimate Exception 9 on the current Payment Estimate.
					5	Sep 3, 2024	SYSTEM	(\$3,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0180 -	Total						\$0.00	
	0220	MISC. FENCING	Construction Stockpile		6	Sep 16, 2024	SYSTEM	\$14,796.77	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$14,796.77	
			Construction	Stockpile S	TMI - Tota			\$14,796.77	
	0220 -	Total						\$14,796.77	
	0240	TRUNCATED DOMES	Material		2	Jul 16, 2024	SYSTEM	\$560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Paymen Estimate Exception 4 on the current Payment Estimate.
					2	Jul 16, 2024	SYSTEM	(\$560.00)	
					3	Aug 2, 2024	SYSTEM	\$560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Paymen Estimate Exception 4 on the current Payment Estimate.
					3	Aug 2, 2024	SYSTEM	(\$560.00)	
					4	Aug 16, 2024	SYSTEM	\$840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Aug 16, 2024	SYSTEM	(\$840.00)	
					5	Sep 3, 2024	SYSTEM	\$840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Paymen Estimate Exception 10 on the current Payment Estimate.
					5	Sep 3, 2024	SYSTEM	(\$840.00)	
					6	Sep 16, 2024	SYSTEM	\$840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Sep 16, 2024	SYSTEM	(\$840.00)	
					7	Oct 1, 2024	SYSTEM	\$1,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Paymen Estimate Exception 3 on the current Payment Estimate.
					7	Oct 1, 2024	SYSTEM	(\$1,120.00)	
					8	Oct 16, 2024	SYSTEM	\$1,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payme Estimate Exception 4 on the current Payment Estimate.
					8	Oct 16, 2024	SYSTEM	(\$1,120.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0240 -	Total						\$0.00	
	0260	6 IN. CONCRETE MEDIAN STRIP	Material		8	Oct 16, 2024	SYSTEM	\$31,756.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Paymen Estimate Exception 5 on the current Payment Estimate.
					8	Oct 16, 2024	SYSTEM	(\$31,756.16)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3417	0260	6 IN.	Material	- Total				\$0.00	
		CONCRETE MEDIAN STRIP	Material - To	tal				\$0.00	
	0260 -	Total						\$0.00	
	0270	PAVED APPROACH, 8 IN.	Material		1	Jul 1, 2024	SYSTEM	\$25,153.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Jul 1, 2024	SYSTEM	(\$25,153.20)	
					2	Jul 16, 2024	SYSTEM	\$37,444.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	Jul 16, 2024	SYSTEM	(\$37,444.20)	
					3	Aug 2, 2024	SYSTEM	\$68,176.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Aug 2, 2024	SYSTEM	(\$68,176.80)	
					4	Aug 16, 2024	SYSTEM	\$89,199.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Aug 16, 2024	SYSTEM	(\$89,199.00)	
					5	Sep 3, 2024	SYSTEM	\$135,364.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					5	Sep 3, 2024	SYSTEM	(\$135,364.20)	
					6	Sep 16, 2024	SYSTEM	\$173,542.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					6	Sep 16, 2024	SYSTEM	(\$173,542.80)	
					7	Oct 1, 2024	SYSTEM	\$202,918.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Oct 1, 2024	SYSTEM	(\$202,918.80)	
					8	Oct 16, 2024	SYSTEM	\$202,918.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					8	Oct 16, 2024	SYSTEM	(\$202,918.80)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0270 -							\$0.00	
	0280	CONCRETE SIDEWALK, 4 IN.	Material		3	Aug 2, 2024	SYSTEM	\$12,994.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Aug 2, 2024	SYSTEM	(\$12,994.80)	
					4	Aug 16, 2024	SYSTEM	\$44,956.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Aug 16, 2024	SYSTEM	(\$44,956.50)	
					5	Sep 3, 2024	SYSTEM	\$51,943.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					5	Sep 3, 2024	SYSTEM	(\$51,943.50)	
					6	Sep 16, 2024	SYSTEM	\$59,782.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Sep 16,	SYSTEM	(\$59,782.20)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3417	0280	CONCRETE	Material			2024			
		SIDEWALK, 4 IN.			7	Oct 1, 2024	SYSTEM	\$66,789.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Oct 1, 2024	SYSTEM	(\$66,789.60)	
					8	Oct 16, 2024	SYSTEM	\$66,789.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Oct 16, 2024	SYSTEM	(\$66,789.60)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0280 -	Total						\$0.00	
	0300	MISC. CONCRETE	Material		1	Jul 1, 2024	SYSTEM	\$33,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					1	Jul 1, 2024	SYSTEM	(\$33,600.00)	
					2	Jul 16, 2024	SYSTEM	\$50,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					2	Jul 16, 2024	SYSTEM	(\$50,400.00)	
					3	Aug 2, 2024	SYSTEM	\$98,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					3	Aug 2, 2024	SYSTEM	(\$98,400.00)	
					4	Aug 16, 2024	SYSTEM	\$117,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					4	Aug 16, 2024	SYSTEM	(\$117,600.00)	
					5	Sep 3, 2024	SYSTEM	\$136,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					5	Sep 3, 2024	SYSTEM	(\$136,800.00)	
					6	Sep 16, 2024	SYSTEM	\$146,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Sep 16, 2024	SYSTEM	(\$146,400.00)	
					7	Oct 1, 2024	SYSTEM	\$158,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Oct 1, 2024	SYSTEM	(\$158,400.00)	
					8	Oct 16, 2024	SYSTEM	\$158,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Oct 16, 2024	SYSTEM	(\$158,400.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0300 -	Total						\$0.00	
	0370	FURN. TYPE 2 ROCK DITCH LINER	Material		6	Sep 16, 2024	SYSTEM	\$603.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					6	Sep 16, 2024	SYSTEM	(\$603.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
6S3417	0370 -	Total						\$0.00					
	0480	MANHOLE FRAME AND COVER, TYPE 1-B	Material		5	Sep 3, 2024	SYSTEM	\$588.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
		0-1			5	Sep 3, 2024	SYSTEM	(\$588.00)					
					6	Sep 16, 2024	SYSTEM	\$588.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 14 on the current Payment Estimate.				
					6	Sep 16, 2024	SYSTEM	(\$588.00)					
					7	Oct 1, 2024	SYSTEM	\$588.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
					7	Oct 1, 2024	SYSTEM	(\$588.00)					
					8	Oct 16, 2024	SYSTEM	\$1,176.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 9 on the current Payment Estimate.				
					8	Oct 16, 2024	SYSTEM	(\$1,176.00)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	0480 ·	Total						\$0.00					
	0890	12 IN. PIPE GROUP A	Material		5	Sep 3, 2024	SYSTEM	\$91,630.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate.				
					5	Sep 3, 2024	SYSTEM	(\$91,630.00)					
					6	Sep 16, 2024	SYSTEM	\$91,630.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 15 on the current Payment Estimate.				
					6	Sep 16, 2024	SYSTEM	(\$91,630.00)					
					7	Oct 1, 2024	SYSTEM	\$91,630.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					7	Oct 1, 2024	SYSTEM	(\$91,630.00)					
					8	Oct 16, 2024	SYSTEM	\$91,630.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
					8	Oct 16, 2024	SYSTEM	(\$91,630.00)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	0890 -	Total						\$0.00					
	0900	15 IN. PIPE GROUP A	Material		5	Sep 3, 2024	SYSTEM	\$20,554.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate.				
					5	Sep 3, 2024	SYSTEM	(\$20,554.00)					
									6	Sep 16, 2024	SYSTEM	\$20,554.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					6	Sep 16, 2024	SYSTEM	(\$20,554.00)					
				7	Oct 1, 2024	SYSTEM	\$20,554.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 9 on the current Payment Estimate.					
					7	Oct 1, 2024	SYSTEM	(\$20,554.00)					
					8	Oct 16, 2024	SYSTEM	\$20,554.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment Estimate.				



Oct 18, 2024

Initial is intermed with the second of	Droiget	Line	Description	Adjustment	Other	Eat	Created	Created	Amount	Demarka					
JASSATZ OPE INTERNAL OPE OPE NO OPE NO OPE NO INTERNAL INTERNAL INTERNAL INTERNAL INTERNAL INTERNAL INTERNAL INTERNAL INTERNAL INTERNAL INTERNAL INT	Project	Line	Description	Adjustment Type		Est. Number	Created Date	Created By	Amount	Remarks					
Image: Second	J6S3417	0900		Material	Туре	8		SYSTEM	(\$20,554.00)						
OUTE Outeral Use of a constraint of the const			GROOP A		- Total		2024		\$0.00						
9909 Total OFF 15.00 Interdipotent disest for adjoint operated Material Payment Extension 0010 0000 F 00000 F 00000 F 00000 F 000000 F 00000 F 00000 F				Material - To											
990 10 N. PRE GROUPA A PLACE Material CROUPA A PLACE Material CROUPA A PLACE Material SCROUPA A PLACE SCROUPA A PLACE <		0900 -	Total												
			18 IN. PIPE	Material		5		SYSTEM		Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment					
						5		SYSTEM	(\$396.00)						
Vision Vision Vision Normal System generated Material Payment Estimate Conjunct system generated Material Payment Estimate Exception 10 on the current Payment Estimate. Vision 0 cit Visit Statistical Controlling Payment Estimate Exception 10 on the current Payment Estimate. Vision 0 cit Visit Statistical Controlling						6		SYSTEM	\$396.00	Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment					
Visite Visite<						6		SYSTEM	(\$396.00)						
Image: Provide the set of the se						7		SYSTEM	\$396.00	Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment					
Visit Visit <th< td=""><td></td><td></td><td></td><td></td><td></td><td>7</td><td></td><td>SYSTEM</td><td>(\$396.00)</td><td></td></th<>						7		SYSTEM	(\$396.00)						
Option Control Source						8		SYSTEM	\$396.00	Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment					
Instant in the indication of the indicatin the indication of the indication of the indication of						8		SYSTEM	(\$396.00)						
0310-Total Underside Section					- Total				\$0.00						
0950 15 IN. GROUP A FLARED END SECT Material Network 7 Oct 1. 2024 SYSTEM \$6,960.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate. 7 Oct 1, 2024 SYSTEM \$6,960.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate. 8 Oct 16, 2024 SYSTEM \$6,960.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate. 0950 - Total 50.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate. 0950 - Total 50.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate. 0977 24 IN. GROUP A FLARED END SECT Sep 3, 529 Sep 3, SYSTEM SYSTEM \$1,800.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate. 0977 24 IN. GROUP A FLARED END SECT Sep 16, 2024 SYSTEM \$1,800.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate. 0977 </td <td></td> <td></td> <td></td> <td>Material - To</td> <td>tal</td> <td></td> <td></td> <td></td> <td>\$0.00</td> <td></td>				Material - To	tal				\$0.00						
A FLARED END SECT A FLARED END SECT 		0910 -	Total						\$0.00						
V V		0950	A FLARED END	Material		7		SYSTEM	\$6,960.00	Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment					
Image: Constraint of the second sec			SECT								7		SYSTEM	(\$6,960.00)	
Image: Control in the control in th											8		SYSTEM	\$6,960.00	Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment
Material - Total \$0.00 0950 - Total \$0.00 0970 24 IN GROUP A FLARED END SECT Material \$						8		SYSTEM	(\$6,960.00)						
0950 - Total 90.00 0970 24 IN. GROUP A FLARED END SECT Material 5 Sep 3, 2024 SYSTEM \$1.800.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate. 5 Sep 3, 2024 SYSTEM \$1.800.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate. 6 Sep 16, 2024 SYSTEM \$1.800.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. 6 Sep 16, 2024 SYSTEM \$1.800.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. 7 Oct 1, 2024 SYSTEM \$1.800.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate. 7 Oct 1, 2024 SYSTEM \$1.800.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate. 8 Oct 16, 2024 SYSTEM \$1.800.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate. 8 Oct 16					- Total				\$0.00						
0970 24 IN. GROUP A FLARED END SECT Material A FLARED END SECT Material A FLARED END SECT Material F F F F F F F F F F F F F F F F F F F				Material - To	tal				\$0.00						
SECT SECT Image: Sect image:			24 IN. GROUP	Material		5		SYSTEM							
6 Sep 16, 2024 SYSTEM \$1,800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate. 6 Sep 16, 2024 SYSTEM (\$1,800.00) 7 Oct 1, 2024 SYSTEM \$1,800.00 8 Oct 16, 2024 SYSTEM \$1,800.00 1 This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate. 8 Oct 16, 2024 SYSTEM \$1,800.00 1 Oct 16, 2024 SYSTEM \$1,800.00						5		SYSTEM	(\$1,800.00)						
Image: Figure 1 Image: Figure 1 <tdi< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td>2024 Sep 16,</td><td></td><td>x · · · y</td><td></td></tdi<>							2024 Sep 16,		x · · · y						
- Total 2024 C						0		OVOTEN	(\$4,000,00)						
Image: star in the star i							2024			This adjustment offects the crisical system concreted Material Deutscret					
Image: Section of the section of t				7		2024	Estimate Item Adjustment (0011) due to user fullerk Estimate Exception 12 on the current Payment Esti	Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment							
- Total 2024 2024 Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate - Total - Total \$0.00															
- Total \$0.00						8		SYSTEM	\$1,800.00	Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment					
						8		SYSTEM	(\$1,800.00)						
Material - Total \$0.00					- Total				\$0.00						
				Material - To	tal				\$0.00						



Oct 18, 2024

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3417	0970 -	Total						\$0.00	
	0990	TURF TYPE TALL FESCUE SODDING	Material		8	Oct 16, 2024	SYSTEM	\$39,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user fullerk2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					8	Oct 16, 2024	SYSTEM	(\$39,780.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0990 -	Total			_			\$0.00	
	1030	ALTERNATE DITCH CHECK	Material		8	Oct 16, 2024	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					8	Oct 16, 2024	SYSTEM	(\$1,440.00)	
				- Total				\$0.00	
			Material - To					\$0.00	
	1030 -	Total						\$0.00	
	1040	CURB INLET CHECK	Material		8	Oct 16, 2024	SYSTEM	\$160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					8	Oct 16, 2024	SYSTEM	(\$160.00)	
				- Total				\$0.00	
			Material - To					\$0.00	
	1040 -	Total						\$0.00	
	1580	BREAKAWAY ASSEMBLY	Construction Stockpile		4 Aug 16, SYSTEM 2024		SYSTEM	\$546.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		(PERFORATED SQUARE	STMI	MI - Total nstruction Stockpile STMI - Total					
		STEEL TUBE)	Construction	Stockpile S	MI - Tota			\$546.00	
	1580 -	Total						\$546.00	
	1590	2 IN. PSST POST - 12 GA.	Construction Stockpile		8	Oct 16, 2024	SYSTEM	(\$924.43)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$924.43)	
			Construction	Stockpile - 1	「otal			(\$924.43)	
			Construction Stockpile STMI		4	Aug 16, 2024	SYSTEM	\$4,892.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$4,892.50	
				Stockpile S				\$4,892.50	
			Material		8	Oct 16, 2024	SYSTEM	\$2,495.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					8	Oct 16, 2024	SYSTEM	(\$2,495.95)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1590 -	Total						\$3,968.07	
	1600	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12	Construction Stockpile		8	Oct 16, 2024	SYSTEM	(\$705.60)	Payment Estimate Item Adjustment generated Stockpile Transaction
		GA.		- Total				(\$705.60)	
			Construction	Stockpile - 1	「otal			(\$705.60)	
			Construction Stockpile STMI		4	Aug 16, 2024	SYSTEM	\$2,721.60	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$2,721.60	
			Construction	Stockpile S	ſMI - Tota			\$2,721.60	
			Material		8	Oct 16, 2024	SYSTEM	\$1,871.59	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					8	Oct 16,	SYSTEM	(\$1,871.59)	



Oct 18, 2024

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3417	1600	DRIVEN POST	Material	Type		2024			
	1000	ANCHOR FOR	Waterial	- Total		2024		\$0.00	
		2 IN. PSST - 12 GA.	Material - To					\$0.00	
	1600	Total						\$2,016.00	
	1600 - Total 1610 2.25 IN. PSST		Construction		4	Aug 16	SYSTEM	\$124.32	Payment Estimate Item Adjustment generated Steeknile Transaction
	1610	2.25 IN: PSST POST INSERT (6 FT.) - 12 GA.	Stockpile STMI	- Total	4	Aug 16, 2024	STOTEM	\$124.32	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction					\$124.32	
	4040	T-4-1	Construction Stockpile STMI - Total						
	1610 -		Ormateriation		4	Aug. 40	OVOTEM	\$124.32	Deservent Estimate New Adjustment was under Otesheile Tesses stier
	1620	CONCRETE POST ANCHOR FOR 2 IN. PSST 7 GA.	Construction Stockpile STMI	Tetel	4	Aug 16, 2024	SYSTEM	\$1,411.20	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,411.20	
			Construction	Stockpile STMI - Total				\$1,411.20	
	1620 -			1				\$1,411.20	
	1630	2.5 IN. PSST POST - 12 GA.	Construction Stockpile		8	Oct 16, 2024	SYSTEM	(\$711.38)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$711.38)	
			Construction	Construction Stockpile - Total				(\$711.38)	
			Construction Stockpile STMI		4	Aug 16, 2024	SYSTEM	\$2,377.13	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$2,377.13	
			Construction Stockpile STMI - Total					\$2,377.13	
			Material		8	Oct 16, 2024	SYSTEM	\$1,818.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user fullerk2 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					8	Oct 16, 2024	SYSTEM	(\$1,818.86)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1630 -	Total						\$1,665.75	
	1640	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Construction Stockpile		8	Oct 16, 2024	SYSTEM	(\$481.04)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$481.04)	
			Construction Stockpile - Total					(\$481.04)	
			Construction Stockpile		4	Aug 16, 2024	SYSTEM	\$1,563.38	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$1,563.38	
			Construction Stockpile STMI - Total					\$1,563.38	
			Material		8	Oct 16, 2024	SYSTEM	\$1,283.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					8	Oct 16, 2024	SYSTEM	(\$1,283.36)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	16 <u>40 -</u>	- Total						\$1,082.34	
	1650	SH-FLAT SHEET	Construction Stockpile		8	Oct 16, 2024	SYSTEM	(\$749.93)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$749.93)	
			Construction Stockpile - Total					(\$749.93)	
			Construction Stockpile STMI		4	Aug 16, 2024	SYSTEM	\$3,732.30	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$3,732.30	
			Construction	Stockpile STMI - Total				\$3,732.30	
	1650 -	Total						\$2,982.37	
	1660	SHF-FLAT	Construction		8	Oct 16,	SYSTEM	(\$451.44)	Payment Estimate Item Adjustment generated Stockpile Transaction
					-			(+ · - · · · ·)	,



Oct 18, 2024

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3417	1660	SHEET FLUORESCENT	Stockpile			2024			
				- Total				(\$451.44)	
			Construction Stockpile - Total					(\$451.44)	
			Construction Stockpile STMI		4	Aug 16, 2024	SYSTEM	\$2,109.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$2,109.00	
			Construction Stockpile STMI - Total					\$2,109.00	
	1660 -	Total						\$1,657.56	
J6S3417 ·	Total						\$30,250.38		
Overall -	Total						\$30,250.38		



There are no contract adjustments to display for this contract.