

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 2, 2025

| Progress Estim | ate Number  | Contract ID Prime Contractor |                     |                           |                   | Original Contract Amount<br>Net Change Order Amount<br>Current Contract Amount | \$3,088,480.85<br>\$2,851.31<br>\$3,091,332.16 |  |
|----------------|-------------|------------------------------|---------------------|---------------------------|-------------------|--|--|--|
| Approval Date  |             |                              |                     |                           |                   |  |  |  |
| May 2, 2025    |             |                              | Generated and App   | proved (and should be cor | sidered Draft) a  | t the Project Office Level by  | smithh5  |  |
| May 2, 2025    |             | Re                           | eviewed and Approve | d (and should be conside  | ed Draft) at the  | Resident Engineer Level by   | REDHAC   |  |
| May 5, 2025    |             |                              | Rev                 | viewed and Approved at t  | ne Central Office | e Controllers Office Level by  | ramses1  |  |
| Original Comp  | letion Date | Current Com                  | pletion Date        | Actual Completion Da      | te %              | of Current Contract Amoun  | t Complete                                     |  |
| August 1,      | 2025        | August 1                     | , 2025              |                           |                   | 51.68%   |  |  |

|                        | Contract Informational Dates |                                  |  |  |  |  |  |  |  |  |
|------------------------|------------------------------|----------------------------------|--|--|--|--|--|--|--|--|
| Date Description       | Original Completion Date     | No Milestones Exist for Contract |  |  |  |  |  |  |  |  |
| Acceptance Date        |                              |                                  |  |  |  |  |  |  |  |  |
| Awarded Date           | May 1, 2024                  | May 1, 2024                      |  |  |  |  |  |  |  |  |
| Letting Date           | April 19, 2024               | April 19, 2024                   |  |  |  |  |  |  |  |  |
| Notice to Proceed Date | June 3, 2024                 | June 3, 2024                     |  |  |  |  |  |  |  |  |
| Open to Traffic Date   |                              |                                  |  |  |  |  |  |  |  |  |
| Work Began Date        | October 15, 2024             | October 15, 2024                 |  |  |  |  |  |  |  |  |

| Contract Total Pa | y For Estimate No. 14      |               |                |                |
|-------------------|----------------------------|---------------|----------------|----------------|
|                   |                            | This Estimate | Previous       | To Date        |
| 240419-F06        |                            |               |                |                |
|                   | Total Posted Items Pay     | \$203,589.34  | \$1,394,082.97 | \$1,597,672.31 |
|                   | Gross Item Adjustments     | (\$73,568.75) | \$151,613.76   | \$78,045.01    |
|                   | Incentive                  | \$0.00        | \$0.00         | \$0.00         |
|                   | Disincentive               | \$0.00        | \$0.00         | \$0.00         |
|                   | Liquidated Damage          | \$0.00        | \$0.00         | \$0.00         |
|                   | Other Contract Adjustments | \$0.00        | \$0.00         | \$0.00         |
|                   |                            |               | \$1,545,696.73 | \$1,675,717.32 |
| Contract Total Pa | yable This Estimate:       | \$130,020.59  |                |                |

### **Items Paid This Estimate Period**

| Project<br>Number | Line<br>Number | Item<br>Code | Item Description  | Unit | Unit Price   | Current<br>Installed Qty | Current<br>Installed<br>Amount |
|-------------------|----------------|--------------|---|------|--------------|--------------------------|--------------------------------|
| J6S3640           | 0030           | 2031000      | CLASS A EXCAVATION  | CUYD | \$27.020     | 162                      | \$4,377.24                     |
|                   | 0040           | 2036000      | COMPACTING EMBANKMENT   | CUYD | \$9.650      | 1,100                    | \$10,615.00                    |
|                   | 0800           | 3040504      | TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)                       | SQYD | \$2.560      | 450.6                    | \$1,153.54                     |
|                   | 0090           | 3040506      | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)                       | SQYD | \$3.840      | 500.6                    | \$1,922.30                     |
|                   | 0110           | 4019905      | MISC.OPTIONAL PAVEMENT  | SQYD | \$93.220     | 498                      | \$46,423.56                    |
|                   | 0230           | 6089902      | MISC.ADA CONCRETE CURB RAMP (WITH TRUNCATED DOME)             | EA   | \$3,335.300  | 1                        | \$3,335.30                     |
|                   | 0250           | 6091052      | CURB AND GUTTER TYPE B  | LF   | \$56.080     | 18                       | \$1,009.44                     |
|                   | 0320           | 6141121      | CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM) | EA   | \$2,114.560  | 2                        | \$4,229.12                     |
|                   | 0430           | 6191000      | PAVEMENT EDGE TREATMENT                                       | LF   | \$2.200      | 207                      | \$455.40                       |
|                   | 0770           | 8061019      | SILT FENCE  | LF   | \$2.570      | 85                       | \$218.45                       |
|                   | 0840           | 9020121      | SIGNAL HEAD, TYPE 11T   | EA   | \$1,208.550  | 2                        | \$2,417.10                     |
|                   | 0850           | 9020213      | SIGNAL HEAD, TYPE 3S  | EA   | \$1,082.550  | 2                        | \$2,165.10                     |
|                   | 0860           | 9020513      | SIGNAL HEAD, TYPE 3B  | EA   | \$1,335.600  | 7                        | \$9,349.20                     |
|                   | 0870           | 9020514      | SIGNAL HEAD, TYPE 4B  | EA   | \$1,613.850  | 3                        | \$4,841.55                     |
|                   | 0880           | 9020833      | SH-FLAT SHEET - SIGNAL SIGN                                   | SQFT | \$35.700     | 106                      | \$3,784.20                     |
|                   | 0890           | 9020834      | SIGNAL SIGN, MOUNTING HARDWARE                                | EA   | \$257.250    | 18                       | \$4,630.50                     |
|                   | 0900           | 9022708      | POST, SIGNAL 8 FT.  | EA   | \$1,157.100  | 2                        | \$2,314.20                     |
|                   | 0910           | 9022715      | POST, SIGNAL 15 FT.   | EA   | \$1,732.500  | 2                        | \$3,465.00                     |
|                   | 0980           | 9024283      | CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER              | EA   | \$22,475.250 | 1                        | \$22,475.25                    |

Revision 3/23/2023 Page 1 of 20



# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 2, 2025

| Progress Estimate Number | Contract ID      | 240419-F06              | •              |             | Original Contract Amount       | . , ,          |
|--------------------------|------------------|-------------------------|----------------|-------------|--------------------------------|----------------|
| 4.4                      | Prime Contractor | Pavement Solutions, LLC | Pay Period End | May 1, 2025 | Net Change Order Amount        | \$2,851.31     |
| 14                       |                  |                         |                |             | <b>Current Contract Amount</b> | \$3,091,332.16 |

| Project<br>Number | Line<br>Number           | Item<br>Code | Item Description  | Unit | Unit Price   | Current<br>Installed Qty | Current<br>Installed<br>Amount |
|-------------------|--------------------------|--------------|---|------|--------------|--------------------------|--------------------------------|
| J6S3640           | 1000                     | 9025300      | CONDUIT, 3 IN., TRENCH WITH TRACER WIRE   | LF   | \$15.230     | 24                       | \$365.52                       |
|                   | 1120                     | 9028821      | PULL BOX, CONCRETE, DOUBLE, TYPE A  | EA   | \$5,688.900  | 1                        | \$5,688.90                     |
|                   | 1130                     | 9029100      | BASE, CONCRETE  | CUYD | \$1,652.700  | 13.71                    | \$22,658.52                    |
|                   | 1190                     | 9029902      | MISC.COMBINATION PAD MOUNTED 120/240 VOLT POWER SUPPLY AND LIGHTING CONTROLLER WITH UPS | EA   | \$22,182.300 | 1                        | \$22,182.30                    |
|                   | 1200                     | 9029902      | MISC.COUNTDOWN PEDESTRIAN SIGNAL HEAD, TYPE 1S  | EA   | \$733.950    | 6                        | \$4,403.70                     |
|                   | 1210                     | 9029902      | MISC.NETWORK CONNECTED SIGNAL MONITOR   | EA   | \$1,597.050  | 1                        | \$1,597.05                     |
|                   | 1340                     | 9109902      | MISC.CCTV CAMERA ASSEMBLY   | EA   | \$3,224.550  | 1                        | \$3,224.55                     |
|                   | 1350                     | 9109902      | MISC.FURISH AND INSTALL SM FIBER OPTIC PIGTAIL  | EA   | \$19.950     | 8                        | \$159.60                       |
|                   | 1360                     | 9109902      | MISC.FURNISH AND INSTALL SM FIBER OPTIC JUMPER  | EA   | \$29.400     | 8                        | \$235.20                       |
|                   | 1370                     | 9109902      | MISC.INSTALL CCTV CAMERA ASSEMBLY   | EA   | \$1,043.700  | 1                        | \$1,043.70                     |
|                   | 1410                     | 9109902      | MISC.ITS PULL BOX WITH CONCRETE PAD, PREFORMED CLASS 5                                  | EA   | \$3,636.150  | 1                        | \$3,636.15                     |
|                   | 1430                     | 9109902      | MISC.SINGLE MODE FUSION SPLICE  | EA   | \$94.500     | 30                       | \$2,835.00                     |
|                   | 1440                     | 9109902      | MISC.WALL-MOUNTED FIBER INTERCONNECT CENTER   | EA   | \$441.000    | 1                        | \$441.00                       |
|                   | 1480                     | 9109903      | MISC.FIBER OPTIC CABLE, 24 STRAND, SINGLE MODE  | LF   | \$2.100      | 2,827                    | \$5,936.70                     |
| Project Je        | 6 <mark>S3640 - T</mark> | otal         |   |      |              |                          | \$203,589.34                   |
| Overall -         | Total                    |              |   |      |              |                          | \$203,589.34                   |

### **Contract Adjustments This Estimate**

|                   |             | ments Exist on Contract  |                    |                                  |   |                        |                                       |                   |
|-------------------|-------------|--------------------------|--------------------|----------------------------------|---|------------------------|---------------------------------------|-------------------|
|                   |             |                          |                    |                                  |   |                        |                                       |                   |
| Project<br>Number | Line<br>No. | Item Description         | Adjustment<br>Type | Other Item<br>Adjustment<br>Type | Comments  | Adjustment<br>Quantity | Line Item<br>Adjustment<br>Unit Price | Adjustment amount |
| J6S3640           | 0040        | COMPACTING EMBANKMENT    | Material           |                                  |   | -2,100                 | \$9.65                                | (\$20,265.00)     |
|                   | 0040        | COMPACTING<br>EMBANKMENT | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0001) due to user smithh5<br>overridding Payment Estimate Exception 1 on<br>the current Payment Estimate. | 2,100                  | \$9.65                                | \$20,265.00       |
|                   | 0110        | MISC.                    | Material           |                                  |   | -3,491.5               | \$93.22                               | (\$325,477.63)    |
|                   | 0110        | MISC.                    | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0002) due to user smithh5<br>overridding Payment Estimate Exception 2 on<br>the current Payment Estimate. | 3,491.5                | \$93.22                               | \$325,477.63      |
|                   | 0200        | TRUNCATED DOMES          | Material           |                                  |   | -23                    | \$20.24                               | (\$465.52)        |
|                   | 0200        | TRUNCATED DOMES          | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0003) due to user smithh5<br>overridding Payment Estimate Exception 3 on<br>the current Payment Estimate. | 23                     | \$20.24                               | \$465.52          |
|                   | 0210        | PAVED APPROACH, 8 IN.    | Material           |                                  |   | -311                   | \$96.67                               | (\$30,064.37)     |
|                   | 0210        | PAVED APPROACH, 8 IN.    | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0004) due to user smithh5<br>overridding Payment Estimate Exception 4 on<br>the current Payment Estimate. | 311                    | \$96.67                               | \$30,064.37       |
|                   | 0220        | CONCRETE SIDEWALK, 4 IN. | Material           |                                  |   | -82.7                  | \$85.03                               | (\$7,031.98)      |
|                   | 0220        | CONCRETE SIDEWALK, 4 IN. | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item  | 82.7                   | \$85.03                               | \$7,031.98        |

Page 2 of 20 Revision 3/23/2023



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 2, 2025

Progress Estimate Number
14

Contract ID 240419-F06 Pay Period Start April 16, 2025 Original Contract Amount Prime Contractor Pavement Solutions, LLC Pay Period End May 1, 2025 Original Contract Amount Sq. 83,088,480.85

Net Change Order Amount Current Contract Amount Sq. 93,091,332.16

| Project<br>Number | Line<br>No. | Item Description                                       | Adjustment<br>Type        | Other Item<br>Adjustment<br>Type | Comments   | Adjustment<br>Quantity | Line Item<br>Adjustment<br>Unit Price | Adjustment amount |
|-------------------|-------------|--|---------------------------|----------------------------------|--|------------------------|---------------------------------------|-------------------|
| J6S3640           |             |  |                           |                                  | Adjustment (0005) due to user smithh5 overridding Payment Estimate Exception 5 on the current Payment Estimate.  |                        |                                       |                   |
|                   | 0230        | MISC.  | Material                  |                                  |  | -4                     | \$3,335.30                            | (\$13,341.20)     |
|                   | 0230        | MISC.  | Material                  |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0006) due to user smithh5<br>overridding Payment Estimate Exception 6 on<br>the current Payment Estimate.  | 4                      | \$3,335.30                            | \$13,341.20       |
|                   | 0250        | CURB AND GUTTER TYPE B                                 | Material                  |                                  |  | -1,242.5               | \$56.08                               | (\$69,679.40)     |
|                   | 0250        | CURB AND GUTTER TYPE B                                 | Material                  |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0007) due to user smithh5<br>overridding Payment Estimate Exception 8 on<br>the current Payment Estimate.  | 1,242.5                | \$56.08                               | \$69,679.40       |
|                   | 0900        | POST, SIGNAL 8 FT.                                     | Material                  |                                  |  | -2                     | \$1,157.10                            | (\$2,314.20)      |
|                   | 0900        | POST, SIGNAL 8 FT.                                     | Material                  |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0008) due to user smithh5<br>overridding Payment Estimate Exception 10<br>on the current Payment Estimate. | 2                      | \$1,157.10                            | \$2,314.20        |
|                   | 0910        | POST, SIGNAL 15 FT.                                    | Material                  |                                  |  | -2                     | \$1,732.50                            | (\$3,465.00)      |
|                   | 0910        | POST, SIGNAL 15 FT.                                    | Material                  |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0009) due to user smithh5<br>overridding Payment Estimate Exception 12<br>on the current Payment Estimate. | 2                      | \$1,732.50                            | \$3,465.00        |
|                   | 0980        | CONTROLLER ASSEMBLY<br>HOUSING, NEMA TS2<br>CONTROLLER | Construction<br>Stockpile |                                  | Payment Estimate Item Adjustment generated Stockpile Transaction   |                        |                                       | (\$32,052.28)     |
|                   | 1190        | MISC.  | Construction<br>Stockpile |                                  | Payment Estimate Item Adjustment generated Stockpile Transaction   |                        |                                       | (\$27,445.28)     |
|                   | 1190        | MISC.  | Material                  |                                  |  | -2                     | \$22,182.30                           | (\$44,364.60)     |
|                   | 1190        | MISC.  | Material                  |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0012) due to user smithh5<br>overridding Payment Estimate Exception 13<br>on the current Payment Estimate. | 2                      | \$22,182.30                           | \$44,364.60       |
|                   | 1210        | MISC.  | Construction<br>Stockpile |                                  | Payment Estimate Item Adjustment generated<br>Stockpile Transaction  |                        |                                       | (\$1,239.14)      |
|                   | 1340        | MISC.  | Material                  |                                  |  | -1                     | \$3,224.55                            | (\$3,224.55)      |
|                   | 1350        | MISC.  | Material                  |                                  |  | -8                     | \$19.95                               | (\$159.60)        |
|                   | 1360        | MISC.  | Material                  |                                  |  | -8                     | \$29.40                               | (\$235.20)        |
|                   | 1430        | MISC.  | Material                  |                                  |  | -30                    | \$94.50                               | (\$2,835.00)      |
|                   | 1440        | MISC.  | Material                  |                                  |  | -1                     | \$441.00                              | (\$441.00)        |
|                   | 1480        | MISC.  | Material                  |                                  |  | -2,827                 | \$2.10                                | (\$5,936.70)      |
| Total             |             |  |                           |                                  |  |                        |                                       | (\$73,568.75)     |

Revision 3/23/2023 Page 3 of 20



Incentive Disincentive Liquidated Damages Other Contract Adjustments

## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

|                   |                            |   |       |            | C  | contract Project Information                                 |  |  |  |  |  |  |  |
|-------------------|----------------------------|---|-------|------------|--|--|--|--|--|--|--|--|--|
| Project<br>Number | Federal<br>Proj.<br>Number | Project<br>Description  | Route | County     |  | Location of Work   |  |  |  |  |  |  |  |
| J6S3640           | FAF<br>61-5(43)            | Coldmill,<br>resurface,<br>add turn<br>lanes,<br>signals and<br>ADA | 61,67 | JEFFERSON  | at Miller Road and St.Jo                                       | at Miller Road and St.John's Church Road in Arnold           |  |  |  |  |  |  |  |
| Totals by .       | Job Numbe                  | ers   |       |            |  |  |  |  |  |  |  |  |  |
| J6S3640           |                            | ed Item Pay<br>s Item Adjustn                                       |       | s Item Pay | This Estimate<br>\$203,589.34<br>(\$73,568.75)<br>\$130,020.59 | Previous<br>\$1,394,082.97<br>\$151,613.76<br>\$1,545,696.73 | To Date<br>\$1,597,672.31<br>\$78,045.01<br>\$1,675,717.32 |  |  |  |  |  |  |

\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00

\$0.00 \$0.00 \$0.00 \$0.00

Revision 3/23/2023 Page 4 of 20



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## **Exceptions (Discrepancies) This Estimate Period**

| Exceptions (Discrepancies) This Estimate Period  Exceptions / Discrepancies  | Explanation  | Entered | Status       |
|--|--|---------|--------------|
| Exceptions / Biodispondice   |  | Ву      | Julia        |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 2036000, Project Item Line<br>Number 0040, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade<br>orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.           | Working with District Material with sample records issue   | smithh5 | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 4019905, Project Item Line Number 0110, Material Set 401990596, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 50/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.    | Informed Contractor about missing Certs, will work with Contractor and District Material to resolve issue. | smithh5 | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 6081012, Project Item Line<br>Number 0200, Material Set 608101296, Material 1067TRDO - Truncated Domes for ADA, Acceptance<br>Action Generic 1067TRDO is insufficient.                            | Informed Contractor about missing Certs, will work with Contractor and District Material to resolve issue. | smithh5 | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 6085008, Project Item Line<br>Jumber 0210, Material Set 608500896, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl<br>②, Acceptance Action Generic 1057JMFRPF is insufficient.         | Informed Contractor about missing Certs, will work with Contractor and District Material to resolve issue. | smithh5 | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 6086004, Project Item Line Number 0220, Material Set 608600496, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.       | Certs and been submitted, Working with District Material with sample records issue                         | smithh5 | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 6089902, Project Item Line Number 0230, Material Set 608990296, Material 1055CMMLT1D - Clear Pavement Cure (non-lissipating) @, Acceptance Action Generic 1055CMMLT1D is insufficient.            | Certs and been submitted, Working with District Material with sample records issue                         | smithh5 | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 6089902, Project Item Line<br>Number 0230, Material Set 608990296, Material 1067TRDO - Truncated Domes for ADA, Acceptance<br>Action Generic 1067TRDO is insufficient.                            | Informed Contractor about missing Certs, will work with Contractor and District Material to resolve issue. | smithh5 | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 6091052, Project Item Line<br>Number 0250, Material Set 609105296, Material 1055CMMLDST1D - Clear Pavement-Bridge<br>Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient. | Certs and been submitted, Working with District Material with sample records issue                         | smithh5 | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 9022708, Project Item Line Number 0900, Material Set 902270896, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.            | Certs and been submitted, Working with District Material with sample records issue                         | smithh5 | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 9022708, Project Item Line<br>Number 0900, Material Set 902270896, Material 1092TSPS - Traffic Signal Post(s) - All Types,<br>Acceptance Action Generic 1092TSPS is insufficient.                 | Certs and been submitted, Working with District Material with sample records issue                         | smithh5 | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 9022715, Project Item Line<br>Number 0910, Material Set 902271596, Material 1092TSPS - Traffic Signal Post(s) - All Types,<br>Acceptance Action Generic 1092TSPS is insufficient.                 | Certs and been submitted, Working with District Material with sample records issue                         | smithh5 | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 9022715, Project Item Line Number 0910, Material Set 902271596, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.            | Certs and been submitted, Working with District Material with sample records issue                         | smithh5 | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 9029902, Project Item Line Number 1190, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.                                   | Received Cert today, will complete sample record   | smithh5 | Overridden   |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 9109902, Project Item Line<br>Number 1340, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components,<br>Acceptance Action Generic 0910ITXX is insufficient.              | Informed Contractor about missing Certs, will work with Contractor and District Material to resolve issue. | smithh5 | Acknowledged |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 9109902, Project Item Line Number 1350, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.                    | Informed Contractor about missing Certs, will work with Contractor and District Material to resolve issue. | smithh5 | Acknowledged |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 9109902, Project Item Line<br>Number 1360, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components,<br>Acceptance Action Generic 0910ITXX is insufficient.              | Informed Contractor about missing Certs, will work with Contractor and District Material to resolve issue. | smithh5 | Acknowledged |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 9109902, Project Item Line Number 1430, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.                    | Informed Contractor about missing Certs, will work with Contractor and District Material to resolve issue. | smithh5 | Acknowledged |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 9109902, Project Item Line Number 1440, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.                    | Informed Contractor about missing Certs, will work with Contractor and District Material to resolve issue. | smithh5 | Acknowledged |
| Estimate Exception Type: Insufficient Materials: Project J6S3640, Item 9109903, Project Item Line Number 1480, Material Set 9109903, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.                    | Informed Contractor about missing Certs, will work with Contractor and District Material to resolve issue. | smithh5 | Acknowledged |

Revision 3/23/2023 Page 5 of 20



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract<br>m.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | Description  | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit | Total<br>Posted<br>Approved<br>Qty | Unit Price   | Total Value POSTEI<br>To Date (See report<br>generated date) |
|------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|--------------|--|
| 10419-F06              | J6S3640        | 0001     | 0010        | 2013000      | CLEARING AND GRUBBING  | 1.00            | 0.00                   | 1.00                         | ACRE | 0.90                               | \$13,650.00  | \$12,285.0   |
|                        |                | 0001     | 0020        | 2022010      | REMOVAL OF IMPROVEMENTS  | 1.00            | 0.00                   | 1.00                         | LS   | 0.50                               | \$95,000.00  | \$47,500.0   |
|                        |                | 0001     | 0030        | 2031000      | CLASS A EXCAVATION   | 3,183.00        | 0.00                   | 3,183.00                     | CUYD | 3,133.00                           | \$27.02      | \$84,653.6   |
|                        |                | 0001     | 0040        | 2036000      | COMPACTING EMBANKMENT  | 2,288.00        | 0.00                   | 2,288.00                     | CUYD | 2,100.00                           | \$9.65       | \$20,265.0   |
|                        |                | 0001     | 0050        | 2063000      | CLASS 3 EXCAVATION   | 859.00          | -23.00                 | 836.00                       | CUYD | 641.00                             | \$11.03      | \$7,070.2  |
|                        |                | 0001     | 0060        | 2065500      | TEMPORARY SHORING  | 1.00            | 0.00                   | 1.00                         | LS   | 0.50                               | \$5,500.00   | \$2,750.0  |
|                        |                | 0001     | 0070        | 2071000      | LINEAR GRADING CLASS 1   | 3.10            | 0.00                   | 3.10                         | STA  | 0.00                               | \$2,728.26   | \$0.0  |
|                        |                | 0001     | 0080        | 3040504      | TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)  | 1,623.00        | 0.00                   | 1,623.00                     | SQYD | 1,105.00                           | \$2.56       | \$2,828.8  |
|                        |                | 0001     | 0090        | 3040506      | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  | 7,201.00        | 0.00                   | 7,201.00                     | SQYD | 4,025.80                           | \$3.84       | \$15,459.  |
|                        |                | 0001     | 0100        | 4011209      | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  | 15.40           | 0.00                   | 15.40                        | TONS | 0.00                               | \$275.05     | \$0.   |
|                        |                | 0001     | 0110        | 4019905      | MISC.OPTIONAL PAVEMENT   | 6,126.80        | 0.00                   | 6,126.80                     | SQYD | 3,491.50                           | \$93.22      | \$325,477.6  |
|                        |                | 0001     | 0120        | 4030016      | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP048F MIX)   | 1,027.90        | 0.00                   | 1,027.90                     | TONS | 0.00                               | \$115.48     | \$0.0  |
|                        |                | 0001     | 0130        | 4030109      | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)   | 2,183.80        | 0.00                   | 2,183.80                     | TONS | 0.00                               | \$111.65     | \$0.0  |
|                        |                |          | 0140        | 4030306      | ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP250C MIX)   | 290.20          | 0.00                   | 290.20                       | TONS | 0.00                               | \$107.58     | \$0.0  |
|                        |                | 0001     |             |              |  |                 |                        |                              |      |                                    |              |  |
|                        |                | 0001     | 0150        | 4030308      | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP250C MIX)   | 145.10          | 0.00                   | 145.10                       | TONS | 0.00                               | \$129.89     | \$0.0  |
|                        |                | 0001     | 0160        | 4039905      | MISC.SYSTEM B GEOSYNTHETIC INTERLAYER (COMPOSITE PAVING FABRIC/REINFORCING GRID)                   | 1,335.00        | 0.00                   | 1,335.00                     | SQYD | 0.00                               | \$3.09       | \$0.0  |
|                        |                | 0001     | 0170        | 4071005      | TACK COAT  | 4,030.00        | 0.00                   | 4,030.00                     | GAL  | 0.00                               | \$3.01       | \$0.   |
|                        |                | 0001     | 0180        | 4079912      | MISC.POLYMER MODIFIED EMULSION MEMBRANE  | 1,225.00        | 0.00                   | 1,225.00                     | GAL  | 0.00                               | \$5.45       | \$0.0  |
|                        |                | 0001     | 0190        | 6081000      | CONCRETE MEDIAN  | 13.90           | 0.00                   | 13.90                        | SQYD | 13.90                              | \$241.54     | \$3,357.   |
|                        |                | 0001     | 0200        | 6081012      | TRUNCATED DOMES  | 23.00           | 0.00                   | 23.00                        | SQFT | 23.00                              | \$20.24      | \$465.   |
|                        |                | 0001     | 0210        | 6085008      | PAVED APPROACH, 8 IN.  | 442.50          | 0.00                   | 442.50                       | SQYD | 311.00                             | \$96.67      | \$30,064.  |
|                        |                | 0001     | 0220        | 6086004      | CONCRETE SIDEWALK, 4 IN.   | 191.20          | 0.00                   | 191.20                       | SQYD | 82.70                              | \$85.03      | \$7,031.9  |
|                        |                | 0001     | 0230        | 6089902      | MISC.ADA CONCRETE CURB RAMP (WITH TRUNCATED DOME)  | 11.00           | 0.00                   | 11.00                        | EA   | 4.00                               | \$3,335.30   | \$13,341.  |
|                        |                | 0001     | 0240        | 6091010      | CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S  | 483.00          | 0.00                   | 483.00                       | LF   | 116.00                             | \$46.56      | \$5,400.   |
|                        |                | 0001     | 0250        | 6091052      | CURB AND GUTTER TYPE B   | 1,245.00        | 0.00                   | 1,245.00                     | LF   | 1,242.50                           | \$56.08      | \$69,679.4   |
|                        |                | 0001     | 0260        | 6096010A     | FURNISHING TYPE 1 ROCK DITCH LINER   | 7.00            | 0.00                   | 7.00                         | CUYD | 0.00                               | \$43.31      | \$0.   |
|                        |                | 0001     | 0270        | 6096041      | PLACING TYPE 1 ROCK DITCH LINER  | 7.00            | 0.00                   | 7.00                         | CUYD | 0.00                               | \$95.44      | \$0.   |
|                        |                | 0001     | 0280        | 6097000      | ROCK LINING  | 10.00           | 0.00                   | 10.00                        | CUYD | 0.00                               | \$111.17     | \$0.   |
|                        |                | 0001     | 0290        | 6123001      | TRUCK MOUNTED ATTENUATOR (TMA)   | 1.00            | 0.00                   | 1.00                         | LS   | 0.00                               | \$29,925.00  | \$0.   |
|                        |                | 0001     | 0300        | 6141021      | GRATE AND BEARING PLATE (3 FT. X 2 FT. OR 914 MM X 610   | 2.00            | 0.00                   | 2.00                         | EA   | 0.00                               | \$2,333.06   | \$0.0  |
|                        |                |          |             |              | MM)  |                 |                        |                              |      |                                    |              |  |
|                        |                | 0001     | 0310        | 6141120      | CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)                                       | 6.00            | 0.00                   | 6.00                         | EA   | 0.00                               | \$1,646.51   | \$0.0  |
|                        |                | 0001     | 0320        | 6141121      | CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)                                      | 3.00            | 0.00                   | 3.00                         | EA   | 3.00                               | \$2,114.56   | \$6,343.   |
|                        |                | 0001     | 0330        | 6143010      | MANHOLE FRAME AND COVER, TYPE 1-A  | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$603.75     | \$0.   |
|                        |                | 0001     | 0340        | 6143013      | MANHOLE FRAME AND COVER, TYPE 3  | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$292.10     | \$0.   |
|                        |                | 0001     | 0350        | 6143014      | MANHOLE FRAME AND COVER, TYPE 4  | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$480.70     | \$0.   |
|                        |                | 0001     | 0360        | 6161098A     | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 5.00            | 0.00                   | 5.00                         | EA   | 0.00                               | \$2,940.00   | \$0.   |
|                        |                | 0001     | 0370        | 6169901      | MISC.TEMPORARY TRAFFIC CONTROL   | 1.00            | 0.00                   | 1.00                         | LS   | 0.75                               | \$26,625.90  | \$19,969.  |
|                        |                | 0001     | 0380        | 6173600D     | TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED   | 250.00          | 0.00                   | 250.00                       | LF   | 0.00                               | \$39.67      | \$0.   |
|                        |                | 0001     | 0390        | 6174000A     | TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION  | 2.00            | 0.00                   | 2.00                         | EA   | 0.00                               | \$1,491.00   | \$0.   |
|                        |                | 0001     | 0400        | 6175010A     | RELOCATING TEMPORARY TRAFFIC BARRIER   | 130.00          | 0.00                   | 130.00                       | LF   | 0.00                               | \$17.59      | \$0.   |
|                        |                | 0001     | 0410        | 6181000      | MOBILIZATION   | 1.00            | 0.00                   | 1.00                         | LS   | 0.75                               | \$304,400.00 | \$228,300  |
|                        |                | 0001     | 0420        | 6181020      | ADDITIONAL MOBILIZATION FOR SEEDING  | 4.00            | 0.00                   | 4.00                         | EA   | 0.00                               | \$600.00     | \$0.   |
|                        |                | 0001     | 0430        | 6191000      | PAVEMENT EDGE TREATMENT  | 2,247.00        | 0.00                   | 2,247.00                     | LF   | 1,847.00                           | \$2.20       | \$4,063.   |
|                        |                | 0001     | 0440        | 6200009      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN.  | 3,176.00        | 0.00                   | 3,176.00                     | LF   | 0.00                               | \$3.15       | \$0.0  |

Revision 3/23/2023 Page 6 of 20



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract<br>Nm.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | Description   | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit | Total<br>Posted<br>Approved<br>Qty | Unit Price | Total Value POSTE<br>To Date (See repor<br>generated date) |
|-------------------------|----------------|----------|-------------|--------------|---|-----------------|------------------------|------------------------------|------|------------------------------------|------------|--|
| 40419-F06               | J6S3640        | 0001     | 0450        | 6200015      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE                              | 305.00          | 0.00                   | 305.00                       | LF   | 0.00                               | \$21.00    | \$0.0  |
|                         |                | 0001     | 0460        | 6200021      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW                          | 13.00           | 0.00                   | 13.00                        | EA   | 0.00                               | \$315.00   | \$0.0  |
|                         |                | 0001     | 0470        | 6200027      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT                     | 3.00            | 0.00                   | 3.00                         | EA   | 0.00                               | \$472.50   | \$0.0  |
|                         |                | 0001     | 0480        | 6200042      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES         | 19.00           | 0.00                   | 19.00                        | EA   | 0.00                               | \$78.75    | \$0.0  |
|                         |                | 0001     | 0490        | 6205901A     | 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT<br>MARKING PAINT, TYPE L BEADS          | 9,902.00        | 0.00                   | 9,902.00                     | LF   | 0.00                               | \$0.26     | \$0.0  |
|                         |                | 0001     | 0500        | 6205902A     | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS              | 6,736.00        | 0.00                   | 6,736.00                     | LF   | 0.00                               | \$0.37     | \$0.0  |
|                         |                | 0001     | 0510        | 6206000C     | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS                | 1,712.00        | 0.00                   | 1,712.00                     | LF   | 0.00                               | \$1.05     | \$0.   |
|                         |                | 0001     | 0520        | 6206125A     | 24 IN. YELLOW STANDARD WATERBORNE PAVEMENT<br>MARKING PAINT, TYPE P BEADS           | 128.00          | 0.00                   | 128.00                       | LF   | 0.00                               | \$10.50    | \$0.   |
|                         |                | 0001     | 0530        | 6221003      | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK) | 18,334.00       | 0.00                   | 18,334.00                    | SQYD | 0.00                               | \$6.02     | \$0.   |
|                         |                | 0001     | 0540        | 6224010      | MODIFIED COLDMILLING (DEPTH TRANSITIONS)  | 41.00           | 0.00                   | 41.00                        | SQYD | 0.00                               | \$5.51     | \$0.   |
|                         |                | 0001     | 0550        | 6274000      | CONTRACTOR FURNISHED SURVEYING AND STAKING  | 1.00            | 0.00                   | 1.00                         | LS   | 0.25                               | \$9,187.50 | \$2,296.   |
|                         |                | 0001     | 0560        | 7250415      | 15 IN. PIPE GROUP C   | 189.00          | 0.00                   | 189.00                       | LF   | 189.00                             | \$80.47    | \$15,208.  |
|                         |                | 0001     | 0570        | 7250418      | 18 IN. PIPE GROUP C   | 130.00          | 0.00                   | 130.00                       | LF   | 130.00                             | \$80.70    | \$10,491.  |
|                         |                | 0001     | 0580        | 7261015      | 15 IN. PIPE GROUP A   | 588.00          | 0.00                   | 588.00                       | LF   | 569.00                             | \$78.58    | \$44,712.  |
|                         |                | 0001     | 0590        | 7261018      | 18 IN. PIPE GROUP A   | 93.00           | 0.00                   | 93.00                        | LF   | 51.00                              | \$85.67    | \$4,369.   |
|                         |                | 0001     | 0600        | 7310048      | PRECAST CONCRETE MANHOLE - 48 IN.   | 9.00            | 0.00                   | 9.00                         | FT   | 9.00                               | \$553.36   | \$4,980  |
|                         |                | 0001     | 0610        | 7311022      | PRECAST CONCRETE DROP INLET 2 FT X 2 FT   | 18.00           | 0.00                   | 18.00                        | FT   | 18.00                              | \$819.50   | \$14,751   |
|                         |                | 0001     | 0620        | 7311032      | PRECAST CONCRETE DROP INLET 3 FT X 2 FT   | 9.00            | 0.00                   | 9.00                         | FT   | 3.00                               | \$616.61   | \$1,849  |
|                         |                | 0001     | 0630        | 7311042      | PRECAST CONCRETE DROP INLET 4 FT X 2 FT   | 10.00           | 0.00                   | 10.00                        | FT   | 10.00                              | \$879.12   | \$8,791  |
|                         |                | 0001     | 0640        | 7311053      | PRECAST CONCRETE DROP INLET 5 FT X 3 FT   | 5.00            | 0.00                   | 5.00                         | FT   | 5.00                               | \$723.73   | \$3,618  |
|                         |                | 0001     | 0650        | 7320615A     | 15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END<br>SECTION                          | 1.00            | 0.00                   | 1.00                         | EA   | 1.00                               | \$1,939.77 | \$1,939  |
|                         |                | 0001     | 0660        | 7320618A     | 18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END<br>SECTION                          | 1.00            | 0.00                   | 1.00                         | EA   | 1.00                               | \$2,003.02 | \$2,003  |
|                         |                | 0001     | 0670        | 7320815A     | 15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION                             | 4.00            | 0.00                   | 4.00                         | EA   | 4.00                               | \$1,939.77 | \$7,759  |
|                         |                | 0001     | 0680        | 7320818A     | 18 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END<br>SECTION                          | 2.00            | 0.00                   | 2.00                         | EA   | 2.00                               | \$2,003.02 | \$4,006  |
|                         |                | 0001     | 0690        | 8025006      | MULCHING  | 2.00            | 0.00                   | 2.00                         | ACRE | 0.00                               | \$1,837.50 | \$0  |
|                         |                | 0001     | 0700        | 8051000A     | SEEDING - COOL SEASON GRASSES   | 0.90            | 0.00                   | 0.90                         | ACRE | 0.00                               | \$2,887.50 | \$0  |
|                         |                | 0001     | 0710        | 8061003      | SEDIMENT TRAP EXCAVATION  | 5.00            | 0.00                   | 5.00                         | CUYD | 0.00                               | \$178.54   | \$0  |
|                         |                | 0001     | 0720        | 8061004      | SEDIMENT TRAP ROCK  | 5.00            | 0.00                   | 5.00                         | CUYD | 0.00                               | \$78.75    | \$0  |
|                         |                | 0001     | 0730        | 8061005      | ROCK DITCH CHECK  | 90.00           | 0.00                   | 90.00                        | LF   | 0.00                               | \$26.25    | \$0  |
|                         |                | 0001     | 0740        | 8061007A     | CURB INLET CHECK  | 10.00           | 0.00                   | 10.00                        | EA   | 0.00                               | \$157.50   | \$0  |
|                         |                | 0001     | 0750        | 8061016      | SEDIMENT REMOVAL  | 72.00           | 0.00                   | 72.00                        | CUYD | 0.00                               | \$15.05    | \$0  |
|                         |                | 0001     | 0760        | 8061017      | TEMPORARY SEEDING   | 0.90            | 0.00                   | 0.90                         | ACRE | 0.00                               | \$1,050.00 | \$0  |
|                         |                | 0001     | 0770        | 8061019      | SILT FENCE  | 4,076.00        | 0.00                   | 4,076.00                     | LF   | 1,787.00                           | \$2.57     | \$4,592  |
|                         |                | 0001     | 0780        | 9029902      | MISC.POT HOLING UTILITY FACILITIES  | 6.00            | 0.00                   | 6.00                         | EA   | 0.00                               | \$612.57   | \$0  |
|                         |                | 0020     | 0790        | 9017110      | CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET   | 700.00          | 0.00                   | 700.00                       | LF   | 390.00                             | \$1.00     | \$390  |
|                         |                | 0020     | 0800        | 9018230      | POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)                                   | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$1,411.20 | \$0  |
|                         |                | 0020     | 0810        | 9019902      | MISC.120V TOP MOUNTED LED-A LUMINAIRE   | 9.00            | 0.00                   | 9.00                         | EA   | 4.00                               | \$565.95   | \$2,263  |
|                         |                | 0020     | 0820        | 9019902      | MISC.30 FT. TOP MOUNT LIGHTING POLE   | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$3,018.75 | \$0  |
|                         |                | 0020     | 0830        | 9028302      | CABLE, 12 AWG 2 CONDUCTOR   | 1,240.00        | 0.00                   | 1,240.00                     | LF   | 660.00                             | \$2.00     | \$1,320  |
|                         |                | 0030     | 0840        | 9020121      | SIGNAL HEAD, TYPE 11T   | 4.00            | 0.00                   | 4.00                         | EA   | 2.00                               | \$1,208.55 | \$2,417  |
|                         |                | 0030     | 0850        | 9020213      | SIGNAL HEAD, TYPE 3S  | 4.00            | 0.00                   | 4.00                         | EA   | 2.00                               | \$1,082.55 | \$2,165  |
|                         |                | 0030     | 0860        | 9020513      | SIGNAL HEAD, TYPE 3B  | 16.00           | 0.00                   | 16.00                        | EA   | 7.00                               | \$1,335.60 | \$9,349  |
|                         |                |          |             | 9020514      | SIGNAL HEAD, TYPE 4B  | 4.00            | 0.00                   | 4.00                         | EA   | 3.00                               | \$1,613.85 | \$4,841.   |

Page 7 of 20 Revision 3/23/2023



### Total Paid / All Items / All Estimates (Including this Estimate)

| Contract<br>Nm.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | Description   | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit | Total<br>Posted<br>Approved<br>Qty | Unit Price  | Total Value POSTED<br>To Date (See report<br>generated date) |
|-------------------------|----------------|----------|-------------|--------------|---|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 240419-F06              | J6S3640        | 0030     | 0880        | 9020833      | SH-FLAT SHEET - SIGNAL SIGN   | 191.00          | 0.00                   | 191.00                       | SQFT | 106.00                             | \$35.70     | \$3,784.2  |
|                         |                | 0030     | 0890        | 9020834      | SIGNAL SIGN, MOUNTING HARDWARE  | 32.00           | 0.00                   | 32.00                        | EA   | 18.00                              | \$257.25    | \$4,630.5  |
|                         |                | 0030     | 0900        | 9022708      | POST, SIGNAL 8 FT.  | 4.00            | 0.00                   | 4.00                         | EA   | 2.00                               | \$1,157.10  | \$2,314.2  |
|                         |                | 0030     | 0910        | 9022715      | POST, SIGNAL 15 FT.   | 4.00            | 0.00                   | 4.00                         | EA   | 2.00                               | \$1,732.50  | \$3,465.0  |
|                         |                | 0030     | 0920        | 9023130      | POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM  | 1.00            | 0.00                   | 1.00                         | EA   | 1.00                               | \$11,441.85 | \$11,441.8   |
|                         |                | 0030     | 0930        | 9023135      | POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM   | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$11,676.00 | \$0.0  |
|                         |                | 0030     | 0940        | 9023140      | POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM   | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$12,871.95 | \$0.0  |
|                         |                | 0030     | 0950        | 9023145      | POST, TYPE CL, 45 FT. ARM OR 13.7 M ARM   | 3.00            | 0.00                   | 3.00                         | EA   | 2.00                               | \$13,225.80 | \$26,451.6   |
|                         |                | 0030     | 0960        | 9023150      | POST, TYPE CL, 50 FT. ARM OR 15.2 M ARM   | 1.00            | 0.00                   | 1.00                         | EA   | 1.00                               | \$15,010.80 | \$15,010.8   |
|                         |                | 0030     | 0970        | 9023155      | POST, TYPE CL, 55 FT. ARM   | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$15,948.45 | \$0.0  |
|                         |                | 0030     | 0980        | 9024283      | CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER  | 2.00            | 0.00                   | 2.00                         | EA   | 2.00                               | \$22,475.25 | \$44,950.5   |
|                         |                | 0030     | 0990        | 9025200      | CONDUIT, 2 IN., TRENCH WITH TRACER WIRE   | 2,219.00        | 0.00                   | 2,219.00                     | LF   | 2,219.00                           | \$12.86     | \$28,536.0   |
|                         |                | 0030     | 1000        | 9025300      | CONDUIT, 3 IN., TRENCH WITH TRACER WIRE   | 245.00          | 0.00                   | 245.00                       | LF   | 151.00                             | \$15.23     | \$2,299.7  |
|                         |                | 0030     | 1010        | 9027200      | CONDUIT, 2 IN., PUSHED WITH TRACER WIRE   | 1,091.00        | 0.00                   | 1,091.00                     | LF   | 1,091.00                           | \$28.35     | \$30,929.8   |
|                         |                | 0030     | 1020        | 9027300      | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE   | 615.00          | 0.00                   | 615.00                       | LF   | 615.00                             | \$39.90     | \$24,538.  |
|                         |                | 0030     | 1030        | 9028208      | CABLE, 8 AWG 1 CONDUCTOR, POWER   | 160.00          | 0.00                   | 160.00                       | LF   | 0.00                               | \$1.73      | \$0.   |
|                         |                | 0030     | 1040        | 9028308      | CABLE, 16 AWG 2 CONDUCTOR   | 1,340.00        | 0.00                   | 1,340.00                     | LF   | 763.00                             | \$0.79      | \$602.   |
|                         |                | 0030     | 1050        | 9028309      | CABLE, 16 AWG 3 CONDUCTOR   | 4,110.00        | 0.00                   | 4,110.00                     | LF   | 1,687.00                           | \$1.10      | \$1,855.   |
|                         |                | 0030     | 1060        | 9028310      | CABLE, 16 AWG 5 CONDUCTOR   | 1,360.00        | 0.00                   | 1,360.00                     | LF   | 769.00                             | \$1.73      | \$1,330.   |
|                         |                | 0030     | 1070        | 9028311      | CABLE, 16 AWG 7 CONDUCTOR   | 4,240.00        | 0.00                   | 4,240.00                     | LF   | 2,029.00                           | \$2.52      | \$5,113.   |
|                         |                | 0030     | 1100        | 9028810      | PULL BOX, PREFORMED CLASS 1   | 31.00           | 0.00                   | 31.00                        | EA   | 31.00                              | \$1,686.30  | \$52,275.  |
|                         |                | 0030     | 1110        | 9028811      | PULL BOX, PREFORMED CLASS 2   | 6.00            | 0.00                   | 6.00                         | EA   | 5.00                               | \$2,214.45  | \$11,072.  |
|                         |                | 0030     | 1120        | 9028821      | PULL BOX, CONCRETE, DOUBLE, TYPE A  | 2.00            | 0.00                   | 2.00                         | EA   | 2.00                               | \$5,688.90  | \$11,377.  |
|                         |                | 0030     | 1130        | 9029100      | BASE, CONCRETE  | 35.00           | 0.00                   | 35.00                        | CUYD | 31.14                              | \$1,652.70  | \$51,465.  |
|                         |                | 0030     | 1140        | 9029401      | TEMPORARY TRAFFIC SIGNALS AND LIGHTING  | 1.00            | 0.00                   | 1.00                         | LS   | 0.00                               | \$26,250.00 | \$0.   |
|                         |                | 0030     | 1160        | 9029901      | MISC.TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING   | 1.00            | 0.00                   | 1.00                         | LS   | 0.00                               | \$11,532.15 | \$0.   |
|                         |                | 0030     | 1170        | 9029902      | MISC.ATC TRAFFIC SIGNAL CONTROL   | 2.00            | 0.00                   | 2.00                         | EA   | 0.00                               | \$5,036.85  | \$0.   |
|                         |                | 0030     | 1180        | 9029902      | MISC.AUDIBLE PEDESTRIAN PUSHBUTTON AND SIGNING WITH VERBAL WALK MESSAGE                 | 10.00           | 0.00                   | 10.00                        | EA   | 0.00                               | \$930.30    | \$0  |
|                         |                | 0030     | 1190        | 9029902      | MISC.COMBINATION PAD MOUNTED 120/240 VOLT POWER SUPPLY AND LIGHTING CONTROLLER WITH UPS | 2.00            | 0.00                   | 2.00                         | EA   | 2.00                               | \$22,182.30 | \$44,364   |
|                         |                | 0030     | 1200        | 9029902      | MISC.COUNTDOWN PEDESTRIAN SIGNAL HEAD, TYPE 1S  | 10.00           | 0.00                   | 10.00                        | EA   | 6.00                               | \$733.95    | \$4,403  |
|                         |                | 0030     | 1210        | 9029902      | MISC.NETWORK CONNECTED SIGNAL MONITOR   | 2.00            | 0.00                   | 2.00                         | EA   | 1.00                               | \$1,597.05  | \$1,597.   |
|                         |                | 0030     | 1220        | 9029902      | MISC.PEDESTRIAN PUSH BUTTON STANCHION   | 4.00            | 0.00                   | 4.00                         | EA   | 0.00                               | \$928.20    | \$0.   |
|                         |                | 0030     | 1240        | 9029902      | MISC.SL DISTRICT TRAFFIC SIGNAL DETECTION SYSTEM  | 2.00            | 0.00                   | 2.00                         | EA   | 0.00                               | \$41,103.30 | \$0.   |
|                         |                | 0040     | 1250        | 9031270A     | 2 IN. PSST POST - 12 GA.  | 176.00          | 0.00                   | 176.00                       | LF   | 0.00                               | \$36.58     | \$0.   |
|                         |                | 0040     | 1260        | 9031274      | CONCRETE POST ANCHOR FOR 2 IN. PSST 7 GA.   | 11.00           | 0.00                   | 11.00                        | EA   | 0.00                               | \$343.06    | \$0  |
|                         |                | 0040     | 1270        | 9031280      | 2.5 IN. PSST POST - 12 GA.  | 30.00           | 0.00                   | 30.00                        | LF   | 0.00                               | \$44.69     | \$0  |
|                         |                | 0040     | 1280        | 9031285      | CONCRETE POST ANCHOR FOR 2.5 IN. PSST 7 GA.   | 2.00            | 0.00                   | 2.00                         | EA   | 0.00                               | \$937.59    | \$0  |
|                         |                | 0040     | 1290        | 9035004A     | SH-FLAT SHEET   | 36.00           | 0.00                   | 36.00                        | SQFT | 0.00                               | \$37.53     | \$0  |
|                         |                | 0040     | 1300        | 9035069A     | SHF-FLAT SHEET FLUORESCENT  | 130.00          | 0.00                   | 130.00                       | SQFT | 0.00                               | \$42.93     | \$0  |
|                         |                | 0040     | 1310        | 9039902      | MISC.SIGN REMOVAL & RELOCATION  | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$4,138.72  | \$0.   |
|                         |                | 0050     | 1320        | 9029902      | MISC.FURNISH & INSTALL EXTENSION POLE   | 2.00            | 0.00                   | 2.00                         | EA   | 0.00                               | \$2,253.30  | \$0  |
|                         |                | 0050     | 1330        | 9109901      | MISC.ITS ASSET MANAGEMENT TOOL  | 1.00            | 0.00                   | 1.00                         | LS   | 0.00                               | \$1,319.85  | \$0  |
|                         |                | 0050     | 1340        | 9109902      | MISC.CCTV CAMERA ASSEMBLY   | 2.00            | 0.00                   | 2.00                         | EA   | 1.00                               | \$3,224.55  | \$3,224  |
|                         |                | 0050     | 1350        | 9109902      | MISC.FURISH AND INSTALL SM FIBER OPTIC PIGTAIL  | 16.00           | 0.00                   | 16.00                        | EA   | 8.00                               | \$19.95     | \$159.   |
|                         |                | 0050     | 1360        | 9109902      | MISC.FURNISH AND INSTALL SM FIBER OPTIC JUMPER  | 16.00           | 0.00                   | 16.00                        | EA   | 8.00                               | \$29.40     | \$235.   |

Revision 3/23/2023 Page 8 of 20



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract<br>Nm.CONTRACT | Project<br>No. | Category    | Line<br>No. | Item<br>Code  | Description  | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit | Total<br>Posted<br>Approved<br>Qty | Unit Price | Total Value POSTED<br>To Date (See report<br>generated date) |
|-------------------------|----------------|-------------|-------------|---------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|------------|--|
| 240419-F06              | J6S3640        | 0050        | 1370        | 9109902       | MISC.INSTALL CCTV CAMERA ASSEMBLY                      | 2.00            | 0.00                   | 2.00                         | EA   | 1.00                               | \$1,043.70 | \$1,043.70   |
|                         |                | 0050        | 1380        | 9109902       | MISC.INSTALL COMMUNICATIONS EQUIPMENT                  | 2.00            | 0.00                   | 2.00                         | EA   | 0.00                               | \$530.25   | \$0.00   |
|                         |                | 0050        | 1390        | 9109902       | MISC.INSTALL CONDUIT INTO EXISTING BOX                 | 4.00            | 0.00                   | 4.00                         | EA   | 0.00                               | \$520.80   | \$0.00   |
|                         |                | 0050        | 1400        | 9109902       | MISC.ITS PULL BOX WITH CONCRETE PAD, PREFORMED CLASS 2 | 5.00            | 0.00                   | 5.00                         | EA   | 5.00                               | \$2,881.20 | \$14,406.00  |
|                         |                | 0050        | 1410        | 9109902       | MISC.ITS PULL BOX WITH CONCRETE PAD, PREFORMED CLASS 5 | 6.00            | 0.00                   | 6.00                         | EA   | 4.00                               | \$3,636.15 | \$14,544.60  |
|                         |                | 0050        | 1420        | 9109902       | MISC.MODOT BURIED CABLE DRIVEABLE DELINEATOR POST      | 20.00           | 0.00                   | 20.00                        | EA   | 0.00                               | \$201.60   | \$0.00   |
|                         |                | 0050        | 1430        | 9109902       | MISC.SINGLE MODE FUSION SPLICE                         | 60.00           | 0.00                   | 60.00                        | EA   | 30.00                              | \$94.50    | \$2,835.00   |
|                         |                | 0050        | 1440        | 9109902       | MISC.WALL-MOUNTED FIBER INTERCONNECT CENTER            | 4.00            | 0.00                   | 4.00                         | EA   | 1.00                               | \$441.00   | \$441.00   |
|                         |                | 0050        | 1450        | 9109903       | MISC.CCTV CAMERA CABLE                                 | 261.00          | 0.00                   | 261.00                       | LF   | 0.00                               | \$1.21     | \$0.00   |
|                         |                | 0050        | 1460        | 9109903       | MISC.CONDUIT, HDPE, 2", DRILL, WITH TRACER WIRE        | 2,073.00        | 0.00                   | 2,073.00                     | LF   | 2,073.00                           | \$27.30    | \$56,592.90  |
|                         |                | 0050        | 1470        | 9109903       | MISC.CONDUIT, HDPE, 2", TRENCH, WITH TRACER WIRE       | 3,730.00        | 0.00                   | 3,730.00                     | LF   | 3,730.00                           | \$13.65    | \$50,914.50  |
|                         |                | 0050        | 1480        | 9109903       | MISC.FIBER OPTIC CABLE, 24 STRAND, SINGLE MODE         | 6,330.00        | 0.00                   | 6,330.00                     | LF   | 2,827.00                           | \$2.10     | \$5,936.70   |
|                         |                | 0001        | 5001        | 2063100       | CLASS 3 EXCAVATION IN ROCK                             | 0.00            | 23.00                  | 23.00                        | CUYD | 23.00                              | \$135.00   | \$3,105.00   |
|                         |                | 0001        | 5011        | 6085007       | PAVED APPROACH, 7 IN.                                  | 0.00            | 0.00                   | 0.00                         | SQYD | 0.00                               | \$0.00     | \$0.00   |
|                         | Project J      | 6S3640 - To | otal Value  | Posted to D   | Date as of Report Generated Date                       |                 |                        |                              |      |                                    |            | \$1,597,672.32   |
| 240419-F06 Ove          | erall - Total  | Value Post  | ted to Dat  | te as of Repo | ort Generated Date                                     |                 |                        |                              |      |                                    |            | \$1,597,672.32   |

Revision 3/23/2023 Page 9 of 20



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

## The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6S3640

| Line<br>lumber | Item<br>Code | Description  | DWR<br>Date       | DWR<br>Approval<br>Date | Quantity<br>Posted | Units | Location  | From<br>Station/<br>Log<br>Mile | Offset/<br>Distance | To<br>Station/<br>Log<br>Mile | Offset/<br>Distance | Comments  |
|----------------|--------------|--|-------------------|-------------------------|--------------------|-------|---|---------------------------------|---------------------|-------------------------------|---------------------|---|
| 0030           | 2031000      | CLASS A EXCAVATION   | 5/1/25            | 5/2/25                  | 162.00             | CUYD  | US 61/67 northbound and southbound                    | 257+34                          |                     | 272+18                        |                     |   |
| 0040           | 2036000      | COMPACTING EMBANKMENT  | 5/1/25            | 5/2/25                  | 1,100.00           | CUYD  | Miller Road East                                      | 0+32                            |                     | 2+72                          |                     |   |
| 0080           | 3040504      | TYPE 5 AGGREGATE FOR BASE  | 4/16/25           | 5/2/25                  | 50.00              | SQYD  | US 61/67 north bound                                  | 270+68                          |                     | 270+90                        |                     | pour 7" pave approach at sta. 270+68 to 270+90 pay of plan (50 SY) 7" pave approach   |
|                |              |  | 4/18/25           | 5/2/25                  | 24.50              | SQYD  | US 61/67 south bound                                  | 257+52                          |                     | 257+85                        |                     | Setting forms and grading for 7 " pave entrance at Link Auto, and Vally View Drive South 1/2.  Paur 7" pave approach at the (Links and Valle View)                            |
|                |              |  |                   |                         |                    |       |   |                                 |                     |                               |                     | Pour 7" pave approach at sta. (Links and Valle View) (Change Order #2) Sta 257+85 to 257+52 RT (13.2 SY) Vally View), Links (11.3 SY)   |
|                |              |  | 4/22/25           | 5/2/25                  | 72.70              | SQYD  | US 61/67 Miller Road East southbound and north        | 262+50                          |                     | 272+00                        |                     | Pour 7" pave approach at sta. (Mac Auto sale (4.5 SY and Public water district (17.5 SY) 262+88 to 262+50 263, and North side of New Trail Road( 272+18 to 272+00 ) (50.7 SY) |
|                |              |  | 4/23/25           | 5/2/25                  | 43.30              | SQYD  | US 61/67 southbound                                   | 259+51                          |                     | 258+79                        |                     | Pour 7" pave approach entrance south entrance to Lin<br>(Sta. 259+51 to 258+79) RT (43.3 SY)<br>25SLHFFS0001 PCCP Vally Material  |
|                |              |  | 4/24/25           | 5/2/25                  | 72.70              | SQYD  | US 61/67 north bound                                  | 270+68                          |                     | 270+90                        |                     | 7 " pave entrance at Parcell 17 north entrance (49.7 S and Percell 18 entrance (23 SY). (Change Order #2) 269+56 LT to 268+43 LT  |
|                |              |  | 4/25/25           | 5/2/25                  | 93.00              | SQYD  | US 61/67 north bound                                  | 259+42                          |                     | 260+05                        |                     | Setting forms and grade for 7 " pave entrance at team entrance (70.0SY) and Flyer south 1/2 of entrance (23 SY). 259+42 to 260+05 LT  |
|                |              |  | 4/28/25           | 5/2/25                  | 72.00              | SQYD  | US 61/67 north bound                                  | 262+21                          |                     | 270+68                        |                     | Pour 7" pave approach Jungermann Road North half (SY) Pour 7" pave approach Animal Hospital south half (20  |
|                |              |  | 5/1/25            | 5/2/25                  | 22.40              | SQYD  | US 61/67 northbound                                   | 262+21                          |                     | 270+68                        |                     | 2 ADA ramps sidewalk at NE corner 265+01 LT Dollar<br>General   |
| 0090           | 3040506      | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)                          | 4/16/25           | 5/2/25                  | 66.70              | SQYD  | US 61/67 southbound                                   | 268_59                          |                     | 267+99                        |                     |   |
|                |              |  | 4/18/25           | 5/2/25                  | 207.10             | SQYD  | US 61/67 southbound                                   | 269+99                          |                     | 271+74                        |                     | Pour Optional Pavement at Sta. 269+99 to 271+74, R with 9.5' to 11', (199.3 SY) Gutter Pan paid as Optional pavement. Sta. 257+86 to 257+52 RT, 23.5x3/9= 7.8 SY              |
|                |              |  | 4/21/25           |                         |                    |       | US 61/67 southbound                                   | 268_59                          |                     | 267+99                        |                     |   |
|                |              |  | 4/22/25           | 5/2/25                  |                    |       | US 61/67 Southbound, RT US 61/67 Southbound           | 262+47<br>262+74                |                     | 262+87<br>262+87              |                     | Optional Pavement (40 LF x3) (13.3 SY) sta. 262+47<br>267+87 RT<br>Setting forms to Optional pavement in front of Macs a  |
|                |              |  |                   |                         |                    |       |   |                                 |                     |                               |                     | and Public water (73.3 SY)<br>Sta.262+47 to 262+87RT<br>Optional Pavement (41x3), (13.7 SY) (Sta. 259+43 to<br>259+02 RT)   |
|                |              |  |                   |                         |                    |       |   |                                 |                     |                               |                     | curb and gutter 2.6 SY  |
|                |              |  | 4/24/25           | 5/2/25                  | 87.20              | SQYD  | US 61/67 southbound                                   | 259+51                          |                     | 58+79                         |                     | Optional pavement entrance south entrance to Links 259+51 to 258+79) RT ( 87.2 SY)  |
|                |              |  | 5/1/25            | 5/2/25                  | 37.30              | SQYD  | US 61/67 Southbound                                   | 266+15                          |                     | 266+96                        |                     | Southbound US 61/67n Sta (266+15 to 266+96) RT (84x4), (37.3 SY)  |
| 0110           | 4019905      | MISC.  |                   |                         |                    |       | US 61/67 southbound                                   |                                 | 267+99              |                               |                     | pour OP at Sta. 268+59 to 267+99 (66.7Y)  |
|                |              |  | 4/18/25           |                         |                    |       | US 61/67 southbound                                   |                                 | 269+99              |                               |                     | Pour Optional Pavement at Sta. 269+99 to 271+74, F<br>with 9.5' to 11', (199.3 SY)<br>Gutter Pan paid as Optional pavement. Sta. 257+86 t<br>257+52 RT, 23.5x3/9= 7.8 SY      |
|                |              |  | 4/21/25           |                         |                    |       | US 61/67 southbound US 61/67 Southbound, RT           | 268+59<br>262+47                | 267+99              | 262+87                        |                     | pour OP at Sta. 268+59 to 267+99 (66.7Y)  Optional Pavement (40 LF x3) (13.3 SY) sta. 262+47  |
|                |              |  | 4/23/25           |                         |                    |       | US 61/67 Southbound Miller Road East                  | 262+74                          |                     | 262+87                        |                     | Setting forms to Optional pavement in front of Macs a and Public water (73.3 SY)  |
|                |              |  |                   |                         |                    |       |   |                                 |                     |                               |                     | Sta.262+47 to 262+87RT Optional Pavement (41x3), (13.7 SY) (Sta. 259+43 to 259+02 RT)   |
|                |              |  | 4/24/25           | 5/2/25                  | 87.20              | SQYD  | US 61/67 southbound                                   | 259+51                          | 267+99              | 258+79                        |                     | MIX ID 24SLHFRS0023 PCCP Vally Material  QC Test MIX ID 25SLHFFS001 PCCP Vally Materials  Optional pavement entrance south entrance to Links (                                |
|                |              |  | 5/1/25            | 5/2/25                  | 37.30              | SQYD  | US 61/67 Southbound RT                                | 266+15                          |                     | 266+99                        |                     | 259+51 to 258+79) RT (87.2 SY)  Southbound US 61/67n Sta (266+15 to 266+96) RT (84x4), (37.3 SY)  |
| 0230           | 6089902      | MISC. CONCRETE   | 5/1/25            | 5/2/25                  | 1.00               | EA    | US 61/67 Northbound                                   | 265+01                          |                     | 256+01                        |                     | 2 ADA ramps sidewalk at NE corner 265+01 LT Dolla   |
| 0250           | 6001052      | CURB AND GUTTER TYPE B   | 4/18/25           | 5/2/25                  | 10.00              | 1 E   | South Bound US 61/67                                  | 257+69                          |                     | 257+52                        |                     | General   |
| 0230           | 0091032      | CORB AND GOTTER TIPE B   | 4/23/25           |                         | 8.00               |       | US61/67 southbound RT                                 | 259+51                          |                     | 259+43                        |                     | Curb and Gutter (links auto south side 8 FT) Sta. 259   |
|                |              |  |                   |                         |                    |       |   |                                 |                     |                               |                     | to 259+43 RT  |
|                |              | CURVED VANE GRATE AND FRAME(4 FT. X 2 FT PAVEMENT EDGE TREATMENT | 4/29/25<br>5/1/25 |                         | 2.00               |       | St. John Church Road US 61/67 northbound / southbound | 189+52<br>257+34                |                     | 189+59<br>272+18              |                     | 1-1A, 1B  |
|                |              | SILT FENCE   | 4/21/25           |                         | 85.00              |       | St. John Church Road                                  | 0+50                            |                     | 1+35                          |                     |   |
| 0840           |              | SIGNAL HEAD, TYPE 11T  | 4/22/25           |                         | 2.00               |       | ST. John Church Road                                  | 196+40                          |                     | 182+08                        |                     | Face 25, 65   |
| 0850           | 9020213      | SIGNAL HEAD, TYPE 3S   | 4/16/25           | 5/2/25                  | 2.00               | EA    | US 61/67 and St. John Church Road                     | 189+64                          |                     | 189+74                        |                     |   |
| 0860           | 9020513      | SIGNAL HEAD, TYPE 3B   | 4/16/25           | 5/2/25                  | 3.00               | EA    | US 61/67 and St. John Church Road                     | 189+64                          |                     | 189+74                        |                     |   |
|                |              |  | 4/17/25           |                         | 2.00               |       | US 61/67 and St. John Church Road                     | 189+64                          |                     | 189+64                        |                     |   |
|                |              |  | 4/18/25           |                         | 2.00               |       | US 61/67 and St. John Church Road                     | 189+64                          |                     | 189+74                        |                     |   |
| 0870           | 9020514      | SIGNAL HEAD, TYPE 4B   | 4/17/25           |                         | 1.00               |       | US 61/67 and St. John Church Road                     | 189+64                          |                     | 189+74                        |                     |   |
| 005-           | 0005         | QUELAT QUEET - QUOUNT -::  | 4/18/25           |                         | 2.00               |       | US 61/61 St. John Church Road                         | 189+64                          |                     | 189+74                        |                     | D10 074 4 54  |
| 0880           | 9020833      | SH-FLAT SHEET - SIGNAL SIGN                                      | 4/22/25           | 5/2/25                  | 106.00             | SQFT  | US 61/67 St. John Church Road                         | 189+64                          |                     | 189+74                        |                     | R10-27A, 4 EA,<br>R3-5L 4 EA,<br>R10-3EL 4 EA<br>D3-1 A 2 EA<br>D3-1 B 1 EA<br>D3-1 C 1 EA  |
| 0890           | 9020834      | SIGNAL SIGN, MOUNTING HARDWARE                                   | 4/22/25           | 5/2/25                  | 18.00              | EA    | US 61/67 St. John Church Road                         | 189+64                          |                     | 189+75                        |                     | R10-27A, 4 EA,<br>R3-5L 4 EA,   |
|                |              |  |                   |                         |                    |       |   |                                 |                     |                               |                     | R10-3EL 4 EA<br>D3-1 A 2 EA   |

Revision 3/23/2023 Page 10 of 20



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

| Line<br>Number | Item<br>Code | Description                             | DWR<br>Date | DWR<br>Approval<br>Date | Quantity<br>Posted | Units | Location  | From<br>Station/<br>Log<br>Mile | Offset/<br>Distance | To<br>Station/<br>Log<br>Mile | Offset/<br>Distance | Comments  |
|----------------|--------------|---|-------------|-------------------------|--------------------|-------|---|---------------------------------|---------------------|-------------------------------|---------------------|---|
|                |              |   |             |                         |                    |       |   |                                 |                     |                               |                     | D3-1 B 1 EA<br>D3-1 C 1 EA  |
| 0900           | 9022708      | POST, SIGNAL 8 FT.                      | 4/18/25     | 5/2/25                  | 2.00               | EA    | US 61/67 St, John Church Road                     | 189+74                          |                     | 189+64                        |                     |   |
| 0910           | 9022715      | POST, SIGNAL 15 FT.                     | 4/22/25     | 5/2/25                  | 2.00               | EA    | US 61/67 St. John Church Road                     | 182+08                          |                     | 196+40                        |                     | Post 7, and 8   |
| 0980           | 9024283      | CONTROLLER ASSEMBLY HOUSING,            | 4/24/25     | 5/2/25                  | 1.00               | EA    | US 61/67 Miller road East                         | 265+84                          |                     | 265+84                        |                     | set cabinet   |
| 1000           | 9025300      | CONDUIT, 3 IN., TRENCH WITH TRACER WIRE | 4/22/25     | 5/2/25                  | 16.00              | LF    | US 61/67 Miller Road East,                        | 265+84                          |                     | 265+84                        |                     | Controller to PB 1= 16  |
|                |              |   | 4/24/25     | 5/2/25                  | 8.00               | LF    | US 61/67 Miller road                              | 274+85                          |                     | 274+85                        |                     | PB 2 to Post 6 8 LF   |
| 1120           | 9028821      | PULL BOX, CONCRETE, DOUBLE, TYPE A      | 4/23/25     | 5/2/25                  | 1.00               | EA    | Miller Road East                                  | 265+81                          |                     | 265+81                        |                     | PB 1  |
| 1130           | 9029100      | BASE, CONCRETE                          | 4/16/25     | 5/2/25                  | 4.15               | CUYD  | US 61/67 at Miller road East                      | 264+87                          |                     | 274+85                        |                     | Post 4, Post 7 Post 8 at Miller Road East   |
|                |              |   | 4/18/25     | 5/2/25                  | 2.85               | CUYD  | US 61/67 Miller Road East                         | 265+91                          |                     | 265+91                        |                     | poured<br>Controller 1.93 CY, Sta. 265+84<br>PWR Supply .92 CY Sta. 265+91  |
|                |              |   | 4/23/25     | 5/2/25                  | 0.44               | CUYD  | US 61/67 Miller Road East                         | 274+85                          |                     | 274+85                        |                     | POST 6<br>23SLB0RS001 MO Class B 25% FA WR American Ready<br>Mix  |
|                |              |   | 4/28/25     | 5/2/25                  | 3.27               | CUYD  | US 61/67 Miller Road East                         | 265+66                          |                     | 265+66                        |                     | POST 2 3.27<br>SOFT POST 1<br>MIX ID: 23SLB0RS001 MO Class B 25% FA WR.<br>American Ready Mix                           |
|                |              |   | 5/1/25      | 5/2/25                  | 3.00               | CUYD  | US 61/67 Miller Road East                         | 265+75                          |                     | 265+75                        |                     | POST 1 3.01  MIX ID: 23SLB0RS001 MO Class B 25% FA WR. American Ready Mix and c Base at the NE corner of Dollar General |
| 1190           | 9029902      | MISC.                                   | 4/24/25     | 5/2/25                  | 1.00               | EA    | US 61/67 Mller Road East                          | 265+84                          |                     | 265+84                        |                     | Set Cabinet   |
| 1200           | 9029902      | MISC.                                   | 4/18/25     | 5/2/25                  | 6.00               | EA    | US 61/67 and St. Church Road                      | 189+64                          |                     | 189+74                        |                     |   |
| 1210           | 9029902      | MISC.                                   | 4/29/25     | 5/2/25                  | 1.00               | EA    | US 61/67 , St. John Church Road                   | 189+64                          |                     | 198+74                        |                     |   |
| 1340           | 9109902      | MISC. ITS                               | 4/16/25     | 5/2/25                  | 1.00               | EA    | US 61/67 and St. John Church Road                 | 189+74                          |                     | 189+64                        |                     |   |
| 1350           | 9109902      | MISC. ITS                               | 4/29/25     | 5/2/25                  | 8.00               | EA    | US 61/67 St. Joun church Road and Richardson Road | 188+00                          |                     | 209+00                        |                     | Chruch=4<br>Richardson=4  |
| 1360           | 9109902      | MISC. ITS                               | 4/29/25     | 5/2/25                  | 8.00               | EA    | US 61/67 St. Joun church Road and Richardson Road | 188+00                          |                     | 209+00                        |                     | US 61/67 St. Joun church Road and Richardson Road<br>Chruch=4<br>Richardson=4   |
| 1370           | 9109902      | MISC. ITS                               | 4/16/25     | 5/2/25                  | 1.00               | EA    | US 61/67 and St. John Church Road                 | 189+64                          |                     | 189+74                        |                     |   |
| 1410           | 9109902      | MISC. ITS                               | 4/28/25     | 5/2/25                  | 1.00               | EA    | US 61/67 Miller Road East                         | 258+44                          |                     | 258+44                        |                     | iPB11   |
| 1430           | 9109902      | MISC. ITS                               | 4/29/25     | 5/2/25                  | 30.00              | EA    | US 61/67 St. Joun church Road and Richardson Road | 188+00                          |                     | 209+00                        |                     | US 61/67 St. Joun church Road and Richardson Road<br>Chruch=4<br>Richardson=26  |
| 1440           | 9109902      | MISC. ITS                               | 4/29/25     | 5/2/25                  | 1.00               | EA    | US 61/67 St. John Church Road                     | 190+00                          |                     | 188+00                        |                     |   |
| 1480           | 9109903      | MISC. ITS                               | 4/28/25     | 5/2/25                  | 2,827.00           | LF    |   | 189+64                          |                     | 189+74                        |                     | New CONT, TO IPB01 = 65<br>IPB01 TO IPB02 974'<br>IPB02 TO PB03= 1545<br>IPB03 TO EIPB04=169<br>EIPB04 TO EX. CONTR=74  |

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023 Page 11 of 20



| Project | Line   | Description               | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks  |
|---------|--------|---------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| J6S3640 | 0040   | COMPACTING<br>EMBANKMENT  | Material           |                             | 12             | Apr 3,<br>2025  | SYSTEM        | \$9,650.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate.  |
|         |        |                           |                    |                             | 12             | Apr 3,<br>2025  | SYSTEM        | (\$9,650.00)  |  |
|         |        |                           |                    |                             | 13             | Apr 16,<br>2025 | SYSTEM        | \$9,650.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user smithh5 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
|         |        |                           |                    |                             | 13             | Apr 16,<br>2025 | SYSTEM        | (\$9,650.00)  |  |
|         |        |                           |                    |                             | 14             | May 2,<br>2025  | SYSTEM        | \$20,265.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user smithh5 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
|         |        |                           |                    |                             | 14             | May 2,<br>2025  | SYSTEM        | (\$20,265.00) |  |
|         |        |                           |                    | - Total                     |                |                 |               | \$0.00        |  |
|         |        |                           | Material - Tota    | 1                           |                |                 |               | \$0.00        |  |
|         | 0040 - | · Total                   |                    |                             |                |                 |               | \$0.00        |  |
|         | 0800   | AGGREGATE                 | Material           |                             | 12             | Apr 3,<br>2025  | SYSTEM        | (\$703.74)    |  |
|         |        | FOR BASE                  |                    |                             | 13             | Apr 16,<br>2025 | SYSTEM        | \$1,675.26    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user smithh5 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
|         |        |                           |                    |                             | 13             | Apr 16,<br>2025 | SYSTEM        | (\$1,675.26)  |  |
|         |        |                           |                    | - Total                     |                |                 |               | (\$703.74)    |  |
|         |        |                           | Material - Tota    |                             |                |                 |               | (\$703.74)    |  |
|         |        |                           | MaterialCredit     |                             | 13             | Apr 16,<br>2025 | SYSTEM        | \$703.74      |  |
|         |        |                           |                    | - Total                     |                |                 |               | \$703.74      |  |
|         |        |                           | MaterialCredit     | - Total                     |                |                 |               | \$703.74      |  |
|         | 0080 - | · Total                   |                    |                             |                |                 |               | \$0.00        |  |
|         | 0090   | TYPE 5<br>AGGREGATE       | Material           |                             | 9              | Feb 18,<br>2025 | SYSTEM        | (\$2,629.63)  |  |
|         |        | FOR BASE (6<br>IN. THICK) |                    |                             | 10             | Mar 3,<br>2025  | SYSTEM        | \$3,005.95    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user smithh5 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
|         |        |                           |                    |                             | 10             | Mar 3,<br>2025  | SYSTEM        | (\$3,005.95)  |  |
|         |        |                           |                    |                             | 11             | Mar 17,<br>2025 | SYSTEM        | (\$5,179.39)  |  |
|         |        |                           |                    |                             | 12             | Apr 3,<br>2025  | SYSTEM        | (\$10,840.70) |  |
|         |        |                           |                    |                             | 13             | Apr 16,<br>2025 | SYSTEM        | \$13,536.77   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user smithh5 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
|         |        |                           |                    |                             | 13             | Apr 16,<br>2025 | SYSTEM        | (\$13,536.77) |  |
|         |        |                           |                    | - Total                     |                |                 |               | (\$18,649.72) |  |
|         |        |                           | Material - Tota    | ıl                          |                |                 |               | (\$18,649.72) |  |
|         |        |                           | MaterialCredit     |                             | 10             | Mar 3,<br>2025  | SYSTEM        | \$2,629.63    |  |
|         |        |                           |                    |                             | 12             | Apr 3,<br>2025  | SYSTEM        | \$5,179.39    |  |
|         |        |                           |                    |                             | 13             | Apr 16,<br>2025 | SYSTEM        | \$10,840.70   |  |
|         |        |                           |                    | - Total                     |                |                 |               | \$18,649.72   |  |
|         |        |                           | MaterialCredit     | - Total                     |                |                 |               | \$18,649.72   |  |
|         | 0090 - | · Total                   |                    |                             |                |                 |               | \$0.00        |  |
|         | 0110   | MISC.                     | Material           |                             | 10             | Mar 3,<br>2025  | SYSTEM        | \$47,178.64   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user smithh5 overridding Payment   |



| Project | Line   | Description                 | Adjustment<br>Type | Other<br>Adjustment | Est.<br>Number | Created<br>Date | Created<br>By | Amount         | Remarks  |
|---------|--------|-----------------------------|--------------------|---------------------|----------------|-----------------|---------------|----------------|--|
| J6S3640 | 0110   | MISC.                       | Material           | Туре                | 10             | Mar 3,          | SYSTEM        | (\$47,178.64)  |  |
|         |        |                             |                    |                     |                | 2025            |               | (, , , , , ,   |  |
|         |        |                             |                    |                     | 11             | Mar 17,<br>2025 | SYSTEM        | \$88,764.08    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user smithh5 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
|         |        |                             |                    |                     | 11             | Mar 17,<br>2025 | SYSTEM        | (\$88,764.08)  |  |
|         |        |                             |                    |                     | 12             | Apr 3,<br>2025  | SYSTEM        | \$215,599.22   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user burlbe overridding Payment Estimate Exception 5 on the current Payment Estimate.  |
|         |        |                             |                    |                     | 12             | Apr 3,<br>2025  | SYSTEM        | (\$215,599.22) |  |
|         |        |                             |                    |                     | 13             | Apr 16,<br>2025 | SYSTEM        | \$279,054.07   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user smithh5 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
|         |        |                             |                    |                     | 13             | Apr 16,<br>2025 | SYSTEM        | (\$279,054.07) |  |
|         |        |                             |                    |                     | 14             | May 2,<br>2025  | SYSTEM        | \$325,477.63   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user smithh5 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
|         |        |                             |                    |                     | 14             | May 2,<br>2025  | SYSTEM        | (\$325,477.63) |  |
|         |        |                             |                    | - Total             |                |                 |               | \$0.00         |  |
|         |        |                             | Material - Tota    | ıl                  |                |                 |               | \$0.00         |  |
|         | 0110 - | Total                       |                    |                     |                |                 |               | \$0.00         |  |
|         | 0200   | TRUNCATED DOMES             | Material           |                     | 11             | Mar 17,<br>2025 | SYSTEM        | (\$465.52)     |  |
|         |        |                             |                    |                     | 12             | Apr 3,<br>2025  | SYSTEM        | (\$465.52)     |  |
|         |        |                             |                    |                     | 13             | Apr 16,<br>2025 | SYSTEM        | \$465.52       | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user smithh5 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
|         |        |                             |                    |                     | 13             | Apr 16,<br>2025 | SYSTEM        | (\$465.52)     |  |
|         |        |                             |                    |                     | 14             | May 2,<br>2025  | SYSTEM        | \$465.52       | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user smithh5 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
|         |        |                             |                    |                     | 14             | May 2,<br>2025  | SYSTEM        | (\$465.52)     |  |
|         |        |                             |                    | - Total             |                |                 |               | (\$931.04)     |  |
|         |        |                             | Material - Tota    | ıl                  |                |                 |               | (\$931.04)     |  |
|         |        |                             | MaterialCredit     |                     | 12             | Apr 3,<br>2025  | SYSTEM        | \$465.52       |  |
|         |        |                             |                    |                     | 13             | Apr 16,<br>2025 | SYSTEM        | \$465.52       |  |
|         |        |                             |                    | - Total             |                |                 |               | \$931.04       |  |
|         |        |                             | MaterialCredit     | - Total             |                |                 |               | \$931.04       |  |
|         | 0200 - | Total                       |                    |                     |                |                 |               | \$0.00         |  |
|         | 0210   | PAVED<br>APPROACH, 8<br>IN. | Material           |                     | 12             | Apr 3,<br>2025  | SYSTEM        | \$15,273.86    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user burlbe overridding Payment Estimate Exception 9 on the current Payment Estimate.  |
|         |        | 114.                        |                    |                     | 12             | Apr 3,<br>2025  | SYSTEM        | (\$15,273.86)  |  |
|         |        |                             |                    |                     | 13             | Apr 16,<br>2025 | SYSTEM        | \$30,064.37    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user smithh5 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
|         |        |                             |                    |                     | 13             | Apr 16,<br>2025 | SYSTEM        | (\$30,064.37)  |  |
|         |        |                             |                    |                     | 14             | May 2,<br>2025  | SYSTEM        | \$30,064.37    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user smithh5 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
|         |        |                             |                    |                     | 14             | May 2,<br>2025  | SYSTEM        | (\$30,064.37)  |  |
|         |        |                             |                    | - Total             |                |                 |               | \$0.00         |  |



| Project | Line                              | Description                 | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number  | Created<br>Date | Created<br>By | Amount   | Remarks   |               |  |
|---------|-----------------------------------|-----------------------------|--------------------|-----------------------------|-----------------|-----------------|---------------|--|---|---------------|--|
| J6S3640 | 0210                              | PAVED<br>APPROACH, 8<br>IN. | Material - Tota    |                             |                 |                 |               | \$0.00   |   |               |  |
|         | 0210 -                            | Total                       |                    |                             |                 |                 |               | \$0.00   |   |               |  |
|         | 0220                              | SIDEWALK, 4                 | Material           |                             | 11              | Mar 17,<br>2025 | SYSTEM        | (\$1,581.56)   |   |               |  |
|         |                                   | IN.                         |                    |                             | 12              | Apr 3,<br>2025  | SYSTEM        | \$7,031.98   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user burlbe overridding Payment Estimate Exception 11 on the current Payment Estimate.  |               |  |
|         |                                   |                             |                    |                             | 12              | Apr 3,<br>2025  | SYSTEM        | (\$7,031.98)   |   |               |  |
|         |                                   |                             |                    |                             | 13              | Apr 16,<br>2025 | SYSTEM        | \$7,031.98   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user smithh5 overridding Payment Estimate Exception 9 on the current Payment Estimate.  |               |  |
|         |                                   |                             |                    |                             | 13              | Apr 16,<br>2025 | SYSTEM        | (\$7,031.98)   |   |               |  |
|         |                                   |                             |                    |                             | 14              | May 2,<br>2025  | SYSTEM        | \$7,031.98   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user smithh5 overridding Payment Estimate Exception 5 on the current Payment Estimate.  |               |  |
|         |                                   |                             |                    |                             | 14              | May 2,<br>2025  | SYSTEM        | (\$7,031.98)   |   |               |  |
|         |                                   |                             |                    | - Total                     |                 |                 |               | (\$1,581.56)   |   |               |  |
|         |                                   |                             | Material - Tota    | ıl                          |                 |                 |               | (\$1,581.56)   |   |               |  |
|         |                                   |                             | MaterialCredit     |                             | 12              | Apr 3,<br>2025  | SYSTEM        | \$1,581.56   |   |               |  |
|         |                                   |                             |                    | - Total                     |                 |                 |               | \$1,581.56   |   |               |  |
|         |                                   |                             | MaterialCredit     | - Total                     |                 |                 |               | \$1,581.56   |   |               |  |
|         | 0220 -                            | Total                       |                    |                             |                 |                 |               | \$0.00   |   |               |  |
|         | 0230                              | MISC.<br>CONCRETE           | Material           |                             | 11              | Mar 17,<br>2025 | SYSTEM        | (\$3,335.30)   |   |               |  |
|         |                                   |                             |                    |                             | 12              | Apr 3,<br>2025  | SYSTEM        | (\$10,005.90)  |   |               |  |
|         |                                   |                             |                    |                             | 13              | Apr 16,<br>2025 | SYSTEM        | \$10,005.90  | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user smithh5 overridding Payment Estimate Exception 10 on the current Payment Estimate. |               |  |
|         |                                   |                             |                    |                             |                 |                 | 13            | Apr 16,<br>2025  | SYSTEM  | (\$10,005.90) |  |
|         |                                   |                             |                    |                             | 14              | May 2,<br>2025  | SYSTEM        | \$13,341.20  | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user smithh5 overridding Payment Estimate Exception 6 on the current Payment Estimate.  |               |  |
|         |                                   |                             |                    |                             | 14              | May 2,<br>2025  | SYSTEM        | (\$13,341.20)  |   |               |  |
|         |                                   |                             |                    | - Total                     |                 |                 |               | (\$13,341.20)  |   |               |  |
|         |                                   |                             | Material - Tota    | ı                           |                 |                 |               | (\$13,341.20)  |   |               |  |
|         |                                   |                             | MaterialCredit     |                             | 12              | Apr 3,<br>2025  | SYSTEM        | \$3,335.30   |   |               |  |
|         |                                   |                             |                    |                             | 13              | Apr 16,<br>2025 | SYSTEM        | \$10,005.90  |   |               |  |
|         |                                   |                             |                    | - Total                     |                 |                 |               | \$13,341.20  |   |               |  |
|         |                                   |                             | MaterialCredit     | - Total                     |                 |                 |               | \$13,341.20  |   |               |  |
|         | 0230 -                            | 0230 - Total                |                    |                             |                 |                 |               | \$0.00   |   |               |  |
|         | 0250 CURB AND<br>GUTTER TYPE<br>B | Material                    |                    | 9                           | Feb 18,<br>2025 | SYSTEM          | (\$26,525.84) |  |   |               |  |
|         | В                                 |                             |                    | 10                          | Mar 3,<br>2025  | SYSTEM          | \$37,854.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user smithh5 overridding Payment Estimate Exception 6 on the current Payment Estimate. |   |               |  |
|         |                                   |                             |                    |                             | 10              | Mar 3,<br>2025  | SYSTEM        | (\$37,854.00)  |   |               |  |
|         |                                   |                             |                    | 11                          | Mar 17,<br>2025 | SYSTEM          | \$45,032.24   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user smithh5 overridding Payment Estimate Exception 9 on the current Payment Estimate. |   |               |  |
|         |                                   |                             |                    |                             | 11              | Mar 17,<br>2025 | SYSTEM        | (\$45,032.24)  |   |               |  |



| Project | Line               | Description                  | Adjustment<br>Type                | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount                     | Remarks   |
|---------|--------------------|------------------------------|-----------------------------------|-----------------------------|----------------|-----------------|---------------|----------------------------|---|
| J6S3640 | 0250               | CURB AND<br>GUTTER TYPE<br>B | Material                          |                             | 12             | Apr 3,<br>2025  | SYSTEM        | \$64,520.04                | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user burlbe overridding Payment Estimate Exception 14 on the current Payment Estimate.  |
|         |                    |                              |                                   |                             | 12             | Apr 3,<br>2025  | SYSTEM        | (\$64,520.04)              |   |
|         |                    |                              |                                   |                             | 13             | Apr 16,<br>2025 | SYSTEM        | \$68,669.96                | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user smithh5 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
|         |                    |                              |                                   |                             | 13             | Apr 16,<br>2025 | SYSTEM        | (\$68,669.96)              |   |
|         |                    |                              |                                   |                             | 14             | May 2,<br>2025  | SYSTEM        | \$69,679.40                | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user smithh5 overridding Payment Estimate Exception 8 on the current Payment Estimate.  |
|         |                    |                              |                                   |                             | 14             | May 2,<br>2025  | SYSTEM        | (\$69,679.40)              |   |
|         |                    |                              |                                   | - Total                     |                |                 |               | (\$26,525.84)              |   |
|         |                    |                              | Material - Tota                   | ı                           |                |                 |               | (\$26,525.84)              |   |
|         |                    |                              | MaterialCredit                    |                             | 10             | Mar 3,<br>2025  | SYSTEM        | \$26,525.84                |   |
|         |                    |                              |                                   | - Total                     |                |                 |               | \$26,525.84                |   |
|         |                    |                              | MaterialCredit                    | - Total                     |                |                 |               | \$26,525.84                |   |
|         | 0250 -             | · Total                      |                                   |                             |                |                 |               | \$0.00                     |   |
|         | 0320               | CURVED<br>VANE GRATE         | Material                          |                             | 11             | Mar 17,<br>2025 | SYSTEM        | (\$2,114.56)               |   |
|         |                    | AND FRAME(4<br>FT. X 2 FT    |                                   |                             | 12             | Apr 3,<br>2025  | SYSTEM        | (\$2,114.56)               |   |
|         |                    |                              |                                   | - Total                     |                |                 |               | (\$4,229.12)               |   |
|         |                    |                              | Material - Tota                   | ı                           |                |                 |               | (\$4,229.12)               |   |
|         |                    |                              | MaterialCredit                    |                             | 12             | Apr 3,<br>2025  | SYSTEM        | \$2,114.56                 |   |
|         |                    |                              |                                   |                             | 13             | Apr 16,<br>2025 | SYSTEM        | \$2,114.56                 |   |
|         |                    |                              |                                   | - Total                     |                |                 |               | \$4,229.12                 |   |
|         |                    |                              | MaterialCredit                    | - Total                     |                |                 |               | \$4,229.12                 |   |
|         | <b>0320</b> - 0430 | PAVEMENT                     | Material                          |                             | 11             | Mar 17,         | SYSTEM        | \$0.00<br>(\$2,288.00)     |   |
|         |                    | EDGE<br>TREATMENT            |                                   |                             |                | 2025            |               | (00.000.00)                |   |
|         |                    |                              | Material Tata                     | - Total                     |                |                 |               | (\$2,288.00)               |   |
|         |                    |                              | Material - Tota<br>MaterialCredit |                             | 12             | Apr 3,          | SYSTEM        | (\$2,288.00)<br>\$2,288.00 |   |
|         |                    |                              |                                   | - Total                     |                | 2025            |               | \$2,288.00                 |   |
|         |                    |                              | MaterialCredit                    | - Total                     |                |                 |               | \$2,288.00                 |   |
|         | 0430 -             | · Total                      |                                   |                             |                |                 |               | \$0.00                     |   |
|         | 0590               | 18 IN. PIPE<br>GROUP A       | Material                          |                             | 5              | Dec 16,<br>2024 | SYSTEM        | (\$1,799.07)               |   |
|         |                    |                              |                                   |                             | 6              | Jan 2,<br>2025  | SYSTEM        | (\$1,799.07)               |   |
|         |                    |                              |                                   |                             | 7              | Jan 16,<br>2025 | SYSTEM        | (\$1,799.07)               |   |
|         |                    |                              |                                   |                             | 8              | Feb 3,<br>2025  | SYSTEM        | \$1,799.07                 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user smithea overridding Payment Estimate Exception 1 on the current Payment Estimate.  |
|         |                    |                              |                                   |                             | 8              | Feb 3,<br>2025  | SYSTEM        | (\$1,799.07)               |   |
|         |                    |                              |                                   | - Total                     |                |                 |               | (\$5,397.21)               |   |
|         |                    |                              | Material - Tota                   | ı                           |                |                 |               | (\$5,397.21)               |   |
|         |                    |                              | MaterialCredit                    |                             | 6              | Jan 2,<br>2025  | SYSTEM        | \$1,799.07                 |   |
|         |                    |                              |                                   |                             |                |                 |               |                            |   |



| SROUP A   8  | ct  | Line   | Description              | Adjustment                          | Other               | Est.       | Created        | Created | Amount                        | Remarks   |
|--|-----|--------|--------------------------|-------------------------------------|---------------------|------------|----------------|---------|-------------------------------|---|
| GROUP A  |     |        |                          | Туре                                |                     | Number     | Date           | Ву      |                               |   |
| 8   F60 3,   979TEM   \$5.9907   | 40  | 0590   |                          | MaterialCredit                      |                     |            | 2025           |         |                               |   |
| Material Credit - Total  |     |        | GROUP A                  |                                     |                     | 8          |                | SYSTEM  | \$1,799.07                    |   |
| Section   Construction   Construct |     |        |                          |                                     | - Total             |            |                |         | \$5,397.21                    |   |
| PRECAST   Material Continue  |     |        |                          | MaterialCredit                      | - Total             |            |                |         | \$5,397.21                    |   |
| CONCRETE   |     | 0590 - | Total                    |                                     |                     |            |                |         | \$0.00                        |   |
| 8  |     | 0600   | CONCRETE<br>MANHOLE - 48 | Material                            |                     | 8          |                | SYSTEM  | \$2,766.80                    | Estimate Item Adjustment (0003) due to user smithea overridding Payment |
| 10   |     |        | IIN.                     |                                     |                     | 8          |                | SYSTEM  | (\$2,766.80)                  |   |
| 1  |     |        |                          |                                     |                     | 9          |                | SYSTEM  | (\$2,766.80)                  |   |
|  |     |        |                          |                                     |                     | 10         |                | SYSTEM  | (\$4,980.24)                  |   |
| Total   SYSTEM   Sy |     |        |                          |                                     |                     | 11         |                | SYSTEM  | (\$4,980.24)                  |   |
| Material - Total   10   Mar 3   2025   27:96.80  |     |        |                          |                                     |                     | 12         |                | SYSTEM  | (\$4,980.24)                  |   |
| Material - Total   10   Mar 3   2025   27:96.80  |     |        |                          |                                     | - Total             |            |                |         | (\$1 <u>7,70</u> <u>7.52)</u> |   |
| MaterialCredit   |     |        |                          | Material - Tota                     |                     |            |                |         |                               |   |
| 2025   12  |     |        |                          | MaterialCredit                      |                     | 10         |                | SYSTEM  |                               |   |
| 13   |     |        |                          |                                     |                     | 11         |                | SYSTEM  | \$4,980.24                    |   |
| Signal   S |     |        |                          |                                     |                     | 12         |                | SYSTEM  | \$4,980.24                    |   |
| Material Credit - Total   S17,707.52   S000 - Total   S17,707.52   |     |        |                          |                                     |                     | 13         |                | SYSTEM  | \$4,980.24                    |   |
|  |     |        |                          |                                     | - Total             |            |                |         | \$17,707.52                   |   |
| 15 IN. GROUP   A FLARED   END SECT   Material   8  |     |        |                          | MaterialCredit                      | erialCredit - Total |            |                |         | \$17,707.52                   |   |
| A FLARED   Estimate Item Adjustment (0004) due to user smithea overridding Payment Estimate Exception 3 on the current Payment Estimate.   |     | 0600 - | Total                    |                                     |                     |            |                |         | \$0.00                        |   |
| Activation   Construction   Constr |     | 0650   | A FLARED                 | Material                            |                     | 8          |                | SYSTEM  | \$1,939.77                    | Estimate Item Adjustment (0004) due to user smithea overridding Payment |
| Material - Total   S0.00   |     |        |                          |                                     |                     | 8          |                | SYSTEM  | (\$1,939.77)                  |   |
|  |     |        |                          |                                     | - Total             |            |                |         | \$0.00                        |   |
| SILT FENCE   Material   8  |     |        |                          | Material - Tota                     | I                   |            |                |         | \$0.00                        |   |
| 2025   Estimate Item Adjustment (0005) due to user smithea overridding Payment Estimate Exception 4 on the current Payment Estimate.   |     | 0650 - | Total                    |                                     |                     |            |                |         | \$0.00                        |   |
| Total   \$0.00   |     | 0770   | SILT FENCE               | Material                            |                     | 8          | Feb 3,<br>2025 | SYSTEM  | \$3,212.50                    | Estimate Item Adjustment (0005) due to user smithea overridding Payment |
| Material - Total   \$0.00  |     |        |                          |                                     |                     | 8          |                | SYSTEM  | (\$3,212.50)                  |   |
| 1  |     |        |                          |                                     | - Total             |            |                |         | \$0.00                        |   |
| O840 SIGNAL HEAD, TYPE 11T Stockpile STMI - Total \$3,112.16 Payment Estimate Item Adjustment generated Stockpile Transaction \$3,112.16   |     |        |                          | Material - Tota                     |                     |            |                |         | \$0.00                        |   |
| TYPE 11T   |     | 0770 - | Total                    |                                     |                     |            |                |         | \$0.00                        |   |
| Construction Stockpile STMI - Total   \$3,112.16   |     | 0840   |                          | Stockpile                           |                     | 11         |                | SYSTEM  | \$3,112.16                    | Payment Estimate Item Adjustment generated Stockpile Transaction        |
| 0840 - Total  0850 SIGNAL HEAD, TYPE 3S STMI  - Total  Construction Stockpile STMI - Total  \$3,112.16  \$2,234.48 Payment Estimate Item Adjustment generated Stockpile Transaction \$2,234.48  Construction Stockpile STMI - Total  \$2,234.48  | 084 |        |                          | O I IVII                            | - Total             |            |                |         | \$3,112.16                    |   |
| 0850 SIGNAL HEAD, TYPE 3S Stockpile STMI - Total S12,234.48 Payment Estimate Item Adjustment generated Stockpile Transaction \$2,234.48 Payment Estimate Item Adjustment generated Stockpile Transaction \$2,234.48 Payment Estimate Item Adjustment generated Stockpile Transaction \$2,234.48  |     |        |                          | Construction S                      | Stockpile STI       | MI - Total |                |         | \$3,112.16                    |   |
| TYPE 3S   Stockpile   STM    2025  |     | 0840 - | Total                    |                                     |                     |            |                |         | \$3,112.16                    |   |
| - Total \$2,234.48  Construction Stockpile STMI - Total \$2,234.48   |     | 0850   |                          | Stockpile                           |                     | 11         |                | SYSTEM  | \$2,234.48                    | Payment Estimate Item Adjustment generated Stockpile Transaction        |
|  |     |        |                          | O I IVII                            | - Total             |            |                |         | \$2,234.48                    |   |
| 0850 - Total \$2,234.48  |     |        |                          | Construction Stockpile STMI - Total |                     |            |                |         | \$2,234.48                    |   |
|  |     | 0850 - | Total                    |                                     |                     |            |                |         | \$2,234.48                    |   |



| State   Description  |    |        |                      |                 |                |             |        |               |  |
|--|----|--------|----------------------|-----------------|----------------|-------------|--------|---------------|--|
| TYPE 58   Stockhole   Total   Status  | ct | Line   | Description          |                 | Adjustment     |             |        | Amount        | Remarks  |
| Construction Stockpile STM   Total   \$12,334.66   | 40 | 0860   |                      | Stockpile       |                | 11          | SYSTEM | \$12,393.60   | Payment Estimate Item Adjustment generated Stockpile Transaction       |
| SIGNAL FEAD   Construction Stockpile STMI - Total   Signal   Sig   |    |        |                      | STMI            | - Total        |             |        | \$12,393.60   |  |
| SIGNAL HEAD   Construction   Stockpile Transaction   Type 48   Stockpile   Transaction   Type 48   Stockpile   Transaction   Type 48   Stockpile   Transaction   Type 48   Stockpile   Transaction   Type 48   Stockpile   Transaction   Type 48   Stockpile   Type 48   |    |        |                      | Construction    | Stockpile STI  | /II - Total |        | \$12,393.60   |  |
| Type 48   Stockyle   STM   |    | 0860 - | Total                |                 |                |             |        | \$12,393.60   |  |
| Construction Stockple STM - Total   \$3,504.00   |    | 0870   |                      | Stockpile       |                | 11          | SYSTEM | \$3,604.00    | Payment Estimate Item Adjustment generated Stockpile Transaction       |
| 14   |    |        |                      | 011111          | - Total        |             |        | \$3,604.00    |  |
| 14   |    |        |                      | Construction    | Stockpile STI  | /II - Total |        | \$3,604.00    |  |
| SFT.   |    | 0870 - | Total                |                 |                |             |        | \$3,604.00    |  |
| Total   S0.00  |    | 0900   |                      | Material        |                | 14          | SYSTEM | \$2,314.20    | Estimate Item Adjustment (0008) due to user smithh5 overridding Paymer |
| Material - Total   S0 00   |    |        |                      |                 |                | 14          | SYSTEM | (\$2,314.20)  |  |
| POST_SIGNAL   Material   14  |    |        |                      |                 | - Total        |             |        | \$0.00        |  |
| POST, SIGNAL   16 FT.  |    |        |                      | Material - Tota | ıl             |             |        | \$0.00        |  |
| Section   Control   Construction Stockpile   Total   SySTEM   Sy   |    | 0900 - | Total                |                 |                |             |        | \$0.00        |  |
| 2025   Society   |    | 0910   |                      | Material        |                | 14          | SYSTEM | \$3,465.00    | Estimate Item Adjustment (0009) due to user smithh5 overridding Paymer |
| Material - Total   \$0.00  |    |        |                      |                 |                | 14          | SYSTEM | (\$3,465.00)  |  |
| Construction   Stockpile   Total   So.00   Total   S   |    |        |                      |                 | - Total        |             |        | \$0.00        |  |
| Contraction   Stockpile   Transaction   St   |    |        |                      | Material - Tota | ıl             |             |        | \$0.00        |  |
| ASSEMBLY   HOUSING,   -Total   (\$32,0\$2.28)  |    | 0910 - | Total                |                 |                |             |        | \$0.00        |  |
| Total  |    | 0980   | ASSEMBLY             |                 |                | 14          | SYSTEM | (\$32,052.28) | Payment Estimate Item Adjustment generated Stockpile Transaction       |
| Construction Stockpile   11  |    |        | ,                    |                 | - Total        |             |        | (\$32,052.28) |  |
| Stockpile   STMI   |    |        |                      | Construction    | Stockpile - To | tal         |        | (\$32,052.28) |  |
| Construction Stockpile STMI - Total   \$32,052.28  |    |        |                      | Stockpile       |                | 11          | SYSTEM |               | Payment Estimate Item Adjustment generated Stockpile Transaction       |
| 1100   |    |        |                      |                 |                |             |        |               |  |
| 1100   |    |        |                      | Construction    | Stockpile STI  | /II - Total |        |               |  |
| 2024   Estimate Item Adjustment (0001) due to user smithea overridding Paymer Estimate Exception 1 on the current Payment Estimate.  |    | 0980 - | Total                |                 |                |             |        | \$0.00        |  |
| Total   \$0.00   |    | 1100   | PREFORMED            | Material        |                | 1           | SYSTEM | \$3,372.60    | Estimate Item Adjustment (0001) due to user smithea overridding Paymer |
| Material - Total   S0.00   |    |        |                      |                 | T              | 1           | SYSTEM | , , ,         |  |
| 1120 PULL BOX, CONCRETE, DOUBLE, TYPE A  PULL BOX CONCRETE, DOUBLE, TYPE A  PULL BOX CONCRETE, DOUBLE, TYPE A  Pound Box Construction Stockpile STMI  Pound Box Construction Stockpile STMI  Total  Solution Stockpile STMI  Solution Stockpile STMI  Total  Solution Stockpile STMI  Solution Stockpile STMI Solution Stockpile STMI Total  Solution Stockpile STMI Solution Stockpile STMI Total  Solution Stockpile STMI Solution Stockpile STMI Total  Solution Stockpile STMI Solution Solution Stockpile STMI Total  Solution Stockpile STMI Solution Solution Stockpile STMI Total  Solution Stockpile STMI Solution Solution Stockpile STMI Total  Solution Stackpile STMI Total  Solution Stockpile STMI Total  Solution Stackpile STMI Total  Solution St   |    |        |                      | Maderia         |                |             |        |               |  |
| PULL BOX, CONCRETE, DOUBLE, TYPE A   8   Feb 3, 2025   SYSTEM   \$5,688.90   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user smithea overridding Payment Estimate Exception 5 on the current Payment Estimate.   8   Feb 3, 2025   SYSTEM   \$5,688.90   SYSTEM   \$5,688.90    - Total   \$0.00    - Total   \$5,501.40   Payment Estimate Item Adjustment generated Stockpile Transaction    - Total   \$5,501.40    - Total   \$5, |    |        |                      | Material - Tota | "              |             |        |               |  |
| 2025   Estimate Item Adjustment (0006) due to user smithea overridding Paymer Estimate Exception 5 on the current Payment Estimate.    2025  |    |        |                      |                 |                |             |        |               |  |
| Naterial - Total   \$0.00  |    | 1120   | CONCRETE,<br>DOUBLE, | Material        |                | 8           | SYSTEM | \$5,688.90    | Estimate Item Adjustment (0006) due to user smithea overridding Paymer |
| Material - Total   |    |        | 11124                |                 |                | 8           | SYSTEM | ,             |  |
| 1120 - Total  MISC. Construction Stockpile STMI - Total  1180 - Total  Construction Stockpile STMI - Total  S5,501.40 Payment Estimate Item Adjustment generated Stockpile Transaction \$5,501.40  Construction Stockpile STMI - Total  \$5,501.40  1180 - Total  \$5,501.40  MISC. Construction 14 May 2, SYSTEM (\$27,445.28) Payment Estimate Item Adjustment generated Stockpile Transaction   |    |        |                      |                 |                |             |        |               |  |
| 1180 MISC. Construction Stockpile STMI 11 Mar 17, 2025 \$5,501.40 Payment Estimate Item Adjustment generated Stockpile Transaction \$5,501.40 Construction Stockpile STMI - Total \$5,501.40 \$5,501.40 \$180 - Total \$5,501.40 \$190 MISC. Construction 14 May 2, SYSTEM (\$27,445.28) Payment Estimate Item Adjustment generated Stockpile Transaction \$1,000 Payment Estimate Item Adjustment generated St   |    |        |                      | Material - Tota | ıl             |             |        |               |  |
| Stockpile   STMI   |    | 1120 - | Total                |                 |                |             |        | \$0.00        |  |
| Construction Stockpile STMI - Total \$5,501.40  1180 - Total \$5,501.40  1190 MISC. Construction 14 May 2, SYSTEM (\$27,445.28) Payment Estimate Item Adjustment generated Stockpile Transaction   |    | 1180   | MISC.                | Stockpile       | <b>.</b>       | 11          | SYSTEM |               | Payment Estimate Item Adjustment generated Stockpile Transaction       |
| 1180 - Total \$5,501.40  1190 MISC. Construction 14 May 2, SYSTEM (\$27,445.28) Payment Estimate Item Adjustment generated Stockpile Transaction   |    |        |                      |                 |                |             |        |               |  |
| 1190 MISC. Construction 14 May 2, SYSTEM (\$27,445.28) Payment Estimate Item Adjustment generated Stockpile Transaction  |    |        |                      | Construction    | Stockpile STI  | /II - Total |        |               |  |
|  | J  | 1180 - | Total                |                 |                |             |        | \$5,501.40    |  |
|  |    | 1190   | MISC.                |                 |                | 14          | SYSTEM | (\$27,445.28) | Payment Estimate Item Adjustment generated Stockpile Transaction       |



| oject | Line   | Description    | Adjustment<br>Type                | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount                     | Remarks   |
|-------|--------|----------------|-----------------------------------|-----------------------------|----------------|-----------------|---------------|----------------------------|---|
| 53640 | 1190   | MISC.          | Construction<br>Stockpile         | - Total                     |                |                 |               | (\$27,445.28)              |   |
|       |        |                | Construction                      | Stockpile - To              | otal           |                 |               | (\$27,445.28)              |   |
|       |        |                | Construction<br>Stockpile         |                             | 11             | Mar 17,<br>2025 | SYSTEM        | \$27,445.28                | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|       |        |                | STMI                              | - Total                     |                |                 |               | \$27,445.28                |   |
|       |        |                | Construction                      | Stockpile STI               | VII - Total    |                 |               | \$27,445.28                |   |
|       |        |                | Material                          |                             | 13             | Apr 16,<br>2025 | SYSTEM        | \$22,182.30                | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user smithh5 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
|       |        |                |                                   |                             | 13             | Apr 16,<br>2025 | SYSTEM        | (\$22,182.30)              |   |
|       |        |                |                                   |                             | 14             | May 2,<br>2025  | SYSTEM        | \$44,364.60                | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user smithh5 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
|       |        |                |                                   |                             | 14             | May 2,<br>2025  | SYSTEM        | (\$44,364.60)              |   |
|       |        |                |                                   | - Total                     |                |                 |               | \$0.00                     |   |
|       |        |                | Material - Tota                   | ıl                          |                |                 |               | \$0.00                     |   |
|       | 1190 - | Total          |                                   |                             |                |                 |               | \$0.00                     |   |
|       | 1210   | MISC.          | Construction<br>Stockpile         |                             | 14             | May 2,<br>2025  | SYSTEM        | (\$1,239.14)               | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|       |        |                |                                   | - Total                     |                |                 |               | (\$1,239.14)               |   |
|       |        |                | Construction                      | Stockpile - To              | otal           |                 |               | (\$1,239.14)               |   |
|       |        |                | Construction<br>Stockpile<br>STMI |                             | 11             | Mar 17,<br>2025 | SYSTEM        | \$2,478.28                 | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|       |        |                |                                   | - Total                     |                |                 |               | \$2,478.28                 |   |
|       | 1010   |                | Construction                      | Stockpile STI               | VII - Total    |                 |               | \$2,478.28                 |   |
|       | 1210 - |                | Otti                              |                             | 44             | M 47            | OVOTEM        | \$1,239.14                 | Decree of Fatigue to Mary Adjustment accounted Observation Transcriber  |
|       | 1240   | MISC.          | Construction<br>Stockpile<br>STMI | - Total                     | 11             | Mar 17,<br>2025 | SYSTEM        | \$62,792.28<br>\$62,792.28 | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|       |        |                | Construction                      |                             | MI Total       |                 |               | \$62,792.28                |   |
|       | 1240 - | Total          | oonstruction.                     | otookpiio o i i             | iii rotai      |                 |               | \$62,792.28                |   |
|       | 1340   | MISC. ITS      | Material                          |                             | 14             | May 2,          | SYSTEM        | (\$3,224.55)               |   |
|       |        |                |                                   |                             |                | 2025            |               |                            |   |
|       |        |                |                                   | - Total                     |                |                 |               | (\$3,224.55)               |   |
|       | 1240   | Total          | Material - Tota                   | 11                          |                |                 |               | (\$3,224.55)               |   |
|       | 1340 - | Total MISC ITS | Material                          |                             | 14             | May 2           | SVSTEM        | (\$3,224.55)               |   |
|       | 1330   | MISC. ITS      | Material                          | - Total                     | 14             | May 2,<br>2025  | SYSTEM        | (\$159.60)                 |   |
|       |        |                | Material - Tota                   |                             |                |                 |               | (\$159.60)                 |   |
|       | 1350 - | Total          | Total                             |                             |                |                 |               | (\$159.60)                 |   |
|       | 1360   | MISC. ITS      | Material                          |                             | 14             | May 2,<br>2025  | SYSTEM        | (\$235.20)                 |   |
|       |        |                |                                   | - Total                     |                |                 |               | (\$235.20)                 |   |
|       |        |                | Material - Tota                   | ıl                          |                |                 |               | (\$235.20)                 |   |
|       | 1360 - | Total          |                                   |                             |                |                 |               | (\$235.20)                 |   |
|       | 1430   | MISC. ITS      | Material                          |                             | 14             | May 2,<br>2025  | SYSTEM        | (\$2,835.00)               |   |
|       |        |                |                                   | - Total                     |                |                 |               | (\$2,835.00)               |   |
|       |        |                | Material - Tota                   | ıl                          |                |                 |               | (\$2,835.00)               |   |
|       | 1430 - | Total          |                                   |                             |                |                 |               | (\$2,835.00)               |   |
|       | 1440   | MISC. ITS      | Material                          |                             | 14             | May 2,<br>2025  | SYSTEM        | (\$441.00)                 |   |
|       |        |                |                                   | - Total                     |                |                 |               | (\$441.00)                 |   |

May 6, 2025



# Line Item Adjustments by Estimate

| Project   | Line            | Description | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount       | Remarks |
|-----------|-----------------|-------------|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---------|
| J6S3640   | 1440            | MISC. ITS   | Material - Tota    |                             |                |                 |               | (\$441.00)   |         |
|           | 1440 -          | Total       |                    |                             |                |                 |               | (\$441.00)   |         |
|           | 1480            | MISC. ITS   | Material           |                             | 14             | May 2,<br>2025  | SYSTEM        | (\$5,936.70) |         |
|           |                 |             |                    | - Total                     |                |                 |               | (\$5,936.70) |         |
|           |                 |             | Material - Tota    | ı                           |                |                 |               | (\$5,936.70) |         |
|           | 1480 -          | Total       |                    |                             |                |                 |               | (\$5,936.70) |         |
| J6S3640   | S3640 - Total   |             |                    |                             |                |                 |               | \$78,045.01  |         |
| Overall - | Overall - Total |             |                    |                             |                |                 |               |              |         |

# MoDOT

## Contract Adjustments for Contract - 240419-F06

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 20 of 20