

Pay Estimate Created Date: October 16, 2024

Number 6		Contract ID Prime Contractor	240517-D0 Capital Pav LLC	7-D07 Il Paving & Constru		Start		Original Contract Amoun Net Change Order Amount		\$91,235.96				
Approval Date								Current	Contract Amount	By User				
October 16, 2024			Genera	ated and /	Approved (ar	nd should be consid	dered Draft) at the	e Proiect C	Office Level by	ackert1				
October 16, 2024						ould be considered	,	,	,	kronej1				
October 17, 2024		Reviewed and Approved at the Central Office Controllers Office Level by												
Original Com	iginal Completion Date Current Completion Date Actual Completion D							Current C	ontract Amount					
August	A	ugust 1, 2025						86.72%						
Co	ontract Inform	ational Dates					Milestones							
Date Description	Origina Completion		urrent letion Date	Date D	Description	Original Completion Date	Current Completion D		ys Remaining on Milestone	Diary Charge Days				
Acceptance Date				Milestor Calenda		September 9, 2024	September 9, 2024	Mi	lestone Complete					
Awarded Date	June 5, 2024	June 5	2024											
Letting Date	May 17, 2024	4 May 17	, 2024											
Notice to Proceed Date	July 8, 2024	July 8,	2024											
Open to Traffic Date														
Work Began Date	August 5, 20	24 August	5, 2024											

Contract Total Pay For Estimate No. 6 To Date This Estimate Previous 240517-D07 <mark>\$287,871.52</mark> \$0.00 \$1,136,358.79 (\$1,848.90) Total Posted Items Pay \$848,487.27 \$040,407.27 (\$1,848.90) \$0.00 \$0.00 \$0.00 Gross Item Adjustments \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 Incentive Disincentive Liquidated Damage Other Contract Adjustments \$0.00 \$0.00 \$0.00 <mark>\$846,638.37</mark> \$1,134,509.89 Contract Total Payable This Estimate: \$287,871.52

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
JCD0030	0030	2031000	CLASS A EXCAVATION	CUYD	\$34.050	288	\$9,806.40
	0040	2035500	EMBANKMENT IN PLACE	CUYD	\$37.900	285	\$10,801.50
	0050	2036000	COMPACTING EMBANKMENT	CUYD	\$6.050	454	\$2,746.70
	0100	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)	SQYD	\$92.590	551.21	\$51,036.53
	0110	5021333	CONCRETE PAVEMENT (9 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	SQYD	\$85.990	1,289	\$110,841.11
	0130	6161005	CONSTRUCTION SIGNS	SQFT	\$17.030	96	\$1,634.88
	0280	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$10,909.180	0.25	\$2,727.30
	0440	9031210	STRUCTURAL STEEL POSTS	LB	\$24.560	106.2	\$2,608.27
	0450	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	EA	\$352.540	4	\$1,410.16
	0460	9031280	2.5 IN. PSST POST - 12 GA.	LF	\$10.890	192	\$2,090.88
	0470	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	EA	\$205.250	8	\$1,642.00
	0480	9035004A	SH-FLAT SHEET	SQFT	\$15.950	86.938	\$1,386.66
	0490	9035011A	ST-STRUCTURAL	SQFT	\$44.480	49	\$2,179.52
	0500	9035069A	SHF-FLAT SHEET FLUORESCENT	SQFT	\$24.400	86	\$2,098.40



Pay Estimate Created Date: October 16, 2024

Pro	ogress Estin Num 6	ber	Contract ID Prime Contractor	240517-D07 Capital Paving & Construction, LLC	Pay Period Start Pay Period En		ber 15,	Original Contract Ar Net Change Order Amount Current Contract An	\$91,235.96
Project Number	Line Number	Iter Coo		Item Description		Unit	Unit Price	e Current Installed Qty	Current Installed Amount
JCD0030	5002	6083	006 6 IN. CO	NCRETE MEDIAN STRIP		SQYD	\$82.88	30 645	\$53,457.60
	5003	5029	907 MISC.Tir	nted Concrete		CUYD	\$40.00	24.9	\$996.00
	5004	2022	010 REMOV	AL OF IMPROVEMENTS		LS	\$56,097.00	0.15	\$8,414.55
	5009 3049905 MISC.3 Inch Minus Base Rock (6 inch thick) SQYD \$12.740 1,726.3								
Project JCD	0030 - Total								\$287,871.52
Overall - Tot	tal								\$287,871.52

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JCD0030	0100	CONCRETE PAVEMENT (8 IN. NON-REINF)	Material			-290.19	\$92.59	(\$26,868.69)
	0100	CONCRETE PAVEMENT (8 IN. NON-REINF)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user ackert1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	290.19	\$92.59	\$26,868.69
	0110	CONCRETE PAVEMENT (9 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material			-920.686	\$85.99	(\$79,169.79)
	0110	CONCRETE PAVEMENT (9 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user ackert1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	920.686	\$85.99	\$79,169.79
	0300	ROCK DITCH CHECK	Material			-80	\$45.86	(\$3,668.80)
	0300	ROCK DITCH CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user ackert1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	80	\$45.86	\$3,668.80
	0440	STRUCTURAL STEEL POSTS	Material			-106.2	\$24.56	(\$2,608.27)
	0440	STRUCTURAL STEEL POSTS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user ackert1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	106.2	\$24.56	\$2,608.27
	0450	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	Material			-4	\$352.54	(\$1,410.16)
	0450	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user ackert1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	4	\$352.54	\$1,410.16
	0460	2.5 IN. PSST POST - 12 GA.	Material			-192	\$10.89	(\$2,090.88)
	0460	2.5 IN. PSST POST - 12 GA.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user ackert1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	192	\$10.89	\$2,090.88



Pay Estimate Created Date: October 16, 2024

Progress Estimate Number			Contract ID	240517-D0)7		Pay Period Start	October 1, 2024	Original Contra	ct Amount \$	\$1,219,090.90
	6		Prime Contractor	Capital Pa LLC	ving & Constru	October 15, 2024	Net Change Order\$91,235.96Amount\$1,310,326.86Current Contract Amount\$1,310,326.86				
Project Number	Line No.	Item Do	escription	Adjustment Type	Other Item Adjustment Type		Commer	its	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JCD0030	0480	S	H-FLAT SHEET	Material					-86.938	\$15.95	(\$1,386.66
	0480	S	H-FLAT SHEET	Material		genei A	rated Material Pay Adjustment (0008) Iding Payment Es	the original syste yment Estimate Ite due to user acke timate Exception t Payment Estima	em rt1 13	\$15.95	\$1,386.66
	0490	ST	-STRUCTURAL	Material					-49	\$44.48	(\$2,179.52
	0490	ST	-STRUCTURAL	Material		genei A	rated Material Pay Adjustment (0009) Iding Payment Es	the original syste ment Estimate Ite due to user acke timate Exception t Payment Estima	em rt1 14	\$44.48	\$2,179.52
	0500		IF-FLAT SHEET FLUORESCENT	Material					-86	\$24.40	(\$2,098.40
	0500		IF-FLAT SHEET FLUORESCENT	Material		genei A	rated Material Pay adjustment (0010) dding Payment Es	the original syste yment Estimate Ite due to user acke timate Exception t Payment Estima	em rt1 15	\$24.40	\$2,098.40
	5002	6 IN. CON	CRETE MEDIAN STRIP	Material					-645	\$82.88	(\$53,457.60
	5002	6 IN. CON	CRETE MEDIAN STRIP	Material		genei A	rated Material Pay adjustment (0001) ing Payment Estir	the original syste yment Estimate Ite due to user acke nate Exception 5 t Payment Estima	em rt1 on	\$82.88	\$53,457.60
	5008		MISC.	Material					-2,153	\$13.28	(\$28,591.84
	5008		MISC.	Material		genei A	rated Material Pay Adjustment (0003) ing Payment Estir	the original syste yment Estimate Ite due to user acke nate Exception 2 t Payment Estima	em rt1 on	\$13.28	\$28,591.84
	5009		MISC.	Material					-5,285	\$12.74	(\$67,330.90
	5009		MISC.	Material		genei A	rated Material Pay Adjustment (0002) ing Payment Estir	the original syste yment Estimate Ite due to user acke nate Exception 1 t Payment Estima	em rt1 on	\$12.74	\$67,330.90
Fotal											\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information											
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work					
JCD0030	FAF-22-1 (11)	Roundabout	22	BOONE	at Route 124 and Route 151							
Totals by Job Numbers												
JCD0030		d Item Pay Item Adjustme		Item Pay	This Estimate \$287,871.52 \$0.00 \$287,871.52	Previous \$848,487.27 (\$1,848.90) \$846,638.37	To Date \$1,136,358.79 (\$1,848.90) \$1,134,509.89					
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Ferrou			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JCD0030, Item 3049905, Project Item Line Number 5009, Material Set 304990596, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Need Gradation, PI, T1T5, Deleterious completed by both QA and QC $$	ackert1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0030, Item 3049905, Project Item Line Number 5008, Material Set 304990596, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Need Gradation, PI, T1T5, Deleterious completed by both QA and QC $% \left({\frac{{{\left({{{\rm{A}}} \right)}}}{{\left({{\rm{A}} \right)}}}} \right)$	ackert1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0030, Item 5021108, Project Item Line Number 0100, Material Set 502110896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Sample appears to be completed on the sample checklist report from Cognos	ackert1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0030, Item 5021333, Project Item Line Number 0110, Material Set 502133396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Sent e-mail to CD Materials to remove the tests associated with the 1" masonry since the tests is a repeat on the 1" PCCP	ackert1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0030, Item 6083006, Project Item Line Number 5002, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Showing 29.05 gallons short of clear cure but white pigment was used instead. I will notify CD materials to make change	ackert1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0030, Item 6083006, Project Item Line Number 5002, Material Set 608300696, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	same remark as above	ackert1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0030, Item 6083006, Project Item Line Number 5002, Material Set 608300696, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Same remark as above	ackert1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0030, Item 6083006, Project Item Line Number 5002, Material Set 608300696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Same remark as above	ackert1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0030, Item 8061005, Project Item Line Number 0300, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	A cert is required for the rock ditch check, I will contact CD materials to remove requirements.	ackert1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0030, Item 9031210, Project Item Line Number 0440, Material Set 903121096, Material 0903HSPSSS - Structural Steel Post for Highway Signin, Acceptance Action Generic 0903HSPSSS is insufficient.	Requests certs from Amanda with James H. Drew yesterday midafternoon.	ackert1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0030, Item 9031241, Project Item Line Number 0450, Material Set 903124196, Material 0903HSBA - Breakaway Assembly for Highway Signing, Acceptance Action Generic 0903HSBA is insufficient.	Requests certs from Amanda with James H. Drew yesterday midafternoon.	ackert1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0030, Item 9031280, Project Item Line Number 0460, Material Set 903128096, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Requests certs from Amanda with James H. Drew yesterday midafternoon.	ackert1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0030, Item 9035004A, Project Item Line Number 0480, Material Set 9035004A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Cert received from Amanda with James H. Drew which was sent to CD materials for review and approval.	ackert1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0030, Item 9035011A, Project Item Line Number 0490, Material Set 9035011A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Cert received from Amanda with James H. Drew which was sent to CD materials for review and approval.	ackert1	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0030, Item 9035069A, Project Item Line Number 0500, Material Set 9035069A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Cert received from Amanda with James H. Drew which was sent to CD materials for review and approval.	ackert1	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

oral rad rad memory rad resumates (including uns countable) lote: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities a				eport Generated date and can differ from the posted amo	ount at the	e time the	Estimate wa	is Gener	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
240517-D07	JCD0030	0001	0010	1049910	MISC. TEMPORARY SURFACINGGravel (A), Crushed Stone (B)	100.00	0.00	100.00	TONS	49.00	\$69.41	\$3,401.09
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	-1.00	0.00	LS	0.00	\$58,182.74	\$0.00
		0001	0030	2031000	CLASS A EXCAVATION	1,759.00	0.00	1,759.00	CUYD	1,759.00	\$34.05	\$59,893.95
		0001	0040	2035500	EMBANKMENT IN PLACE	516.00	-231.00	285.00	CUYD	285.00	\$37.90	\$10,801.50
		0001	0050	2036000	COMPACTING EMBANKMENT	1,301.00	0.00	1,301.00	CUYD	1,301.00	\$6.05	\$7,871.05
		0001	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	2,153.00	-2,153.00	0.00	SQYD	0.00	\$13.28	\$0.00
		0001	0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	5,285.00	-5,285.00	0.00	SQYD	0.00	\$12.74	\$0.00
		0001	0080	3105002	GRAVEL (A) OR CRUSHED STONE (B)	92.00	0.00	92.00	TONS	0.00	\$58.43	\$0.00
		0001	0090	4019905	MISC.Optional Pavement	2,153.00	176.00	2,329.00	SQYD	2,329.00	\$66.79	\$155,553.91
		0001	0100	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)	1,010.00	0.00	1,010.00	SQYD	1,010.00	\$92.59	\$93,515.90
		0001	0110	5021333	CONCRETE PAVEMENT (9 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	4,710.00	0.00	4,710.00	SQYD	4,710.00	\$85.99	\$405,012.90
		0001	0120	6091011	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	249.00	-249.00	0.00	LF	0.00	\$56.81	\$0.00
		0001	0130	6161005	CONSTRUCTION SIGNS	688.00	0.00	688.00	SQFT	640.00	\$17.03	\$10,899.20
		0001	0140	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$51.10	\$204.40
		0001	0150	6161010	RELOCATED SIGNS	266.00	0.00	266.00	SQFT	141.25	\$17.03	\$2,405.49
		0001	0160	6161025	CHANNELIZER (TRIM LINE)	165.00	0.00	165.00	EA	165.00	\$27.25	\$4,496.25
		0001	0170	6161030	TYPE III MOVEABLE BARRICADE	5.00	0.00	5.00	EA	5.00	\$210.06	\$1,050.30
		0001	0180	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	5.00	0.00	5.00	EA	5.00	\$3,406.34	\$17,031.70
		0001	0190	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$63,825.30	\$63,825.30
		0001	0200	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0210	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	129.00	0.00	129.00	LF	0.00	\$28.39	\$0.00
		0001	0220	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	88.00	0.00	88.00	LF	0.00	\$28.39	\$0.00
		0001	0230	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	36.00	0.00	36.00	EA	0.00	\$51.10	\$0.00
		0001	0240	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	4,794.00	264.00	5,058.00	LF	5,058.00	\$2.10	\$10,621.80
		0001	0250	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	5,068.00	0.00	5,068.00	LF	5,068.00	\$2.10	\$10,642.80
		0001	0260	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,743.00	0.00	1,743.00	LF	0.00	\$1.14	\$0.00
		0001	0270	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,985.00	0.00	1,985.00	LF	0.00	\$1.14	\$0.00
		0001	0280	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$10,909.18	\$10,909.18
		0001	0290	8059901	MISC.Seeding Cool Season Mixtures	1.00	0.00	1.00	LS	0.00	\$5,732.88	\$0.00
		0001	0300	8061005	ROCK DITCH CHECK	104.00	0.00	104.00	LF	80.00	\$45.86	\$3,668.80
		0001	0310	8061016	SEDIMENT REMOVAL	130.00	0.00	130.00	CUYD	0.00	\$14.96	\$0.00
		0020	0320	9011030	LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT	8.00	0.00	8.00	EA	0.00	\$3,344.83	\$0.00
		0020	0330	9011115	BRACKET ARM, 15 FT. OR 4.6 M	8.00	0.00	8.00	EA	0.00	\$1,680.85	\$0.00
		0020	0340	9011311	LUMINAIRE, LED-A	8.00	0.00	8.00	EA	0.00	\$459.84	\$0.00
		0020	0350	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	1.00	0.00	1.00	EA	0.00	\$8,769.65	\$0.00
		0020	0360	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	89.00	0.00	89.00	LF	0.00	\$16.86	\$0.00
		0020	0370	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	135.00	0.00	135.00	LF	0.00	\$21.36	\$0.00
		0020	0380	9016110	PULL BOX, PREFORMED CLASS 1	6.00	0.00	6.00	EA	2.00	\$1,940.57	\$3,881.14
		0020	0390	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	720.00	0.00	720.00	LF	0.00	\$1.12	\$0.00
		0020	20 0400 9017401 CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 2 AWG			110.00	0.00	110.00	LF	0.00	\$21.36	\$0.00
		0020	0410	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	1,100.00	0.00	1,100.00	LF	0.00	\$10.12	\$0.00
		0020	0420	9018230	POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	8.00	0.00	8.00	EA	3.00	\$1,805.65	\$5,416.95
		0020	0430	9018610	POWER SUPPLY ASSEMBLY, TYPE 1, 240/120 VOLT SERVICE, LIGHTING ONLY	1.00	0.00	1.00	EA	0.00	\$10,118.82	\$0.00

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
240517-D07	JCD0030	0040	0440	9031210	STRUCTURAL STEEL POSTS	300.00	0.00	300.00	LB	106.20	\$24.56	\$2,608.27
		0040	0450	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	20.00	0.00	20.00	EA	4.00	\$352.54	\$1,410.16
		0040	0460	9031280	2.5 IN. PSST POST - 12 GA.	704.00	0.00	704.00	LF	192.00	\$10.89	\$2,090.88
		0040	0470	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	24.00	0.00	24.00	EA	8.00	\$205.25	\$1,642.00
		0040	0480	9035004A	SH-FLAT SHEET	343.00	0.00	343.00	SQFT	86.94	\$15.95	\$1,386.66
		0040	0490	9035011A	ST-STRUCTURAL	81.00	0.00	81.00	SQFT	49.00	\$44.48	\$2,179.52
		0040	0500	9035069A	SHF-FLAT SHEET FLUORESCENT	151.00	0.00	151.00	SQFT	86.00	\$24.40	\$2,098.40
		0001	5001	6191000	PAVEMENT EDGE TREATMENT	0.00	1,900.00	1,900.00	LF	1,037.00	\$7.00	\$7,259.00
		0001	5002	6083006	6 IN. CONCRETE MEDIAN STRIP	0.00	645.00	645.00	SQYD	645.00	\$82.88	\$53,457.60
		0001	5003	5029907	MISC.Tinted Concrete	0.00	119.90	119.90	CUYD	119.90	\$40.00	\$4,796.00
		0001	5004	2022010	REMOVAL OF IMPROVEMENTS	0.00	1.00	1.00	LS	0.95	\$56,097.00	\$53,292.15
		0001	5005	2039907	MISC.Removal of unsuitable material and rock base backfill	0.00	300.00	300.00	CUYD	241.00	\$88.94	\$21,434.54
		0001	5006	6207001	PAVEMENT MARKING REMOVAL	0.00	573.00	573.00	LF	573.00	\$3.25	\$1,862.25
		0001	5007	4019910	MISC.Wedging asphalt to create a smooth transition around truck apron	0.00	35.00	35.00	TONS	35.00	\$109.00	\$3,815.00
		0001	5008	3049905	MISC.3 Inch Minus Base Rock (4 inch thick)	0.00	2,153.00	2,153.00	SQYD	2,153.00	\$13.28	\$28,591.84
	0001 5009 3049905 MISC.3 Inch Minus Base Rock (6 inch thick) 0.00 5,285.00 5,285.00 SQYD 5,285.00 \$12.74									\$67,330.90		
	Project JCD0030 - Total Value Posted to Date as of Report Generated Date											\$1,136,358.78
240517-D07 Ove	Overall - Total Value Posted to Date as of Report Generated Date											\$1,136,358.78



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: JCD0030 DWR DWR Date Approval Date From Offset/ Station/ Distance Log Mile Line Number Item Code Description Quantity Units Posted Location To Station/ Offset/ Distance Comments Log Mile 10/15/24 10/16/24 0030 2031000 CLASS A EXCAVATION 288.00 CUYD Stage 5 completed almost done with stage 6 dirt work 0+52 1+49 0040 2035500 EMBANKMENT IN PLACE 10/15/24 10/16/24 285.00 CUYD Stage 5 completed 0+00 4+50 0050 2036000 COMPACTING EMBANKMENT 10/15/24 10/16/24 454.00 CUYD Stage 5 and Stage 6 completed 0+00 4+50 0100 5021108 CONCRETE PAVEMENT (8 IN NON-REINE) 10/1/24 10/1/24 96.90 SQYD Truck apron red dye. 2+52 54 Circle 3+46.64 Circle 10/8/24 10/11/24 40.30 SQYD 0+00 1+92.37 Stage 4 Rte 22 west entry/truck apron island 10/14/24 10/15/24 88.91 SQYD South Splitter Island paid to plan quantity all 0100-line items are completed 0+97 10/15/24 109.90 SQYD West Splitter Island 2+62 10/15/24 10/16/24 107.60 SQYD East Splitter island 1+00 10/16/24 107.60 SQYD North Splitter Island 0+97.00 164.40 SQYD Stage 4 Circle 10/8/24 10/11/24 2+52.54 0110 5021333 CONCRETE PAVEMENT (9 1/2 IN. NON-REINF, 3+46.64 473.60 SQYD 10/11/24 0+00 1+92.37 Stage 4 Rte 22 West Entry Paid to planned quantity Stage 4 Rte 124 exit 10/11/24 651.00 SQYD 1+92.37 3+97.66 6161005 CONSTRUCTION SIGNS 10/8/24 10/11/24 96.00 SQFT 243+00.15 248+36.5 Stage 5 Construction Signing 0130 0.25 6274000 CONTRACTOR FURNISHED SURVEYING AND STAKI 10/15/24 10/16/24 LS signs and pavement completed 243+00.15 248+36.5 0280 LB Sign No. | Sta. 11 94+00 22 256+18 24 252+18 9031210 STRUCTURAL STEEL POSTS 0440 10/15/24 10/16/24 106.20 EA Sign No. | Sta. 26 248+18 35 81+50 0450 9031241 BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE) 10/15/24 10/16/24 4.00 81+50 248+18 0460 9031280 2.5 IN. PSST POST - 12 GA. 10/15/24 10/16/24 192.00 LF Sign No. Station/Log Mile 2 237+49 4 241+00 11 94+00 22 256+18 23 254+18 24 252+18 25 250+18 25 250+18 26 248+18 34 79+50 35 81+50 0470 9031281A DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA. 10/15/24 10/16/24 8.00 EA Sign No. Station/Log Mile 2 237+49 4 241+00 11 94+00 22 256+18 23 254+18 24 252+18 25 250+18 34 79+50 Sign No. Station/Log Mile 0480 9035004A SH-FLAT SHEET 10/15/24 10/16/24 86.94 SQFT 11 94+00 22 256+18 24 252+18 0490 9035011A ST-STRUCTURAL 49.00 SQFT Sign No. Station/Log Mile 10/15/24 10/16/24 26 248+18 35 81+50 0500 9035069A SHE-FLAT SHEET FLUORESCENT 10/15/24 10/16/24 86.00 SQFT Sign No. Station/Log Mile 1 236+19 2 237+49 4 241+00 23 254+18 25 250+18 34 79+50 5002 6083006 6 IN. CONCRETE MEDIAN STRIP 10/10/24 10/15/24 645.00 SQYD Center of roundabout paid to plan 245+00 246+25 5003 5029907 MISC. 10/15/24 10/16/24 24.90 CUYD Tinted concrete completed 245+00 5004 2022010 REMOVAL OF IMPROVEMENTS 10/15/24 10/16/24 0.15 LS Stage 4 and stage 5 completed 243+00.15 248+36.5 5009 3049905 MISC. AGGREGATE FOR BASE 10/15/24 10/16/24 1.726.30 SQYD Route 124 and Route 22 Completed 0+00 3+97

The information below this line are details for Construction Signs (if applicable).

No Data Available



		1			1				
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JCD0030	0050	COMPACTING EMBANKMENT	Material		2	Aug 16, 2024	SYSTEM	\$1,633.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user tayloc6 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Aug 16, 2024	SYSTEM	(\$1,633.50)	
					3	Aug 30, 2024	SYSTEM	\$1,633.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ackert1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Aug 30, 2024	SYSTEM	(\$1,633.50)	
					4	Sep 16, 2024	SYSTEM	\$4,180.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ackert1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$4,180.55)	
					5	Sep 30, 2024	SYSTEM	\$5,124.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ackert1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Sep 30, 2024	SYSTEM	(\$5,124.35)	
				- Total	1	1		\$0.00	
			Material - To					\$0.00	
	0050	- Total							
	0050 -	AGGREGATE FOR BASE	Material		2	Aug 16, 2024	SYSTEM	\$0.00 \$15,160.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user tayloc6 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Aug 16, 2024	SYSTEM	(\$15,160.45)	
					3	Aug 30, 2024	SYSTEM	\$23,293.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ackert1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Aug 30, 2024	SYSTEM	(\$23,293.12)	
					4	Sep 16, 2024	SYSTEM	\$23,293.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ackert1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$23,293.12)	
				- Total				\$0.00	
			Material - Te	otal				\$0.00	
	0060 -	- Total						\$0.00	
	0070	AGGREGATE FOR BASE (6 IN.	Material		3	Aug 30, 2024	SYSTEM	\$27,862.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ackert1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		THICK)			3	Aug 30, 2024	SYSTEM	(\$27,862.38)	
					4	Sep 16, 2024	SYSTEM	\$39,188.24	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ackert1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$39,188.24)	
				- Total				\$0.00	
			Material - Te	otal				\$0.00	
	0070 -	- Total						\$0.00	
	0090	MISC.	Other Item Adjustment	ACAD	2	Aug 16, 2024	tayloc6	(\$393.44)	See AC Index Price Adjustment report file in EProject.
					5	Sep 30, 2024	ackert1	(\$181.03)	318 SQYDS of asphalt placed in the second period of August 2024 using the asphalt mix: SL24-45 with 4.50% of AC.
					5	Sep 30, 2024	ackert1	(\$414.76)	399 SQYDS of asphalt placed in the second period of September 2024 using the asphalt mix: SL24-45 with 4.50% of AC.
					5	Sep 30, 2024	ackert1	(\$859.67)	827 SQYDS of asphalt placed in the first period of September 2024 using the asphalt Mix: SL24-45 with 4.50% of AC.
				ACAD - Tot			(\$1,848.90)		
			Other Item	Adjustment -	Total			(\$1,848.90)	



Oct 18, 2024

CD0003 0090 - Total (51,849.90) 0100 CONCRETE PAVEMENT (8 IN NON-REINF) Material 3 Aug 30, 2024 SYSTEM \$31,127.83 This adjustment offsets the original system-gr Estimate tem Adjustment (0005) due to user Estimate tem Adjustment (0011) due to user Estimate tem Adjustment (0011) due to user Estimate Exception 3 on the current Payment 6 0100 - Total V V S0.00 This adjustment offsets the original system-gr Estimate tem Adjustment (0006) due to user Estimate texception 9 on the current Payment 3	ackert1 overridding Payment Estimate. enerated Material Payment ackert1 overridding Payment Estimate. enerated Material Payment ackert1 overridding Payment ackert1 overridding Payment Estimate. enerated Material Payment Estimate.
PAVEMENT (8 IN, NON-REINF) 2024 2024 SYSTEM (\$31,127.83) Estimate Exception 6 on the current Payment 3 Aug. 30, 2024 SYSTEM (\$42,479.37) This adjustment offsets the original system-gree Estimate term Adjustment (0006) due to user Estimate term Adjustment (0001) due to user Estimate term Adjustment (0011) due to user Estimate term Adjustment (0011) use to user Estimate term Adjustment (0011) use to use	ackert1 overridding Payment Estimate. enerated Material Payment ackert1 overridding Payment Estimate. enerated Material Payment ackert1 overridding Payment ackert1 overridding Payment Estimate. enerated Material Payment Estimate.
0 2024 0 Number of Sets the original system-ge Estimate term Adjustment (0006) due to user Estimate Exception 6 on the current Payment 4 Sep 16, SYSTEM \$42,479.37 This adjustment offsets the original system-ge Estimate Exception 6 on the current Payment 4 Sep 16, SYSTEM \$42,479.37 This adjustment offsets the original system-ge Estimate Exception 6 on the current Payment 5 Sep 30, 2024 \$YSTEM \$26,868.69 This adjustment offsets the original system-ge Estimate Exception 6 on the current Payment 5 Sep 30, 2024 \$YSTEM \$26,868.69 This adjustment offsets the original system-ge Estimate Exception 6 on the current Payment 5 Sep 30, 2024 \$YSTEM \$26,868.69 This adjustment offsets the original system-ge Estimate Item Adjustment (0011) due to user Estimate Exception 3 on the current Payment 6 Oct 16, 2024 \$YSTEM \$26,868.69 This adjustment offsets the original system-ge Estimate Exception 3 on the current Payment 6 Oct 16, 2024 \$YSTEM \$26,868.69 This adjustment offsets the original system-ge Estimate Exception 3 on the current Payment 6 Oct 16, 2024 \$YSTEM \$26,868.69 This adjustment offsets the original system-ge Estimate Exception 3 on the current Payment <td>ackert1 overridding Payment Estimate.</td>	ackert1 overridding Payment Estimate.
 	ackert1 overridding Payment Estimate.
Image: stand stan	ackert1 overridding Payment Estimate. enerated Material Payment ackert1 overridding Payment Estimate. enerated Material Payment ackert1 overridding Payment
Image: Second	ackert1 overridding Payment Estimate. enerated Material Payment ackert1 overridding Payment Estimate. enerated Material Payment ackert1 overridding Payment
0100 - Total CONCRETE PAVEMENT (9 1/2 IN. NON-REINF, Material 3 Aug 30, 2024 SYSTEM \$252,664.42 This adjustment offsets the original system-get Estimate texception 9 on the current Payment 3 Aug 30, 2024 SYSTEM \$194,646.96 This adjustment offsets the original system-get Estimate texception 9 on the current Payment	ackert1 overridding Payment Estimate. enerated Material Payment ackert1 overridding Payment
0100 - Total CONCRETE IN. NON-REINF, Material 3 Aug 30, 2024 SYSTEM (\$26,868.69) 0100 - Total Substrate item Adjustment (0011) due to user Estimate Exception 3 on the current Payment 0110 CONCRETE IN. NON-REINF, Material 3 Aug 30, 2024 SYSTEM \$194,646.96 3 Aug 30, 2024 SYSTEM \$194,646.96 This adjustment (0006) due to user Estimate Exception 9 on the current Payment 3 Aug 30, 2024 SYSTEM \$194,646.96 This adjustment (0006) due to user Estimate Exception 9 on the current Payment	ackert1 overridding Payment Estimate. enerated Material Payment ackert1 overridding Payment
Image: Constraint of the second of	ackert1 overridding Payment
Material - Total \$0.00 O100 - Total O110 CONCRETE PAVEMENT (9 1/2 IN. NON-REINF, Material 3 Aug 30, 2024 \$194,646.96 This adjustment offsets the original system-ge Estimate Item Adjustment (0006) due to user Estimate Exception 9 on the current Payment 3 Aug 30, 2024 \$YSTEM \$194,646.96 This adjustment offsets the original system-ge Estimate Exception 9 on the current Payment 4 Sep 16, 2024 \$YSTEM \$252,664.42 This adjustment (0007) due to user Estimate Exception 9 on the current Payment	ackert1 overridding Payment
O100 - Total S0.00 0110 CONCRETE PAVEMENT (9 1/2 IN. NON-REINF, Material 3 Aug 30, 2024 SYSTEM \$194,646.96 This adjustment offsets the original system-greestimate Exception 9 on the current Payment 4 Sep 16, 2024 SYSTEM \$252,664.42 This adjustment (0007) due to user Estimate texception 9 on the current Payment	ackert1 overridding Payment
0110 CONCRETE PAVEMENT (9 1/2 IN. NON-REINF, Material 3 Aug 30, 2024 SYSTEM \$194,646.96 This adjustment offsets the original system-ge Estimate Exception 9 on the current Payment 3 Aug 30, 2024 SYSTEM \$194,646.96 This adjustment offsets the original system-ge Estimate Exception 9 on the current Payment 4 Sep 16, 2024 SYSTEM \$252,664.42 This adjustment offsets the original system-ge Estimate Exception 9 on the current Payment	ackert1 overridding Payment
PAVEMENT (9 1/2 IN. NON-REINF, 2024 Estimate Item Adjustment (0006) due to user Estimate Exception 9 on the current Payment 3 Aug 30, 2024 SYSTEM (\$194,646.96) 4 Sep 16, 2024 SYSTEM \$252,664.42 This adjustment offsets the original system-ge Estimate Exception 9 on the current Payment	ackert1 overridding Payment
2024 2024 4 Sep 16, 2024 2024 System 252,664.42 Estimate Item Adjustment (0007) due to user Estimate Exception 9 on the current Payment	
2024 Estimate Item Adjustment (0007) due to user Estimate Exception 9 on the current Payment	
	ackert1 overridding Payment
4 Sep 16, SYSTEM (\$252,664.42) 2024	
5 Sep 30, SYSTEM \$131,250.23 This adjustment offsets the original system-ge Estimate Item Adjustment (0006) due to user Estimate Exception 8 on the current Payment	ackert1 overridding Payment
5 Sep 30, SYSTEM (\$131,250.23) 2024	
6 Oct 16, SYSTEM 2024 \$79,169.79 This adjustment offsets the original system-gr Estimate Item Adjustment (0012) due to user Estimate Exception 4 on the current Payment	ackert1 overridding Payment
6 Oct 16, SYSTEM (\$79,169.79) 2024	
- Total \$0.00	
Material - Total \$0.00	
0110 - Total \$0.00	
0180 CMS WITH Material 1 Aug 5, SYSTEM \$13,625.36 This adjustment offsets the original system-get Estimate Item Adjustment (0001) due to user Estimate Exception 1 on the current Payment	ackert1 overridding Payment
CONT F 1 Aug 1, 2024 (\$13,625.36)	
- Total \$0.00	
Material - Total \$0.00	
0180 - Total \$0.00	
0240 TEMPORARY Material REMOVABLE MARKING TAPE 4 1 2 Aug 16, 2024 2024 \$\$3,194.10 This adjustment offsets the original system-get Estimate Item Adjustment (0001) due to user Estimate Exception 4 on the current Payment IN.	tayloc6 overridding Payment
2 Aug 16, SYSTEM (\$3,194.10) 2024	
- Total \$0.00	
Material - Total \$0.00	
0240 - Total \$0.00	



Oct 18, 2024

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JCD0030	0250	TEMPORARY REMOVABLE MARKING TAPE	Material	Type	2	Aug 16, 2024	SYSTEM	\$3,456.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user tayloc6 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	Aug 16, 2024	SYSTEM	(\$3,456.60)	
				- Total	1			\$0.00	
			Material - T	otal				\$0.00	
	0250 -	Total						\$0.00	
	0300	ROCK DITCH CHECK	Material		2	Aug 16, 2024	SYSTEM	\$3,668.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user tayloc6 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					2	Aug 16, 2024	SYSTEM	(\$3,668.80)	
					3	Aug 30, 2024	SYSTEM	\$3,668.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ackert1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					3	Aug 30, 2024	SYSTEM	(\$3,668.80)	
					4	Sep 16, 2024	SYSTEM	\$3,668.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ackert1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$3,668.80)	
					5	Sep 30, 2024	SYSTEM	\$3,668.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ackert1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Sep 30, 2024	SYSTEM	(\$3,668.80)	
					6	Oct 16, 2024	SYSTEM	\$3,668.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ackert1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$3,668.80)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0300 -	Total						\$0.00	
	0440	STRUCTURAL STEEL POSTS	Material		6	Oct 16, 2024	SYSTEM	\$2,608.27	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ackert1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$2,608.27)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0440 -	Total						\$0.00	
	0450	BREAKAWAY ASSEMBLY (PERFORATED	Material		6	Oct 16, 2024	SYSTEM	\$1,410.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user ackert1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
		SQUARE STEEL TUBE)			6	Oct 16, 2024	SYSTEM	(\$1,410.16)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0450 -	Total						\$0.00	
	0460	2.5 IN. PSST POST - 12 GA.	Material		6	Oct 16, 2024	SYSTEM	\$2,090.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ackert1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$2,090.88)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0460 -	Total						\$0.00	
	0480	SH-FLAT SHEET	Material		6	Oct 16, 2024	SYSTEM	\$1,386.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user ackert1 overridding Payment Estimate Exception 13 on the current Payment Estimate.



Oct 18, 2024

	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JCD0030 (0480	SH-FLAT SHEET	Material		6	Oct 16, 2024	SYSTEM	(\$1,386.66)	
				- Total				\$0.00	
			Material - To	aterial - Total				\$0.00	
	0480 -	Total						\$0.00	
(0490	ST-STRUCTURAL	Material		6	Oct 16, 2024	SYSTEM	\$2,179.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user ackert1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$2,179.52)	
			- Total					\$0.00	
			Material - Total					\$0.00	
	0490 -							\$0.00	
(0500	SHF-FLAT SHEET FLUORESCENT	Material		6	Oct 16, 2024	SYSTEM	\$2,098.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user ackert1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$2,098.40)	
			- Total					\$0.00	
			Material - Total					\$0.00	
	0500 -							\$0.00	
ł	5001	PAVEMENT EDGE TREATMENT	Material		4	Sep 16, 2024	SYSTEM	\$7,259.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ackert1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$7,259.00)	
			- Total					\$0.00	
			Material - To	otal				\$0.00	
	5001 -							\$0.00	
ł	5002	6 IN. CONCRETE MEDIAN STRIP	Material		6	Oct 16, 2024	SYSTEM	\$53,457.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ackert1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$53,457.60)	
				- Total				\$0.00	
	Material - Total							\$0.00	
		Total						\$0.00	
1	5008	MISC. AGGREGATE FOR BASE	Material		5	Sep 30, 2024	SYSTEM	\$28,591.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ackert1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Sep 30, 2024	SYSTEM	(\$28,591.84)	
					6	Oct 16, 2024	SYSTEM	\$28,591.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ackert1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$28,591.84)	
				- Total				\$0.00	
	Material - Total							\$0.00	
	5008 -	Total						\$0.00	
ł	5009	MISC. AGGREGATE FOR BASE	Material		5	Sep 30, 2024	SYSTEM	\$45,337.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ackert1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Sep 30, 2024	SYSTEM	(\$45,337.84)	
					6	Oct 16, 2024	SYSTEM	\$67,330.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ackert1 overridding Payment
									Estimate Exception 1 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$67,330.90)	Estimate Exception 1 on the current Payment Estimate.



Oct 18, 2024

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JCD0030	5009	MISC. AGGREGATE FOR BASE		otal				\$0.00	
	5009 - Total							\$0.00	
JCD0030	- Total							(\$1,848.90)	
Overall - 1	Total						(\$1,848.90)		



There are no contract adjustments to display for this contract.